

---

# **CC3100 SimpleLink™**

## **Single-Chip 802.11bgn Networking Solution**

### **Software Development Kit (SDK) v0.5 Release Notes**

---

**TABLE OF CONTENTS**

<b>1</b>	<b>SCOPE.....</b>	<b>5</b>
<b>2</b>	<b>NEW FEATURE ADDED ON TOP OF SDKV0.41 .....</b>	<b>5</b>
<b>3</b>	<b>MATURITY, LIMITATION AND KNOWN ISSUES.....</b>	<b>5</b>
3.1	PRODUCT CONSTRAINTS .....	6
<b>4</b>	<b>RELEASE COMPONENTS .....</b>	<b>8</b>
<b>5</b>	<b>DEVICE HARDWARE.....</b>	<b>10</b>
<b>6</b>	<b>DEVICE FIRMWARE.....</b>	<b>10</b>
6.1	FEATURES LIST .....	10
6.1.1	WiFi .....	10
6.1.2	Networking .....	11
6.1.3	Advanced Features .....	11
6.1.4	Interfaces .....	12
6.1.5	Power Modes .....	12
<b>7</b>	<b>SAMPLE APPLICATIONS.....</b>	<b>12</b>
7.1	SAMPLE APPLICATIONS ON MSP430F5529 LAUNCHPAD .....	12
7.1.1	Antenna Selection .....	12
7.1.2	Connection Policies .....	12
7.1.3	Email .....	13
7.1.4	Enterprise Network Connection .....	13
7.1.5	File Operations.....	13
7.1.6	Get Time .....	13
7.1.7	Get Weather .....	13
7.1.8	Getting Started in AP Mode.....	13
7.1.9	Getting Started in STA Mode .....	13
7.1.10	HTTP Server.....	13
7.1.11	IP Configuration .....	14
7.1.12	MDNS.....	14
7.1.13	Mode Config.....	14
7.1.14	NWP Filters.....	14
7.1.15	NWP Power Policy.....	14
7.1.16	P2P (WiFiDirect).....	14
7.1.17	Provisioning AP .....	14
7.1.18	Provisioning with SmartConfig.....	14
7.1.19	Provisioning with WPS .....	14

7.1.20	Scan Policy .....	15
7.1.21	SPI Diagnostics Tool .....	15
7.1.22	SSL/TLS .....	15
7.1.23	TCP Socket .....	15
7.1.24	Transceiver Mode .....	15
7.1.25	UDP Socket .....	15
7.1.26	XMPP Client .....	15
7.2	SAMPLE APPLICATIONS ON MSP430F5739 EXPERIMENTER BOARD .....	15
7.2.1	Getting Started in AP Mode .....	15
7.2.2	Getting Started in STA Mode .....	15
7.3	SAMPLE APPLICATIONS ON MSP430F5529 EXPERIMENTER BOARD .....	16
7.3.1	Getting Started in AP Mode .....	16
7.3.2	Getting Started in STA Mode .....	16
7.4	SAMPLE APPLICATIONS ON TIVA C LAUNCH PAD .....	16
7.4.1	Getting Started in AP Mode .....	16
7.4.2	Getting Started in STA Mode .....	16
7.5	SAMPLE APPLICATIONS ON SLS .....	16
7.5.1	SLS Getting Started in AP Mode .....	16
7.5.2	SLS Getting Started in STA Mode .....	16
7.5.3	SLS Email .....	16
7.5.4	SLS Get Time .....	16
7.5.5	SLS Get Weather .....	17
7.5.6	SLS XMPP Client .....	17
7.5.7	SLS Transceiver Mode .....	17
7.5.8	SLS Sniffer with Filters .....	17
<b>8</b>	<b>SDK V0.5 PACKAGE CONTENTS .....</b>	<b>17</b>
<b>9</b>	<b>HOW TO START .....</b>	<b>18</b>
<b>10</b>	<b>ITEMS FIXED IN THIS RELEASE (WITH RESPECT TO VERSION 0.41) .....</b>	<b>19</b>
<b>11</b>	<b>ERRATA - KNOWN ISSUES .....</b>	<b>21</b>
11.1	WiFi .....	21
11.2	WiFi - IOP .....	22
11.3	NETWORKING .....	27
11.4	HOST .....	29
11.5	POWER MANAGEMENT .....	29
11.6	APPLICATIONS .....	30
11.7	SUPPORTED API .....	34
11.7.1	API Modified/Added/Removed comparing to former release .....	34

---

## LIST OF TABLES

TABLE 1 : RELEASE GENERAL INFORMATION .....	5
TABLE 2 : PACKAGE CONTENTS .....	18

## 1 Scope

This document describes the CC3100 Software Development Kit version 0.5 Release package. The software package is built for use with CC3100HZ PG1.32, and is targeted for FAEs and for early customer engagement and evaluation. CC31xx SW development is still in progress, and this release can be considered alpha quality. This release is recommended to be used with CC3100 Booster Pack Rev. 3.3 platforms.

Item	Explanation
Date of Release	May 15, 2014
Release Name	CC3100 SDK v0.5
Build Date	May 15, 2014
Firmware Version	2.0.7.0.31.0.0.4.2.1.5.3.3

**Table 1 : Release general information**

## 2 New Feature added on top of SDKv0.41

- UART Driver Support for MSP430F5529 LP and TIVA C LP
- P2P ( WiFiDirect)
- Antenna Selection (reference code for host MCU)
- AP provisioning
- Force AP mode
- Connection Policy (Auto SmartConfig)
- Auto Connection Policy is now enabled by default
- Power Policies (Long Sleep Interval)
- Secure file system
- WAC Ready - simple API to configure the Info Element for Provisioning.

## 3 Maturity, Limitation and Known Issues

- Host SPI interface max speed: 14MHz
- UART 4 wire up to 3Mhz
- Up to 24 hours stability in all traffic scenarios – User may rarely experience:

- Traffic Stops
  - System freeze
- Robustness tests
  - Start/Stop with Wi-Fi Connect/Disconnect and data Tx burst was tested for 5000 cycles and found to be stable
  - Wi-Fi Connect/Disconnect without data was tested for 5000 cycles and found to be stable
- SSL
  - Elliptic-curve based ciphers (e.g. ECDH) have longer connection time
  - Max throughput: 5Mbps
- Network Stack
  - TCP Window size: 16KB
  - TCP Window size is divided among all user sockets.
  - IP Fragmentation is not supported for Tx UDP and RAW sockets
  - In connection mode Tx and Rx traffic should be done after IP is acquired
- File System
  - Up to 100 user files
  - File size is not limited
- SPI Interface
  - Little Endianness is supported
  - 8/16/32bit modes are supported
  - Big Endianness auto detection is supported for SPI interface
- HTTP Server
  - Support HTTP 1.0
- WPS
  - Delay of up to 4 seconds can be seen between association and EAPOL-Start when using WPS connection
- Connection Policies
  - The profile has to be explicitly added when using 'Fast' connection-policy

### 3.1 Product Constraints

- SSL
  - Supported modes
    - Up to one Server (Listen Socket and Accept Socket) + Client (Data socket)
    - Up to Two clients (Data socket)

- 
- CA Certificates must be installed if server authentication is required
  - CA Certificate key length must be less than or equal to 2048-bit
  - SmartConfig
    - Not supported with 5GHz AP (802.11a/n/ac)
    - Not supported for MIMO-capable configuration devices
    - Only Group 0 is supported in auto start mode
  - Tx Power
    - Tx power in AP mode takes effect only after reset
  - Wi-Fi Direct
    - When the Wi-Fi Direct is set to be Group Owner (GO) the recommendation will be to set FAST connection policy to TRUE
  - Rx Filters
    - BSSID can't be filtered while STA is connected (If filtered will cause disconnection)
  - Power Management
    - The device will remain in active after initialization until the host reads all events
  - Network Stack
    - Max Tx payload for Raw packet with IP header is 1460 bytes
    - Max Tx payload for Raw Transceiver is 1488 bytes
    - Closing socket should be done in a proper way (for example not to close a socket while there is blocking receive command on it) - a timeout can be used in this scenarios
  - Supported SFLASH

The product supports JEDEC specification (called SFDP 'serial flash device parameters') – the below list contains the main SFLASH parts that have been verified.

    - Micron            N25Q128- A13BSE40 - 128Mbit
    - Spansion        S25FL208K - 8Mbit
    - Winbond        W25Q16V - 16Mbit
    - Adesto          AT25DF081A - 8Mbit
    - Macronix        MX25L12835F-M2 - 128Mbit

## 4 Release Components

The release package is wrapped in installer **CC3100\_SDK\_v0.5.exe**. The executable is a simple file extractor with click wrap license. It is available only on Windows (XP or Win-7).

Item	Version	Type
Device	CC3100GZ PG1.32	
Device Datasheet		PDF (Supplied separately)
Hardware Platform	CC3100 Booster Pack V3.3, EMUBOOST Board v3.0	HW (Supplied separately), User Guide , Schematics
Device Firmware	Version 0.5	Pre-burnt on Booster Pack and separate package with binaries and Flashing Tool
Host MCU Platform	MSP430F5529 Launch Pad, MSP430FRAM5739Experimenter Board Rev 1.1, MSP430F5529 Experimenter Board and Tiva-C Launchpad (TM4C123GH6PM)	
CC3100 Host Driver	Version 0.5	Source
IDE	IAR version 6.10 (MCU) IAR version 7.10 (ARM) CCS Version : 6.0 (MCU) MS Visual Studio 2010 (SimpleLink Studio) Eclipse 4.3.0 (SimpleLink Studio)	
Sample Applications on MSP430F5529 Launchpad		
	Antenna Selection	Source and App Note
	Connection Policies	Source and App Note
	Email	Source and App Note
	Enterprise Network Connection	Source and App Note
	File Operations	Source and App Note
	Get Time	Source and App Note
	Get Weather	Source and App Note
	Getting Started in AP Mode	Source and App Note
	Getting Started in STA Mode	Source and App Note
	HTTP Server	Source and App Note
	IP Configuration	Source and App Note



	mDNS	Source and App Note
	Mode Config	Source and App Note
	NWP Filters	Source and App Note
	NWP Power Policy	Source and App Note
	P2P	Source and App Note
	Provisioning AP	Source and App Note
	Provisioning with SmartConfig	Source and App Note
	Provisioning with WPS	Source and App Note
	Scan Policy	Source and App Note
	SPI Diagnostics Tool	Source and App Note
	SSL/TLS	Source and App Note
	TCP Socket (Tx, Rx)	Source and App Note
	Transceiver Mode	Source and App Note
	UDP Socket (Tx, Rx)	Source and App Note
	XMPP Client	Source and App Note
Sample Application on MSP430F5739 Experimenter Board		
	Getting Started in AP Mode	Source and App Note
	Getting Started in STA Mode	Source and App Note
Sample Application on MSP430F5529 Experimenter Board		
	Getting Started in AP Mode	Source and App Note
	Getting Started in STA Mode	Source and App Note
Sample Application on TIVA C Launch Pad		
	Getting Started in AP Mode	Source and App Note
	Getting Started in STA Mode	Source and App Note
Sample Applications on SimpleLink-Studio		
	Email	Source and App Note
	Get Time	Source and App Note
	Get Weather	Source and App Note
	Getting Started in AP Mode	Source and App Note
	Getting Started in STA Mode	Source and App Note
	NWP Filters	Source and App Note
	Transceiver Mode	Source and App Note
	XMPP Client	Source and App Note
Out of Box Demo	HTML Files	Source and App Note

Collaterals		
	Quick Start Guide	App Note
	CC3100 Booster Pack User Guide	App Note
Tools		
	FTDI PC driver for FTDI Emulation Board/Booster Pack	Executable and App Note (part of Quick Start Guide)
	Flash-Programmer for flashing SSL and enterprise certificates, html pages	Executable and Readme

## 5 Device Hardware

Refer to CC3100 Datasheet

## 6 Device Firmware

### 6.1 Features List

#### 6.1.1 WiFi

<b>Standards</b>	802.11bgn <b>STA</b> and WiFi Direct <b>Client</b>
<b>Supported Channels</b>	1-13
<b>Security</b>	<b>Personal:</b> WEP, mixed mode WPA2/WPA <b>Enterprise (STA):</b> EAP Fast, EAP PEAPv0 MSCHAPv2, EAP PEAPv0 TLS, EAP PEAPv1 TLS, EAP TLS, EAP TTLS TLS, EAP TTLS MSCHAPv2
<b>Ease Of Use</b>	WPS, Internal HTTP Web Server with option to modify Configuration pages and propriety tokens, Smart Config
<b>Standards</b>	802.11bg <b>AP</b> , WiFi Direct <b>GO</b>
<b>Supported connections (STAs)</b>	1
<b>Supported</b>	1-11

<b>Channels</b>	
<b>Security</b>	<b>Personal (AP and GO) :</b> WEP, WPA1 and WPA2
<b>Ease Of Use</b>	HTTP Web Server, Configurable IE for WAC Provisioning, AP for configurations

### 6.1.2 Networking

<b>IP protocol</b>	IPv4
<b>Transport</b>	UDP, TCP, RAW , ICMP
<b>Cross-Layer Protocols</b>	DHCP, ARP, DNS
<b>Security</b>	SSL3.0 and TLS1.2 – TLS and SSL RSA with RC4 128 SHA1 TLS ECDHE RSA with RC4 128 SHA1 TLS ECDHE RSA with AES 256 CBC SHA1 TLS DHE RSA with AES 256 CBC SHA1 TLS RSA with AES 256 CBC SHA1 SSL RSA with RC4 128 MD5
<b>Sockets</b>	Up to total of 8 sockets (external sockets) Up to 2 secured sockets
<b>Embedded Applications</b>	mDNS, DNS-SD and HTTP Web Server

### 6.1.3 Advanced Features

<b>802.11 Transceiver</b>	Transmit and Receive raw WiFi packets with full control over payload. WiFi disconnect mode.  Can be used for general-purpose applications (e.g. tags, sniffer, RF tests)
<b>Traffic Filters</b>	Embedded filters to preserve power consumption and Wake-on-LAN trigger packets (IP and MAC layer)

### 6.1.4 Interfaces

<b>SPI</b>	Standard SPI up to 14MHz
<b>UART</b>	4 wire UART up to 3MHz

### 6.1.5 Power Modes

<b>Low Power mode</b>	802.11 Power Save and deep sleep power mode
<b>Available modes</b>	<ul style="list-style-type: none"> <li>• <u>Normal (Default)</u> - Best tradeoff between traffic delivery time and power performance</li> <li>• <u>Low power</u> – Device power management algorithm is more opportunistic exploiting opportunities to lower its power mode – Should be used only for Transceiver mode application (Disconnect mode)</li> <li>• <u>Long Sleep Interval</u> – wakes up for the next DTIM, this policy will only work in client mode</li> </ul>

## 7 Sample applications

The release package includes several sample applications, ported to the MSP430FF5529 Launchpad Board. Each of these applications is supported with:

- Detailed Application Notes explaining the functionality and how to use it
- Project file for IDE (IAR, CCS )
- Smartphone Android application as needed

### 7.1 Sample applications on MSP430F5529 Launchpad

#### 7.1.1 Antenna Selection

This is a reference application demonstrating how 'antenna-selection' feature can be implemented on Host-MCU. CC3100, internally, doesn't support this feature

#### 7.1.2 Connection Policies

Profiles are designed to allow connection to pre-defined stored Access Points (APs). The connection policy allows automatic and fast connection by controlling how the SimpleLink device attempts to connect to an AP. The sample applications demonstrate the usage of CC3100's profiles and connection-policies.

---

### 7.1.3 Email

The email application on the MSP430+CC3100 sends emails via SMTP. The email application sends a preconfigured email at the push of a button or a user-configured email through the CLI.

### 7.1.4 Enterprise Network Connection

This example demonstrates the procedure to connect CC3100 to enterprise networks.

### 7.1.5 File Operations

This is an application demonstrating the use of file operation APIs.

### 7.1.6 Get Time

The application connects to an SNTP server and requests time information.

### 7.1.7 Get Weather

The application connects to 'Open Weather Map' and requests weather data

### 7.1.8 Getting Started in AP Mode

The application configures the CC3100 in AP mode. It verifies the connection by pinging the client that gets connected to it.

### 7.1.9 Getting Started in STA Mode

The application configures the CC3100 in STA mode. It verifies the connection by pinging the client that gets connected.

### 7.1.10 HTTP Server

This examples demonstrates how to use the internal (running inside NWP) HTTP Server interface APIs to enable the static and dynamic content on web page.

#### **7.1.11 IP Configuration**

This example demonstrates how to enable static IP configuration instead of using DHCP.

#### **7.1.12 MDNS**

This example registers the service for broadcasting and attempts to get the service by the name broadcasted by another device.

#### **7.1.13 Mode Config**

The application demonstrates the switching of CC3100's operation mode from STA to AP and vice-versa.

#### **7.1.14 NWP Filters**

The Rx-Filters feature enables the user to simply define and manage the Rx-filtering process. This is in order to reduce the amount of traffic transferred to the host, and to achieve efficient power management. The application demonstrates management of the Rx-filtering process.

#### **7.1.15 NWP Power Policy**

The power policies enable the user to reduce the current consumption based on the use case in the station mode. The application shows how to enable different power policy.

#### **7.1.16 P2P (WiFiDirect)**

This application configures the device in P2P/ WiFiDirect mode and demonstrates how to communicate with the remote P2P device.

#### **7.1.17 Provisioning AP**

This application with html pages demonstrates the use of internal http server for Wi-Fi provisioning in AP Mode.

#### **7.1.18 Provisioning with SmartConfig**

The application demonstrates the usage of TI's SmartConfig™ Wi-Fi provisioning technique.

#### **7.1.19 Provisioning with WPS**

The application demonstrates the usage of WPS Wi-Fi provisioning with CC31xx.

---

### **7.1.20 Scan Policy**

The application demonstrates the scan-policy settings in CC3100.

### **7.1.21 SPI Diagnostics Tool**

This is a diagnostics application for checking the SPI configuration.

### **7.1.22 SSL/TLS**

SSL certificates are designed to provide two principles: privacy and authentication. Privacy is achieved by encryption/decryption and authentication is achieved by signature/verification. The application demonstrates the usage of certificates with SSL.

### **7.1.23 TCP Socket**

The application demonstrates the connection scenario and basic TCP functionality.

### **7.1.24 Transceiver Mode**

The application demonstrates the CC3100's transceiver mode of operation.

### **7.1.25 UDP Socket**

The application demonstrates the connection scenario and basic UDP functionality.

### **7.1.26 XMPP Client**

The application demonstrates the connection scenario with an XMPP server.

## **7.2 Sample applications on MSP430F5739 Experimenter Board**

### **7.2.1 Getting Started in AP Mode**

The application configures the CC3100 in AP mode. It verifies the connection by pinging the client that gets connected to it.

### **7.2.2 Getting Started in STA Mode**

The application configures the CC3100 in STA mode. It verifies the connection by pinging the client that gets connected

---

## 7.3 Sample applications on MSP430F5529 Experimenter Board

### 7.3.1 Getting Started in AP Mode

The application configures the CC3100 in AP mode. It verifies the connection by pinging the client that gets connected to it.

### 7.3.2 Getting Started in STA Mode

The application configures the CC3100 in STA mode. It verifies the connection by pinging the client that gets connected

## 7.4 Sample applications on TIVA C Launch Pad

### 7.4.1 Getting Started in AP Mode

The application configures the CC3100 in AP mode. It verifies the connection by pinging the client that gets connected to it.

### 7.4.2 Getting Started in STA Mode

The application configures the CC3100 in STA mode. It verifies the connection by pinging the client that gets connected

## 7.5 Sample applications on SLS

### 7.5.1 SLS Getting Started in AP Mode

The application configures the CC3100 in AP mode. It verifies the connection by pinging the client that gets connected to it.

### 7.5.2 SLS Getting Started in STA Mode

The application configures the CC3100 in STA mode. It verifies the connection by pinging the AP that gets connected

### 7.5.3 SLS Email

The email application on the MSP430+CC3100 sends emails via SMTP. The email application sends a preconfigured email.

### 7.5.4 SLS Get Time

The application connects to an SNTP server and requests time information.



### 7.5.5 SLS Get Weather

The application connects to 'Open Weather Map' and requests weather data

### 7.5.6 SLS XMPP Client

The application demonstrates the connection scenario with an XMPP server.

### 7.5.7 SLS Transceiver Mode

The application demonstrates the CC3100's transceiver mode of operation.

### 7.5.8 SLS Sniffer with Filters

The Rx-Filters feature enables the user to simply define and manage the Rx-filtering process. This is in order to reduce the amount of traffic transferred to the host, and to achieve efficient power management. The application demonstrates management of the Rx-filtering process.

## 8 SDK v0.5 Package Contents

Double-Click on the package to copy the directories (and files) to the preferred location. The first level directory structure is as shown in the table below.

Directory Name	Information
<b>Docs</b>	<ul style="list-style-type: none"> <li>Quick Start Guide with instructions on setting up the platform and executing sample application(s)</li> <li>User Guide with details on 'CC3100 Booster Pack' and it's interfacing with MCU Launch Pad, EMUBOOST Board, schematics and placement diagram</li> <li>Application notes for applications</li> </ul>
<b>Examples</b>	Each application has app notes under <cc3100_sdk>/docs.
<b>Platform</b>	<ul style="list-style-type: none"> <li>Contains all the supported platforms in SDK v0.5 <ul style="list-style-type: none"> <li>MSP430FR55529lp <ul style="list-style-type: none"> <li>Contains CCS projects for all the sample applications that are supported on this platform</li> <li>Contains IAR projects for 'getting_started_with_wlan_station' and 'getting_started_with_AP'</li> <li>Contains all the required drivers</li> <li>Contains 'user.h' (Details in the abstract @</li> </ul> </li> </ul> </li> </ul>

	<p>&lt;cc3100_sdk&gt;/simplelink</p> <ul style="list-style-type: none"> <li>○ MSP430FR5529, TM4C123GH6PM, MSP430FR5739 <ul style="list-style-type: none"> <li>▪ Contains IAR and CCS projects for 'getting_started_with_wlan_station' and 'getting_started_with_AP' application</li> <li>▪ Contains all the required drivers</li> <li>▪ Contains 'user.h' (Details in the abstract @ &lt;cc3100_sdk&gt;/simplelink</li> </ul> </li> <li>○ simplelinkstudio: <ul style="list-style-type: none"> <li>▪ Contains Visual-Studio and Eclipse projects for the sample applications that are supported on this platform</li> <li>▪ Contains 'user.h' (Details in the abstract @ &lt;cc3100_sdk&gt;/simplelink</li> </ul> </li> </ul>
<b>SimpleLink</b>	<ul style="list-style-type: none"> <li>• Contains 'SimpleLink Host Driver' code.</li> <li>• The package contains a template 'template_user.h' file which should be filled by the user for his specific application and platform.</li> </ul>
<b>Tools</b>	<ul style="list-style-type: none"> <li>• <b>cc31xx_board_drivers:</b> Drivers to be installed on Host-PC</li> <li>• <b>sl_progammer_command_line:</b> Flash Programmer with additional support for flashing certificates</li> </ul>

Table 2 : Package Contents

## 9 How to Start

- Get the hardware platform from your TI representative.
- Follow the Quick Start User Guide to make your very first connection to your Access Point using the CC3100 (WLAN router).

## 10 Items Fixed in this release (with respect to version 0.41)

<b>ID</b>	MCS00127993
<b>Title</b>	Filtering: System Stuck when filtering control, management or Data packets during traffic

<b>ID</b>	MCS00128669
<b>Title</b>	Rx Filtering: 'Destination MAC' in RX filter doesn't work with RX statistics in transceiver mode
<b>Description</b>	When trying to filter only specific device MAC address, RX statistics shows valid packets counter increasing although nothing is transmitted to the device.

<b>ID</b>	MCS00128697
<b>Title</b>	Regulatory domain: Connection is established on channel 13 even though the regulatory domain is "US"

<b>ID</b>	MCS00127697
<b>Title</b>	STA connects to the first AP found and not to the AP with strongest RSSI

<b>ID</b>	MCS00128718
<b>Title</b>	Application Scan is not initiated while the device is already scanning for connection

<b>ID</b>	MCS00127455
<b>Title</b>	System might get stuck while running TCP Tx with low TP after a few hours

<b>ID</b>	MCS00128592
<b>Title</b>	IOP: Can't initiate Rx Traffic with Netgear WNR3500v1. due to unacknowledged Action from the AP
<b>Description</b>	AP doesn't respond to all 11b packet from the STA AP doesn't respect 802.11 Power Save at all times

<b>ID</b>	MCS00128708
<b>Title</b>	IOP: Proxim Orinoco AP-4000. SL device initiate DHCP session only for the first initiated connection
<b>Description</b>	When the AP is configured to WPA2-AES DHCP request from STA are working only for the first time

<b>ID</b>	MCS00128699
<b>Title</b>	IOP: Buffalo WHR-HP-GN. UDP Rx throughput is not stable
<b>Description</b>	The AP is not respecting 802.11 power save at all times which make the situation worse

<b>ID</b>	MCS00128887
<b>Title</b>	WPS: The device is not connected automatically after reset is secure AP is used
<b>Description</b>	After connecting with WPS the security part is not stored in NVMEM profiles correctly

<b>ID</b>	MCS00128928
<b>Title</b>	WPS Certifications: test 5.1.1: Serial number attribute in M1 message is empty
<b>Description</b>	Serial number in M1 Eapol is empty

<b>ID</b>	MCS00128939
<b>Title</b>	WPS Certifications: test 5.1.1: Serial number attribute in M1 message is empty
<b>Description</b>	Serial number in M1 Eapol is empty

<b>ID</b>	MCS00128546
<b>Title</b>	On TCP Tx retry packet all packet is been Retransmitted
<b>Description</b>	Receiver is sending an ACK only on part of the Tx packet but the Simple Link device is retransmitting the entire packet

<b>ID</b>	MCS00128613
<b>Title</b>	SL does not send reply when received request includes Options fields in IP Header

<b>ID</b>	MCS00128363
<b>Title</b>	Closing TCP Tx Socket can return immediately with success - in some cases not all packet will be transmitted (usually because of an Error)

<b>ID</b>	MCS00127547
<b>Title</b>	Delayed response when using BSD non polling commands (e.g. accept/recv) with high speed platform in NonOS
<b>Description</b>	Polling the non-Blocking commands in high speed is delaying the response due to system overload

<b>ID</b>	MCS00128656
<b>Title</b>	HTTP Server: It takes ~55 seconds for the internal web page to load in Nexus7 tablet with Chrome browser
<b>Description</b>	The Chrome browser seems to have issue with .net postfix

<b>ID</b>	MCS00128704
<b>Title</b>	mDNS : SimpleLink fail to move all field to new name service after unique check process
<b>Description</b>	After registering a new service only SRV and PTR move to new name service TXT left on old name service

<b>ID</b>	MCS00128904
<b>Title</b>	HTTP Server: In POST requests the 9 <sup>th</sup> character of the token is converted to ' '

## 11 Errata - Known Issues

### 11.1 WiFi

<b>ID</b>	MCS00123349
<b>Title</b>	Wi-Fi Security: CC31xx Supports only WEP with Key Index 0 (==> AP Key index 1)
<b>Description</b>	When using WEP security – only WEP index 0 is supported
<b>Impact</b>	Can't use more than one key in WEP security
<b>Workaround</b>	None
<b>Fix Expected</b>	TBD

<b>ID</b>	MCS00106970
<b>Title</b>	Wi-Fi Security: Traffic Stop while WPA EAP-TLS Enterprise and Reauthentication enabled
<b>Description</b>	In WPA EAP-TLS security the traffic stopped when Reauthentication packet is received
<b>Impact</b>	Traffic stopped
<b>Workaround</b>	Disabled Reauthentication or set it to a very long time
<b>Fix Expected</b>	TBD

<b>ID</b>	MCS00130040
-----------	-------------

<b>Title</b>	Wi-Fi Direct Reliability: 65% Success rate when Peer device is initiator of connection
<b>Description</b>	Negotiation with other peer not always successful at first chance
<b>Impact</b>	The first connection doesn't success
<b>Workaround</b>	Try to connect again
<b>Fix Expected</b>	Next Revision

<b>ID</b>	MCS00130160
<b>Title</b>	Scan: Can't invoke Scan while connection is in progress
<b>Description</b>	While trying to connect using connect command or profiles invoking an explicitly Scan the connection doesn't success
<b>Impact</b>	Connection might not succeed
<b>Workaround</b>	Avoid calling scan during connection
<b>Fix Expected</b>	Next Revision

## 11.2 WiFi - IOP

<b>ID</b>	MCS00128381
<b>Title</b>	IOP: D-Link DWL 8600 AP - STA stops receiving Multicast traffic when WPA2 and key rotation are configured
<b>Description</b>	The AP is too busy transmitting the multicast frames, and tries to initiate the 2-way hand shake of the broadcast key rotation while SUT is in power save
<b>Impact</b>	The STA Stop receiving multicast traffic
<b>Workaround</b>	Disable Key Rotation in the AP
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00128441
<b>Title</b>	IOP: Can't acquire DHCP IP address with 3COM WL-450 if security is configured to WPA2-AES
<b>Impact</b>	No IP address
<b>Workaround</b>	Configure the IP to static or disable security
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00128156
<b>Title</b>	IOP: Connection to PCI MZK-MF300N doesn't complete when AP is configured to - Channel Width 40Mhz
<b>Impact</b>	No connection
<b>Workaround</b>	Configure the Channel Width to 20Mhz
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00130071
<b>Title</b>	IOP: Connection to Belkin F7D2301 v1 doesn't complete when AP is configured to - Channel Width 40Mhz
<b>Impact</b>	No connection
<b>Workaround</b>	Configure the Channel Width to 20Mhz
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00128440
<b>Title</b>	IOP: D-Link DAP-2690. Low and unstable TCP Rx traffic due to AP not respecting 802.11 power save
<b>Impact</b>	Unstable traffic
<b>Workaround</b>	None
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00126520
<b>Title</b>	IOP: AP initiates deauth to the SL After ~5 Min of UDP Tx, when Remote PC is configured to 10M Full Duplex link speed
<b>Description</b>	Only in this network card configuration the AP sends deauth during the traffic
<b>Impact</b>	AP disconnected the STA during the UDP traffic
<b>Workaround</b>	Change the configuration of the network drive to Auto mode
<b>Fix Expected</b>	Not Expected due to Network card definition

<b>ID</b>	MCS00128462
<b>Title</b>	IOP: Linksys WAP55AG AP Is not compliant to 802.11 Power Save spec when configured to WAP2-AES
<b>Impact</b>	No Connection
<b>Workaround</b>	Disable security
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00128725
<b>Title</b>	IOP: TRENDnet TEW-671BR – SL device doesn't respond to AP's frames at 11b rates
<b>Impact</b>	Can't establish stable connection with the AP
<b>Workaround</b>	N/A
<b>Fix Expected</b>	TBD

<b>ID</b>	MCS00128719
<b>Title</b>	IOP: TP-Link TD-W89841Nv4 AP. Is not compliant to 802.11 PS spec. Never asserts the Group bit in TIM IE
<b>Description</b>	AP never advertises the Group bit inside the TIM IE before and after transmitting of the ARP Request (broadcast packet) AP version: FW: 0.8.0 10.1 v0003.0 Build 121227 Rel.65166s
<b>Impact</b>	Can't Initiate Rx traffic
<b>Workaround</b>	Send Ping from the device to the AP after the connection
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00128717
<b>Title</b>	IOP: Siemens Gigaset 01. Is not compliant to 802.11 PS spec. Never asserts the Group bit in TIM IE
<b>Description</b>	AP never advertises the Group bit inside the TIM IE before and after transmitting of the ARP Request (broadcast packet) AP version: FW: v1.0.0.1
<b>Impact</b>	Can't Initiate Rx traffic
<b>Workaround</b>	Send Ping from the device to the AP after the connection
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00128462
<b>Title</b>	IOP: Linksys WAP55AG AP Is not compliant to 802.11 Power Save spec when configured to WAP2-AES
<b>Description</b>	AP doesn't Ack ARP response packets coming from the device when AES is enabled
<b>Impact</b>	Can't acquire IP when DHCP is enabled
<b>Workaround</b>	Disable AP security
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00128703
<b>Title</b>	IOP: PCI MZK-MF300N AP. Is not compliant to 802.11 Power Save spec
<b>Description</b>	AP advertises the Group bit inside the TIM IE after transmitting of the ARP Request. SL device can't receive the packet AP version: FW: v1.00.05_B4
<b>Impact</b>	Can't Initiate Rx traffic
<b>Workaround</b>	Send Ping from the device to the AP after the connection
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00128701
-----------	-------------



<b>Title</b>	IOP: I-O Data WN-G54/R4. Is not compliant to 802.11 Power Save spec
<b>Description</b>	AP advertises the Group bit inside the TIM IE after transmitting of the ARP Request. SL device can't receive the packet
<b>Impact</b>	Can't Initiate Rx traffic
<b>Workaround</b>	Send Ping from the device to the AP after the connection
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00128693
<b>Title</b>	IOP: Netgear WNDAP350. Is not compliant to 802.11 Power Save spec
<b>Description</b>	AP advertises the Group bit inside the TIM IE after transmitting of the ARP Request. SL device can't receive the packet
<b>Impact</b>	Can't Initiate Rx traffic
<b>Workaround</b>	Send Ping from the device to the AP after the connection
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00128607
<b>Title</b>	IOP: Netgear B90-7550. Is not compliant to 802.11 Power Save spec
<b>Description</b>	AP advertises the Group bit inside the TIM IE after transmitting of the ARP Request. SL device can't receive the packet
<b>Impact</b>	Can't Initiate Rx traffic
<b>Workaround</b>	Send Ping from the device to the AP after the connection
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00128606
<b>Title</b>	IOP: Belkin F7D5301v3. Is not compliant to 802.11 Power Save spec
<b>Description</b>	AP advertises the Group bit inside the TIM IE after transmitting of the ARP Request. SL device can't receive the packet
<b>Impact</b>	Can't Initiate Rx traffic
<b>Workaround</b>	Send Ping from the device to the AP after the connection
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00128367
<b>Title</b>	IOP: AP - STA Linksys AE1000 send NULL data with different sequence number
<b>Description</b>	When Linksys AE1000 dongle is connected to APUT, it sends NULL data

	with different sequence number than regular data. this yield to duplicated packet in the AP Rx side
<b>Impact</b>	Duplicated packet in AP Rx (mostly impact UDP)
<b>Workaround</b>	Disable AP security
<b>Fix Expected</b>	Not Expected due to STA behavior

<b>ID</b>	MCS00128672
<b>Title</b>	IOP: DLink DIR825 B1. UDP Rx Traffic is not Stable - AP stop transmitting Beacons after traffic starts
<b>Description</b>	At some point, AP stop transmitting Beacons, but does transmit data packets and RTS.
<b>Impact</b>	Traffic performance is not stable
<b>Workaround</b>	N/A
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00129371
<b>Title</b>	IOP: Netgear3700v1 AP - TCP Tx traffic doesn't Always start between two STA devices
<b>Description</b>	The AP doesn't always forward the ARP Req if the STA was connect and disconnect for it number of times
<b>Impact</b>	Traffic doesn't start
<b>Workaround</b>	The AP is stuck – need to restart
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00130102
<b>Title</b>	IOP: DLink-615 With Security doesn't allow STA to fast reconnect
<b>Description</b>	The AP doesn't allow fast reconnect without a formal de-authentication or long time out
<b>Impact</b>	Initial connection failed immediately upon reset Successful connection was established soon after
<b>Workaround</b>	Using the Fast and Auto Policy will insure the 2 <sup>nd</sup> connection will work In Manual connection Disconnect before connect command solves the problem
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00130098
<b>Title</b>	IOP: WiFi Direct - Failure to connect as client to Galaxy S2
<b>Description</b>	With old versions of Galaxy S2 WiFi Direct – SimpleLink in client mode is not able to connect
<b>Impact</b>	Connection is not possible
<b>Workaround</b>	Switch the WiFi Direct policy to GO and enable Fast

<b>Fix Expected</b>	Not Expected due to WiFi Direct behavior
---------------------	--

<b>ID</b>	MCS00129417
<b>Title</b>	IOP: Intellinet Wireless 3G Router. Is not compliant to 802.11 Power Save spec.
<b>Description</b>	AP advertises PVB wrongly before Action frame
<b>Impact</b>	In some cases can't Initiate Rx traffic
<b>Workaround</b>	Send Ping from the device to the AP after the connection
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00130025
<b>Title</b>	IOP: WiFi Direct - Re-Connection after SL device is client with Zopo device is unsuccessful
<b>Description</b>	Trying to disconnect and reconnect to a Zopo device is not successful if the SL device was a client
<b>Impact</b>	Re-Connection is not possible
<b>Workaround</b>	Switch the WiFi Direct policy to GO and enable Fast
<b>Fix Expected</b>	Not Expected

<b>ID</b>	MCS00129759
<b>Title</b>	IOP: WPS - SL can't establish a WPS connection to the Actiontec PK5000 AP
<b>Description</b>	The AP is not excepting the WPS2.0 extension and refuse the connection
<b>Impact</b>	Can't connect with WPS
<b>Workaround</b>	Use other provisioning methods
<b>Fix Expected</b>	Not Expected (pending on SW upgrade to the AP)

### 11.3 Networking

<b>ID</b>	MCS00127876
<b>Title</b>	sl_NetAppDnsGetHostByName return with no answer in high traffic
<b>Description</b>	In high Rx traffic some DNS packets can get lost
<b>Impact</b>	No answer on request
<b>Workaround</b>	Run the API again
<b>Fix Expected</b>	TBD

<b>ID</b>	MCS00128353
<b>Title</b>	UDP/RAW socket data payload is limited to MTU size

<b>Description</b>	Tx IP Fragmentation is not supported for UDP and RAW Tx
<b>Impact</b>	Packet bigger than MTU size will lead that portion of the packet will be discard
<b>Workaround</b>	Use packet size <= MTU size
<b>Fix Expected</b>	TBD

<b>ID</b>	MCS00128580
<b>Title</b>	IOP: Microsoft MN-700 AP. Low Throughput Performance
<b>Description</b>	Throughput performance is low comparing to average throughout with other AP. The issue was also observed with other STA as well
<b>Impact</b>	Low Throughput Performance
<b>Workaround</b>	N/A
<b>Fix Expected</b>	Not Expected due to AP behavior

<b>ID</b>	MCS00128429
<b>Title</b>	IOP: Buffalo WZR-G300N AP. Low Rx Throughput Performance
<b>Description</b>	Rx throughput performance is lower comparing to average throughout with other AP
<b>Impact</b>	Low Throughput Performance
<b>Workaround</b>	N/A
<b>Fix Expected</b>	Not Expected due to AP behavior with aggregated packet in Rx

<b>ID</b>	MCS00119806
<b>Title</b>	IOP: Linksys WRT54gx v2 AP. Fails to obtain IP from DHCP server when operating with WPA2-PSK AES only privacy
<b>Description</b>	AP answers with a packet that is suspected as DHCP Offer, but this packet has MIC failure when decrypted, so the DHCP process is stuck
<b>Impact</b>	Connection is not feasible with WPA2-PSK AES and DHCP
<b>Workaround</b>	Use different security or disable DHCP
<b>Fix Expected</b>	Not Expected due to AP behavior during WPA2-PSK AES

<b>ID</b>	MCS00128959
<b>Title</b>	DHCP: SL continues using its previous IP address if an invalid IP in the DHCPACK (before lease time expired)
<b>Description</b>	DHCPACK arrives to SL with invalid address in the DHCPACK params address field but also the IP destination is the same invalid address (MAC address is the valid SL address). SL does not listen to other IPs address as destination but his own therefore this DHCPACK is not processed and SL continue to use his old address until the lease time expires
<b>Impact</b>	The device will continue to use the previous IP address

<b>Workaround</b>	N/A
<b>Fix Expected</b>	Not expected

<b>ID</b>	MCS00129407
<b>Title</b>	NS: SL device should discard datagram with problem in IP Header
<b>Description</b>	If the gateway or host processing a datagram finds a problem with the header parameters such that it cannot complete processing the datagram it must discard the datagram
<b>Impact</b>	Low impact – The SL device sends ICMP reply message
<b>Workaround</b>	N/A
<b>Fix Expected</b>	TBD

## 11.4 Host

<b>ID</b>	MCS00127283
<b>Title</b>	Free RTOS OS is not stable when running UDP traffic and Ping
<b>Description</b>	Known issue with free RTOS that can cause deadlock
<b>Impact</b>	Deadlock in OS
<b>Workaround</b>	Use TI RTOS
<b>Fix Expected</b>	TBD

<b>ID</b>	MCS00130291
<b>Title</b>	WPS PIN Connect might fail if pin code is not null-terminated
<b>Description</b>	If the PIN code from the HOST is not null terminated the string can be wrongly used and in some cases the connection doesn't succeed
<b>Impact</b>	Connection doesn't succeed
<b>Workaround</b>	Add null termination to the PIN code string
<b>Fix Expected</b>	TBD

## 11.5 Power Management

<b>ID</b>	MCS00128947
<b>Title</b>	In Enterprise network the device will Frequently Wakeup due to IPV4 BRDCST Rx frames
<b>Description</b>	On enterprise network there a lot of BRDCST packets
<b>Impact</b>	Increase in power consumption

<b>Workaround</b>	Add a filter to block the broadcast packets (will be different for each enterprise network)
<b>Fix Expected</b>	Not expected – the filter is specific to the network

## 11.6 Applications

<b>ID</b>	MCS00128652
<b>Title</b>	HTTP Server: When entering the internal web page with Huawei phone, GUI is zoomed in
<b>Impact</b>	Web page displayed incorrectly
<b>Workaround</b>	N/A
<b>Fix Expected</b>	TBD

<b>ID</b>	MCS00128658
<b>Title</b>	HTTP Server: GUI is only displayed correctly after refresh in Nexus one phone
<b>Impact</b>	Web page displayed incorrectly
<b>Workaround</b>	N/A
<b>Fix Expected</b>	TBD

<b>ID</b>	MCS00128130
<b>Title</b>	HTTP Server: With In Dolphin web application cursor is sometimes seen on two rows simultaneously
<b>Impact</b>	Double cursor
<b>Workaround</b>	N/A
<b>Fix Expected</b>	TBD

<b>ID</b>	MCS00128425
<b>Title</b>	HTTP Server: Default Galaxy Tablet browser shows wrong authentication GUI
<b>Impact</b>	Wrong GUI is displayed
<b>Workaround</b>	Use different browser or disable authentication option
<b>Fix Expected</b>	TBD

<b>ID</b>	MCS00129384
<b>Title</b>	HTTP Server: GUI - In IE7 browser, GUI boarder is truncated
<b>Impact</b>	Web page displayed incorrectly
<b>Workaround</b>	Use different browser

---

<b>Fix Expected</b>	Not Expected due to browser issue
<b>ID</b>	MCS00129385
<b>Title</b>	HTTP Server: On some mobile devices, "Wi-Fi Connectivity" & "Profile Settings" are seen in two lines
<b>Impact</b>	Web page displayed incorrectly
<b>Workaround</b>	Use different browser
<b>Fix Expected</b>	Not Expected due to browser issue

<b>ID</b>	MCS00129390
<b>Title</b>	HTTP Server: On some mobile devices "some parameters were changed, System may require reset" is seen in two lines
<b>Impact</b>	Web page displayed incorrectly
<b>Workaround</b>	Use different browser
<b>Fix Expected</b>	Not Expected due to browser issue

<b>ID</b>	MCS00129392
<b>Title</b>	HTTP Server: On some mobile devices all tabs are merged together in browser
<b>Impact</b>	Web page displayed incorrectly
<b>Workaround</b>	Use different browser
<b>Fix Expected</b>	Not Expected due to browser issue

<b>ID</b>	MCS00129393, MCS00129394, MCS00129397, MCS00129399, MCS00129401
<b>Title</b>	HTTP Server: On some mobile devices lines and tabs are displayed incorrectly
<b>Impact</b>	Web page displayed incorrectly
<b>Workaround</b>	Use different browser
<b>Fix Expected</b>	Not Expected due to browser issue

<b>ID</b>	MCS00130155
<b>Title</b>	HTTP Server: Can't configure the Default Gateway from the HTTP Server pages (with default tokens)
<b>Impact</b>	When working with default HTTP server pages, only default gateway can be used (192.168.1.xxx)
<b>Workaround</b>	Add proprietary token to modify the default Gateway for user pages
<b>Fix Expected</b>	Next Revision

<b>ID</b>	MCS00130240
<b>Title</b>	DNS Server: In AP mode the internal DNS Server can't be disabled
<b>Impact</b>	Can't disabled the internal DNS server – can't use external DNS server in AP mode
<b>Workaround</b>	N/A
<b>Fix Expected</b>	TBD

<b>ID</b>	MCS00130241
<b>Title</b>	HTTP Server: 'AnyP2P' and 'Auto smart config' policies can be changed only in station or P2P mode



---

<b>Impact</b>	Can't change these specific configurations from the HTTP server in AP mode
<b>Workaround</b>	Change the configurations in STA mode
<b>Fix Expected</b>	TBD

## 11.7 Supported API

All the APIs are documented with the new SimpleLink Host Driver HTML Programmer's Guide.

### 11.7.1 API Modified/Added/Removed comparing to former release

API	Silo	Status
sl_DeviceSet	Device	Changed to sl_DevSet
sl_DeviceGet	Device	Changed to sl_DevGet
sl_Start	Device	Added const to pDevname
sl_UartSetMode	Device	New API
sl_NetAppGetServiceList	NetApp	New API
sl_WlanProfileGet	Wlan	Changed prototype
sl_WlanCfgSet	Wlan	Changed to Sl_WlanSet
sl_WlanCfgGet	Wlan	Changed to Sl_WlanGet
MACROS	All	Removed

File name change: nvmmem.c, nvmmem.h are now fs.h,fs.c