

USB7002/USB7006/USB7016/USB7052N Silicon Errata

This document describes known silicon errata for the USB7002/USB7006/USB7016/USB7052N devices. The silicon errata discussed in this document are for silicon revisions as listed in [Table 1](#). A summary of USB70xx silicon errata is provided in [Table 2](#).

TABLE 1: AFFECTED SILICON REVISIONS

Part Numbers	Silicon Revision
USB7002, USB7006, USB7016, USB7052N	B0

TABLE 2: SILICON ISSUE SUMMARY

Item Number	Silicon Issue Summary
1.	Ganged port power control mode limitations
2.	Incompatibility issue with SST25 series SPI flash devices
3.	Undefined SMBus OTP access commands execute an OTP read
4.	Unsupported 'Set Interface' command does not issue a STALL response
5.	Suspend Current Consumption delta between SPI FW execution and ROM FW execution
6.	VCONN overcurrent loops infinite retries while in DCP mode
7.	Invalid memory region access is not blocked
8.	Force DCP feature overcurrent bug
9.	Multi-Host Endpoint Reflector cannot be used on downstream ports 5 and 6

Silicon Errata Issues

Module 1: Ganged port power control mode limitations

DESCRIPTION

'Ganged mode' port power control is not recommended when using Type-C ports, as Type-C ports require individual VBUS enable controls to operate in a fully compliant way. The hub should only be configured for 'ganged mode' operation if all of the downstream ports are re-configured for legacy Type-A operation via the PORT_CFG_SEL register.

END USER IMPLICATIONS

None. Ganged port power control mode should not be used if any downstream ports are configured as Type-C ports.

Work Around

None.

PLAN

There is no plan to address this item.

USB70xx

Module 2: Incompatibility issue with SST25 series SPI flash devices

DESCRIPTION

The Hub ROM firmware fails to retrieve the JEDEC ID for SST25 series SPI Flash when hub has booted and is executing the firmware from the SPI Flash device. The resulting issue is that attempts to program the pseudo-OTP memory space within the SPI flash device will fail. It is possible to program the pseudo OTP when running from ROM

END USER IMPLICATIONS

Updating the pseudo-OTP memory will not work in the standard way when running and external firmware image from an SST25 series SPI flash.

Work Around

If running the firmware image from an external SST25 series SPI Flash device, and it is required to update the pseudo-OTP, the hub must be forced to reset and boot from internal ROM firmware image first. The pseudo OTP of the SPI Flash can then be updated while the hub is running from internal ROM firmware.

PLAN

There is no plan to address this item.

Module 3: Undefined SMBus OTP access commands execute an OTP read

DESCRIPTION

The OTP Read via SMBus command is 0x07. Commands 0x0A - 0xFF are undefined commands, but operate as OTP Read if issued.

END USER IMPLICATIONS

If undefined SMBus OTP commands 0x0A to 0xFF are issued, then an OTP Read will occur. This should have no negative impact on any applications.

Work Around

None.

PLAN

There is no plan to address this item.

Module 4: Unsupported 'Set Interface' command does not issue a STALL response

DESCRIPTION

When configuring an unsupported firmware interface & alternate setting combination through a SET_INTERFACE command from host to the hub's internal Hub Feature Controller device (UDC0), the Hub Feature Controller will not issue a STALL response.

END USER IMPLICATIONS

None. The end user should never issue unsupported SET_INTERFACE commands.

Work Around

None.

PLAN

There is no plan to address this item.

Module 5: Suspend Current Consumption delta between SPI FW execution and ROM FW execution

DESCRIPTION

Suspend current of the hub is typically 16mA when running from internal ROM firmware, and 11.8mA when running from external SPI firmware.

END USER IMPLICATIONS

While power consumption of the hub IC while in suspend is higher when running from internal ROM firmware image than with an external SPI firmware image, the total system power consumption may still lower when executing from internal ROM firmware image because this figure does not take into account the amount of power required to power a SPI Flash device.

Work Around

None.

PLAN

There is no plan to address this item.

Module 6: VCONN overcurrent loops infinite retries while in DCP mode

DESCRIPTION

When a USB port has battery charging enabled, and the port is in the DCP state (no USB host is present), a persistent fault on the VCONN supply will retry endlessly.

For comparison, if a persistent fault has been detected on VBUS while in the DCP state, the hub will latch off VBUS after several consecutive failed retries.

END USER IMPLICATIONS

A consumer with a defective electronically marked cable may observe constant toggling of power to the attached device. This may result in rapid appearance and disappearance of a charging icon or indicator on an attached device.

Work Around

Use the latest firmware version executed externally from a connected SPI Flash memory.

PLAN

This issue has been fixed in an updated firmware release. The latest firmware release may be loaded to an external SPI flash device and executed by the hub. There is no plan to update the hub ROM firmware image at this time.

Module 7: Invalid memory region access is not blocked

DESCRIPTION

The hub firmware does not prevent access for the invalid memory region 0xBF90_0000 - 0xBF90_2FFF. Attempting to access this memory region will result in a firmware exception.

END USER IMPLICATIONS

None. These memory addresses have no use, and should never be accessed in a normal application.

Work Around

Use the latest firmware version executed externally from a connected SPI Flash memory.

PLAN

This issue has been fixed in an updated firmware release. The latest firmware release may be loaded to an external SPI flash device and executed by the hub. There is no plan to update the hub ROM firmware image at this time.

Module 8: Force DCP feature overcurrent bug

DESCRIPTION

When using the “Force DCP” feature on a port by issuing the SET_PORT_DCP_MODE vendor request, the hub memory read/write functionality will cease to work following an overcurrent event on the port.

END USER IMPLICATIONS

The “Force DCP” feature if using the hub ROM firmware.

Work Around

Use the latest firmware version executed externally from a connected SPI Flash memory.

PLAN

This issue has been fixed in an updated firmware release. The latest firmware release may be loaded to an external SPI flash device and executed by the hub. There is no plan to update the hub ROM firmware image at this time.

Module 9: Multi-Host Endpoint Reflector cannot be used on downstream ports 5 and 6

DESCRIPTION

For USB7006 and USB7016 hubs, the Multi-Host Endpoint Reflector device cannot be enabled on downstream ports 5 and 6.

END USER IMPLICATIONS

End system integrators should ensure their systems limit Multi-Host Endpoint Reflector operation to downstream ports 1-4 only.

Work Around

None.

PLAN

There is no plan to address this item.

APPENDIX A: DOCUMENT REVISION HISTORY

Revision Level & Date	Section/Figure/Entry	Correction
DS80000811B (02-10-22)	All	Added USB7006, USB7016, and USB7052N to document.
	Module 9 .	Added new module.
DS80000811A (11-26-18)	All	Initial release

THE MICROCHIP WEB SITE

Microchip provides online support via our WWW site at www.microchip.com. This web site is used as a means to make files and information easily available to customers. Accessible by using your favorite Internet browser, the web site contains the following information:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQ), technical support requests, online discussion groups, Microchip consultant program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

CUSTOMER CHANGE NOTIFICATION SERVICE

Microchip's customer notification service helps keep customers current on Microchip products. Subscribers will receive e-mail notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, access the Microchip web site at www.microchip.com. Under "Support", click on "Customer Change Notification" and follow the registration instructions.

CUSTOMER SUPPORT

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Field Application Engineer (FAE)
- Technical Support

Customers should contact their distributor, representative or field application engineer (FAE) for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in the back of this document.

Technical support is available through the web site at: <http://microchip.com/support>

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is “unbreakable”. Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at <https://www.microchip.com/en-us/support/design-help/client-support-services>.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Klear, LANCheck, LinkMD, maxStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-B, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, NVM Express, NVMe, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQL, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, Symmcom, and Trusted Time are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2022, Microchip Technology Incorporated and its subsidiaries.

All Rights Reserved.

ISBN: 9781522497875

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.



Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Austin, TX
Tel: 512-257-3370

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Novi, MI
Tel: 248-848-4000

Houston, TX
Tel: 281-894-5983

Indianapolis
Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453
Tel: 317-536-2380

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608
Tel: 951-273-7800

Raleigh, NC
Tel: 919-844-7510

New York, NY
Tel: 631-435-6000

San Jose, CA
Tel: 408-735-9110
Tel: 408-436-4270

Canada - Toronto
Tel: 905-695-1980
Fax: 905-695-2078

ASIA/PACIFIC

Australia - Sydney
Tel: 61-2-9868-6733

China - Beijing
Tel: 86-10-8569-7000

China - Chengdu
Tel: 86-28-8665-5511

China - Chongqing
Tel: 86-23-8980-9588

China - Dongguan
Tel: 86-769-8702-9880

China - Guangzhou
Tel: 86-20-8755-8029

China - Hangzhou
Tel: 86-571-8792-8115

China - Hong Kong SAR
Tel: 852-2943-5100

China - Nanjing
Tel: 86-25-8473-2460

China - Qingdao
Tel: 86-532-8502-7355

China - Shanghai
Tel: 86-21-3326-8000

China - Shenyang
Tel: 86-24-2334-2829

China - Shenzhen
Tel: 86-755-8864-2200

China - Suzhou
Tel: 86-186-6233-1526

China - Wuhan
Tel: 86-27-5980-5300

China - Xian
Tel: 86-29-8833-7252

China - Xiamen
Tel: 86-592-2388138

China - Zhuhai
Tel: 86-756-3210040

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444

India - New Delhi
Tel: 91-11-4160-8631

India - Pune
Tel: 91-20-4121-0141

Japan - Osaka
Tel: 81-6-6152-7160

Japan - Tokyo
Tel: 81-3-6880-3770

Korea - Daegu
Tel: 82-53-744-4301

Korea - Seoul
Tel: 82-2-554-7200

Malaysia - Kuala Lumpur
Tel: 60-3-7651-7906

Malaysia - Penang
Tel: 60-4-227-8870

Philippines - Manila
Tel: 63-2-634-9065

Singapore
Tel: 65-6334-8870

Taiwan - Hsin Chu
Tel: 886-3-577-8366

Taiwan - Kaohsiung
Tel: 886-7-213-7830

Taiwan - Taipei
Tel: 886-2-2508-8600

Thailand - Bangkok
Tel: 66-2-694-1351

Vietnam - Ho Chi Minh
Tel: 84-28-5448-2100

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4485-5910
Fax: 45-4485-2829

Finland - Espoo
Tel: 358-9-4520-820

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Garching
Tel: 49-8931-9700

Germany - Haan
Tel: 49-2129-3766400

Germany - Heilbronn
Tel: 49-7131-72400

Germany - Karlsruhe
Tel: 49-721-625370

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Germany - Rosenheim
Tel: 49-8031-354-560

Israel - Ra'anana
Tel: 972-9-744-7705

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Italy - Padova
Tel: 39-049-7625286

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Norway - Trondheim
Tel: 47-7288-4388

Poland - Warsaw
Tel: 48-22-3325737

Romania - Bucharest
Tel: 40-21-407-87-50

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

Sweden - Gothenberg
Tel: 46-31-704-60-40

Sweden - Stockholm
Tel: 46-8-5090-4654

UK - Wokingham
Tel: 44-118-921-5800
Fax: 44-118-921-5820