

Practical Guide To Soldering

Sophia M Schillai (sms4g13@soton.ac.uk)

"THIS PRACTICAL ADVICE IS PROVIDED ``AS IS" AND WITHOUT ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, WITHOUT LIMITATION, THE IMPLIED WARRANTIES OF SAFETY, PRACTICALITY, CORRECT SPELLING, AND FITNESS FOR A PARTICULAR PURPOSE."

Motivation

I know you already know everything that could possibly be known about soldering, but a little reminder just in case won't harm anyone, right?



(better) Results

Tip size

increase tip size for:

- faster heat transfer
- larger parts

Choose the largest tip that you can fit next to your parts

Solder parts grouped by size, switch tip inbetween



Temperature

Start around 270° C for lead free solder, increase as far as needed in steps of 10°.

For larger pads/metal pins/pads connected to GND conducting heat away, you may need to wait for several seconds before solder will melt on them. This is normal, no need to increase temperature!

Increase temperature slightly for

- pads that need a large amount of solder
 - heat transfer problems with tiny tips
 - faster damage to parts and tip
 - faster evaporation and thus waste of flux
- 400° C is definitely too much!!!

DANGER



Whilst the solder we use is lead-free, it still contains a lot of unhealthy chemicals. Avoid inhaling the rising smoke. Against popular practice, your nose does not actually need to be less than 5 cm from the solder tip for a good connection!

Finished... cleaning up!

- Wipe tip one last time, add a thin coating of solder, e.g. by gently stroking the tip through the tip cleaner paste, switch off soldering iron
- Empty your small waste container
- Cut off section of solderwick you saturated with solder
- Wash your hands



References

<http://cornfieldelectronics.com/cfe/images/mfaire/soldercomic.jpg>
<https://learn.sparkfun.com/tutorials/how-to-solder-through-hole-soldering>
<https://www.sparkfun.com/tutorials/category/2>
https://www.elexp.com/Images/Weller_Coping_with_Lead_Free.pdf
<http://www.mouser.com/pdfdocs/TechspraySolderTips.pdf>

Novelty

You will leave the soldering area in a usable state for the next person and the stuff you solder might actually work for a while!



Soldering Iron

Use the tip to heat your parts
Parts are hot when the solder seems to get 'sucked' onto them



Solder

Hot glue for making circuits
Most solder have a flux core, flux is only needed for repairs



Safety Goggles

Keep your eyesight!
Not always but sometimes small hot solder spheres splash around, don't catch them with your eyes




Small Waste Container

Collect bits you cut off
Keep a small waste container in your work area to keep your work area clean



Silver Wire

Looks like solder, does not melt
Used especially on breadboard for making connections that look like nice clean lines



Wire Clippers

Use one hand to catch the bits you're cutting of
Place cuttings in the small waste container



Sponge

Remove flux residues, oxidation
Metal sponges are ready to go
All other sponges need to be kept humid by adding water



Flux


Increases surface tension of solder
Solder forms smooth surfaces
Don't confuse w/ tip cleaner paste
Removes oxidation from pads



Solder Wick

Ctrl+Z for soldering
Place over solder, heat with tip to suck up solder
Remove whilst hot, or it gets stuck

Making good connections



Do: Touch the iron to the component leg and metal ring at the same time.



Do: While continuing to hold the iron in contact with the leg and metal ring, feed solder into the joint.



Don't: Glob the solder straight onto the iron and try to apply the solder with the iron.



Do: Use a sponge to clean your iron whenever black oxidation builds up on the tip.



A Solder flows around the leg and fills the hole - forming a volcano-shaped mound of solder.



B Error: Solder balls up on the leg, not connecting the leg to the metal ring.
Solution: Add flux, then touch up with iron.




C Error: Bad Connection (i.e. it doesn't look like a volcano)
Solution: Flux then add solder.



D Error: Bad Connection...and ugly...oh so ugly.
Solution: Flux then add solder.



E Error: Too much solder connecting adjacent legs (aka a solder jumper).
Solution: Wick off excess solder.



From: <https://learn.sparkfun.com/tutorials/how-to-solder-through-hole-soldering>