

UNIT-II MEASUREMENT OF ENGINEERING QUANTITIES

Measurement is required to assess the output, Capacity and Performance of m/c and system. It is also required to control the m/c and system, so that they keep working within required limit.

Measurement of Temperature : →

measurement of temp and Control of temp is play very important role in Furnance, processes and many engineering system.

Different m/c work with diff temp range.

Temperature cannot be measured by ~~direct~~ basic standard for direct measurement change in temp is measured by the effects like change in physical state of substance, change in dimension, change in electrical property et-c

- | | |
|-------------------------------|--------------------------|
| ① Liquid in glass Thermometer | ④ Bimetallic Thermometer |
| ② pressure gauge Thermometer | ⑤ Thermocouple |
| ③ Resistance Thermometer | ⑥ Pyrometer. |

Liquid - in - glass Thermometer : →


eg - Clinical Thermometer

large bulb at one end, and fine capillary tube in a glass rod having a scale, a small bulb at the other end.

Thermometric liquid which is filled in the bulb and the part of capillary. Remaining part of capillary has either vacuum or filled with inert gas


Property of Thermometric liquid :-

- ① The expansion of liquid should be linear
- ② Low freezing and high boiling point
- ③ Coefficient of thermal expansion should be large
- ④ visible as fine line inside the capillary
- ⑤ Should not stick on the wall of capillary



PRESSURE THERMOMETER

- A bulb may be filled with liquid, gas or vapour.
- One end of the tube connect with the bulb while another end connect with the pressure gauge
- The length of the tube may be as long as 75m.
- When the temp of the bulb change, the pressure and volume of the fluid inside it also change. The change in pressure is recorded on the pressure gauge. The scale of the pressure gauge can be calibrated to give temp directly
- error occurs due to high length of tube.
- error can be minimise by keeping the volume of bulb is larger as compare with the tube.
- Temp range -200°C to 500°C



Thermocouple : \rightarrow

Seebeck discovered that emf exists across a junction formed by two dissimilar metals. Peltier discovered that this emf depends upon the temperature of the junction (Peltier effect). Thomson found that the emf also depends upon the temperature gradient along the conductor wires (Thomson effect). These principles are used in thermocouple for measure of temperature. The emf due to Thomson effect is quite small as compare to that due to Peltier effect.



Common method for making thermocouple joint

material used in thermocouple are

[Copper 60%, Nickel 40%]	[Cr 10%, Ni 90%]	[Al 2%, 90% Ni remaining Si, Mn]
Copper constant thermocouple	chromel constantan	
used -200 to 350°C	-20 to 500°C	


* Thermocouple are made by twisting two wire of dissimilar metal and making a junction b/w them by brazing or welding. The voltage output of thermocouple is in millivolt. Therefore suitable circuitry is required for its amplification ~~display~~ display & recording.

Pyrometer : \rightarrow Any body having temp above the absolute zero temp i.e. gives radiation. When a steel body is heated, it radiates energy in the infrared region. When the temp is increased, the colour of radiation becomes dull red. Again heating continues the colour of body become red, bright red and finally bluish. This change in colour is due to dominance of higher frequency in spectrum at higher temp. The Pyrometer measure the temp on the basis of radiation.

① Total Radiation Pyrometer ② Optical Pyrometer

x [Optical Pyrometer use optical mean for estimating the temperature. They use the radiation in the visible range of the spectrum of radiation from the hot body. They are non contact instrument. A Pyrometer must be calibrated for Particular application before it is put to regular use.] x.

Optical Pyrometer match the colour of radiation from a hot body, with the colour of filament bulb. The current through the bulb filament can be controlled through an electric circuit. When this current is varied, the colour of filament changes. The operator tries to adjust the current in such a manner that the colour of filament become the same as the colour of radiation from hot body.




Working principle of optical Pyrometer

PRESSURE MEASUREMENT



Pressure is defined as the force exerted by a fluid on a unit area. This pressure is the Absolute Pressure. The measuring devices usually measure the difference of pressure b/w absolute pressure from a source and atmospheric pressure. This pressure is termed as Gage Pressure.

$$1 \text{ atm} = 1.01325 \text{ bar}$$


$$1 \text{ bar} = 10^5 \text{ Pa}$$




Pressure Measuring Devices: →



- U-Tube Manometer
- Inclined Manometer
- Piezometer



Bourdon Tube Pressure Gauge : \rightarrow



○ Cross-section of Bourdon Tube

- # oval cross section of tube deform to become more circular.
- # for more accuracy use more no. of turns.
- # Calculate Press diff b/w atm press & applied pressure.
- # The circular scale is calibrated to read pressure directly.
- # The arc of bourdon tube is usually less than 360° .

Elastic Diaphragms :-

The U-tube manometer and bourdon tube pressure gauges are suitable for small pressure ~~range~~ range, low medium sensitivity and when the variation in pressure is low. For measurement of dynamic pressure i.e. pressure very fast with time they are not suitable.

- for High pressure difference we use elastic diaphragms.
- These diaphragms are usually circular and of thin metallic sheet.
- Two basic type of Diaphragms are -

* Flat Diaphragm * Corrugated Diaphragm.


- ~~Diaphragm~~ Diaphragm is enclosed in a housing. The housing has threads for fitting on a suitable opening. It is fitted on the vessel or pipeline where pressure is to be measured. When the pressure is applied on one side of the diaphragm, it gets deformed. This deformation is a function of applied pressure. The deformation is measured using a suitable device for measurement of displacement.

Measurement of Velocity : →

Velocity is the rate of change of displacement. Velocity may be Linear or Angular. Direct measurement of linear velocity is not easy. Linear velocity can be determine by calculating linear or angular displacement. It can also be calculated by first converting linear displacement to angular displacement and then measure the angular velocity. where is angular velocity can directly measure.

Velocity measuring Devices.

① Centrifugal Speedometers : →



Centrifugal Speedometer

② Tachometer : → (A) Contact method (B) Non Contact method


Measurement of Flow

Flow rate can be define as the quantity of a substance flowing from a desired cross section in per unit time. unit is kg/sec or m^3/sec .

Flow measuring devices.


- ① Volumetric Tank ② Obstruction meter
- venturimeter ←
 - orifice meter ←
 - Rotameter ←

②




Venturimeter

- ① 98% recover press
- ② length is very high
- ③ High cost




Nozzle meter

- ① Not good as Venturimeter
- ② good as orifice meter
- ③ Short length
- ④ Low cost




Orifice meter

- ① cheap
- ② Easy mfg



probe may be type of sensor.

⑤ Pitot Tube :- $Q = AV$
 $U = \sqrt{\frac{2P_{max}}{\rho}}$
 measure velocity when fluid strike on wall of the tube velocity of fluid become zero and sudden pressure increase fluid strike on probe and measure pressure also. calculate pressure difference pressure sudden increase called stagnation.



Measurement of Strain % →

Measurement of strain is done for two major reasons. Firstly, strain is related to stress, and measurement of strain is done to determine stress in a machine component. Determine of strain is also useful for determine other quantity indirectly, like temperature, force, torque, pressure and motion. The electrical Resistance strain gage is one of the most widely used sensor for measurement of strain.

Electrical Resistance Strain gage :-


Electrical Resistance of wire

$$R = \frac{\rho L}{A}$$

ρ = electric Resistivity

L = Length

A = Area of cross section of wire





Axial force apply on wire then length increase and dia decrease. Due to these change the electric resistance also change. This is the principle on which electrical resistance strain gages work. This property of metal, due to which their resistance changes on applying stress is called piezo resistivity.

It consist of a grid of fine wire, sandwiched b/w two thin paper sheet. The strain gage is bonded on the surface where stress is to be measured, by means of a suitable adhesive. The commonly used adhesive are nitrocellulose or bakelite (phenolic)

The Sensitivity of strain gage is measured by its gage factor

$$G = \frac{dR/R}{dL/L} = \frac{dR/R}{\epsilon}$$





strain gage measure
very small strain
0.000001

MEASUREMENT OF FORCE

Force is measured using different type of elastic Transducers and strain gauges. When force is applied to an elastic body it deflects. This deflection is related to the magnitude of force. Thus by measuring the deflection caused by the force, its magnitude can be determined.

Spring Balance : →


$$F = K \delta$$



Curve gives spring rate


Electric Load Cell : →

In such type of load cell have strain gage mounted on an elastic element. There is a large variety of load cell, using different geometries of elastic element, and different arrangement for mounting the strain gage. No. of strain gage mounted on elastic body



Hydraulic and Pneumatic Load Cells : →

Force can also be measured by measuring the Pressure exerted by it, on a known area. This principle is used in Hydraulic & Pneumatic Load cell




Measurement of Torque


Torque is the moment applied by a force. The shaft of diff m/c like Pump, engine, generator and other rotary equipment transmit power through angular motion and torque. The product of torque and angular velocity give Power (mechanical). Torque measuring devices are known as dynamometer.

Poony Brake Dynamometer:-

It is into the Category of Absorption Dynamometer. Absorbing or dissipating the power.



Poony Brake Dynamometer




Rope Brake Dynamometer

Error and Uncertainty in Measurement

Error:-

The error of a measurement is defined as the difference b/w measured value and the true physical value of the quantity. The error cannot be calculated exactly unless the true value of the quantity is known. As there is some error is always present in every measurement so it is very difficult to find out true value of quantity.



Uncertainty : → It is the range or region in which error may vary. It is not the same as accuracy.

Eg (dia of shaft) 99.5 mm to 100.5 mm

Systematic or fixed:- Due to improper design, fabrication or maintenance. incorrect marking, defect in gear. This may happen due to improper training, incorrect technique, lack of knowledge etc.

Random or Accidental:- → consider average value (eg) different person take different value. Temp, pressure, speed, vibration. Tolerances in dimension and material are also responsible for these errors. Sometime the edge of sheet having proper edge and sometime chamfer, fillet for eliminate these error use method of symmetry.

Illegitimate error:- → occur when wrong procedure follow, occur due to improper care, These error can be taken care of by identifying their source and removing it.


Measuring Instruments:-> There are no. of instrument available for measuring ~~length~~^{linear} dimension, (length, dia, depth) and angular dimension. During inspection and quality control, it is sometimes sufficient to know whether a mfg component is within the specified tolerance or not.

1) Vernier Calipers (2) Micrometer (3) Dial gages (4) Slip gages (5) Sine bar

Slip gages:-> It is also called precision gage block. It is a set of very accurate rectangular block, which are used for verifying and calibrating the measuring tools, limit gages and other quality control gages. It is made of steel (alloy) plate and smooth surface high hardness and minimum wear and tear. having 5 grade, Grade I, Grade II, Grade O, Grade 00 calibrated grade mainly use grade I MSB

Size Range mm	Increment mm	No of Pieces
1.0005	—	1
1.001 to 1.009	0.001	9
1.01 to 1.49	0.01	49
0.5 to 2.5	0.5	13
10 to 100	10.	10
		total 88 piece.

Dial Gages :-> Also called Dial indicator have a circular dial with pointer. A plunger is attached to the pointer through a gear train mechanism. The plunger moves in and out of the body of dial gage. This linear



motion of plunger is convert into rotary motion by gear train mechanism. Total 100 division. Each division correspond to 0.01 mm. This is the least count of the dial gage. one complete revolution of the pointer correspond to displacement of 1 mm of the plunger. Available in the range of


0 to 3 mm
0 to 5 mm
0 to 10 mm

Sine Bar

Sine Bar is used to determination of angle trigonometrically, by using measured linear dimension.

It is also used for setting angle and tapers. Slip gages are used to measure or set the linear dimension. Sine bar is a steel bar with step at both end.

It is made of steel and super finished by lapping operation.



* Distance b/w two roller is known.

* Most Common size is 100mm
Available upto 250mm size

Measurement of Angle using
Sine Bar

* Accuracy of sine bar depends upon the correctness of roller diameter and centre distance b/w them.