

**Article No.:** TCTIP-10-05

**Author:** Ed Lee

**Total Pages:** 3

## A primer on proper parting procedures

**Note: This is the first in a two-part series on proper parting procedures. In Part 1, some basics.**

When the first automatic transmissions were introduced in the late 1930s, the fluid coupling was routinely serviced as part of a transmission overhaul. The fluid coupling was bolted together and servicing it didn't require any skills that a regular mechanic wouldn't have. When the fluid coupling evolved into the torque converter, it was still a bolt-together unit and the only new challenge for the mechanic was to learn about stators.

But then everything changed. The torque converter became a sealed unit and even the best mechanics weren't equipped with the machining and welding skills necessary to rebuild these new units. It's not hard to see why in-house converter rebuilding facilities were so slow to develop.

Most of the early torque converter technicians were self-taught, and passed that knowledge along over the years. Being able to cut a converter apart in a manner that makes reassembly as easy as possible is one of the first skills new technicians learn. Industry veterans will tell you they relied on their senses when cutting a converter apart. A veteran cutter can tell you when the tool bit stops cutting the harder weld material and starts cutting the softer material of the cover or impeller by the feel of his hand on the cross

feed. He can also tell you how deep to cut by looking at the weld. The veteran knows that the discoloration of the metal next to the weld is about as deep as the penetration of the weld, and that you will see oil when that line disappears. (See Figure 1.) Unfortunately, it takes years to develop these skills, and new technicians need to know what to do now. So here's a primer on some basic techniques.

### The tools

The fixturing for cutting a converter apart needs to be as rigid as possible. An industrial or military-grade lathe has the mass for a good solid base. A CNC lathe is also a good choice because of its mass. How rigid your fixturing is will not only dictate what grade of cutting bit to use, but also the life expectancy of your bits. The experts agree that a roughing grade of carbide is your best choice, and most agree that the tool bit should have a 00 relief and that less radius on the bit will result in less clean-up work. There is little else that anyone in the industry agrees on.

Since the grade of carbide that works best depends on how rigid your fixturing is, here's a good rule of thumb. Start with as hard a grade of carbide as your fixturing can handle with as minimal breakage as you can handle. Work down to as soft of a grade of carbide as necessary for the longevity of your cutting bits. It would be a good idea to make friends with your tool supplier since the price of carbide is a factor! The shops that are cutting their converters apart on CNC lathes report they are cutting between 400 and 500 converters with a single side of an insert.

### How to cut

Where to start your cut? How deep to cut? Which direction to cut? These are your next concerns.

With the possible exception of the BM25 converter, the mating parts of all converters are joined by a single fillet weld and, with the exception of the ring gears or mounting rings, the largest diameter of a converter is usually the overlapping member of the fillet weld. Figure 2 illustrates a converter with a cover that overlaps and Figure 3 illustrates a converter with the



Figure 1

*continued on page 2*



Automatic Drive P.O. Box 440  
Bellows Falls, VT 05101-0440 USA  
800-843-2600 • fax: 802-463-4059  
email: [info@sonnax.com](mailto:info@sonnax.com) •  
[www.sonnax.com](http://www.sonnax.com)

©2005 Sonnax Industries, Inc.

impeller as the overlapping member.

The point where the overlapping member and the weld meet is where you start your cut, but before you start, you may want to remove any high points that might protrude above the weld. Carbide does not like interrupted cuts, and any high points will only widen as the tool bit is plunged



Figure 2

into the weld, causing increased pin point resistance with each revolution.

After the high points have been removed, zero the cross feed dial and you are ready to start your cut. The depth of your cut is determined by the thickness of the overlapping member. Knowing this

thickness is the secret to successfully parting a converter on the first try. Find your converter on the following chart (see Figure 4) and plunge in the corresponding thickness.

Please note that where it says flush on the chart, that means flush with the cover. Touch your tool bit on the cover, zero the dial, back the tool bit away, and cut in until the dial returns to zero.



Figure 3

*continued on page 3*

## CUT-OPEN LIST

### GENERAL MOTORS

	Cut (in inches)
TC	0.170
125	0.130
440	0.130
4L30-E	0.200
4L80-E	FLUSH
200LU	0.140
350CH	FLUSH
350LU	0.190
400	FLUSH
700LU	0.165
BPO	0.150
JSFM	0.150
JTFM	0.150
JXFM	0.150
JZFM	0.150
POWERGLIDE	0.150
NORTHSTAR	0.150

### TOYOTA

	Cut (in inches)
TC	0.150
TO18	0.110
TO19	0.125
TO21	0.180
TO28	0.150
TO39	0.140
TO42	0.150
TO51	0.210
TO64	0.160
TO67	
TO74	

### FORD

	Cut (in inches)
TC	0.165
5R55W/4/8	0.150
AODE	0.130
A4LD	0.125
ATX	0.200
AXOD	0.180
AXODE	0.180
AXODE25	0.165
AXODESHO	0.165
AXODE25SHO	0.100
C4 11"	0.140
C4 12"	0.150
C5	0.100
C6 EARLY	0.145
CD4E A	0.175
CD4E C	0.140
CD4E H	

### MITSUBISHI

	Cut (in inches)
TC	0.110
CT10 TP	0.110
CT11	0.160
CT12	0.150
CT12-1	0.130
CT13	0.135
CT15	0.140
CT15-1 / CT15-2	0.140
CT20	0.170
CT27	0.170
CT27-9	0.140
CT29	

### CHRYSLER

	Cut (in inches)
TC	0.170
470LU	0.170
604 24T	0.170
604 11" 22T	0.150
606	0.170
727 / 727LU	0.170
904 / 904LU	0.170
TC6 / TC6LU	0.170
TC8 / TC8LU	0.210
CUMMINGS NL	0.185
CUMMINGS LU	0.110
W. GERMAN JEEP	

### NISSAN / DATSUN

	Cut (in inches)
TC	0.125
DA6	0.125
DA7	0.100
DA8	0.150
DA11	0.125
DA13	0.210
DA16 T.C.	0.110
DA16 T.P.	0.150
DA18	0.190
DA24	0.150
DA25	0.155
DA30	0.120
DA34	0.150
DA37	0.110
DA38	0.150
DA39	0.160
DA44	0.195
DA50	0.190
DA53	0.150
DA55	

If your converter is running true, you will then move the cutter perpendicular to the plunge cut, moving away from the weld, until you see oil exiting the converter at the cutting tip. If your converter is not running true, you will want to add an additional .005" to .010" to your plunge cut before moving the cutter to the side.

## Some additional hints

On some Subaru converters (SU15) you will have to remove the ring gear before cutting the converter apart.

On the BM25 converter with 2 welds, cut at the weld closest to the pump.

On late-model Hondas, do not clean off all of the weld. Leave a 45° angle of weld after the halves separate. Due to the close proximity of the ring gear to the weld, it is difficult to get a good angle on the welder head when you are welding the converter back together. The remaining 45° angle will leave a nice area for a bead of weld.

*Next month, the specifics of proper parting procedures.*

*Special thanks to Rich Rossiello from Perfect Shift for his technical assistance in writing this article.*

*Ed Lee is a Sonnax technical specialist with a focus on issues of interest to torque converter builders.*

©Sonnax 2005

## HONDA, BMW, JAG, MERC, VW

	Cut (in inches)
TC	
HO1	0.115
HO7	0.115
HO12	0.115
HO14	0.210
HO16	0.115
HO17	0.115
HO18	0.115
HO21	0.115
BM11	0.125
BM17	0.125
BM25	0.181
MC6	FLUSH
MC10	FLUSH
MC18	0.160
MC19	0.160
JAG E.	0.131
VW4	0.100
RE8	0.190
RE9	
RE10	
SU11	0.110
SU12	0.120
SU13	0.120
SU16	0.125
SU18	0.125
SA4	0.075
SA6	0.100
SA7	0.100