

COMPLAINT

Loss of 2nd and 4th gear

CAUSE

The OEM strut splits in half under pressure from the servo piston.


CORRECTION

This strut is made from higher quality material and has a wider cross section.

Servo Band Strut

69700-01

1 Servo Band Strut



Sonnax Part Summary

In RE4R01A, RL4R01A, RE4RO3A, R4AX-EL and R4A-EL transmissions, the OEM strut has a tendency to split in half under pressure from the servo piston. This results in loss of 2nd and 4th gear.