

COMPLAINT

SECONDARY COMPLAINTS

Burned forward clutch

- Loose sleeve • Loose fitting direct drum

CAUSE

The OEM sleeve stretches due to excess heat from the burned forward clutch, and there is too much clearance between the OEM sleeve and the direct drum bushing.

CORRECTION


This sleeve is a direct replacement for a loose OEM sleeve, and is also thicker to provide a tighter fit and better support for the direct drum.

Center Support/Direct Drum Sleeve

56219-02K

1 Sleeve

Note: Fits '96 & earlier bushing style center supports only.



Sonnax Part Summary

In A4LD, 4R44E & 4R55E units the center support has a steel sleeve that supports the direct drum. Heat from clutch failure expands both the center support and the steel sleeve. Because the center support is aluminum, it expands at about twice the rate of the steel sleeve. This can cause the sleeve to stretch permanently and become loose when the unit cools. Sonnax now offers a replacement sleeve **56219-02K** for a loose OEM sleeve.

Features & Benefits

- The Sonnax sleeve is designed with a thicker wall thickness to provide more stability and better fit to the direct drum.
- This sleeve is recommended even if the OEM sleeve is still intact.