

COMPLAINT

Delay in reverse or slipping causing burnt clutches and bands

CAUSE

A worn boost valve in this unit can cause a delay in reverse or slippage, eventually burning the Low Reverse band and/or the Direct clutch.

CORRECTION

Replace the worn boost valve assembly with the appropriate Sonnax boost valve assembly.

Reverse Boost Valve Kits

63741-09K

Late Style

1 Boost Sleeve
1 Boost Valve

63741-12K

Early Style

1 Spring
1 Boost Sleeve
1 Boost Valve

Note: Fits Nissan, Infiniti RE5R05A and Kia A5SR1/A5SR2.

Also Available

Oversized PR Valve & Reverse Boost Assembly


63741-01K

1 Pressure Regulator Valve
1 Spring
1 Boost Sleeve
1 Boost Valve



F-63741-TL

1 Reamer
1 Guide Pin
1 Reamer Jig



Features & Benefits

- Drop-in replacement, no special tools required.
- Sonnax sleeves are manufactured from highly wear-resistant aluminum for increased durability.

You need this if....

Either a Wet Air Test or a Vacuum Test in the location shown, results in leakage. A vacuum test must hold a minimum of 18".

