


"A" Servo Spring

76831-SP

1 Servo Spring



Instructions:

The OEM green spring for the "A" servo is not strong enough, allowing the overdrive band to apply before the forward clutch releases. This replacement spring increases the spring rate almost 30% over the OEM spring, which provides more strength and prevents premature apply of the overdrive band which creates a 3-4 shift tie-up.

Simply replace the existing servo spring with this stronger spring. Verify that the tip of the piston assembly engages the band pocket when reassembling.