



APPALACHIAN INSPECTIONS, LLC.

8284348543

chris@appinspect.net

<https://www.appinspect.net/>



HOME INSPECTION REPORT

1234 Main St.
Boone, NC 28607

Buyer Name

03/02/2020 9:00AM



Inspector
Chris Lusk

NC Licensed Home Inspector #3741

8284348543

chris@appinspect.net



Agent

Agent Name

555-555-5555

agent@spectora.com

HOW TO READ THIS REPORT

Defects are organized into 3 categories within the report:

Minor Concerns/Update Items: These items are very minor issues or improvements that can usually be addressed by the homeowner or a handyman. These items may also include outdated systems that function properly but are beyond service life. (items will not appear in summary page).

Moderate Concerns/Maintenance Items: These items are more serious and may effect the functionality of the component or system. These also include items that are in need of normal maintenance and service. Repairs should be performed by a qualified professional.

Major Defects/Safety Hazards: These items consist of major defects or damage to systems and components. These items may also be safety hazards that can cause personal injury. Any repairs should be conducted by a licensed professional and may be more expensive.

It is strongly advised that all updates or repairs be performed by a licensed professional of the component or system.

ITEMS NOT INSPECTED/LIMITATIONS

There are items that are not inspected in a home inspection including, but not limited to; fences and gates, pools and spas, outbuildings or any other detached structure, storm doors and storm windows, screens, window AC units, central vacuum systems, water softeners, alarm and intercom systems, and any item that is not a permanently attached component of the home. Also drop ceiling tiles are not removed unless water damage is visible, as they are easily damaged, and this is a non-invasive inspection. Subterranean systems are also excluded, such as but not limited to: sewer lines, septic tanks, water delivery systems, and underground fuel storage tanks.

Water and gas shut off valves are not operated under any circumstances. As well, any component or appliance that is unplugged or "shut off" is not turned on or connected for the sake of evaluation. I don't have knowledge of why a component may be shut down, and can't be liable for damages that may result from activating said components / appliances.

Also not reported on are the causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; Calculate the strength, adequacy, design or efficiency of any system or component; Enter any area or perform any procedure that may

damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility.

Lastly a home inspection does not address environmental concerns including, but not limited to: Asbestos, lead, lead based paint, radon (unless requested), mold, wood destroying organisms (termites, etc), cockroaches, rodents, pesticides, fungus, treated lumber, Chinese drywall, mercury, or carbon monoxide.

SUMMARY



ITEMS INSPECTED



MINOR CONCERNS/UPDATE
ITEMS



MODERATE
CONCERNS/MAINTENANCE
ITEMS



MAJOR DEFECTS/SAFETY
HAZARDS

- 2.2.1 Grounds - Vegetation, Grading, Drainage & Retaining Walls: Negative Grading
- 2.2.2 Grounds - Vegetation, Grading, Drainage & Retaining Walls: Tree Overhang
- 2.2.3 Grounds - Vegetation, Grading, Drainage & Retaining Walls: Leaning Retaining Wall
- 2.2.4 Grounds - Vegetation, Grading, Drainage & Retaining Walls: Failed Retaining Wall
- 2.2.5 Grounds - Vegetation, Grading, Drainage & Retaining Walls: Improper drainage/wash out
- 2.3.1 Grounds - Decks, Balconies, Porches & Steps: Deck
- 2.3.2 Grounds - Decks, Balconies, Porches & Steps: Stairs
- 2.3.3 Grounds - Decks, Balconies, Porches & Steps: Front stoop
- 3.1.1 Exterior - Siding, Flashing & Trim: Siding
- 3.2.1 Exterior - Eaves, Soffits & Fascia: Fascia - Damaged
- 3.2.2 Exterior - Eaves, Soffits & Fascia: Displaced Soffit
- 4.1.1 Roof - Coverings: Roof-Older
- 4.2.1 Roof - Roof Drainage Systems, Gutters: Downspouts Drain Near House
- 4.2.2 Roof - Roof Drainage Systems, Gutters: Gutter Damaged
- 4.2.3 Roof - Roof Drainage Systems, Gutters: Gutters Missing
- 4.2.4 Roof - Roof Drainage Systems, Gutters: Gutter missing end cap
- 5.1.1 Doors, Windows & Interior - Exterior Doors: Door Does Not Close or Latch
- 5.1.2 Doors, Windows & Interior - Exterior Doors: Water entry evident
- 5.2.1 Doors, Windows & Interior - Interior Doors: Door Doesn't Latch
- 5.2.2 Doors, Windows & Interior - Interior Doors: Door Sticks
- 5.2.3 Doors, Windows & Interior - Interior Doors: Bifold Doors - Missing
- 5.3.1 Doors, Windows & Interior - Windows: Failed Seal
- 5.3.2 Doors, Windows & Interior - Windows: Windows will not stay open
- 5.4.1 Doors, Windows & Interior - Walls: Bowing wall panels
- 5.5.1 Doors, Windows & Interior - Ceilings: Stain(s) on Ceiling
- 5.6.1 Doors, Windows & Interior - Floors: Moderate Wear
- 5.6.2 Doors, Windows & Interior - Floors: Moisture Damage

- 5.6.3 Doors, Windows & Interior - Floors: Sloping Floor
- 5.7.1 Doors, Windows & Interior - Steps, Stairways & Railings: Missing railing
- 6.1.1 Built-in Appliances - Dishwasher: Improperly Installed Drain line
- 6.1.2 Built-in Appliances - Dishwasher: Improperly installed wiring
- 6.7.1 Built-in Appliances - Dryer: Dryer vent duct too long
- 7.7.1 Lower Level Built-in Appliances - Dryer: Dryer vent disconnected
- 8.1.1 Fireplace - Firebox/Mantel: Cracks in Firebrick/panels
- 8.3.1 Fireplace - Vents, Flues & Chimneys: No exhaust
- 9.1.1 HVAC - Heat Systems: Inoperable
- 10.2.1 Plumbing - Drain, Waste, & Vent Systems: Leaking Pipe
- 10.3.1 Plumbing - Water Supply, Distribution Systems & Fixtures: Toilet Leaking
- 10.3.2 Plumbing - Water Supply, Distribution Systems & Fixtures: Leaking Faucet
- 10.3.3 Plumbing - Water Supply, Distribution Systems & Fixtures: Missing control valve
- 10.3.4 Plumbing - Water Supply, Distribution Systems & Fixtures: Malfunctioning diverter
- 10.5.1 Plumbing - Fuel Storage & Distribution Systems: CSST not bonded
- 11.3.1 Electrical - Branch Wiring Circuits, Breakers & Fuses: Improper Wiring
- 11.3.2 Electrical - Branch Wiring Circuits, Breakers & Fuses: Double Tap
- 11.4.1 Electrical - Lighting Fixtures, Switches & Receptacles: Cover Plates Missing
- 11.4.2 Electrical - Lighting Fixtures, Switches & Receptacles: Drooping ceiling fan
- 11.5.1 Electrical - GFCI & AFCI: Missing GFCI Protection
- 11.5.2 Electrical - GFCI & AFCI: GFCI Receptacle - did not trip/reset
- 11.6.1 Electrical - Smoke/CO Detectors: Older Smoke Alarms
- 11.6.2 Electrical - Smoke/CO Detectors: No CO Detectors Installed
- 12.3.1 Attic and Roof Structure - Exhaust Systems: Bathroom Vents Into Attic
- 12.3.2 Attic and Roof Structure - Exhaust Systems: Bathroom Vent Inoperable
- 13.1.1 Basement, Foundation, Crawlspace & Structure - Foundation: Foundation Cracks - Major
- 13.1.2 Basement, Foundation, Crawlspace & Structure - Foundation: Foundation Wall Water Intrusion
- 13.2.1 Basement, Foundation, Crawlspace & Structure - Floor Structure: Modified construction
- 13.2.2 Basement, Foundation, Crawlspace & Structure - Floor Structure: Subfloor - water stains/damage
- 13.3.1 Basement, Foundation, Crawlspace & Structure - Insulation: Falling/damaged insulation
- 13.5.1 Basement, Foundation, Crawlspace & Structure - Vapor Retarders (Crawlspace or Basement): Displaced





1: INSPECTION DETAILS

Information

In Attendance Client	Occupancy Furnished	Style Mountain
Type of Building Single Family	Weather Conditions Clear, Recent Snow/Ice	Temperature (approximate) 32 Fahrenheit (F)
Main Entrance Faces West		

2: GROUNDS

Information

Walkways, Patios & Driveways: Driveway/Parking Area Material Gravel	Walkways, Patios & Driveways: Walkway/Patio Material Pavers	Decks, Balconies, Porches & Steps: Appurtenance Stoop/Steps, Multi Level deck
		
Decks, Balconies, Porches & Steps: Material Wood		
Vegetation, Grading, Drainage & Retaining Walls: Retaining Wall Concrete Block		
		

Limitations

General
SNOW/ICE COVERED
PARKING AREA, STAIRS, ROOF
Exterior Surfaces are covered with snow/ice. These areas could not be seen to be fully inspected.

General
MULTI-LEVEL DECK

This home has an attached multi-level deck. This structure is beyond the scope of a home inspection as it requires extensive engineering for construction. While it is inspected for common defects, you may wish to have a structural engineer evaluate the structure before closing.



Deficiencies

2.2.1 Vegetation, Grading,
Drainage & Retaining
Walls



Moderate Concerns/Maintenance Items

NEGATIVE GRADING

WEST WALL

Grading is sloping towards the home in some areas. This could lead to water intrusion and foundation issues. Recommend qualified landscaper or foundation contractor evaluate to ensure that water flows away from home or is otherwise controlled.

[Here is a helpful article](#) discussing negative grading.

Note: Home inspectors have no way of knowing if adequate drain systems are installed below grade. You may wish to verify with the seller if a drain system is installed and whether or not they have had water intrusion issues.

Recommendation

Contact a qualified grading contractor.



2.2.2 Vegetation, Grading,
Drainage & Retaining
Walls




Moderate Concerns/Maintenance Items

TREE OVERHANG

Trees observed overhanging the roof. This can cause damage to the roof and prevent proper drainage. Recommend a qualified tree service trim any overhanging branches.

Recommendation

Contact a qualified tree service company.



2.2.3 Vegetation, Grading,
Drainage & Retaining
Walls



Moderate Concerns/Maintenance Items

LEANING RETAINING WALL

SW RETAINING WALL

Retaining wall appears to be leaning and showing signs of deterioration. This is an indication of inadequate construction, deteriorating from age or overwhelming pressure on the wall. Over time, the wall may continue to lean and potentially fail. A landscaping professional is recommended to evaluate further.

Recommendation

Contact a qualified landscaping contractor



2.2.4 Vegetation, Grading,
Drainage & Retaining
Walls



Moderate Concerns/Maintenance Items

FAILED RETAINING WALL

LOWER PARKING AREA RETAINING WALL

The retaining wall has failed and no longer functions as originally intended. A general contractor is recommended to repair/replace as needed to ensure adequate drainage and prevent potential safety hazards.

Recommendation

Contact a qualified general contractor.



2.2.5 Vegetation, Grading, Drainage
& Retaining Walls



Major Defects/Safety Hazards

IMPROPER DRAINAGE/WASH OUT

NORTH WALL

There appears to be one or more areas of inadequate drainage indicated by wash out next to exterior walls and/or around deck footings. A grading professional is recommended to evaluate further to repair/replace wash out areas and improve drainage around the home.

Recommendation

Contact a qualified grading contractor.



2.3.1 Decks, Balconies, Porches & Steps

DECK




Major Defects/Safety Hazards

The multi-level deck has several areas of concern including but not limited to:

- No lateral support or bracing,
- Wall anchors improperly installed through siding,
- Upper level deck and roof structure supported by cantilever,
- Support posts installed on retaining wall,
- Structure leaning heavily away from home,
- 4x4 support posts used to support upper deck and roof structure,
- rims and bands nailed to 4x4 posts instead of bearing directly on top of posts,
- Improperly installed roof support structure.

These Items are serious structural concerns and safety hazards that may lead to structure failure. A structural engineer is recommended to evaluate further and provide a course of action for repair/replacement/modification as needed.

Recommendation
Contact a qualified structural engineer.



The exterior stair structures have serious areas of concern, including but not limited to:

- Missing handrail and balusters,
- no center stringer,
- Missing footers,
- Heavy leaning to one side,
- inadequate attachment and support structure,
- exposed footers from wash out,
- Stairs detaching from landing with no bottom stringer support,
- missing, damaged and overall inadequate footings,

These items are serious structural and safety concerns which could lead to trip hazards and structural failure. A structural engineer is recommended to evaluate further and provide a course of action for repair/replacement/modification as needed.


Recommendation
Contact a qualified professional.



The front stoop has detached from the house and has overall inadequate/improper construction. This is a serious safety and structural concern. Replacement by a qualified contractor is recommended.

Recommendation

Contact a qualified general contractor.



3: EXTERIOR

Information

Inspection Method Visual	Siding, Flashing & Trim: Siding Material Wood	Siding, Flashing & Trim: Siding Style Panels
Wall Structure: Wall Construction Framed		

Deficiencies

3.1.1 Siding, Flashing & Trim

SIDING

 Moderate Concerns/Maintenance Items

The exterior wood siding, trim and flashing has several areas of deterioration evident. Over time, these areas will continue to deteriorate and allow further damage, organic growth, and/or water entry. A siding professional is recommended to evaluate and repair/replace as needed. Hidden damage may be present.

Recommendation
Contact a qualified siding specialist.



South wall, detached/loose siding.




South wall, improper siding to ground clearance



North Wall, Damage from failed gutter and growing vines



Water damage, North Wall



rusting flashing, north wall



Deteriorating siding and trim, SW corner

3.2.1 Eaves, Soffits & Fascia

FASCIA - DAMAGED

WEST AND NORTH WALLS


Several sections of the fascia are damaged do to excessive water exposure and lack of maintenance. Recommend qualified professional evaluate, determine cause and repair/replace as needed to prevent further deterioration. Hidden damage will be present under gutter.

Recommendation

Contact a qualified professional.



Moderate Concerns/Maintenance Items



3.2.2 Eaves, Soffits & Fascia

DISPLACED SOFFIT

WEST AND NORTH WALLS

The soffit is displaced areas at the eaves of the home. This can promote pest and water intrusion and damage in these areas. Securely replacing the displaced areas is recommended. Hidden damage may be present.

Recommendation

Contact a qualified professional.



Moderate Concerns/Maintenance Items



4: ROOF

Information

Inspection Method Binoculars, Ground	Roof Type/Style Gable	Layers 1 layer
Estimated Age 20+ years	Coverings: Material Metal (lapped seam)	Roof Drainage Systems, Gutters: Gutter Material Seamless Aluminum
Flashings: Material Aluminum	Skylights, Chimneys & Other Roof Penetrations: Chimney Roof Penetration None	Skylights, Chimneys & Other Roof Penetrations: Penetrations Plumbing Vents, Power mast

Limitations

General

SNOW/ICE COVERED

The roof is partially covered with snow/ice. It could not be seen to be fully inspected. Roofing professional is recommended to fully evaluate the roof before closing.

Deficiencies

4.1.1 Coverings

Moderate Concerns/Maintenance Items

ROOF-OLDER

The installed roofing material appears to be older. Metal roofs have a typical service life of 50+ years with proper maintenance. Because of the age of the roof and the state of the rest of the home, a roofing contractor is recommended to evaluate further and determine its remaining useful life as well as perform any needed maintenance.

Recommendation

Contact a qualified roofing professional.

4.2.1 Roof Drainage Systems, Gutters


Moderate Concerns/Maintenance Items

DOWNSPOUTS DRAIN NEAR HOUSE

NE CORNER

One or more downspouts drain too close to the home's foundation and/or deck support footings. This can result in excessive moisture in the soil at the foundation, which can lead to foundation/structural movement and water entry. Recommend a qualified professional adjust downspout extensions to drain at least 6 feet from the foundation.

[Here is a helpful DIY link](#) and video on draining water flow away from your house.



Recommendation

Contact a qualified professional.

4.2.2 Roof Drainage
Systems, Gutters

Moderate Concerns/Maintenance Items

GUTTER DAMAGED

Gutters were damaged/dented/sagging. This can result in overflow and excessive moisture in the soil at the foundation, which can lead to water intrusion foundation/structural movement. It can also damage wood components below and promote water entry. Recommend a gutter contractor evaluate and repair.

Recommendation

Contact a qualified gutter contractor

4.2.3 Roof Drainage Systems,
Gutters

Minor Concerns/Update Items

GUTTERS MISSING

There are no gutters present in one or more areas on the structure. Gutters are recommended because they collect rain water from the roof and direct it away from the building. With no gutters in place, rainwater can fall at the soil directly below deck support footers and foundation walls. This can soften the soil and cause potential structural concerns or water entry. A gutter professional is recommended to install gutters.

Recommendation

Contact a qualified gutter contractor

4.2.4 Roof Drainage
Systems, Gutters

Moderate Concerns/Maintenance Items

GUTTER MISSING END CAP

NW CORNER

The gutter has a missing end cap. A gutter professional is recommended to properly install the end cap to ensure adequate water control.

Recommendation

Contact a qualified gutter contractor



5: DOORS, WINDOWS & INTERIOR

Information

Exterior Doors: Exterior Entry Door Fiberglass, Glass, Hollow Core, Wood	Exterior Doors: Sliding Doors None	Windows: Window Manufacturer Unknown
Windows: Window Type Double-hung, Thermal	Walls: Wall Material Paneling	Ceilings: Ceiling Material Popcorn, Sheetrock
Floors: Floor Coverings Carpet, Hardwood, Tile, Vinyl	Countertops & Cabinets: Cabinetry Wood	Countertops & Cabinets: Countertop Material Laminate

Limitations

General

FURNISHED

This home is fully or partially furnished. Furniture and other items may conceal potential defects that could not be seen or reported.

Deficiencies

5.1.1 Exterior Doors

DOOR DOES NOT CLOSE OR LATCH

SAUNA AREA

Door does not close or latch properly. Recommend qualified handyman adjust strike plate and/or lock to ensure ease of use and security.

[Here is a DIY troubleshooting article](#) on fixing door issues.

Recommendation

Contact a handyman or DIY project

 Minor Concerns/Update Items



5.1.2 Exterior Doors

WATER ENTRY EVIDENT

LOWEST LEVEL ENTRY

Heavy water entry is evident at the base of the lowest level exterior door. This is likely the result of the failed gutter and deteriorating exterior. A general contractor is recommended to evaluate further, determine cause and extent of the damage and repair/replace as needed.

 Moderate Concerns/Maintenance Items



Recommendation

Contact a qualified general contractor.

5.2.1 Interior Doors

DOOR DOESN'T LATCH

LOWER SE BEDROOM. LOWER LEVEL BATHROOM


Door doesn't latch properly. Recommend handyman repair latch and/or strike plate to ensure proper operation.

Recommendation

Contact a handyman or DIY project



Minor Concerns/Update Items



5.2.2 Interior Doors

DOOR STICKS

LOWER, SW BEDROOM, LOWEST LEVEL BATHROOM

Door sticks and is tough to open/close. Recommend adjusting the door in the frame and/or sanding down offending sides.

[Here is a helpful DIY article](#) on how to fix a sticking door.

Recommendation

Contact a handyman or DIY project



Moderate Concerns/Maintenance Items



5.2.3 Interior Doors

BIFOLD DOORS - MISSING

MASTER BEDROOM

The master bedroom has a missing bifold door. Replacement is recommended to ensure full functionality.

Recommendation

Contact a handyman or DIY project



Minor Concerns/Update Items



5.3.1 Windows

FAILED SEAL

LOWER LEVEL DINING AND LIVING ROOM

Observed condensation between the window panes, which indicates a failed seal. Recommend qualified window contractor evaluate & replace to ensure window clarity, thermal integrity and prevent potential water entry and damage.

Note: Windows may just need to be cleaned. Cleaning is recommended before any other action is taken.

Recommendation

Contact a qualified window repair/installation contractor.



Moderate Concerns/Maintenance Items



5.3.2 Windows

WINDOWS WILL NOT STAY OPEN

LOWER LEVEL LIVING ROOM

One or more windows will not stay open when lifted. This is an indication of failed hardware. A window repair specialist is recommended to evaluate further to ensure proper operation.

Recommendation

Contact a qualified window repair/installation contractor.



Moderate Concerns/Maintenance Items



5.4.1 Walls

BOWING WALL PANELS

LOWER, SW BEDROOM



Moderate Concerns/Maintenance Items

The lower level bedroom walls have bowing wall panels. This is an indication of heavy ambient air moisture or water entry from the below grade wall. A general contractor is recommended to evaluate further and determine the cause of the bowing wall panels, remedy and moisture/water issues and repair replace damaged panels. Hidden damage and organic growth may be present behind the walls.



5.5.1 Ceilings

STAIN(S) ON CEILING

LOWER LEVEL LIVING ROOM



Minor Concerns/Update Items

Moisture staining was observed on the ceiling. The stain was inactive when tested with a moisture meter. Verify with the seller that the issue has been resolved. Monitor the area for further evidence of water intrusion. If additional leaking is evident, a qualified professional is recommended to evaluate further.

Recommendation

Contact the seller for more info



5.6.1 Floors

MODERATE WEAR

Moderate Concerns/Maintenance Items

Floors in the home exhibited moderate surface wear along major paths of travel. Recommend a qualified flooring contractor evaluate for possible re-finish.

5.6.2 Floors

MOISTURE DAMAGE

IN FRONT OF HOT TUB AND LOWEST LEVEL TOILET




Moderate Concerns/Maintenance Items

Floors had areas of visible moisture damage and soft areas. Recommend a qualified flooring contractor evaluate & repair areas of moisture.

Recommendation

Contact a qualified flooring contractor



5.6.3 Floors



Moderate Concerns/Maintenance Items

SLOPING FLOOR

There several areas in the home where the floors are sloping or not level. While there is no structural issue evident, you may wish to have the floor system evaluated by a general contractor and leveled out to your satisfaction.

Recommendation

Contact a qualified general contractor.



5.7.1 Steps, Stairways & Railings




Major Defects/Safety Hazards

MISSING RAILING

There is no railing installed on the interior stairway. This is a potential safety/fall hazard. A qualified professional is recommended to install adequate railing.

Recommendation

Contact a qualified professional.



6: BUILT-IN APPLIANCES

Information

Dishwasher: Brand
Whirlpool



Range/Oven/Cooktop: Exhaust
Hood Type
Re-circulate

Range/Oven/Cooktop:
Range/Oven Brand
GE



Range/Oven/Cooktop:
Range/Oven Energy Source
Electric

Garbage Disposal: Garbage
Disposal
Tested, Functional



Washing Machine: Brand
GE



Dryer: Dryer Power Source
220 Electric

Dryer: Dryer Vent
Metal (Flex)

Dryer: Brand
GE



Limitations

General
REFRIGERATOR NOT ON

Deficiencies

6.1.1 Dishwasher

IMPROPERLY INSTALLED DRAIN LINE



Minor Concerns/Update Items

The dishwasher drain line has no high loop installed. This allows water from the sink to drain back into the dishwasher and can allow organic growth build up in the drain line. Installing a high loop is recommended.

[Click here](#) for a DIY resource.

Recommendation

Contact a handyman or DIY project



6.1.2 Dishwasher

IMPROPERLY INSTALLED WIRING



Moderate Concerns/Maintenance Items

Recommendation

Contact a qualified professional.



6.7.1 Dryer

DRYER VENT DUCT TOO LONG



Minor Concerns/Update Items

The dryer vent duct is excessively long. This can cause lint buildup inside the duct and prevent adequate ventilation for the dryer causing potential malfunction. Shortening the duct to ensure the most direct path to the exterior is recommended.




Recommendation

Recommended DIY Project



7: LOWER LEVEL BUILT-IN APPLIANCES

Information

Range/Oven/Cooktop: Exhaust Hood Type None	Range/Oven/Cooktop: Cooktop Brand/Energy Source Electric, GE	Washing Machine: Brand GE
		
Dryer: Dryer Power Source 220 Electric	Dryer: Dryer Vent Vinyl (Flex)	Dryer: Brand GE
		

Limitations

General
REFRIGERATOR NOT ON

Deficiencies


7.7.1 Dryer

DRYER VENT DISCONNECTED

Dryer vent is disconnected or does not vent to the exterior. This can allow a lint build up causing a potential fire hazard and may also cause moisture build-up damaging wood components. Routing the vent directly to the exterior is recommended.

Recommendation

Contact a handyman or DIY project

 Minor Concerns/Update Items



8: FIREPLACE

Information

Type

Gas, Prefabricated, Ventless



Limitations

General

GAS SUPPLY SHUT OFF

Gas supply or pilot light was turned off, so operation of gas fireplaces could not be verified. Recommend having gas supply or pilot light turned on and operation of fireplaces confirmed.

Deficiencies

8.1.1 Firebox/Mantel

CRACKS IN FIREBRICK/PANELS

The firebrick/panels inside the firebox is cracked or has open mortar joints. This is a potential fire hazard as the brick/panel is a barrier between the fire and structure. A professional chimney sweep is recommended to evaluate further.

Recommendation

Contact a qualified chimney sweep.



Major Defects/Safety Hazards



8.3.1 Vents, Flues & Chimneys

NO EXHAUST

The fireplace flue has been removed but has not been properly sealed. This allows the gases, moisture and heat from the logs to vent directly into the attic space. This is a fire hazard. A general contractor is recommended to evaluate further.

Recommendation

Contact a qualified general contractor.



Major Defects/Safety Hazards




9: HVAC

Information

Inspection Method	Heat Systems: Energy Source	Heat Systems: Heat Type
Standard Operation Controls	Electric, Propane	Electric Baseboard, Monitor Heat, Ceiling Heater



Normal Operating Controls:
Thermostat Location(s)
In each room



Limitations

General

SYSTEM SHUT DOWN

MONITOR HEAT

One or more heating systems in the home were shut down or otherwise did not respond with normal controls. You may wish to have a system technician evaluate before closing.



General

WINDOW AC UNIT

This home is equipped with a window AC unit. This system is beyond the scope of a home inspection and was not inspected.



Deficiencies

9.1.1 Heat Systems

INOPERABLE

LOWER AND LOWEST LEVEL BATHROOM CEILING HEATERS

Heating unit was inoperable at time of inspection. Recommend qualified HVAC professional evaluate & ensure functionality.

Recommendation



Contact a qualified HVAC professional.

 Moderate Concerns/Maintenance Items



10: PLUMBING

Information

Filters None	Water Source Public	Main Water Shut-off Device: Location Crawlspace, At street/meter
		
Drain, Waste, & Vent Systems: Material ABS	Water Supply, Distribution Systems & Fixtures: Distribution Material Copper, Pex, Insulated	Water Supply, Distribution Systems & Fixtures: Water Supply Material Poly
Water Supply, Distribution Systems & Fixtures: Fixtures (sinks, tubs, showers, toilets) Traps P-Type	Hot Water Systems, Controls, Flues & Vents: Location Lower level, Closet	Hot Water Systems, Controls, Flues & Vents: Power Source/Type Electric
		
Hot Water Systems, Controls, Flues & Vents: Capacity 50 gallons	Hot Water Systems, Controls, Flues & Vents: Model NE3F50RD 110	Hot Water Systems, Controls, Flues & Vents: Serial 1814109862457
Hot Water Systems, Controls, Flues & Vents: Manufactured year 2018		

Fuel Storage & Distribution Systems: Main Gas Shut-off Location	Fuel Storage & Distribution Systems: Distribution material
Exterior North, Above Ground Tank	CSST

Hot Water Systems, Controls, Flues & Vents: Manufacturer
US Craftmaster

I recommend flushing & servicing your water heater tank annually for optimal performance. Water temperature should be set to at least 120 degrees F to kill microbes and no higher than 130 degrees F to prevent scalding. Replacing the anode rod every 5 years or according to manufacturer recommendations is also recommended. [Here is a nice maintenance guide from Lowe's to help.](#)

Limitations

General

HOT TUB/SAUNA

This home is equipped with am indoor hot tub and sauna. These systems along with support structures, plumbing, and electrical connections are outside the scope of a home inspection. A system professional is strongly advised to fully evaluate before closing.



Deficiencies

10.2.1 Drain, Waste, & Vent Systems

Moderate Concerns/Maintenance Items

LEAKING PIPE

LOWEST LEVEL SHOWER DRAIN LINE

A DWV pipe showed signs of a leak. Recommend a qualified plumber evaluate and repair to prevent additional leaking and potential water damage.

Recommendation
Contact a qualified plumbing contractor.



10.3.1 Water Supply,
Distribution Systems &
Fixtures



Moderate Concerns/Maintenance Items

TOILET LEAKING

LOWEST LEVEL TOILET

Toilet is leaking from the tank. A plumbing contractor is recommended to repair/replace as needed to prevent additional leaking and water damage.

Recommendation

Contact a qualified plumbing contractor.



10.3.2 Water Supply,
Distribution Systems &
Fixtures



Moderate Concerns/Maintenance Items

LEAKING FAUCET

MAIN LEVEL KITCHEN SINK

There is evidence of leaking from the water supply faucet. repair/replacement is recommended to prevent potential water damage to the wall or cabinet below and ensure proper operation.

Recommendation

Contact a qualified professional.



10.3.3 Water Supply, Distribution
Systems & Fixtures



Minor Concerns/Update Items


MISSING CONTROL VALVE

EAST WALL UNDER DECK

One or more exterior hose bibs have missing/damaged water control valves. Replacing the missing/damaged valves is recommended to ensure proper operation.

Recommendation

Recommended DIY Project



10.3.4 Water Supply,
Distribution Systems &
Fixtures



Moderate Concerns/Maintenance Items

MALFUNCTIONING DIVERTER

LOWER LEVEL SHOWER

The shower diverter did not function properly when tested.

Repair/replacement is recommended to ensure proper operation and ease-of-use

Recommendation

Contact a qualified professional.



10.5.1 Fuel Storage & Distribution Systems

CSST NOT BONDED



Major Defects/Safety Hazards

The gas piping system of this home includes corrugated stainless steel tubing (CSST). This flexible gas line system has specific installation requirements related to electrical bonding, designed to reduce the potential for lightning related electrical arcing that can perforate the tubing and result in gas leaks or fires. During the home inspection, the CSST could not be verified to be integrally bonded or to have a bonding attachment. An electrical contractor should be consulted for a complete evaluation of the CSST installation to ensure the presence of an electrical bonding path.

Recommendation


Contact a qualified electrical contractor.

11: ELECTRICAL

Information

Main Disconnect Breaker
Location

Interior, Main Panel



Service Entrance Conductors:
Electrical Service Conductors

Overhead, Aluminum, 240 Volts

Main & Subpanels, Service &
Grounding, Main Overcurrent
Device: Main Panel Location

Lower Level, Closet



Main & Subpanels, Service &
Grounding, Main Overcurrent
Device: Panel Capacity

200 AMP

Main & Subpanels, Service &
Grounding, Main Overcurrent
Device: Panel Manufacturer

Cutler Hammer

Main & Subpanels, Service &
Grounding, Main Overcurrent
Device: Panel Type

Circuit Breaker

Main & Subpanels, Service &
Grounding, Main Overcurrent
Device: Sub Panel Location

Crawl space

Branch Wiring Circuits, Breakers
& Fuses: Branch Wire 15 and 20
AMP

Copper

Branch Wiring Circuits, Breakers
& Fuses: Wiring Method

Conduit, Romex





Smoke/CO Detectors: Inspection
Method

Not tested

Main & Subpanels, Service & Grounding, Main Overcurrent Device: Front Cover Removed for Inspection?

Yes



Deficiencies

11.3.1 Branch Wiring Circuits,
Breakers & Fuses



Major Defects/Safety Hazards

IMPROPER WIRING

CRAWL SPACE SUB PANEL

The sub panel is improperly wired. The grounds and neutrals are not separated/isolated. This is a potential safety hazard if there is ever an over current event such as a lightning strike. A licensed electrician is recommended to evaluate further.

Recommendation

Contact a qualified electrical contractor.




11.3.2 Branch Wiring Circuits,
Breakers & Fuses



Major Defects/Safety Hazards

DOUBLE TAP

The electric system has one or more breakers that are double tapped. This means that two conductors are installed into one breaker that is only designed to hold one conductor. This is a potential safety hazard as it can cause arcing or overheating. A licensed electrician is recommended to evaluate and repair/replace as needed.



Recommendation

Contact a qualified electrical contractor.

11.4.1 Lighting Fixtures, Switches & Receptacles

COVER PLATES MISSING

CLOSETS, DINING ROOM, CRAWL SPACE


One or more receptacles are missing a cover plate. This causes short and shock risk. Recommend installation of plates.

Recommendation

Contact a handyman or DIY project



Minor Concerns/Update Items

11.4.2 Lighting Fixtures,
Switches & Receptacles

Moderate Concerns/Maintenance Items

DROOPING CEILING FAN

LOWER LEVEL LIVING ROOM

The ceiling fan in the lower level has drooping fan blades. This is an indication of heavy moisture in this level and can cause the fan to malfunction. A qualified professional is recommended to repair/replace as needed.

Recommendation

Contact a qualified professional.



11.5.1 GFCI & AFCI

MISSING GFCI PROTECTION

KITCHENS, BATHROOMS, EXTERIOR

GFCI protected receptacles were missing in one or more recommended areas in the home. GFCI receptacles help protect against potential shock hazards in areas near water. A licensed electrician is recommended to update all receptacle in the recommended areas.


[Here is a link](#) to read about how GFCI receptacles keep you safe.

Recommendation

Contact a qualified electrical contractor.



Minor Concerns/Update Items



11.5.2 GFCI & AFCI

GFCI RECEPTACLE - DID NOT TRIP/RESET

LOWEST LEVEL BATHROOM


One or more GFCI receptacles did not trip/reset when tested. A licensed electrician is recommended to evaluate further and repair/replace as needed to alleviate potential safety concerns and ensure proper operation.

Recommendation

Contact a qualified electrical contractor.



Moderate Concerns/Maintenance Items



11.6.1 Smoke/CO Detectors

OLDER SMOKE ALARMS


The installed smoke alarms appear to be older than 10 years. Replacing smoke alarms every 10 years is recommended as they lose sensitivity over time.

Recommendation

Recommended DIY Project



Minor Concerns/Update Items



11.6.2 Smoke/CO Detectors

NO CO DETECTORS INSTALLED

There are no permanently installed CO detectors in the home. This is a potential safety concern as fuel burning appliances are in use. Installing CO detectors according to manufacturers instructions is recommended.

Recommendation



Contact a handyman or DIY project



Moderate Concerns/Maintenance Items

12: ATTIC AND ROOF STRUCTURE

Information

Attic Access Scuttlehole/Hatch	Location of Attic Access Bedroom Closet	Inspected From From Access Panel
		
Attic Insulation: Insulation Type/Depth Batt, Fiberglass, 10-15 Inches	Attic Insulation: Insulation Installed In Between Ceiling Joists	Ventilation: Ventilation Type Gable Vents, Passive
Exhaust Systems: Exhaust Fans Fan/Heat/Light	Roof Structure: Material Plywood, Trusses	Roof Structure: Type Gable
Ceiling Structure: Type Of Ceiling Structure Conventional		

Deficiencies

12.3.1 Exhaust Systems

Moderate Concerns/Maintenance Items

BATHROOM VENTS INTO ATTIC

Bathroom fan vents into the attic, which can cause moisture and organic growth. Recommend a qualified professional property install exhaust fan to terminate to the exterior.

Recommendation

Contact a qualified professional.

12.3.2 Exhaust Systems

Moderate Concerns/Maintenance Items


BATHROOM VENT INOPERABLE

MAIN LEVEL VENT FAN

The bathroom vent fan did not function properly when tested. A licensed electrician is recommended to evaluate further and repair/replace as needed to ensure proper operation and alleviate potential safety concerns.

Recommendation

Contact a qualified electrical contractor.



13: BASEMENT, FOUNDATION, CRAWLSPACE & STRUCTURE

Information

Conditioned Not conditioned	Foundation: Foundation Type Crawl Space	Foundation: Foundation Wall CMU
Floor Structure: Basement/Crawlspace Floor Dirt	Floor Structure: Floor Structure Material Wood Beams, 2x10 Joists, Steel Columns	Floor Structure: Sub-floor Inaccessible, Plywood
Insulation: Flooring Insulation Batt, Fiberglass	Ventilation: Type Wall Vents	
Inspection Method Visual, Inspected From Inside		



Deficiencies

13.1.1 Foundation

FOUNDATION CRACKS - MAJOR

NORTH WALL, NW CORNER, WEST WALL

Severe cracking noted at the foundation. This is typically consistent with soil movement and could lead to serious damage to structural components, foundation and/or slabs. Recommend a structural engineer evaluate and provide a report on course of action and remedy.

[Here is an informational article](#) on foundation cracks.

Major Defects/Safety Hazards



North Wall, left of lowest level entry.

NW Corner

Middle of West Wall

13.1.2 Foundation

FOUNDATION WALL WATER INTRUSION

NW AND SW CORNERS



Moderate Concerns/Maintenance Items

Water intrusion is evident through the foundation wall with darker stains and efflorescence. This is an indication of inadequate exterior drainage. Moisture in a crawlspace/basement can cause potential organic growth and damage to wood components. A grading or basement professional is recommended to evaluate further.

Recommendation

Contact a qualified grading contractor.



13.2.1 Floor Structure

MODIFIED CONSTRUCTION

WEST CRAWL SPACE AREA, HOT TUB SUPPORT STRUCTURE.



Major Defects/Safety Hazards

The floor structure has areas of modified or added supports. This is an indication of previous structural issues in the home. Verify with the seller what structural issues are present. A general contractor or structural engineer is recommended to evaluate further.

Recommendation

Contact a qualified structural engineer.



13.2.2 Floor Structure

SUBFLOOR - WATER STAINS/DAMAGE

UNDER HOT TUB AND LOWEST LEVEL ENTRY DOOR



Major Defects/Safety Hazards

There is water staining/damage on the subfloor visible from the crawl space. This is an indication of potential leaking from the exterior and plumbing leaks. A general contractor is recommended to evaluate further to determine the extent of the damage and repair/replace as needed. Hidden damage may be present under the insulation

Recommendation

Contact a qualified general contractor.



13.3.1 Insulation

FALLING/DAMAGED INSULATION





Moderate Concerns/Maintenance Items

There are areas of falling, damaged or missing insulation under the home. This can make the home less energy efficient and is an indication of inadequate ventilation and/or moisture control. An insulation professional is recommended to evaluate further.

Recommendation

Contact a qualified insulation contractor.



13.5.1 Vapor Retarders (Crawlspace or Basement)

DISPLACED

Moderate Concerns/Maintenance Items

The vapor barrier in the crawl space is displaced and missing in several areas. This can allow harmful moisture to enter the crawl space and cause damage, organic growth, and unhealthy living conditions. replacing or adding additional vapor barrier to cover the entire floor space is recommended.

Recommendation

Contact a qualified insulation contractor.



STANDARDS OF PRACTICE

Inspection Details

.1102 STANDARDS OF PRACTICE

This Section sets forth the minimum standards of practice required of licensed home inspectors. In this Section, the term "home inspectors" means licensed home inspectors.

.1103 PURPOSE AND SCOPE

- (a) Home inspections performed according to this Section shall provide the client with an understanding of the property conditions, as inspected at the time of the home inspection.
- (b) Home inspectors shall:
 - (1) provide a written contract, signed by the client, before the home inspection is performed that shall:
 - (A) State that the home inspection is in accordance with the Standards of Practice of the North Carolina Home Inspector Licensure Board as set forth in this Section;
 - (B) State what services shall be provided and the cost; and
 - (C) When an inspection is for only one or a limited number of systems or components, state that the inspection is limited to only those systems or components;
 - (2) inspect readily visible and readily accessible installed systems and components described in Rules .1106 through .1115 of this Section;
 - (3) submit a written report, pursuant to G.S. 143-151.58(a), to the client that shall:
 - (A) Describe those systems and components required to be described in Rules .1106 through .1115 of this Section;
 - (B) State which systems and components present at the home and designated for inspection in this Section were not inspected, and the reason for not inspecting;
 - (C) State any systems or components inspected that do not function as intended, allowing for normal wear and tear, or appear not to function as intended, based upon documented tangible evidence;
 - (D) Describe each system or component, pursuant to Part (b)(3)(C) of this Rule; state how the condition is defective; explain the implications of defective conditions reported; and direct the client to a course of action for repair, monitoring, or further investigation by a specialist;
 - (E) State the name, license number, and signature of the person conducting the inspection.
 - (4) submit a summary page(s) pursuant to G.S. 143-151.58(a1).
- (c) Home inspectors may:
 - (1) report observations and conditions, including safety or habitability concerns, or render opinions of items in addition to those required in Paragraph (b) of this Rule; or
 - (2) exclude systems and components from the inspection if requested by the client, and so stated in the written contract.

.1104 GENERAL LIMITATIONS

- (a) Home inspections done in accordance with this Section are not technically exhaustive.
- (b) This Section applies to buildings with four or fewer dwelling units, and individually owned residential units within multi-family buildings, and their attached garages or carports.

.1105 GENERAL EXCLUSIONS:

- (a) Home inspectors are not required to report on:
 - (1) Life expectancy of any component or system;
 - (2) The causes of the need for a repair;
 - (3) The methods, materials, and costs of corrections;
 - (4) The suitability of the property for any specialized use;
 - (5) Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements, or restrictions;
 - (6) The market value of the property or its marketability;
 - (7) The advisability or inadvisability of purchase of the property;
 - (8) Any component or system that was not inspected;
 - (9) The presence or absence of pests such as wood damaging organisms, rodents, or insects; or
 - (10) Cosmetic damage, underground items, or items not installed; or
 - (11) The presence or absence of systems installed to control or remove suspected hazardous substances listed in Subparagraph (b)(7) of this Rule.
- (b) Home inspectors are not required to:
 - (1) Offer warranties or guarantees of any kind;
 - (2) Calculate the strength, adequacy, or efficiency of any system or component;
 - (3) Enter any area or perform any procedure that may damage the property or its components or

be dangerous to or adversely affect the health or safety of the home inspector or other persons;

- (4) Operate any system or component that is shut down or otherwise inoperable;
- (5) Operate any system or component that does not respond to normal operating controls;
- (6) Move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility;
- (7) Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including mold, toxins, carcinogens, noise, contaminants in the building or in soil, water, and air;
- (8) Determine the effectiveness of any system installed to control or remove suspected hazardous substances;
- (9) Determine House Energy Ratings (HER), insulation R values, system or component efficiencies;
- (10) Inspect heat recovery and similar whole house ventilation systems;
- (11) Predict future condition, including failure of components;
- (12) Project operating costs of components;
- (13) Evaluate acoustical characteristics of any system or component;
- (14) Inspect equipment or accessories that are not listed as components to be inspected in this Section; or
- (15) Disturb insulation, except as required in Rule .1114 of this Section.

(c) Home inspectors shall not:

- (1) Offer or perform any act or service contrary to law; or
- (2) Offer or perform engineering, architectural, plumbing, electrical, or any other job function requiring an occupational license in the jurisdiction where the inspection is taking place, unless the home inspector holds a valid occupational license. In that case the home inspector shall inform the client that the home inspector is so licensed, and therefore qualified to go beyond this Section and perform additional inspections beyond those within the scope of the Standards of Practice.

.1116 CODE OF ETHICS

- (a) Licensees shall discharge their duties with fidelity to the public and to their clients, with fairness and impartiality to all.
- (b) Opinions expressed by licensees shall be based only on their education, experience, and honest convictions.
- (c) A licensee shall not disclose any information about the results of an inspection without the approval of the client for whom the inspection was performed, or the client's representative.
- (d) No licensee shall accept compensation or any other consideration from more than one interested party for the same service without the written consent of all interested parties.
- (e) No licensee shall compensate, either financially or through other services or benefits, realty agents or other parties with a financial interest in closing or settlement of real estate transactions for the following:
 - (1) Referral of inspections; or
 - (2) Inclusion on a list of recommended inspectors or preferred providers.
- (f) No licensee shall express, within the context of an inspection, an appraisal or opinion of the market value of the inspected property.
- (g) Before the execution of a contract to perform a home inspection, a licensee shall disclose to the client any interest he or she has in a business that may create a conflict of interest for the home inspector. No licensee shall allow his or her interest in any business to affect the quality or results of the inspection work that the licensee may be called upon to perform.
- (h) A licensee shall not solicit for repairs of systems or components found defective in the course of a home inspection performed by the licensee or that licensee's company.
- (i) Licensees shall not engage in false or misleading advertising or otherwise misrepresent any matters to the public.
- (j) Licensees shall not inspect properties under contingent arrangements whereby any compensation or future referrals are dependent on reported findings or on the sale of a property.
- (k) A licensee shall not impugn the professional reputation or practice of another home inspector, nor criticize another inspector's reports.

Exterior

.1107 EXTERIOR

(a) The home inspector shall inspect:

- (1) Wall cladding, flashings, and trim;
- (2) Entryway doors and a representative number of windows;
- (3) Garage door operators;
- (4) Decks, balconies, stoops, steps, areaways, porches, and appurtenant railings;
- (5) Eaves, soffits, and fascias;
- (6) Driveways, patios, walkways, and retaining walls; and
- (7) Vegetation, grading, and drainage with respect only to their effect on the condition of

the building.

(b) The home inspector shall:

- (1) Describe wall cladding materials;
- (2) Operate all entryway doors;
- (3) Operate garage doors manually or by using installed controls for any garage door operator;
- (4) Report whether or not any garage door operator will automatically reverse or stop when meeting reasonable resistance during closing; and
- (5) Probe exterior wood components where deterioration is suspected.

(c) The home inspector is not required to inspect:

- (1) Storm windows, storm doors, screening, shutters, and awnings;
- (2) Fences;
- (3) For the presence of safety glazing in doors and windows;
- (4) Garage door operator remote control transmitters;
- (5) Geological conditions;
- (6) Soil conditions;
- (7) Recreational facilities (including spas, saunas, steam baths, swimming pools, tennis courts, playground equipment, and other exercise, entertainment, or athletic facilities), except as otherwise required in 11 NCAC 8.1109(d)(5)(F);
- (8) Detached buildings or structures; or
- (9) For the presence or condition of buried fuel storage tanks.

Roof

.1108 ROOFING

(a) The home inspector shall inspect:

- (1) Roof coverings;
- (2) Roof drainage systems;
- (3) Flashings;
- (4) Skylights, chimneys, and roof penetrations; and
- (5) Signs of leaks or abnormal condensation on building components.

(b) The home inspector shall:

- (1) Describe the type of roof covering materials; and
- (2) Report the methods used to inspect the roofing.

(c) The home inspector is not required to:

- (1) Walk on the roofing; or
- (2) Inspect attached accessories including solar systems, antennae, and lightning arrestors.

Doors, Windows & Interior

.1113 INTERIORS

(a) The home inspector shall inspect:

- (1) Walls, ceiling, and floors;
- (2) Steps, stairways, balconies, and railings;
- (3) Counters and a representative number of built-in cabinets; and
- (4) A representative number of doors and windows.

(b) The home inspector shall:

- (1) Operate a representative number of windows and interior doors; and
- (2) Report signs of water penetration into the building or signs of abnormal or harmful condensation on building components.

(c) The home inspector is not required to inspect:

- (1) Paint, wallpaper, and other finish treatments on the interior walls, ceilings, and floors;
- (2) Carpeting; or
- (3) Draperies, blinds, or other window treatments; or
- (4) Coatings on and hermetic seals between panes of glass in windows and doors.

Built-in Appliances

.1115 BUILT-IN KITCHEN APPLIANCES

(a) The home inspector shall inspect and operate the basic functions of the following kitchen appliances:

- (1) Installed dishwasher(s), through a complete cycle;
- (2) Range(s), cook top(s), and permanently installed oven(s);
- (3) Trash compactor(s);
- (4) Garbage disposal(s);
- (5) Ventilation equipment or range hood(s); and
- (6) Installed microwave oven(s).

(b) The home inspector is not required to inspect:

- (1) Clocks, timers, self-cleaning oven functions, or thermostats for calibration or automatic

operation;

(2) Non built-in appliances; or

(3) Refrigeration units.

(c) The home inspector is not required to operate:

(1) Appliances in use; or

(2) Any appliance that is shut down or otherwise inoperable.

Lower Level Built-in Appliances

.1115 BUILT-IN KITCHEN APPLIANCES

(a) The home inspector shall inspect and operate the basic functions of the following kitchen appliances:

(1) Installed dishwasher(s), through a complete cycle;

(2) Range(s), cook top(s), and permanently installed oven(s);

(3) Trash compactor(s);

(4) Garbage disposal(s);

(5) Ventilation equipment or range hood(s); and

(6) Installed microwave oven(s).

(b) The home inspector is not required to inspect:

(1) Clocks, timers, self-cleaning oven functions, or thermostats for calibration or automatic operation;

(2) Non built-in appliances; or

(3) Refrigeration units.

(c) The home inspector is not required to operate:

(1) Appliances in use; or

(2) Any appliance that is shut down or otherwise inoperable.

Fireplace

.1111 HEATING (a) The home inspector shall inspect permanently installed heating systems including: (1) Heating equipment; (2) Normal operating controls; (3) Automatic safety controls; (4) Chimneys, flues, and vents, where readily visible; (5) Solid fuel heating devices; (6) Heat distribution systems including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units, convectors; and (7) The presence or absence of an installed heat source for each habitable space. (b) The home inspector shall describe the: (1) Energy source; and (2) Heating equipment and distribution type. (c) The home inspector shall operate the systems using normal operating controls appropriate to weather conditions at the time of the inspection. (d) The home inspector shall open readily openable access panels provided by the manufacturer or installer for routine homeowner maintenance. The home inspector shall report the method of inspection used to inspect the heating system and whether or not access panels were removed. (e) The home inspector is not required to: (1) Operate heating systems when weather conditions or other circumstances may cause equipment damage or when inappropriate to weather conditions at the time of inspection; (2) Operate automatic safety controls; (3) Ignite or extinguish solid fuel fires; or (4) Ignite a pilot light; or (5) Inspect: (A) The interior of flues; (B) Fireplace insert flue connections; (C) Heat exchanges; (D) Humidifiers; (E) Electronic air filters; (F) The uniformity or adequacy of heat supply to the various rooms; or (G) Solar space heating equipment.

HVAC

.1111 HEATING

(a) The home inspector shall inspect permanently installed heating systems including:

(1) Heating equipment;

(2) Normal operating controls;

(3) Automatic safety controls;

(4) Chimneys, flues, and vents, where readily visible;

(5) Solid fuel heating devices;

(6) Heat distribution systems including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units, convectors; and

(7) The presence or absence of an installed heat source for each habitable space.

(b) The home inspector shall describe the:

(1) Energy source; and

(2) Heating equipment and distribution type.

(c) The home inspector shall operate the systems using normal operating controls appropriate to weather conditions at the time of the inspection.

(d) The home inspector shall open readily openable access panels provided by the manufacturer or installer for routine homeowner maintenance. The home inspector shall report the method of inspection used to inspect the heating system and whether or not access panels were removed.

(e) The home inspector is not required to:

(1) Operate heating systems when weather conditions or other circumstances may cause equipment damage or when inappropriate to weather conditions at the time of inspection;

(2) Operate automatic safety controls;

(3) Ignite or extinguish solid fuel fires; or

- (4) Ignite a pilot light; or
- (5) Inspect:
 - (A) The interior of flues;
 - (B) Fireplace insert flue connections;
 - (C) Heat exchanges;
 - (D) Humidifiers;
 - (E) Electronic air filters;
 - (F) The uniformity or adequacy of heat supply to the various rooms; or
 - (G) Solar space heating equipment.

.1112 AIR CONDITIONING

- (a) The home inspector shall inspect:
 - (1) Central air conditioning and through-the-wall ductless installed cooling systems including:
 - (A) Cooling and air handling equipment; and
 - (B) Normal operating controls.
 - (2) Cooling distribution systems including:
 - (A) Fans, pumps, ducts and piping, with associated supports, dampers, insulation, air filters, registers, fan- coil units; and
 - (B) The presence or absence of an installed cooling source for each habitable space.
- (b) The home inspector shall describe the:
 - (1) Energy sources; and
 - (2) Cooling equipment type.
- (c) The home inspector shall operate the systems using normal operating controls appropriate to weather conditions at the time of the inspection.
- (d) The home inspector shall open readily openable access panels provided by the manufacturer or installer for routine homeowner maintenance. The home inspector shall report the method used to inspect the air conditioning system and whether or not access panels were removed.
- (e) The home inspector is not required to:
 - (1) Operate cooling systems when weather conditions or other circumstances may cause equipment damage;
 - (2) Inspect window air conditioners; or
 - (3) Inspect the uniformity or adequacy of cool-air supply to the various rooms.

Plumbing

.1109 PLUMBING

- (a) The home inspector shall inspect:
 - (1) Interior water supply and distribution system, including: piping materials, supports, and insulation; fixtures and faucets; functional flow; leaks; and cross connections;
 - (2) Interior drain, waste, and vent system, including: traps; drain, waste, and vent piping; piping supports and pipe insulation; leaks; and functional drainage;
 - (3) Hot water systems including: water heating equipment; normal operating controls; automatic safety controls; and chimneys, flues, and vents;
 - (4) Fuel storage and distribution systems including: interior fuel storage equipment, supply piping, venting, and supports; leaks; and
 - (5) Sump pumps.
- (b) The home inspector shall describe:
 - (1) Water supply and distribution piping materials;
 - (2) Drain, waste, and vent piping materials;
 - (3) Water heating equipment, including fuel or power source, storage capacity or tankless point of use demand systems, and location; and
 - (4) The location of any main water supply shutoff device.
- (c) The home inspector shall operate all plumbing fixtures, including their faucets and all exterior faucets attached to the house, except where the flow end of the faucet is connected to an appliance.
- (d) The home inspector is not required to:
 - (1) State the requirement for or effectiveness of anti-siphon devices;
 - (2) Determine whether water supply and waste disposal systems are public or private or the presence or absence of backflow devices;
 - (3) Operate automatic safety controls;
 - (4) Operate any valve except water closet flush valves, fixture faucets, and hose faucets;
 - (5) Inspect:
 - (A) Water conditioning systems;
 - (B) Fire and lawn sprinkler systems;
 - (C) On-site water supply quantity and quality;
 - (D) On-site waste disposal systems;
 - (E) Foundation irrigation systems;
 - (F) Bathroom spas, whirlpools, or air jet tubs except as to functional flow and functional

drainage;

- (G) Swimming pools;
- (H) Solar water heating equipment; or
- (I) Fixture overflow devices or shower pan liners;
- (6) Inspect the system for proper sizing, design, or use of materials.
- (7) Report on the absence or presence of thermal expansion tanks; or,
- (8) Report on the adequacy of the reported water heater capacity.

Electrical

.1110 ELECTRICAL

(a) The home inspector shall inspect:

- (1) Electrical service entrance conductors;
- (2) Electrical service equipment, grounding equipment, main overcurrent device, and interiors of panelboard enclosures unless unsafe conditions are reported;
- (3) Amperage and voltage ratings of the electrical service;
- (4) Branch circuit conductors, their overcurrent devices, and the compatibility of their ampacities at the interiors of panelboard enclosures unless unsafe conditions are reported;
- (5) The operation of a representative number of installed ceiling fans, lighting fixtures, switches, and receptacles located inside the house, garage, and on the dwelling's exterior walls;
- (6) The polarity and grounding of all receptacles within six feet of interior plumbing fixtures, and all receptacles in the garage or carport, and on the exterior of inspected structures;
- (7) The operation of ground fault circuit interrupters; and
- (8) Smoke detectors and installed carbon monoxide alarms.

(b) The home inspector shall describe:

- (1) Electrical service amperage and voltage;
- (2) Electrical service entry conductor materials;
- (3) The electrical service type as being overhead or underground; and
- (4) The location of main and distribution panels.

(c) The home inspector shall report in writing the presence of any readily accessible single strand aluminum branch circuit wiring.

(d) The home inspector shall report in writing on the presence or absence of smoke detectors, and installed carbon monoxide alarms in any homes with fireplaces, fuel fired appliances, or attached garages, and operate their test function, if readily accessible, except when detectors are part of a central system.

(e) The home inspector is not required to:

- (1) Insert any tool, probe, or testing device inside the panels;
- (2) Test or operate any overcurrent device except ground fault circuit interrupters;
- (3) Dismantle any electrical device or control other than to remove the covers of panelboard enclosures; or
- (4) Inspect:
 - (A) Low voltage systems;
 - (B) Security systems and heat detectors;
 - (C) Telephone, security, cable TV, intercoms, or other ancillary wiring that is not a part of the primary electrical distribution system;
 - (D) Built-in vacuum equipment;
 - (E) Back up electrical generating equipment;
 - (F) Other alternative electrical generating or renewable energy systems such as solar, wind, or hydro power;
 - (G) Battery or electrical automotive charging systems; or

(H) Electrical systems to swimming pools or spas, including bonding and grounding.

Attic and Roof Structure

.1114 INSULATION AND VENTILATION

(a) The home inspector shall inspect:

- (1) Insulation and vapor retarders in unfinished spaces;
- (2) Ventilation of attics and foundation areas;
- (3) Kitchen, bathroom, and laundry venting systems; and
- (4) The operation of any readily accessible attic ventilation fan, and, when temperature permits, the operation of any readily accessible thermostatic control.

(b) The home inspector shall describe:

- (1) Insulation in unfinished spaces; and
- (2) The absence of insulation in unfinished space at conditioned surfaces.

(c) The home inspector is not required to report on:

- (1) Concealed insulation and vapor retarders; or
- (2) Venting equipment for household appliances that are not required to be inspected pursuant to the North Carolina Home Inspector Standards of Practice.

(d) The home inspector shall:

- (1) Move insulation where readily visible evidence indicates a problem; and
- (2) Move floor insulation where plumbing drain/waste pipes penetrate floors, adjacent to earth-filled stoops or porches, and at exterior doors.

Basement, Foundation, Crawlspace & Structure

.1106 STRUCTURAL COMPONENTS

(a) The home inspector shall inspect structural components including:

- (1) Foundation;
- (2) Floors;
- (3) Walls;
- (4) Columns or piers;
- (5) Ceilings; and
- (6) Roofs.

(b) The home inspector shall describe the type of:

- (1) Foundation;
- (2) Floor structure;
- (3) Wall structure;
- (4) Columns or piers;
- (5) Ceiling structure; and
- (6) Roof structure.

(c) The home inspector shall:

- (1) Probe structural components where deterioration is suspected;
- (2) Enter under floor crawl spaces, basements, and attic spaces except when access is obstructed, when entry could damage the property, or when dangerous or adverse situations are suspected;
- (3) Report the methods used to inspect under floor crawl spaces and attics; and
- (4) Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful building components.