

# Virtual Connect Manager May be Unable to Communicate (NO\_COMM)

Last week when I was working on my LAB I found a pretty interesting status message on my VCM. By the by I am using a C7000 enclosure and mixed of total 10 blades which combines half height and full height.


So now when I look at the Status message of my enclosure domain I found there is no communication from VC (Virtual Connect).

I started having a hard time finding what happened to our VCM (Virtual Connect Ethernet Module). All of a sudden we lost communications to our servers and while investigating I can see that both our VC is showing it is gone. Below are the screenshots. While I went back to my enclosure it is showing me the LAN connections are blinking. So now am completely confused as to what direction I need to go for.

















Further troubleshooting revealed that apparently there is some problem with the DNS and it is a known issue. So digging to it we got the external CA ([Customer Advisory](#)) out which talked about this. So now there could be two ways to get out of it.

Quick fix is to disable DNS on all the Virtual Connect Modules. Permanent fix is to upgrade to VC 3.17 firmware. I immediately started working on the first option which would not have create any issues at all. So I went ahead to the Enclosure Settings > Enclosure Bay IP Addressing and then looked under the "Interconnect Bays" tab and removed DNS server IP address entries from the bays that include VC Ethernet Modules and clicked Apply.

Within 5 minutes, the DNS settings for the modules get updated and normal module communication has been restored. If that does not happen then from the VCM GUI, select "Tools" => "Reset Virtual Connect Manager." This will force resynchronization of the modules if not synchronized already.



## OAC7K [REDACTED]\_vc\_domain Domain Status

Domain Alerts				
Device Name	Status	Log Severity	Device Type	Enclosure
 OAC7K [REDACTED]	Failed	Critical	Enclosure	OAC7K [REDACTED]
 Profile_Bay15	Degraded	Minor	Server Profile	
 Profile_Bay16	Degraded	Minor	Server Profile	
 Profile_Bay3	Degraded	Minor	Server Profile	
 Profile_Bay4	Degraded	Minor	Server Profile	
 Profile_Bay5	Degraded	Minor	Server Profile	
 Profile_Bay6	Degraded	Minor	Server Profile	
 Profile_Bay7	Degraded	Minor	Server Profile	
 Profile_Bay8	Degraded	Minor	Server Profile	
 Profile_Bay1	Degraded	Minor	Server Profile	
 Profile_Bay2	Degraded	Minor	Server Profile	
 Management	Unknown	Unknown	Ethernet Network	
 Production	Unknown	Unknown	Ethernet Network	
 iSCSI-Traffic	Unknown	Unknown	Ethernet Network	
 Bay 1 (HP VC Flex-10 Enet Module)	No Communication	Major	Interconnect Bay	OAC7K [REDACTED]
 Bay 2 (HP VC Flex-10 Enet Module)	No Communication	Major	Interconnect Bay	OAC7K [REDACTED]

**Domain Status**

Domain Status: 1 2 10 0 3 0

[View Legend...](#)

**Elements and Events**

- VMotion
- SAN Fabrics
  - Labfabric1
  - Labfabric2
- Hardware Overview
  - OAC7K
- Interconnect Bays
  - Bay 1 (HP VC Flex-10 Enet)
  - Bay 2 (HP VC Flex-10 Enet)
  - Bay 3 (HP Virtual Connect)
  - Bay 4 (HP Virtual Connect)
- Device Bays
  - Bay 1 (ProLiant xw460c BL)
  - Bay 2 (ProLiant xw460c BL)
  - Bay 3 (ProLiant BL680c G5)
  - Bay 4 (ProLiant BL680c G5)
  - Bay 5 (ProLiant BL680c G5)
  - Bay 6 (ProLiant BL685c G5)

Define ▾ Configure ▾ Tools ▾ Help ▾













## Bay 2 (HP VC Flex-10 Enet Module)

**Interconnect Bay Status - Bay 2 (HP VC Flex-10 Enet Module)**

Overall Status:	No Communication
Hardware Status:	OK
VC Status:	No Communication
OA Communication Status:	Failed
Rack Name:	OAC7K
Enclosure Name:	OAC7K
Bay:	Bay 2
Power Status/Control:	On

**Interconnect Bay Information - Bay 2 (HP VC Flex-10 Enet Module)**

Part Number:	455880-B21
Product Name:	HP VC Flex-10 Enet Module
Serial Number:	TVW20170074
Dip Switch Setting:	0x0
Spare Part Number:	456095-001
Manufacturer:	HP
Firmware Rev.	3.15 2010-10-09T07:18:16Z


Interconnect Bays Summary				
Bay	Status	Module	Power	Firmware Rev.
Bay 1 (LAN)	 No Communication	 HP VC Flex-10 Enet Module	 On	3.15 2010-10-09T07:18:16Z
Bay 2 (LAN)	 No Communication	 HP VC Flex-10 Enet Module	 On	3.15 2010-10-09T07:18:16Z
Bay 3 (SAN)	 OK	 HP Virtual Connect 4Gb FC Module	 On	1.41 7.12.4.11
Bay 4 (SAN)	 OK	 HP Virtual Connect 4Gb FC Module	 On	1.41 7.12.4.11

OAC7K

Enclosure Information

Enclosure Status

## Enclosure Overview

Overall Status:  FailedHardware Status:  OKVC Status:  FailedOA Communication Status:  OK

