

Fixed Issues R511.2_SCN_to_R511.4_SCN

PAR	Impact	Subsystem	Description	Release	Unnamed: 0
1-ESD7I83	Engineering/ Configuration	CE900-IO	Single Channel Download.	R520.1_TCU2_SCN	nan
1-ASYXVEB	System Stability	Standard Series C IO Modules	Redundant DI-24V (DC-PDIL51), R520.1_TCU2_SCN	R520.1_TCU2_SCN	Onwards randomly on IOLINK violet.
1-E9OAOLH	System Stability	I/O-Series C	Series C Mark II DC-PDIL51 Module turns the system a power cycle	R520.1_TCU2_SCN	of the system.
1-CZ28NXD	System Stability	Fieldbus Interface Module-Series C	AO block went to 3354 error device after the FIM8/FIM4 switchover	R520.1_TCU2_SCN	and all the AO are freezed.
1-EICDGNJ	Engineering/ Configuration	Control Builder	Not able to load IO Ref due to Link error	R520.1_TCU2_SCN	nan
1-E8Q4OZZ	Engineering/ Configuration	Control Builder	After download of AIREF from project the Values SOURCE and SRCOPT do not update in Monitor	R520.1_TCU2_SCN	
1-E9QUJJR	System Stability	Fieldbus Interface Module	Primary FIM8 module failed with error code 1	R520.1_TCU2_SCN	nan
1-ECGZSTH	System Stability	ELCN-Bridge	ELCN Bridge not bridging anymore after the transmit buffers	R520.1_TCU2_SCN	nan
1-EDVVU7Z	System Stability	ELCN-Bridge	ELCN Bridge still uses Cable A, R520.1_TCU2_SCN had improper connection and Cable B was good.	R520.1_TCU2_SCN	
1-DNGQNEF	Usability	ModBus TCP Blocks	PCDI PV scaling is not working as expected	R520.1_TCU2_SCN	nan
1-EF6I9U9	System Stability	CDA- Embedded	FIM does not initiate connection with CDA	R520.1_TCU2_SCN	FIM is working.
1-E6WJ8CF	Engineering/ Configuration	CTools	Need introduce CC-PAIH51 firmwares to Series 8 to solve the supply chain shortage.	R520.1_TCU2_SCN	
1-EH3B4BV	Migration	OPM- Controller Migration	Need to support R501.6 HF8 to R520.1_TCU2_SCN	R520.1_TCU2_SCN	nan
1-EHCHK3X	Usability	OPM- Controller Migration	Need to support R511.4 HF7 to R520.1_TCU2_SCN	R520.1_TCU2_SCN	nan
1-EJV6EB1	Migration	OPM- Controller Migration	Need to support R511.4 HF8 to R520.1_TCU2_SCN	R520.1_TCU2_SCN	nan
1-ELAJVWJ	Migration	OPM- Controller Migration	Need to support R511.3 HF15 to R520.1_TCU2_SCN	R520.1_TCU2_SCN	nan
1-ERO3X9B	Migration	OPM- Controller Migration	Migration from R520.1 TCU4/ R511.1 TCU4 to R520.1 TCU2/ R511.1 HF9/R510.2 HF12 to R520.2 TCU2.	R520.1_TCU2_SCN	
1-E8TJQRN	Engineering/ Configuration	PGM Hilscher Sycon .NET	Missing range definitions of parameters in GSD file	R520.1_TCU2_SCN	nan
1-E8TJQRX	Engineering/ Configuration	PGM Hilscher Sycon .NET	Slot Restriction Definitions in HEX	R520.1_TCU2_SCN	nan

1-E1YPP07	System Stability	C300 (CC- PCNT05)-Hardware	C300 (CC-PCNT05) Failed T148	R520.1 TC02.1 SCN	nan
1-DR2B4L3	System Stability	C300 (CC- PCNT05)-Hardware	Secondary C300 (CC-PCNT05) failed POST T177 (full cycle interrupt test) after switchover.	R520.1 TC02.1 SCN	
1-DX7RMEZ	System Stability	Procedure Explorer	Frequently, the Procedure Explorer view is missing certain procedure items.	R520.1 TC02.1 SCN	
1-E1H0YA5	Usability	Procedure Explorer	When the mouse scroll button is pressed, the Zoom option in Procedure Explorer zooms in.	R520.1 TC02.1 SCN	
1-E7HGG4R	Usability	Procedure Explorer	Procedure Explorer does not allow scrolling into SCN structure.	R520.1 TC02.1 SCN	nan
1-E8I9OZN	Usability	FIRMWARE	(Error 1199) "Alarm Reporting Device Changed" SCN migrating to R520.1/R511.4.	R520.1 TC02.1 SCN	
1-EGNPYAJ	Usability	ELCN Appliance EPLCG	Some process alarms are not being notified by the UEA (Universal Embedded Appliance)-based EPLCG.	R520.1 TC02.1 SCN	
1-EHEGX39	System Stability	ELCN Appliance EPLCG	ELCN, UEA (Universal Embedded Appliance)-based EPLCG alarm function is not working.	R520.1 TC02.1 SCN	
1-E9BLI3Z	Engineering /Configuration	C300 Controller	Prevent unauthorized changes in C300 controller configuration.	R520.1 TC02.1 SCN	nan
1-EAG9FZR	Usability	Series C Universal IO Modules	AIH or UIO_2 module incorrectly reports the Device type mismatch for HART7 device.	R520.1 TC02.1 SCN	
1-DWYBT6V	Usability	EBM-Controller	Pre-execution activities of MR before starting SCN two seconds with Lookahead ON.	R520.1 TC02.1 SCN	
1-DZ53OZV	Usability	Control Functions - Batch	Loss of Batch alarm flooding observed every time batches are executing in C300PM and C300 (CC-PCNT05)-Hardware.	R520.1 TC02.1 SCN	
1-E02W78X	Usability	UI Toolkit	The dynamic re-binding of toolkit to UI leads to hang displays.	R520.1 TC02.1 SCN	nan
REUCN-4728	System Stability	EHPM	Make it possible for Enhanced High-Performance Manager to use an alternative Level 1 switch(PCI-E).	R520.1 TC02.1 SCN	
1-E9I4LA5	Engineering /Configuration	Control Builder	When performing an update to the SCN, E_INT 10527 occurs.	R520.1 TC02.1 SCN	
REUCN-5070	Usability	EHPM	EHPM (Enhanced High-Performance Manager) AI (Analog input) point is having station display issue.	R520.1 TC02.1 SCN	
1-E8189NX	Usability	CAB-Embedded- Runtime	CAB data type implicit conversion from INT32 to INT6 not working.	R520.1 TC02.1 SCN	
1-EEAFPRV	System Stability	ELCN Appliance EPLCG	After flashing backup ELCN EPLCG, the runtime window displays the state as "Not Loaded" and "OFF."	R520.1 TC02.1 SCN	
1-EE7SN4B	System Stability	ModBus TCP Blocks	C300 failed with following errors: R520.1 and TC02.1 SCN	R520.1 TC02.1 SCN	nan
1-EFRBRVB	System Stability	ModBus TCP Blocks	Readback PV values from PCDI Analog Channels are getting swapped for long and float.	R520.1 TC02.1 SCN	
1-E3AWTI5	Engineering /Configuration	EHPM_Tools	When importing data from the Engineering Library (repository database) that included P2P references with P2P references.	R520.1 TC02.1 SCN	
1-EIJAXGB	Migration	EIM - Platform	Incompatible RDN IP address on R520.1 firmware prevents migration when device index >= 255.	R520.1 TC02.1 SCN	
1-EIPBH6P	System Stability	CEE-Database	Dual failure during download of C300 controller containing message block logic.	R520.1 TC02.1 SCN	

1-DUO1HAB	System Stability	C300 (CC- PCNT05)-Hardware	C300 (CC-PCNT05) New Primary Reporting and Unexpected ?	Memory Backup Assembly Warning.?
1-EAOIF2L	Usability	ELCN Appliance EPLCG	UEA (Universal Embedded Appli	R520.1_ELCN2_SCN Res power cycles after flashing new firmware.
REUCN-5229	Usability	C300PM	CL Phase Alarm behavior difference	R520.1_TCU3_SCN (Enhanced High Performance Process Manager) and
REUCN-4905	Usability	C300PM	Post RR,C300PM CEE-PID writing	R520.1_EPB_SCN (PMIO) via E
1-E3D54U7	Engineering /Configuration	CDA-Control Data Access	ICPP communication between C	R520.1_TCU3_SCN C300 (CC-PCNT05), C300PM- C300PM , C300 (CC-
1-EXQ99CX	Engineering/ Configuration	PDA	Enable Profibus Integration [PG	R520.1_TCU3_SCN
1-EJYPEL	Migration	OPM-Controller Migration	Migration support for Cx-PPIX01	R520.1_TCU3_SCN 03.35 is missing from R430.1 onwards.
1-DWDGZQL	System Stability	UOC-SERIES-A	After conversion from C200 to U	R520.1_TCU3_SCN C-ODA161 n
1-EE7WQ7V	System Stability	C300 Controller	The C300 Module should alarm i	R520.1_TCU3_SCN better view of the network.
1-EVONW9X	System Stability	ELCN-Bridge	ELCN Bridge LCNI fails to compl	R520.1_TCU3_SCN
1-EELKZWF	System Stability	CF-Control Function	ACE failure was observed during	R520.1_TCU3_SCN
1-EOQPPBL	System Stability	Control Builder	If the OPTDIR parameter is unde	R520.1_TCU3_SCN
1-E2YOI9F	Engineering/ Configuration	Control Builder- Fieldbus	While importing Rosemount dev	R520.1_TCU3_SCN
1-E2J3ND6	System Stability	System Repository	CDA disconnect and server switc	R520.1_TCU3_SCN
1-E7WD4AB	System Stability	Control Functions - Batch	With Dynamic Fetch enabled tra	R520.1_TCU3_SCN
1-EQ7MODZ	Migration	OPM-Controller Migration	Need to support R511.3 HF18 to	R520.2_TCU3_SCN
1-EX987N7	Engineering/ Configuration	Control Builder- Profibus	[C300v5-PGM]Unable to configu	R520.1_TCU3_SCN
1-EY2U6ZX	Engineering/ Configuration	PGM	Unable to configure more than 4	R520.1_TCU3_SCN
1-F00ZR6N	System Stability	EHPM	LOC (loss of control) and LOV (l	R520.1_TCU3_SCN
1-EPF3PIV	Engineering/ Configuration	Control Builder- Load/Upload/Up	Yellow triangle appears after up	R520.1_TCU3_SCN
1-EBCHOB7	System Stability	PGM	[PCT] The PIOMB-AI module rep	R520.1_TCU3_SCN
1-EPB8R8D	System Stability	EHPM	EHPM has an IP address conflic	R520.1_TCU3_SCN
1-ES7W86B	System Stability	CEUOC-Platform	Save UOC diagnostic data to NV	R520.1_TCU3_SCN

1-ES3THSH	System Stability	CEUOC-Platform	Controller must ensure redundancy by applying a communication is available for coordination.	R520.1_TCU3_SCN	nan
1-ERSU45K	Usability	Firmware	EHPM points have reverse video on the HCU display during checkpointing operations.	R520.1_TCU3_SCN	nan
REUCN-5873	System Stability	EHPM	Frequent LOV (loss of view) in HCU display SCNIO parameters from legacy EHPM that are loaded to	R520.1_TCU3_SCN	nan
1-EU4FJE5	System Stability	PGM	PROFIBUS Inputs at DSBs are dropped during SCN failover.	R520.1_TCU3_SCN	nan
1-EY77YFP	System Stability	PGM	Profibus Network Freeze on Inputs R520.1_TCU3_SCN	R520.1_TCU3_SCN	nan
RELCN-3290	System Stability	UVA FTE	Dual FTE failure of the BACKUP ENIM node results in LOV (loss of view) on the ENIM node and LOC (loss of	R520.1_TCU3_SCN	nan
1-EK3TBP4	System Stability	CDA-Control Data Access	SN2023-06-22 01B.	R520.1_TCU3_SCN	nan
1-EHR5MVM	Engineering/ Configuration	ELCN DB Import Utility	A parameter mismatch is observed between the EHPM project and the monitoring side for the LLMUX point.	R520.1_TCU3_SCN	nan
1-E3VQIS1	System Stability	CEUOC-Platform	Implement diagnostics on the UCU3 (Unit Operation Controller) to better understand BI hardware watchdog	R520.1_TCU3_SCN	nan
1-E8WMWQR	Engineering/ Configuration	Control Builder	Enhancement to the inactivation of the EHPM SCNE from the monitoring side.	R520.1_TCU3_SCN	nan
1-E98F7WL	Engineering/ Configuration	Control Builder Tools	The ELCN database import tool is not working properly. LLMUX points in R511.5.	R520.1_TCU3_SCN	nan
1-DODJI3B	System Stability	Control Builder-Chart	Moving LOGIC gates (Nothing Lost) to the EHPM application failure on R511.4.	R520.1_TCU3_SCN	nan
1-EEC79WN	Engineering/ Configuration	IEC61850_Tools	EIM Config limit issue with Config R520.1_TCU3_SCN	R520.1_TCU3_SCN	nan
1-EDAGW39	Engineering/ Configuration	ELCN DB Import Utility	ELCN DB Import Utility Tools failed to import EHPMs during the bulk import of EHPMs.	R520.1_TCU3_SCN	nan
1-EES6TKP	Engineering/ Configuration	ELCN DB Import Utility	Issues with ELCN Import Utility logs R520.1_TCU3_SCN	R520.1_TCU3_SCN	nan
1-E48LYZZ	System Stability	EBM-Tools	UnitCisID is not unique, eliminating the possibility of a collision could cause runtime issues with the wrong unit.	R520.1_TCU3_SCN	nan
1-DAGHVYP	Usability	Server - Displays - General	Active state on all digital faceplates R520.1_TCU3_SCN is hard to read after migration to R511.3.	R520.1_TCU3_SCN	nan
1-ELF6YGL	Usability	I/O-Series 8	Integrate Series C Mark II Non-H R520.1_TCU3_SCN01) to PC/LX and Experion - supply chain shortage.	R520.1_TCU3_SCN	nan
1-DEWGGZF	System Stability	I/O-Series 8	Excessive AO Channel Initialization R520.1_TCU3_SCN (OH1M).	R520.1_TCU3_SCN	nan
1-DZKBE0D	Usability	EHPM_Tools	Allow DEB operations check box R520.1_TCU3_SCN block is not retaining the selected option.	R520.1_TCU3_SCN	nan
RELCN-3218	System Stability	ENIM	Backup ENIM went to a FAIL state R520.1_TCU3_SCN during automated UEA ENIM swaps.	R520.1_TCU3_SCN	nan
1-ET1EBA7	Usability	CF-Control Function	PV Off Normal On-Delay Time is R520.1_TCU3_SCN configured time	R520.1_TCU3_SCN	nan
1-EN461BH	Usability	I/O-Series 8	The DO Driver chips on the 8C-PR520.1_TCU3_SCN EOL, need to refresh the HW and FW.	R520.1_TCU3_SCN	nan

1-EN4D82B	Usability	I/O-Series C	The DO Driver chips on the DC-PS20.1_TCU3_SCN EOL, need to refresh the HW and FW.	R520.1_TCU3_SCN	nan
1-EYZFHQ5	Migration	OPM-Controller Migration	Need to support R511.4 HF10, R520.1_HFCUR53CN TCU3 to R520.2 TCU3.	R520.1_HFCUR53CN	nan
1-DNF2N4P	System Stability	EBM-Tools	Data Block crash when attempting to modify a parameter inside.	R520.1_TCU3_SCN	nan
1-EELKZWF	System Stability	CF-Control Function	ACE failure was observed during R520.1_TCU3_SCN 0.2 patch 13	R520.1_TCU3_SCN	nan
1-EZD1EMR	Engineering/ Configuration	Control Builder-Delete	If we delete CM containing Series C, the channels, then the deleted channels cannot be reused.	R520.1_TCU3_SCN	nan
1-EFT8RIP	System Stability	EIP-COMMUNICATION	EIP process was stuck in an infinite loop after takeover as primary and failed.	R520.1_TCU3_SCN	nan
1-EYNIO47	System Stability	Firmware	LOV (loss of view) occurs when Primary EHPM (Enhanced High-Performance Process Manager) with Exp	R520.1_TCU3_SCN	nan
1-F00ZR6N	System Stability	EHPM	LOC (Loss of control) and LOV (Loss of view) occurs when the EHPM (Enhanced High-Performance Pro	R520.1_TCU3_SCN	nan
1-EPB8R8D	System Stability	EHPM	EHPM (Enhanced High-Performance Process Manager) has an IP address conflict with its partner when u	R520.1_TCU3_SCN	nan
1-EYNIO47	System Stability	Firmware	LOV (loss of view) occurs when Primary EHPM (Enhanced High-Performance Process Manager) with Exp	R520.1_TCU3_SCN	nan
1-EBCHOB7	System Stability	PGM	During a stable run, the PIOMB-R520.1_TCU3_SCN communication error and returned after 1 second.	R520.1_TCU3_SCN	nan
1-EX987N7	Engineering/ Configuration	Control Builder- Profibus	[C300v5-PGM] Unable to configure the TCU3_BGM connections with C300v5	R520.1_TCU3_SCN	nan
1-EY2U6ZX	Engineering/ Configuration	PGM	Unable to configure more than 4 TCU3 connections with C300v5 (PANT05)	R520.1_TCU3_SCN	nan
1-ESD7I83	Engineering/ Configuration	CE900-IO	Single Channel Download.	R520.1_TCU3_SCN	nan
1-ASYXVEB	System Stability	Standard Series C IO Modules	Redundant DI-24V (DC-PDIL51), R520.1_TCU3_SCN report Ok, then randomly on IOLINK violet.	R520.1_TCU3_SCN	nan
1-E9OALH	System Stability	I/O-Series C	Series C Mark II DC-PDIL51 Module turns on a power cycle of the system.	R520.1_TCU3_SCN	nan
1-CZ28NXD	System Stability	Fieldbus Interface Module-Series C	AO block went to 3354 error device after the FIM8/FIM4 switchover and all the AO are freezed.	R520.1_TCU3_SCN	nan
1-EICDGNJ	Engineering/ Configuration	Control Builder	Not able to load IO Ref due to License error.	R520.1_TCU3_SCN	nan
1-E8Q4OZZ	Engineering/ Configuration	Control Builder	After download of AIREF from project, the values of SOURCE and VSRCOPT do not update in Monitoring	R520.1_TCU3_SCN	nan
1-E9QUJJR	System Stability	Fieldbus Interface Module	Primary FIM8 module failed with R520.1_TCU3_SCN	R520.1_TCU3_SCN	nan
1-ECGZSTH	System Stability	ELCN-Bridge	ELCN Bridge not bridging anymore to TCU3. Transmit buffers	R520.1_TCU3_SCN	nan
1-EDVVU7Z	System Stability	ELCN-Bridge	ELCN Bridge still uses Cable A, R520.1_TCU3_SCN had improper connection and Cable B was good.	R520.1_TCU3_SCN	nan
1-DNGQNEF	Usability	ModBus TCP Blocks	PCDI PV scaling is not working as expected.	R520.1_TCU3_SCN	nan

1-EF6I9U9	System Stability	CDA- Embedded	FIM does not initiate connection	R520.1 TC03_SCN	FIM is working.
1-E6WJ8CF	Engineering/ Configuration	CTools	Need introduce CC-PAIH51 firm	R520.1 TC03_SCN	the supply chain shortage.
1-EH3B4BV	Migration	OPM-Controller Migration	Need to support R501.6 HF8 to	R520.1 TC03_SCN	nan
1-EHCHK3X	Usability	OPM-Controller Migration	Need to support R511.4 HF7 to	R520.1 TC03_SCN	nan
1-EJV6EB1	Migration	OPM-Controller Migration	Need to support R511.4 HF8 to	R520.1 TC03_SCN	nan
1-ELAJVWJ	Migration	OPM-Controller Migration	Need to support R511.3 HF15 to	R520.2 TCU3_SCN	nan
1-ERO3X9B	Migration	OPM-Controller Migration	Migration from R520.1 TCU4/ R	R520.2 TCU3_SCN	nan
1-E8TJQRN	Engineering/ Configuration	PGM Hilscher Sycon .NET	Missing range definitions of para	R520.1 TCU3_SCN	nan
1-E8TJQRX	Engineering/ Configuration	PGM Hilscher Sycon .NET	Slot Restriction Definitions in HE	R520.1 TCU3_SCN	nan
1-E1YPP07	System Stability	C300 (CC- PCNT05)-Hardware	C300 (CC-PCNT05) Failed T148	R520.1 TC03_SCN	nan
1-DR2B4L3	System Stability	C300 (CC- PCNT05)-Hardware	Secondary C300 (CC-PCNT05) fa	R520.1 TC03_SCN	cycle interrupt test) after switchover.
1-DX7RMEZ	System Stability	Procedure Explorer	Frequently, the Procedure Explor	R520.1 TC03_SCN	nan
1-E1H0YA5	Usability	Procedure Explorer	When the mouse scroll button is	R520.1 TC03_SCN	Procedure Explorer zooms in.
1-E7HGG4R	Usability	Procedure Explorer	Procedure Explorer does not allo	R520.1 TC03_SCN	nan
1-E8I9OZN	Usability	FIRMWARE	(Error 1199) "Alarm Reporting De	R520.1 TC03_SCN	nan
1-EGNPYAJ	Usability	ELCN Appliance EPLCG	Some process alarms are not bei	R520.1 TC03_SCN	nan
1-EHEGX39	System Stability	ELCN Appliance EPLCG	ELCN, UEA (Universal Embedded	R520.1 TC03_SCN	nan
1-E9BLI3Z	Engineering /Configuration	C300 Controller	Prevent unauthorized changes in	R520.1 TC03_SCN	nan
1-EAG9FZR	Usability	Series C Universal IO Modules	AIH or UIO_2 module incorrectly	R520.1 TC03_SCN	nan
1-DWYBT6V	Usability	EBM-Controller	Pre-execution activities of MR	R520.1 TC03_SCN	nan
1-DZ53OZV	Usability	Control Functions - Batch	Loss of Batch alarm flooding obs	R520.1 TC03_SCN	nan
1-E02W78X	Usability	UI Toolkit	The dynamic re-binding of toolkit	R520.1 TC03_SCN	nan
REUCN-4728	System Stability	EHPM	Make it possible for Enhanced H	R520.1 TC03_SCN	nan

1-E9I4LA5	Engineering /Configuration	Control Builder	When performing an update to the project, the error: ELCN_E_INT 10527 occurs.
REUCN-5070	Usability	EHPM	EHPM (Enhanced High-Performance Process Manager) AI (Analog Input) point is having station display i
1-E8189NX	Usability	CAB-Embedded- Runtime	CAB data type implicit conversion from INT32 to INT16 not working.
1-EEAFPRV	System Stability	ELCN Appliance EPLCG	After flashing backup ELCN EPLCG the runtime view displays the state as "Not Loaded" and "OFF."
1-EE7SN4B	System Stability	ModBus TCP Blocks	C300 failed with following errors: R520.1 and C00B1SCN nan
1-EFRBRVB	System Stability	ModBus TCP Blocks	Readback PV values from PCDI R520.1 and C00B1SCN are getting swapped for long and float.
1-E3AWTI5	Engineering /Configuration	EHPM_Tools	When importing data from the EHPM (Enhanced High-Performance Process Manager) repository database that included P2P references with
1-EIJAXGB	Migration	EIM - Platform	Incompatible RDN IP address on R520.1 firmware prevents migration when device index >= 255.
1-EIPBH6P	System Stability	CEE-Database	Dual failure during download of C520 on TCM3 SCN containing message block logic.
1-DUO1HAB	System Stability	C300 (CC- PCNT05)-Hardware	C300 (CC-PCNT05) New Primary Report Tag is unexpected ? Memory Backup Assembly Warning.?
1-EAOIF2L	Usability	ELCN Appliance EPLCG	UEA (Universal Embedded Appliance) EPLCG requires power cycle after flashing new firmware.
REUCN-5229	Usability	C300PM	CL Phase Alarm behavior different in C520, both CEEB SCN (Enhanced High-Performance Process Manager) and
REUCN-4905	Usability	C300PM	Post RR,C300PM CEE-PID writing to EPX SCN (PMIO) via EUIANOUT has INITMAN ON permanently.
1-E3D54U7	Engineering /Configuration	CDA-Control Data Access	ICPP communication between C520 (CC-PCNT05) and C300 (CC-PCNT05), C300PM- C300PM , C300 (CC-
1-EV7PVBV	Engineering/ Configuration	Control Builder	In the download of AOREF from R520 project, the vmode, modperm, and nmode do not update in M
RELCN-3297	System Stability	ELCN_Appliance_ENIM	Primary ENIM (Enhanced Network Interface Module) failed, and secondary ENIM (Enhanced Network Interface
REUCN-7093	Usability	EHPMX	Eventlogs are flooding with "xilinx R520d local4 SCN[728]: clsZmqBase."
1-EPFOFJT	System Stability	IEC61850_Embedded	EIM (Ethernet Interface Module) R520d and CEE26 SCN, and both Ethernet ports are silent.
1-ETKD3LB	System Stability	ModBus TCP Blocks	The C3000 failed with an error code R520D1TCU4 SCN shared memory corruption.
1-EVDYZ2U	System Stability	PGM	PROFIBUS during connection handshake R520d triggered SCN event. nan
1-EYGNFSX	Usability	EBM-Controller	When transterm and hold occur at the same time, the recipe does not proceed to the next step.
1-DN7VOWG	System Stability	CE900-IO	SCA-CE900-DO remains ON and does not take SCN OFF command when the DO Open Wire Alarm is ena
1-75QOLRN	Engineering/ Configuration	Control Builder- Load/Upload/Update	In PCR Dlg (Dialog), the load from R520d project with SCN parameter does not get updated into the co

1-F1EXDI7	System Stability	ELCN Appliance ENIM	UVA (Universal Virtual Appliance) ENIM (Enhanced Network Interface Module) experience periodic RDN	R520.1.TCU4.SCN	
RELCN-3130	System Stability	ELCN_Appliance_ENIM	vELCN ENIM (Enhanced Network Interface Module) Secondary failed during extended runtime.	R520.1.TCU4.SCN	
1-F1F6AG3	System Stability	ELCN Appliance EPLCG	ELCN and EPLCG stop sending R520.1.TCU4.SCNs, or EIPs, on heavily loaded systems.	R520.1.TCU4.SCN	
1-F1FM3SP	System Stability	ELCN Appliance EPLCG	Process alarms misbehave in PER520.1.TCU4.SCN (UEA) tags, and alarms are not reporting.	R520.1.TCU4.SCN	
RELCN-3670	System Stability	ELCN Appliance ENIM	BKUP (Backup) ENIM (Enhanced Network Interface Module) failed with an OPSTAT busy timeout during	R520.1.TCU4.SCN	
1-F1GL1RD	Migration	ELCN Appliance EPLCG	Migration from EPLCG to UEA (Universal Embedded Appliance) EPLCG failed during the loading checkp	R520.1.TCU4.SCN	
1-F1UVMS7	System Stability	EIP-COMMUNICATION	The controller does not handle if R520.1.TCU4.SCNs information cannot sent by the device in the Forward	R520.1.TCU4.SCN	
1-F8C7O3P	System Stability	CEUOC-Platform	During initial synchronization, CER520.1.TCU4.SCNat 12% after a long period of stable drop synchroniz	R520.1.TCU4.SCN	
1-F8U9CHF	Migration	EHPM_Tools	EHPM Auto Import Service is not R520.1.TCU4.SCNing to R520.2.TCU3.	R520.1.TCU4.SCN	
REUCN-7093	Usability	EHPMX	Eventlogs are flooding with "xilinR520.1.TCU4.SCN[728]: clsZmqBase."	R520.1.TCU4.SCN	
RELCN-3733	System Stability	ELCN_Appliance_Common	On-process recovery method for R520.1.TCU4.SCN ConfigWait time to failed IPC communications on th	R520.1.TCU4.SCN	
REUCN-6548	System Stability	C300PM	EHPM (Enhanced High-Performance R520.1.TCU4.SCNger) is failing with an error: 06C4, when EHPM (Enha	R520.1.TCU4.SCN	
1-FA4VHS1	Migration	OPM-Controller Migration	R511.3HF16/17 Ver-rev entries are R520.1.TCU4.SCNre missing for all controllers in R520.2TCU3.	R520.1.TCU4.SCN	
RELCN-3795	System Stability	ELCN Bridge	Enhance ELCN Bridge LCN cable R520.1.TCU4.SCN in the Control Builder and Event.	R520.1.TCU4.SCN	
RCEPROC-1301	Usability	CE900IO	ControlEdge900 IO-structure par R520.1 (VLSB.TCN) channel status byte of pulse and frequency channels	R520.1.TCU4.SCN	
1-F8T3KEM	System Stability	CDA-Embedded	The single step is not working wh R520.1.TCU4.SCN parallel section to a single section.	R520.1.TCU4.SCN	
1-FBMEU98	System Stability	C300 Controller	After migrating controllers to R520.2.TCU3, use a "Partner Display Connections Degraded" alarm.	R520.1.TCU4.SCN	
1-FAN4FQ1	System Stability	PDA	PGM (PROFIBUS Gateway Mod R520.PDAT(Pulse Data Access) buffer leak.	R520.1.TCU4.SCN	
1-FBBCI1B	System Stability	PDA	PIOMB is unable to write to DSB R520.1.TCU4.SCNon error.	R520.1.TCU4.SCN	
RELCN-3826	System Stability	ELCN_Bridge	LCN Cable testing failure in UEA R520.1.TCU4.SCNed Appliance and BRG (Bridge).	R520.1.TCU4.SCN	
RELCN-3731	System Stability	ELCN_Appliance_ENIM	The automatic re-enablement of R520.1.TCU4.SCN synchronization prior UEA (Universal Embedded Appliance	R520.1.TCU4.SCN	
RELCN-3788	System Stability	ELCN Bridge	Relax the default trip point and p R520.1.TCU4.SCN trip point from the error rate.	R520.1.TCU4.SCN	
RELCN-3789	System Stability	ELCN Bridge	Prevent failover of ELCN Bridge R520.1.TCU4.SCNsynchronized) for at least 180 secs when failover is being	R520.1.TCU4.SCN	

RELCN-3790	System Stability	ELCN Bridge	Provide the option to disable LCN handling during SCN maintenance	R520.1-TCU4-SCN	troubleshooting and increase the second
1-F04422J	System Stability	ELCN Appliance ENIM	Backup UEA (Universal Embedded Appliance) ENIM (Enhanced Network Interface Module) failed right af	R520.1-TCU4-SCN	right af
1-FCGTGJT	System Stability	C300v5-Hardware	Update C300v5 FPGA to latest R520.1-TCU4-SCN correct rate limiting on FTE (Fault Tolerant Ethernet)	R520.1-TCU4-SCN	limiting on FTE (Fault Tolerant Ethernet)
1-ECBW2XR	System Stability	ModBus TCP Infrastructure	If two or more arrays are writing to the same ModBus address/index, the arrays may stop writing/free.	R520.1-TCU4-SCN	the arrays may stop writing/free.
RELCN-3713	System Stability	ELCNNODE	ELCNNODE UVA (Universal Virtual Appliance) is not loading, and the LCN number remains 0 even after	R520.1-TCU4-SCN	the LCN number remains 0 even after
RELCN-3508	System Stability	Virtual ENIM	UVA (Universal Virtual Appliance) ENIM (Enhanced Network Interface Module) fails while deploying the U	R520.1-TCU4-SCN	are
RELCN-3898	System Stability	ELCN Bridge	Dual FTE (Fault Tolerant Ethernet) capable TCU4-SCN uses backup target primary IP, causing dual primary.	R520.1-TCU4-SCN	target primary IP, causing dual primary.
1-FCLQB83	System Stability	Software	The backup module fails to sync R520.1-TCU4-SCN after 300 days of runtime during upgrades, compro	R520.1-TCU4-SCN	after 300 days of runtime during upgrades, compro
1-FGFC8Q9	System Stability	ELCN-Bridge	The ELCN Bridge experienced a R520.1-TCU4-SCN, if errors exist on both LCN cables.	R520.1-TCU4-SCN	on both LCN cables.
1-FAN4FQ1	System Stability	PDA	PGM PDA buffer leak.	R520.1-TCU4-SCN	nan
1-FBBCI1B	System Stability	PDA	PIOMB is unable to write to DSB after a communication error.	R520.1-TCU4-SCN	nan
1-DN7VOWG	System Stability	CE900-IO	SCA-CE900-DO remains ON and does not take SCN command when DO Open Wire Alarm is enabled or	R520.1-TCU4-SCN	when DO Open Wire Alarm is enabled or
1-F1FM3SP	System Stability	ELCN Appliance EPLCG	Process alarms misbehavior for R520.1-TCU4-SCN tags and alarms are not reporting.	R520.1-TCU4-SCN	are not reporting.
1-F1F6AG3	System Stability	ELCN Appliance EPLCG	ELCN EPLCG stops sending dig R520.1-TCU4-SCN, or EIPs, on a heavily loaded system.	R520.1-TCU4-SCN	heavily loaded system.
1-FA4VHS1	Migration	OPM- Controller Migration	[M&I] R511.3HF16/17 Ver-rev en R520.1-TCU4-SCN are missing for all controllers in R520.2TCU3.	R520.1-TCU4-SCN	missing for all controllers in R520.2TCU3.
1-ETKD3LB	System Stability	ModBus TCP Blocks	C300 failed with an error 00D1 during R520.1-TCU4-SCN memory corruption.	R520.1-TCU4-SCN	memory corruption.
1-F1EXDI7	System Stability	ELCN Appliance ENIM	UVA ENIMs experience periodic R520.1-TCU4-SCN	R520.1-TCU4-SCN	nan
RELCN-3130	System Stability	ELCN_ Appliance_ ENIM	vELCN ENIM Secondary failed during R520.1-TCU4-SCN PCT SYS2.	R520.1-TCU4-SCN	nan
RELCN-3670	System Stability	ELCN Appliance ENIM	BKUP ENIM failed with an OPST R520.1-TCU4-SCN the stable can.	R520.1-TCU4-SCN	can.
1-F8U9CHF	Migration	EHPM	EHPM Auto Import Service is not R520.1-TCU4-SCN to R520.2TCU3.	R520.1-TCU4-SCN	to R520.2TCU3.
REUCN-7093	Usability	EHPMX	[EHPMX] Eventlogs are flooding R520.1-TCU4-SCN 4.err pdt[726]rcIsZmqBase."	R520.1-TCU4-SCN	4.err pdt[726]rcIsZmqBase."
1-EXQ99CX	Engineering/ Configuration	PDA	Enable Profibus Integration [PGM R520.1-TCU4-SCN	R520.1-TCU4-SCN	nan
1-EJYPEL	Migration	OPM-Controller Migration	Migration support for Cx-PPIX01 R520.1-TCU4-SCN 03.35 is missing from R430.1 onwards.	R520.1-TCU4-SCN	missing from R430.1 onwards.

1-DWDGZQL	System Stability	UOC-SERIES-A	After conversion from C200 to UOC-Series-A, UOC-NTC-ODA161 v2.3 failing to communicate.	R520.1_TCU4_SCN	nan
1-EE7WQ7V	System Stability	C300 Controller	The C300 Module should alarm if the C300 has a better view of the network.	R520.1_TCU4_SCN	nan
1-EVONW9X	System Stability	ELCN-Bridge	ELCN Bridge LCNI fails to complete the connection.	R520.1_TCU4_SCN	nan
1-EELKZWF	System Stability	CF-Control Function	ACE failure was observed during R520.1_TCU4_SCN 0.2 patch 13	R520.1_TCU4_SCN	nan
1-EOQPPBL	System Stability	Control Builder	If the OPTDIR parameter is unchanged in the OPC window, OPDIR is changed.	R520.1_TCU4_SCN	nan
1-E2YOI9F	Engineering/ Configuration	Control Builder-Fieldbus	While importing Rosemount device files, the control builder is crashing.	R520.1_TCU4_SCN	nan
1-E2J3ND6	System Stability	System Repository	CDA disconnect and server switch R520.1_TCU4_SCN type updates	R520.1_TCU4_SCN	nan
1-E7WD4AB	System Stability	Control Functions - Batch	With Dynamic Fetch enabled transaction level update order may be unexpected.	R520.1_TCU4_SCN	nan
1-EQ7MODZ	Migration	OPM-Controller Migration	Need to support R511.3 HF18 to R520.2_TCU4_SCN	R520.2_TCU4_SCN	nan
1-EX987N7	Engineering/ Configuration	Control Builder-Profibus	[C300v5-PGM]Unable to configure more than 4 C300v5 connections with C300v5.	R520.1_TCU4_SCN	nan
1-EY2U6ZX	Engineering/ Configuration	PGM	Unable to configure more than 4 C300v5 connections with C300v5 (PGM05).	R520.1_TCU4_SCN	nan
1-F00ZR6N	System Stability	EHPM	LOC (loss of control) and LOV (loss of view) occur when the EHPM runs with high P2P traffic and UCN d	R520.1_TCU4_SCN	nan
1-EPF3PIV	Engineering/ Configuration	Control Builder- Load/Upload/Update	Yellow triangle appears after update R520.1_TCU4_SCN project while using Projected parameters connection b	R520.1_TCU4_SCN	nan
1-EBCHOB7	System Stability	PGM	[PCT] The PIOMB-AI module reports a communication error and returns (returned) after 1 sec during a s	R520.1_TCU4_SCN	nan
1-EPB8R8D	System Stability	EHPM	EHPM has an IP address conflict with its partner when updating firmware from non-Experion to Experion.	R520.1_TCU4_SCN	nan
1-ES7W86B	System Stability	CEUOC-Platform	Save UOC diagnostic data to NV R520.1_TCU4_SCN or fault is detected.	R520.1_TCU4_SCN	nan
1-ES3THSH	System Stability	CEUOC-Platform	Controller must ensure redundancy application communication is available for coordination.	R520.1_TCU4_SCN	nan
1-ERSU45K	Usability	Firmware	EHPM points have reverse video R520.1_TCU4_SCN during checkpointing operations.	R520.1_TCU4_SCN	nan
REUCN-5873	System Stability	EHPM	Frequent LOV (loss of view) in HMI R520.1_TCU4_SCN parameters from legacy EHPM that are loaded to	R520.1_TCU4_SCN	nan
1-EU4FJE5	System Stability	PGM	PROFIBUS Inputs at DSBs are dropped during failover.	R520.1_TCU4_SCN	nan
1-EY77YFP	System Stability	PGM	Profibus Network Freeze on Input R520.1_TCU4_SCN	R520.1_TCU4_SCN	nan
RELCN-3290	System Stability	UVA FTE	Dual FTE failure of the BACKUP R520.1_TCU4_SCN LOV (loss of view) on the ENIM node and LOC (loss	R520.1_TCU4_SCN	nan
1-EK3TBP4	System Stability	CDA-Control Data Access	SN2023-06-22 01B.	R520.1_TCU4_SCN	nan

1-EHR5MVM	Engineering/ Configuration	ELCN DB Import Utility	A parameter mismatch is observed between the SBN project and the monitoring side for the LLMUX point.	
1-E3VQIS1	System Stability	CEUOC-Platform	Implement diagnostics on the UC520 Unit Operation Controller) to better understand BI hardware watchdog	
1-E8WMWQR	Engineering/ Configuration	Control Builder	Enhancement to the inactivation of the TCU4_SCE from the monitoring side.	
1-E98F7WL	Engineering/ Configuration	Control Builder Tools	The ELCN database import tool is failing to import LLMUX points in R511.5.	
1-DODJI3B	System Stability	Control Builder-Chart	Moving LOGIC gates (Nothing Loaded) to the SBN application failed on R511.4.	
1-EEC79WN	Engineering/ Configuration	IEC61850_Tools	EIM Config limit issue with Conf R520.1_TCU4_SCN	nan
1-EDAGW39	Engineering/ Configuration	ELCN DB Import Utility	ELCN DB Import Utility Tools failed to import ELCN during the bulk import of EHPMs.	
1-EES6TKP	Engineering/ Configuration	ELCN DB Import Utility	Issues with ELCN Import Utility logs R520.1_TCU4_SCN	nan
1-E48LYZZ	System Stability	EBM-Tools	UnitCIsID is not unique, eliminating it from the SBN could cause runtime issues with the wrong unit.	
1-DAGHVYP	Usability	Server - Displays - General	Active state on all digital faceplates is not clear, the SBN is hard to read after migration to R511.3.	
1-ELF6YGL	Usability	I/O-Series 8	Integrate Series C Mark II Non-High-Speed AO (TCU4_PSON01) to PC/LX and Experion - supply chain shortage.	
1-DEWGGZF	System Stability	I/O-Series 8	Excessive AO Channel Initialization Time (Series C AO (TCU4_PSON01) to PC/LX and Experion - supply chain shortage).	
1-DZKBE0D	Usability	EHPM_Tools	Allow DEB operations check box R520.1_EHPM_PSON block is not retaining the selected option.	
RELCN-3218	System Stability	ENIM	Backup ENIM went to a FAIL state R520.1_TCU4_SCN during automated UEA ENIM swaps.	
1-ET1EBA7	Usability	CF-Control Function	PV Off Normal On-Delay Time is R520.1_TCU4_SCN configured in time	
1-EN461BH	Usability	I/O-Series 8	The DO Driver chips on the 8C- R520.1_TCU4_SCN NEOL, need to be refreshed the HW and FW.	
1-EN4D82B	Usability	I/O-Series C	The DO Driver chips on the DC- R520.1_TCU4_SCN NEOL, need to be refreshed the HW and FW.	
1-EYZFHQ5	Migration	OPM-Controller Migration	Need to support R511.4 HF10, R520.1_HF10_U3_C15 TCU3 to R520.2 TCU3.	
1-DNF2N4P	System Stability	EBM-Tools	Data Block crash when attempting R520.1_TCU4_SCN to load parameter inside.	nan
1-EELKZWF	System Stability	CF-Control Function	ACE failure was observed during R520.1_TCU4_SCN 0.2 patch 13	nan
1-EZD1EMR	Engineering/ Configuration	Control Builder-Delete	If we delete CM containing Series R520.1_TCU4_SCN the deleted channels cannot be reused.	
1-EFT8RIP	System Stability	EIP-COMMUNICATION	EIP process was stuck in an infinite R520.1_TCU4_SCN loop as primary and failed.	
1-EYNIO47	System Stability	Firmware	LOV (loss of view) occurs when R520.1_EHPM_PSON (Enhanced High-Performance Process Manager) with Ex	

1-F00ZR6N	System Stability	EHPM	LOC (Loss of control) and LOV (Loss of view) occurs when the EHPM (Enhanced High-Performance Process Manager) has an IP address conflict with its partner when the EHPM is started.	R520.1_TCU4_SCN	nan
1-EPB8R8D	System Stability	EHPM	EHPM (Enhanced High-Performance Process Manager) has an IP address conflict with its partner when the EHPM is started.	R520.1_TCU4_SCN	nan
1-EYNIO47	System Stability	Firmware	LOV (loss of view) occurs when the EHPM (Enhanced High-Performance Process Manager) with Expander is started.	R520.1_TCU4_SCN	nan
1-EBCHOB7	System Stability	PGM	During a stable run, the PIOMB-R520.1_TCU4_SCN communication error and returned after 1 second.	R520.1_TCU4_SCN	nan
1-EX987N7	Engineering/ Configuration	Control Builder- Profibus	[C300v5-PGM] Unable to configure more than 4 BGM connections with C300v5.	R520.1_TCU4_SCN	nan
1-EY2U6ZX	Engineering/ Configuration	PGM	Unable to configure more than 4 BGM connections with C300v5 (PANT05).	R520.1_TCU4_SCN	nan
1-ESD7I83	Engineering/ Configuration	CE900-IO	Single Channel Download.	R520.1_TCU4_SCN	nan
1-ASYXVEB	System Stability	Standard Series C IO Modules	Redundant DI-24V (DC-PDIL51), DI24V (DC-PDIL51) report Ok, but randomly on IOLINK violet.	R520.1_TCU4_SCN	nan
1-E9OAO LH	System Stability	I/O-Series C	Series C Mark II DC-PDIL51 Module reports a power cycle of the system.	R520.1_TCU4_SCN	nan
1-CZ28NXD	System Stability	Fieldbus Interface Module-Series C	AO block went to 3354 error device, but the FIM8 switchover and all the AO are frozen.	R520.1_TCU4_SCN	nan
1-EICDGNJ	Engineering/ Configuration	Control Builder	Not able to load IO Ref due to License error.	R520.1_TCU4_SCN	nan
1-E8Q4OZZ	Engineering/ Configuration	Control Builder	After download of AIREF from project, the values of SOURCE and SRCOPT do not update in Monitoring.	R520.1_TCU4_SCN	nan
1-E9QUJJR	System Stability	Fieldbus Interface Module	Primary FIM8 module failed with error code.	R520.1_TCU4_SCN	nan
1-ECGZSTH	System Stability	ELCN-Bridge	ELCN Bridge not bridging anymore to TCU4 of SCN transmit buffers.	R520.1_TCU4_SCN	nan
1-EDVVU7Z	System Stability	ELCN-Bridge	ELCN Bridge still uses Cable A, but the TCU4 of SCN had improper connection and Cable B was good.	R520.1_TCU4_SCN	nan
1-DNGQNEF	Usability	ModBus TCP Blocks	PCDI PV scaling is not working as expected in SCN300 scaling.	R520.1_TCU4_SCN	nan
1-EF6I9U9	System Stability	CDA-Embedded	FIM does not initiate connection with TCU4 of SCN initiating to FIM is working.	R520.1_TCU4_SCN	nan
1-E6WJ8CF	Engineering/ Configuration	CTools	Need introduce CC-PAIH51 firm package to Series 8 to solve the supply chain shortage.	R520.1_TCU4_SCN	nan
1-EH3B4BV	Migration	OPM-Controller Migration	Need to support R501.6 HF8 to R520.1 TCU4 of SCN	R520.1_TCU4_SCN	nan
1-EHCHK3X	Usability	OPM-Controller Migration	Need to support R511.4 HF7 to R520.1 TCU4 of SCN	R520.1_TCU4_SCN	nan
1-EJV6EB1	Migration	OPM-Controller Migration	Need to support R511.4 HF8 to R520.1 TCU4 of SCN	R520.1_TCU4_SCN	nan
1-ELAJVWJ	Migration	OPM-Controller Migration	Need to support R511.3 HF15 to R520.2 TCU2 of SCN	R520.2_TCU2_SCN	nan
1-ERO3X9B	Migration	OPM-Controller Migration	Migration from R520.1 TCU4/ R520.1 TCU4 of SCN to R520.2 TCU2/ R511.4 HF9/R510.2 HF12 to R520.2 TCU2.	R520.2_TCU2_SCN	nan

1-E8TJQRN	Engineering/ Configuration	PGM Hilscher Sycon .NET	Missing range definitions of parameters in TCU4_SCN	R520.1_TCU4_SCN	nan
1-E8TJQRX	Engineering/ Configuration	PGM Hilscher Sycon .NET	Slot Restriction Definitions in HE	R520.1_TCU4_SCN	nan
1-E1YPP07	System Stability	C300 (CC- PCNT05)- Hardware	C300 (CC-PCNT05) Failed T148	R520.1_TCU4_SCN	nan
1-DR2B4L3	System Stability	C300 (CC- PCNT05)- Hardware	Secondary C300 (CC-PCNT05) failed POST U1500	R520.1_TCU4_SCN	nan one interrupt test) after switchover.
1-DX7RMEZ	System Stability	Procedure Explorer	Frequently, the Procedure Explorer view is missing certain procedure items.	R520.1_TCU4_SCN	nan
1-E1H0YA5	Usability	Procedure Explorer	When the mouse scroll button is pressed, the Zoom option in Procedure Explorer zooms in.	R520.1_TCU4_SCN	nan
1-E7HGG4R	Usability	Procedure Explorer	Procedure Explorer does not allow scrolling through structure.	R520.1_TCU4_SCN	nan
1-E8I9OZN	Usability	FIRMWARE	(Error 1199) "Alarm Reporting Device Change" when migrating to R690.1/R511.4.	R520.1_TCU4_SCN	nan
1-EGNPYAJ	Usability	ELCN Appliance EPLCG	Some process alarms are not being triggered by the UEA (Universal Embedded Appliance)-based EPLCG	R520.1_TCU4_SCN	nan
1-EHEGX39	System Stability	ELCN Appliance EPLCG	ELCN, UEA (Universal Embedded Appliance)-based EPLCG alarm function is not working.	R520.1_TCU4_SCN	nan
1-E9BLI3Z	Engineering /Configuration	C300 Controller	Prevent unauthorized changes in C300 controller configuration.	R520.1_TCU4_SCN	nan
1-EAG9FZR	Usability	Series C Universal IO Modules	AIH or UIO_2 module incorrectly reports the device type mismatch for HART7 device.	R520.1_TCU4_SCN	nan
1-DWYBT6V	Usability	EBM-Controller	Pre-execution activities of MR before start of the scan two seconds with Lookahead ON.	R520.1_TCU4_SCN	nan
1-DZ53OZV	Usability	Control Functions - Batch	Loss of Batch alarm flooding observed. Even though batches are executing in C300PM and C300 (CC-PCNT05)	R520.1_TCU4_SCN	nan
1-E02W78X	Usability	UI Toolkit	The dynamic re-binding of toolkit controls to the hang displays an error message.	R520.1_TCU4_SCN	nan
REUCN-4728	System Stability	EHPM	Make it possible for Enhanced High-Performance Manager to use an alternative Level 1 switch (if available).	R520.1_TCU4_SCN	nan
1-E9I4LA5	Engineering /Configuration	Control Builder	When performing an update to the project, the error: SCN_E_INT 10527 occurs.	R520.1_TCU4_SCN	nan
REUCN-5070	Usability	EHPM	EHPM (Enhanced High-Performance Manager) AI (Analog Input) point is having station display issue.	R520.1_TCU4_SCN	nan
1-E8189NX	Usability	CAB-Embedded- Runtime	CAB data type implicit conversion from INT16 to INT32 not working.	R520.1_TCU4_SCN	nan
1-EEAFPRV	System Stability	ELCN Appliance EPLCG	After flashing backup ELCN EPLCG, the alarm view displays the state as "Not Loaded" and "OFF."	R520.1_TCU4_SCN	nan
1-EE7SN4B	System Stability	ModBus TCP Blocks	C300 failed with following errors: R520.1_TCU4_SCN	R520.1_TCU4_SCN	nan
1-EFRBRVB	System Stability	ModBus TCP Blocks	Readback PV values from PCDI are getting swapped for long and float.	R520.1_TCU4_SCN	nan
1-E3AWTI5	Engineering /Configuration	EHPM_Tools	When importing data from the EHPM (Enhanced High-Performance Manager) repository database that included P2P references with	R520.1_TCU4_SCN	nan

1-EIJAXGB	Migration	EIM - Platform	Incompatible RDN IP address on R5201 firmware prevents migration when device index >= 255.
1-EIPBH6P	System Stability	CEE-Database	Dual failure during download of C300 (CC-TCNT05) containing message block logic.
1-DUO1HAB	System Stability	C300 (CC- PCNT05)- Hardware	C300 (CC-PCNT05) New Primary Reporting and Expected ?Memory Backup Assembly Warning.?
1-EAOIF2L	Usability	ELCN Appliance EPLCG	UEA (Universal Embedded Appliances) EPLCG resumes power cycle after flashing new firmware.
REUCN-5229	Usability	C300PM	CL Phase Alarm behavior difference between C300 (CC-PCNT05) Enhanced High Performance Process Manager) and C300 (CC-PCNT05).
REUCN-4905	Usability	C300PM	Post RR,C300PM CEE-PID writing failed to EPLCG (PMIO) via EPLCG OUT has INITMAN ON permanently.
1-E3D54U7	Engineering /Configuration	CDA-Control Data Access	ICPP communication between C300 (CC-PCNT05) and C300 (CC-PCNT05), C300PM- C300PM , C300 (CC-PCNT05).