

Summary

Cold Working(CW):

1. Room temperature deformation.
2. Rolling on Metal piece in a given direction which may be transverse or Normal direction results in increment of strength, ductility.
3. **Yield Strength** of the material increases as **density of dislocations** increases.

Effect of Heating (Annealing) after Cold Working:

1. **Annealing** of the cold worked structure at high temperature **softens the metal** and reverts to a strain-free condition.
2. Annealing restores the ductility to a metal that has been severely strain hardened.
3. Annealing consists of three features(processes):
 - i) **Recovery**
 - ii) **Recrystallization**
 - iii) **Grain growth**

Recovery:

The restoration of the physical properties of the CW metal without any observable change in microstructure. Strength is not affected.

Recrystallization:

The cold worked structure is replaced by a new set of strain free grains due to migration of high angle boundaries. Hardness and strength decrease but ductility increase.

Grain growth:

Occurs at higher temperature where some of the recrystallized fine grains start to grow rapidly.

