

### Applicability

This document applies to the part numbers of STM32F469xx and STM32F479xx devices listed in [Table 1](#) and their variants shown in [Table 1](#).

The STM32F469xx and STM32F479xx devices feature an ARM® 32-bit Cortex®-M4 core with FPU, for which an errata notice is also available (see [Section 1](#) for details).

[Section 2](#) gives a summary and the description of workarounds for device limitations, with respect to the device datasheet and reference manual RM0386.

**Table 1. Device summary**

| Reference   | Part numbers   |
|-------------|--|
| STM32F469xx | STM32F469AE, STM32F469AG, STM32F469AI<br>STM32F469BE, STM32F469BG, STM32F469BI<br>STM32F469IE, STM32F469IG, STM32F469II<br>STM32F469NE, STM32F469NG, STM32F469NI |
| STM32F479xx | STM32F479AI, STM32F479AG<br>STM32F479BI, STM32F479BG<br>STM32F479II, STM32F479IG<br>STM32F479NI, STM32F479NG   |

**Table 2. Device variants**

| Reference                | Silicon revision codes        |                       |
|--------------------------|-------------------------------|-----------------------|
|                          | Device marking <sup>(1)</sup> | REV_ID <sup>(2)</sup> |
| STM32F469xx, STM32F479xx | "A"                           | 0x1000                |

1. Refer to the device datasheet for details on how to identify this code on different types of package.
2. The REV\_ID[15:0] bit field of DBGMCU\_IDC register (refer to the reference manual RM0386).

# Contents

|          |  |          |
|----------|--|----------|
| <b>1</b> | <b>ARM® 32-bit Cortex®-M4 with FPU limitations</b>   | <b>6</b> |
| 1.1      | Cortex®-M4 interrupted loads to stack pointer can cause erroneous behavior   | 6        |
| 1.2      | VDIV or VSQRT instructions might not complete correctly when very short ISRs are used                              | 7        |
| <b>2</b> | <b>Summary of silicon limitations</b>  | <b>8</b> |
| 2.1      | System limitations   | 11       |
| 2.1.1    | Debugging Stop mode and system tick timer  | 11       |
| 2.1.2    | Debugging Sleep/Stop mode with WFE/WFI entry   | 11       |
| 2.1.3    | Full JTAG configuration without NJTRST pin cannot be used  | 11       |
| 2.1.4    | MPU attribute to RTC and IWDG registers could be managed incorrectly   | 12       |
| 2.1.5    | Delay after an RCC peripheral clock enabling   | 12       |
| 2.1.6    | Internal noise impacting the ADC accuracy  | 12       |
| 2.1.7    | Wakeup from Standby mode with RTC  | 13       |
| 2.1.8    | Data Cache might be corrupted during Flash Read While Write operation  | 13       |
| 2.1.9    | FMC_SDNWEN alternate function on PA7   | 14       |
| 2.2      | RTC limitations  | 14       |
| 2.2.1    | Spurious tamper detection when disabling the tamper channel  | 14       |
| 2.2.2    | Detection of a tamper event occurring before enabling the tamper detection is not supported in edge detection mode | 14       |
| 2.3      | IWDG peripheral limitation   | 15       |
| 2.3.1    | RVU and PVU flags are not reset in STOP mode   | 15       |
| 2.4      | I2C peripheral limitations   | 15       |
| 2.4.1    | SMBus standard not fully supported   | 15       |
| 2.4.2    | Start cannot be generated after a misplaced Stop   | 15       |
| 2.4.3    | Mismatch on the "Setup time for a repeated Start condition" timing parameter                                       | 16       |
| 2.4.4    | Data valid time ( $t_{VD;DAT}$ ) violated without the OVR flag being set   | 16       |
| 2.4.5    | Both SDA and SCL maximum rise time ( $t_r$ ) violated when VDD_I2C bus is higher than $((VDD+0.3) / 0.7)$ V        | 17       |
| 2.4.6    | Spurious Bus Error detection in master mode  | 17       |
| 2.5      | SPI peripheral limitations   | 17       |

|        |  |    |
|--------|--|----|
| 2.5.1  | BSY bit may stay high at the end of a data transfer in slave mode . . . .  | 17 |
| 2.5.2  | The last transacted bit of data or CRC calculation can be corrupted for the received data in master mode depending on the timing of the feedback communication clock respect to the APB clock (SPI or I2S) . | 18 |
| 2.5.3  | Wrong CRC calculation when the polynomial is even. . . . .   | 19 |
| 2.6    | I2S peripheral limitation . . . . .  | 19 |
| 2.6.1  | In I2S slave mode WS level must be set by the external master when enabling the I2S . . . . .  | 19 |
| 2.7    | USART peripheral limitations . . . . .   | 20 |
| 2.7.1  | Idle frame is not detected if receiver clock speed is deviated . . . . .   | 20 |
| 2.7.2  | In full duplex mode, the Parity Error (PE) flag can be cleared by writing to the data register . . . . .   | 20 |
| 2.7.3  | Parity Error (PE) flag is not set when receiving in Mute mode using address mark detection . . . . .   | 20 |
| 2.7.4  | Break frame is transmitted regardless of nCTS input line status . . . . .  | 20 |
| 2.7.5  | nRTS signal abnormally driven low after a protocol violation . . . . .   | 21 |
| 2.7.6  | Start bit detected too soon when sampling for NACK signal from the smartcard . . . . .   | 21 |
| 2.7.7  | Break request can prevent the Transmission Complete flag (TC) from being set . . . . .   | 22 |
| 2.7.8  | Guard time is not respected when data are sent on TXE events . . . . .   | 22 |
| 2.7.9  | nRTS is active while RE or UE = 0 . . . . .  | 22 |
| 2.8    | bxCAN limitation . . . . .   | 22 |
| 2.8.1  | bxCAN time triggered communication mode not supported . . . . .  | 22 |
| 2.9    | Ethernet peripheral limitations . . . . .  | 23 |
| 2.9.1  | Incorrect layer 3 (L3) checksum is inserted in transmitted IPv6 packets without TCP, UDP or ICMP payloads . . . . .  | 23 |
| 2.9.2  | The Ethernet MAC processes invalid extension headers in the received IPv6 frames . . . . .   | 23 |
| 2.9.3  | MAC stuck in the Idle state on receiving the TxFIFO flush command exactly 1 clock cycle after a transmission completes . . . . .   | 23 |
| 2.9.4  | Transmit frame data corruption . . . . .   | 24 |
| 2.9.5  | Successive write operations to the same register might not be fully taken into account . . . . .   | 24 |
| 2.10   | FMC peripheral limitation . . . . .  | 27 |
| 2.10.1 | Dummy read cycles inserted when reading synchronous memories . . .   | 27 |
| 2.11   | QUADSPI peripheral limitation . . . . .  | 27 |
| 2.11.1 | Extra data written in the FIFO at the end of a read transfer . . . . .   | 27 |
| 2.11.2 | First nibble of data is not written after dummy phase . . . . .  | 28 |

|          |  |           |
|----------|--|-----------|
| 2.11.3   | Wrong data can be read in memory-mapped after an indirect mode operation . . . . .   | 28        |
| 2.12     | SDIO peripheral limitations . . . . .  | 29        |
| 2.12.1   | Wrong CCRCFAIL status after a response without CRC is received . . .   | 29        |
| 2.12.2   | No underrun detection with wrong data transmission . . . . .   | 29        |
| 2.13     | ADC peripheral limitation . . . . .  | 29        |
| 2.13.1   | ADC sequencer modification during conversion . . . . .   | 29        |
| 2.14     | DAC peripheral limitations . . . . .   | 30        |
| 2.14.1   | DMA underrun flag management . . . . .   | 30        |
| 2.14.2   | DMA request not automatically cleared by DMAEN=0 . . . . .   | 30        |
| 2.15     | DSI Host peripheral limitations . . . . .  | 30        |
| 2.15.1   | When used over the DSI link, the Tearing Effect Interrupt Flag is set when an Acknowledge Trigger is received from the display . . . . . | 30        |
| 2.15.2   | The time to activate the clock between HS transmissions is not calculated correctly . . . . .  | 31        |
| 2.15.3   | The immediate update procedure may fail . . . . .  | 31        |
| <b>3</b> | <b>Revision history . . . . .</b>  | <b>33</b> |

## List of tables

|          |  |    |
|----------|--|----|
| Table 1. | Device summary . . . . .   | 1  |
| Table 2. | Device variants . . . . .  | 1  |
| Table 3. | Cortex®-M4 core limitations and impact on microcontroller behavior . . . . . | 6  |
| Table 4. | Summary of silicon limitations . . . . .                                     | 8  |
| Table 5. | Maximum APB frequency vs. GPIOx_OSPEEDR setting . . . . .                    | 19 |
| Table 6. | Impacted registers and bits. . . . .   | 25 |
| Table 7. | Document revision history . . . . .  | 33 |

# 1 ARM® 32-bit Cortex®-M4 with FPU limitations

An errata notice of the STM32F469xx and STM32F479xx core is available from <http://infocenter.arm.com>.

All the described limitations are minor and related to the revision r0p1-v1 of the Cortex®-M4 core. [Table 3](#) summarizes these limitations and their implications on the behavior of STM32F469xx and STM32F479xx devices.

**Table 3. Cortex®-M4 core limitations and impact on microcontroller behavior**

| ARM ID | ARM category | ARM summary of errata   | Impact on STM32F469xx and STM32F479xx |
|--------|--------------|---|---------------------------------------|
| 752770 | Cat B        | Interrupted loads to SP can cause erroneous behavior                                  | Minor                                 |
| 776924 | Cat B        | VDIV or VSQRT instructions might not complete correctly when very short ISRs are used | Minor                                 |

## 1.1 Cortex®-M4 interrupted loads to stack pointer can cause erroneous behavior

### Description

An interrupt occurring during the data-phase of a single word load to the stack pointer (SP/R13) can cause an erroneous behavior of the device. In addition, returning from the interrupt results in the load instruction being executed an additional time.

For all the instructions performing an update of the base register, the base register is erroneously updated on each execution, resulting in the stack pointer being loaded from an incorrect memory location.

The instructions affected by this limitation are the following:

- LDR SP, [Rn],#imm
- LDR SP, [Rn,#imm]!
- LDR SP, [Rn,#imm]
- LDR SP, [Rn]
- LDR SP, [Rn,Rm]

### Workaround

As of today, no compiler generates these particular instructions. This limitation can only occur with hand-written assembly code.

Both limitations can be solved by replacing the direct load to the stack pointer by an intermediate load to a general-purpose register followed by a move to the stack pointer.

Example:

Replace LDR SP, [R0] by

```
LDR R2,[R0]
```

```
MOV SP,R2
```

## 1.2 VDIV or VSQRT instructions might not complete correctly when very short ISRs are used

### Description

On Cortex®-M4 with FPU core, 14 cycles are required to execute a VDIV or VSQRT instruction.

This limitation is present when the following conditions are met:

- A VDIV or VSQRT is executed
- The destination register for VDIV or VSQRT is one of s0 - s15
- An interrupt occurs and is taken
- The ISR being executed does not contain a floating point instruction
- 14 cycles after the VDIV or VSQRT is executed, an interrupt return is executed

In this case, if there are only one or two instructions inside the interrupt service routine, then the VDIV or VSQRT instruction does not complete correctly and the register bank and FPSCR are not updated, meaning that these registers hold incorrect out-of-date data.

### Workaround

Two workarounds are applicable:

- Disable lazy context save of floating point state by clearing LSPEN to 0 (bit 30 of the FPCCR at address 0xE00EF34).
- Ensure that every ISR contains more than 2 instructions in addition to the exception return instruction.

## 2 Summary of silicon limitations

[Table 4](#) gives quick references to all documented limitations of STM32F469xx and STM32F479xx, and their status:

- A = limitation present, workaround available
- N = limitation present, no workaround available
- P = limitation present, partial workaround available
- '-' = limitation absent

**Table 4. Summary of silicon limitations**

| Links to silicon limitations            |  | Revision A |
|---|--|------------|
| Section 2.1: System limitations         | <a href="#">Section 2.1.1: Debugging Stop mode and system tick timer</a>   | A          |
|   | <a href="#">Section 2.1.2: Debugging Sleep/Stop mode with WFE/WFI entry</a>  | A          |
|   | <a href="#">Section 2.1.3: Full JTAG configuration without NJTRST pin cannot be used</a>   | A          |
|   | <a href="#">Section 2.1.4: MPU attribute to RTC and IWDG registers could be managed incorrectly</a>  | A          |
|   | <a href="#">Section 2.1.5: Delay after an RCC peripheral clock enabling</a>  | A          |
|   | <a href="#">Section 2.1.6: Internal noise impacting the ADC accuracy</a>   | A          |
|   | <a href="#">Section 2.1.7: Wakeup from Standby mode with RTC</a>   | A          |
|   | <a href="#">Section 2.1.8: Data Cache might be corrupted during Flash Read While Write operation</a>   | A          |
|   | <a href="#">Section 2.1.9: FMC_SDNWEN alternate function on PA7</a>  | A          |
| Section 2.2: RTC limitations            | <a href="#">Section 2.2.1: Spurious tamper detection when disabling the tamper channel</a>   | A          |
|   | <a href="#">Section 2.2.2: Detection of a tamper event occurring before enabling the tamper detection is not supported in edge detection mode</a>              | A          |
| Section 2.3: IWDG peripheral limitation | <a href="#">Section 2.3.1: RVU and PVU flags are not reset in STOP mode</a>  | A          |
| Section 2.4: I2C peripheral limitations | <a href="#">Section 2.4.1: SMBus standard not fully supported</a>  | A          |
|   | <a href="#">Section 2.4.2: Start cannot be generated after a misplaced Stop</a>  | A          |
|   | <a href="#">Section 2.4.3: Mismatch on the "Setup time for a repeated Start condition" timing parameter</a>  | A          |
|   | <a href="#">Section 2.4.4: Data valid time (<math>t_{VD, DAT}</math>) violated without the OVR flag being set</a>  | A          |
|   | <a href="#">Section 2.4.5: Both SDA and SCL maximum rise time (<math>t_r</math>) violated when VDD_I2C bus is higher than <math>((VDD+0.3) / 0.7)</math> V</a> | A          |
|   | <a href="#">Section 2.4.6: Spurious Bus Error detection in master mode</a>   | A          |



Table 4. Summary of silicon limitations (continued)

| Links to silicon limitations                 |   | Revision A |
|--|---|------------|
| Section 2.5: SPI peripheral limitations      | Section 2.5.1: BSY bit may stay high at the end of a data transfer in slave mode  | A          |
|  | Section 2.5.2: The last transacted bit of data or CRC calculation can be corrupted for the received data in master mode depending on the timing of the feedback communication clock respect to the APB clock (SPI or I2S) | A          |
|  | Section 2.5.3: Wrong CRC calculation when the polynomial is even.   | A          |
| Section 2.6: I2S peripheral limitation       | Section 2.6.1: In I2S slave mode WS level must be set by the external master when enabling the I2S  | A          |
| Section 2.7: USART peripheral limitations    | Section 2.7.1: Idle frame is not detected if receiver clock speed is deviated   | N          |
|  | Section 2.7.2: In full duplex mode, the Parity Error (PE) flag can be cleared by writing to the data register   | A          |
|  | Section 2.7.3: Parity Error (PE) flag is not set when receiving in Mute mode using address mark detection   | N          |
|  | Section 2.7.4: Break frame is transmitted regardless of nCTS input line status  | N          |
|  | Section 2.7.5: nRTS signal abnormally driven low after a protocol violation   | A          |
|  | Section 2.7.6: Start bit detected too soon when sampling for NACK signal from the smartcard   | N          |
|  | Section 2.7.7: Break request can prevent the Transmission Complete flag (TC) from being set   | A          |
|  | Section 2.7.8: Guard time is not respected when data are sent on TXE events   | A          |
|  | Section 2.7.9: nRTS is active while RE or UE = 0  | A          |
| Section 2.8: bxCAN limitation                | Section 2.8.1: bxCAN time triggered communication mode not supported  | N          |
| Section 2.9: Ethernet peripheral limitations | Section 2.9.1: Incorrect layer 3 (L3) checksum is inserted in transmitted IPv6 packets without TCP, UDP or ICMP payloads  | A          |
|  | Section 2.9.2: The Ethernet MAC processes invalid extension headers in the received IPv6 frames   | N          |
|  | Section 2.9.3: MAC stuck in the Idle state on receiving the TxFIFO flush command exactly 1 clock cycle after a transmission completes   | A          |
|  | Section 2.9.4: Transmit frame data corruption   | A          |
|  | Section 2.9.5: Successive write operations to the same register might not be fully taken into account   | A          |
| Section 2.10: FMC peripheral limitation      | Section 2.10.1: Dummy read cycles inserted when reading synchronous memories  | N          |

Table 4. Summary of silicon limitations (continued)

| Links to silicon limitations                         |  | Revision A |
|--|--|------------|
| Section 2.11:<br>QUADSPI<br>peripheral<br>limitation | Section 2.11.1: Extra data written in the FIFO at the end of a read transfer   | A          |
|  | Section 2.11.2: First nibble of data is not written after dummy phase  | A          |
|  | Section 2.11.3: Wrong data can be read in memory-mapped after an indirect mode operation   | A          |
| Section 2.12:<br>SDIO peripheral<br>limitations      | Section 2.12.1: Wrong CCRCFAIL status after a response without CRC is received   | A          |
|  | Section 2.12.2: No underrun detection with wrong data transmission   | A          |
| Section 2.13:<br>ADC peripheral<br>limitation        | Section 2.13.1: ADC sequencer modification during conversion   | A          |
| Section 2.14:<br>DAC peripheral<br>limitations       | Section 2.14.1: DMA underrun flag management   | A          |
|  | Section 2.14.2: DMA request not automatically cleared by DMAEN=0   | A          |
| Section 2.15: DSI<br>Host peripheral<br>limitations  | Section 2.15.1: When used over the DSI link, the Tearing Effect Interrupt Flag is set when an Acknowledge Trigger is received from the display | A          |
|  | Section 2.15.2: The time to activate the clock between HS transmissions is not calculated correctly  | A          |
|  | Section 2.15.3: The immediate update procedure may fail  | A          |

## 2.1 System limitations

### 2.1.1 Debugging Stop mode and system tick timer

#### Description

If the system tick timer interrupt is enabled during the Stop mode debug (DBG\_STOP bit set in the DBGMCU\_CR register), it will wake up the system from Stop mode.

#### Workaround

To debug the Stop mode, disable the system tick timer interrupt.

### 2.1.2 Debugging Sleep/Stop mode with WFE/WFI entry

#### Description

When the Sleep debug or Stop debug mode is enabled (DBG\_SLEEP bit or DBG\_STOP bit are set in the DBGMCU\_CR register), this allows software debugging during Sleep or Stop mode. After wakeup some unreachable instructions could be executed if the following conditions are met:

- The application software disables the Prefetch queue
- The number of wait state configured on Flash interface is higher than 0
- Linker place WFE or WFI instructions on 4-bytes aligned addresses (0x080xx\_xxx4)

#### Workaround

Three workarounds are possible:

- Add three NOPs after WFI/WFE instruction
- Keep one AHB master active during sleep (example keep DMA1 or DMA2 RCC clock enable bit set)
- Execute WFI/WFE instruction from routines inside the SRAM. To debug Stop mode with WFE entry, the WFE instruction must be inside a dedicated function with one instruction (NOP) between the execution of the WFE and the Bx LR.

### 2.1.3 Full JTAG configuration without NJTRST pin cannot be used

#### Description

When using the JTAG debug port in debug mode, the connection with the debugger is lost if the NJTRST pin (PB4) is used as a GPIO. Only the 4-wire JTAG port configuration is impacted.

#### Workaround

Use the SWD debug port instead of the full 4-wire JTAG port.

### 2.1.4 MPU attribute to RTC and IWDG registers could be managed incorrectly

#### Description

If the MPU is used and the non bufferable attribute is set to the RTC or IWDG memory map region, the CPU access to the RTC or IWDG registers could be treated as bufferable, provided that there is no APB prescaler configured (AHB/APB prescaler is equal to 1).

#### Workaround

If the non bufferable attribute is required for these registers, the software could perform a read after the write to guaranty the completion of the write access.

### 2.1.5 Delay after an RCC peripheral clock enabling

#### Description

A delay between an RCC peripheral clock enable and the effective peripheral enabling should be taken into account in order to manage the peripheral read/write to registers.

This delay depends on the peripheral's mapping:

- If the peripheral is mapped on AHB: the delay should be equal to 2 AHB cycles.
- If the peripheral is mapped on APB: the delay should be equal to 1 + (AHB/APB prescaler) cycles.

#### Workarounds

1. Use the DSB instruction to stall the Cortex<sup>®</sup>-M4 CPU pipeline until the instruction is completed.
2. Insert "n" NOPs between the RCC enable bit write and the peripheral register writes (n = 2 for AHB peripherals, n = 1 + AHB/APB prescaler in case of APB peripherals).
3. Or simply insert a dummy read operation to the corresponding register just after enabling the peripheral clock.

### 2.1.6 Internal noise impacting the ADC accuracy

#### Description

An internal noise generated on V<sub>DD</sub> supplies and propagated internally may impact the ADC accuracy.

This noise is always active whatever the power mode of the MCU (RUN or Sleep).

#### Workarounds

To adapt the accuracy level to the application requirements, set one of the following options:

- Option1  
Set the ADCDC1 bit in the PWR\_CR register.
- Option2  
Set the corresponding ADCxDC2 bit in the SYSCFG\_PMC register.

Only one option can be set at a time.

For more details on option 1 and option2 mechanisms, refer to AN4073.

### 2.1.7 Wakeup from Standby mode with RTC

#### Description

After wakeup from Standby mode with one of the following events

- RTC alarm
- RTC TAMPER
- RTC TimeStamp
- RTC wake up timer

the wakeup flag WUPF in the PWR\_CSR register will be kept pending even if the wakeup flag is cleared by setting the CWUPF bit in the PWR\_CR register. This prevents the system from entering in Standby mode.

The wakeup from Standby mode with WKUP pin is not impacted.

#### Workaround

After wakeup from Standby when using RTC wakeup events:

- Check if the SBF flag was set, then clear it by setting the CSBF bit in the PWR\_CR register.
- Generate a system reset in order to clear the pending wakeup flag, and allow the system to enter Standby mode next time and to wakeup by RTC.

### 2.1.8 Data Cache might be corrupted during Flash Read While Write operation

#### Description

When a write to the internal Flash memory is done, the Data Cache is normally updated to reflect the data value update. During this Data Cache update, a read to the other memory bank may occur; this read can corrupt the Data Cache content, and subsequent read operations at the same address (Cache hits) will be corrupted.

This limitation occurs only in dual bank mode, when reading (data access or code execution) from one Flash Bank while writing to the other Flash Bank with Data Cache enabled.

#### Workaround

When the application is performing data accesses in both Flash memory banks, the Data Cache must be disabled by resetting the DCEN bit before any write to the Flash. Before enabling the Data Cache again, it must be reset by setting and then resetting the DCRST bit.

Example of code

```
/* Disable data cache */
__HAL_FLASH_DATA_CACHE_DISABLE();

/* Set PG bit */
SET_BIT(FLASH->CR, FLASH_CR_PG);
```

```
/* Program the Flash word */
WriteFlash(Address, Data);

/* Reset data cache */
__HAL_FLASH_DATA_CACHE_RESET();
/* Enable data cache */
__HAL_FLASH_DATA_CACHE_ENABLE();
```

### 2.1.9 FMC\_SDNWEN alternate function on PA7

#### Description

The FMC\_SDNWEN alternate function is not available on PA7.

#### Workaround

Use FMC\_SDNWEN alternate function on PH5 or PC0.

## 2.2 RTC limitations

### 2.2.1 Spurious tamper detection when disabling the tamper channel

#### Description

If the tamper detection is configured for detection on the falling edge event (TAMPFLT=00 and TAMPxTRG=1) and if the tamper event detection is disabled when the tamper pin is at high level, a false tamper event is detected.

#### Workaround

The false tamper event detection cannot be avoided, but the backup registers erase can be avoided by setting TAMPxNOERASE bit before clearing TAMPxE bit. The two bits must be written in two separate RTC\_TAMPCR write accesses.

### 2.2.2 Detection of a tamper event occurring before enabling the tamper detection is not supported in edge detection mode

#### Description

When the tamper detection is enabled in edge detection mode (TAMPFLT=00):

- When TAMPxTRG=0 (rising edge detection): if the tamper input is already high before enabling the tamper detection, the tamper event may or may not be detected when enabling the tamper detection. The probability to detect it increases with the APB frequency.
- When TAMPxTRG=1 (falling edge detection): if the tamper input is already low before enabling the tamper detection, the tamper event is not detected when enabling the tamper detection.

**Workaround**

The I/O state should be checked by software in the GPIO registers, just after enabling the tamper detection and before writing sensitive values in the backup registers, in order to ensure that no active edge occurred before enabling the tamper event detection.

**2.3 IWDG peripheral limitation****2.3.1 RVU and PVU flags are not reset in STOP mode****Description**

The RVU and PVU flags of the IWDG\_SR register are set by hardware after a write access to the IWDG\_RLR and the IWDG\_PR registers, respectively. If the Stop mode is entered immediately after the write access, the RVU and PVU flags are not reset by hardware.

Before performing a second write operation to the IWDG\_RLR or the IWDG\_PR register, the application software must wait for the RVU or PVU flag to be reset. However, since the RVU/PVU bit is not reset after exiting the Stop mode, the software goes into an infinite loop and the independent watchdog (IWDG) generates a reset after the programmed timeout period.

**Workaround**

Wait until the RVU or PVU flag of the IWDG\_SR register is reset before entering the Stop mode.

**2.4 I2C peripheral limitations****2.4.1 SMBus standard not fully supported****Description**

The I<sup>2</sup>C peripheral is not fully compliant with the SMBus v2.0 standard since It does not support the capability to NACK an invalid byte/command.

**Workarounds**

A higher-level mechanism should be used to verify that a write operation is being performed correctly at the target device, such as:

1. Using the SMBAL pin if supported by the host
2. the alert response address (ARA) protocol
3. the Host notify protocol

**2.4.2 Start cannot be generated after a misplaced Stop****Description**

If a master generates a misplaced Stop on the bus (bus error), while the peripheral tries to switch to master mode by setting the START bit, the Start condition is not properly generated.

### Workaround

In the I<sup>2</sup>C standard, it is allowed to send a Stop only at the end of the full byte (8 bits + acknowledge), so this scenario is not allowed. Other derived protocols like CBUS allow it, but they are not supported by the I<sup>2</sup>C peripheral.

A software workaround consists in asserting the software reset using the SWRST bit in the I2C\_CR1 control register.

## 2.4.3 Mismatch on the “Setup time for a repeated Start condition” timing parameter

### Description

In case of a repeated Start, the “Setup time for a repeated Start condition” (named  $T_{su;sta}$  in the I<sup>2</sup>C specification) can be slightly violated when the I<sup>2</sup>C operates in Master Standard mode at a frequency between 88 kHz and 100 kHz.

The limitation can occur only in the following configuration:

- in Master mode
- in Standard mode at a frequency between 88 kHz and 100 kHz (no limitation in Fast-mode)
- SCL rise time:
  - If the slave does not stretch the clock and the SCL rise time is more than 300 ns (if the SCL rise time is less than 300 ns, the limitation cannot occur)
  - If the slave stretches the clock

The setup time can be violated independently of the APB peripheral frequency.

### Workaround

Reduce the frequency down to 88 kHz or use the I<sup>2</sup>C Fast-mode, if supported by the slave.

## 2.4.4 Data valid time ( $t_{VD;DAT}$ ) violated without the OVR flag being set

### Description

The data valid time ( $t_{VD;DAT}$ ,  $t_{VD;ACK}$ ) described by the I<sup>2</sup>C standard can be violated (as well as the maximum data hold time of the current data ( $t_{HD;DAT}$ )) under the conditions described below. This violation cannot be detected because the OVR flag is not set (no transmit buffer underrun is detected).

This limitation can occur only under the following conditions:

- in Slave transmit mode
- with clock stretching disabled (NOSTRETCH=1)
- if the software is late to write the DR data register, but not late enough to set the OVR flag (the data register is written before)

### Workaround

If the master device allows it, use the clock stretching mechanism by programming the bit NOSTRETCH=0 in the I2C\_CR1 register.



If the master device does not allow it, ensure that the software is fast enough when polling the TXE or ADDR flag to immediately write to the DR data register. For instance, use an interrupt on the TXE or ADDR flag and boost its priority to the higher level.

#### 2.4.5 Both SDA and SCL maximum rise time ( $t_r$ ) violated when VDD\_I2C bus is higher than $((V_{DD}+0.3) / 0.7)$ V

##### Description

When an external legacy I<sup>2</sup>C bus voltage (VDD\_I2C) is set to 5 V while the MCU is powered from V<sub>DD</sub>, the internal 5-Volt tolerant circuitry is activated as soon the input voltage (V<sub>IN</sub>) reaches the V<sub>DD</sub> + diode threshold level. An additional internal large capacitance then prevents the external pull-up resistor (R<sub>P</sub>) from rising the SDA and SCL signals within the maximum timing ( $t_r$ ) which is 300 ns in fast mode and 1000 ns in Standard mode.

The rise time ( $t_r$ ) is measured from V<sub>IL</sub> and V<sub>IH</sub> with levels set at 0.3 VDD\_I2C and 0.7 VDD\_I2C.

##### Workaround

The external VDD\_I2C bus voltage should be limited to a maximum value of  $((V_{DD}+0.3) / 0.7)$  V. As a result, when the MCU is powered from V<sub>DD</sub>=3.3 V, VDD\_I2C should not exceed 5.14 V to be compliant with I<sup>2</sup>C specifications.

#### 2.4.6 Spurious Bus Error detection in master mode

##### Description

In master mode, a bus error can be detected by mistake, so the BERR flag can be wrongly raised in the status register. This will generate a spurious Bus Error interrupt if the interrupt is enabled. A bus error detection has no effect on the transfer in master mode, therefore the I<sup>2</sup>C transfer can continue normally.

##### Workaround

If a bus error interrupt is generated in master mode, the BERR flag must be cleared by software. No other action is required and the on-going transfer can be handled normally.

### 2.5 SPI peripheral limitations

#### 2.5.1 BSY bit may stay high at the end of a data transfer in slave mode

##### Description

BSY flag may sporadically remain high at the end of a data transfer in slave mode. The issue appears when an accidental synchronization happens between internal CPU clock and external SCK clock provided by master.

This is related to the end of data transfer detection while the SPI is enabled in slave mode.

As a consequence, the end of data transaction may be not recognized when software needs to monitor it (e.g. at the end of session before entering the low power mode or before

direction of data line has to be changed at half duplex bidirectional mode). The BSY flag is unreliable to detect the end of any data sequence transaction.

### Workaround

When NSS hardware management is applied and NSS signal is provided by master, the end of a transaction can be detected by the NSS polling by slave.

- If SPI receiving mode is enabled, the end of a transaction with master can be detected by the corresponding RXNE event signaling the last data transfer completion.
- In SPI transmit mode, user can check the BSY under timeout corresponding to the time necessary to complete the last data frame transaction. The timeout should be measured from TXE event signaling the last data frame transaction start (it is raised once the second bit transaction is ongoing). Either BSY becomes low normally or the timeout expires when the synchronization issue happens.

When upper workarounds are not applicable, the following sequence can be used to prevent the synchronization issue at SPI transmit mode.

1. Write last data to data register
2. Poll TXE until it becomes high to ensure the data transfer has started
3. Disable SPI by clearing SPE while the last data transfer is still ongoing
4. Poll the BSY bit until it becomes low
5. The BSY flag works correctly and can be used to recognize the end of the transaction.

*Note: This workaround can be used only when CPU has enough performance to disable SPI after TXE event is detected while the data frame transfer is still ongoing. It is impossible to achieve it when ratio between CPU and SPI clock is low and data frame is short especially. In this specific case timeout can be measured from TXE, while calculating fixed number of CPU clock periods corresponding to the time necessary to complete the data frame transaction.*

## 2.5.2 The last transacted bit of data or CRC calculation can be corrupted for the received data in master mode depending on the timing of the feedback communication clock respect to the APB clock (SPI or I2S)

### Description

When the SPI or I2S is configured in master mode (in full duplex or receiver mode, reading back the data register or CRC enabled), the data received may have the last transacted bit corrupted if delay of internal feedback derived from SCK pin is comparable with APB clock period. The last bit value is strobed too late into the shift register, while its content has been already either copied into the data register or compared with CRC pattern calculated internally. In case of data corruption, the bit position in the data register contains the value of the last bit received during the previous data transfer and CRCERR flag is asserted in spite of all the data being received correctly.

The main factors that contribute negatively to the delay are decreased  $V_{DD}$  level, high temperature, high SPI bus capacity load and low SCK IO output speed. SPI communication speed has no impact.

### Workaround

- Decrease the APB clock.
- Set the IO pad configuration for the SCK pin to be faster.

[Table 5](#) gives an overview about maximum APB frequency vs. GPIOx\_OSPEEDR output speed register setting for the SCK pin with a maximum load 30 pF.

**Table 5. Maximum APB frequency vs. GPIOx\_OSPEEDR setting**

| OSPEEDR bits [1:0] for the SCK pin | Maximum APB frequency |         |
|------------------------------------|-----------------------|---------|
|                                    | For SPI               | For I2S |
| High (10) and Very high (11)       | 90 MHz                | 45 MHz  |
| Medium (01)                        | 75 MHz                | 35 MHz  |
| Low (00)                           | 26 MHz                | 12 MHz  |

### 2.5.3 Wrong CRC calculation when the polynomial is even.

#### Description

When the CRC is enabled, the CRC calculation will be wrong if the polynomial is even.

#### Workaround

Use odd polynomial.

## 2.6 I2S peripheral limitation

### 2.6.1 In I2S slave mode WS level must be set by the external master when enabling the I2S

#### Description

In slave mode, the WS signal level is used only to start the communication. If the I2S (in slave mode) is enabled while the master is already sending the clock and the WS signal level is low (for I2S protocol) or is high (for the LSB or MSB-justified mode), the slave starts communicating data immediately. In this case, the master and slave will be desynchronized throughout the whole communication.

#### Workaround

The I2S peripheral must be enabled when the external master sets the WS line at:

- High level when the I2S protocol is selected.
- Low level when the LSB or MSB-justified mode is selected.

## 2.7 USART peripheral limitations

### 2.7.1 Idle frame is not detected if receiver clock speed is deviated

#### Description

If the USART receives an idle frame followed by a character, and the clock of the transmitter device is faster than the USART receiver clock, the USART receive signal falls too early when receiving the character start bit, with the result that the idle frame is not detected (IDLE flag is not set).

#### Workaround

None.

### 2.7.2 In full duplex mode, the Parity Error (PE) flag can be cleared by writing to the data register

#### Description

In full duplex mode, when the Parity Error flag is set by the receiver at the end of a reception, it may be cleared while transmitting by reading the USART\_SR register to check the TXE or TC flags and writing data to the data register.

Consequently, the software receiver can read the PE flag as '0' even if a parity error occurred.

#### Workaround

The Parity Error flag should be checked after the end of reception and before transmission.

### 2.7.3 Parity Error (PE) flag is not set when receiving in Mute mode using address mark detection

#### Description

The USART receiver is in Mute mode and is configured to exit the Mute mode using the address mark detection. When the USART receiver recognizes a valid address with a parity error, it exits the Mute mode without setting the Parity Error flag.

#### Workaround

None.

### 2.7.4 Break frame is transmitted regardless of nCTS input line status

#### Description

When CTS hardware flow control is enabled (CTSE = 1) and the Send Break bit (SBK) is set, the transmitter sends a break frame at the end of the current transmission regardless of nCTS input line status.

Consequently, if an external receiver device is not ready to accept a frame, the transmitted break frame is lost.

**Workaround**

None.

**2.7.5 nRTS signal abnormally driven low after a protocol violation****Description**

When RTS hardware flow control is enabled, the nRTS signal goes high when data is received. If this data was not read and new data is sent to the USART (protocol violation), the nRTS signal goes back to low level at the end of this new data.

Consequently, the sender gets the wrong information that the USART is ready to receive further data.

On USART side, an overrun is detected, which indicates that data has been lost.

**Workaround**

Workarounds are required only if the other USART device violates the communication protocol, which is not the case in most applications.

Two workarounds can be used:

- After data reception and before reading the data in the data register, the software takes over the control of the nRTS signal as a GPIO and holds it high as long as needed. If the USART device is not ready, the software holds the nRTS pin high, and releases it when the device is ready to receive new data.
- The time required by the software to read the received data must always be lower than the duration of the second data reception. For example, this can be ensured by treating all the receptions by DMA mode.

**2.7.6 Start bit detected too soon when sampling for NACK signal from the smartcard****Description**

In the ISO7816, when a character parity error is incorrect, the Smartcard receiver shall transmit a NACK error signal at  $(10.5 \pm 0.2)$  etu after the character START bit falling edge. In this case, the USART transmitter should be able to detect correctly the NACK signal by sampling at  $(11.0 \pm 0.2)$  etu after the character START bit falling edge.

The USART peripheral used in Smartcard mode doesn't respect the  $(11 \pm 0.2)$  etu timing, and when the NACK falling edge arrives at 10.68 etu or later, the USART might misinterpret this transition as a START bit even if the NACK is correctly detected.

**Workaround**

None.

### 2.7.7 Break request can prevent the Transmission Complete flag (TC) from being set

#### Description

After the end of transmission of a data (D1), the Transmission Complete (TC) flag will not be set in the following conditions: - CTS hardware flow control is enabled. - D1 is being transmitted - A break transfer is requested before the end of D1 transfer - nCTS is de-asserted before the end of transfer of D1

#### Workaround

If the application needs to detect the end of transfer of the data, the break request should be done after making sure that the TC flag is set.

### 2.7.8 Guard time is not respected when data are sent on TXE events

#### Description

In smartcard mode, when sending a data on TXE event, the programmed guard time is not respected i.e. the data written in the data register is transferred on the bus without waiting the completion of the guardtime duration corresponding to the previous transmitted data.

#### Workaround

Write the data after TC is set because in smartcard mode, the TC flag is set at the end of the guard time duration.

### 2.7.9 nRTS is active while RE or UE = 0

#### Description

The nRTS line is driven low as soon as RTSE bit is set even if the USART is disabled (UE = 0) or the receiver is disabled (RE=0) i.e. not ready to receive data.

#### Workaround

Configure the I/O used for nRTS as alternate function after setting the UE and RE bits.

## 2.8 bxCAN limitation

### 2.8.1 bxCAN time triggered communication mode not supported

#### Description

The time triggered communication mode described in the reference manual is not supported. As a result timestamp values are not available. TTCM bit must be kept cleared in the CAN\_MCR register (time triggered communication mode disabled).

#### Workaround

None.

## 2.9 Ethernet peripheral limitations

### 2.9.1 Incorrect layer 3 (L3) checksum is inserted in transmitted IPv6 packets without TCP, UDP or ICMP payloads

#### Description

The application provides the per-frame control to instruct the MAC to insert the L3 checksums for TCP, UDP and ICMP packets. When automatic checksum insertion is enabled and the input packet is an IPv6 packet without the TCP, UDP or ICMP payload, then the MAC may incorrectly insert a checksum into the packet. For IPv6 packets without a TCP, UDP or ICMP payload, the MAC core considers the next header (NH) field as the extension header and continues to parse the extension header. Sometimes, the payload data in such packets matches the NH field for TCP, UDP or ICMP and, as a result, the MAC core inserts a checksum.

#### Workaround

When the IPv6 packets have a TCP, UDP or ICMP payload, enable checksum insertion for transmit frames, or bypass checksum insertion by using the CIC (checksum insertion control) bits in TDES0 (bits 23:22).

### 2.9.2 The Ethernet MAC processes invalid extension headers in the received IPv6 frames

#### Description

In IPv6 frames, there can be zero or some extension headers preceding the actual IP payload. The Ethernet MAC processes the following extension headers defined in the IPv6 protocol: Hop-by-Hop Options header, Routing header and Destination Options header. All extension headers, except the Hop-by-Hop extension header, can be present multiple times and in any order before the actual IP payload. The Hop-by-Hop extension header, if present, has to come immediately after the IPv6's main header.

The Ethernet MAC processes all (valid or invalid) extension headers including the Hop-by-Hop extension headers that are present after the first extension header. For this reason, the GMAC core will accept IPv6 frames with invalid Hop-by-Hop extension headers. As a consequence, it will accept any IP payload as valid IPv6 frames with TCP, UDP or ICMP payload, and then incorrectly update the Receive status of the corresponding frame.

#### Workaround

None.

### 2.9.3 MAC stuck in the Idle state on receiving the TxFIFO flush command exactly 1 clock cycle after a transmission completes

#### Description

When the software issues a TxFIFO flush command, the transfer of frame data stops (even in the middle of a frame transfer). The TxFIFO read controller goes into the Idle state (TFRS=00 in ETH\_MACDBGR) and then resumes its normal operation.

However, if the TxFIFO read controller receives the TxFIFO flush command exactly one clock cycle after receiving the status from the MAC, the controller remains stuck in the Idle state and stops transmitting frames from the TxFIFO. The system can recover from this state only with a reset (e.g. a soft reset).

#### Workaround

Do not use the TxFIFO flush feature.

If TxFIFO flush is really needed, wait until the TxFIFO is empty prior to using the TxFIFO flush command.

### 2.9.4 Transmit frame data corruption

Frame data corrupted when the TxFIFO is repeatedly transitioning from non-empty to empty and then back to non-empty.

#### Description

Frame data may get corrupted when the TxFIFO is repeatedly transitioning from non-empty to empty for a very short period, and then from empty to non-empty, without causing an underflow.

This transitioning from non-empty to empty and back to non-empty happens when the rate at which the data is being written to the TxFIFO is almost equal to or a little less than the rate at which the data is being read.

This corruption cannot be detected by the receiver when the CRC is inserted by the MAC, as the corrupted data is used for the CRC computation.

#### Workaround

Use the Store-and-Forward mode: TSF=1 (bit 21 in ETH\_DMAOMR). In this mode, the data is transmitted only when the whole packet is available in the TxFIFO.

### 2.9.5 Successive write operations to the same register might not be fully taken into account

#### Description

A write to a register might not be fully taken into account if a previous write to the same register is performed within a time period of four TX\_CLK/RX\_CLK clock cycles. When this error occurs, reading the register returns the most recently written value, but the Ethernet MAC continues to operate as if the latest write operation never occurred.

See [Table 6](#) for registers and bits impacted by this limitation.



Table 6. Impacted registers and bits

| Register name  | Bit number | Bit name                  |
|----------------|------------|---------------------------|
| DMA registers  |            |                           |
| ETH_DMABMR     | 7          | EDFE                      |
| ETH_DMAOMR     | 26         | DTCEFD                    |
|                | 25         | RSF                       |
|                | 20         | FTF                       |
|                | 7          | FEF                       |
|                | 6          | FUGF                      |
|                | 4:3        | RTC                       |
| GMAC registers |            |                           |
| ETH_MACCR      | 25         | CSTF                      |
|                | 23         | WD                        |
|                | 22         | JD                        |
|                | 19:17      | IFG                       |
|                | 16         | CSD                       |
|                | 14         | FES                       |
|                | 13         | ROD                       |
|                | 12         | LM                        |
|                | 11         | DM                        |
|                | 10         | IPCO                      |
|                | 9          | RD                        |
|                | 7          | APCS                      |
|                | 6:5        | BL                        |
|                | 4          | DC                        |
|                | 3          | TE                        |
|                | 2          | RE                        |
| ETH_MACFFR     | -          | MAC frame filter register |
| ETH_MACHTHR    | 31:0       | Hash Table High Register  |
| ETH_MACHTLR    | 31:0       | Hash Table Low Register   |
| ETH_MACFCR     | 31:16      | PT                        |
|                | 7          | ZQPD                      |
|                | 5:4        | PLT                       |
|                | 3          | UPFD                      |
|                | 2          | RFCE                      |
|                | 1          | TFCE                      |
|                | 0          | FCB/BPA                   |

Table 6. Impacted registers and bits (continued)

| Register name                  | Bit number | Bit name                    |
|--------------------------------|------------|-----------------------------|
| ETH_MACVLANTR                  | 16         | VLANTC                      |
|                                | 15:0       | VLANTI                      |
| ETH_MACRWUFR                   | -          | all remote wakeup registers |
| ETH_MACPMTCSR                  | 31         | WFFRPR                      |
|                                | 9          | GU                          |
|                                | 2          | WFE                         |
|                                | 1          | MPE                         |
|                                | 0          | PD                          |
| ETH_MACA0HR                    | -          | MAC address 0 high register |
| ETH_MACA0LR                    | -          | MAC address 0 low register  |
| ETH_MACA1HR                    | -          | MAC address 1 high register |
| ETH_MACA1LR                    | -          | MAC address 1 low register  |
| ETH_MACA2HR                    | -          | MAC address 2 high register |
| ETH_MACA2LR                    | -          | MAC address 2 low register  |
| ETH_MACA3HR                    | -          | MAC address 3 high register |
| ETH_MACA3LR                    | -          | MAC address 3 low register  |
| IEEE 1588 time stamp registers |            |                             |
| ETH_PTPTSCR                    | 18         | TSPFFMAE                    |
|                                | 17:16      | TSCNT                       |
|                                | 15         | TSSMRME                     |
|                                | 14         | TSSEME                      |
|                                | 13         | TSSIPV4FE                   |
|                                | 12         | TSSIPV6FE                   |
|                                | 11         | TSSPTPOEFE                  |
|                                | 10         | TSPTPPSV2E                  |
|                                | 9          | TSSSR                       |
|                                | 8          | TSSARFE                     |
|                                | 5          | TSARU                       |
|                                | 3          | TSSTU                       |
|                                | 2          | TSSTI                       |
|                                | 1          | TSFCU                       |
|                                | 0          | TSE                         |

**Workaround**

Two workarounds are applicable:

- Ensure a delay of four TX\_CLK/RX\_CLK clock cycles between the successive write operations to the same register.
- Make several successive write operations without delay, then read the register when all the operations are complete, and finally reprogram it after a delay of four TX\_CLK/RX\_CLK clock cycles.

## **2.10 FMC peripheral limitation**

### **2.10.1 Dummy read cycles inserted when reading synchronous memories**

**Description**

When performing a burst read access to a synchronous memory, two dummy read accesses are performed at the end of the burst cycle whatever the type of AHB burst access. However, the extra data values which are read are not used by the FSMC and there is no functional failure.

**Workaround**

None.

## **2.11 QUADSPI peripheral limitation**

### **2.11.1 Extra data written in the FIFO at the end of a read transfer**

**Description**

When all the conditions listed below are gathered:

- QUADSPI is used in indirect mode
- QUADSPI clock is AHB/2 (PRESCALER = 0x01 in the QUADSPI\_CR)
- QUADSPI is in quad mode (DMODE = 0b11 in the QUADSPI\_CCR)
- QUADSPI is in DDR mode (DDRM = 0b1 in the QUADSPI\_CCR)

an extra data is incorrectly written in the FIFO when a data is read at the same time that the FIFO gets full at the end of a read transfer.

**Workaround**

One of the two workarounds listed below can be used:

- Read out the extra data until the BUSY flag goes low and discard it.
- Request an abort after reading out all the correct received data from FIFO in order to flush FIFO and have the busy low. Abort will keep the last register configuration (set the ABORT bit in the QUADSPI\_CR).

### 2.11.2 First nibble of data is not written after dummy phase

#### Description

The first nibble of data to be written to the external Flash memory is lost when both following conditions are met:

- QUADSPI is used in indirect write mode
- At least one dummy cycle is used

#### Workaround

Use alternate bytes instead of dummy phases to add latency between address phase and data phase. This works only if the number of dummy cycles corresponds to a multiple of 8 bits of data.

Example: to generate

- one dummy cycle: send one alternate byte, possible only in four data lines DDR mode or Dual-flash SDR mode
- two dummy cycles: send one alternate byte in four data lines SDR mode
- four dummy cycles: send two alternate bytes in four data lines SDR mode, or send one alternate byte in two data lines SDR mode
- eight dummy cycles: send one alternate byte in one data line SDR mode.

### 2.11.3 Wrong data can be read in memory-mapped after an indirect mode operation

#### Description

Wrong data can be read with the first memory-mapped read request when Quad-SPI peripheral entered memory-mapped mode with both LSB bits in the address register QUADSPI\_AR[1:0] not reset.

#### Workaround

QUADSPI\_AR register must be reset just before entering memory-mapped mode.

This can be done in two different ways, depending on the current Quad-SPI operating mode:

1. Indirect read mode:
  - a) Reset address register
  - b) Do an abort request to stop reading and clear busy bit
  - c) Enter memory-mapped mode.

*Note:* User should take care not to read QUADSPI\_DR register after resetting address register.

2. Indirect write mode: reset the address register then enter to memory-mapped mode

*Note:* User should take care not to write to QUADSPI\_DR register after resetting address register.

## 2.12 SDIO peripheral limitations

### 2.12.1 Wrong CCRCFAIL status after a response without CRC is received

#### Description

The CRC is calculated even if the response to a command does not contain any CRC field. As a consequence, after the SDIO command IO\_SEND\_OP\_COND (CMD5) is sent, the CCRCFAIL bit of the SDIO\_STA register is set.

#### Workaround

The CCRCFAIL bit in the SDIO\_STA register shall be ignored by the software. CCRCFAIL must be cleared by setting CCRCFAILC bit of the SDIO\_ICR register after reception of the response to the CMD5 command.

### 2.12.2 No underrun detection with wrong data transmission

#### Description

In case there is an ongoing data transfer from the SDIO host to the SD card and the hardware flow control is disabled (bit 14 of the SDIO\_CLKCR is not set), if an underrun condition occurs, the controller may transmit a corrupted data block (with wrong data word) without detecting the underrun condition when the clock frequencies are such that:

$$[3 \times \text{period(PCLK2)} + 3 \times \text{period(SDIOCLK)}] \geq (32 / (\text{BusWidth})) \times \text{period(SDIO\_CK)}.$$

#### Workaround

Avoid the above-mentioned clock frequency relationship, by:

- incrementing the APB frequency;
- or decreasing the transfer bandwidth;
- or reducing SDIO\_CK frequency.

## 2.13 ADC peripheral limitation

### 2.13.1 ADC sequencer modification during conversion

#### Description

If an ADC conversion is started by software (writing the SWSTART bit), and if the ADC\_SQRx or ADC\_JSQRx registers are modified during the conversion, the current conversion is reset and the ADC does not restart a new conversion sequence automatically.

If an ADC conversion is started by hardware trigger, this limitation does not apply. The ADC restarts a new conversion sequence automatically.

#### Workaround

When an ADC conversion sequence is started by software, a new conversion sequence can be restarted only by setting the SWSTART bit in the ADC\_CR2 register.

## 2.14 DAC peripheral limitations

### 2.14.1 DMA underrun flag management

#### Description

If the DMA is not fast enough to input the next digital data to the DAC, as a consequence, the same digital data is converted twice. In these conditions, the DMAUDR flag is set, which usually leads to disable the DMA data transfers. This is not the case: the DMA is not disabled by DMAUDR=1, and it keeps servicing the DAC.

#### Workaround

To disable the DAC DMA stream, reset the EN bit (corresponding to the DAC DMA stream) in the DMA\_SxCR register.

### 2.14.2 DMA request not automatically cleared by DMAEN=0

#### Description

If the application wants to stop the current DMA-to-DAC transfer, the DMA request is not automatically cleared by DMAEN=0, or by DACEN=0.

If the application stops the DAC operation while the DMA request is high, the DMA request will be pending while the DAC is reinitialized and restarted; with the risk that a spurious unwanted DMA request is serviced as soon as the DAC is re-enabled.

#### Workaround

To stop the current DMA-to-DAC transfer and restart, the following sequence should be applied:

1. Check if DMAUDR is set.
2. Clear the DAC/DMAEN bit.
3. Clear the EN bit of the DAC DMA/Stream
4. Reconfigure by software the DAC, DMA, triggers etc.
5. Restart the application.

## 2.15 DSI Host peripheral limitations

### 2.15.1 When used over the DSI link, the Tearing Effect Interrupt Flag is set when an Acknowledge Trigger is received from the display

#### Description

In Adapted Command Mode, when the Tearing Effect mechanism is used over the DSI link, the Tearing Effect Interrupt Flag (TEIF) of the DSI Wrapper Interrupt Status Register (DSI\_WISR) is asserted when an Acknowledge Trigger is received from the display.

Acknowledges Trigger can be received from the display:

- for each packet when the Acknowledge Request Enable (ARE) bit of the DSI Host Command Mode Configuration Register (DSI\_CMCR) is set
- when a response is awaited from the display

### Workaround

Do not use the Tearing Effect over the link but use the dedicated TE pin.

When using the Tearing Effect over the link, do not use the Tearing Effect interrupt nor Automatic Refresh Mode, but launch the display refresh immediately after a `set_tear_on` or a `set_scanline` DCS command (as the display is driving the DSI link until the Tearing Effect occurs, the refresh will be automatically stalled until the Tearing Effect).

## 2.15.2 The time to activate the clock between HS transmissions is not calculated correctly

### Description

In Automatic Clock Lane control mode, the DSI Host can turn off the clock lane between two High-Speed transmissions.

To do so, the DSI Host calculates the time required for the clock lane to change from High-Speed to Low-Power and from Low-Power to High-Speed.

These timings are configured by the `HS2LP_TIME` and `LP2HS_TIME` in the DSI Host Clock Lane Timer Configuration Register (DSI\_CLTCCR). DSI Host is not calculating `LP2HS_TIME + HS2LP_TIME` but `2 x HS2LP_TIME` instead.

### Workaround

Configure `HS2LP_TIME` and `LP2HS_TIME` with the same value as the max between `HS2LP_TIME` and `LP2HS_TIME`.

As an example, if `HS2LP_TIMER = 44` and `LP2HS_TIME = 113` configure the register fields as follows:

- `HS2LP_TIME = 113`
- `LP2HS_TIME = 113`

## 2.15.3 The immediate update procedure may fail

### Description

The immediate update procedure implies that both the Update Register (UR) and the Enable (EN) bits of the DSI Host Video Shadow Control Register (DSI\_VSCR) are initially cleared, and are set by the same instruction.

Because of a race condition between the two signals, this immediate update procedure may fail in few cases, leading the DSI Host to wait until the next frame end before updating the configuration.

### Workaround

After an "Immediate update" procedure, verify if the configuration is updated by reading the auto-cleared bit UR.

If the UR bit is not cleared, repeat the process by writing first 0x0000 then 0x0101 in DSIHOST\_VSCR.



### 3 Revision history

**Table 7. Document revision history**

| Date        | Revision | Changes  |
|-------------|----------|--|
| 27-Aug-2015 | 1        | Initial release.   |
| 26-Oct-2015 | 2        | Updated <a href="#">Table 4: Summary of silicon limitations</a> .<br>Updated <a href="#">Section 2.11.1: Extra data written in the FIFO at the end of a read transfer</a> .<br>Added <a href="#">Section 2.15: DSI Host peripheral limitations</a> and its subsections.  |
| 14-Jan-2016 | 3        | Updated <a href="#">Table 4: Summary of silicon limitations</a> .<br>Added <a href="#">Section 2.1.7: Wakeup from Standby mode with RTC</a> .  |
| 13-Oct-2016 | 4        | Updated <a href="#">Table 4: Summary of silicon limitations</a> .<br>Updated <a href="#">Section 2.1.5: Delay after an RCC peripheral clock enabling</a> , <a href="#">Section 2.4.2: Start cannot be generated after a misplaced Stop</a> , <a href="#">Section 2.5.1: BSY bit may stay high at the end of a data transfer in slave mode</a> and <a href="#">Section 2.5.2: The last transacted bit of data or CRC calculation can be corrupted for the received data in master mode depending on the timing of the feedback communication clock respect to the APB clock (SPI or I2S)</a> .<br>Added <a href="#">Section 2.1.8: Data Cache might be corrupted during Flash Read While Write operation</a> , <a href="#">Section 2.5.3: Wrong CRC calculation when the polynomial is even.</a> , <a href="#">Section 2.11.2: First nibble of data is not written after dummy phase</a> and <a href="#">Section 2.11.3: Wrong data can be read in memory-mapped after an indirect mode operation</a> . |
| 28-Jul-2017 | 5        | Replaced former <a href="#">Silicon identification</a> with <a href="#">Applicability</a> , and former <a href="#">Table 1: Device identification</a> with <a href="#">Table 2: Device variants</a> .<br>Updated <a href="#">Section 2: Summary of silicon limitations</a> .<br>Updated <a href="#">Table 4: Summary of silicon limitations</a> .<br>Added <a href="#">Section 2.1.9: FMC_SDNWEN alternate function on PA7</a> .   |

**IMPORTANT NOTICE – PLEASE READ CAREFULLY**

STMicroelectronics NV and its subsidiaries ("ST") reserve the right to make changes, corrections, enhancements, modifications, and improvements to ST products and/or to this document at any time without notice. Purchasers should obtain the latest relevant information on ST products before placing orders. ST products are sold pursuant to ST's terms and conditions of sale in place at the time of order acknowledgement.

Purchasers are solely responsible for the choice, selection, and use of ST products and ST assumes no liability for application assistance or the design of Purchasers' products.

No license, express or implied, to any intellectual property right is granted by ST herein.

Resale of ST products with provisions different from the information set forth herein shall void any warranty granted by ST for such product.

ST and the ST logo are trademarks of ST. All other product or service names are the property of their respective owners.

Information in this document supersedes and replaces information previously supplied in any prior versions of this document.

© 2017 STMicroelectronics – All rights reserved