


3-5-3 Example of Machining with E.S.P.E.R Light 1 (Punch shape - single part/2nd cut machining)

<Machining shape>



<Example of machining conditions>

Wire diameter and type	= $\phi 0.2$ mm, brass
Workpiece material	= SKD11
Surface roughness	= $4\mu\text{mR}_{\text{max}}$
Workpiece thickness	= 20mm
Finish margin	= 0 (one side)
Approach machining distance	= 3.0mm

<Machining procedure>

- 1) Install the workpiece, and set the flatness and parallelism.
- 2) Position, and then move the axis to the start point
- 3) Insert the wire, and adjust the nozzle height.
- 4) Input the program, and then input the parameters on the "E.S.P.E.R LT" screen.
- 5) Press "Machining OK", and start machining.

- Machining is carried out to finishing in the uncut state. Three programs are required, one for the forward direction, one for the reverse direction and one for cutoff.
- E No. (E), machining speed (FA) and offset (H) are not required as these are automatically set when the "E.S.P Light Search" is used.

Example of creating NC program

<Forward direction>

```

M80M82M84
G90
G92X0.Y0.
G41G01X0.Y5.
G01X-5.Y5.
G01X-5.Y15.
G01X5.Y15.
G01X5.Y5.
G01X3.Y5.
G40G01X3.Y4.5
G23 (Return to main program)
%
```

<Reverse direction>

```

M80M82M84
G90
G92X3.Y4.5
G42G01X3.Y5.
G01X5.Y5.
G01X5.Y15.
G01X-5.Y15.
G01X-5.Y5.
G01X0.Y5
G40G01X0.Y0
G23 (Return to main program)
%
```

<Cut off>

```


M00 (Stop)
M80M82M84
G90
G92X0.Y0.
G42G01X0.Y5.
G01X3.Y5.
M00
M21 (Cut wire)
M91 (Optimum feed OFF)
G40G01X3.Y4.5
G01X0.Y0.F60.
G23 (Return to main program)
%
```

Insert M00 since the scrap will drop off.

Insert G23 at the end (after G40) to make this a subprogram

Example of machining operation 1 (Punch shape - single part/2nd cut machining)

- (1) Input the program to be machined (L101, L102, L103 for this example)
- (2) Press twice.
- (3) Press the main menu . → The "MONITOR" screen will open.
- (4) Press the submenu (E.S.P Light Search). → The "E.S.P.E.R LT" screen will open.
- (5) Set the highlighted fields on the screen. → The machining conditions will be searched for automatically, and when completed, the "Search Successful. OK to machine after checking results" message will appear at the lower right of the screen.



- (6) Press the submenu (search results/edit). → The "SEARCH RESULTS/EDIT" screen will open, and the number of cuts, offset amount, machining conditions, machining speed and predicted surface roughness will be displayed.
- (7) Check the machining conditions and number of cuts, and then press "CLOSE".
- (8) Press the submenu (machining OK).
 - The machining shape will be automatically drawn and checked.
- (9) Press . → 2nd cut will be executed, and then operation will stop.
- (10) Press . → Cutoff machining will be executed, and then operation will stop.
- (11) Press , enter the manual mode, raise the upper guide, and remove any scraps.
- (12) Press to return to the automatic mode, and then press . → The axis will return to the start point, and machining will end.

COMPILED DATA/EDIT

NO. CUTS	OFFSET:H	E-SET:E	FEEDRATE:FA
APRC	0	942	1.000
1	180	1021	5.000
2	120	1022	2.500
3	103	1023	3.000
4	0	0	0.000
5	0	0	0.000

EST. SURF.FIN. 4.0 Rmax[μm]

CUT OFF

NO. CUTS	OFFSET:H	E-SET:E	FEEDRATE:FA
APRC	0	942	1.000
1	180	1021	5.000