

Weldment Assembly Repair

<h1 style="margin: 0;">SIKORSKY</h1> <h1 style="margin: 0;">AIRCRAFT</h1> <h1 style="margin: 0;">DESIGN RECORD BOOK</h1>			
Prepared by: <u>Kenny Welch</u>		DRB No: <u>2017-SA-92-090</u>	
Title: <u>Weldment Assembly Repair</u>			
Start Date: <u>6/21/2017</u>		Detail Dwg: <u>92306-04102</u>	
End Date: _____		Assy Dwg: <u>92306-04102-057</u>	
No. Pages: _____		Related Documents: (1) _____ (3) _____	
Model: <u>S-92A</u>		(2) _____ (4) _____	
Keyword: (1) <u>Crack</u> (2) <u>Weldment</u>		Hours: _____	
(3) _____		Model Effectivity: <u>920145</u>	
Supersedes: _____		FEM Analysis: _____	
Analysis Type: <u>Repair</u>		Charge No: _____	
Reason for Analysis: <u>Field Support</u>		Superseded By: _____	
<b>Description:</b>			
Customer found chafing marks on the Weldment assy, P/No 92306-04102-057. See attached photo for details.			
Customer request a welding procedure for the weldment assy.			
Note: This repair is similar to DRB 2016-SA-92-149.			
<b>Results:</b>			
The repair procedure is specified in this DRB, and for FAA purposes, this repair is considered "MINOR".			
Assigned: <u>Kenny Welch</u>		Approval: <u><i>Al Miller</i></u>	
Approve Date: <u>6/21/17</u>		Approve Date: <u>6/21/2017</u>	

## Background

TAS are completing a 1500 hour inspection on A/C S/N 920146

The No. 1 engine weldment assembly P/N 92306-04102-057 was found chafed by the No. 1 engine inboard expandable pin due to pin migration.

Reference attached JPEG image.

The chafed opening measures 0.625 in. long x 0.125 in. wide, and is located approximately mid-span on the tube.

A replacement weldment assembly has been on order with SCI since 10 JUN 2017. Reference RSA 003000279802.

SCI is unable to supply a replacement weldment or even provide a delivery date for a replacement.


This is the last remaining part required to return 920146 to service.

TAS request a weld repair scheme on an AOG basis.

The repair procedure is specified in this DRB, and for FAA purposes, this repair is considered "MINOR".

**Note: This repair is similar to repair outlined in DRB 2016-SA-92-149**





McConnell, David P e338737  
Thai Aviation Services S-92A  
A/C S/N 920146 A/C TT 5590.8

Total Length 0.625"  
Width 0.125"

Weldment P/N 92306-04102-057  
IPC Ref. 21-27-01 Fig. 402 Item 190  
Position #1 Engine Installation

**Figure 1- Reported Damage**

**Procedure:**

Note: A complete review of this DRB is recommended before starting the repair. This repair involving sheet metal and structural parts, routine steps such as cleaning, layout and drilling, deburring, standard repairs, corrosion control, clean up after rework, chemical coating for aluminum after cutting/trimming parts, and paint touch up may not be called out herein. However, these steps and all other required routine tasks shall be done.

1. Remove the Weldment Assembly from the aircraft.
2. Repair the chafe damage by welding per MIL-STD-2219 Class B using AMS 4951 filler wire. Grind flush.  
Note: Do not cut the damaged area out - just apply a weld bead (puddle) into the chafe.
3. After welding, stress relieve per AMS-H-81200 AT 850 +/-25F FOR 2 +/- 0.25 hours.
4. Penetrant inspect ASTM-1417, no cracks allowed.
5. Upon completion of repair the unit will be pressure tested to 120 PSIG for 5 minutes. Zero leakage is allowed.
6. If any problems are encountered or if further assistance is required, please contact Service Engineering.