

## Grant Robinson

---

**From:** McConnell, DAVE P <dave.p.mcconnell@lmco.com>  
**Sent:** Friday, October 20, 2017 9:27 AM  
**To:** Russell Squires  
**Cc:** Grant Robinson  
**Subject:** RE: Float Test S76C++

Russ

Following is the CSE response to my request to clarify Sikorsky's position regarding S-76 float test procedures.

Case Number: C0072301  
Customer: Thai Aviation Services Limited  
Aircraft S/N: 760XXX  
Aircraft Model: S-76C++  
Part Number: 76251-01106-018  
Case Subject: RFM Float System Test Procedure Deviation

**Problem Description:**

Reference  
S-76C RFM SA 4047-76C-15 Pt. 1 Sec II, Normal Procedures, Page 2-33

TAS is reviewing legacy operating procedures from the time when the TAS S-76C++ fleet was owned and managed by CHC.

One legacy CHC procedure approved removal of the daily Flotation System Test from the RFM and created it as a separate 25-hour maintenance task.

TAS is unable to confirm through existing documentation that this procedural deviation was approved by Sikorsky.

Please advise if SA has given approval to CHC to perform a 25-hour float system check by maintainers as a substitute for the daily RFM check by crew. Please advise CRM Log ID Number, or FTR or Case number if known. EoM

This email notification is provided as the case has been reviewed and does not contain technical data in the issue description.

**Problem Resolution:**

CSE does not have any record of giving CHC approval to remove Flotation System Test from the FAA Approved RFM.

Sikorsky Engineering recommends customer follow the RFM and perform Flotation System Test Daily prior to aircraft performing overwater flights IAW S-76S RFM SA 4047-76C-15 Pt. 1 Sec II, Normal Procedures, Page 2-33.

This email notification is provided as the case has been reviewed and does not contain technical data in the resolution.

**David P. McConnell**  
Senior Field Service Representative  
Sikorsky, a Lockheed Martin company  
Email [dave.p.mcconnell@lmco.com](mailto:dave.p.mcconnell@lmco.com)

Smartphone +1 (203) 873-8552 (US)  
Efax +1 (860) 998-8791 (US)  
Cell +66 (0)8 7750-7920 (Thailand)



**WARNING:** THE INFORMATION IN THIS TRANSMISSION IS CONFIDENTIAL AND IS MEANT TO BE READ AND USED ONLY BY THE INTENDED RECIPIENT. ENCLOSED COMMODITIES, TECHNICAL DATA OR SOFTWARE ARE SUBJECT TO THE EXPORT CONTROL OF EITHER THE INTERNATIONAL TRAFFIC IN ARMS REGULATIONS (ITAR) OR THE EXPORT ADMINISTRATION REGULATIONS (EAR) AND CANNOT BE EXPORTED WITHOUT THE AUTHORIZATION OF EITHER THE DEPARTMENT OF STATE OR THE DEPARTMENT OF COMMERCE PRIOR TO EXPORT. EXPORT INCLUDES DISCLOSURE AND OR ACCESS TO COMMODITIES, TECHNICAL DATA OR SOFTWARE BY FOREIGN NATIONALS WHETHER LOCATED IN THE UNITED STATES OR ABROAD. THIS REQUIREMENT APPLIES EQUALLY TO FOREIGN NATIONAL EMPLOYEES OF U.S. COMPANIES AND THEIR FOREIGN SUBSIDIARIES. THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLUDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE FOR ANYONE OTHER THAN SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES WITHOUT ITS WRITTEN CONSENT, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED HEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES. ANY REVIEW, USE, DISSEMINATION, DISTRIBUTION OR COPYING OF THIS TRANSMITTAL BY AN UNINTENDED RECIPIENT IS STRICTLY PROHIBITED, AND MAY BE A VIOLATION OF LAW SUBJECT TO PENALTY.

---

**From:** Russell Squires [mailto:Russell\_s@tasl.co.th]  
**Sent:** Thursday, October 19, 2017 13:34  
**To:** Mcconnell, DAVE P (TH) <dave.p.mcconnell@lmco.com>  
**Subject:** EXTERNAL: Fwd: Float Test S76C++

Thanks,  
Russ Squires  
Maintenance Planning Manager  
Thai Aviation Services Ltd.  
Mobile +66 (0) 819630968  
Nakhon Si Thammarat  
Thailand

Begin forwarded message:

**From:** Russell Squires <[Russell\\_s@tasl.co.th](mailto:Russell_s@tasl.co.th)>  
**Date:** October 18, 2017 at 1:50:38 PM GMT+7  
**To:** "Mcconnell, DAVE P" <[dave.p.mcconnell@lmco.com](mailto:dave.p.mcconnell@lmco.com)>, James O'Brien  
<[Jim\\_o@tasl.co.th](mailto:Jim_o@tasl.co.th)>  
**Cc:** Nattawut Wongyai <[Nattawut\\_w@tasl.co.th](mailto:Nattawut_w@tasl.co.th)>, Grant Robinson <[Grant\\_r@tasl.co.th](mailto:Grant_r@tasl.co.th)>,  
Daryl Balmer <[Daryl\\_b@tasl.co.th](mailto:Daryl_b@tasl.co.th)>, Daryl Dixon <[daryl\\_d@tasl.co.th](mailto:daryl_d@tasl.co.th)>, Christopher  
Thompson <[Christopher\\_t@tasl.co.th](mailto:Christopher_t@tasl.co.th)>  
**Subject: RE: Float Test S76C++**

Hi Dave

As requested see below and let me know if you need more info.



Thanks,  
Russ Squires  
Maintenance Planning Manager  
Thai Aviation Services Ltd.  
Nakhon Si Thammarat  
Thailand  
Mobile; +66 (0) 819630968

---

**From:** Mcconnell, DAVE P [<mailto:dave.p.mcconnell@lmco.com>]  
**Sent:** Tuesday, October 17, 2017 10:49 AM  
**To:** Russell Squires <[Russell\\_s@tasl.co.th](mailto:Russell_s@tasl.co.th)>; James O'Brien <[Jim\\_o@tasl.co.th](mailto:Jim_o@tasl.co.th)>  
**Cc:** Nattawut Wongyai <[Nattawut\\_w@tasl.co.th](mailto:Nattawut_w@tasl.co.th)>; Grant Robinson <[Grant\\_r@tasl.co.th](mailto:Grant_r@tasl.co.th)>; Daryl Balmer <[Daryl\\_b@tasl.co.th](mailto:Daryl_b@tasl.co.th)>; Daryl Dixon <[daryl\\_d@tasl.co.th](mailto:daryl_d@tasl.co.th)>; Christopher Thompson

<[Christopher\\_t@tasl.co.th](mailto:Christopher_t@tasl.co.th)>

**Subject:** RE: Float Test S76C++

Russ

I'll look into this.

Please clarify the reference to RFM 2.33, below. I'm unable to locate it.

Dave

---

**From:** Russell Squires [[mailto:Russell\\_s@tasl.co.th](mailto:Russell_s@tasl.co.th)]

**Sent:** Tuesday, October 17, 2017 09:51

**To:** James O'Brien <[Jim\\_o@tasl.co.th](mailto:Jim_o@tasl.co.th)>; Mcconnell, DAVE P (TH) <[dave.p.mcconnell@lmco.com](mailto:dave.p.mcconnell@lmco.com)>

**Cc:** Nattawut Wongyai <[Nattawut\\_w@tasl.co.th](mailto:Nattawut_w@tasl.co.th)>; Grant Robinson <[Grant\\_r@tasl.co.th](mailto:Grant_r@tasl.co.th)>; Daryl Balmer <[Daryl\\_b@tasl.co.th](mailto:Daryl_b@tasl.co.th)>; Daryl Dixon <[daryl\\_d@tasl.co.th](mailto:daryl_d@tasl.co.th)>; Christopher Thompson <[Christopher\\_t@tasl.co.th](mailto:Christopher_t@tasl.co.th)>

**Subject:** EXTERNAL: Re: Float Test S76C++

Hi Dave

While working under the umbrella of CHC the float test on the S76 was removed from the pilot check list and placed into the maintenance inspection program on a 25 hour interval. The reason for this change was due to incidents of floats being inadvertently deployed during tests.

As per our discussion please go ahead with the idea of checking with Sikorsky to see if they have any request in the past for AMOC for the RFM daily float test requirement.

The following copied from the RFM 2.33

Make this check for electrical continuity daily before all anticipated overwater flights.

Please let me know if you need more info.

Thanks,  
Russ Squires  
Maintenance Planning Manager  
Thai Aviation Services Ltd.  
Mobile +66 (0) 819630968  
Nakhon Si Thammarat  
Thailand

On Oct 16, 2017, at 10:17 AM, Russell Squires <[Russell\\_s@tasl.co.th](mailto:Russell_s@tasl.co.th)> wrote:

Make this check for electrical continuity daily before all anticipated overwater flights.

TAS web portal : <http://saas.tasl.co.th>

*The information contained in this message is confidential and is intended for the addressee only.*

*If you have received this message in error or there are any problems please notify the originator immediately.*

*The unauthorised use, disclosure, copying or alteration of this message is strictly forbidden.*

TAS web portal : <http://saas.tasl.co.th>

*The information contained in this message is confidential and is intended for the addressee only.*

*If you have received this message in error or there are any problems please notify the originator*

*immediately.*

*The unauthorised use, disclosure, copying or alteration of this message is strictly forbidden.*