

Repair of Cracks Found in Float Bottle Support Brackets

<h1 style="margin: 0;">SIKORSKY AIRCRAFT DESIGN RECORD BOOK</h1>				Record NO:
Prepared by Steve Morgan		DRB No: 2017-SA-92-081		
Title Repair of Cracks Found in Float Bottle Support Brackets				
Start Date: 8/4/2017	Detail Dwg 			
End Date: 	Assy Dwg 			
No. Pages: 	Related Documents: (1) (3) 		(2) (4) 	
Model: S-92A				
Keyword: (1) Float Bottle (2) Crack		Hours: 		
(3) Support Bracket		Model Effectivity: S92A		
Supersedes: 				
Analysis Type Repair				
Reason for Analysis Field Support				
Charge No: 				
Superseded By: 				
Description: This document provides a repair for cracking damage found on the 92202-05126 or 92202-05132 Float Bottle Support Brackets.				
Results: Repair with the procedure documented in this DRB. The repair procedure is specified in this DRB, and for FAA purposes, this repair is considered "MINOR".				
Assigned: John Scheib		Approval: <i>John W Scheib</i>		
Approve Date: 8/4/2017				

Repair of Cracks Found in Float Bottle Support Brackets

Background:

During replacement of rear float assembly the customer found the support bracket for the bottle has a small crack in the corner. Typical cracks in each bracket originate in the upper radius of the inboard attach clip and extend outboard in a downward curve. Ensure cracking does not exceed lengths shown in the Figures below.




Figure 1 – General Location of Crack




Figure 2 – Crack Location

Repair of Cracks Found in Float Bottle Support Brackets




Figure 3 – Looking Down at Crack



Figure 4 – View Looking Up at Crack

Repair of Cracks Found in Float Bottle Support Brackets

Repair Procedure:

1. Prepare the ship for ground maintenance.
2. Remove any legacy fasteners from the repair area. Disconnect the steel band from the repair area.
3. Fabricate an inner doubler from .032" thick, 301 ¼ hard stainless steel sheet approximately as shown in Figure 5. Corner radii of the doublers shall be 0.190" minimum. Temporarily clamp the doublers into position and check for fit. If satisfied with the fit, back – drill the holes for the legacy rivets (shown in Figure 2) into the doublers. Strive to maintain 2D edge distance for the fasteners in the doublers, but the edge distance can be as low as 1.5D if necessary. Deburr the fastener holes and the edges of the doublers. Vacuum the area to remove any loose particles.
4. Fabricate an outer finger doubler from .020 gauge, 301 ¼ hard stainless steel sheet approximately as shown in Figure 6. Corner radii of the doubler shall be 0.190" minimum. Strive to maintain 2D edge distance and for the fasteners, but the edge distance can be as low as 1.5D if necessary. Bend the "fingers" of the finger doubler to fit over the straight doubler as shown in Figure 6. Temporarily clamp the finger doubler into position and check for fit. Back – drill the holes in the "fingers. Also back – drill the holes for the 3 legacy band fasteners into the doubler at this time using the existing holes as templates. De-burr the fastener holes and the edges of the doubler. Vacuum the area to remove any loose particles.
5. Layout and drill the .128" dia BJ4 field repair rivet locations as shown in either Figure 5 or Figure 6. Strive to maintain 2D edge distance and for the fasteners, but the edge distance can be as low as 1.5D if necessary.
6. Degrease the doublers and the repair area by wiping with a low-lint cleaning cloth (conforming to A-A-59323, Type II) using acetone (conforming to ASTM D329) or ethyl alcohol (conforming to A-A-51693). Wash with clean water to a water-break free condition.
7. Brush cadmium plate the doublers per MIL-STD-865.
8. Apply one coat of MIL-P-23377 epoxy primer to the doublers.
9. Prior to installation, lightly coat the mating surfaces of the doublers with MIL-S-8802 sealant.
10. Rivet the doublers into place on the bracket as shown in Figure 5 and Figure 6. Use BJ4 field rivets through the "fingers", and fasteners of the same type, size and material as the legacy fasteners in all the other locations. Wet – install the fasteners with MIL-S-8802 sealant.
11. After the sealant has cured, clean up any excess with a non-metallic scraper
12. Again degrease the repair area by wiping with a low-lint cleaning cloth (conforming to A-A-59323, Type II) using acetone (conforming to ASTM D329) or ethyl alcohol (conforming to A-A-51693). Wash with clean water to a water-break free condition.
13. Apply another coat of MIL-P-23377 epoxy primer to the repair area.

Repair of Cracks Found in Float Bottle Support Brackets





Figure 5 – Inner Repair Doubler

Repair of Cracks Found in Float Bottle Support Brackets



★ = BJ4 Repair Fastener

Outer Finger Doubler
(green profile)




Figure 6 – Outer Finger Doubler