

Program - 2

Receive a stepper Motor interface to rotate the motor in clockwise by N steps. Introduce suitable delay between successive steps.

```
#include <stdio.h>
#include <reg51.h>
char *data port = 0xe803;
char *data port = 0xe800;
char *data acc = 0x30;

delay() // Delay between the rotation of the Stepper Motor.
{
    int j;
    for (j=0; j<800; j++)
    {
        //
    }
}

void main()
{
    port = 0x80; // Configure All the ports of 8255 as output port.

    while (1)
    {
        acc = 0x88;
        port a = acc;
        delay();
        acc = 0x44;
        port a = acc;
    }
}
```

```
delay();  
acc = 0x22;  
port a = acc;  
delay();  
acc = 0x11  
port a = acc;  
delay();  
}  
}
```