

4 Axis Motion Control Development Platform Manual

Contact No: 9960664674
Email Id: pmsroboticsrc@gmail.com

4 Axis Motion Control Development Platform



Contact No: 9960664674
Email Id: pmsroboticsrc@gmail.com

4 Axis Development Platform

- Four-axis motion control development platform is specially designed for Motion Control study and real time implementation of the same.
- It meets the requirements in technique development and real time testing.
- Also, it helps in teaching various kinds of motion control systems.

- Building logic with inputs and outputs
- Study of position , velocity and acceleration
- Development of automation software
- Explanation and setting of PID control parameters
- Single axis control
- Simultaneous axis control
- Interpolation-linear and circular
- Study of S-curve and T-curve
- Plotting preview graphs of position ,acceleration and velocity. Actual verses generated.

Experiments of 4 axis development platform.

Tools and Software Required: 4 axis Development Platform Hardware Setup, GT commander Software and MCE Studio Software.

For installation of software refer the below links:

GT Commander:

https://drive.google.com/drive/folders/1r6fm1GnkV23eN_Bydb3iDWRirbbkRsju?usp=sharing

MCE Studio:

<https://drive.google.com/drive/folders/1sWkjBwLTK1pbS55mPsPbC8sL6-7vHn1s?usp=sharing>

- Experiment no 1 : Testing of 4 axis development platform


Tools and Software Required: Development Platform Hardware setup and GT commander Software.

Open the GT Commander Software.


- Select Individual axis control menu:




- For axis 1 and axis 2 use $P = 10$, $I = 5$, $D=20$;




- Control mode=0 servo mode.



- Update it



- Click on servo on



- Give position=15000, acceleration=0.01 , velocity=1

Axis Control

Axis 1

Servo Filter Para

Kp : 10

Ki : 05

Kd : 20

Kvff : 0

Kaff : 0

Intergration Limit : 32767

Motion Limit : 32767

Motion Bias : 0

Pos Error Limit : 32767

Pulse Width : 4096

Motor Control value : 0

Actual Position : 0

Acc Limit : 16384

Brk Position : 0

Intr Mask : 0

☒ Servo On/Off
☒ Loop Closed/Open
☒ Auto Stop On/Off
☐ Auto Update On/Off
☒ Limits On/Off

Home Capt Index Capt

Brk Pnt Mode

☒ Brk Pnt Mode Disabled
☐ Pos Brk Pnt Mode
☐ Neg Brk Pnt Mode
☐ Home Brk Mode
☐ Motion Done Brk Mode

Control Mode: 0 Servo Mode

T-Curve | S-Curve | Vel contouring | G-Mode


Position : 15000 Acceleration : 0.01

Velocity : 1


Analog Input Interrupt Axis Servo Output Pos Syn
 Encode Pos Cmd Status Get Capture Abrupt Stop
 Encode Vel Driver Reset Zero Position Smooth Stop
 Prob Capture Clear Status Update

- Update it
- Then the motor will start running.


- Further
- For axis 3 and axis 4 don't use pid ;




- Control mode= dir mode



- Update it



- Click on servo on



- Give position=10000, acceleration=0.01, velocity=0.1

Axis Control

Axis 3

Servo Filter Para

Kp : 0

Ki : 0

Kd : 0

Kvff : 0

Kaff : 0

Intergration Limit : 32767

Motion Limit : 32767

Motion Bias : 0

Pos Error Limit : 32767

Pulse Width : 4096

Motor Control value : 0

Actual Position : 0

Acc Limit : 16384

Brk Position : 0

Intr Mask : 0

☒ Servo On/Off

☒ Loop Closed/Open

☒ Auto Stop On/Off

☐ Auto Update On/Off

☒ Limits On/Off

Home Capt

Index Capt

Brk Pnt Mode

☒ Brk Pnt Mode Disabled

☐ Pos Brk Pnt Mode

☐ Neg Brk Pnt Mode

☐ Home Brk Mode

☐ Motion Done Brk Mode

Control Mode: 2 Dir Mode

T-Curve | S-Curve | Vel contouring | G-Mode

Position : 10000

Acceleration : 0.01

Velocity : 0.1

Analog Input

Interrupt Axis

Servo Output

Pos Syn

Encode Pos

Cmd Status

Get Capture

Abrupt Stop

Encode Vel

Driver Reset

Zero Position

Smooth Stop

Prob Capture


Clear Status

Update

- Update it
- Then the motor will start running.

Further Check the inputs in IO status menu

By manually making input knob on and off , you should get signal on the dashboard of IO screen.



- Experiment no 2: Setting up PPR for Each Motor and rotating all motors for desired resolution.
- Tools and Software Required: Development Platform Hardware setup and GT commander Software.


PPR Found out for :

Axis 1= 10000 pulses, Axis 2=10000 pulses, Axis 3 =1600 pulses, Axis 4 = 4000 pulses

Position = PPR * Revolutions

Example1: If we want to rotate axis 1 motor for 3 revolutions, Find the position value.

Ans = ppr of first axis * rev =10000*3 =30000 pulses.



The screenshot shows the 'Axis Control' window for 'Axis 1'. It contains several sections:

- Servo Filter Para:** Kp: 10, Ki: 05, Kd: 20, Kvff: 0, Kaff: 0, Intergration Limit: 32767, Motion Limit: 32767, Motion Bias: 0, Pos Error Limit: 32767.
- Brk Pnt Mode:**
 - ☐ Servo On/Off
 - ☒ Loop Closed/Open
 - ☒ Auto Stop On/Off
 - ☐ Auto Update On/Off
 - ☒ Limits On/Off
 - ☒ Brk Pnt Mode Disabled
 - ☐ Pos Brk Pnt Mode
 - ☐ Neg Brk Pnt Mode
 - ☐ Home Brk Mode
 - ☐ Motion Done Brk Mode
- Buttons:** Home Capt, Index Capt.
- Control Mode:** 0 Servo Mode.
- T-Curve | S-Curve | Vel contouring | G-Mode:**
 - Position: 30000
 - Acceleration: 0.01
 - Velocity: 1

Eg2: if we want to rotate axis 3 motor for 4 revolutions find position value

Ans = ppr of third axis * rev = $1600 \times 4 = 6400$ pulses.

Eg3: if we want to rotate axis 4 motor for 8 revolutions find position value

Ans = ppr of fourth axis * 8 = $4000 \times 8 = 32000$ pulses.

Experiment 2 Exercise:

Exercise1: If we want to rotate axis 2 motor for 1.5(1 and a half) revolutions, Find the position value.


Exercise2: If we want to rotate axis 3 motor for 5 revolutions, Find the position value.

Exercise3: If we want to rotate axis 4 motor for 2.5(2 and a half) revolutions in clockwise and anticlockwise direction, Find the position value.

Experiment no 3: Single Axis control Experiment

- S-curve and T-curve
- Tools and Software Required: Development Platform Hardware setup and MCE Studio

Select Single Axis Mode in MCE Studio



Select Motor from 1-4



Set mode - Pulse / Voltage



Set S-curve or T-curve

S-CurveT-CurveVel. Contourin◀▶

Acc.:0.01Pls/ST^2

Velocity:1Pls/ST

Position:10000Pls

PID Filter

Kp:10

Ki:5

Kd:20

Click on Servo On

General Control

Servo On

R

Click On Run

Control

n

Run

Stop


Then The Graphs will be Generated

Plot Graph of Position vs Time

Plot Graph of Acceleration vs Time

Plot Graph of Velocity vs time

Googol MCE_Single Axis Experiment Module



Preview the full graph and take screen shot if required.

Contact No: 9960664674
Email Id: pmsroboticsrc@gmail.com

- Experiment no 4: Simultaneous Control for 2 motors(Linear Interpolation)

Tools and Software Required: Development Platform Hardware setup and MEC Studio Software.

Before conduction of practical ensure parameters are set correctly.

Password for the Para. Settings is *googol* in lowercase(small letters)

Select two axis(x and y) 1and2 or 3and4

Select Linear Interpolation

And give start point and end point

Servo On

Run

Verify the graphical representation.

Parameters Setting Window

Basic Para. Setting

Counts of Axes: Current Axis:

Command Type

☐ Pulse ☒ Voltage

Pulse

☒ Pulse+Direction ☐ Plus/Minus Pulse

PID Filter

Kp:
Ki:
Kd:

Parameter


Pulse Per mm: PLS/mm Homing Type:

Homing Vel.(pls/st): PLS/ST Homing Acc.: pls/st^2

Parameter of G00/G01

Vel. of G00: m/min Acc. of G00: m/min^2
Vel. Of G01: m/min Acc. of G01: m/min^2

Save



- Experiment no 5: Simultaneous Control for 2 motors (Circular Interpolation)

Tools and Software Required: Development Platform Hardware setup and MEC Studio Software.

Before conduction of practical ensure parameters are set correctly.

Select two axis(x and y) 1and2 or 3and4

Select circular Interpolation(End Pt./Radius)


And give start point and end point and required parameters

Servo On

Run

Verify the graphical representation.


on algorithm Experiment Module




4 Axis Motion Control Development Platform with visual C++ :

- STEPS:


1)Open “Microsoft Visual C++”Application.




2) Click on the “File” Menu in the Toolbar and Click on “Open Workspace”.




3) Browse to the location of "4axis platform" folder, then click on "4axis platform.dsw", then click on "Open".




4) Click on the "Execute Program" option located on the right side of Toolbar, it is Denoted by "Red Colour Exclamation Mark"



5)After that the Below Scree will Appear.



6)Click on the On button to Turn on the GT-400 Controller.



7)Click on “INI4” to Initialize ”Motor 4”.



8)Type the Position Value(example:1000,-1000,-5000,etc.) in the edit box below the initialize(INI4) button.



9)Click on the run button,so that the motor starts Running.



10)If you want to Run another Motor(example-Motor2),Click on the respective initialize button(INI2).



11) Type the Position Value in the edit box below the initialize(INI2) button.



12) Click on the run button,so that the motor-2 starts Running.



13)To Switch OFF all the Motors and Controller,Simply Click on the “OFF” button.



Google drive Link for 4 Axis Motion Control Development Platform

- Folder of all videos, photos and study and reference material related to 4 Axis Motion Control Development Platform:
<https://drive.google.com/drive/folders/1pO4o91-jD6U0Di0byat0Csh9jsq40T-S?usp=sharing>
- Servo Motor and Driver pdf:
https://drive.google.com/file/d/1Pw8kSOs_HX28N9Y1JnNmpv7CCcimEfOq/view?usp=sharing
- Stepper Motor and Driver pdf:
<https://drive.google.com/file/d/16SMYUXlNzmUVUH0cJF8SbpTLrnFWmmeb/view?usp=sharing>
- BLDC Motor and Driver pdf:
<https://drive.google.com/file/d/1CL0sQ7hglyml0YOn7mxLXdMgy5KbtJAf/view?usp=sharing>
- MCE Studio Manual:
https://drive.google.com/file/d/1aKHr_2Fz5UDAqsQBD77KlzuzKDskJvEB/view?usp=sharing
- GT User Manual:
<https://drive.google.com/file/d/1H2wVFMHD40s1zMGG30FujyNdjDp554On/view?usp=sharing>
- GT Programming Manual:
<https://drive.google.com/file/d/14SOzTa3nWfiscxIHVPRBfFkgdBv95ywB/view?usp=sharing>
- Simulink User Manual:
<https://drive.google.com/file/d/1bxKOkPze-cplieGvi0nCX3tesLfwZ8Yv/view?usp=sharing>