































FUJIKURA FIBER OPTICS VIETNAM LTD.			
TECHNICAL REPORT			
Form: 4-Pr-007-4-Fo-005	Version: 08	Page: 1/3	
Record No (get by EIC program): 4-PR-007-4-fo-005-9-RC-0071		Date: 22-Mar-22	
Report title: Changing packing method for Acacia products			
Prepared by: ChauVNB	Checked by: HienNTN	Reviewed by Technical Advisor (if any)	Approved by: DucTNM 5-Apr-22 
I. Background: CNC would like to transfer package without using PDMS contamination material such as pink sponge INOAC EAS-3. This package is used for SFF, SFF NH and LFF. This technical report is made to testing for ability of new packing design could protect product from damage during transportation.			
Product	Current packing method	New packing method	Drawing No of new packing method
SFF (or SFF NH)	 <ul style="list-style-type: none"> ➢ Too much PDMS pink sponge. ➢ Label wrapped to fiber ➢ Fiber coiling complicated 	 <ul style="list-style-type: none"> ➢ Only 1 small Non PMDS sponge per product ➢ Label stick to tray ➢ Fiber coiling with ease 	+Package case type C: 7-DWM-0567 ver.E (Test report: 000-4-TSR-927) +Package cover type C: 7-DWM-0568 ver.D (Test report: 000-4-TSR-928) +Sponge: 7-DWM-0648 (Test report: 000-4-TSR-1040)
LFF			+Package case type C: 7-DWM-0567 ver.E (Test report: 000-4-TSR-927) +Package cover type C: 7-DWM-0568 ver.D (Test report: 000-4-TSR-928) +Sponge: 7-DWM-0648 ver.02 (Test report: 000-4-TSR-1040)
II. Conclusion: -We can apply new packing method include new tray as well as quality don't change based on testing result -Productivity of packing process was improve with new packing method (use new type of label):21s/set			
III. Analysis (Yield ratio, Productivity, Cpk, Process Reliability, product's reliability...): 1. Details of changing packing method in new tray			
Step		New method	Remark
Preparation	- Stick label into black tray directly.		We applied new label (LBL0048, size: 7mmx15mm) instead of current label (PLA0130, 25.4x38.1mm) to prevent risk fiber damage when inserting current label into product.
Array packing	- Insert array & sleeve into tray & fixed by black sponge. - Lid need to be up to prevent fiber twist.	  	
Fiber packing	- Wrap fiber into tray.		
LC connector packing	- Put LC connectors into tray. - Check boot position. - Stick internal serial number into tray at this position.	 	Current process is to insert internal label into product. By sticking label into tray, we could prevent fiber damage by inserting and removing tape at QC Appearance process.
Finishing	- Remove internal Serial Number after mapping with label into system. - Close the package cover. - Fix by 8 tapes at correct positions as picture.	 	Reduce operation: insert 23pcs small pink sponge (SPG0084) & 2 pcs large pink sponge (SPG0055, SPG0085) in current method SPG0084: 7-DWM-0521A SPG0085: 7-DWM-0522A SPG0055: 7-DWG-0454
"Confidential: FOV's property, do not take out without FOV BOM's approval"			

FUJIKURA FIBER OPTICS VIETNAM LTD.			
TECHNICAL REPORT			
Form: 4-Pr-007-4-Fo-005	Version: 08	Page: 2/3	
Record No (get by EIC program): 4-PR-007-4-fo-005-9-RC-0071		Date: 22-Mar-22	
Report title: Changing packing method for Acacia products			
2. Evaluation test for new packing method We verified tray follow WD: EN-00374(2) 2.1 SFF product 2.1.1 Drop test			
We verified new packing method on new tray by drop test condition: GR63 5.3.1 for Category A follow WD: EN-00374(2)			
Times	Before drop test	After drop test	Conclusion
First drop test			<p>-All product's appearance is OK by microscope follow current Appearance criteria. After testing, we found 1/5pcs have new defect: Delamination near sleeve. Follow current criteria, it is OK & only happened on product which have fiber damaged before testing. And the fiber damaged is still same level, no larger than before testing. So we don't action for this case.</p> <div></div> <p>Fiber damage near sleeve Fiber damage near sleeve Delamination : OK</p> <p>-The array No.2 & No.3 is moved. We think that it can be come from removing the SN of sponge after packing so have gap between product & sponge. We decided 2nd testing time to confirm again.</p>
Second drop test			<p>- All product's appearance is OK by microscope follow current appearance criteria. - The fiber of first product jumped out of position as picture beside.</p> <p>=> Investigation: During observe the packing tray, we could see a risk that there's a small gap created between packing tray body and packing tray during droptest. This gap make the space for fiber jump out. We need to make this position fixed better.</p> <p>=>Countermeasure: + Make additional tapes from 6pcs to 8pcs + We fixed 3pcs tape at sponge position No. 1,3,5 to prevent gap between cover & sponge. + We fixed 3pcs tape on the right of LC connector No. 1,3,5. + We fixed 2 pcs tape at stoper of tray. => We decided 3rd time drop test to verify effectiveness of this improvement.</p>
Third drop testing	<div></div> <p>Before improvement After improvement (Countermeasure from 2nd test)</p>	 <p>Good result. All positions are kept as original.</p>	<p>-All of part position(fiber, array, sleeve, LC connectors) is fixed and not moving -Because this 3rd drop test confirm the improvement of both 1st drop test & 2nd drop test so we only check the product position is still kept or moved. -We use the result of appearance of product in 2nd testing time to confirm for 3rd time.</p>
Fourth drop test	<div></div> <p>Before improvement After improvement (Change sponge length)</p>	 <p>Good result. All positions are kept as original. There is no damage on a half of fiber circle above.</p>	<p>During first drop test for LFF product base on all of improvement SFF product, the fiber of second LFF product still jumped out. So we apply new structure of sponge from 7-DWM-0648 ver.01 to 7-DWM-0648 ver.02, especially change length from 15mm to 29mm for both SFF & LFF product as final actions to keep fiber in this position. => We decided 4th time drop test to verify effectiveness of this improvement.</p> <p>=> Result: -All of part position(fiber, array, sleeve, LC connectors) is fixed and not moving. -Because this 4th drop test confirm additional improvement so we only check the product position is still kept or moved. And inspect the appearance of a half of fiber cycle as beside. The result is OK -We use the result of appearance of product in 2nd testing time to confirm for 4th time.</p>
**Note: During testing used temporary LC cap (MCOTH0197-PNJHY-0048-22-34) but it isn't effect to testing result			
2.1.2. Vibration test GR-63 4.4 The result is OK. There isn't abnormal after testing			
No	Before testing	After testing	Remark
1			<p>The product's appearance is checked OK All of part position(fiber, array, sleeve, LC connectors) is fixed, not move. No found new defects (misalignment of the product, fiber burse out, scratches on the product, etc) after testing.</p>
Conclusion: -We can apply new packing method include new tray as well as quality don't change based on testing result.			
"Confidential: FOV's property, do not take out without FOV BOM's approval"			

TECHNICAL REPORT

Form: 4-Pr-007-4-Fo-005

Version: 08

Page: 3/3



Record No (get by EIC program): 4-PR-007-4-fo-005-9-RC-0071

Date: 22-Mar-22

Report title: Changing packing method for Acacia products

2.2 LFF product

2.2.1 Drop test

We verified new packing method on new tray by drop test condition: GR63 5.3.1 for Category A

Times	Before drop test	After drop test	Conclusion
First drop test			-All product's appearance is OK by microscope follow current Appearance criteria. -The fiber of second product jumped out of position as picture beside. => Investigation: Although we take many actions from SFF products, fiber still jumped out because the size of LFF fiber is only 0.16mm, very small. so we need to make this position fixed better. =>Countermeasure: + Apply new structure sponge's length is 29±1 instead of Sponge W8.5xL15XH8.5 to prevent completely risk fiber jumped out. => We decided 2nd time drop test to verify effectiveness of this improvement.
Second drop test	 Before improvement After improvement (Change sponge length)	 Good result. All positions are kept as original.	-All product's appearance is OK by microscope follow current Appearance criteria. -All of part position(fiber, array, sleeve, LC connectors) is fixed and not moving. -The fiber of first product is between sponge & packing tray body, still not jump out of position as picture beside-> Judge it: OK

**Note: During testing used temporary LC cap (MCOTH0197-PNJHY-0048-22-34) but it isn't effect to testing result

2.1.2. Vibration test GR-63 4.4

The result is OK. There isn't abnormal after testing

No	Before testing	After testing	Remark
1			The product's appearance is checked OK All of part position(fiber, array, sleeve, LC connectors) is fixed, not move. No found new defects (misalignment of the product, fiber burse out, scratches on the product, etc) after testing.

**Note: During testing used temporary LC cap (MCOTH0197-PNJHY-0048-22-34) but it isn't effect to testing result because this cap the same structure with final LC cap(C-09-1500-05), only different color.

Conclusion:

-We can apply new packing method include new tray as well as quality don't change based on testing result.

IV. Appendix standardization (revised quality documentation):

N/A

V. Others:

PRE3 controlled

"Confidential: FOV's property, do not take out without FOV BOM's approval"