



Audit Report for MBAEX on January 16th, 2019.

## Summary

Audit Report prepared by Solidified for MBAEX covering the MultiSigRoot smart contracts (and their associated components).

## Process and Delivery

Three (3) independent Solidified experts performed an unbiased and isolated audit of the code below. The debrief took place on January 16th, 2019, and the final results are presented here.

## Audited Files

The following contracts were covered during the audit:

- MultiSigRoot (published contract, with multiple contracts that compose it)

## Notes

The audit was based on the Rinkeby testnet contracts provided at the following addresses:

- MultiSig:
  - <https://rinkeby.etherscan.io/address/0xeaefa4027a1dff7d517c57705f3e74e4f9ea1b1ff#code>

## Issues Found

### 1. **MultiSigRoot: onlyWallet modifier can be circumvented (minor)**

---

The `onlyWallet` modifier works by checking if the given wallet address is registered as type `WALLET_TYPE_WALLET`. Since this type is set when the wallet is first attached to the node, it can be circumvented in case a contract address that has no contract deployed yet is precomputed and attached as a wallet, then a contract is deployed to the same address at a later stage when `WALLET_TYPE_WALLET` has already been set.

#### Recommendation

Instead of relying on checking `WALLET_TYPE_WALLET`, call the `isContract()` function directly in the modifier.

#### Amended [24-01-2019]

The issue was fixed and is no longer present in the contract `0x75D27Fe3Fd376CC21E958bA12FEC53081F01Cb15` (Rinkeby).

### 2. **MultiSigRoot: MultiSigRoot should not be accepting ETH (minor)**

---

`MultiSigRoot` has a payable default function, so it can accept Ether transfers. However, the `MultiSigRegulator` contract will fail to create a requirement for any transaction which has `Ether _value > 0`, since the `call(..).value(...)` function at L570 will fail.

#### Recommendation

If the described above is an intended behavior, it would be better to explicitly reject transactions transferring Ether value rather than relying on implicit failure (due to `MultiSigRegulator`'s non-payable functions and empty balance)

If `MultiSigRegulator` is changed to ignore the `_value` at L570, then any `STAKER_CONTROLLER` could transfer out Ether from `MultiSigRoot` by crafting a transaction to

some external contract's payable `pause()` function, since this function requires only one `STAKER_CONTROLLER` wallet's approval.

**Amended [24-01-2019]**

The issue was fixed and is no longer present in the contract `0x75D27Fe3Fd376CC21E958bA12FEC53081F01Cb15` (Rinkeby).

### 3. **MultiSigRoot: flag bits do not cover all node wallet indices (minor)**

---

Only 16 `flag` bits are ever set, leaving the rest of the 64 `MAX_WALLET` flags unassigned. If there is any wallet within a node which is created at an index greater than 16, that wallet will not be allowed to sign a transaction – as a consequence the transactions which require all node's wallets approval could never be executed.

**Recommendation**

Either set `flag` to `2^64-1` instead of `65535`, or remove flags all-together since all flags are presently set to `1`.

**Amended [24-01-2019]**

The issue was fixed and is no longer present in the contract `0x75D27Fe3Fd376CC21E958bA12FEC53081F01Cb15` (Rinkeby).

### 4. **MultiSigNode: Fallback function is redundant (note)**

---

Starting from Solidity 0.4.0, contracts without a fallback function automatically revert payments, making the code redundant.

**Recommendation**

As it is not utilized, this code can be removed. The contract will reject payments automatically.

**Amended [24-01-2019]**

The issue was fixed and is no longer present in the contract `0x75D27Fe3Fd376CC21E958bA12FEC53081F01Cb15` (Rinkeby).

## 5. **MultiSigNode**: **onlyParent** modifier is redundant (note)

---

The **onlyParent** modifier is not used throughout the scope of the contract.

### **Recommendation**

As it is not utilized, this code can be removed.

### **Amended [24-01-2019]**

The issue was fixed and is no longer present in the contract

`0x75D27Fe3Fd376CC21E958bA12FEC53081F01Cb15` (Rinkeby).

## 6. **MultiSigRegulator**: Not all **StableCoin**'s functions are implemented in **MultiSigRegulator** (note)

---

**StableCoin**'s **burn()** function is not implemented in **MultiSigRegulator** and do not define any requirements for execution – thus they cannot be executed from the **MultiSigRoot**.

### **Recommendation**

These functions should either be implemented or otherwise augmented so that they can be explicitly executed from the **MultiSigRoot**.

## 7. **MultiSigRegulator**: Transaction Limits are not meaningful when transferring other Tokens (note)

---

**MultiSigRegulator** allows any token transfer out of **MultiSigRoot** (because it does not check the destination address of a transaction) as long as the call function matches the ERC-20 standard. If that is intentional, the transaction limit amounts are not very meaningful, since other Tokens might have different USD value and different number of units (decimals) than the **StableCoin** Token.

**Amended [24-01-2019]**

The issue was fixed and is no longer present in the contract  
`0x75D27Fe3Fd376CC21E958bA12FEC53081F01Cb15` (Rinkeby).

## 8. MultiSigRegulator: Avoid excess computation (note)

---

Currently Node Labels (e.g. "STAKER", "STAKER\_CONTROLLER") are defined in multiple places (MultiSigRegulator, MultiSigRoot), and `keccak256` is calculated multiple times in every transaction.

**Recommendation**

Consider moving all Node Class/Labels definitions in a single contract (either Label or a new contract inheriting from Label).

**Amended [24-01-2019]**

The issue was fixed and is no longer present in the contract  
`0x75D27Fe3Fd376CC21E958bA12FEC53081F01Cb15` (Rinkeby).

## 9. Transaction requirements do not fully match the document provided for Staker and Staker Controller (note)

---

Transaction requirements do not fully match the document provided for Staker and Staker Controller, namely:

- cannot "disallow to add/remove in Staker group" - document states it can
- can add/remove Signer Controller - documents does not state it can
- can set Transaction Limit - document does not state it can

**Recommendation**

Augment the presently existing documentation to accurately reflect the transaction requirements.

**Amended [24-01-2019]**

The issue was fixed and is no longer present in the contract  
`0x75D27Fe3Fd376CC21E958bA12FEC53081F01Cb15` (Rinkeby).



Audit Report for MBAEX on January 16th, 2019.

## Closing Summary

---

MBAEX's contracts contain a few minor issues, along with several areas of note.

We recommend the minor issues are amended, while the notes are up to MBAEX's discretion, as they mainly refer to improving the operation of the smart contract.

## Disclaimer

---

Solidified audit is not a security warranty, investment advice, or an endorsement of the MBAEX platform or its products. This audit does not provide a security or correctness guarantee of the audited smart contract. Securing smart contracts is a multistep process, therefore running a bug bounty program as a complement to this audit is strongly recommended.

The individual audit reports are anonymized and combined during a debrief process, in order to provide an unbiased delivery and protect the auditors of Solidified platform from legal and financial liability.

*Solidified Technologies Inc.*



Audit Report for MBAEX on January 16th, 2019.