




# Welding problems and defects – causes and remedies




## Spatter

### Causes

- Welding current too high.
- Arc too long.
- Incorrect polarity – arc blow.
- Insufficient gas shielding.

### Remedies

- Reduce welding current.
- Reduce arc length.
- Check use of correct polarity for the consumable in question.
- Check shielding gas type and flow rate. Clean gas nozzle.
- Increase torch to plate angle.




## Deformation

### Causes

- Unsuitable welding sequence.
- Too many and too thin beads, usually because the electrode is too small.
- Poor plate fit-up before welding.
- Plates clamped insufficiently.

### Remedies

- Weld from both sides of the joint.
- Weld from the centre out, in opposite directions.
- Use a larger electrode. If possible, a high recovery type.
- Compensate for shrinkage by fixing the work pieces with a counter-angle.
- Clamp.




## Arc blow

### Causes

- Arc deflection as a result of magnetic effects into the opposite direction of the earth lead clamp.
- Arc deflection as a result of magnetic effects in the direction of heavy parts of the work piece (with magnetic materials) – especially at corners and edges.

### Remedies

- Use an AC electrode where possible.
- Try welding away from the earth clamp connection. Try splitting the earth clamp and connect to both sides of the joint.
- Use an AC electrode where possible. Position earth lead clamp such that it counteracts the influence of heavy work piece parts. Keep arc as short as possible.




## Longitudinal cracks in the heat affected zone

### Causes

- The base material is prone to hardening (because of a high C content or other alloying elements).
- Weld cools down too rapidly.
- Hydrogen in the weld e.g. because of wet weld edges, wrong or damp electrodes or shielding gases.

### Remedies

- If possible, choose a material with a better weldability. If not, apply and maintain preheat and interpass temperature and delayed cooling.
- Apply a higher preheat temperature.
- Remove moisture from welding zone. Use low-hydrogen welding consumables from moisture protective packagings or rebake welding consumables.




## Arc striking difficulties

### Causes

- Welding current too low.
- Arc voltage too low.
- Earth lead is not connected properly.
- Striking end of electrode covered by coating.

### Remedies

- Increase welding current.
- Use power source with a higher open circuit voltage.
- Ensure proper earth lead connection.
- Uncover striking end and touch-strike.




## Solidification cracks

### Causes

- Formation of phases with a low melting point in the weld, due to P, S, Cu – mostly from the parent metal).
- Unfavourable joint geometry – width/depth ratio <1.
- Weld pool too large.
- Travel speed too high (weld solidifies in an arrow shape).
- Tack welds or root passes not sufficiently strong for shrinkage forces, in case of restrained joints.

### Remedies

- Select cleaner parent material or buffer plate edges.
- Increase joint angle, use lower welding current.
- Use smaller electrode, use lower welding current. Apply stringer bead technique.
- Lower the travel speed until weld solidifies in an elliptical form.
- Apply stronger tacks and bottom passes.




## Lack of fusion defects

### Causes

- Heat input too low.
- Weld pool too large and running ahead of the arc.
- Joint included angle too small
- Electrode or torch angle is incorrect.
- Unfavourable bead positioning

### Remedies

- Increase welding current and lower travel speed.
- Reduce deposition rate and/or increase travel speed.
- Increase joint included angle.
- Position electrode or torch in such a way that the plate edges are melted.
- Position beads in such a way that sharp angles with other beads or plate edges are avoided.




## Crater cracks

### Causes

- The welding ended far too abruptly. The crack begins at a void in the welding crater, caused by the solidification shrinkage.

### Remedies

- When finishing, move back the electrode to fill-up the crater.
- With root pass welding, quickly move the arc from the weld pool to the plate edge.
- Increase crater fill time on power source.




## Undercut

### Causes

- Arc voltage too high.
- Arc too long.
- Incorrect electrode use or electrode angle.
- The electrode is too large for the plate thickness in question.
- Travel speed too high

### Remedies

- Lower arc voltage.
- Reduce arc length.
- Apply electrode angle of 30° to 45° with the standing leg. Weld lightly trailing.
- Use a smaller diameter electrode.
- Reduce travel speed.




## Porosity

### Causes

- Moisture, for example from incorrectly stored electrodes or fluxes, humid shielding gas or leaks in water-cooled welding torches.
- Moisture, rust, grease or paint on the plate edges.
- Insufficient gas shielding.
- Welding onto small gaps filled with air.

### Remedies

- Rebake or use fresh welding consumables, connect new gas bottle, check welding torch for leaks.
- Dry or clean plate edges.
- Check shielding gas type and flow-rate. Clean gas nozzle. Ensure torch to plate angle is not too small.
- Increase welding gap. When possible, apply butt joints instead of fillet or overlap welds.




## Slag inclusions

### Causes

- Slag runs ahead of the weld
- Insufficient de-slagging between passes
- Convex passes which produce slag pockets.
- Unfavourable bead sequence.

### Remedies

- Increase the travel speed or electrode angle.
- Remove slag carefully, grind if necessary.
- Avoid sharp angles or grooves between beads and layers. Increase arc voltage.
- Plan bead sequence such that sharp corners are avoided. Apply stringer bead technique.



## Lack of root penetration

### Causes

- Root gap too small.
- Electrode size too big.
- Travel speed too high.
- Incorrect use of electrode.

### Remedies

- User wider root gap.
- Use electrodes with a diameter of approximately the gap width.
- Apply lower travel speed.
- Weave between plate edges. Weld on ceramic weld metal support at high currents.