


Lead-Lag compensator:



General form of $G_c(s) = K \frac{(s + \frac{1}{T})}{(s + \frac{1}{\alpha T})}$

$G(s)$ - given (fixed)
 $G_c(s)$ - designable

zeros:


$$s = -\frac{1}{T}$$

poles:

$$s = -\frac{1}{\alpha T}$$

Lead compensator


Desired dominant closed loop pole



$$0 < \alpha < 1$$

Lag compensator

Desired dominant closed loop pole



$$\alpha > 1$$

$$G_c(s) = \frac{(s + 1/T)}{(s + 1/\alpha T)}$$

$$\angle G_c(s) = \angle s + 1/T - \angle s + 1/\alpha T$$

$$\angle G_c(s) = \theta_z - \theta_p$$

* For lead compensator: $\theta_z - \theta_p > 0$

* For lag compensator: $\theta_z - \theta_p < 0$

A point "s" is said to be on root locus (conditions):

① Angle / Phase condition:

$$\angle G_c \quad G(p') = \pi \pm 2n\pi \quad n = 0, 1, 2, \dots$$

$p' \rightarrow$ desired closed loop poles

② Magnitude condition:

$$|G_c \quad G(p')| = 1$$

Steps for lead-lag compensator design:

① Determine the desired location of the dominant closed loop poles (GIVEN)

② Evaluate $G(s)$ at the desired pole

③ Determine angle deficiency ϕ .

If $\phi > 0$ = lead compensator

else lag compensator

④ Determine $-1/T$, $-1/\alpha T$:

* Draw a ^{horizontal} line parallel to real axis passing through desired pole.

* Join the pole p' with origin

* Bisect the angle θ

* Draw lines of $\phi/2$

* Intersection with (-ve) real axis are desired points.

Lead compensator:

* Improves stability

Lag compensator:

* reduces steady state error

from below example: desired poles

$$(s-p_1')(s-p_2')=0$$


$$s^2 + 3s + 9 = 0$$

$$2\zeta\omega_n = 3$$

$$\omega_n^2 = 9$$

$$\omega_n = 3$$

Example:



$$* G_c(s) = K \frac{(s + 1/T)}{(s + \frac{1}{\alpha T})}$$

①

Desired dominant closed loop poles:

$$p' = 3(-\cos 60^\circ \pm j \sin 60^\circ)$$

$$p' = -3 \cos 60^\circ \pm j 3 \sin 60^\circ$$

$$p' = -\frac{3}{2} \pm j \frac{3\sqrt{3}}{2} \approx -1.5 \pm j 2.59$$

$$* G(s) = \frac{10}{s(s+1)} \quad * H(s) = 1$$


$$\sqrt{\frac{0.1234}{4}}$$

② Evaluate $|G(s)|$ at desired poles

$$\angle G(p') = 110^\circ - (\angle p' + \angle p'+1)$$

$$\angle G(p') = - (120^\circ + 100.93^\circ) = -220.93^\circ$$

Does not satisfy phase condition





* Desired closed loop poles are not on the root locus. So simple gain adjusted will not work. So introduce a compensator in such a way that root locus passes through desired poles.

③ Calculate Angle deficiency:


It should be -180° but it actually is -220.93° . Therefore angle compensation of 40.93° is required

$$\phi = 40.93^\circ \therefore \text{Lead compensator.}$$

④



Draw horizontal line parallel to the real axis passing through desired pole



* Determine the position of pole:


$$? + (\frac{\phi}{2} + 60^\circ) + 60^\circ = 180^\circ$$

$$? = 39.535^\circ$$

Law of Sines

$$\frac{x}{\sin(80.465^\circ)} = \frac{3}{\sin(39.535^\circ)}$$

$$x = 4.647$$




$$\therefore \frac{1}{\alpha_T} = 4.647$$

* Determine the position of zero:

$$? + 39.535^\circ + 60^\circ = 180^\circ$$

$$? = 80.465^\circ$$



Law of sines:

$$\frac{3}{\sin 80.465^\circ} = \frac{\gamma}{\sin 39.535^\circ}$$

$$\boxed{\gamma = 1.9364}$$

$$\therefore \frac{1}{T} = 1.9364$$

$$\boxed{T = 0.5164}$$


$$\frac{1}{\alpha T} = 4.647$$

$$\alpha = \frac{1}{4.647 \times T} = 0.4167$$

$$\boxed{\alpha = 0.4167}$$

Compensation Transfer function:

$$G_c(s) = K \frac{(s + 1.9364)}{(s + 4.647)}$$



Determine K:

$$|G_c(s) G(s)| = 1$$

Using magnitude condition

$$\left| K \frac{(s + 1.9364)}{(s + 4.647)} \cdot \frac{10}{s(s+1)} \right| = 1$$

$$@ s = -1.5 \pm j2.59$$

$$K = \left| \frac{(s + 4.647) s (s+1)}{10 (s + 1.9364)} \right| @ s = -1.5 \pm j2.59$$

$$K = \left| \frac{(3.147 + j2.59)(-1.5 + j2.59)(-0.5 + j2.59)}{10(0.4364 + j2.59)} \right|$$

$$\boxed{K = 1.2251}$$

* Lead compensator T.F $G_c(s) = \frac{1.2251 (s + 1.9364)}{(s + 4.647)}$

* Open loop compensated system: $G_c(s) G(s) = \frac{1.2251 (s + 1.9364)}{(s + 4.647)} \cdot \frac{10}{s(s+1)}$

* closed loop compensated system: $\frac{Y(s)}{R(s)} = \frac{12.251 (s + 1.9364)}{s(s+1)(s+4.647) + 12.251 (s + 1.9364)}$



$$G(s) = \frac{4}{s(s+2)}$$

$$\text{I}_f \quad G_c(s) = 1$$

$$2\zeta\omega_n = 2$$

$$\omega_n^2 = 4$$

$$\boxed{\zeta = 0.5}$$

$$\boxed{\omega_n = 2}$$

$$\frac{Y}{R} = \frac{G(s)}{1 + G(s)} = \frac{\frac{4}{s(s+2)}}{1 + \frac{4}{s(s+2)}}$$

* Specifications of the uncompensated system

$$\frac{Y}{R} = \frac{\frac{4}{s(s+2)}}{\frac{s(s+2)+4}{s(s+2)}} = \frac{4}{s^2 + 2s + 4}$$

* Required specifications of the compensated system

$$\boxed{\omega_n = 4}$$

$$\boxed{\zeta = 0.5}$$

$$s^2 + 2\zeta\omega_n s + \omega_n^2 = 0$$

↑
desired poles can be
computed from this
equation