


Troubleshooting

1. The software cannot be started
 - o Defender SmartScreen prevented an unrecognized app from starting.



Solution steps:

1. Click Properties
 - Right click the installer and click Properties.
2. Click the small box
 - In the open window, find [Unlock] and click [Small Box] in the front
3. Click OK to unlock the small box in front [Check] and click [OK]

- The software cannot be started Please ensure that the NET class library is installed on the computer, and the download address (advance to NET6.0): <https://dotnet.microsoft.com/en-us/download/dotnet/6.0>.

6.0.11

[Release notes](#) Latest release date November 8, 2022

Build apps - SDK

SDK 6.0.403

OS	Installers	Binaries
Linux	Package manager instructions	Arm32 Arm32 Alpine Arm64 Arm64 Alpine x64 x64 Alpine
macOS	Arm64 x64	Arm64 x64
Windows	Arm64 x64 x86 winget instructions	Arm64 x64 x86
All	dotnet-install scripts	

Visual Studio support
Visual Studio 2022 (v17.3)
Visual Studio 2022 for Mac (v17.4)

Run apps - Runtime

ASP.NET Core Runtime 6.0.11

The ASP.NET Core Runtime enables you to run existing web/server applications. **On Windows, we recommend installing the Hosting Bundle, which includes the .NET Runtime and IIS support.**

IIS runtime support (ASP.NET Core Module v2)
16.0.22296.11

OS	Installers	Binaries
Linux	Package manager instructions	Arm32 Arm32 Alpine Arm64 Arm64 Alpine x64 x64 Alpine
macOS		Arm64 x64

2. ECOLink One click Login, If an error is reported, please delete the following file

(Ecolink_SNPSK_tool.dll.msalcache.bin3) and log in again.

Reason: When packaging, the software is still in use. For security reasons, the login information cannot be used anywhere else, so it should not be packaged. Please exit or close the software before packaging.

« 本地磁盘 (C:) > GitHub > ECOLAB.IOT > ECOLAB.IOT.WinFormsApp > bin > Release > net6.0-windows


名称	修改日期	类型	大小
ECOLAB.IOT.Provider.pdb	2022/11/24 16:34	Program Debug Da...	16 KB
ECOLAB.IOT.Service.dll	2022/11/24 16:34	应用程序扩展	15 KB
ECOLAB.IOT.Service.pdb	2022/11/24 16:34	Program Debug Da...	16 KB
ECOLAB.IOT.Transmit.dll	2022/11/24 16:34	应用程序扩展	27 KB
ECOLAB.IOT.Transmit.pdb	2022/11/24 16:34	Program Debug Da...	20 KB
Ecolink_SNPSK_tool.deps.json	2022/11/24 17:51	JSON 源文件	37 KB
Ecolink_SNPSK_tool.dll	2022/11/24 17:51	应用程序扩展	382 KB
Ecolink_SNPSK_tool.dll.msalcache.bin3	2022/11/25 10:35	BIN3 文件	7 KB
Ecolink_SNPSK_tool.exe	2022/11/24 17:51	应用程序	175 KB
Ecolink_SNPSK_tool.pdb	2022/11/24 17:51	Program Debug Da...	41 KB
Ecolink_SNPSK_tool.runtimeconfig.json	2022/11/24 17:51	JSON 源文件	1 KB

3. Write failed, and the XShell tool displays timeout.

- Please check the COM port of the computer link. It may be that the computer COM is not in good contact. Please replace the computer with a good COM. If not, please replace the

computer.

- It is possible that the parameter selection is wrong, and the correct COM port and parameter should be selected in the software.



- If the writing is successful, and the XShell is restarted successfully with the command, but it cannot be found on the website (URL of the test environment <https://ecolinkdmp-d.ecolab.com.cn/#/Device/dtuList>) , please try hard restart directly (power off and restart the board).
4. If the writing is unsuccessful, please carefully check the writing steps. For example, if SN already exists in the board, the original SN number needs to be deleted. Whether it is necessary to restart the device.
 5. How to send the file unsuccessfully? Please check the file size. Currently, the board supports files below 1M.
 6. Write device, associated with software and hardware. If it fails, there may be problems in both aspects.
 - For software, please contact the software designer: xudong.xu@ecolab.com
 - For hardware (Device or Gateway), please contact the relevant designer: jian.zhang3@ecolab.com; ying.zhang@ecolab.com; kai.chen@ecolab.com; yi.xiao@ecolab.com Etc
 - For computer related problems, please contact IT: chinait@ecolab.com
 - For SNAndPSK firing process, please contact: peiguo.yuan@ecolab.com