

 ABBOTT ADD	INDEX INSTRUMENT SERVICE ADVISORY
--	--

PRODUCT: TDx® (09)	DATE: 07-JUL-98
------------------------------	---------------------------

ISA #	SUBJECT	EFFECTIVITY DATE
09-114	TDx® Service Manual	07-JUL-98
09-113	TDx® Patent Label (Catalog Number 3-47642-01)	PENDING
09-112	BARCODE ALIGNMENT FLOWCHART	28-JUN-95
09-111	TDx®/TDxFLx® DT MANUAL	07-FEB-95
09-110	NOVRAM COPIER TOOL	11-JAN-94
09-109	PENDING	PENDING
09-108	MOTOR BOARD DIAGNOSTIC TEST (TEST 5.7)	02-JUL-93
09-107	RS232 PORT AND REV. 15.0	17-AUG-93
09-106	ONEAC LINE CONDITIONER	20-AUG-93
09-105A	FPIA OPTICS DIAGNOSTIC PROCEDURE	26-JAN-93
09-104	RIBBON POST AND CARD CAGE FAN	17-AUG-93
09-103	METAL OPTICS ASSEMBLIES	20-APR-92
09-102	PUMP ASSEMBLY IMPROVEMENTS	CLOSED
09-101	POWER ENTRY ASSEMBLY	03-DEC-91
09-100	PRINTER WIRING CRIMPS	08-NOV-91
09-099	PENDING	PENDING
09-098	NEW FACTORY SET PASSWORD	08-NOV-91
09-097	PROBE HOLDER KIT	13-MAR-92
09-096	TUBING	18-JAN-91
09-095	STEPPER MOTORS	18-JAN-91
09-094	FLUOROMETRIC STANDARDS CAROUSEL	26-NOV-90
09-093	NEW STYLE AIR HEATER FAN AND CABLE	07-SEP-90
09-092	LIGHTWEIGHT SAMPLE CARTRIDGES	22-MAY-90
09-091	MULTICONSTITUENT CONTROLS	22-MAY-90
09-090	NEW THUMBSCREWS / LLS TIPS	CLOSED
09-089A	BOOM / REAGENT PACK FIT	CLOSED
09-088	DIGOXIN NXT SYSTEM LOCKUP	CLOSED
09-087	ERRATIC RESULTS TROUBLESHOOTING	INCORP.

TDx® (09) Index

09-086	PROBE AND ELECTRODE ASSEMBLIES	18-AUG-89
09-085	PUMP ASSEMBLIES	26-MAY-89
09-084	METAL BOOM VS -103 PLASTIC BASEPLATES	01-FEB-89
09-083	DATATRAC - SCREWLOCKS AND STATIC TOUCH PADS	15-DEC-88
09-082	PUMP SET SCREWS	CLOSED
09-081	CAROUSEL HOME SENSOR	14-NOV-88
09-080	DOOR GROUND STRAP UPDATE	14-NOV-88
09-079C	TDx RETURN INSTRUCTIONS	18-AUG-93
09-078	LAMP HOUSING LENSES	INCORP.
09-077	TURBO CAROUSEL PROBLEMS	INCORP.
09-076	NEW STAINLESS STEEL PROBE	CLOSED
09-075	POLYCARBONATE BASE	24-JUL-87
09-074	PHOTO CHECK SPECS	02-JUN-87
09-073	NEW SAMPLE SYRINGE	CLOSED
09-072	IRON SPLASHING	CLOSED
09-071	BUN ELEVATED RESULTS	CLOSED
09-070	TEMPERATURE TIPS	12-SEP-86
09-069	NEW OPTICAL SENSOR	02-SEP-86
09-068	NEW TDx DILUENT SYRINGE	CLOSED
09-067	UNIT DOSE PARAMETERS	INCORP.
09-066	REV 10 REPLACEMENT	CLOSED
09-065	REV 10 & T-UPTAKE ASSAY	CLOSED
09-064	NEW LIQUID HEATER ASSEMBLY	CLOSED
09-063	PLASTIC OPTICS ASSEMBLY	CLOSED
09-062	HIGH VOLTAGE SUPPLY	CLOSED
09-061	CUVETTE BREAKAGE	CLOSED
09-060	NO AIR SPACE PROBLEMS	INCORP.
09-059K	Assays to Activate After FAcTory Set for TDx® and TDxFLx® Analyzers	09-FEB-96
09-058A	TEMP. VERIFICATION	INCORP.
09-057	NOVRAM DESCRIPTIONS/FACTORY SET INFORMATION	INCORP.
09-056	TEMP SPEC FAILURES	CLOSED
09-055	NEW DIG II ASSAY INFORMATION	CLOSED
09-054	LLS PROBLEMS WITH U.D. PROBE	09-DEC-85
09-053	REA IRON/TIBC ASSAY INFORMATION	CLOSED
09-052	U/D CAROUSEL WEIGHT	CLOSED
09-051	BARCODE READER ADJUST	INCORP.
09-050	CURVE FIT MESSAGES	CLOSED
09-049	TDx PROBES	CLOSED
09-048	LIQUID LEVEL SENSING PROBLEMS	CLOSED
09-047	LCD SWITCHING PROBLEMS	CLOSED
09-046	VALVE HELPS	CLOSED
09-045	TEMP. CK.-VERIFICATION	INCORP.
09-044	GENERAL INFORMATION	CLOSED
09-043	BD. 12 MODIFICATION	CLOSED

09-042	UPDATE TO TEMPERATURE CALIBRATION & CK. PROCEDURES	CLOSED
09-041	HOME SENSOR WIRING	06-SEP-84
09-040	REPLACEMENT OF MEMORY CARTRIDGE & CPU BD	CLOSED
09-039	NEW TEMPERATURE PROBE & TEMP. CAL.	CLOSED
09-038A	NEW LAMPS - SYLVANIA	CLOSED
09-037	LIQ XTAL FAIL - BD. #10	INCORP.
09-036	SHORTING OUT OF DISPLAY BD	04-JUN-84
09-035	REV 8.1 PHOTO CAL.	CLOSED
09-034A	NO CAROUSEL PROBLEMS	INCORP.
09-033	EFFECTS OF NON-STANDARD CONSUMABLES/PRACTICES	INCORP.
09-032	METHOTREXATE ERRORS IN RESULTS	CLOSED
09-031	THYROXINE LLS ERRORS	CLOSED
09-030	POOR ASSAY PRECISION AND REPRODUCIBILITY	INCORP.
09-029	LAMP OUT AND LOW INTENSITY	INCORP.
09-028	RANGE TOO LARGE - DIGOXIN	INCORP.
09-027	BARCODE LABELS	CLOSED
09-026	VALVE BLOCKS	CLOSED
09-025	ASSAY CAROUSELS	CLOSED
09-024	PACKING OF ASSEMBLIES	CLOSED
09-023	OPTICS ASSEMBLY	INCORP.
09-022	BOOM ASSEMBLY	CLOSED
09-021	PIPE CHECK SOLUTION	CLOSED
09-020	CORRECTION TO ISA 15	CLOSED
09-019	NEW TUBING	CLOSED
09-018	SOFTWARE UPDATES	CLOSED
09-017	NEW CPU	CLOSED
09-016	SYRINGES	INCORP.
09-015	PROBE OPTIMIZATION	CLOSED
09-014	LAMP OUT ERRORS	INCORP.
09-013	MEMORY BOARD	CLOSED
09-012	PRINTER/PRINTER DRIVER	29-JUL-83
09-011	PUMP ASSEMBLY	CLOSED
09-010	BARCODE READER ERRORS	CLOSED
09-009	NEW POWER ENTRY	CLOSED
09-008	DISPLAY/KEYPAD PROBLEMS	CLOSED
09-007	LOOSE SCREWS ON TRANSISTORS	CLOSED
09-006	REV. F SOFTWARE CHANGES	CLOSED
09-005	MANUAL Z-BOOM HOME CAL.	CLOSED
09-004	ERRORS IN REV. E SOFTWARE	CLOSED
09-003	USE OF FLUOROMETRIC STANDARDS CAROUSEL	CLOSED
09-002	MEMORY BOARD REPLACEMENT	CLOSED
09-001	LIQUID HEATER REPLACEMENT	CLOSED

PENDING -	ISA index number has been reserved for a future ISA.
CANCELLED -	ISA index number is cancelled.
INCORPORATED -	ISA was incorporated into another document or manual.
OBSOLETE -	ISA no longer applies.
COMPLETE -	ISA is complete.

END OF DOCUMENT

 <div>ABBOTT ADD</div>	INSTRUMENT SERVICE ADVISORY
--	------------------------------------

SUBJECT: TDx® Service Manual	ISA#: 09-114
ORIGINATOR: Eric Tormos	PRODUCT: TDx® (09)
APPROVED: Jack B. Hall 7/7/98	EFFECTIVITY DATE: 07-JUL-98

TDx® is a registered trademark of Abbott Laboratories.

I. **DISTRIBUTION:**
Worldwide

II. **PURPOSE:**
This ISA is to notify the field of a revised TDx® Analyzers Total Service Call Procedure. This procedure has been developed from customer site visits made to correct various customer issues. The purpose of this new procedure is to reduce the number of preventive maintenance procedure requirements, while continuing to maintain optimum performance of the instrument.

The Total Service Call Procedure makes sure that the three major subsystems, i.e., temperature, photo and dispense, are checked. Solving an error on one of the subsystems should result in checking the other two as well.

III. **PARTS:**
None.

IV. **PROCEDURE:**
6.1 PM/TOTAL SERVICE CALL PROCEDURE

Suggested PM/Total Service Call Procedures

1. Verify proper TSB level.
2. Obtain printout of System Parameters 1, 2, 3, 6, 7 and 9.
3. Wipe analyzer base and cover with 95% ethanol or methanol.
4. Clean and inspect optics and lamp housing with compressed air.
5. Remove boom assembly.

6. Remove air duct cover, clean dust from heater coils and thermistor with compressed air or vacuum cleaner.
7. Reinstall boom assembly and perform necessary boom verification procedures as per TDx/TDxFLx Service Manual pages 4-9.
8. Prime buffer 5 times and inspect instrument and accessories for leaks in tubing or multivalve block.
9. Run boom calibration (only if it was not yet requested as a verification procedure).
10. Run temperature check (only if it was not yet requested as a verification procedure).
11. Run photo check (only if it was not yet requested as a verification procedure).
12. Run pipe check (only if it was not yet requested as a verification procedure).
13. Run assay of customer's choice with controls.
14. Obtain printout of System Parameters 1, 2, 3, 6, 7, 9, 10 and 11.

6.2 PM/TOTAL SERVICE CALL CHECKLIST

Suggested PM/Total Call Procedures Performed

1.		Verify proper TSB level.
2.		Obtain printout of System Parameters 1, 2, 3, 6, 7 and 9.
3.		Wipe analyzer base and cover with 95% ethanol or methanol.
4.		Clean and inspect optics and lamp housing with compressed air.
5.		Remove boom assembly.
6.		Remove air duct cover, clean dust from heater coils and thermistor with compressed air or vacuum cleaner.
7.		Reinstall boom assembly and perform necessary boom verification procedures as per TDx/TDxFLx Service Manual pages 4-9.
8.		Prime buffer 5 times and inspect instrument and accessories for leaks in tubing or multivalve block.
9.		Run boom calibration (only if it was not yet requested as a verification procedure).
10.		Run temperature check (only if it was not yet requested as a verification procedure).
11.		Run photo check (only if it was not yet requested as a verification procedure).
12.		Run pipe check (only if it was not yet requested as a verification procedure).
13.		Run an assay of the customer's choice with controls.
14.		Obtain printout of System Parameters 1, 2, 3, 6, 7, 9, 10 and 11.

END OF DOCUMENT



ABBOTT
ADD

INSTRUMENT SERVICE ADVISORY

SUBJECT:
Barcode Alignment Flowchart

ISA#:
09-112

ORIGINATOR:
Michael A. Mowen

PRODUCT:
TDx® (09)

APPROVED:
Bob Schabel 28/June/95

EFFECTIVITY DATE:
28-JUN-95


TDx is a registered trademark of Abbott Laboratories.

I. DISTRIBUTION:

International and USA

II. PURPOSE:

To provide the field with a guide to adjust the barcode reader for proper operation, and to save time and repeat calls.



END OF DOCUMENT



ABBOTT
ADD

INSTRUMENT SERVICE ADVISORY

SUBJECT:
TDx®/TDxFLx® DT MANUAL

ISA#:
09-111

ORIGINATOR:
Michael A. Mowen

PRODUCT:
TDx® (09)

APPROVED:
Bob Schabel 02/08/95

EFFECTIVITY DATE:
07-FEB-95

TDx and TDxFLx are registered trademarks of Abbott Laboratories.

I. DISTRIBUTION:

United States: If a new manual is needed, it can be ordered via a FieldWatch message to Field Service Logistics. The cost of the manual will be charged to the district's department number.

International: International locations should forecast requirements for the manual to their responsible logistics organization.

II. PARTS :

To order the complete TDx®/TDxFLx® DT-size manual use the following number:

3-45331-02 Complete manual (binders both volume one and two, tabs, text)

This manual replaces the previously released manual for the TDx®/TDxFLx® System, 3-45331-01.

III. PURPOSE:

The New TDx®/TDxFLx® DT-size Service Manual is now available.

IMPROVEMENTS:

The manual is now in the small binder format and updates the previous manual to include TDxFLx Rev. 2.0/2.1, the digital centrifuge, thermal printer, VDE information, and other new information. Volume One corresponds to the IMx® DT service manual, but with text based troubleshooting only. Volume Two contains the reference material, such as the schematics, theory, RS232 specifications, etc. Feedback from FSE/FSRs, has prompted the binders to have locking rings and Mylar reinforced holes, on all pages.

The following TSBs and ISAs were incorporated into the text as follows:

TSBs

TDx

09-039	TDx REV. 15.1 Software
09-037B	Lamp Socket Assembly
09-035	TDx REV 15.0 Software

TDxFLx

67-011	TDxFLx REV. 2.1 Software
67-009	TDxFLx REV. 2.0 Software
67-008B	Lamp Socket Assembly
67-007	Thermal Printer
67-005	VDE Instrumentation
67-002A	Improved Waste Container Sensor

ISAs

TDx

09-110	NOVRAM Copier Tool
09-108	Motor Board Diagnostic Test (Test 5.7)
09-107	RS232 Port and REV. 15.0
09-106	ONEAC Line Conditioner
09-105A	FPIA Optics Diagnostics Procedure
09-104	Ribbon Post and Card Cage Fan
09-098	New Factory Set Password

TDxFLx

67-020	NOVRAM Copier Tool
67-018	PCB Retainer Brackets
67-016	Wash Station Alignment
67-015	ONEAC Line Conditioner
67-014A	FPIA Optics Diagnostics Procedure
67-013	Thermal Printer Upgrade
67-010	MTBF Counter

67-004 New Factory Set Password

END OF DOCUMENT



ABBOTT
ADD

INSTRUMENT SERVICE ADVISORY

SUBJECT:
MOTOR BOARD DIAGNOSTIC TEST (TEST 5.7)

ISA#:
09-108

ORIGINATOR:
Harry Durstine

PRODUCT:
TDx® (09)

APPROVED:
Bob Schabel 7/2/93 (signature on file)

EFFECTIVITY DATE:
02-JUL-93

TDx is a registered trademark of Abbott Laboratories.

I. PURPOSE:

To inform the field of a potentially false LLS Fail error during the Motor Diagnostic Test (Test 5.7) using ABBOTT TDx® Revision 15.0 software.

II. DESCRIPTION:

During the Motor Diagnostic Test 5.7, a LLS Fail error will occur if Test 5.7 is performed after power up and prior to running as assay. In order to ensure proper functioning of the level sensing portion of Test 5.7, an assay run should be initiated (at least to the point of cuvette count.)

Initially during power up, RGTBOT (System parameter 3.19) and ram location POT3MX are set to zero. When power up is complete, the value of RGTBOT is loaded from NOVRAM. However, ram location POT3MX is not loaded from NOVRAM and remains zero. Ram location POT3MX will be initialized with "RGTBOT" when an assay run is initiated.

END OF DOCUMENT



ABBOTT
ADD

INSTRUMENT SERVICE ADVISORY

SUBJECT:
ONEAC® Line Conditioner available on RZZ for TDx® System

ISA#:
09-106

ORIGINATOR:
Ron Elston/Louis Valich

PRODUCT:
TDx® (09)

APPROVED:
Bob Schabel 8/13/93 (*signature on file*)

EFFECTIVITY DATE:
13-AUG-93

TDx is a registered trademark of Abbott Laboratories.
ONEAC is a registered trademark of ONEAC Corporation, Bannockburn, IL.

This ISA is to inform the FSE in the USA that the ONEAC Line Conditioner can now be ordered by the FSE through Dallas Parts and invoiced to the customer. The following is the list number.

Product Code	List Number	Spec: Amps/Volts	ONEAC Model #
09	4A55-37	4.6A/120V	CP1105
67	4A55-39	6.25A/120V	CP1107

I will also give you information about Uninterruptible Power Supplies. These CAN NOT be ordered through the RZZ system or Dallas Parts. The customer will need to contact the ONEAC Corporation directly. For pricing information or to order call:

312-816-6000

Product Code	List Number	Spec: Amps/Volts	ONEAC Model #
09	N/A	5.0A/120V	ON900
67	N/A	7.5A/120V	ON1300

END OF DOCUMENT

 <div>ABBOTT ADD</div>	INSTRUMENT SERVICE ADVISORY
--	------------------------------------

SUBJECT: Assays to Activate After Factory Set for TDx® and TDxFLx® Analyzers	ISA#: 09-059K
ORIGINATOR: Kyle Hranitzky	PRODUCT: TDx® (09)
APPROVED: Mark Slater 2/9/96	EFFECTIVITY DATE: 09-FEB-96

TDx and TDxFLx are registered trademarks of Abbott Laboratories.

I. **DISTRIBUTION:**
International and USA

II. **PURPOSE:**
This ISA supersedes ISA 09-059J dated 18 April 1994.
The purpose of this ISA is to inform the field of the assays needing activation after performing a Factory Set.
This ISA will be updated on an as needed basis dependent upon when new assay activation letters are released.
If the instrument you are working on has a checksum error, you **MUST** first bypass the checksum error by inputting the password 955251. Once the checksum error is bypassed a Factory Set Test 6.2 **must** be performed. The password for Test 6.2 Factory Set is 247. This ISA supports TDx® software version 15.0 and 15.1 and TDxFLx® software version 2.0 and 2.1.
For activations for older software versions, please contact CSC.
After the Factory Set has passed, the following steps must be performed:

1. Re-enter System 2,3,6,7,8 and 10 parameters and perform Pipe Check Test 2.3 (VP-49).

If these parameters are not available you must perform the following procedures:
TDx and TDxFLx Analyzers

1. CRSL CAL (Test 3.3, VP-32)*
2. a. BOOM CAL (Test 3.2, VP-31)
b. Automated Probe Positioning and Boom Cal (Test 3.10 ,VP-39) TDxFLx only
3. 4-POT BOOM CAL (Test 3.7, VP-35)
4. TEMP CAL (Test 3.1, VP-30) and Verification (VP-30)

- 5. PHOTO CAL (Test 3.4, VP-33)
- 6. PHOTO CHECK (Test 2.2, VP-48)
- 7. PIPE CHECK (Test 2.3, VP-49)

In addition for TDxFLx® Analyzers:

- 8. Reagent Carousel Calibration (Test 3.13, VP-36)
- 9. Reagent Wedge Z-Boom Calibration (VP-38)
- 10. Barcode Reader DAC Setting (VP-37)
- 11. Waste/Wash Station Alignment (VP-24)

NOTE: Tests and VP's can be found in the TDx®/TDxFLx® Service Manual, Catalog No 3-45331-02.

NOTE: If NOVRAMs were replaced, assays specific to that NOVRAM must be recalibrated (reference TDx/TDxFLx Service Manual pp 4-20 and 4-21, Catalog No 3-45331-02).

The following assays have new activation codes due to reagent pool changes or may have parameters that need to be edited following a factory set.

Acetaminophen	FLM II	Phenobarbital
Amikacin	Free Carbamazepine	Phenytoin
Barbiturates II U	Free Phenytoin	Primidone
Benzodiazepines U	Free Phenytoin II	Procainamide
Cannabinoids	Gentamicin	Propoxyphene
Carbamazepine	Lidocaine	Quinidine
Cyclo Meta (WHB)	MEGX	T4
Cyclo Mono (WHB)	Methadone	Theophylline or Theophylline Mono II (LN 8A53)
Cyclo Meta (P/S)	Methotrexate II (LN 7A12)	Tobramycin
Digitoxin	NAPA	Tricyclic Antidepressants
Digoxin II	Opiates	Valproic Acid
Ethosuximide	PCP II	Vancomycin

Assay #	Date	Batch Lot #	RA Lot #	TDx Codes	TDxFLx Codes	MN POL A	MN SPAN
ACET (30)	2/94	85944Q100		SYSTEM 5.1	SYSTEM 5.1	225	110
				52602073326554	52602073326554		
	3/95	03322Q100		SYSTEM 5.1	SYSTEM 5.1	205	80
				62602063326952	62602063326952		
AMIK (3)	6/94	88562Q100	88563Q100	SYSTEM 5.1	SYSTEM 5.1	203	118
				50602160333533	50602160333533		
				SYSTEM 5.2			
				#1 1711150401405			
				#2 5956044303052			
				#3 7573511223527			
	2/95	02334Q100	02342Q100	SYSTEM 5.1	SYSTEM 5.1	200	122
				20602160333503	20602160333503		
				SYSTEM 5.2			
				#1 1911130203607			
				#2 9856064304085			
				#3 4533511264721			

Assay #	Date	Batch Lot #	RA Lot #	TDx Codes	TDxFLx Codes	MN POL A	MN SPAN
BARBS II U (58)	9/94	92663Q100		Edit MN SPAN		150 BKG FAC 1.24	55
BENZ U (63)	9/94	93642Q100		SYSTEM 5.1 48401187217799	SYSTEM 5.1 48401187217799	189 BKG FAC 3.02	122
	2/95	05250Q100		SYSTEM 5.1 13402137267754	SYSTEM 5.1 13402137267754	185 BKG FAC 3.02	108
CANNABS (60)	11/93	85609Q100		SYSTEM 5.1 04401147244009	SYSTEM 5.1 04401147244009	150 BKG FAC 0.73	60
CARB (9)	12/93	84215Q100	84221Q100	SYSTEM 5.1 75403151241551	SYSTEM 5.1 75403151241551	275	140
				SYSTEM 5.2			
				#1 1312131207618			
				#2 0359405519089			
				#3 0552511852822			

Assay #	Date	Batch Lot #	RA Lot #	TDx Codes	TDxFLx Codes	MN POL A	MN SPAN
CYCLO META (WHB) (18) - Refer to Assay Insert							
CYCLO MONO (WHB) (50) - Refer to Assay Insert							
CYCLO META (P/S)(23) - Refer to Assay Insert							

Assay #	Date	Batch Lot #	RA Lot #	TDx Codes	TDxFLx Codes	MN POL A	MN SPAN
DIGITOXIN (27)	9/93	80274Q100		SYSTEM 5.1	SYSTEM 5.1	145	72
				74001083513255	74001083513255		
DIGOXIN II (10)	10/94	94031Q100		SYSTEM 5.1	SYSTEM 5.1	155	75
				31001041512756	31001041512756		
				SYSTEM 5.2 0			
				#1 1511132505510			
				#2 0557025516088			
				#3 6541511550025			
ETHOSUXIMIDE (24)	1/94	85534Q100		SYSTEM 5.1	SYSTEM 5.1	230	110
				42602053360809	42602053360809		

Assay #	Date	Batch Lot #	RA Lot #	TDx Codes	TDxFLx Codes	MN POL A	MN SPAN
FLM II (LN 7A76) (88)							
NEW ASSAY				SYSTEM 5.1	SYSTEM 5.1	300	125
				60403063290009	60403063290009		
SPL VOL =150	HI LIM=160	CAL VOL=150	CONC B=10	CONC C=20	CONC D=40	CONC E=80	
CONC F=160	MODE =23	GAIN=20	MX BKG=8000				
Pipette 250 uL into the sample well							
Low control 22-28 mg/g				High control 85-115 mg/g			
ERR=2	RMSE=1						
FREE CARB (32)							
12/93	84215Q100		SYSTEM 5.1	SYSTEM 5.1	275	120	
			83403144250552	83403144250552			
5/95	03189Q100		32403124240551	32403124240551	275	120	
FREE PHENY (LN 9530) (26)							
5/94	89400Q100		SYSTEM 5.1	SYSTEM 5.1	233	130	
			40402143262839	40402143262839			
12/94	95130Q100		SYSTEM 5.1	SYSTEM 5.1	250	140	
			40403143262801	40403143262801			
FREE PHENY II (LN1B62) (26) NEW ASSAY							
5/95			SYSTEM 5.1	SYSTEM 5.1	265	125	
			00403143262852	00403143262852			
SPL VOL=10	CONC B=0.5	CONC C=1	CONC D=2	CONC E=3	CONC F=4		

Assay #	Date	Batch Lot #	RA Lot #	TDx Codes	TDxFLx Codes	MN POL A	MN SPAN
GENT (1)	6/94	89465Q100	89466Q100	SYSTEM 5.1	SYSTEM 5.1	175	90
				70401140211058	70401140211058		
				SYSTEM 5.2 0			
				#1 1611241205609			
				#2 0403014401087			
#3 0542511141923							
LIDOCAINE (14)	4/94	88586Q100	88587Q100	SYSTEM 5.1	SYSTEM 5.1	225	120
				33402131276059	33402131276059		
				SYSTEM 5.2 0			
				#1 1611252404815			
				#2 5206175422028			
#3 8562511951520							
MEGX (78)	9/92	69771M200		SYSTEM 5.1	SYSTEM 5.1	135	55
				77001161566059	77001161566059		
METHADONE (48)							
Edit BKG FAC to 2.23			Edit CAL REP to 2				

Assay #	Date	Batch Lot #	RA Lot #	TDx Codes	TDxFLx Codes	MN POL A	MN SPAN
METHOTREXATE II (LN 7A12) (22) NEW ASSAY				15.1 Only	2.1 Only		
	10/93			SYSTEM 5.1	SYSTEM 5.1	180	120
				24002442566504	24002442566504		
SPL VOL=10	HI LIM=1000	CONC B=0.05	CONC C=0.15	CONC D=0.30	CONC E=0.60	CONC F=1.00	
MODE 42	GAIN 40	MX BKG 2500					
NAPA (13)							
	6/94	91508Q100	91509Q100	SYSTEM 5.1	SYSTEM 5.2	205	125
				53602121365556	53602121365556		
				#1 1712010102511			
				#2 0859465516085			
				#3 6571511723121			
OPIATES (62)							
	11/92	71678Q100		SYSTEM 5.1	SYSTEM 5.1	170	90
				38401137206407	38401137206407	BKG FAC 1.36	
PCP II (61)							
	4/94	87066Q200		SYSTEM 5.1	SYSTEM 5.1	135	80
				94401127255558	94401127255558	BKG FAC 0.88	

Assay #	Date	Batch Lot #	RA Lot #	TDx Codes	TDxFLx Codes	MN POL A	MN SPAN
PHENOBARB II (05)	5/92	67313Q100	67314Q100	SYSTEM 5.1	SYSTEM 5.1	180	115
				44402090295207	44402090295207		
				SYSTEM 5.2			
				#1 1411241204909			
				#2 0407144418049			
	3/94	87088Q100	87087Q100	#3 9562511641927		180	125
				SYSTEM 5.1	SYSTEM 5.1		
				03402080285206	03402080285206		
				SYSTEM 5.2			
				#1 1411241404901			
PHENYTOIN (LN9507)(4)	5/94	89400Q100	89405Q100	#2 5803175413027		235	135
				#3 1553511212123			
				SYSTEM 5.1	SYSTEM 5.1		
				10402140244857	10402140244857		
				SYSTEM 5.2			
				#1 1012322106019			
				#2 5052235514006			
				#3 9573511042920			

Assay #	Date	Batch Lot #	RA	Lot #	TDx Codes	TDxFLx Codes	MN POL A	MN SPAN
PHENYTOIN (LN 9507) (4) CONTINUED								
	12/94	95130Q100	95131Q100		SYSTEM 5.1 20402140244858 SYSTEM 5.2 0 #1 1712272605902 #2 5053255311039 #3 7522511852222	SYSTEM 5.1 20402140244858	245	145
PHENYTOIN II (LN 1B61) (4)								
	5/95	NEW ASSAY			SYSTEM 5.1 80403140244880 SYSTEM 5.2 0 #1 0000000008211 #2 0000000008062 #3 9500500000120	SYSTEM 5.1	268	168
	SPL VOL=2	CONC B=2.5	CONC C=5		CONC D=10	CONC E=20	CONC F=40	
PRIMIDONE (6)								
	7/93	79423Q100	79415Q100		SYSTEM 5.1 94602150306552 #1 1711211003906 #2 0901245519048 #3 5552511821629	SYSTEM 5.1 94602150306552	225	120

Assay #	Date	Batch Lot #	RA Lot #	TDx Codes	TDxFLx Codes	MN POL A	MN SPAN
PRIMIDONE (6) CONTINUED							
	8/94	91482Q100	91490Q100	SYSTEM 5.1 30602110366558 SYSTEM 5.2 0 #1 1511230208418 #2 0809255519004 #3 7552511641829	SYSTEM 5.1 30602110366558	225	120
PROCAINAMIDE (12)							
	1/94	85475Q100	85476Q100	SYSTEM 5.1 40002071524003 SYSTEM 5.2 0 #1 1711131307915 #2 5854274416042 #3 8551511852522	SYSTEM 5.1 40002071524003	210	115
	6/94	90636Q100	90682Q100	SYSTEM 5.1 41002081534073 #1 9199090902413 #2 6131095418053 #3 3590599190321	SYSTEM 5.1 41002081534073	207	115

Assay #	Date	Batch Lot #	RA	Lot #	TDx Codes	TDxFLx Codes	MN POL A	MN SPAN
PROPOXYPHENE (81)								
	10/91	NEW ASSAY			SYSTEM 5.1 66402112281108	SYSTEM 5.1 66402112281108	200	115
	SPL VOL=3.2 MODE=26	HI LIM=300 GAIN=20	CONC B=150 MX BKG=2500		CONC C=300 BKG FAC=1.44	CONC D=500 CONC E=1000	CONC F=1500	
QUINIDINE (11)								
	1/93	74213Q100	73403Q101		SYSTEM 5.1 36402221273004 SYSTEM 5.2 #1 1511272403411 #2 0503025516032 #3 6531511650126	SYSTEM 5.1 36402221273004	170	85
T4 (79)								
				Edit MN SPAN				100
THEOPHYLLINE II (15)								
	6/93	78596Q100	78598Q100		SYSTEM 5.1 46002151517006 SYSTEM 5.2 #1 2711303803817 #2 0103265529005 #3 6563511081729	SYSTEM 5.1 46002151517006	250	160

Assay #	Date	Batch Lot #	RA	Lot #	TDx Codes	TDxFLx Codes	MN POL A	MN SPAN
THEOPHYLLINE MONOCLONAL II (LN 8A53) (15) NEW ASSAY								
					SYSTEM 5.1	SYSTEM 5.1	240	170
					88002191537507	88002191537507		
					SYSTEM 5.2			
					#1 0000000007221			
					#2 0000000018061			
					#3 9500500000120			
SPL VOL=2	HI LIM=40		CONC B=2.5	CONC C=5	CONC D=10	CONC E=20	CONC F=40	
MODE=17	GAIN=40		MX BKG=1600					
TOBRAMYCIN (02)								
10/92	71007Q100		71008Q100		SYSTEM 5.1	SYSTEM 5.1	175	105
					77602210392456	77602210392456		
					SYSTEM 5.2			
					#1 1111220205702			
					#2 0758064408031			
					#3 1562511542228			
TRICYCLICS ANTIDEPRESSANTS (56)								
8/92	67529Q100				SYSTEM 5.1		180	100
					47002187530001			

Assay #	Date	Batch Lot #	RA Lot #	TDx Codes	TDxFLx Codes	MN POL A	MN SPAN
VALPROIC ACID (8)	2/94	87356Q100	86535Q100	SYSTEM 5.1	SYSTEM 5.1	220	110
				44002091520704	44002091520704		
				SYSTEM 5.2			
				#1 1812180606418			
				#2 0008315515002			
				#3 8552511041824			
VANCOMYCIN (16)	1/94	85096Q100	85097Q100	SYSTEM 5.1	SYSTEM 5.1	215	105
				00402092260357			
				SYSTEM 5.2			
				#1 1411241505127			
				#2 5503045428037			
				#3 4543511831720			

END OF DOCUMENT