

32X TECHNICAL BULLETIN #14

To: Sega and Third Party Developers

From: Developer Technical Support

Date: September 23, 1994

Re: VDP shift bit precaution

In the 32X VDP, the shift bit becomes invalid when the lower byte of the base address set in the line table is \$FF.

Therefore, make sure the lower byte in the table is not \$FF when using shift.