



Cisco FXOS and UCS Manager Software Local Management CLI Command Injection Vulnerability



Advisory ID:	cisco-sa-20200226-fxos-ucs-cli-cmdinj
First Published:	2020 February 26 16:00 GMT
Last Updated:	2020 March 6 16:42 GMT CVE-2020-3171
Version 1.1:	Final
Workarounds:	No workarounds available
Cisco Bug IDs:	CSCvo42634 CSCvo42654 CSCvp44202 More...
CVSS Score:	Base 7.8

[Download CSAF](#) [Download CVRF](#) [Email](#)

Summary

A vulnerability in the local management (local-mgmt) CLI of Cisco FXOS Software and Cisco UCS Manager Software could allow an authenticated, local attacker to execute arbitrary commands on the underlying operating system (OS) of an affected device.

The vulnerability is due to insufficient input validation. An attacker could exploit this vulnerability by including crafted arguments to specific commands. A successful exploit could allow the attacker to execute arbitrary commands on the underlying OS with the privileges of the currently logged-in user for all affected platforms excluding Cisco UCS 6400 Series Fabric Interconnects. On Cisco UCS 6400 Series Fabric Interconnects, the injected commands are executed with *root* privileges.

Cisco Security Vulnerability Policy

To learn about Cisco security vulnerability disclosure policies and publications, see the [Security Vulnerability Policy](#). This document also contains instructions for obtaining fixed software and receiving security vulnerability information from Cisco.

Subscribe to Cisco Security Notifications

Subscribe

Related to This Advisory

Cisco Event Response:
[February 2020 Cisco FXOS and NX-OS Software Security Advisory Bundled Publication](#)

Your Rating:

☐ ☐ ☐ ☐ ☐

Average Rating:

☐ ☐ ☐ ☐ ☐

5 star

Cisco has released software updates that address this vulnerability. There are no workarounds that address this vulnerability.

This advisory is available at the following link:

<https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20200226-fxos-ucs-cli-cmdinj>

This advisory is part of the February 2020 Cisco FXOS and NX-OS Software Security Advisory Bundled Publication, which includes six Cisco Security Advisories that describe six vulnerabilities. For a complete list of the advisories and links to them, see [Cisco Event Response: February 2020 Cisco FXOS and NX-OS Software Security Advisory Bundled Publication](#).

Affected Products

Vulnerable Products

This vulnerability affects the following Cisco products if they are running a vulnerable release of Cisco FXOS Software or Cisco UCS Manager Software:

- Firepower 2100 Series
- Firepower 4100 Series
- Firepower 9300 Security Appliances
- UCS 6200 Series Fabric Interconnects
- UCS 6300 Series Fabric Interconnects
- UCS 6400 Series Fabric Interconnects

For information about which Cisco software releases are vulnerable, see the [Fixed Software](#) section of this advisory.

Products Confirmed Not Vulnerable

Only products listed in the [Vulnerable Products](#) section of this advisory are known to be affected by this vulnerability.

Cisco has confirmed that this vulnerability does not affect the following Cisco products:

- Firepower 1000 Series
- MDS 9000 Series Multilayer Switches
- Nexus 1000 Virtual Edge for VMware vSphere
- Nexus 1000V Switch for Microsoft Hyper-V

4 star



3 star



2 star



1 star



[Leave additional feedback](#)

- Nexus 1000V Switch for VMware vSphere
- Nexus 3000 Series Switches
- Nexus 5500 Platform Switches
- Nexus 5600 Platform Switches
- Nexus 6000 Series Switches
- Nexus 7000 Series Switches
- Nexus 9000 Series Fabric Switches in Application Centric Infrastructure (ACI) mode
- Nexus 9000 Series Switches in standalone NX-OS mode

Workarounds

There are no workarounds that address this vulnerability.

Fixed Software

Cisco has released free software updates that address the vulnerability described in this advisory. Customers may only install and expect support for software versions and feature sets for which they have purchased a license. By installing, downloading, accessing, or otherwise using such software upgrades, customers agree to follow the terms of the Cisco software license:

<https://www.cisco.com/c/en/us/products/end-user-license-agreement.html>

Additionally, customers may only download software for which they have a valid license, procured from Cisco directly, or through a Cisco authorized reseller or partner. In most cases this will be a maintenance upgrade to software that was previously purchased. Free security software updates do not entitle customers to a new software license, additional software feature sets, or major revision upgrades.

When [considering software upgrades](#), customers are advised to regularly consult the advisories for Cisco products, which are available from the [Cisco Security Advisories and Alerts page](#), to determine exposure and a complete upgrade solution.

In all cases, customers should ensure that the devices to be upgraded contain sufficient memory and confirm that current hardware and software configurations will continue to be supported properly by the new release. If the information is not clear, customers are advised to contact the Cisco Technical Assistance Center (TAC) or their contracted maintenance providers.

Customers Without Service Contracts

Customers who purchase directly from Cisco but do not hold a Cisco service contract

and customers who make purchases through third-party vendors but are unsuccessful in obtaining fixed software through their point of sale should obtain upgrades by contacting the Cisco TAC:

<https://www.cisco.com/c/en/us/support/web/tsd-cisco-worldwide-contacts.html>

Customers should have the product serial number available and be prepared to provide the URL of this advisory as evidence of entitlement to a free upgrade.

Cisco FXOS Software

In the following table(s), the left column lists Cisco software releases. The center column indicates whether a release is affected by the vulnerability described in this advisory and the first release that includes the fix for this vulnerability. The right column indicates whether a release is affected by all the vulnerabilities described in this bundle and which release includes fixes for those vulnerabilities.

Firepower 2100 Series appliances use Cisco FXOS Software as an underlying operating system, which is included in Cisco ASA Software unified image bundles or in Cisco FTD Software unified image bundles.

ASA Software for Firepower 2100 Series: [CSCvo42654](#)

Cisco ASA Software Release	First Fixed Release for This Vulnerability	First Fixed Release for All Vulnerabilities Described in the Bundle of Advisories
9.8	9.8.4.3	Migrate to a fixed release.
9.9	9.9.2.47	9.9.2.66
9.10	9.10.1.10	9.10.1.37
9.12	Not vulnerable.	9.12.3.7
9.13	Not vulnerable.	9.13.1.7

FTD Software for Firepower 2100 Series: [CSCvo42654](#)

Cisco FTD Software Release	First Fixed Release for This Vulnerability	First Fixed Release for All Vulnerabilities Described in the Bundle of Advisories
6.2.2	Migrate to a fixed release.	Migrate to a fixed release.
6.2.3	6.2.3.12	6.2.3.16 (Apr 2020)
6.3.0	6.3.0.2	Migrate to a fixed release.
6.4.0	Not vulnerable.	6.4.0.8
6.5.0	Not vulnerable.	6.5.0.2

FXOS Software for Firepower 4100 Series and Firepower 9300 Security Appliances: [CSCvo42634](#)

Cisco FXOS Software Release	First Fixed Release for This Vulnerability	First Fixed Release for All Vulnerabilities Described in the Bundle of Advisories
Earlier than 2.2	Migrate to a fixed release.	Migrate to a fixed release.
2.2	2.2.2.91	Migrate to a fixed release.
2.3	2.3.1.144	2.3.1.179
2.4	2.4.1.234	Migrate to a fixed release.
2.6	Not vulnerable.	2.6.1.187
2.7	Not vulnerable.	2.7.1.106

Cisco UCS Software

In the following table(s), the left column lists Cisco software releases. The center column indicates whether a release is affected by the vulnerability described in this advisory and the first release that includes the fix for this vulnerability. The right column indicates whether a release is affected by all the vulnerabilities described in this bundle and which release includes fixes for those vulnerabilities.

UCS 6200, 6300, and 6400 Series Fabric Interconnects: [CSCvp44202](#) and [CSCvp44232](#)

Cisco UCS Software Release	First Fixed Release for This Vulnerability	First Fixed Release for All Vulnerabilities Described in the Bundle of Advisories
Earlier than 3.2	Migrate to a fixed release.	Migrate to a fixed release.
3.2	3.2(3n)	3.2(3n)
4.0	4.0(4g)	4.0(4g)
4.1	Not vulnerable.	Not vulnerable.

Additional Resources

For help determining the best Cisco NX-OS Software release for a Cisco Nexus Switch, administrators can refer to the following Recommended Releases documents. If a security advisory recommends a later release, Cisco recommends following the advisory guidance.

- [Cisco MDS Series Switches](#)
- [Cisco Nexus 1000V for VMware Switch](#)
- [Cisco Nexus 3000 Series Switches](#)
- [Cisco Nexus 5500 Platform Switches](#)
- [Cisco Nexus 5600 Platform Switches](#)
- [Cisco Nexus 6000 Series Switches](#)
- [Cisco Nexus 7000 Series Switches](#)
- [Cisco Nexus 9000 Series Switches](#)
- [Cisco Nexus 9000 Series ACI-Mode Switches](#)

To determine the best release for Cisco UCS, see the Recommended Releases documents in the release notes for the device.

Exploitation and Public Announcements

The Cisco Product Security Incident Response Team (PSIRT) is not aware of any public announcements or malicious use of the vulnerability that is described in this advisory.

Source

This vulnerability was found during internal security testing.

URL

<https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20200226-fxos-ucs-cli-cmdinj>

Revision History

Version	Description	Section	Status	Date
1.1	Added ASA and FXOS releases.	Fixed Software	Final	2020-March-06
1.0	Initial public release.	-	Final	2020-FEB-26

LEGAL DISCLAIMER

THIS DOCUMENT IS PROVIDED ON AN "AS IS" BASIS AND DOES NOT IMPLY ANY KIND OF GUARANTEE OR WARRANTY, INCLUDING THE WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE. YOUR USE OF THE INFORMATION ON THE DOCUMENT OR MATERIALS LINKED FROM THE DOCUMENT IS AT YOUR OWN RISK. CISCO RESERVES THE RIGHT TO CHANGE OR UPDATE THIS DOCUMENT AT ANY TIME.

A standalone copy or paraphrase of the text of this document that omits the distribution URL is an uncontrolled copy and may lack important information or contain factual errors. The information in this document is intended for end users of Cisco products.