

2] Drive a stepper motor interface to rotate the motor in clockwise by N steps. Introduce suitable delay between successive steps.

```
#include <stdio.h>
```

```
#include <reg51.h>
```

```
char *data port = 0x803;
```

```
char *data porta = 0x800;
```

```
char data acc = 0x30
```

```
delay() // Delay between the rotation of the  
stepper motor
```

```
{ int j;
```

```
for(j=0; j<800; j++)
```

```
{ }
```

```
}
```

```
void main()
```

```
{ port = 0x80; // configure all the ports of  
8255 as output port.
```

```
while(1)
```

```
{
```

```
acc = 0x88;
```

```
porta = acc;
```

```
delay();
```



```

acc = 0x44;
porta = acc;
delay();
acc = 0x22
porta = acc
delay();
acc = 0x11
porta = acc;
delay();
}

```

- Vignesh chandrasekhar
IBM19CS182

[Signature]