

# B-002

## Regarding Procedure to Mill a V-Groove

Vincent W. Finley\*

July 2025

**Abstract:** Cutting a long v-groove in a part is a frequent operation in machining. This article presents a method to mill a v-groove by locating the desired groove center on the work surface.

- The downward distance, +z direction, the milling tool must travel to remove a v-groove in the planar surface.

Given:

- An object with a planar (flat) surface mounted  $\theta = 45^\circ$  to the horizontal.
- *and* a coordinate system drawn from some arbitrary starting location on the object's surface plane, with +x axis to the left, +y axis into the page, and +z axis downward.
- *and* a right triangle with angles  $\theta$ , and sides  $a$ ,  $b$  of length  $L$  and a hypotenuse  $c$ .
- *and* a hypotenuse midpoint that coincides with the coordinate system origin.
- *and* a milling tool with diameter  $D$  whose bottom-left corner is at the coordinate origin.




Figure 1: Initial relationship of work object and milling tool

## 1 Solution

As given, the right triangle shown in Figure 1 has sides  $a = b = L$ . Therefore  $\triangle abc$  is an isosceles triangle.

Furthermore, angles  $\theta$  are

$$\theta = \frac{180^\circ - 90^\circ}{2} = 45^\circ \quad (1)$$

Find:

- The distance to the left, in the +x direction, the milling tool must travel to remove a v-groove in the planar surface.

\*©2025: Bear, DE, USA: CC BY 4.0 license  
<https://creativecommons.org/licenses/by/4.0/legalcode>

This is expected since the mounting angle of the

work relative to the cutting tool was given as  $\theta = 45^\circ$ .

Symmetry of the initial setup can be used to create a symmetrical v-groove in the work.

The diameter  $D$  is relatively unimportant since removal of material from the v-groove is accomplished by the travel of the cutting tool. By gradually plunging the cutting tool downward a distance  $L/2$  along the z-axis, and shifting leftward a distance  $L/2$  along the y-axis, the groove is formed.

Ideally the machinist should use a cutting tool where  $D > L$ , but this is not strictly necessary. This will avoid the need to return past the initial cutting pass.

Choosing  $L \geq D$ , or using a cutting tool with diameter  $D \leq L$ , is possible but will leave missed material before the starting cut. The machinist will need to make extra passes to remove the missed material.

Follow these steps to create a symmetrical v-groove in the work.

### 1.1 Method 1

This method starts cutting on the surface of the v-groove centerline. It is easy to setup. An advantage to this method is the machinist can choose to increase the value of  $L$  while machining, without disturbing the zero position of Digital Readouts or dial indicators.

1. Determine the diameter  $D$  of the cutting tool.
2. Mount the cutting tool in the milling machine.
3. Choose the desired length  $L$  for the depth of side  $a$  and width of side  $b$ .

4. Calculate  $L/2$ , this will determine the travel of the cutting tool.
5. Locate and scribe the place on surface of the work where the v-groove will be centered.
6. Mount the work at a  $\theta = 45^\circ$  angle in a vise in the milling machine, with the scribed line parallel to the y-axis.
7. Position the milling machine table so that the scribed line touches the bottom-left corner of the cutting tool.
8. Zero out any Digital Readouts or dial indicators.
9. Turn on the milling machine, make an initial pass along the y-axis.
10. On subsequent passes, advance the cutter leftward in the x-axis until it has traveled a maximum of  $L/2$  to the left.
11. Advance the depth of cutter downward along the z-axis until it has sunk a maximum of  $L/2$ .

### 1.2 Method 2

This method takes a little longer to setup, but it will be easier to machine. If  $D > L$ , then it will only require the machinist to advance the cut depth along the z-axis until the maximum  $L$  depth (not  $L/2$ ) is reached.

1. Determine the diameter  $D$  of the cutting tool.
2. Mount the cutting tool in the milling machine.
3. Choose the desired length  $L$  for the depth of side  $a$  and width of side  $b$ .

4. Calculate  $L/2$ , this will determine the SETUP travels of the cutting tool.
  5. Locate and scribe the place on surface of the work where the v-groove will be centered.
  6. Mount the work at a  $\theta = 45^\circ$  angle in a vise in the milling machine, with the scribed line parallel to the y-axis.
  7. Position the milling machine table so that the scribed line touches the bottom-left corner of the cutting tool.
  8. Zero out any Digital Readouts or dial indicators.
  9. Now raise the cutting tool a distance  $L/2$  along the z-axis.
  10. Move the cutting tool leftward a distance  $L/2$  along the x-axis.
  11. Again, zero out any Digital Readouts or dial indicators.
  12. Turn on the milling machine, make an initial pass along the y-axis.
  13. On subsequent passes, advance the depth of cutter downward along the z-axis until it has sunk a maximum of  $L$  (not  $L/2$  here)!!!
- Find: Methods to mill out a v-groove where:
- $a = b = L = 0.7 \text{ inches}$
  - One setup method is along desired groove centerline.
  - Another setup method promotes depth-only cutting.
- Basic Steps:
1. Start by labeling Figure 1 with the values of  $D$  and  $L$ .
  2. Calculate the value  $L/2 = 0.70/2 = 0.35 \text{ inches}$  and label the drawing with it, this will be the maximum travel of the cutting tool along the x-axis and z-axis.
  3. Locate and scribe the place on surface of the work where the v-groove will be centered.
  4. Mount the work at a  $\theta = 45^\circ$  angle in a vise in the milling machine, with the scribed line parallel to the y-axis.
  5. Position the milling machine table so that the scribed line touches the bottom-left corner of the cutting tool.
  6. Zero out and Digital Readouts or dial indicators.
- Method #1:
1. Turn on the milling machine, make an initial pass along the y-axis.
  2. On subsequent passes, advance the cutter leftward in the x-axis until it has traveled a maximum of  $L/2 = 0.70/2 = 0.35 \text{ inches}$  to the left.
  3. Advance the depth of cutter downward along the z-axis until it has sunk a maximum of  $L/2 = 0.70/2 = 0.35 \text{ inches}$ .

## 2 Example

Given:

- A piece of flat steel
- Milling cutter whose diameter  $D = 0.75 \text{ inches}$

Method #2:

1. Now raise the cutting tool a distance  $L/2 = 0.70/2 = 0.35 \text{ inches}$  along the z-axis.
2. Move the cutting tool leftward a distance  $L/2 = 0.70/2 = 0.35 \text{ inches}$  along the x-axis.
3. Again, zero out and Digital Readouts or dial indicators.
4. Turn on the milling machine, make an initial pass along the y-axis.
5. On subsequent passes, advance the depth of cutter downward along the z-axis until it has sunk a maximum of  $L = 0.70 \text{ inches}$ , (not  $L/2 = 0.35 \text{ inches}$  here)!!!