

B-002

Regarding Procedure to Mill a V-Groove

Vincent W. Finley*

July 2025

Rev C

Abstract: Cutting a long v-groove in a part is a frequent operation in machining. This article presents a procedure to mill a v-groove by locating the desired groove center on the part work surface.

- *and* a milling cutter tool (endmill) with diameter D whose bottom-left corner is at the coordinate origin.

Find:

1 Problem

Given:

- An object with a planar (flat) surface mounted 45° to the horizontal,
- *and* a right-hand coordinate system drawn from some arbitrary starting location on the object's surface plane, with +x axis to the left, +y axis into the page, and +z axis downward,
- *and* a right triangle with angles θ , and sides a , b of equal length L and a hypotenuse c ,
- *and* a hypotenuse midpoint that coincides with the coordinate system origin,
- *and* a distance d from the origin to the vertex of the right angle $\angle ab$,

- The distance t_x along the x-axis, and t_z along the z-axis, the milling tool must travel to remove a v-groove in the planar surface for some arbitrary value of c .
- The distance t_x along the x-axis, and t_z along the z-axis, the milling tool must travel to remove a v-groove in the planar surface for some arbitrary distance d .

2 Solution

The right triangle shown in Figure 1 has equal sides a and b of some length L

$$a = b = L \quad (1)$$

Since lengths of a and b are equal, $\triangle abc$ is an isosceles triangle. Furthermore, angles θ will be:

$$\theta = \frac{180^\circ - 90^\circ}{2} = 45^\circ \quad (2)$$

*©2025: Bear, DE, USA: CC BY 4.0 license
<https://creativecommons.org/licenses/by/4.0/legalcode>

8 yields:

$$\begin{aligned}
 t_x = t_z &= \frac{L}{2} \\
 t_x = t_z &= \frac{\frac{c}{\sqrt{2}}}{2} \\
 t_x = t_z &= \frac{c}{2\sqrt{2}} \\
 t_x = t_z &= \left(\frac{1}{2\sqrt{2}} \right) c
 \end{aligned}$$

$t_x = t_z = 0.353553 \cdot c$

(10)

Furthermore, substituting L from equation 5 into equation 8 yields:

$$\begin{aligned}
 t_x = t_z &= \frac{L}{2} \\
 t_x = t_z &= \frac{d\sqrt{2}}{2} \\
 t_x = t_z &= \left(\frac{\sqrt{2}}{2} \right) d
 \end{aligned}$$

$t_x = t_z = 0.707107 \cdot d$

(11)

Symmetry of the initial setup can be used to create a symmetrical v-groove in the work by passing the rotating cutter tool along the y-axis.

After each pass, the tool should be stepped slightly leftward until the tool has traveled a distance t_x along the y-axis. Then the tool should be advanced downward after each pass, along the z-axis, until distance t_z has been traveled. Thus the groove is formed.

The machinist should be advised that the diameter D of the cutting tool is relatively unimportant. However if $D \leq 2 \cdot t_x$ then some leftover material may need to be cleaned up before the start point.

3 Procedure

To begin, review Figure 1 and design the v-groove by assigning a length for either $a = b = L$, c or d . This will be the single input variable that will be used to calculate t_x and t_z . You should examine your personal project blueprints to help you choose the input variable and its length.

Input Variable	Use Equation #
$a = b = L$	9
c	10
d	11

Table 1: Input variables and equations

Now do the following:

1. Choose your single input variable and its length.
2. Label Figure 1 with values for D and your selected input variable (remember c spans ENTIRE hypotenuse!)
3. From Table 1 above, find the equation corresponding to the input variable.
4. Substitute the length value of the input variable into the corresponding equation.
5. Use the corresponding equation to calculate t_x and t_z .
6. Record the values of the input variable and calculated values for t_x and t_z onto Figure 1.
7. Locate and scribe the place on surface of the work where the v-groove will be centered.
8. Mount the work at a 45° angle in a vise in the milling machine, with the scribed line parallel to the y-axis.

9. Mount the cutting tool in the milling machine spindle.
10. Position the milling machine table so that the scribed line touches the bottom-left corner of the cutting tool.
11. Zero out any Digital Readouts or dial indicators.
12. Turn on the milling machine, make an initial pass along the y-axis.
13. On subsequent passes, advance the cutter leftward in the x-axis until it has traveled a maximum of t_x to the left.
14. Advance the cutter downward along z-axis until it has sunk a maximum of t_z .
15. If the diameter of the cutter is $D \leq 2 \cdot t_x$, make additional passes to remove missed material before the start point.

4 Example

Given:

- A piece of flat steel bar stock.
- An endmill (cutting tool) whose diameter $D = 0.5 \text{ inches}$

Find: Procedure to mill out a v-groove whose groove “opening” is $c = 0.75 \text{ inches}$.

Basic Steps:

1. The value of $D = 0.5$ and the input variable is $c = 0.75$, label Figure 1 with the values of D and c (remember c spans the ENTIRE hypotenuse!).
2. From Table 1 find the corresponding equation for input variable c (it is equation #10).

3. Input $c = 0.75 \text{ inches}$ into equation #10.

4. Calculate:

$$t_x = t_z = 0.353553 \cdot 0.75 \text{ inches}$$

$$t_x = t_z = 0.2652 \text{ inches}$$

5. Label Figure 1 with:

$$t_x = t_z = 0.2652 \text{ inches}$$

6. Scribe a line on surface of the work where the v-groove will be centered.
7. Mount the work at a 45° angle in a vise, with the scribed line parallel to the y-axis.
8. Position the work so that the scribed line touches the bottom-left corner of endmill.
9. Zero out and Digital Readouts or dial indicators.
10. Turn on the milling machine, make an initial pass along the y-axis.

11. On subsequent passes, advance the cutter leftward along the x-axis until it has traveled a maximum of $t_x = 0.2652 \text{ inches}$ to the left.
12. Advance the depth of cutter downward along the z-axis until it has sunk a maximum of $t_z = 0.2652 \text{ inches}$.
13. Since:

$$D \leq 2 \cdot t_x$$

$$D \leq 2 \cdot 0.2652$$

$$D \leq 0.5304$$

Additional cleanup cuts will be needed to removed missed material before the start point.