




MA3005 Finals CS

Control Theory (Nanyang Technological University)



Scan to open on Studocu

Time function (f(t))	Laplace transform
A unit impulse	1
A unit step	$\frac{1}{s}$
t , a unit ramp	$\frac{1}{s^2}$
e^{-at} , exponential decay	$\frac{1}{s+a}$



using Heaviside theorem

$$G(z) = \frac{S+1}{(S+2)^2(S+3)} = \frac{C_1}{(S+2)^2} + \frac{C_2}{S+2} + \frac{C_3}{S+3}$$

Find C_1 :

$$C_1 = \lim_{S \rightarrow -2} \frac{d}{dS} \left[(S+2)^2 G(z) \right] = \lim_{S \rightarrow -2} \frac{d}{dS} \left[\frac{S+1}{S+3} \right] = \frac{1}{(-2+3)^2} = 1$$

Find C_2 :

$$C_2 = \lim_{S \rightarrow -2} \frac{d}{dS} \left[\frac{S+1}{S+3} \right] = \frac{1}{(-2+3)^2} = 1$$

Find C_3 :

$$C_3 = \lim_{S \rightarrow -3} (S+3) G(z) = \lim_{S \rightarrow -3} \frac{S+1}{(S+2)^2} = \frac{-2}{1} = -2$$

moving a branch point before a block

moving a branch point behind a block

moving a summation point before a block

moving a summation point behind a block

4.1.5 Gear Trains

N = number of teeth
 r = radius of gear

$T_1 \theta_1 = T_2 \theta_2$
 $\frac{T_1}{T_2} = \frac{\theta_2}{\theta_1} = \frac{N_2}{N_1} = \frac{\omega_2}{\omega_1} = \frac{r_1}{r_2} = \frac{1}{n}$

(1) No of teeth & radii
 (2) distance
 (3) work done

SHUNT MOTOR

Speed regulation: $\frac{N_s - N}{N_s}$

Shunt Motor: $T = k \phi I_a$

Starting current: $I_a = \frac{V_T - E_b}{R_a}$

SERIES MOTOR

Speed regulation: $\frac{N_s - N}{N_s}$

Series Motor: $T = k \phi I_a$

Starting current: $I_a = \frac{V_T - E_b}{R_a}$

COMPOUND MOTOR

Speed regulation: $\frac{N_s - N}{N_s}$

Compound Motor: $T = k \phi I_a$

Starting current: $I_a = \frac{V_T - E_b}{R_a}$

Permanent Magnet DC Motor

Voltage equation: $V = R_a I_a + K_e \omega$ (1)
 Armature current: $I_a = \frac{V - K_e \omega}{R_a}$ (2)
 Torque: $T = K_t I_a = \frac{K_t}{R_a} (V - K_e \omega)$ (3)

Equivalent circuit of a DC motor

From Eq (3)

Starting torque: $T_s = \frac{K_t V}{R_a}$ (4)
 No load speed: $\omega_0 = \frac{V}{K_e}$ (5)
 K_t = torque constant (1 Nm A⁻¹)
 K_e = back emf constant (1 Vs rad⁻¹)

Using the above units

$K_t = K_e = K$ (motor constant)
 (1.41 & 0.707 in SI units)

The given motor has the speed-torque characteristics shown in Fig. R-2 ohms

(a) If $V_s = 5V$, calculate the motor no-load speed.
 (b) Calculate the speed of the motor for $V_s = 5V$ and $I_a = 7A$.
 (c) What must the input V_s be to restore the motor speed calculated in part (a) assuming that the 7A no-load is applied?

(a) At no-load speed, $I_a = 0$, $V_s = 5V$
 $\omega_0 = 1000 \text{ rpm}$
 $K_e = \frac{V_s}{\omega_0} = \frac{5}{1000} = 0.005 \text{ Vs/rad}$
 (b) From Eq (3), $T = K_t I_a = 7 \times 1000/4 = 1750 \text{ rpm}$
 (c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$

Starting torque: $T_s = K_t V_s / R_a$ (4)

From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$

(c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$

From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$

(c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$


From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$

(c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$

From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$

(c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$

From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$



From Eq (3)

Starting torque: $T_s = \frac{K_t V_s}{R_a}$ (4)
 No load speed: $\omega_0 = \frac{V_s}{K_e}$ (5)
 K_t = torque constant (1 Nm A⁻¹)
 K_e = back emf constant (1 Vs rad⁻¹)

Using the above units

$K_t = K_e = K$ (motor constant)
 (1.41 & 0.707 in SI units)

The given motor has the speed-torque characteristics shown in Fig. R-2 ohms

(a) If $V_s = 5V$, calculate the motor no-load speed.
 (b) Calculate the speed of the motor for $V_s = 5V$ and $I_a = 7A$.
 (c) What must the input V_s be to restore the motor speed calculated in part (a) assuming that the 7A no-load is applied?

(a) At no-load speed, $I_a = 0$, $V_s = 5V$
 $\omega_0 = 1000 \text{ rpm}$
 $K_e = \frac{V_s}{\omega_0} = \frac{5}{1000} = 0.005 \text{ Vs/rad}$
 (b) From Eq (3), $T = K_t I_a = 7 \times 1000/4 = 1750 \text{ rpm}$
 (c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$

Starting torque: $T_s = K_t V_s / R_a$ (4)

From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$

(c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$

From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$

(c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$

From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$

(c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$

From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$

(c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$

From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$

(c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$

From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$

(c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$

From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$

(c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$

From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$

(c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$

From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$

(c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$


From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$

(c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$

From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$

(c) Using (3) and (4), $7 = \frac{K_t}{R_a} (V_s - K_e \omega_0)$
 $7 = \frac{10 \times 1000}{4} (V_s - 0.005 \times 1000)$
 $V_s = 6.4V$

From Eq (4) $T_s / V_s = K_t / R_a = 20/4 = 5$
 Using Eq (3) $T = 5 \times 5 \times (20/1000) = 1250 \text{ rpm}$
 $V_s = 6.4V$



Assume armature inductance, L_a is small compared to armature resistance R_a

$\frac{\theta_m(s)}{E_a(s)} = \frac{K_t / R_a}{s [s + \frac{1}{J_m} (b_m + \frac{K_t K_e}{R_a})]}$

Armature loop: $E_a(s) = R_a I_a(s) + L_a s I_a(s) + E_b(s)$
 $E_b(s) = K_e s \theta(s)$

Counter emf voltage \propto shaft speed
 $E_b = K_e \dot{\theta}$

Torque Eqn: $T = J \ddot{\theta} + b \dot{\theta}$, $T = J s^2 \theta(s) + b s \theta(s)$

Armature loop: $E_a(s) = R_a I_a(s) + L_a s I_a(s) + E_b(s)$, $E_b(s) = K_e s \theta(s)$

constant I_a source: $T_m = K_t I_a$, $T_m = K_t I_a$

Find the transfer function of an armature-controlled DC motor and load.

Given the system and torque-speed curve, find the transfer function $\theta(s) / E_a(s)$



Total inertia at the armature of the motor is: $J_m = J_a + J_L = \frac{N_1^2}{N_2^2} J_L = 5 + 700 (\frac{1}{10})^2 = 12$

Total damping at the armature of the motor is: $b_m = b_a + b_L (\frac{N_1}{N_2})^2 = 2 + 800 (\frac{1}{10})^2 = 10$

From torque speed curve: $T_{stall} = 500$, $\omega_{no-load} = 50$, $e_a = 100$

Hence the electrical constants: $\frac{K_t}{R_a} = \frac{T_{stall}}{e_a} = \frac{500}{100} = 5$, $K_e = \frac{e_a}{\omega_{no-load}} = \frac{100}{50} = 2$

$\frac{\theta_m(s)}{E_a(s)} = \frac{\frac{K_t}{R_a}}{s [s + \frac{1}{J_m} (b_m + \frac{K_t K_e}{R_a})]}$

Since $N_1/N_2 = \theta(s) / \theta_m(s) = 1/10$, $\frac{\theta(s)}{E_a(s)} = \frac{0.417}{s(s + 1.667)}$

Important equations for first order system

Unit step questions:

2% settling time = time that the system needs to be within 2% of the steady state = $4T$

5% settling time = $3T$

Steady state value: Using final value theorem:
 $\lim_{t \rightarrow \infty} c(t) = \lim_{s \rightarrow 0} s \frac{1}{s} \frac{K}{Ts + 1} = \frac{K}{1} = K$

$\lim_{t \rightarrow \infty} c(t) = K$
 $c(t) = K$

[DC gain]

Underdamped Systems $\zeta < 1$

Step Response ($\rho = k = 1$)

Steady-state value

Steady-state value

Steady-state value

Steady-state value

Steady-state value

Eliminating I_a , E_m , T

$\frac{\theta}{E_a} = \frac{1/K_e}{s (T_m s^2 + (T_m + \gamma T_m) s + \gamma)}$

where $T_m = J_m / (K_e K_t)$ - motor time constant
 $T_a = L_a / R_a$ - armature time constant
 $\gamma = B R_a / K_e K_t$ - damping factor

Assume armature inductance, L_a is small compared to armature resistance R_a

$\frac{\theta_m(s)}{E_a(s)} = \frac{K_t / R_a}{s [s + \frac{1}{J_m} (b_m + \frac{K_t K_e}{R_a})]}$

Armature loop: $E_a(s) = R_a I_a(s) + L_a s I_a(s) + E_b(s)$
 $E_b(s) = K_e s \theta(s)$

Counter emf voltage \propto shaft speed
 $E_b = K_e \dot{\theta}$


Torque Eqn: $T = J \ddot{\theta} + b \dot{\theta}$, $T = J s^2 \theta(s) + b s \theta(s)$

Armature loop: $E_a(s) = R_a I_a(s) + L_a s I_a(s) + E_b(s)$, $E_b(s) = K_e s \theta(s)$

constant I_a source: $T_m = K_t I_a$, $T_m = K_t I_a$

Find the transfer function of an armature-controlled DC motor and load.

Given the system and torque-speed curve, find the transfer function $\theta(s) / E_a(s)$



Total inertia at the armature of the motor is: $J_m = J_a + J_L = \frac{N_1^2}{N_2^2} J_L = 5 + 700 (\frac{1}{10})^2 = 12$

Total damping at the armature of the motor is: $b_m = b_a + b_L (\frac{N_1}{N_2})^2 = 2 + 800 (\frac{1}{10})^2 = 10$

From torque speed curve: $T_{stall} = 500$, $\omega_{no-load} = 50$, $e_a = 100$

Hence the electrical constants: $\frac{K_t}{R_a} = \frac{T_{stall}}{e_a} = \frac{500}{100} = 5$, $K_e = \frac{e_a}{\omega_{no-load}} = \frac{100}{50} = 2$

$\frac{\theta_m(s)}{E_a(s)} = \frac{\frac{K_t}{R_a}}{s [s + \frac{1}{J_m} (b_m + \frac{K_t K_e}{R_a})]}$

Since $N_1/N_2 = \theta(s) / \theta_m(s) = 1/10$, $\frac{\theta(s)}{E_a(s)} = \frac{0.417}{s(s + 1.667)}$

Important equations for first order system

Unit step questions:

2% settling time = time that the system needs to be within 2% of the steady state = $4T$

5% settling time = $3T$

Steady state value: Using final value theorem:
 $\lim_{t \rightarrow \infty} c(t) = \lim_{s \rightarrow 0} s \frac{1}{s} \frac{K}{Ts + 1} = \frac{K}{1} = K$

$\lim_{t \rightarrow \infty} c(t) = K$
 $c(t) = K$

[DC gain]

Underdamped Systems $\zeta < 1$

Step Response ($\rho = k = 1$)

Steady-state value

Steady-state value

Steady-state value

Step input C_s

$k_p = \lim_{s \rightarrow 0} G(s) = G(s=0)$

$G(s) \rightarrow OLTf$

Ramp input E_{ss}

$k_v = \lim_{s \rightarrow 0} sG(s)$

Unit parabolic E_{ss}

$k_a = \lim_{s \rightarrow 0} s^2 G(s)$

E_{ss} are related to k_p, k_v, k_a

Increasing system type requires an integrator in the forward path but this will have destabilizing effect

Designing a stable system with more than two integrators in the forward path is generally difficult

PD controller PI controller

Good Neutral Bad

Increase speed + stability Eliminate E_{ss}

Controllers	K_p	$K_D s$	$\frac{K_I}{s}$
Proportional	Stability	Stability	Stability
Derivative	Steady-state error (E_{ss})	Steady-state error (E_{ss})	Steady-state error (E_{ss})
Integral	Speed	Speed	Speed
	Disturbance rejection	Disturbance rejection	Disturbance rejection
	Noise rejection	Noise rejection	Noise rejection

Block diagram: $R(s) \rightarrow \text{Summing junction} \rightarrow K_p + K_D s \rightarrow \frac{1}{s^2 + 2s + 2} \rightarrow C(s)$

Desired poles: $s = -2 \pm j\sqrt{3}$

Desired Transient Response: 10% overshoot, 2% settling time of 0.5 s

Determine the DESIRED closed-loop poles

Criterion 1: 10% OS $e^{-\frac{\pi \zeta}{\sqrt{1-\zeta^2}}} = 0.1$

Criterion 2: 2% settling time $\frac{4}{\zeta \omega_n} = 0.5$

$\zeta = 0.59, \omega_n = 13.5$

CL poles define transient response

Root Locus Summary

- Starting and ending points of the locus
 - Starting points - open-loop POLES
 - Ending points - open-loop ZEROS
- Asymptotes (infinite open-loop ZEROS)
 - Angles $\theta = \frac{360^\circ (q-p)}{n-m}$
 - Location $\sigma = \frac{\sum p_i - \sum z_i}{n-m}$
- Locus on real axis
- Break-in and break-out points
 - Break-in (minimum K) (Zero)
 - Break-out (maximum K) (pole)
- Departure and arrival angles (poles) (zeros)
- Imaginary axis intersection

OL Poles $[|c=0]$

OL Zeros $[|c=\infty]$

$\sigma_a = \frac{\sum_{i=1}^n (-p_i) - \sum_{j=1}^m (-z_j)}{n-m}$

$\angle s = \frac{\pi(1+2q)}{n-m}$

Let $\frac{dK}{ds} = 0$ Intersection of imaginary axis: $s = j\omega$ into CLTF CE

$\sum_{i=1}^n \angle(s + z_i) - \sum_{j=1}^m \angle(s + p_j) = \pm \pi$

PD controller

$k_D s + k_p = k_D (s + \frac{k_p}{k_D}) = G_c$

k_p & z_c change CL poles

Noise Amplification: $\lim_{\omega \rightarrow \infty} |G_c(s=j\omega)|$

Alternative Controller: $\lim_{\omega \rightarrow \infty} |k_D(j\omega + z_c)| \rightarrow \infty$

Lead compensator

PI controller

$k_p + \frac{k_i}{s} = k_p \frac{(s + \frac{k_i}{k_p})}{s}$

PI controller eliminates steady-state error

- Steps for PD controller:
- Step 1: Find Desired CL-poles
 - Step 2: CLTF CE in terms of k_p & k_D
 - Step 3: sub poles into CE
 - Step 4: solve Re & Im parts of CE to obtain k_p & k_D

Lead compensator

$G_c = k \frac{(s + z_c)}{(s + p_c)}$

Note Amplification: $\lim_{\omega \rightarrow \infty} |G_c(s=j\omega)| = k$

Finite Amplification \rightarrow Btr than PD controller

Designing slow PD first then slow for lead from PD

steps: 1) $k_D s + k_p = 14(s + 13.5) = k_D(s + z_c)$

2) $z_c < z_c' \rightarrow z_c = 10$

lead compensator $= k \frac{(s + z_c)}{(s + p_c)}$

3) use CE to determine k & p_c

sub desired poles into CE

PI controller cannot be realized with passive components

Alternative: Lag compensator Controller

$G_c = k \frac{(s + z_c)}{(s + p_c)}$ pole / zero cancellation

$p_c < z_c < 1$

$k_p = \lim_{s \rightarrow 0} G_c G = \lim_{s \rightarrow 0} k \frac{(s + z_c)}{(s + p_c)} G(s)$

$\uparrow k_p$ factor $= k \frac{z_c}{p_c} G(0)$

$\downarrow E_{ss} = \frac{1}{1 + k_p}$

Error reduces but not fully eliminated

PID controllers

$G_c = k_D (s + z_c) \frac{(s + z_i)}{s}$

PD PI

Lead-lag compensators



$G_c = \frac{k_1(s + z_1)}{(s + p_1)} \cdot \frac{k_2(s + z_2)}{(s + p_2)}$

lead compensator $z_1 < p_1$

lag compensator $z_2 < p_2 < 1$

Harmonic Input Input: $r = r_0 \cos(\omega t)$

$C_{ss} = (r_0 |G(s=j\omega)|) \cos[\omega t + \angle G(s=j\omega)]$



Gain & Phase Margins

Gain Margin (Stable G_{OL})

Phase Margin (Stable G_{OL})

1. Occurs at the frequency when $\angle G = -\pi$ rad (ω_{gm})

2. Gain Margin (GM) $= 0 - |G(s = j\omega_{gm})|_{dB}$

Stability

Unity feedback is stable if and only if:

$\gamma > 0$ & $GM > 0$

Closed-loop ζ_{cl} $\gamma \uparrow$ implies that $\zeta_{cl} \uparrow$

Bandwidth The frequency when $|G| = -3$ dB. We denote it as ω_{BW}

In general, higher bandwidth of the OL system \rightarrow higher natural frequency of closed loop system (affects location of CL poles)

Closed-loop $\omega_{n,cl}$ Closed-loop Poles

$\omega_{BW} \uparrow$ implies that $\omega_{n,cl} \uparrow$

$s_{1,2} = -\zeta_{cl} \omega_{n,cl} \pm j\omega_{n,cl} \sqrt{1 - \zeta_{cl}^2}$

