

**B&R Revision Information**

**Version ARSG4\_4.00.22\_V4.00 Automation Runtime SG4 Upgrade (V4.00)**

**06-Sep-2011**

## Contents

<b>B&amp;R Revision Information (06.09.2011)Version ARSG4_4.00.22_V4.00 Automation Runtime SG4 Upgrade (V4.00)</b>	<b>1</b>
Contents	1
Requests and problems by product and version	1
1A4000.02 (2.0 Automation Runtime SG4)	1
1A4300.02 (1.0 Automation Studio 3.x)	6
Requests and problems by product/component	6
1A4000.02 (2.0 Automation Runtime SG4)	6
AR - ARemb	6
AR - ARsim	6
AR - ARwin	6
AR - General SG4	7
AR - PP45	9
Diagnose - Debugger	9
Diagnose - Logger	9
Diagnose - SDM	10
Diagnose - Tracer	10
IO System - 2003 Backplane	10
IO System - CANIQ	10
IO System - CANopen	11
IO System - General	11
IO System - ModbusTCP	12
IO System - netX	12
IO System - Powerlink	12
IO System - Profibus	14
IO System - X2X	14
Library - AsARClg	14
Library - AsARLog	15
Library - AsCANopen	15
Library - AsEPL	16
Library - AsIMA	16
Library - AsIODiag	16
Library - AsL2DP	17
Library - AsMem	17
Library - AsNxCoM	17
Library - AsUSB	17
Library - AsXML	17
Library - CAN lib	17
Library - FileIQ	18
Library - LoopConR	18
Library - SYS lib	18
System - ANSL	18
System - Firmware	19
System - Firmware	19
System - FTP Server	19
System - OPC	19
System - WebServer	20
1A4300.02 (1.0 Automation Studio 3.x)	20
Build - Transfer To Target	21

## B&R Revision Information (06.09.2011)

### Version ARSG4\_4.00.22\_V4.00 Automation Runtime SG4 Upgrade (V4.00)

The current revision information can be downloaded from the B&R Homepage download area (<http://www.br-automation.com/download>).

#### Contents

- [Requests and problems by product/version](#)
- [Requests and problems by product/component](#)

#### Requests and problems by product and version

##### 1A4000.02 (2.0 Automation Runtime SG4)

ID	valuation	solved since	known since	Description
<a href="#">400007523</a>	Problem	-	V3.0.71.16 SP01	AsIMA ignores time zone information
<a href="#">400007523</a>	Problem	-	V3.0.71.16 SP01	AsIMA ignores time zone information
<a href="#">400066089</a>	Problem	-	V2.7.0.4102 [V2.94]	30479, 27306 when starting 7CP570.60-1 with four AF modules
<a href="#">400066089</a>	Problem	-	V2.7.0.4102 [V2.94]	30479, 27306 when starting 7CP570.60-1 with four AF modules
<a href="#">400055446</a>	Problem	-	V2.7.0.0015 SP08	Address error occurs when a breakpoint is reached on a command that is 1 byte long
<a href="#">400055446</a>	Problem	-	V2.7.0.0015 SP08	Address error occurs when a breakpoint is reached on a command that is 1 byte long
<a href="#">400055446</a>	Problem	-	V2.7.0.0015 SP08	Address error occurs when a breakpoint is reached on a command that is 1 byte long
<a href="#">400055836</a>	New function	-	-	PP45 could fail at low temperatures
<a href="#">400067831</a>	Problem	-	-	Memory management problem with task overload corrected with library version V2.80.1 and up
<a href="#">400037284</a>	New function	-	-	Improved response time for PP065 touch screen
<a href="#">400059335</a>	Problem	-	-	Correction of the error in which very short and light pressure on the touch screen can cause the position to be evaluated incorrectly
<a href="#">268630</a>	Problem	-	ARSG4_4.00.17_Q04.00	ARwin on Windows 7 doesn't work in Shared mode (when using more than 2GB DRAM)
<a href="#">268405</a>	Problem	-	ARSG4_4.00.16_P04.00	Problems with ARwin in Windows 7 when firewall is on
<a href="#">238445</a>	Problem	-	ARSG4_3.08.1_A03.08	StaleData on local X2X Link interface when X2X cycle > system cycle
<a href="#">400069705</a>	Problem	-	ARSG4_3.07.5_E03.07	Backup of remanent data to SRAM doesn't complete if ARwin is operated in Shared mode.
<a href="#">400069705</a>	Problem	-	ARSG4_3.07.5_E03.07	Backup of remanent data to SRAM doesn't complete if ARwin is operated in Shared mode.
<a href="#">400065938</a>	Problem	-	ARSG4_3.07.4_D03.07	c command line argument in the ARwin configuration disables not only the COM2 interface but also COM1.
<a href="#">400066308</a>	Problem	-	ARSG4_3.06.22_V03.06	Error copying CAN CMS objects
<a href="#">400066308</a>	Problem	-	ARSG4_3.06.22_V03.06	Error copying CAN CMS objects
<a href="#">400055674</a>	Problem	-	ARSG4_3.06.22_V03.06	Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem
<a href="#">400046190</a> <a href="#">400041900</a>	Problem	-	ARSG4_3.06.22_V03.06	Upgrade to AR Version E3.01 can cause the CPU to continuously reboot
<a href="#">400072106</a>	Problem	-	ARSG4_3.06.22_V03.06	Accessing the "Safety" and "Fieldbus" logbooks via library (with an index) causes a PageFault. The problem can be avoided by specifying the names "\$safety" or "\$fieldbus."
<a href="#">400072106</a>	Problem	-	ARSG4_3.06.22_V03.06	Accessing the "Safety" and "Fieldbus" logbooks via library (with an index) causes a PageFault. The problem can be avoided by specifying the names "\$safety" or "\$fieldbus."
<a href="#">400072106</a>	Problem	-	ARSG4_3.06.22_V03.06	Accessing the "Safety" and "Fieldbus" logbooks via library (with an index) causes a PageFault. The problem can be avoided by specifying the names "\$safety" or "\$fieldbus."
<a href="#">400054833</a>	Problem	-	ARSG4_3.06.22_V03.06	PP065: Warning "26061 Cannot configure minimum reduced cycle time due to old firmware" because of different drivers or POWERLINK firmware
<a href="#">400048657</a>	Problem	-	ARSG4_3.06.22_V03.06	PP045 with IF24 (L2DP) returns incorrect data when odd addresses are read in the Profibus image
<a href="#">400054833</a>	Problem	-	ARSG4_3.06.22_V03.06	PP065: Warning "26061 Cannot configure minimum reduced cycle time due to old firmware" because of different drivers or POWERLINK firmware
<a href="#">400054111</a>	Problem	-	ARSG4_3.01.9_I03.01	Debugger terminates online connection
<a href="#">400054111</a>	Problem	-	ARSG4_3.01.9_I03.01	Debugger terminates online connection
<a href="#">400054111</a>	Problem	-	ARSG4_3.01.9_I03.01	Debugger terminates online connection
<a href="#">400039843</a>	Problem	-	ARSG4_3.01.1_A03.01	Under certain circumstances (INAaction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC
<a href="#">400039843</a>	Problem	-	ARSG4_3.01.1_A03.01	Under certain circumstances (INAaction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC
<a href="#">400039843</a>	Problem	-	ARSG4_3.01.1_A03.01	Under certain circumstances (INAaction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC
<a href="#">400035792</a> <a href="#">400020837</a>	Problem	-	ARSG4_3.00.22_V03.00	Under certain circumstances (INAaction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 /

				SGC
<a href="#">400035792</a> <a href="#">400020837</a>	Problem	-	ARSG4_3.00.22_V03.00	Under certain circumstances (INAaction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC
<a href="#">400035792</a> <a href="#">400020837</a>	Problem	-	ARSG4_3.00.22_V03.00	Under certain circumstances (INAaction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC
<a href="#">400005281</a>	Problem	-	ARSG4_2.94.22_V02.94	INA online connection to X20CS1020 stops working when the modem configuration is also activated
<a href="#">400048512</a>	New function	ARSG4_4.00.9_I04.00	V3.00.80.31 SP01	It is not possible to use C variables larger than 16 MB.
<a href="#">251322</a>	Problem	ARSG4_4.00.9_I04.00	ARSG4_3.06.22_V03.06	POWERLINK: ACOPOSmulti with SafeMC as chained station
<a href="#">400055971</a>	Problem	ARSG4_4.00.9_I04.00	ARSG4_3.06.22_V03.06	ARemb terminates INA connection if an attempt is made to access a non-existing partition via FTP
<a href="#">400054674</a>	Problem	ARSG4_4.00.9_I04.00	ARSG4_3.00.22_V03.00	Module transfer to target not saved if there is not sufficient memory in the back-up partition.
<a href="#">400060887</a>	New function	ARSG4_4.00.8_H04.00	V3.00.81.22 SP01	CANopen slave not started by the master if it sends only an emergency telegram with data =0 instead of a Boot-Up message
<a href="#">400055699</a>	Problem	ARSG4_4.00.8_H04.00	V3.00.81.22 SP01	VC Windows Terminal: Changes to Enum variables are not updated on the terminal, but changes from the terminal are updated on the CPU
<a href="#">400053004</a> <a href="#">400052525</a>	Problem	ARSG4_4.00.8_H04.00	V3.00.81.18	Trigger condition not working
<a href="#">400039937</a>	Problem	ARSG4_4.00.8_H04.00	V3.00.80.25	CANIO slaves are not always found after startup
<a href="#">400050977</a>	Problem	ARSG4_4.00.8_H04.00	-	AsIMA doesn't adjust for daylight savings time when reading the time from a peer station
<a href="#">400055614</a>	Problem	ARSG4_4.00.8_H04.00	PVI3.00.00.3119	"VT_DATE local" wrong for DCOM routines - in leap years the date is offset by one day
<a href="#">400060899</a>	Problem	ARSG4_4.00.8_H04.00	ARSG4_3.07.4_D03.07	Due to an error in the task queue of the Modbus driver, packages that are received may no longer be allocated to the sent queries, thereby causing a connection timeout.
<a href="#">400055610</a>	Problem	ARSG4_4.00.8_H04.00	ARSG4_3.07.1_A03.07	DT and DATE_AND_TIME variables are converted incorrectly by VT_DATE when they are written.
<a href="#">400057308</a>	Problem	ARSG4_4.00.8_H04.00	ARSG4_3.01.9_I03.01	Target crashes with page fault in the web server module when an ASP write command is run from a website with more than 9 variables.
<a href="#">400057456</a>	Problem	ARSG4_4.00.8_H04.00	ARSG4_3.01.7_G03.01	Update to ARwin configurator
<a href="#">400053444</a>	Problem	ARSG4_4.00.8_H04.00	ARSG4_3.00.22_V03.00	Variable values sometimes displayed incorrectly on ASP pages
<a href="#">400002467</a> <a href="#">400058853</a> <a href="#">400058855</a>	New function	ARSG4_4.00.7_G04.00	V3.00.81.23 SP02	Task class stack can only be configured up to a size of 1MB.
<a href="#">400058109</a>	Problem	ARSG4_4.00.7_G04.00	V3.00.81.22 SP01	It can take very long to install I/O mappings, which can result in the connection being terminated due to a time violation.
<a href="#">400051942</a>	Problem	ARSG4_4.00.7_G04.00	-	ModbusTCP doesn't start all slaves
<a href="#">400060652</a>	Problem	ARSG4_4.00.7_G04.00	ARSG4_3.07.3_C03.07	CANrwtab() returns invalid data
<a href="#">400057809</a>	Problem	ARSG4_4.00.7_G04.00	ARSG4_3.01.8_H03.01	Using logger functions in fast task classes can lead to cycle time violations
<a href="#">400056892</a>	Problem	ARSG4_4.00.6_F04.00	V3.00.81.22 SP01	If the requested bur_heap_size (C++) is too large, the installation error ERR_LOADER_USERHEAP (5150) is now triggered
<a href="#">400007099</a> <a href="#">400044198</a>	Problem	ARSG4_4.00.6_F04.00	V2.7.0.0010 SP03	AsMemPartFree returned -8 byte free memory size
<a href="#">400011003</a>	Problem	ARSG4_4.00.6_F04.00	ARSG4_4.00.3_C04.00	TIM_usec returns incorrect time when the system tick isn't a whole number multiple or factor of 10 milliseconds
<a href="#">245157</a>	New function	ARSG4_4.00.6_F04.00	ARSG4_3.08.3_C03.08	The value specified for AsMemPartCreate now corresponds to the largest allocated block
<a href="#">400056515</a>	Problem	ARSG4_4.00.6_F04.00	ARSG4_3.07.2_B03.07	Watchdog after CanWrite() on IF060 with IF621
<a href="#">400057340</a>	Problem	ARSG4_4.00.6_F04.00	ARSG4_3.07.2_B03.07	POWERLINK reports error 27306 when starting a visualization application
<a href="#">400051015</a>	Problem	ARSG4_4.00.6_F04.00	ARSG4_3.07.1_A03.07	Support for barcode scanner Cino F788-G
<a href="#">400054123</a> <a href="#">400055855</a>	Problem	ARSG4_4.00.6_F04.00	ARSG4_3.06.22_V03.06	When downloading in one cycle mode, an interrupt block can cause an I/O cycle time violation (27306)
<a href="#">400059082</a>	Problem	ARSG4_4.00.6_F04.00	ARSG4_3.06.22_V03.06	Creating a new logger module using AsArLogCreate() deletes any existing tasks with the same name
<a href="#">400047724</a>	Problem	ARSG4_4.00.6_F04.00	ARSG4_3.01.9_I03.01	When multiple Ethernet interfaces are used, interference in the routing table causes Error 29004 when the function block CfgSetDefaultGateway() is called
<a href="#">400053732</a>	Problem	ARSG4_4.00.5_E04.00	V3.00.81.18	Priority of Profibus master can be configured
<a href="#">400055674</a>	Problem	ARSG4_4.00.5_E04.00	ARSG4_3.06.22_V03.06	Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem
<a href="#">400056272</a>	Problem	ARSG4_4.00.5_E04.00	ARSG4_3.06.22_V03.06	Priority of CANopen master can be configured
<a href="#">400046190</a> <a href="#">400041900</a>	Problem	ARSG4_4.00.4_D04.00	ARSG4_3.06.22_V03.06	Upgrade to AR Version E3.01 can cause the CPU to continuously reboot
<a href="#">400054457</a>	Problem	ARSG4_4.00.4_D04.00	ARSG4_3.06.22_V03.06	CANopenSDOWriteData() terminates after downloading several hundred bytes due to a full CAN buffer
<a href="#">400054911</a>	Problem	ARSG4_4.00.4_D04.00	ARSG4_3.06.22_V03.06	Function blocks from AsXML library ignore enable input
<a href="#">400055214</a>	Problem	ARSG4_4.00.4_D04.00	ARSG4_3.01.8_H03.01	Using CANopenNMT() can prevent a task download from completing
<a href="#">400054360</a>	Problem	ARSG4_4.00.3_C04.00	V3.00.81.20 SP01	With the function block CanOpenGetState(), when enable=FALSE the function block freezes during execution
<a href="#">400048657</a>	Problem	ARSG4_4.00.3_C04.00	ARSG4_3.06.22_V03.06	PP045 with IF24 (L2DP) returns incorrect data when odd addresses are read in the Profibus image
<a href="#">400055463</a>	Problem	ARSG4_4.00.3_C04.00	ARSG4_3.01.9_I03.01	CANopenSDOWrite8() only sends every second SDO
<a href="#">253632</a>	New function	ARSG4_4.00.16_P04.00	nicht relevant	Detection of POWERLINK hardware using AS-IO-Diag
<a href="#">400068763</a>	Problem	ARSG4_4.00.16_P04.00	ARSG4_3.08.11_K03.08	Naming of POWERLINK devices from other vendors in AsIODiag

<a href="#">400060016</a>	Problem	ARSG4_4.00.16_P04.00	ARSG4_3.07.2_B03.07	Error 26051 in logbook when X20CS2770 after X20BCx083 on APC or Power Panel
<a href="#">400065938</a>	Problem	ARSG4_4.00.15_O04.00	ARSG4_3.07.4_D03.07	c command line argument in the ARwin configuration disables not only the COM2 interface but also COM1.
<a href="#">400069009</a>	Problem	ARSG4_4.00.15_O04.00	ARSG4_3.07.4_D03.07	VC application blocks netX data communication
<a href="#">400069276</a>	Problem	ARSG4_4.00.14_N04.00	ARSG4_3.08.10_J03.08	Using a handle that has already been closed can cause a page fault (read, write, or close on a handle)
<a href="#">400065540</a>	Problem	ARSG4_4.00.12_L04.00	V3.00.81.24 SP0x	ARwin shows incorrect amount of available DRAM memory in SDM
<a href="#">400057456</a>	Problem	ARSG4_4.00.12_L04.00	ARSG4_3.01.7_G03.01	Update to ARwin configurator
<a href="#">400048318</a>	New function	ARSG4_4.00.11_K04.00	V3.00.80.31 SP01	New function blocks FileWriteEx() and FileTruncate()
<a href="#">400052213</a>	Problem	ARSG4_4.00.11_K04.00	V3.00.80.31 SP01	ENUM data types in ASP functions
<a href="#">400035047</a> <a href="#">400036404</a>	Problem	ARSG4_4.00.11_K04.00	ARSG4_3.08.25_Y03.08	If a breakpoint is reached in the INIT SP, then it is no longer possible to leave the breakpoint. Execute (F5), Step Over (F10) or Step Into (F11) do not have an affect.
<a href="#">258192</a>	Problem	ARSG4_4.00.11_K04.00	ARSG4_3.07.2_B03.07	Firmware Update for SafeMC did not complete.
<a href="#">400066313</a>	Problem	ARSG4_4.00.11_K04.00	ARSG4_3.06.22_V03.06	If, for example, the X2X timer is used as the system clock, then remanent variables aren't saved when there is a power failure
<a href="#">400030702</a>	New function	ARSG4_4.00.11_K04.00	ARSG4_2.95.22_V02.95	New function block L2DPGetNode() for reading Profibus station number
<a href="#">400030702</a>	New function	ARSG4_4.00.11_K04.00	ARSG4_2.95.22_V02.95	New function block L2DPGetNode() for reading Profibus station number
<a href="#">400038864</a>	New function	ARSG4_4.00.10_J04.00	V3.00.80.25	Function blocks now return the error 20709 (fiERR_FILE_DEVICE) if a device is not present
<a href="#">400064601</a>	Problem	ARSG4_4.00.10_J04.00	ARSG4_3.08.8_H03.08	Insufficient logbook entry when ArConfig has double channels/QLinks.
<a href="#">400062576</a>	Problem	ARSG4_4.00.10_J04.00	ARSG4_3.07.4_D03.07	Error handling SYSCONF module in SYSROM
<a href="#">400062449</a>	Problem	ARSG4_4.00.10_J04.00	ARSG4_3.07.4_D03.07	When using multiple netX CANopen master modules, a different handle is used for each module, which speeds up asynchronous function block processing.
<a href="#">400064575</a>	Problem	ARSG4_4.00.10_J04.00	ARSG4_3.07.3_C03.07	Attempt to download AsCANopen library to ARsim rejected with error 9650 "Library function not available"
<a href="#">400062877</a>	Problem	ARSG4_4.00.10_J04.00	ARSG4_3.06.22_V03.06	Remanent/permanent variables not saved when exiting ARsim
<a href="#">400063458</a>	New function	ARSG4_4.00.10_J04.00	ARSG4_3.06.22_V03.06	DevLink() blocks other file actions for a relatively long time
<a href="#">400038864</a>	New function	ARSG4_3.08.9_I03.08	V3.00.80.25	Function blocks now return the error 20709 (fiERR_FILE_DEVICE) if a device is not present
<a href="#">400013287</a>	New function	ARSG4_3.08.9_I03.08	V3.0.71.20 SP02	Use the Diagnostics System Manager to list modules' diagnostics data points
<a href="#">400062877</a>	Problem	ARSG4_3.08.9_I03.08	ARSG4_3.06.22_V03.06	Remanent/permanent variables not saved when exiting ARsim
<a href="#">400054674</a>	Problem	ARSG4_3.08.9_I03.08	ARSG4_3.00.22_V03.00	Module transfer to target not saved if there is not sufficient memory in the back-up partition.
<a href="#">400028352</a>	Problem	ARSG4_3.08.9_I03.08	ARSG4_3.00.15_O03.00	If global variables mapped to I/O points receive new addresses due to a change to the project, it is possible that the variable values are no longer transferred to the I/O points.
<a href="#">400028352</a> <a href="#">400065604</a>	Problem	ARSG4_3.08.9_I03.08	ARSG4_3.00.15_O03.00	If global variables mapped to I/O points receive new addresses due to a change to the project, it is possible that the variable values are no longer transferred to the I/O points.
<a href="#">400060157</a>	Problem	ARSG4_3.08.9_I03.08	ARSG4_2.96.12_L02.96	The status BUSY can remain set for up to 120 minutes if the connection is lost when using the function block DirInfo() over a network
<a href="#">400060887</a>	Problem	ARSG4_3.08.8_H03.08	V3.00.81.22 SP01	CANopen slave not started by the master if it sends only an emergency telegram with data =0 instead of a Boot-Up message
<a href="#">400053004</a> <a href="#">400052525</a>	Problem	ARSG4_3.08.8_H03.08	V3.00.81.18	Trigger condition not working
<a href="#">400039937</a>	Problem	ARSG4_3.08.8_H03.08	V3.00.80.25	CANIO slaves are not always found after startup
<a href="#">400055836</a>	New function	ARSG4_3.08.8_H03.08	-	PP45 could fail at low temperatures
<a href="#">400050977</a>	Problem	ARSG4_3.08.8_H03.08	-	AsIMA doesn't adjust for daylight savings time when reading the time from a peer station
<a href="#">400055614</a>	Problem	ARSG4_3.08.8_H03.08	PVI3.00.00.3119	"VT_DATE local" wrong for DCOM routines - in leap years the date is offset by one day
<a href="#">400058774</a>	Problem	ARSG4_3.08.8_H03.08	ARSG4_3.08.4_D03.08	Incorrect version of rtosdrv.dll
<a href="#">400060899</a>	Problem	ARSG4_3.08.8_H03.08	ARSG4_3.07.4_D03.07	Due to an error in the task queue of the Modbus driver, packages that are received may no longer be allocated to the sent queries, thereby causing a connection timeout.
<a href="#">400055610</a>	Problem	ARSG4_3.08.8_H03.08	ARSG4_3.07.1_A03.07	DT and DATE_AND_TIME variables are converted incorrectly by VT_DATE when they are written.
<a href="#">400053444</a>	Problem	ARSG4_3.08.8_H03.08	ARSG4_3.00.22_V03.00	Variable values sometimes displayed incorrectly on ASP pages
<a href="#">400053444</a>	Problem	ARSG4_3.08.8_H03.08	ARSG4_3.00.22_V03.00	Variable values sometimes displayed incorrectly on ASP pages
<a href="#">400057308</a>	Problem	ARSG4_3.08.8_H03.08	-	Target crashes with page fault in the web server module when an ASP write command is run from a website with more than 9 variables.
<a href="#">400002467</a> <a href="#">400058853</a> <a href="#">400058855</a>	New function	ARSG4_3.08.7_G03.08	V3.00.81.23 SP02	Task class stack can only be configured up to a size of 1MB.
<a href="#">400058109</a>	Problem	ARSG4_3.08.7_G03.08	V3.00.81.22 SP01	It can take very long to install I/O mappings, which can result in the connection being terminated due to a time violation.
<a href="#">400058774</a>	Problem	ARSG4_3.08.7_G03.08	ARSG4_3.08.4_D03.08	Incorrect version of rtosdrv.dll
<a href="#">400060652</a>	Problem	ARSG4_3.08.7_G03.08	ARSG4_3.07.3_C03.07	CANrwtab() returns invalid data
<a href="#">400056892</a>	Problem	ARSG4_3.08.6_F03.08	V3.00.81.22 SP01	If the requested bur_heap_size (C++) is too large, the installation error ERR_LOADER_USERHEAP (5150) is now triggered
<a href="#">400047408</a> <a href="#">400049937</a>	Problem	ARSG4_3.08.6_F03.08	V3.00.81.12	Error 29009 occurs when reading the default gateway
<a href="#">400007099</a> <a href="#">400044198</a>	Problem	ARSG4_3.08.6_F03.08	V2.7.0.0010 SP03	AsMemPartFree returned -8 byte free memory size
<a href="#">400051942</a>	Problem	ARSG4_3.08.6_F03.08	-	ModbusTCP doesn't start all slaves
<a href="#">400058774</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.08.4_D03.08	Incorrect version of rtosdrv.dll

<a href="#">400011003</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.08.4_D03.08	TIM_usec returns incorrect time when the system tick isn't a whole number multiple or factor of 10 milliseconds
<a href="#">400056515</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.07.2_B03.07	Watchdog after CanWrite() on IF060 with IF621
<a href="#">400057340</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.07.2_B03.07	POWERLINK reports error 27306 when starting a visualization application
<a href="#">400057746</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.06.4_D03.06	Calling the function block CfgSetEthConfigMode() with the same mode that is already in use triggers Error 29003
<a href="#">400054123</a> <a href="#">400055855</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.06.22_V03.06	When downloading in one cycle mode, an interrupt block can cause an I/O cycle time violation (27306)
<a href="#">400046190</a> <a href="#">400041900</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.06.22_V03.06	Upgrade to AR Version E3.01 can cause the CPU to continuously reboot
<a href="#">400059082</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.06.22_V03.06	Creating a new logger module using AsArLogCreate() deletes any existing tasks with the same name
<a href="#">400047724</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.01.9_I03.01	When multiple Ethernet interfaces are used, interference in the routing table causes Error 29004 when the function block CfgSetDefaultGateway() is called
<a href="#">400057809</a>	Problem	ARSG4_3.08.6_F03.08	-	Using logger functions in fast task classes can lead to cycle time violations
<a href="#">400053732</a>	Problem	ARSG4_3.08.5_E03.08	V3.00.81.18	Priority of Profibus master can be configured
<a href="#">400053957</a>	Problem	ARSG4_3.08.5_E03.08	-	Time calculation incorrect for logger entries in SDM
<a href="#">400056381</a>	Problem	ARSG4_3.08.5_E03.08	ARSG4_3.06.22_V03.06	Priority of CANopen master can be configured
<a href="#">400049979</a>	Problem	ARSG4_3.08.5_E03.08	ARSG4_3.01.7_G03.01	SDM - Update problems with dynamic page content
<a href="#">400062152</a>	Problem	ARSG4_3.08.4_D03.08	V3.00.81.24 SP0x	Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem
<a href="#">400051015</a>	Problem	ARSG4_3.08.4_D03.08	ARSG4_3.07.1_A03.07	Support for Cino F788-G barcode scanner
<a href="#">400055674</a>	Problem	ARSG4_3.08.4_D03.08	ARSG4_3.06.22_V03.06	Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem
<a href="#">400054457</a>	Problem	ARSG4_3.08.4_D03.08	ARSG4_3.06.22_V03.06	CANopenSDOWriteData() terminates after downloading several hundred bytes due to a full CAN buffer
<a href="#">400054833</a>	Problem	ARSG4_3.08.4_D03.08	ARSG4_3.06.22_V03.06	PP065: Warning "26061 Cannot configure minimum reduced cycle time due to old firmware" because of different drivers or POWERLINK firmware
<a href="#">400055463</a>	Problem	ARSG4_3.08.4_D03.08	ARSG4_3.01.9_I03.01	CANopenSDOWrite8() only sends every second SDO
<a href="#">400055214</a>	Problem	ARSG4_3.08.4_D03.08	ARSG4_3.01.8_H03.01	Using CANopenNMT() can prevent a task download from completing
<a href="#">400054360</a>	Problem	ARSG4_3.08.3_C03.08	V3.00.81.20 SP01	With the function block CanOpenGetState(), when enable=FALSE the function block freezes during execution
<a href="#">400037524</a>	Problem	ARSG4_3.08.3_C03.08	V3.00.80.25	Error "9098 - System I/O cross-link task cycle time violation" is generated when a a SafePLC and standard PLC are linked and a breakpoint is set on the standard PLC.
<a href="#">400054911</a>	Problem	ARSG4_3.08.3_C03.08	ARSG4_3.06.22_V03.06	Function blocks from AsXML library ignore enable input
<a href="#">237362</a>	New function	ARSG4_3.08.2_B03.08	-	Logbook entry for firmware update now contains old and new version
<a href="#">400040758</a>	New function	ARSG4_3.08.2_B03.08	-	Old and new firmware version entered in logbook
<a href="#">400051743</a>	Problem	ARSG4_3.08.2_B03.08	ARSG4_3.06.22_V03.06	If no destination directory is specified for DirCopy(), copying to ARsim doesn't work.
<a href="#">257265</a>	New function	ARSG4_3.08.16_P03.08	nicht relevant	Detection of POWERLINK hardware using AS-IO-Diag
<a href="#">400065938</a>	Problem	ARSG4_3.08.15_O03.08	ARSG4_3.07.4_D03.07	c command line argument in the ARwin configuration disables not only the COM2 interface but also COM1.
<a href="#">400069009</a>	Problem	ARSG4_3.08.15_O03.08	ARSG4_3.07.4_D03.07	VC application blocks netX data communication
<a href="#">400068763</a>	Problem	ARSG4_3.08.14_N03.08	ARSG4_3.08.11_K03.08	Naming of POWERLINK devices from other vendors in AsIODiag
<a href="#">400069276</a>	Problem	ARSG4_3.08.14_N03.08	ARSG4_3.08.10_J03.08	Using a handle that has already been closed can cause a page fault (read, write, or close on a handle)
<a href="#">400061758</a>	Problem	ARSG4_3.08.14_N03.08	ARSG4_3.06.22_V03.06	ACOPOS synchronization problem 6002 in cascading POWERLINK networks when POWERLINK cycle time > 2ms
<a href="#">400055409</a>	Problem	ARSG4_3.08.14_N03.08	ARSG4_3.01.9_I03.01	EplSDORead() stays in the status "Busy" after the enable FB is set to FALSE
<a href="#">400065540</a>	Problem	ARSG4_3.08.12_L03.08	V3.00.81.24 SP0x	ARwin shows incorrect amount of available DRAM memory in SDM
<a href="#">400068762</a>	New function	ARSG4_3.08.12_L03.08	nicht relevant	Read ACOPOS device type using AsIODiag function block
<a href="#">400060016</a>	Problem	ARSG4_3.08.12_L03.08	ARSG4_3.07.2_B03.07	Error 26051 in logbook when X20CS2770 after X20BCx083 on APC or Power Panel
<a href="#">400055409</a>	Problem	ARSG4_3.08.12_L03.08	ARSG4_3.01.9_I03.01	EplSDORead() stays in the status "Busy" after the enable FB is set to FALSE
<a href="#">400048318</a>	New function	ARSG4_3.08.11_K03.08	V3.00.80.31 SP01	New function blocks FileWriteEx() and FileTruncate()
<a href="#">400052213</a>	Problem	ARSG4_3.08.11_K03.08	V3.00.80.31 SP01	ENUM data types in ASP functions
<a href="#">400066313</a>	Problem	ARSG4_3.08.11_K03.08	ARSG4_3.06.22_V03.06	If, for example, the X2X timer is used as the system clock, then remanent variables aren't saved when there is a power failure
<a href="#">400057308</a>	Problem	ARSG4_3.08.11_K03.08	ARSG4_3.01.9_I03.01	Target crashes with page fault in the web server module when an ASP write command is run from a website with more than 9 variables.
<a href="#">400059335</a>	Problem	ARSG4_3.08.10_J03.08	-	Correction of the error in which very short and light pressure on the touch screen can cause the position to be evaluated incorrectly
<a href="#">400037284</a>	New function	ARSG4_3.08.10_J03.08	-	Improved response time for PP065 touch screen
<a href="#">400064601</a>	Problem	ARSG4_3.08.10_J03.08	ARSG4_3.08.8_H03.08	Insufficient logbook entry when ArConfig has double channels/QLinks.
<a href="#">400062576</a>	Problem	ARSG4_3.08.10_J03.08	ARSG4_3.07.4_D03.07	Error handling SYSCONF module in SYSROM
<a href="#">400062449</a>	Problem	ARSG4_3.08.10_J03.08	ARSG4_3.07.4_D03.07	When using multiple netX CANopen master modules, a different handle is used for each module, which speeds up asynchronous function block processing.
<a href="#">400064575</a>	Problem	ARSG4_3.08.10_J03.08	ARSG4_3.07.3_C03.07	Attempt to download AsCANopen library to ARsim rejected with error 9650 "Library function not available"
<a href="#">400063458</a>	New function	ARSG4_3.08.10_J03.08	ARSG4_3.06.22_V03.06	DevLink() blocks other file actions for a relatively long time
<a href="#">257375</a>	Problem	ARSG4_3.08.10_J03.08	ARSG4_3.01.11_K03.01	PP065 in combination with a 4PP065.IF23-1 no longer booting due to a faulty flash access after a firmware update
<a href="#">400069276</a>	Problem	ARSG4_3.07.9_I03.07	ARSG4_3.08.10_J03.08	Using a handle that has already been closed can cause a page fault (read, write, or close on a handle)
<a href="#">40009063</a> <a href="#">400065339</a>	New function	ARSG4_3.07.8_H03.07	V3.0.71.16 SP01	Find unconfigured POWERLINK stations with AsIODiag
<a href="#">400066313</a>	Problem	ARSG4_3.07.8_H03.07	ARSG4_3.06.22_V03.06	



				If, for example, the X2X timer is used as the system clock, then remanent variables aren't saved when there is a power failure
<a href="#">400057456</a>	Problem	ARSG4_3.07.8_H03.07	ARSG4_3.01.7_G03.01	Update to ARwin configurator
<a href="#">400065562</a>	Problem	ARSG4_3.07.7_G03.07	ARSG4_3.07.6_F03.07	SDM 1 (Automation Studio 3.0.80) doesn't work with Firefox 4.0 and higher
<a href="#">400062576</a>	Problem	ARSG4_3.07.7_G03.07	ARSG4_3.07.4_D03.07	Error handling SYSCONF module in SYSROM
<a href="#">400062449</a>	Problem	ARSG4_3.07.7_G03.07	ARSG4_3.07.4_D03.07	When using multiple netX CANopen master modules, a different handle is used for each module, which speeds up asynchronous function block processing.
<a href="#">400065361</a>	Problem	ARSG4_3.07.7_G03.07	ARSG4_3.07.3_C03.07	IF1063-1 doesn't work on the BC1083
<a href="#">400064575</a>	Problem	ARSG4_3.07.7_G03.07	ARSG4_3.07.3_C03.07	Attempt to download AsCANopen library to ARsim rejected with error 9650 "Library function not available"
<a href="#">400065239</a>	Problem	ARSG4_3.07.7_G03.07	ARSG4_3.07.2_B03.07	Firmware Update for SafeMC did not complete.
<a href="#">400060887</a>	Problem	ARSG4_3.07.6_F03.07	V3.00.81.22 SP01	CANopen slave not started by the master if it sends only an emergency telegram with data =0 instead of a Boot-Up message
<a href="#">400058109</a>	Problem	ARSG4_3.07.6_F03.07	V3.00.81.22 SP01	It can take very long to install I/O mappings, which can result in the connection being terminated due to a time violation.
<a href="#">400053447</a>	Problem	ARSG4_3.07.6_F03.07	V3.00.81.20 SP01	In some circumstances, the watchdog may be triggered during debugging because a required system resource (Mutex) is not available
<a href="#">400053004</a> <a href="#">400052525</a>	Problem	ARSG4_3.07.6_F03.07	V3.00.81.18	Trigger condition not working
<a href="#">400039937</a>	Problem	ARSG4_3.07.6_F03.07	V3.00.80.25	CANIO slaves are not always found after startup
<a href="#">400055836</a>	New function	ARSG4_3.07.6_F03.07	-	PP45 could fail at low temperatures
<a href="#">400059335</a>	Problem	ARSG4_3.07.6_F03.07	-	Correction of the error in which very short and light pressure on the touch screen can cause the position to be evaluated incorrectly
<a href="#">400060899</a>	Problem	ARSG4_3.07.6_F03.07	ARSG4_3.07.4_D03.07	Due to an error in the task queue of the Modbus driver, packages that are received may no longer be allocated to the sent queries, thereby causing a connection timeout.
<a href="#">257430</a>	Problem	ARSG4_3.07.6_F03.07	ARSG4_3.01.11_K03.01	PP065 in combination with a 4PP065.IF23-1 no longer booting due to a faulty flash access after a firmware update
<a href="#">400060157</a>	Problem	ARSG4_3.07.6_F03.07	ARSG4_2.96.12_L02.96	The status BUSY can remain set for up to 120 minutes if the connection is lost when using the function block DirInfo() over a network
<a href="#">- 400047408</a> <a href="#">400049937</a>	Problem	ARSG4_3.07.5_E03.07	V3.00.81.12	Error 29009 occurs when reading the default gateway
<a href="#">- 400047408</a> <a href="#">400049937</a>	Problem	ARSG4_3.07.5_E03.07	V3.00.81.12	Error 29009 occurs when reading the default gateway
<a href="#">400051942</a>	Problem	ARSG4_3.07.5_E03.07	-	ModbusTCP doesn't start all slaves
<a href="#">400060652</a>	Problem	ARSG4_3.07.5_E03.07	ARSG4_3.07.3_C03.07	CANrwtab() returns invalid data
<a href="#">400057746</a>	Problem	ARSG4_3.07.5_E03.07	ARSG4_3.06.4_D03.06	Calling the function block CfgSetEthConfigMode() with the same mode that is already in use triggers Error 29003
<a href="#">400057746</a>	Problem	ARSG4_3.07.5_E03.07	ARSG4_3.06.4_D03.06	Calling the function block CfgSetEthConfigMode() with the same mode that is already in use triggers Error 29003
<a href="#">251317</a>	Problem	ARSG4_3.07.5_E03.07	ARSG4_3.06.22_V03.06	POWERLINK: ACOPOSmulti with SafeMC as chained station
<a href="#">400060965</a>	Problem	ARSG4_3.07.5_E03.07	ARSG4_3.06.22_V03.06	POWERLINK: ACOPOSmulti with SafeMC as chained station
<a href="#">400047724</a>	Problem	ARSG4_3.07.5_E03.07	ARSG4_3.01.9_I03.01	When multiple Ethernet interfaces are used, interference in the routing table causes Error 29004 when the function block CfgSetDefaultGateway() is called
<a href="#">400057308</a>	Problem	ARSG4_3.07.5_E03.07	ARSG4_3.01.9_I03.01	Target crashes with page fault in the web server module when an ASP write command is run from a website with more than 9 variables.
<a href="#">400048959</a>	Problem	ARSG4_3.07.5_E03.07	ARSG4_2.96.10_J02.96	ModbusTCP master doesn't work on AC141
<a href="#">400053732</a>	Problem	ARSG4_3.07.4_D03.07	V3.00.81.18	Priority of Profibus master can be configured
<a href="#">400056515</a>	Problem	ARSG4_3.07.4_D03.07	ARSG4_3.07.2_B03.07	Watchdog after CanWrite() on IF060 with IF621
<a href="#">400057340</a>	Problem	ARSG4_3.07.4_D03.07	ARSG4_3.07.2_B03.07	POWERLINK reports error 27306 when starting a visualization application
<a href="#">400057827</a>	Problem	ARSG4_3.07.4_D03.07	ARSG4_3.07.1_A03.07	Maximum number of device handles exceeded with approx. 400 safety modules
<a href="#">400053957</a>	Problem	ARSG4_3.07.4_D03.07	ARSG4_3.06.22_V03.06	Time calculation incorrect for logger entries in SDM
<a href="#">400056381</a>	Problem	ARSG4_3.07.4_D03.07	ARSG4_3.06.22_V03.06	Priority of CANopen master can be configured
<a href="#">400055214</a>	Problem	ARSG4_3.07.4_D03.07	ARSG4_3.01.8_H03.01	Using CANopenNMT() can prevent a task download from completing
<a href="#">400049979</a>	Problem	ARSG4_3.07.4_D03.07	ARSG4_3.01.7_G03.01	SDM - Update problems with dynamic page content
<a href="#">400051015</a>	Problem	ARSG4_3.07.3_C03.07	ARSG4_3.07.1_A03.07	Support for Cino F788-G barcode scanner
<a href="#">400054123</a> <a href="#">400055855</a>	Problem	ARSG4_3.07.3_C03.07	ARSG4_3.06.22_V03.06	When downloading in one cycle mode, an interrupt block can cause an I/O cycle time violation (27306)
<a href="#">400055674</a>	Problem	ARSG4_3.07.3_C03.07	ARSG4_3.06.22_V03.06	Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem
<a href="#">400054457</a>	Problem	ARSG4_3.07.3_C03.07	ARSG4_3.06.22_V03.06	CANopenSDOWriteData() terminates after downloading several hundred bytes due to a full CAN buffer
<a href="#">400055463</a>	Problem	ARSG4_3.07.3_C03.07	ARSG4_3.01.9_I03.01	CANopenSDOWrite8() only sends every second SDO
<a href="#">400053444</a>	Problem	ARSG4_3.07.3_C03.07	ARSG4_3.00.22_V03.00	Variable values sometimes displayed incorrectly on ASP pages
<a href="#">400054360</a>	Problem	ARSG4_3.07.2_B03.07	V3.00.81.20 SP01	With the function block CanOpenGetState(), when enable=FALSE the function block freezes during execution
<a href="#">400053201</a>	Problem	ARSG4_3.07.2_B03.07	ARSG4_3.06.22_V03.06	Automation Runtime boots cyclically or crashes addresses in the same subnet are assigned on both Ethernet interfaces
<a href="#">400051241</a>	Problem	ARSG4_3.07.2_B03.07	ARSG4_3.06.22_V03.06	Remanent variables are not initialized with their INIT values when the CF is regenerated and a warm restart is performed.
<a href="#">400053665</a> <a href="#">400054105</a> <a href="#">400055244</a>	Problem	ARSG4_3.07.2_B03.07	ARSG4_3.06.22_V03.06	I/O cycle time violation during startup due to initialization of graphic card
<a href="#">400054911</a>	Problem	ARSG4_3.07.2_B03.07	ARSG4_3.06.22_V03.06	Function blocks from AsXML library ignore enable input
<a href="#">400046414</a>	Problem	ARSG4_3.07.1_A03.07	ARSG4_3.06.3_C03.06	Pagefault / Memory not in heap

<a href="#">400043785</a>	Problem	ARSG4_3.07.1_A03.07	ARSG4_2.95.20_T02.95	No clear text in the error logbook when data in the SRAM is lost while shutting down
---------------------------	---------	---------------------	----------------------	--

**1A4300.02 (1.0 Automation Studio 3.x)**

ID	valuation	solved since	known since	Description
<a href="#">400062152</a>	Problem	ARSG4_3.07.3_C03.07	V3.00.81.24 SP0x	Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem

**Requests and problems by product/component****1A4000.02 (2.0 Automation Runtime SG4)****AR - ARemb**

ID#400053201 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.2\_B03.07

Automation Runtime boots cyclically or crashes addresses in the same subnet are assigned on both Ethernet interfaces

**AR - ARsim**

ID#400062877 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.9\_I03.08

Remanent/permanent variables not saved when exiting ARsim

ID#400062877 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_4.00.10\_J04.00

Remanent/permanent variables not saved when exiting ARsim

ID#400055446 : known problem since V2.7.0.0015 SP08, correction planned for ARSG4\_3.07.3\_C03.07

Address error occurs when a breakpoint is reached on a command that is 1 byte long

ID#400055446 : known problem since V2.7.0.0015 SP08, correction planned for ARSG4\_3.08.4\_D03.08

Address error occurs when a breakpoint is reached on a command that is 1 byte long

ID#400055446 : known problem since V2.7.0.0015 SP08, correction planned for ARSG4\_4.00.4\_D04.00

Address error occurs when a breakpoint is reached on a command that is 1 byte long

**AR - ARwin**

ID#400065938 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.08.15\_O03.08

c command line argument in the ARwin configuration disables not only the COM2 interface but also COM1.

ID#400065938 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_4.00.15\_O04.00

c command line argument in the ARwin configuration disables not only the COM2 interface but also COM1.

ID#400065540 : solved problem, known since V3.00.81.24 SP0x, solved since ARSG4\_3.08.12\_L03.08

ARwin shows incorrect amount of available DRAM memory in SDM

ID#400065540 : solved problem, known since V3.00.81.24 SP0x, solved since ARSG4\_4.00.12\_L04.00

ARwin shows incorrect amount of available DRAM memory in SDM

ID#400066313 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.8\_H03.07

If, for example, the X2X timer is used as the system clock, then remanent variables aren't saved when there is a power failure

ID#400066313 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.11\_K03.08

If, for example, the X2X timer is used as the system clock, then remanent variables aren't saved when there is a power failure

ID#400066313 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_4.00.11\_K04.00

If, for example, the X2X timer is used as the system clock, then remanent variables aren't saved when there is a power failure

ID#400057456 : solved problem, known since ARSG4\_3.01.7\_G03.01, solved since ARSG4\_3.07.8\_H03.07

Update to ARwin configurator

It is now possible to set the broadcast address and the subnet mask.

ID#400057456 : solved problem, known since ARSG4\_3.01.7\_G03.01, solved since ARSG4\_4.00.8\_H04.00

Update to ARwin configurator

It is now possible to set the broadcast address and the subnet mask.

ID#400058774 : solved problem, known since ARSG4\_3.08.4\_D03.08, solved since ARSG4\_3.08.8\_H03.08

Incorrect version of rtosdrv.dll

If an APC with 16 interrupts (PIC types) is used as the target platform, e.g. an APC620 with an E855 board, there are problems with setup and when upgrading via AS. This is caused by incorrect versions of the dlls and driver involved.



ID#400058774 : solved problem, known since ARSG4\_3.08.4\_D03.08, solved since ARSG4\_3.08.7\_G03.08

Incorrect version of rtosdrv.dll

If an APC with 16 interrupts (PIC types) is used as the target platform, e.g. an APC620 with an E855 board, there are problems with setup and when upgrading via AS. This is caused by incorrect versions of the dlls and driver involved.

ID#400058774 : solved problem, known since ARSG4\_3.08.4\_D03.08, solved since ARSG4\_3.08.6\_F03.08

Incorrect version of rtosdrv.dll

If an APC with 16 interrupts (PIC types) is used as the target platform, e.g. an APC620 with an E855 board, there are problems with setup and when upgrading via AS. This is caused by incorrect versions of the dlls and driver involved.

ID#400057456 : solved problem, known since ARSG4\_3.01.7\_G03.01, solved since ARSG4\_4.00.12\_L04.00

Update to ARwin configurator

It is now possible to set the broadcast address and the subnet mask.

ID#268630 : known problem since ARSG4\_4.00.17\_Q04.00, correction planned for ARSG4\_4.00.18\_R04.00

ARwin on Windows 7 doesn't work in Shared mode (when using more than 2GB DRAM)

ID#268405 : known problem since ARSG4\_4.00.16\_P04.00, correction planned for ARSG4\_4.02.1\_A04.02

Problems with ARwin in Windows 7 when firewall is on

In order to avoid ARwin communication problems in Windows 7, the Windows Firewall must be disabled for the "Realtime OS Virtual Network interface.

ID#400069705 : known problem since ARSG4\_3.07.5\_E03.07, correction planned for ARSG4\_3.07.11\_K03.07

Backup of remanent data to SRAM doesn't complete if ARwin is operated in Shared mode.

Solution: Use Exclusive mode

ID#400069705 : known problem since ARSG4\_3.07.5\_E03.07, correction planned for ARSG4\_3.09.1\_A03.09

Backup of remanent data to SRAM doesn't complete if ARwin is operated in Shared mode.

Solution: Use Exclusive mode

ID#400065938 : known problem since ARSG4\_3.07.4\_D03.07, correction planned for ARSG4\_4.02.1\_A04.02

c command line argument in the ARwin configuration disables not only the COM2 interface but also COM1.

#### AR - General SG4

ID#400062576 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.07.7\_G03.07

Error handling SYSCONF module in SYSROM

ID#400062152 : solved problem, known since V3.00.81.24 SP0x, solved since ARSG4\_3.08.4\_D03.08

Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem

ID#400062576 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.08.10\_J03.08

Error handling SYSCONF module in SYSROM

ID#400062576 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_4.00.10\_J04.00

Error handling SYSCONF module in SYSROM

ID#400054674 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.08.9\_I03.08

Module transfer to target not saved if there is not sufficient memory in the back-up partition.

If storage space runs out while writing the back-up copy of a .br module (to the back-up partition), then both files (original and back-up copy) will remain on the CF, but the module in the back-up copy will be incomplete. An error will not be reported in this case. This doesn't cause any problems until the "healthy" file in the first partition is restored using the incomplete module from the second partition. A checksum error for the .br module will now be detected.

ID#400054674 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_4.00.9\_I04.00

Module transfer to target not saved if there is not sufficient memory in the back-up partition.

If storage space runs out while writing the back-up copy of a .br module (to the back-up partition), then both files (original and back-up copy) will remain on the CF, but the module in the back-up copy will be incomplete. An error will not be reported in this case. This doesn't cause any problems until the "healthy" file in the first partition is restored using the incomplete module from the second partition. A checksum error for the .br module will now be detected.

ID#400056892 : solved problem, known since V3.00.81.22 SP01, solved since ARSG4\_3.08.6\_F03.08

If the requested bur\_heap\_size (C++) is too large, the installation error ERR\_LOADER\_USERHEAP (5150) is now triggered

ID#400056892 : solved problem, known since V3.00.81.22 SP01, solved since ARSG4\_4.00.6\_F04.00

If the requested `bur_heap_size` (C++) is too large, the installation error `ERR_LOADER_USERHEAP` (5150) is now triggered

ID#400056515 : solved problem, known since ARSG4\_3.07.2\_B03.07, solved since ARSG4\_3.07.4\_D03.07

Watchdog after `CanWrite()` on IF060 with IF621

Initialization problems in the CAN IRQ routine can prevent IRQs from being acknowledged and trigger a watchdog error.

ID#400056515 : solved problem, known since ARSG4\_3.07.2\_B03.07, solved since ARSG4\_3.08.6\_F03.08

Watchdog after `CanWrite()` on IF060 with IF621

Initialization problems in the CAN IRQ routine can prevent IRQs from being acknowledged and trigger a watchdog error.

ID#400056515 : solved problem, known since ARSG4\_3.07.2\_B03.07, solved since ARSG4\_4.00.6\_F04.00

Watchdog after `CanWrite()` on IF060 with IF621

Initialization problems in the CAN IRQ routine can prevent IRQs from being acknowledged and trigger a watchdog error.

ID# 400054123, 400055855 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.3\_C03.07

When downloading in one cycle mode, an interrupt block can cause an I/O cycle time violation (27306)

ID# 400054123, 400055855 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.6\_F03.08

When downloading in one cycle mode, an interrupt block can cause an I/O cycle time violation (27306)

ID#400055674 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.4\_D03.08

Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem

ID#400055674 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.3\_C03.07

Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem

ID#400055674 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_4.00.5\_E04.00

Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem

ID# 400046190, 400041900 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_4.00.4\_D04.00

Upgrade to AR Version E3.01 can cause the CPU to continuously reboot

ID# 400054123, 400055855 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_4.00.6\_F04.00

When downloading in one cycle mode, an interrupt block can cause an I/O cycle time violation (27306)

ID#400051241 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.2\_B03.07

Remanent variables are not initialized with their INIT values when the CF is regenerated and a warm restart is performed.

ID# 400046190, 400041900 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.6\_F03.08

Upgrade to AR Version E3.01 can cause the CPU to continuously reboot

ID#400043785 : solved problem, known since ARSG4\_2.95.20\_T02.95, solved since ARSG4\_3.07.1\_A03.07

No clear text in the error logbook when data in the SRAM is lost while shutting down

ID# 400002467, 400058853, 400058855 : new function since ARSG4\_3.08.7\_G03.08

Task class stack can only be configured up to a size of 1MB.

ID#400048512 : new function since ARSG4\_4.00.9\_I04.00

It is not possible to use C variables larger than 16 MB.

If variables larger than 16 MB are declared in C programs, Error 4522 will be generated when the project is built.

ID# 400002467, 400058853, 400058855 : new function since ARSG4\_4.00.7\_G04.00

Task class stack can only be configured up to a size of 1MB.

ID#400066308 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_3.07.10\_J03.07

Error copying CAN CMS objects

Data is copied byte-wise from the CMS object to the PVs, although the target PVs may have data types larger than one byte.

ID#400066308 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_4.02.1\_A04.02

Error copying CAN CMS objects

Data is copied byte-wise from the CMS object to the PVs, although the target PVs may have data types larger than one byte.

ID#400055674 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_3.08.4\_D03.08

Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem

ID# 400046190, 400041900 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_3.07.11\_K03.07

Upgrade to AR Version E3.01 can cause the CPU to continuously reboot

ID#400005281 : known problem since ARSG4\_2.94.22\_V02.94, correction planned for ARSG4\_3.08.2\_B03.08

INA online connection to X20CS1020 stops working when the modem configuration is also activated

#### AR - PP45

ID#400055836 : new function since ARSG4\_3.07.6\_F03.07

PP45 could fail at low temperatures

Low temperatures can cause a timer on the CPU to stop running. This problem can only be corrected by resetting the timer.

ID#400055836 : new function since ARSG4\_3.08.8\_H03.08

PP45 could fail at low temperatures

Low temperatures can cause a timer on the CPU to stop running. This problem can only be corrected by resetting the timer.

ID#400055836 : new function planned for ARSG4\_4.00.8\_H04.00

PP45 could fail at low temperatures

Low temperatures can cause a timer on the CPU to stop running. This problem can only be corrected by resetting the timer.

#### Diagnose - Debugger

ID#400053447 : solved problem, known since V3.00.81.20 SP01, solved since ARSG4\_3.07.6\_F03.07

In some circumstances, the watchdog may be triggered during debugging because a required system resource (Mutex) is not available

ID# 400035047, 400036404 : solved problem, known since ARSG4\_3.08.25\_Y03.08, solved since ARSG4\_4.00.11\_K04.00

If a breakpoint is reached in the INIT SP, then it is no longer possible to leave the breakpoint. Execute (F5), Step Over (F10) or Step Into (F11) do not have an affect.

ID#400037524 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.08.3\_C03.08

Error "9098 - System I/O cross-link task cycle time violation" is generated when a SafePLC and standard PLC are linked and a breakpoint is set on the standard PLC.

ID#400054111 : known problem since ARSG4\_3.01.9\_I03.01, correction planned for ARSG4\_3.07.4\_D03.07

Debugger terminates online connection

If application data is being exchanged with a target system via Ethernet, and a breakpoint is reached, all Ethernet buffers are used up (since the data is no longer picked up) and Ethernet communication is terminated. It is also no longer possible to establish an online connection.

ID#400054111 : known problem since ARSG4\_3.01.9\_I03.01, correction planned for ARSG4\_3.08.5\_E03.08

Debugger terminates online connection

If application data is being exchanged with a target system via Ethernet, and a breakpoint is reached, all Ethernet buffers are used up (since the data is no longer picked up) and Ethernet communication is terminated. It is also no longer possible to establish an online connection.

ID#400054111 : known problem since ARSG4\_3.01.9\_I03.01, correction planned for ARSG4\_4.00.4\_D04.00

Debugger terminates online connection

If application data is being exchanged with a target system via Ethernet, and a breakpoint is reached, all Ethernet buffers are used up (since the data is no longer picked up) and Ethernet communication is terminated. It is also no longer possible to establish an online connection.

#### Diagnose - Logger

ID#400057809 : solved problem, known since , solved since ARSG4\_3.08.6\_F03.08

Using logger functions in fast task classes can lead to cycle time violations

Due to the copying required, using logger functions in fast task classes can lead to cycle time violations.

ID#400057809 : solved problem, known since ARSG4\_3.01.8\_H03.01, solved since ARSG4\_4.00.7\_G04.00

Using logger functions in fast task classes can lead to cycle time violations

Due to the copying required, using logger functions in fast task classes can lead to cycle time violations.

**Diagnose - SDM**

ID#400065562 : solved problem, known since ARSG4\_3.07.6\_F03.07, solved since ARSG4\_3.07.7\_G03.07

SDM 1 (Automation Studio 3.0.80) doesn't work with Firefox 4.0 and higher

The first version of the System Diagnostics Manager (SDM), delivered with Automation Studio 3.00.80 / 3.00.81 doesn't work correctly with Firefox version 4.0 or higher.  
Customers who use Firefox 4.0 or higher need to switch to SDM 2, provided with Automation Studio 3.00.90.

ID#400053957 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.4\_D03.07

Time calculation incorrect for logger entries in SDM

When time zones were used, calculation of the local time for logger entries in SDM was incorrect. This has been corrected.

ID#400053957 : solved problem, known since unbekannt, solved since ARSG4\_3.08.5\_E03.08

Time calculation incorrect for logger entries in SDM

When time zones were used, calculation of the local time for logger entries in SDM was incorrect. This has been corrected.

ID#400013287 : new function since ARSG4\_3.08.9\_I03.08

Use the Diagnostics System Manager to list modules' diagnostics data points

The System Diagnostics Manager can be used to save all of a module's diagnostic data points in a system dump.

**Diagnose - Tracer**

ID# 400053004, 400052525 : solved problem, known since V3.00.81.18, solved since ARSG4\_3.07.6\_F03.07

Trigger condition not working

If a trace with trigger condition is installed in the trace editor, then the trace will begin after the defined trigger event and automatically stop as soon as the buffer is full. If the trace is started again using the "Trace / Start" option in the main menu, the Start option in the shortcut menu or the "green traffic light" button, then the trace will be extremely slow or will not be started correctly.

ID# 400053004, 400052525 : solved problem, known since V3.00.81.18, solved since ARSG4\_3.08.8\_H03.08

Trigger condition not working

If a trace with trigger condition is installed in the trace editor, then the trace will begin after the defined trigger event and automatically stop as soon as the buffer is full. If the trace is started again using the "Trace / Start" option in the main menu, the Start option in the shortcut menu or the "green traffic light" button, then the trace will be extremely slow or will not be started correctly.

ID# 400053004, 400052525 : solved problem, known since V3.00.81.18, solved since ARSG4\_4.00.8\_H04.00

Trigger condition not working

If a trace with trigger condition is installed in the trace editor, then the trace will begin after the defined trigger event and automatically stop as soon as the buffer is full. If the trace is started again using the "Trace / Start" option in the main menu, the Start option in the shortcut menu or the "green traffic light" button, then the trace will be extremely slow or will not be started correctly.

**IO System - 2003 Backplane**

ID#400066089 : known problem since V2.7.0.4102 [V2.94], correction planned for ARSG4\_3.07.11\_K03.07

30479, 27306 when starting 7CP570.60-1 with four AF modules

When a fourth 7AF101.7 module with some free connections and five 7DM465.7 modules were connected to a 7AF101.7 module with three 7AF101.7 modules with no free connections, then turning on the analog module connected to the fourth 7AF101.7 caused a timeout, and Error 30479 was entered in the logbook. Then the AR resets the firmware of the 2003 backplane, and there is an I/O cycle time violation (27306). The timeout was set to low for this configuration and has been increased accordingly in the current version of AR.

ID#400066089 : known problem since V2.7.0.4102 [V2.94], correction planned for ARSG4\_3.09.1\_A03.09

30479, 27306 when starting 7CP570.60-1 with four AF modules

When a fourth 7AF101.7 module with some free connections and five 7DM465.7 modules were connected to a 7AF101.7 module with three 7AF101.7 modules with no free connections, then turning on the analog module connected to the fourth 7AF101.7 caused a timeout, and Error 30479 was entered in the logbook. Then the AR resets the firmware of the 2003 backplane, and there is an I/O cycle time violation (27306). The timeout was set to low for this configuration and has been increased accordingly in the current version of AR.

**IO System - CANIO**

ID#400039937 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.07.6\_F03.07

CANIO slaves are not always found after startup

ID#400039937 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.08.8\_H03.08

CANIO slaves are not always found after startup

ID#400039937 : solved problem, known since V3.00.80.25, solved since ARSG4\_4.00.8\_H04.00

CANIO slaves are not always found after startup

#### IO System - CANopen

ID#400060887 : solved problem, known since V3.00.81.22 SP01, solved since ARSG4\_3.07.6\_F03.07

CANopen slave not started by the master if it sends only an emergency telegram with data =0 instead of a Boot-Up message

ID#400060887 : solved problem, known since V3.00.81.22 SP01, solved since ARSG4\_3.08.8\_H03.08

CANopen slave not started by the master if it sends only an emergency telegram with data =0 instead of a Boot-Up message

ID#400056381 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.4\_D03.07

Priority of CANopen master can be configured

The user can configure the priority of the CANopen master in order to adjust the system load for a particular application.

ID#400056381 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.5\_E03.08

Priority of CANopen master can be configured

The user can configure the priority of the CANopen master in order to adjust the system load for a particular application.

ID#400056272 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_4.00.5\_E04.00

Priority of CANopen master can be configured

The user can configure the priority of the CANopen master in order to adjust the system load for a particular application.

ID#400060887 : new function since ARSG4\_4.00.8\_H04.00

CANopen slave not started by the master if it sends only an emergency telegram with data =0 instead of a Boot-Up message

#### IO System - General

ID#400064601 : solved problem, known since ARSG4\_3.08.8\_H03.08, solved since ARSG4\_3.08.10\_J03.08

Insufficient logbook entry when ArConfig has double channels/QLinks.

If the ArConfig contains double channels or QLinks, then Error 30965 "No name specification" appears, which hardly explains the actual cause of the error.

ID#400064601 : solved problem, known since ARSG4\_3.08.8\_H03.08, solved since ARSG4\_4.00.10\_J04.00

Insufficient logbook entry when ArConfig has double channels/QLinks.

If the ArConfig contains double channels or QLinks, then Error 30965 "No name specification" appears, which hardly explains the actual cause of the error.

ID#400028352 : solved problem, known since ARSG4\_3.00.15\_O03.00, solved since ARSG4\_3.08.9\_I03.08

If global variables mapped to I/O points receive new addresses due to a change to the project, it is possible that the variable values are no longer transferred to the I/O points.

ID#400058109 : solved problem, known since V3.00.81.22 SP01, solved since ARSG4\_3.07.6\_F03.07

It can take very long to install I/O mappings, which can result in the connection being terminated due to a time violation.

ID#400058109 : solved problem, known since V3.00.81.22 SP01, solved since ARSG4\_3.08.7\_G03.08

It can take very long to install I/O mappings, which can result in the connection being terminated due to a time violation.

ID#400058109 : solved problem, known since V3.00.81.22 SP01, solved since ARSG4\_4.00.7\_G04.00

It can take very long to install I/O mappings, which can result in the connection being terminated due to a time violation.

ID#400057340 : solved problem, known since ARSG4\_3.07.2\_B03.07, solved since ARSG4\_4.00.6\_F04.00

POWERLINK reports error 27306 when starting a visualization application

When initializing the graphics card, the SOC interrupt is delayed, which causes an I/O cycle time violation to be reported. Since cyclic data is not transferred in this early boot phase, I/O cycle time violations are now only evaluated after the beginning of cyclic data transfer.

ID#400057340 : solved problem, known since ARSG4\_3.07.2\_B03.07, solved since ARSG4\_3.08.6\_F03.08

POWERLINK reports error 27306 when starting a visualization application

When initializing the graphics card, the SOC interrupt is delayed, which causes an I/O cycle time violation to be reported. Since cyclic data is not transferred in this early boot phase, I/O cycle time violations are now only evaluated after the beginning of cyclic data transfer.

ID#400057340 : solved problem, known since ARSG4\_3.07.2\_B03.07, solved since ARSG4\_3.07.4\_D03.07

POWERLINK reports error 27306 when starting a visualization application

When initializing the graphics card, the SOC interrupt is delayed, which causes an I/O cycle time violation to be reported. Since cyclic data is not transferred in this early boot phase, I/O cycle time violations are now only evaluated after the beginning of cyclic data transfer.



ID#400057827 : solved problem, known since ARSG4\_3.07.1\_A03.07, solved since ARSG4\_3.07.4\_D03.07

Maximum number of device handles exceeded with approx. 400 safety modules

A setup with approx. 400 safety modules and an X20CP1485 ran out of device handles, which is indicated in the logbook by Error 26003 "AR-DevMan: no free admin entry". The maximum number of device instances has been increased and is now 2.5 times higher

ID# 400053665, 400054105, 400055244 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.2\_B03.07

I/O cycle time violation during startup due to initialization of graphic card

During the startup of the CPU with a highly utilized PCI bus a IO cycle time violation 27306 could be triggered by the initialization of the visualization tasks. IO cycle time violations in early startup phases are now caught by the system.

ID# 400028352, 400065604 : solved problem, known since ARSG4\_3.00.15\_O03.00, solved since ARSG4\_3.08.9\_I03.08

If global variables mapped to I/O points receive new addresses due to a change to the project, it is possible that the variable values are no longer transferred to the I/O points.

#### **IO System - ModbusTCP**

ID#400060899 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.07.6\_F03.07

Due to an error in the task queue of the Modbus driver, packages that are received may no longer be allocated to the sent queries, thereby causing a connection timeout.

ID#400060899 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.08.8\_H03.08

Due to an error in the task queue of the Modbus driver, packages that are received may no longer be allocated to the sent queries, thereby causing a connection timeout.

ID#400060899 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_4.00.8\_H04.00

Due to an error in the task queue of the Modbus driver, packages that are received may no longer be allocated to the sent queries, thereby causing a connection timeout.

ID#400051942 : solved problem, known since unbekannt, solved since ARSG4\_3.07.5\_E03.07

ModbusTCP doesn't start all slaves

The problem is caused when there are no sockets available when establishing the connection. The ModbusTCP driver doesn't finish the initialization.

ID#400051942 : solved problem, known since unbekannt, solved since ARSG4\_4.00.7\_G04.00

ModbusTCP doesn't start all slaves

The problem is caused when there are no sockets available when establishing the connection. The ModbusTCP driver doesn't finish the initialization.

ID#400051942 : solved problem, known since unbekannt, solved since ARSG4\_3.08.6\_F03.08

ModbusTCP doesn't start all slaves

The problem is caused when there are no sockets available when establishing the connection. The ModbusTCP driver doesn't finish the initialization.

ID#400048959 : solved problem, known since ARSG4\_2.96.10\_J02.96, solved since ARSG4\_3.07.5\_E03.07

ModbusTCP master doesn't work on AC141

#### **IO System - netX**

ID#400069009 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.08.15\_O03.08

VC application blocks netX data communication

A priority problem interrupts netX data collection in the rhythm of the default update time of the data source.

ID#400069009 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_4.00.15\_O04.00

VC application blocks netX data communication

A priority problem interrupts netX data collection in the rhythm of the default update time of the data source.

ID#400065361 : solved problem, known since ARSG4\_3.07.3\_C03.07, solved since ARSG4\_3.07.7\_G03.07

IF1063-1 doesn't work on the BC1083

#### **IO System - Powerlink**

ID#400068763 : solved problem, known since ARSG4\_3.08.11\_K03.08, solved since ARSG4\_4.00.16\_P04.00

Naming of POWERLINK devices from other vendors in AsIODiag

The function blocks of the Library AsIODiag returned "plk\_any" or "epi\_any" for POWERLINK-Devices from other vendors than B&R in former versions.

The current Automation Runtime returns device names in the format "u%xv%x-unknown" where the first %x is replaced with the device identifier and the second %x is replaced by the vendor identifier.

Only if the option "Verify Device Type" is switched off, devices configured by XDD-Import will return "epi\_any".

ID#400068763 : solved problem, known since ARSG4\_3.08.11\_K03.08, solved since ARSG4\_3.08.14\_N03.08

Naming of POWERLINK devices from other vendors in AsIODiag

The function blocks of the Library AsIODiag returned "plk\_any" or "epi\_any" for POWERLINK-Devices from other vendors than B&R in former versions.

The current Automation Runtime returns device names in the format "u%xv%x-unknown" where the first %x is replaced with the device identifier and the second %x is replaced by the vendor identifier.

Only if the option "Verify Device Type" is switched off, devices configured by XDD-Import will return "epi\_any".

ID#400060016 : solved problem, known since ARSG4\_3.07.2\_B03.07, solved since ARSG4\_4.00.16\_P04.00

Error 26051 in logbook when X20CS2770 after X20BCx083 on APC or Power Panel

If CANIO is enabled on both CAN interfaces of an X20CS2770 device being operated downstream from an X20BCx083 device, which itself is downstream from an APC or Power Panel, the error message "26051 AR-DD: xDeviceInit() error" is entered in the logbook. Starting with AR K4.00, CANIO can be run on both CAN interfaces.

ID#258192 : solved problem, known since ARSG4\_3.07.2\_B03.07, solved since ARSG4\_4.00.11\_K04.00

Firmware Update for SafeMC did not complete.

Due to a change in A4.00, the firmware update for SafeMC modules doesn't complete. The R/E LED for SafeMC modules continues to double-blink green.

Starting with J4.00, the firmware update for SafeMC modules functions correctly again.

ID#400065239 : solved problem, known since ARSG4\_3.07.2\_B03.07, solved since ARSG4\_3.07.7\_G03.07

Firmware Update for SafeMC did not complete.

Due to a change in B3.07, the firmware update for SafeMC modules doesn't complete. The R/E LED for SafeMC modules continues to double-blink green.

Starting with G3.07, the firmware update for SafeMC modules functions correctly again.

ID#400061758 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.14\_N03.08

ACOPOS synchronization problem 6002 in cascading POWERLINK networks when POWERLINK cycle time > 2ms

If a CPU with a system cycle time >2ms is synchronized as iCN with a higher level POWERLINK network, and ACOPOS stations with a POWERLINK cycle time >2ms are operated on a second POWERLINK interface, then the error 6002 can occur on the ACOPOS if the MN of the higher level POWERLINK network is still not active when the controller is started up.

Starting with AR version H3.08, the algorithm for starting synchronization upon startup has been improved so that the ACOPOS firmware can also be synchronized at startup even when there are very long cycle times and the MN has not been activated.

ID#251322 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_4.00.9\_I04.00

POWERLINK: ACOPOSMulti with SafeMC as chained station

ACOPOSMulti with SafeMC didn't work as a chained station.

ID#251317 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.5\_E03.07

POWERLINK: ACOPOSMulti with SafeMC as chained station

ACOPOSMulti with SafeMC didn't work as a chained station.

ID#400060965 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.5\_E03.07

POWERLINK: ACOPOSMulti with SafeMC as chained station

ACOPOSMulti with SafeMC didn't work as a chained station.

ID#400060016 : solved problem, known since ARSG4\_3.07.2\_B03.07, solved since ARSG4\_3.08.12\_L03.08

Error 26051 in logbook when X20CS2770 after X20BCx083 on APC or Power Panel

If CANIO is enabled on both CAN interfaces of an X20CS2770 device being operated downstream from an X20BCx083 device, which itself is downstream from an APC or Power Panel, the error message "26051 AR-DD: xDeviceInit() error" is entered in the logbook.

Starting with AR K3.08, CANIO can be run on both CAN interfaces.

ID#400068762 : new function since ARSG4\_3.08.12\_L03.08

Read ACOPOS device type using AsIODiag function block

Starting with ACOPOS OS 2.28.0, the ACOPOS device type can be read using the function blocks of the AsIODiag library.

ID#237362 : new function since ARSG4\_3.08.2\_B03.08

Logbook entry for firmware update now contains old and new version

When the firmware for POWERLINK stations is updated, both the old and new version numbers are noted in the logbook

ID#400040758 : new function since ARSG4\_3.08.2\_B03.08

Old and new firmware version entered in logbook

If the firmware on a POWERLINK V2 station is updated, the old and new firmware versions are now entered in the logbook, like they are for POWERLINK V1.

ID# 400009063, 400065339 : new function since ARSG4\_3.07.8\_H03.07

Find unconfigured POWERLINK stations with ASIODiag

Unconfigured POWERLINK stations can now be found using the ASIODiag library.

#### IO System - Profibus

ID#400053732 : solved problem, known since V3.00.81.18, solved since ARSG4\_3.07.4\_D03.07

Priority of Profibus master can be configured

The user can configure the priority of the Profibus master in order to adjust the system load for a particular application.

ID#400053732 : solved problem, known since V3.00.81.18, solved since ARSG4\_3.08.5\_E03.08

Priority of Profibus master can be configured

The user can configure the priority of the Profibus master in order to adjust the system load for a particular application.

ID#400053732 : solved problem, known since V3.00.81.18, solved since ARSG4\_4.00.5\_E04.00

Priority of Profibus master can be configured

The user can configure the priority of the Profibus master in order to adjust the system load for a particular application.

#### IO System - X2X

ID#238445 : known problem since ARSG4\_3.08.1\_A03.08, correction planned for ARSG4\_3.08.2\_B03.08

StaleData on local X2X Link interface when X2X cycle > system cycle

If the X2X cycle time was longer than the system cycle time, the StaleData flag has been set during system cycles in which no new data was received on the X2X Link. This behaviour was inconsistent to X2X Link modules which were connected to a X2X Link/POWERLINK buscontroller. Now the StaleData flag is only set, if no data was received from the module during the X2X Link cycle. The Nettime of the X2X Link interface can be used. To determine if new X2X Link data was received during the latest system cycle.

#### Library - AsARCfg

ID#400047724 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.07.5\_E03.07

When multiple Ethernet interfaces are used, interference in the routing table causes Error 29004 when the function block CfgSetDefaultGateway() is called

ID#400047724 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.08.6\_F03.08

When multiple Ethernet interfaces are used, interference in the routing table causes Error 29004 when the function block CfgSetDefaultGateway() is called

ID# -, 400047408, 400049937 : solved problem, known since V3.00.81.12, solved since ARSG4\_3.07.5\_E03.07

Error 29009 occurs when reading the default gateway

ID# -, 400047408, 400049937 : solved problem, known since V3.00.81.12, solved since ARSG4\_3.08.6\_F03.08

Error 29009 occurs when reading the default gateway

ID#400047724 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_4.00.6\_F04.00

When multiple Ethernet interfaces are used, interference in the routing table causes Error 29004 when the function block CfgSetDefaultGateway() is called

ID#400057746 : solved problem, known since ARSG4\_3.06.4\_D03.06, solved since ARSG4\_3.07.5\_E03.07

Calling the function block CfgSetEthConfigMode() with the same mode that is already in use triggers Error 29003

ID#400057746 : solved problem, known since ARSG4\_3.06.4\_D03.06, solved since ARSG4\_3.08.6\_F03.08

Calling the function block CfgSetEthConfigMode() with the same mode that is already in use triggers Error 29003

ID#400057746 : solved problem, known since ARSG4\_3.06.4\_D03.06, solved since ARSG4\_3.07.5\_E03.07

Calling the function block CfgSetEthConfigMode() with the same mode that is already in use triggers Error 29003

ID# -, 400047408, 400049937 : solved problem, known since V3.00.81.12, solved since ARSG4\_3.07.5\_E03.07

Error 29009 occurs when reading the default gateway

#### Library - AsARLog

ID#400059082 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.6\_F03.08

Creating a new logger module using AsArLogCreate() deletes any existing tasks with the same name

ID#400059082 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_4.00.6\_F04.00

Creating a new logger module using AsArLogCreate() deletes any existing tasks with the same name

ID#400072106 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_3.09.1\_A03.09

Accessing the "Safety" and "Fieldbus" logbooks via library (with an index) causes a PageFault. The problem can be avoided by specifying the names "\$safety" or "\$fieldbus."

ID#400072106 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_4.01.1\_A04.01

Accessing the "Safety" and "Fieldbus" logbooks via library (with an index) causes a PageFault. The problem can be avoided by specifying the names "\$safety" or "\$fieldbus."

ID#400072106 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_4.02.1\_A04.02

Accessing the "Safety" and "Fieldbus" logbooks via library (with an index) causes a PageFault. The problem can be avoided by specifying the names "\$safety" or "\$fieldbus."

#### Library - AsCANopen

ID#400064575 : solved problem, known since ARSG4\_3.07.3\_C03.07, solved since ARSG4\_3.07.7\_G03.07

Attempt to download AsCANopen library to ARsim rejected with error 9650 "Library function not available"

ID#400064575 : solved problem, known since ARSG4\_3.07.3\_C03.07, solved since ARSG4\_3.08.10\_J03.08

Attempt to download AsCANopen library to ARsim rejected with error 9650 "Library function not available"

ID#400064575 : solved problem, known since ARSG4\_3.07.3\_C03.07, solved since ARSG4\_4.00.10\_J04.00

Attempt to download AsCANopen library to ARsim rejected with error 9650 "Library function not available"

ID#400055214 : solved problem, known since ARSG4\_3.01.8\_H03.01, solved since ARSG4\_3.07.4\_D03.07

Using CANopenNMT() can prevent a task download from completing

As a result the section of code for releasing the semaphore is not executed. The second time this function is called it is blocked by the semaphore and the task can't be completely transferred.

ID#400055214 : solved problem, known since ARSG4\_3.01.8\_H03.01, solved since ARSG4\_3.08.4\_D03.08

Using CANopenNMT() can prevent a task download from completing

As a result the section of code for releasing the semaphore is not executed. The second time this function is called it is blocked by the semaphore and the task can't be completely transferred.

ID#400055214 : solved problem, known since ARSG4\_3.01.8\_H03.01, solved since ARSG4\_4.00.4\_D04.00

Using CANopenNMT() can prevent a task download from completing

As a result the section of code for releasing the semaphore is not executed. The second time this function is called it is blocked by the semaphore and the task can't be completely transferred.

ID#400054457 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.3\_C03.07

CANopenSDOWriteData() terminates after downloading several hundred bytes due to a full CAN buffer

ID#400054457 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.4\_D03.08

CANopenSDOWriteData() terminates after downloading several hundred bytes due to a full CAN buffer

ID#400054457 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_4.00.4\_D04.00

CANopenSDOWriteData() terminates after downloading several hundred bytes due to a full CAN buffer

ID#400055463 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.07.3\_C03.07

CANopenSDOWrite8() only sends every second SDO

ID#400055463 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.08.4\_D03.08

CANopenSDOWrite8() only sends every second SDO

ID#400055463 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_4.00.3\_C04.00

CANopenSDOWrite8() only sends every second SDO

ID#400054360 : solved problem, known since V3.00.81.20 SP01, solved since ARSG4\_3.07.2\_B03.07

With the function block CanOpenGetState(), when enable=FALSE the function block freezes during execution

ID#400054360 : solved problem, known since V3.00.81.20 SP01, solved since ARSG4\_3.08.3\_C03.08

With the function block CanOpenGetState(), when enable=FALSE the function block freezes during execution

ID#400054360 : solved problem, known since V3.00.81.20 SP01, solved since ARSG4\_4.00.3\_C04.00

With the function block CanOpenGetState(), when enable=FALSE the function block freezes during execution

#### Library - AsEPL

ID#400055409 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.08.12\_L03.08

EplSDORead() stays in the status "Busy" after the enable FB is set to FALSE

ID#400055409 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.08.14\_N03.08

EplSDORead() stays in the status "Busy" after the enable FB is set to FALSE

#### Library - AsIMA

ID#400050977 : solved problem, known since unbekannt, solved since ARSG4\_3.08.8\_H03.08

AsIMA doesn't adjust for daylight savings time when reading the time from a peer station

ID#400050977 : solved problem, known since unbekannt, solved since ARSG4\_4.00.8\_H04.00

AsIMA doesn't adjust for daylight savings time when reading the time from a peer station

ID#400039843 : known problem since ARSG4\_3.01.1\_A03.01, correction planned for ARSG4\_3.07.9\_I03.07

Under certain circumstances (INAaction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC

ID#400039843 : known problem since ARSG4\_3.01.1\_A03.01, correction planned for ARSG4\_3.08.14\_N03.08

Under certain circumstances (INAaction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC

ID# 400035792, 400020837 : known problem since ARSG4\_3.00.22\_V03.00, correction planned for ARSG4\_3.07.9\_I03.07

Under certain circumstances (INAaction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC

ID# 400035792, 400020837 : known problem since ARSG4\_3.00.22\_V03.00, correction planned for ARSG4\_3.08.14\_N03.08

Under certain circumstances (INAaction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC

ID#400039843 : known problem since ARSG4\_3.01.1\_A03.01, correction planned for ARSG4\_4.00.14\_N04.00

Under certain circumstances (INAaction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC

ID#400007523 : known problem since V3.0.71.16 SP01, correction planned for ARSG4\_3.08.10\_J03.08

AsIMA ignores time zone information

ID# 400035792, 400020837 : known problem since ARSG4\_3.00.22\_V03.00, correction planned for ARSG4\_4.00.14\_N04.00

Under certain circumstances (INAaction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC

ID#400007523 : known problem since V3.0.71.16 SP01, correction planned for ARSG4\_4.00.10\_J04.00

AsIMA ignores time zone information

#### Library - AsIODiag

ID#257265 : new function since ARSG4\_3.08.16\_P03.08

Detection of POWERLINK hardware using AS-IO-Diag

In the past, when POWERLINK devices from other manufacturers were detected, the function block DiagGetStrInfo with infoCode asdiagPLUGGED\_MODULE returned the string "epl\_any".

Starting with AR N3.08, devices from other manufacturers will return a string with the format "u% xV% x-PL-unknown", where the first %x represents the hexadecimal product code and the second %x represents the hexadecimal vendor ID.

If the function for checking the vendor ID and product code is enabled and these codes match the detected POWERLINK device, then the model number of the configured device is applied so that the strings returned with the infoCodes asdiagCONFIG\_MODULE and asdiagPLUGGED\_MODULE match.

ID#253632 : new function since ARSG4\_4.00.16\_P04.00

Detection of POWERLINK hardware using AS-IO-Diag

In the past, when POWERLINK devices from other manufacturers were detected, the function block DiagGetStrInfo with infoCode asdiagPLUGGED\_MODULE returned the string "epl\_any".

Starting with AR N4.00, devices from other manufacturers will return a string with the format "u% xV% x-PL-unknown", where the first %x represents the hexadecimal product code and the second %x represents the hexadecimal vendor ID.

If the function for checking the vendor ID and product code is enabled and these codes match the detected POWERLINK device, then the model number of the configured device is applied so that the strings returned with the infoCodes asdiagCONFIG\_MODULE and asdiagPLUGGED\_MODULE match.



**Library - AsL2DP**

ID#400030702 : new function since ARSG4\_4.00.11\_K04.00

New function block L2DPGetNode() for reading Profibus station number

ID#400030702 : new function since ARSG4\_4.00.11\_K04.00

New function block L2DPGetNode() for reading Profibus station number

**Library - AsMem**

ID# 400007099, 400044198 : solved problem, known since V2.7.0.0010 SP03, solved since ARSG4\_3.08.6\_F03.08

AsMemPartFree returned -8 byte free memory size

The function block AsMemPartFree for requesting the free memory size of a memory partition created with AsMemPartFree returned the value numByteFree = 4294967288 (= 16#FFFFFFF8 = -8), if the whole memory was allocated.

ID# 400007099, 400044198 : solved problem, known since V2.7.0.0010 SP03, solved since ARSG4\_4.00.6\_F04.00

AsMemPartFree returned -8 byte free memory size

The function block AsMemPartFree for requesting the free memory size of a memory partition created with AsMemPartFree returned the value numByteFree = 4294967288 (= 16#FFFFFFF8 = -8), if the whole memory was allocated.

ID#245157 : new function since ARSG4\_4.00.6\_F04.00

The value specified for AsMemPartCreate now corresponds to the largest allocated block

The value entered for AsMemPartCreate is rounded up to the closest multiple of 8, and then matches the largest allocated block. In older versions of AR, the management overhead of up to 112 bytes was also taken from the created partition.

**Library - AsNxCoM**

ID#400062449 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.07.7\_G03.07

When using multiple netX CANopen master modules, a different handle is used for each module, which speeds up asynchronous function block processing.

ID#400062449 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.08.10\_J03.08

When using multiple netX CANopen master modules, a different handle is used for each module, which speeds up asynchronous function block processing.

ID#400062449 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_4.00.10\_J04.00

When using multiple netX CANopen master modules, a different handle is used for each module, which speeds up asynchronous function block processing.

**Library - AsUSB**

ID#400051015 : solved problem, known since ARSG4\_3.07.1\_A03.07, solved since ARSG4\_3.07.3\_C03.07

Support for Cino F788-G barcode scanner

ID#400051015 : solved problem, known since ARSG4\_3.07.1\_A03.07, solved since ARSG4\_3.08.4\_D03.08

Support for Cino F788-G barcode scanner

ID#400051015 : solved problem, known since ARSG4\_3.07.1\_A03.07, solved since ARSG4\_4.00.6\_F04.00

Support for barcode scanner Cino F788-G

**Library - AsXML**

ID#400054911 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.2\_B03.07

Function blocks from AsXML library ignore enable input

ID#400054911 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.3\_C03.08

Function blocks from AsXML library ignore enable input

ID#400054911 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_4.00.4\_D04.00

Function blocks from AsXML library ignore enable input

**Library - CAN\_lib**

ID#400060652 : solved problem, known since ARSG4\_3.07.3\_C03.07, solved since ARSG4\_3.07.5\_E03.07

CANrwtab() returns invalid data

When CAN telegrams with fewer than 8 bytes are received, 8 are always written to the receive buffer (unused bytes are not written with 0).

ID#400060652 : solved problem, known since ARSG4\_3.07.3\_C03.07, solved since ARSG4\_3.08.7\_G03.08

CANrwtab() returns invalid data

When CAN telegrams with fewer than 8 bytes are received, 8 are always written to the receive buffer (unused bytes are not written with 0).

ID#400060652 : solved problem, known since ARSG4\_3.07.3\_C03.07, solved since ARSG4\_4.00.7\_G04.00

CANrwtab() returns invalid data

When CAN telegrams with fewer than 8 bytes are received, 8 are always written to the receive buffer (unused bytes are not written with 0).

#### Library - FileIO

ID#400069276 : solved problem, known since ARSG4\_3.08.10\_J03.08, solved since ARSG4\_3.07.9\_I03.07

Using a handle that has already been closed can cause a page fault (read, write, or close on a handle)

ID#400069276 : solved problem, known since ARSG4\_3.08.10\_J03.08, solved since ARSG4\_3.08.14\_N03.08

Using a handle that has already been closed can cause a page fault (read, write, or close on a handle)

ID#400069276 : solved problem, known since ARSG4\_3.08.10\_J03.08, solved since ARSG4\_4.00.14\_N04.00

Using a handle that has already been closed can cause a page fault (read, write, or close on a handle)

ID#400060157 : solved problem, known since ARSG4\_2.96.12\_L02.96, solved since ARSG4\_3.07.6\_F03.07

The status BUSY can remain set for up to 120 minutes if the connection is lost when using the function block DirInfo() over a network

ID#400060157 : solved problem, known since ARSG4\_2.96.12\_L02.96, solved since ARSG4\_3.08.9\_I03.08

The status BUSY can remain set for up to 120 minutes if the connection is lost when using the function block DirInfo() over a network

ID#400051743 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.2\_B03.08

If no destination directory is specified for DirCopy(), copying to ARsim doesn't work.

ID#400048318 : new function since ARSG4\_3.08.11\_K03.08

New function blocks FileWriteEx() and FileTruncate()

ID#400063458 : new function since ARSG4\_3.08.10\_J03.08

DevLink() blocks other file actions for a relatively long time

ID#400038864 : new function since ARSG4\_3.08.9\_I03.08

Function blocks now return the error 20709 (fiERR\_FILE\_DEVICE) if a device is not present

ID#400063458 : new function since ARSG4\_4.00.10\_J04.00

DevLink() blocks other file actions for a relatively long time

ID#400048318 : new function since ARSG4\_4.00.11\_K04.00

New function blocks FileWriteEx() and FileTruncate()

ID#400038864 : new function since ARSG4\_4.00.10\_J04.00

Function blocks now return the error 20709 (fiERR\_FILE\_DEVICE) if a device is not present

#### Library - LoopConR

ID#400067831 : known problem since unbekannt, correction planned for ARSG4\_4.02.1\_A04.02

Memory management problem with task overload corrected with library version V2.80.1 and up

#### Library - SYS\_lib

ID#400011003 : solved problem, known since ARSG4\_4.00.3\_C04.00, solved since ARSG4\_4.00.6\_F04.00

TIM\_musec returns incorrect time when the system tick isn't a whole number multiple or factor of 10 milliseconds

If the system tick is not a real factor or whole number multiple of 10 milliseconds, then the microsecond counter is not reset after exactly 10 milliseconds as specified.

For example, with a system tick of 1600µs it is reset after 9600µs (6x1600) or 11200µs (7x1600).

The AslTimeStamp() function from the AslTime library is better suited for time measurements.

ID#400011003 : solved problem, known since ARSG4\_3.08.4\_D03.08, solved since ARSG4\_3.08.6\_F03.08

TIM\_musec returns incorrect time when the system tick isn't a whole number multiple or factor of 10 milliseconds

If the system tick is not a real factor or whole number multiple of 10 milliseconds, then the microsecond counter is not reset after exactly 10 milliseconds as specified.

For example, with a system tick of 1600µs it is reset after 9600µs (6x1600) or 11200µs (7x1600).

The AslTimeStamp() function from the AslTime library is better suited for time measurements.

#### System - ANSL

ID#400055699 : solved problem, known since V3.00.81.22 SP01, solved since ARSG4\_4.00.8\_H04.00

VC Windows Terminal: Changes to Enum variables are not updated on the terminal, but changes from the terminal are updated on the CPU

#### System - Firmware

ID#257430 : solved problem, known since ARSG4\_3.01.11\_K03.01, solved since ARSG4\_3.07.6\_F03.07

PP065 in combination with a 4PP065.IF23-1 no longer booting due to a faulty flash access after a firmware update

ID#257375 : solved problem, known since ARSG4\_3.01.11\_K03.01, solved since ARSG4\_3.08.10\_J03.08

PP065 in combination with a 4PP065.IF23-1 no longer booting due to a faulty flash access after a firmware update

ID#400059335 : solved problem, known since unbekannt, solved since ARSG4\_3.07.6\_F03.07

Correction of the error in which very short and light pressure on the touch screen can cause the position to be evaluated incorrectly

ID#400059335 : solved problem, known since unbekannt, solved since ARSG4\_3.08.10\_J03.08

Correction of the error in which very short and light pressure on the touch screen can cause the position to be evaluated incorrectly

ID#400054833 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.4\_D03.08

PP065: Warning "26061 Cannot configure minimum reduced cycle time due to old firmware" because of different drivers or POWERLINK firmware

ID#400048657 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_4.00.3\_C04.00

PP045 with IF24 (L2DP) returns incorrect data when odd addresses are read in the Profibus image

ID#400037284 : new function since ARSG4\_3.08.10\_J03.08

Improved response time for PP065 touch screen

ID#400037284 : new function planned for ARSG4\_3.07.2\_B03.07

Improved response time for PP065 touch screen

ID#400059335 : known problem since unbekannt, correction planned for ARSG4\_4.00.7\_G04.00

Correction of the error in which very short and light pressure on the touch screen can cause the position to be evaluated incorrectly

ID#400054833 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_3.07.2\_B03.07

PP065: Warning "26061 Cannot configure minimum reduced cycle time due to old firmware" because of different drivers or POWERLINK firmware

ID#400048657 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_3.07.2\_B03.07

PP045 with IF24 (L2DP) returns incorrect data when odd addresses are read in the Profibus image

ID#400054833 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_4.00.3\_C04.00

PP065: Warning "26061 Cannot configure minimum reduced cycle time due to old firmware" because of different drivers or POWERLINK firmware

#### System - Firmware

ID#400037284 : new function since ARSG4\_3.07.2\_B03.07

Improved response time for PP065 touch screen

ID#400048657 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_3.08.4\_D03.08

PP045 with IF24 (L2DP) returns incorrect data when odd addresses are read in the Profibus image

#### System - FTP Server

ID#400055971 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_4.00.9\_I04.00

ARemb terminates INA connection if an attempt is made to access a non-existing partition via FTP

#### System - OPC

ID#400055614 : solved problem, known since PVI3.00.00.3119, solved since ARSG4\_3.08.8\_H03.08

"VT\_DATE local" wrong for DCOM routines - in leap years the date is offset by one day

ID#400055610 : solved problem, known since ARSG4\_3.07.1\_A03.07, solved since ARSG4\_3.08.8\_H03.08

DT and DATE\_AND \_TIME variables are converted incorrectly by VT\_DATE when they are written.

ID#400055610 : solved problem, known since ARSG4\_3.07.1\_A03.07, solved since ARSG4\_4.00.8\_H04.00

DT and DATE\_AND \_TIME variables are converted incorrectly by VT\_DATE when they are written.

ID#400055614 : solved problem, known since PVI3.00.00.3119, solved since ARSG4\_4.00.8\_H04.00

"VT\_DATE local" wrong for DCOM routines - in leap years the date is offset by one day

ID#400046414 : solved problem, known since ARSG4\_3.06.3\_C03.06, solved since ARSG4\_3.07.1\_A03.07

Pagefault / Memory not in heap

Incorrect handling of strings leads to page fault or "Memory not in heap" errors.

#### System - WebServer

ID#400057308 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.07.5\_E03.07

Target crashes with page fault in the web server module when an ASP write command is run from a website with more than 9 variables.

ID#400052213 : solved problem, known since V3.00.80.31 SP01, solved since ARSG4\_3.08.11\_K03.08

ENUM data types in ASP functions

With the current version of AR, it is now possible to use ENUM data types in HTML pages via ASP functions.

ID#400057308 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.08.11\_K03.08

Target crashes with page fault in the web server module when an ASP write command is run from a website with more than 9 variables.

ID#400053444 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.07.3\_C03.07

Variable values sometimes displayed incorrectly on ASP pages

On large ASP pages, some PV values are not evaluated correctly by the respective ASP function. As a result, the HTML page displays illegible special characters instead of the actual PV value. This error has been corrected.

ID#400053444 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.08.8\_H03.08

Variable values sometimes displayed incorrectly on ASP pages

On large ASP pages, some PV values are not evaluated correctly by the respective ASP function. As a result, the HTML page displays illegible special characters instead of the actual PV value. This error has been corrected.

ID#400057308 : solved problem, known since , solved since ARSG4\_3.08.8\_H03.08

Target crashes with page fault in the web server module when an ASP write command is run from a website with more than 9 variables.

ID#400057308 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_4.00.8\_H04.00

Target crashes with page fault in the web server module when an ASP write command is run from a website with more than 9 variables.

ID#400053444 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.08.8\_H03.08

Variable values sometimes displayed incorrectly on ASP pages

On large ASP pages, some PV values are not evaluated correctly by the respective ASP function. As a result, the HTML page displays illegible special characters instead of the actual PV value. This error has been corrected.

ID#400049979 : solved problem, known since ARSG4\_3.01.7\_G03.01, solved since ARSG4\_3.07.4\_D03.07

SDM - Update problems with dynamic page content

If a PC has multiple connections to the SDM (via multiple browser windows or multiple tabs within one browser), then dynamic SVG pages (CPU temperature, CPU load) are not updated continuously. This problem has been corrected.

ID#400053444 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_4.00.8\_H04.00

Variable values sometimes displayed incorrectly on ASP pages

On large ASP pages, ASP functions are not evaluated correctly. As a result, the HTML page displays illegible special characters instead of the actual PV value. This error has been corrected.

ID#400052213 : solved problem, known since V3.00.80.31 SP01, solved since ARSG4\_4.00.11\_K04.00

ENUM data types in ASP functions

With the current version of AR, it is now possible to use ENUM data types in HTML pages via ASP functions.

ID#400049979 : solved problem, known since ARSG4\_3.01.7\_G03.01, solved since ARSG4\_3.08.5\_E03.08

SDM - Update problems with dynamic page content

If a PC has multiple connections to the SDM (via multiple browser windows or multiple tabs within one browser), then dynamic SVG pages (CPU temperature, CPU load) are not updated continuously. This problem has been corrected.

**Build - Transfer To Target**

ID#400062152 : solved problem, known since V3.00.81.24 SP0x, solved since ARSG4\_3.07.3\_C03.07

Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem