

**B&R Revision Information**

**Version ARSG4\_3.08.22\_V3.08 Automation Runtime SG4 Upgrade (V3.08)**

**06-Sep-2011**

## Contents

<b>B&amp;R Revision Information (06.09.2011)Version ARSG4_3.08.22_V3.08 Automation Runtime SG4 Upgrade (V3.08)</b>	<b>1</b>
Contents	1
Requests and problems by product and version	1
1A4000.02 (2.0 Automation Runtime SG4)	1
1A4000.02 Visual Components	7
1A4300.02 (1.0 Automation Studio 3.x)	7
Requests and problems by product/component	7
1A4000.02 Visual Components	7
SG4 Runtime - Alarmsystem	7
SG4 Runtime - Common	7
1A4000.02 (2.0 Automation Runtime SG4)	7
AR - ARemb	7
AR - ARsim	7
AR - ARwin	8
AR - General SG4	9
AR - PP45	10
Diagnose - Debugger	11
Diagnose - Logger	11
Diagnose - SDM	11
Diagnose - Tracer	12
IO System - 2003 Backplane	12
IO System - 2005 Backplane	13
IO System - CANIO	13
IO System - CANopen	13
IO System - General	14
IO System - HWD	15
IO System - ModbusRTU	15
IO System - ModbusTCP	15
IO System - netX	15
IO System - Powerlink	15
IO System - Profibus	17
IO System - X2X	17
Library - AsARCfg	18
Library - AsARLog	18
Library - AsCANopen	18
Library - AsEPL	19
Library - AsIMA	19
Library - AsIOAcc	20
Library - AsIODiag	20
Library - AsL2DP	20
Library - AsMem	20
Library - AsNxCoM	20
Library - AsSem	20
Library - AsSNMP	20
Library - AsTcp	20
Library - AsUSB	20
Library - AsXML	20
Library - CAN_lib	21
Library - FileIO	21
Library - INAcient	22
Library - LoopConR V2.72.3	22
Library - SYS_lib	22
System - ANSL	22
System - DHCP	22
System - Firmware	22
System - Firmware	23
System - INA	23
System - Netboot	23
System - OPC	23
System - USB Support	24
System - WebServer	24
1A4300.02 (1.0 Automation Studio 3.x)	25
Build - Transfer To Target	25

## B&R Revision Information (06.09.2011)

### Version ARSG4\_3.08.22\_V3.08 Automation Runtime SG4 Upgrade (V3.08)

The current revision information can be downloaded from the B&R Homepage download area (<http://www.br-automation.com/download>).

#### Contents

- [Requests and problems by product/version](#)
- [Requests and problems by product/component](#)

#### Requests and problems by product and version

##### 1A4000.02 (2.0 Automation Runtime SG4)

ID	valuation	solved since	known since	Description
<a href="#">400007523</a>	Problem	-	V3.0.71.16 SP01	AsiMA ignores time zone information
<a href="#">400066089</a>	Problem	-	V2.7.0.4102 [V2.94]	30479, 27306 when starting 7CP570.60-1 with four AF modules
<a href="#">400066089</a>	Problem	-	V2.7.0.4102 [V2.94]	30479, 27306 when starting 7CP570.60-1 with four AF modules
<a href="#">400066089</a>	Problem	-	V2.7.0.4102 [V2.94]	30479, 27306 when starting 7CP570.60-1 with four AF modules
<a href="#">400066089</a>	Problem	-	V2.7.0.4102 [V2.94]	30479, 27306 when starting 7CP570.60-1 with four AF modules
<a href="#">400055446</a>	Problem	-	V2.7.0.0015 SP08	Address error occurs when a breakpoint is reached on a command that is 1 byte long
<a href="#">400055446</a>	Problem	-	V2.7.0.0015 SP08	Address error occurs when a breakpoint is reached on a command that is 1 byte long
<a href="#">400008018</a>	Problem	-	V2.7.0.0010 SP03	If a 7XX408.50-1 module is operated using an X20BC0083 and a BT9100, the PWM outputs do not function properly
<a href="#">400055836</a>	New function	-	-	PP45 could fail at low temperatures
<a href="#">400055836</a>	New function	-	-	PP45 could fail at low temperatures
<a href="#">400037284</a>	New function	-	-	Improved response time for PP065 touch screen
<a href="#">400037284</a>	New function	-	-	Improved response time for PP065 touch screen
<a href="#">238445</a>	Problem	-	ARSG4_3.08.1_A03.08	StaleData on local X2X Link interface when X2X cycle > system cycle
<a href="#">400069705</a>	Problem	-	ARSG4_3.07.5_E03.07	Backup of remanent data to SRAM doesn't complete if ARwin is operated in Shared mode.
<a href="#">400069705</a>	Problem	-	ARSG4_3.07.5_E03.07	Backup of remanent data to SRAM doesn't complete if ARwin is operated in Shared mode.
<a href="#">400066308</a>	Problem	-	ARSG4_3.06.22_V03.06	Error copying CAN CMS objects
<a href="#">400055674</a>	Problem	-	ARSG4_3.06.22_V03.06	Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem
<a href="#">400046190</a> <a href="#">400041900</a>	Problem	-	ARSG4_3.06.22_V03.06	Upgrade to AR Version E3.01 can cause the CPU to continuously reboot
<a href="#">400072106</a>	Problem	-	ARSG4_3.06.22_V03.06	Accessing the "Safety" and "Fieldbus" logbooks via library (with an index) causes a PageFault. The problem can be avoided by specifying the names "\$safety" or "\$fieldbus."
<a href="#">400054833</a>	Problem	-	ARSG4_3.06.22_V03.06	PP065: Warning "26061 Cannot configure minimum reduced cycle time due to old firmware" because of different drivers or POWERLINK firmware
<a href="#">400048657</a>	Problem	-	ARSG4_3.06.22_V03.06	PP045 with IF24 (L2DP) returns incorrect data when odd addresses are read in the Profibus image
<a href="#">400054111</a>	Problem	-	ARSG4_3.01.9_I03.01	Debugger terminates online connection
<a href="#">400054111</a>	Problem	-	ARSG4_3.01.9_I03.01	Debugger terminates online connection
<a href="#">400054111</a>	Problem	-	ARSG4_3.01.9_I03.01	Debugger terminates online connection
<a href="#">400039843</a>	Problem	-	ARSG4_3.01.1_A03.01	Under certain circumstances (INAaction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC
<a href="#">400039843</a>	Problem	-	ARSG4_3.01.1_A03.01	Under certain circumstances (INAaction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC
<a href="#">400042900</a>	Problem	-	ARSG4_3.00.22_V03.00	ModuleOK status for screw-in modules is not determined correctly in some cases
<a href="#">400035792</a> <a href="#">400020837</a>	Problem	-	ARSG4_3.00.22_V03.00	Under certain circumstances (INAaction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC
<a href="#">400035792</a> <a href="#">400020837</a>	Problem	-	ARSG4_3.00.22_V03.00	Under certain circumstances (INAaction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC
<a href="#">400005281</a>	Problem	-	ARSG4_2.94.22_V02.94	INA online connection to X20CS1020 stops working when the modem configuration is also activated
<a href="#">400038864</a>	New function	ARSG4_3.08.9_I03.08	V3.00.80.25	Function blocks now return the error 20709 (fiERR_FILE_DEVICE) if a device is not present
<a href="#">400013287</a>	New function	ARSG4_3.08.9_I03.08	V3.0.71.20 SP02	Use the Diagnostics System Manager to list modules' diagnostics data points
<a href="#">400062877</a>	Problem	ARSG4_3.08.9_I03.08	ARSG4_3.06.22_V03.06	Remanent/permanent variables not saved when exiting ARsim
<a href="#">400054674</a>	Problem	ARSG4_3.08.9_I03.08	ARSG4_3.00.22_V03.00	Module transfer to target not saved if there is not sufficient memory in the back-up partition.
<a href="#">400028352</a>	Problem	ARSG4_3.08.9_I03.08	ARSG4_3.00.15_O03.00	If global variables mapped to I/O points receive new addresses due to a change to the project, it is possible that the variable values are no longer transferred to the I/O points.
<a href="#">400028352</a>	Problem	ARSG4_3.08.9_I03.08	ARSG4_3.00.15_O03.00	If global variables mapped to I/O points receive new addresses due to a change to

<a href="#">400065604</a>				the project, it is possible that the variable values are no longer transferred to the I/O points.
<a href="#">400060157</a>	Problem	ARSG4_3.08.9_I03.08	ARSG4_2.96.12_L02.96	The status BUSY can remain set for up to 120 minutes if the connection is lost when using the function block DirInfo() over a network
<a href="#">400060887</a>	Problem	ARSG4_3.08.8_H03.08	V3.00.81.22 SP01	CANopen slave not started by the master if it sends only an emergency telegram with data =0 instead of a Boot-Up message
<a href="#">400053004</a> <a href="#">400052525</a>	Problem	ARSG4_3.08.8_H03.08	V3.00.81.18	Trigger condition not working
<a href="#">400039937</a>	Problem	ARSG4_3.08.8_H03.08	V3.00.80.25	CANIO slaves are not always found after startup
<a href="#">400055836</a>	New function	ARSG4_3.08.8_H03.08	-	PP45 could fail at low temperatures
<a href="#">400050977</a>	Problem	ARSG4_3.08.8_H03.08	-	AsIMA doesn't adjust for daylight savings time when reading the time from a peer station
<a href="#">400055614</a>	Problem	ARSG4_3.08.8_H03.08	PVI3.00.00.3119	"VT_DATE local" wrong for DCOM routines - in leap years the date is offset by one day
<a href="#">400058774</a>	Problem	ARSG4_3.08.8_H03.08	ARSG4_3.08.4_D03.08	Incorrect version of rtosdrv.dll
<a href="#">400060899</a>	Problem	ARSG4_3.08.8_H03.08	ARSG4_3.07.4_D03.07	Due to an error in the task queue of the Modbus driver, packages that are received may no longer be allocated to the sent queries, thereby causing a connection timeout.
<a href="#">400055610</a>	Problem	ARSG4_3.08.8_H03.08	ARSG4_3.07.1_A03.07	DT and DATE_AND_TIME variables are converted incorrectly by VT_DATE when they are written.
<a href="#">400053444</a>	Problem	ARSG4_3.08.8_H03.08	ARSG4_3.00.22_V03.00	Variable values sometimes displayed incorrectly on ASP pages
<a href="#">400053444</a>	Problem	ARSG4_3.08.8_H03.08	ARSG4_3.00.22_V03.00	Variable values sometimes displayed incorrectly on ASP pages
<a href="#">400057308</a>	Problem	ARSG4_3.08.8_H03.08	-	Target crashes with page fault in the web server module when an ASP write command is run from a website with more than 9 variables.
<a href="#">400002467</a> <a href="#">400058853</a> <a href="#">400058855</a>	New function	ARSG4_3.08.7_G03.08	V3.00.81.23 SP02	Task class stack can only be configured up to a size of 1MB.
<a href="#">400058109</a>	Problem	ARSG4_3.08.7_G03.08	V3.00.81.22 SP01	It can take very long to install I/O mappings, which can result in the connection being terminated due to a time violation.
<a href="#">400058774</a>	Problem	ARSG4_3.08.7_G03.08	ARSG4_3.08.4_D03.08	Incorrect version of rtosdrv.dll
<a href="#">400060652</a>	Problem	ARSG4_3.08.7_G03.08	ARSG4_3.07.3_C03.07	CANrwtab() returns invalid data
<a href="#">400056892</a>	Problem	ARSG4_3.08.6_F03.08	V3.00.81.22 SP01	If the requested bur_heap_size (C++) is too large, the installation error ERR_LOADER_USERHEAP (5150) is now triggered
<a href="#">400047408</a> <a href="#">400049937</a>	Problem	ARSG4_3.08.6_F03.08	V3.00.81.12	Error 29009 occurs when reading the default gateway
<a href="#">400007099</a> <a href="#">400044198</a>	Problem	ARSG4_3.08.6_F03.08	V2.7.0.0010 SP03	AsMemPartFree returned -8 byte free memory size
<a href="#">400051942</a>	Problem	ARSG4_3.08.6_F03.08	-	ModbusTCP doesn't start all slaves
<a href="#">400058774</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.08.4_D03.08	Incorrect version of rtosdrv.dll
<a href="#">400011003</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.08.4_D03.08	TIM_usec returns incorrect time when the system tick isn't a whole number multiple or factor of 10 milliseconds
<a href="#">400056515</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.07.2_B03.07	Watchdog after CanWrite() on IF060 with IF621
<a href="#">400057340</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.07.2_B03.07	POWERLINK reports error 27306 when starting a visualization application
<a href="#">400057746</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.06.4_D03.06	Calling the function block CfgSetEthConfigMode() with the same mode that is already in use triggers Error 29003
<a href="#">400054123</a> <a href="#">400055855</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.06.22_V03.06	When downloading in one cycle mode, an interrupt block can cause an I/O cycle time violation (27306)
<a href="#">400046190</a> <a href="#">400041900</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.06.22_V03.06	Upgrade to AR Version E3.01 can cause the CPU to continuously reboot
<a href="#">400059082</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.06.22_V03.06	Creating a new logger module using AsArLogCreate() deletes any existing tasks with the same name
<a href="#">400047724</a>	Problem	ARSG4_3.08.6_F03.08	ARSG4_3.01.9_I03.01	When multiple Ethernet interfaces are used, interference in the routing table causes Error 29004 when the function block CfgSetDefaultGateway() is called
<a href="#">400057809</a>	Problem	ARSG4_3.08.6_F03.08	-	Using logger functions in fast task classes can lead to cycle time violations
<a href="#">400053732</a>	Problem	ARSG4_3.08.5_E03.08	V3.00.81.18	Priority of Profibus master can be configured
<a href="#">400053957</a>	Problem	ARSG4_3.08.5_E03.08	-	Time calculation incorrect for logger entries in SDM
<a href="#">400056381</a>	Problem	ARSG4_3.08.5_E03.08	ARSG4_3.06.22_V03.06	Priority of CANopen master can be configured
<a href="#">400049979</a>	Problem	ARSG4_3.08.5_E03.08	ARSG4_3.01.7_G03.01	SDM - Update problems with dynamic page content
<a href="#">400062152</a>	Problem	ARSG4_3.08.4_D03.08	V3.00.81.24 SP0x	Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem
<a href="#">400051015</a>	Problem	ARSG4_3.08.4_D03.08	ARSG4_3.07.1_A03.07	Support for Cino F788-G barcode scanner
<a href="#">400055674</a>	Problem	ARSG4_3.08.4_D03.08	ARSG4_3.06.22_V03.06	Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem
<a href="#">400054457</a>	Problem	ARSG4_3.08.4_D03.08	ARSG4_3.06.22_V03.06	CANopenSDOWriteData() terminates after downloading several hundred bytes due to a full CAN buffer
<a href="#">400054833</a>	Problem	ARSG4_3.08.4_D03.08	ARSG4_3.06.22_V03.06	PP065: Warning "26061 Cannot configure minimum reduced cycle time due to old firmware" because of different drivers or POWERLINK firmware
<a href="#">400055463</a>	Problem	ARSG4_3.08.4_D03.08	ARSG4_3.01.9_I03.01	CANopenSDOWrite8() only sends every second SDO
<a href="#">400055214</a>	Problem	ARSG4_3.08.4_D03.08	ARSG4_3.01.8_H03.01	Using CANopenNMT() can prevent a task download from completing
<a href="#">400054360</a>	Problem	ARSG4_3.08.3_C03.08	V3.00.81.20 SP01	With the function block CanOpenGetState(), when enable=FALSE the function block freezes during execution
<a href="#">400037524</a>	Problem	ARSG4_3.08.3_C03.08	V3.00.80.25	Error "9098 - System I/O cross-link task cycle time violation" is generated when a SafePLC and standard PLC are linked and a breakpoint is set on the standard PLC.
<a href="#">400054911</a>	Problem	ARSG4_3.08.3_C03.08	ARSG4_3.06.22_V03.06	Function blocks from AsXML library ignore enable input
<a href="#">237362</a>	New function	ARSG4_3.08.2_B03.08	-	Logbook entry for firmware update now contains old and new version
<a href="#">400040758</a>	New function	ARSG4_3.08.2_B03.08	-	Old and new firmware version entered in logbook

<a href="#">400051743</a>	Problem	ARSG4_3.08.2_B03.08	ARSG4_3.06.22_V03.06	If no destination directory is specified for DirCopy(), copying to ARsim doesn't work.
<a href="#">257265</a>	New function	ARSG4_3.08.16_P03.08	nicht relevant	Detection of POWERLINK hardware using AS-IO-Diag
<a href="#">400065938</a>	Problem	ARSG4_3.08.15_O03.08	ARSG4_3.07.4_D03.07	c command line argument in the ARwin configuration disables not only the COM2 interface but also COM1.
<a href="#">400069009</a>	Problem	ARSG4_3.08.15_O03.08	ARSG4_3.07.4_D03.07	VC application blocks netX data communication
<a href="#">400068763</a>	Problem	ARSG4_3.08.14_N03.08	ARSG4_3.08.11_K03.08	Naming of POWERLINK devices from other vendors in AsIODiag
<a href="#">400069276</a>	Problem	ARSG4_3.08.14_N03.08	ARSG4_3.08.10_J03.08	Using a handle that has already been closed can cause a page fault (read, write, or close on a handle)
<a href="#">400061758</a>	Problem	ARSG4_3.08.14_N03.08	ARSG4_3.06.22_V03.06	ACOPOS synchronization problem 6002 in cascading POWERLINK networks when POWERLINK cycle time > 2ms
<a href="#">400055409</a>	Problem	ARSG4_3.08.14_N03.08	ARSG4_3.01.9_I03.01	EplSDORead() stays in the status "Busy" after the enable FB is set to FALSE
<a href="#">400065540</a>	Problem	ARSG4_3.08.12_L03.08	V3.00.81.24 SP0x	ARwin shows incorrect amount of available DRAM memory in SDM
<a href="#">400068762</a>	New function	ARSG4_3.08.12_L03.08	nicht relevant	Read ACOPOS device type using AsIODiag function block
<a href="#">400060016</a>	Problem	ARSG4_3.08.12_L03.08	ARSG4_3.07.2_B03.07	Error 26051 in logbook when X20CS2770 after X20BCx083 on APC or Power Panel
<a href="#">400055409</a>	Problem	ARSG4_3.08.12_L03.08	ARSG4_3.01.9_I03.01	EplSDORead() stays in the status "Busy" after the enable FB is set to FALSE
<a href="#">400048318</a>	New function	ARSG4_3.08.11_K03.08	V3.00.80.31 SP01	New function blocks FileWriteEx() and FileTruncate()
<a href="#">400052213</a>	Problem	ARSG4_3.08.11_K03.08	V3.00.80.31 SP01	ENUM data types in ASP functions
<a href="#">400066313</a>	Problem	ARSG4_3.08.11_K03.08	ARSG4_3.06.22_V03.06	If, for example, the X2X timer is used as the system clock, then remanent variables aren't saved when there is a power failure
<a href="#">400057308</a>	Problem	ARSG4_3.08.11_K03.08	ARSG4_3.01.9_I03.01	Target crashes with page fault in the web server module when an ASP write command is run from a website with more than 9 variables.
<a href="#">400059335</a>	Problem	ARSG4_3.08.10_J03.08	-	Correction of the error in which very short and light pressure on the touch screen can cause the position to be evaluated incorrectly
<a href="#">400037284</a>	New function	ARSG4_3.08.10_J03.08	-	Improved response time for PP065 touch screen
<a href="#">400064601</a>	Problem	ARSG4_3.08.10_J03.08	ARSG4_3.08.8_H03.08	Insufficient logbook entry when ArConfig has double channels/QLinks.
<a href="#">400062576</a>	Problem	ARSG4_3.08.10_J03.08	ARSG4_3.07.4_D03.07	Error handling SYSCONF module in SYSROM
<a href="#">400062449</a>	Problem	ARSG4_3.08.10_J03.08	ARSG4_3.07.4_D03.07	When using multiple netX CANopen master modules, a different handle is used for each module, which speeds up asynchronous function block processing.
<a href="#">400064575</a>	Problem	ARSG4_3.08.10_J03.08	ARSG4_3.07.3_C03.07	Attempt to download AsCANopen library to ARsim rejected with error 9650 "Library function not available"
<a href="#">400063458</a>	New function	ARSG4_3.08.10_J03.08	ARSG4_3.06.22_V03.06	DevLink() blocks other file actions for a relatively long time
<a href="#">257375</a>	Problem	ARSG4_3.08.10_J03.08	ARSG4_3.01.11_K03.01	PP065 in combination with a 4PP065.IF23-1 no longer booting due to a faulty flash access after a firmware update
<a href="#">400069276</a>	Problem	ARSG4_3.07.9_I03.07	ARSG4_3.08.10_J03.08	Using a handle that has already been closed can cause a page fault (read, write, or close on a handle)
<a href="#">400009063</a> <a href="#">400065339</a>	New function	ARSG4_3.07.8_H03.07	V3.0.71.16 SP01	Find unconfigured POWERLINK stations with ASIODiag
<a href="#">400066313</a>	Problem	ARSG4_3.07.8_H03.07	ARSG4_3.06.22_V03.06	If, for example, the X2X timer is used as the system clock, then remanent variables aren't saved when there is a power failure
<a href="#">400057456</a>	Problem	ARSG4_3.07.8_H03.07	ARSG4_3.01.7_G03.01	Update to ARwin configurator
<a href="#">400065562</a>	Problem	ARSG4_3.07.7_G03.07	ARSG4_3.07.6_F03.07	SDM 1 (Automation Studio 3.0.80) doesn't work with Firefox 4.0 and higher
<a href="#">400062576</a>	Problem	ARSG4_3.07.7_G03.07	ARSG4_3.07.4_D03.07	Error handling SYSCONF module in SYSROM
<a href="#">400062449</a>	Problem	ARSG4_3.07.7_G03.07	ARSG4_3.07.4_D03.07	When using multiple netX CANopen master modules, a different handle is used for each module, which speeds up asynchronous function block processing.
<a href="#">400065361</a>	Problem	ARSG4_3.07.7_G03.07	ARSG4_3.07.3_C03.07	IF1063-1 doesn't work on the BC1083
<a href="#">400064575</a>	Problem	ARSG4_3.07.7_G03.07	ARSG4_3.07.3_C03.07	Attempt to download AsCANopen library to ARsim rejected with error 9650 "Library function not available"
<a href="#">400065239</a>	Problem	ARSG4_3.07.7_G03.07	ARSG4_3.07.2_B03.07	Firmware Update for SafeMC did not complete.
<a href="#">400060887</a>	Problem	ARSG4_3.07.6_F03.07	V3.00.81.22 SP01	CANopen slave not started by the master if it sends only an emergency telegram with data =0 instead of a Boot-Up message
<a href="#">400058109</a>	Problem	ARSG4_3.07.6_F03.07	V3.00.81.22 SP01	It can take very long to install I/O mappings, which can result in the connection being terminated due to a time violation.
<a href="#">400053447</a>	Problem	ARSG4_3.07.6_F03.07	V3.00.81.20 SP01	In some circumstances, the watchdog may be triggered during debugging because a required system resource (Mutex) is not available
<a href="#">400053004</a> <a href="#">400052525</a>	Problem	ARSG4_3.07.6_F03.07	V3.00.81.18	Trigger condition not working
<a href="#">400039937</a>	Problem	ARSG4_3.07.6_F03.07	V3.00.80.25	CANIO slaves are not always found after startup
<a href="#">400055836</a>	New function	ARSG4_3.07.6_F03.07	-	PP45 could fail at low temperatures
<a href="#">400059335</a>	Problem	ARSG4_3.07.6_F03.07	-	Correction of the error in which very short and light pressure on the touch screen can cause the position to be evaluated incorrectly
<a href="#">400060899</a>	Problem	ARSG4_3.07.6_F03.07	ARSG4_3.07.4_D03.07	Due to an error in the task queue of the Modbus driver, packages that are received may no longer be allocated to the sent queries, thereby causing a connection timeout.
<a href="#">257430</a>	Problem	ARSG4_3.07.6_F03.07	ARSG4_3.01.11_K03.01	PP065 in combination with a 4PP065.IF23-1 no longer booting due to a faulty flash access after a firmware update
<a href="#">400060157</a>	Problem	ARSG4_3.07.6_F03.07	ARSG4_2.96.12_L02.96	The status BUSY can remain set for up to 120 minutes if the connection is lost when using the function block DirInfo() over a network
<a href="#">- 400047408</a> <a href="#">400049937</a>	Problem	ARSG4_3.07.5_E03.07	V3.00.81.12	Error 29009 occurs when reading the default gateway
<a href="#">- 400047408</a> <a href="#">400049937</a>	Problem	ARSG4_3.07.5_E03.07	V3.00.81.12	Error 29009 occurs when reading the default gateway
<a href="#">400051942</a>	Problem	ARSG4_3.07.5_E03.07	-	ModbusTCP doesn't start all slaves
<a href="#">400060652</a>	Problem	ARSG4_3.07.5_E03.07	ARSG4_3.07.3_C03.07	CANrwtab() returns invalid data
<a href="#">400057746</a>	Problem	ARSG4_3.07.5_E03.07	ARSG4_3.06.4_D03.06	Calling the function block CfgSetEthConfigMode() with the same mode that is already in use triggers Error 29003



<a href="#">400057746</a>	Problem	ARSG4_3.07.5_E03.07	ARSG4_3.06.4_D03.06	Calling the function block CfgSetEthConfigMode() with the same mode that is already in use triggers Error 29003
<a href="#">251317</a>	Problem	ARSG4_3.07.5_E03.07	ARSG4_3.06.22_V03.06	POWERLINK: ACOPOSmulti with SafeMC as chained station
<a href="#">400060965</a>	Problem	ARSG4_3.07.5_E03.07	ARSG4_3.06.22_V03.06	POWERLINK: ACOPOSmulti with SafeMC as chained station
<a href="#">400047724</a>	Problem	ARSG4_3.07.5_E03.07	ARSG4_3.01.9_I03.01	When multiple Ethernet interfaces are used, interference in the routing table causes Error 29004 when the function block CfgSetDefaultGateway() is called
<a href="#">400057308</a>	Problem	ARSG4_3.07.5_E03.07	ARSG4_3.01.9_I03.01	Target crashes with page fault in the web server module when an ASP write command is run from a website with more than 9 variables.
<a href="#">400048959</a>	Problem	ARSG4_3.07.5_E03.07	ARSG4_2.96.10_J02.96	ModbusTCP master doesn't work on AC141
<a href="#">400053732</a>	Problem	ARSG4_3.07.4_D03.07	V3.00.81.18	Priority of Profibus master can be configured
<a href="#">400056515</a>	Problem	ARSG4_3.07.4_D03.07	ARSG4_3.07.2_B03.07	Watchdog after CanWrite() on IF060 with IF621
<a href="#">400057340</a>	Problem	ARSG4_3.07.4_D03.07	ARSG4_3.07.2_B03.07	POWERLINK reports error 27306 when starting a visualization application
<a href="#">400057827</a>	Problem	ARSG4_3.07.4_D03.07	ARSG4_3.07.1_A03.07	Maximum number of device handles exceeded with approx. 400 safety modules
<a href="#">400053957</a>	Problem	ARSG4_3.07.4_D03.07	ARSG4_3.06.22_V03.06	Time calculation incorrect for logger entries in SDM
<a href="#">400056381</a>	Problem	ARSG4_3.07.4_D03.07	ARSG4_3.06.22_V03.06	Priority of CANopen master can be configured
<a href="#">400055214</a>	Problem	ARSG4_3.07.4_D03.07	ARSG4_3.01.8_H03.01	Using CANopenNMT() can prevent a task download from completing
<a href="#">400049979</a>	Problem	ARSG4_3.07.4_D03.07	ARSG4_3.01.7_G03.01	SDM - Update problems with dynamic page content
<a href="#">400051015</a>	Problem	ARSG4_3.07.3_C03.07	ARSG4_3.07.1_A03.07	Support for Cino F788-G barcode scanner
<a href="#">400054123</a> <a href="#">400055855</a>	Problem	ARSG4_3.07.3_C03.07	ARSG4_3.06.22_V03.06	When downloading in one cycle mode, an interrupt block can cause an I/O cycle time violation (27306)
<a href="#">400055674</a>	Problem	ARSG4_3.07.3_C03.07	ARSG4_3.06.22_V03.06	Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem
<a href="#">400054457</a>	Problem	ARSG4_3.07.3_C03.07	ARSG4_3.06.22_V03.06	CANopenSDOWriteData() terminates after downloading several hundred bytes due to a full CAN buffer
<a href="#">400055463</a>	Problem	ARSG4_3.07.3_C03.07	ARSG4_3.01.9_I03.01	CANopenSDOWrite8() only sends every second SDO
<a href="#">400053444</a>	Problem	ARSG4_3.07.3_C03.07	ARSG4_3.00.22_V03.00	Variable values sometimes displayed incorrectly on ASP pages
<a href="#">400054360</a>	Problem	ARSG4_3.07.2_B03.07	V3.00.81.20 SP01	With the function block CanOpenGetState(), when enable=FALSE the function block freezes during execution
<a href="#">400053201</a>	Problem	ARSG4_3.07.2_B03.07	ARSG4_3.06.22_V03.06	Automation Runtime boots cyclically or crashes addresses in the same subnet are assigned on both Ethernet interfaces
<a href="#">400051241</a>	Problem	ARSG4_3.07.2_B03.07	ARSG4_3.06.22_V03.06	Remanent variables are not initialized with their INIT values when the CF is regenerated and a warm restart is performed.
<a href="#">400053665</a> <a href="#">400054105</a> <a href="#">400055244</a>	Problem	ARSG4_3.07.2_B03.07	ARSG4_3.06.22_V03.06	I/O cycle time violation during startup due to initialization of graphic card
<a href="#">400054911</a>	Problem	ARSG4_3.07.2_B03.07	ARSG4_3.06.22_V03.06	Function blocks from AsXML library ignore enable input
<a href="#">400046414</a>	Problem	ARSG4_3.07.1_A03.07	ARSG4_3.06.3_C03.06	Pagefault / Memory not in heap
<a href="#">400043785</a>	Problem	ARSG4_3.07.1_A03.07	ARSG4_2.95.20_T02.95	No clear text in the error logbook when data in the SRAM is lost while shutting down
<a href="#">400046213</a>	Problem	ARSG4_3.06.5_E03.06	ARSG4_3.06.3_C03.06	EX350 modules that are configured but not connected hinder other 2005 system modules
<a href="#">400031607</a>	Problem	ARSG4_3.06.4_D03.06	ARSG4_3.06.1_A03.06	Index of Emergency COB IDs can't be overwritten
<a href="#">208190</a>	Problem	ARSG4_3.06.4_D03.06	ARSG4_3.00.12_L03.00	Size limit in the System Diagnostics Manager hardware display
<a href="#">400044495</a>	Problem	ARSG4_3.06.2_B03.06	ARSG4_3.06.1_A03.06	Logbook entry 33300 when ARsim is started in Windows 7 64-bit
<a href="#">229222</a>	Problem	ARSG4_3.06.1_A03.06	ARSG4_3.05.2_B03.05	Logbook entry ERR_DDIOPLK_WRITEPARAM 30296 showed value 0 at Offset 8 in binary data
<a href="#">400042036</a>	Problem	ARSG4_3.06.1_A03.06	ARSG4_3.00.22_V03.00	When the connection to the terminal interface IP fails, the ARwin doesn't start
<a href="#">400031708</a>	New function	ARSG4_3.05.2_B03.05	V3.00.80.22	AsArRead() supports 0 for the parameter lenBin, memBin, lenAscii and memAscii - when 0 is transferred, the respective data isn't copied
<a href="#">400039697</a>	New function	ARSG4_3.05.2_B03.05	-	New functions in ARwin console
<a href="#">400036902</a>	Problem	ARSG4_3.05.2_B03.05	ARSG4_3.00.22_V03.00	If an empty string is written to the AR OPC server, a page fault occurs
<a href="#">400024449</a>	Problem	ARSG4_3.05.1_A03.05	ARSG4_3.04.2_B03.04	Attempting to copy a directory to a subordinate directory is no longer permitted, and generates the error fiERR_INVALID_PATH
<a href="#">400038170</a>	New function	ARSG4_3.05.1_A03.05	ARSG4_3.00.22_V03.00	New AsSNMP library
<a href="#">400031184</a>	Problem	ARSG4_3.04.5_E03.04	V3.0.71.32 SP06	Memory requirements of local remanent variables when copying the PV values in Copy Mode
<a href="#">400019086</a>	Problem	ARSG4_3.04.5_E03.04	V2.7.0.0015 SP08	Newly created global variables are always initialized with 0 during download in Copy Mode instead of with the corresponding initialization value
<a href="#">400019096</a>	Problem	ARSG4_3.04.5_E03.04	V2.6.0.0012 SP02	Copy Mode supports the acceptance of structure elements starting with AR E3.04
<a href="#">400012433</a>	New function	ARSG4_3.04.4_D03.04	V3.0.71.20 SP02	New function blocks: CANopenSDOReadData(), CANopenSDOWriteData()
<a href="#">400032621</a>	Problem	ARSG4_3.04.4_D03.04	ARSG4_2.95.19_S02.95	In PIC mode, programs that change the resolution of the NT timer can reduce the network performance of the ARwin ETH interface.
<a href="#">400027971</a>	Problem	ARSG4_3.04.2_B03.04	V3.0.71.31 SP05	DirRead() reads the wrong time local time is not considered
<a href="#">400026881</a>	Problem	ARSG4_3.04.2_B03.04	ARSG4_3.00.13_M03.00	When the SemCreate() function block from the AsSem library is called with the parameter values initCount = maxCount, the function block reports the Status 33320 (semaphore could not be generated).
<a href="#">400046190</a> <a href="#">400041900</a>	Problem	ARSG4_3.01.9_I03.01	ARSG4_3.06.22_V03.06	Upgrade to AR Version E3.01 can cause the CPU to continuously reboot
<a href="#">400051264</a>	Problem	ARSG4_3.01.9_I03.01	ARSG4_3.06.22_V03.06	Static routing doesn't work with DHCP
<a href="#">400049393</a>	Problem	ARSG4_3.01.9_I03.01	ARSG4_3.01.7_G03.01	Communication places heavy load on the Terminal CPU
<a href="#">400048365</a> <a href="#">400048594</a>	Problem	ARSG4_3.01.8_H03.01	V3.00.80.31 SP01	When using the function blocks CANopenSDORead8(), CANopenSDOWrite8(), CANopenSDOReadData() and CANopenSDOWriteData() a watchdog error occurs after running for a longer period of time.
<a href="#">400046272</a>	Problem	ARSG4_3.01.8_H03.01	ARSG4_3.00.22_V03.00	Hyperthreading disturbs real-time behavior
<a href="#">400047219</a>	Problem	ARSG4_3.01.7_G03.01	V3.00.80.29 SP01	CAN exception not executed after calling CANwrite.enable = 0
<a href="#">400046758</a>	Problem	ARSG4_3.01.7_G03.01	V3.00.80.25	CANopen master sends incorrect PDO

<a href="#">235290</a>	Problem	ARSG4_3.01.7_G03.01	ARSG4_3.01.6_F03.01	Error 32244 when using 8AC114.60-2 only in NC Mapping table
<a href="#">400047305</a>	Problem	ARSG4_3.01.7_G03.01	ARSG4_3.01.5_E03.01	Empty string not permitted as attribute value
<a href="#">400047610</a>	Problem	ARSG4_3.01.7_G03.01	ARSG4_3.01.5_E03.01	Terminal variables are not updated when they are initialized after startup.
<a href="#">400046901</a>	Problem	ARSG4_3.01.7_G03.01	ARSG4_3.01.3_C03.01	CANopen system task can cause a cycle time violation, among other things
<a href="#">400041502</a> , <a href="#">400042654</a> , <a href="#">400043447</a>	Problem	ARSG4_3.01.6_F03.01	V3.00.80.25	Due to an internal AR management problem, the warning "Mutex Table Overflow" is sometimes entered in the logbook. The application program is not affected by this.
<a href="#">400046704</a>	New function	ARSG4_3.01.6_F03.01	-	After updating ARwin from < V3.00 to V3.00 or higher, the following error appears when the ARwin is started: "bradi.dll fehlt"
<a href="#">400035631</a>	New function	ARSG4_3.01.6_F03.01	-	New function blocks CANopenSDOReadData() and CANopenSDOWriteData()
<a href="#">400045366</a>	New function	ARSG4_3.01.6_F03.01	-	New AsSNMP library
<a href="#">400045929</a>	Problem	ARSG4_3.01.6_F03.01	ARSG4_3.06.2_B03.06	ARsim doesn't work on Windows XP Embedded
<a href="#">400042627</a>	Problem	ARSG4_3.01.6_F03.01	ARSG4_3.04.5_E03.04	Debugging in ARsim causes memory leak
<a href="#">400045626</a> , <a href="#">400046770</a>	Problem	ARSG4_3.01.6_F03.01	ARSG4_3.01.4_D03.01	ModbusRTU only works for one interface - simultaneous use of multiple interfaces not possible
<a href="#">400043972</a>	Problem	ARSG4_3.01.6_F03.01	ARSG4_3.00.22_V03.00	The maximum number of parallel asynchronous function block calls is limited to 15
<a href="#">400041072</a>	Problem	ARSG4_3.01.5_E03.01	V3.00.80.25	ReadPlc only reads the top two values of 4-byte values.
<a href="#">400043289</a>	Problem	ARSG4_3.01.5_E03.01	ARSG4_3.01.3_C03.01	The webserver cache mechanism doesn't test the file date - as a result, changed data isn't displayed
<a href="#">400042474</a>	Problem	ARSG4_3.01.5_E03.01	ARSG4_3.01.2_B03.01	Depending on the selected timer device, hardware detection may not be completed
<a href="#">400042115</a>	Problem	ARSG4_3.01.5_E03.01	ARSG4_3.00.22_V03.00	Error 28826 when calling the AsL2DP function block with Max_Module > 10 and S7 Profibus
<a href="#">400041949</a> , <a href="#">400043852</a>	Problem	ARSG4_3.01.5_E03.01	ARSG4_3.00.1_A03.00	When there is a task overload, CANrwtab() doesn't work anymore
<a href="#">400041484</a>	Problem	ARSG4_3.01.4_D03.01	V3.00.80.25	INA routing via POWERLINK doesn't work
<a href="#">400028201</a>	New function	ARSG4_3.01.4_D03.01	V3.0.71.31 SP05	Running a DEVLink() or DEVUnlink() from ARwin on a directory shared in Windows (CIFS) can take up to 30 seconds
<a href="#">400033999</a>	Problem	ARSG4_3.01.4_D03.01	V2.7.0.0019 SP12	Memory leak due to cyclic DevLink() / DevUnlink()
<a href="#">400041569</a>	Problem	ARSG4_3.01.4_D03.01	ARSG4_3.01.2_B03.01	Trace is stopped when the configuration is changed or if the AS connection is lost
<a href="#">400041545</a>	Problem	ARSG4_3.01.4_D03.01	ARSG4_3.01.2_B03.01	On ARsim, calling DirCreate() a second time with the same directory name does not report status 20725, but rather 20709
<a href="#">400037131</a>	Problem	ARSG4_3.01.4_D03.01	ARSG4_3.01.2_B03.01	Receiving a DHCP offer package with the option 81 causes page fault
<a href="#">400041193</a>	Problem	ARSG4_3.01.4_D03.01	ARSG4_3.01.1_A03.01	As soon as a website is accessed that is either write-protected itself or that is inside a write-protected folder, the CPU crashes with a page fault.
<a href="#">400041999</a>	Problem	ARSG4_3.01.4_D03.01	ARSG4_3.00.22_V03.00	Running a DEVLink() or DEVUnlink() from ARwin on a directory shared in Windows (CIFS) can take up to 30 seconds
<a href="#">400039603</a>	Problem	ARSG4_3.01.4_D03.01	ARSG4_3.00.22_V03.00	INA routing via POWERLINK doesn't work
<a href="#">400041410</a>	Problem	ARSG4_3.01.3_C03.01	V3.00.80.25	PDOs and SDOs get lost when using the AsCANopen library and when there is a heavy load on the CPU
<a href="#">400040238</a>	Problem	ARSG4_3.01.3_C03.01	V3.00.80.25	AsIOAccWrite() doesn't work for ACOPOSinverter modules on the Modbus (call BUSY)
<a href="#">400038693</a>	Problem	ARSG4_3.01.3_C03.01	V3.00.80.25	Parameter transfer for "webprint" function doesn't work with AR 3.00 and up. String cut off after "="
<a href="#">400040658</a>	Problem	ARSG4_3.01.3_C03.01	ARSG4_3.01.2_B03.01	When connecting from the server to the client, the client freezes in the step "IMA_CONNECTING"
<a href="#">400039214</a>	Problem	ARSG4_3.01.3_C03.01	ARSG4_3.01.1_A03.01	Because of an internal timing error, the system clock is executed too often, which causes the ARsim to run "too fast"
<a href="#">225099</a>	Problem	ARSG4_3.01.3_C03.01	ARSG4_3.00.22_V03.00	Mapping PVs to I/O is not updated during task overload
<a href="#">400039303</a>	Problem	ARSG4_3.01.3_C03.01	ARSG4_3.00.22_V03.00	POWERLINK: SDO communication interrupted
<a href="#">400038150</a> , <a href="#">400037974</a>	Problem	ARSG4_3.01.3_C03.01	ARSG4_3.00.22_V03.00	AR OPC server doesn't work on ARwin
<a href="#">400036980</a>	Problem	ARSG4_3.01.2_B03.01	V3.00.80.25	Due to an error calculating the offset, I/O channels are not applied with the setting "Mapping = Channels"
<a href="#">400036104</a>	Problem	ARSG4_3.01.2_B03.01	V3.00.80.25	VC4 > Terminal Mode > Operating the visualization with AS3.00.80 considerably slower than in earlier versions
<a href="#">400036153</a>	Problem	ARSG4_3.01.2_B03.01	ARSG4_3.00.22_V03.00	Using three 5LS182.6-1 in an APC results in the error 32173 "POWERLINK V2: Bind failed".
<a href="#">400037264</a>	Problem	ARSG4_3.01.2_B03.01	ARSG4_3.00.22_V03.00	Task overload causes memory leak
<a href="#">400035047</a> , <a href="#">400036404</a>	Problem	ARSG4_3.01.2_B03.01	ARSG4_3.00.22_V03.00	If a breakpoint is reached in the INIT SP, then it is no longer possible to leave the breakpoint. Execute (F5), Step Over (F10) or Step Into (F11) do not have an affect.
<a href="#">400033456</a>	Problem	ARSG4_3.01.2_B03.01	ARSG4_3.00.22_V03.00	Value changes to enumerations are not displayed on the terminal
<a href="#">400032324</a>	Problem	ARSG4_3.01.2_B03.01	ARSG4_3.00.22_V03.00	The AR OPC server can only be accessed via the first Ethernet interface on the target system.
<a href="#">400029923</a> , <a href="#">400037586</a>	Problem	ARSG4_3.01.2_B03.01	ARSG4_3.00.14_N03.00	Web server doesn't work on User Partition (F:)
<a href="#">257435</a>	Problem	ARSG4_3.01.12_L03.01	ARSG4_3.01.11_K03.01	PP065 in combination with a 4PP065.IF23-1 no longer booting due to a faulty flash access after a firmware update
<a href="#">400053447</a>	Problem	ARSG4_3.01.11_K03.01	V3.00.81.20 SP01	In some circumstances, the watchdog may be triggered during debugging because a required system resource (Mutex) is not available
<a href="#">400051942</a>	Problem	ARSG4_3.01.11_K03.01	-	ModbusTCP doesn't start all slaves
<a href="#">400059335</a>	Problem	ARSG4_3.01.11_K03.01	-	Correction of the error in which very short and light pressure on the touch screen can cause the position to be evaluated incorrectly
<a href="#">400060899</a>	Problem	ARSG4_3.01.11_K03.01	ARSG4_3.07.4_D03.07	Due to an error in the task queue of the Modbus driver, packages that are received may no longer be allocated to the sent queries, thereby causing a connection timeout.
<a href="#">400048959</a>	Problem	ARSG4_3.01.11_K03.01	ARSG4_2.96.10_J02.96	ModbusTCP master doesn't work on AC141

<a href="#">400053325</a>	Problem	ARSG4_3.01.10_J03.01	V3.00.80.25	The maximum length for the device name when calling DevLink() on ARsim targets has been increased from 128 characters to 256 characters.
<a href="#">400051561</a>	Problem	ARSG4_3.01.10_J03.01	ARSG4_3.06.22_V03.06	Querying whether hyperthreading is active does not work reliably
<a href="#">400055463</a>	Problem	ARSG4_3.01.10_J03.01	ARSG4_3.01.9_I03.01	CANopenSDOWrite8() only sends every second SDO
<a href="#">400052797</a> <a href="#">400048509</a>	Problem	ARSG4_3.01.10_J03.01	ARSG4_3.00.22_V03.00	After changing the ARwin IP address using the configurator, the online connection can no longer be established.
<a href="#">400051798</a>	Problem	ARSG4_3.01.10_J03.01	ARSG4_3.00.22_V03.00	ModuleOk detections sometimes takes very long for S44
<a href="#">400044951</a>	Problem	ARSG4_3.01.1_A03.01	ARSG4_3.01.1_A03.01	Page fault caused by AsIOAccWrite on local X2X bus
<a href="#">400030615</a>	Problem	ARSG4_3.01.1_A03.01	ARSG4_3.00.22_V03.00	Client doesn't read all PVs, reads incorrect values or no values at all.
<a href="#">400045098</a>	Problem	ARSG4_2.96.9_I02.96	ARSG4_2.96.9_I02.96	PP065: If a device is operated at low temperatures, the background lighting remains dark.
<a href="#">225792</a>	Problem	ARSG4_2.96.9_I02.96	ARSG4_2.96.7_G02.96	Variables with data types other than SINT and USINT can now be connected to OCTET data points
<a href="#">400039483</a> <a href="#">400040973</a>	Problem	ARSG4_2.96.9_I02.96	ARSG4_2.96.6_F02.96	When connecting from the server to the client, the client freezes in the step "IMA_CONNECTING"
<a href="#">400033779</a> <a href="#">400048786</a>	Problem	ARSG4_2.96.9_I02.96	ARSG4_2.95.22_V02.95	ARwin Setup doesn't update the interface driver for APC820
<a href="#">400040510</a> <a href="#">400040224</a> <a href="#">400040220</a>	Problem	ARSG4_2.96.8_H02.96	ARSG4_3.00.22_V03.00	Some USB flash drives don't work in Automation Runtime
<a href="#">400033130</a>	Problem	ARSG4_2.96.8_H02.96	ARSG4_2.96.3_C02.96	Using the debugger can cause cycle time violations
<a href="#">400038343</a> <a href="#">400039888</a> <a href="#">400040075</a>	Problem	ARSG4_2.96.8_H02.96	ARSG4_2.96.1_A02.96	PP45 reports the wrong Module ID
<a href="#">206455</a>	Problem	ARSG4_2.96.7_G02.96	ARSG4_3.00.11_K03.00	EX450 modules sporadically won't start - "No ReadyFlag from Interface"
<a href="#">400028102</a>	Problem	ARSG4_2.96.6_F02.96	ARSG4_2.95.19_S02.95	Higher priority for AsUDP
<a href="#">400028038</a>	Problem	ARSG4_2.96.5_E02.96	V2.7.0.0017 SP10	29-bit CAN ID when using the X20CS1070 causes an error when calling CANopen()
<a href="#">218739</a>	Problem	ARSG4_2.96.5_E02.96	ARSG4_2.96.3_C02.96	High resource load for INA Client connection with no peer station (server)
<a href="#">400021425</a>	Problem	ARSG4_2.96.5_E02.96	ARSG4_2.95.2_B02.95	Stack overflow on the DHCP server causes PageFault
<a href="#">400029507</a>	Problem	ARSG4_2.96.4_D02.96	V3.00.80.20	NonVolatile option doesn't work with CfgSetEthConfigMode() function block
<a href="#">400022378</a> <a href="#">400024266</a> <a href="#">400024392</a> <a href="#">400024391</a> <a href="#">400024462</a> <a href="#">400025270</a> <a href="#">400026541</a> <a href="#">400031748</a> <a href="#">400032414</a> <a href="#">400034127</a>	Problem	ARSG4_2.96.4_D02.96	V3.0.71.28 SP05	ACOPOSinverter X64 frequency inverter is sometimes not started correctly when turned off and turned back on. The CANopen slave doesn't go into operational mode.
<a href="#">400032504</a> <a href="#">400033988</a>	Problem	ARSG4_2.96.4_D02.96	-	High resource load for CANopen system task
<a href="#">400031304</a>	Problem	ARSG4_2.96.4_D02.96	-	Error during slave configuration
<a href="#">400034627</a> <a href="#">400034661</a>	New function	ARSG4_2.96.4_D02.96	-	Long boot time when many modules are configured that are not connected
<a href="#">400032367</a>	Problem	ARSG4_2.96.4_D02.96	ARSG4_2.96.2_B02.96	Node guarding fails temporarily
<a href="#">216445</a>	Problem	ARSG4_2.96.4_D02.96	ARSG4_2.96.1_A02.96	Not enough time between frames on the X2X Link bus
<a href="#">400020057</a>	Problem	ARSG4_2.96.4_D02.96	ARSG4_2.95.12_L02.95	Activating "Module monitoring" when using an X20BC0063 causes the controller to go into Service mode when booting
<a href="#">400031906</a> <a href="#">400022988</a> <a href="#">400026463</a>	Problem	ARSG4_2.96.3_C02.96	V3.0.71.31 SP05	AsArLogRead() provides incorrect time
<a href="#">400031340</a>	Problem	ARSG4_2.96.3_C02.96	-	ARwin boot not complete
<a href="#">400021790</a>	Problem	ARSG4_2.96.3_C02.96	-	Commands are lost due to faulty socket connection
<a href="#">400031454</a> <a href="#">400030919</a>	New function	ARSG4_2.96.3_C02.96	-	Changes to the ARwin installation procedure
<a href="#">400031784</a>	Problem	ARSG4_2.96.3_C02.96	ARSG4_2.96.1_A02.96	Sometimes the ARwin takes a long time to boot
<a href="#">400030593</a>	Problem	ARSG4_2.96.2_B02.96	ARSG4_2.95.22_V02.95	Cycle time violation caused by CANwrite()
<a href="#">400030026</a>	Problem	ARSG4_2.96.2_B02.96	ARSG4_2.95.21_U02.95	Because of a system stack that is configured too small, error 9101 can occur on the ARsim
<a href="#">400029925</a>	Problem	ARSG4_2.96.2_B02.96	ARSG4_2.95.21_U02.95	The exception routine is not called correctly if multiple cycle time violations occur
<a href="#">400027276</a>	Problem	ARSG4_2.96.2_B02.96	ARSG4_2.95.19_S02.95	Profibus master sends the wrong ident in the config frame
<a href="#">400023079</a>	Problem	ARSG4_2.96.2_B02.96	ARSG4_2.95.19_S02.95	Terminal mode: With a string length of 1024 or larger, the string is no longer transferred correctly
<a href="#">257680</a>	Problem	ARSG4_2.96.14_N02.96	ARSG4_3.01.11_K03.01	PP065 in combination with a 4PP065.IF23-1 no longer booting due to a faulty flash access after a firmware update
<a href="#">400059335</a>	Problem	ARSG4_2.96.13_M02.96	-	Correction of the error in which very short and light pressure on the touch screen can cause the position to be evaluated incorrectly
<a href="#">400060157</a>	Problem	ARSG4_2.96.13_M02.96	ARSG4_2.96.12_L02.96	The status BUSY can remain set for up to 120 minutes if the connection is lost when using the function block DirInfo() over a network
<a href="#">400048959</a>	Problem	ARSG4_2.96.13_M02.96	ARSG4_2.96.10_J02.96	ModbusTCP master doesn't work on AC141
<a href="#">400044001</a>	New function	ARSG4_2.96.12_L02.96	-	Remote install causes Warning 27058 "NV memory block cannot be backed up"
<a href="#">400049163</a>	Problem	ARSG4_2.96.12_L02.96	ARSG4_2.95.18_R02.95	PnP resources are sometimes not recognized during startup
<a href="#">400048831</a>	Problem	ARSG4_2.96.11_K02.96	ARSG4_3.01.4_D03.01	System clock doubled when using the LS172 as a timer device
<a href="#">400028877</a> <a href="#">400038632</a>	Problem	ARSG4_2.96.11_K02.96	ARSG4_2.95.5_E02.95	ST_name() doesn't return task names in the EXIT
	Problem	ARSG4_2.96.10_J02.96	ARSG4_3.01.4_D03.01	



<a href="#">400045867</a> <a href="#">400045710</a>				CANOpen master sporadically returns incorrect slave node status or incorrect ModuleOK status
<a href="#">400034964</a> <a href="#">400034661</a>	New function	ARSG4_2.96.10_J02.96	ARSG4_3.00.22_V03.00	Modules that are configured downstream from the POWERLINK X2X controller but not physically present make the controller take longer to boot.
<a href="#">400028109</a>	Problem	ARSG4_2.96.1_A02.96	ARSG4_2.95.20_T02.95	CanQurw() sporadically delivers status 8810
<a href="#">400025215</a>	Problem	ARSG4_2.95.20_T02.95	V3.0.71.30 SP05	INA routing via POWERLINK sometimes doesn't work because timeout times too low

**1A4000.02 Visual Components**

ID	valuation	solved since	known since	Description
<a href="#">400043532</a>	Problem	ARSG4_3.06.5_E03.06	VC 3.64.0	On ARsim, after approx. 2000 calls, VA_GetAlarmList only returns BUSY 247
<a href="#">400017783</a>	Problem	ARSG4_2.95.17_Q02.95	V2.6.0.0007	Calibration lost after restart
<a href="#">400013764</a>	Problem	ARSG4_2.95.15_O02.95	-	PageFault when executing AsRfbExt functions without preceding RfbExtInit

**1A4300.02 (1.0 Automation Studio 3.x)**

ID	valuation	solved since	known since	Description
<a href="#">400062152</a>	Problem	ARSG4_3.07.3_C03.07	V3.00.81.24 SP0x	Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem

**Requests and problems by product/component****1A4000.02 Visual Components****SG4 Runtime - Alarmsystem**

ID#400043532 : solved problem, known since VC 3.64.0, solved since ARSG4\_3.06.5\_E03.06

On ARsim, after approx. 2000 calls, VA\_GetAlarmList only returns BUSY 247

**SG4 Runtime - Common**

ID#400017783 : solved problem, known since V2.6.0.0007, solved since ARSG4\_2.95.17\_Q02.95

Calibration lost after restart

Calibration must be carried out after each restart, since the calibration data isn't saved.

ID#400013764 : solved problem, known since unbekannt, solved since ARSG4\_2.95.15\_O02.95

PageFault when executing AsRfbExt functions without preceding RfbExtInit

**1A4000.02 (2.0 Automation Runtime SG4)****AR - ARemb**

ID#400053201 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.2\_B03.07

Automation Runtime boots cyclically or crashes addresses in the same subnet are assigned on both Ethernet interfaces

ID#400036153 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.01.2\_B03.01

Using three 5LS182.6-1 in an APC results in the error 32173 "POWERLINK V2: Bind failed".

**AR - ARsim**

ID#400062877 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.9\_I03.08

Remanent/permanent variables not saved when exiting ARsim

ID#400045929 : solved problem, known since ARSG4\_3.06.2\_B03.06, solved since ARSG4\_3.01.6\_F03.01

ARsim doesn't work on Windows XP Embedded

ID#400044495 : solved problem, known since ARSG4\_3.06.1\_A03.06, solved since ARSG4\_3.06.2\_B03.06

Logbook entry 33300 when ARsim is started in Windows 7 64-bit

ID#400042627 : solved problem, known since ARSG4\_3.04.5\_E03.04, solved since ARSG4\_3.01.6\_F03.01

Debugging in ARsim causes memory leak

ID#400039214 : solved problem, known since ARSG4\_3.01.1\_A03.01, solved since ARSG4\_3.01.3\_C03.01

Because of an internal timing error, the system clock is executed too often, which causes the ARsim to run "too fast"

ID#400030026 : solved problem, known since ARSG4\_2.95.21\_U02.95, solved since ARSG4\_2.96.2\_B02.96

Because of a system stack that is configured too small, error 9101 can occur on the ARsim

ID#400055446 : known problem since V2.7.0.0015 SP08, correction planned for ARSG4\_3.07.3\_C03.07

Address error occurs when a breakpoint is reached on a command that is 1 byte long

ID#400055446 : known problem since V2.7.0.0015 SP08, correction planned for ARSG4\_3.08.4\_D03.08

Address error occurs when a breakpoint is reached on a command that is 1 byte long

#### AR - ARwin

ID#400065938 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.08.15\_O03.08

c command line argument in the ARwin configuration disables not only the COM2 interface but also COM1.

ID#400065540 : solved problem, known since V3.00.81.24 SP0x, solved since ARSG4\_3.08.12\_L03.08

ARwin shows incorrect amount of available DRAM memory in SDM

ID#400066313 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.8\_H03.07

If, for example, the X2X timer is used as the system clock, then remanent variables aren't saved when there is a power failure

ID#400066313 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.11\_K03.08

If, for example, the X2X timer is used as the system clock, then remanent variables aren't saved when there is a power failure

ID#400057456 : solved problem, known since ARSG4\_3.01.7\_G03.01, solved since ARSG4\_3.07.8\_H03.07

Update to ARwin configurator

It is now possible to set the broadcast address and the subnet mask.

ID#400058774 : solved problem, known since ARSG4\_3.08.4\_D03.08, solved since ARSG4\_3.08.8\_H03.08

Incorrect version of rtosdrv.dll

If an APC with 16 interrupts (PIC types) is used as the target platform, e.g. an APC620 with an E855 board, there are problems with setup and when upgrading via AS. This is caused by incorrect versions of the dlls and driver involved.

ID#400058774 : solved problem, known since ARSG4\_3.08.4\_D03.08, solved since ARSG4\_3.08.7\_G03.08

Incorrect version of rtosdrv.dll

If an APC with 16 interrupts (PIC types) is used as the target platform, e.g. an APC620 with an E855 board, there are problems with setup and when upgrading via AS. This is caused by incorrect versions of the dlls and driver involved.

ID#400058774 : solved problem, known since ARSG4\_3.08.4\_D03.08, solved since ARSG4\_3.08.6\_F03.08

Incorrect version of rtosdrv.dll

If an APC with 16 interrupts (PIC types) is used as the target platform, e.g. an APC620 with an E855 board, there are problems with setup and when upgrading via AS. This is caused by incorrect versions of the dlls and driver involved.

ID# 400052797, 400048509 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.01.10\_J03.01

After changing the ARwin IP address using the configurator, the online connection can no longer be established.

ID#400051561 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.01.10\_J03.01

Querying whether hyperthreading is active does not work reliably

ID#400049163 : solved problem, known since ARSG4\_2.95.18\_R02.95, solved since ARSG4\_2.96.12\_L02.96

PnP resources are sometimes not recognized during startup

ID#400046272 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.01.8\_H03.01

Hyperthreading disturbs real-time behavior

ID#400042036 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.06.1\_A03.06

When the connection to the terminal interface IP fails, the ARwin doesn't start

ID#400041999 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.01.4\_D03.01

Running a DEVLink() or DEVUnlink() from ARwin on a directory shared in Windows (CIFS) can take up to 30 seconds

ID#400032621 : solved problem, known since ARSG4\_2.95.19\_S02.95, solved since ARSG4\_3.04.4\_D03.04

In PIC mode, programs that change the resolution of the NT timer can reduce the network performance of the ARwin ETH interface.

ID# 400033779, 400048786 : solved problem, known since ARSG4\_2.95.22\_V02.95, solved since ARSG4\_2.96.9\_I02.96

ARwin Setup doesn't update the interface driver for APC820

ID#400031784 : solved problem, known since ARSG4\_2.96.1\_A02.96, solved since ARSG4\_2.96.3\_C02.96

Sometimes the ARwin takes a long time to boot

ID#400031340 : solved problem, known since unbekannt, solved since ARSG4\_2.96.3\_C02.96

ARwin boot not complete

Due to a problem in the socket connection between the ARwin and the loader, the ARwin doesn't finish booting.

ID#400021790 : solved problem, known since unbekannt, solved since ARSG4\_2.96.3\_C02.96

Commands are lost due to faulty socket connection

If the ARwin is closed using the tool ar010end.exe, the APC sometimes reboots. The reason for this is that the command for shutting down doesn't reach the ARwin due to a damaged socket connection.

ID#400046704 : new function since ARSG4\_3.01.6\_F03.01

After updating ARwin from < V3.00 to V3.00 or higher, the following error appears when the ARwin is started: "bradi.dll fehlt"

ID#400039697 : new function since ARSG4\_3.05.2\_B03.05

New functions in ARwin console

The ARwin console now also provides the switches "Warmstart", "Coldstart" and "Service".

ID# 400031454, 400030919 : new function since ARSG4\_2.96.3\_C02.96

Changes to the ARwin installation procedure

Prevention of sporadic errors (e.g. missing drivers) during installation by changing the order of installation.

ID#400069705 : known problem since ARSG4\_3.07.5\_E03.07, correction planned for ARSG4\_3.07.11\_K03.07

Backup of remanent data to SRAM doesn't complete if ARwin is operated in Shared mode.

Solution: Use Exclusive mode

ID#400069705 : known problem since ARSG4\_3.07.5\_E03.07, correction planned for ARSG4\_3.09.1\_A03.09

Backup of remanent data to SRAM doesn't complete if ARwin is operated in Shared mode.

Solution: Use Exclusive mode

#### AR - General SG4

ID#400062576 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.07.7\_G03.07

Error handling SYSCONF module in SYSROM

ID#400062152 : solved problem, known since V3.00.81.24 SP0x, solved since ARSG4\_3.08.4\_D03.08

Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem

ID#400062576 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.08.10\_J03.08

Error handling SYSCONF module in SYSROM

ID#400054674 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.08.9\_I03.08

Module transfer to target not saved if there is not sufficient memory in the back-up partition.

If storage space runs out while writing the back-up copy of a .br module (to the back-up partition), then both files (original and back-up copy) will remain on the CF, but the module in the back-up copy will be incomplete. An error will not be reported in this case. This doesn't cause any problems until the "healthy" file in the first partition is restored using the incomplete module from the second partition. A checksum error for the .br module will now be detected.

ID#400056892 : solved problem, known since V3.00.81.22 SP01, solved since ARSG4\_3.08.6\_F03.08

If the requested bur\_heap\_size (C++) is too large, the installation error ERR\_LOADER\_USERHEAP (5150) is now triggered

ID#400056515 : solved problem, known since ARSG4\_3.07.2\_B03.07, solved since ARSG4\_3.07.4\_D03.07

Watchdog after CanWrite() on IF060 with IF621

Initialization problems in the CAN IRQ routine can prevent IRQs from being acknowledged and trigger a watchdog error.

ID#400056515 : solved problem, known since ARSG4\_3.07.2\_B03.07, solved since ARSG4\_3.08.6\_F03.08

Watchdog after CanWrite() on IF060 with IF621

Initialization problems in the CAN IRQ routine can prevent IRQs from being acknowledged and trigger a watchdog error.

ID# 400054123, 400055855 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.3\_C03.07

When downloading in one cycle mode, an interrupt block can cause an I/O cycle time violation (27306)

ID# 400054123, 400055855 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.6\_F03.08

When downloading in one cycle mode, an interrupt block can cause an I/O cycle time violation (27306)

ID#400055674 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.4\_D03.08

Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem

ID#400055674 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.3\_C03.07

Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem

ID# 400046190, 400041900 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.01.9\_I03.01

Upgrade to AR Version E3.01 can cause the CPU to continuously reboot

ID#400051241 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.2\_B03.07

Remanent variables are not initialized with their INIT values when the CF is regenerated and a warm restart is performed.

ID# 400046190, 400041900 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.6\_F03.08

Upgrade to AR Version E3.01 can cause the CPU to continuously reboot

ID#400043785 : solved problem, known since ARSG4\_2.95.20\_T02.95, solved since ARSG4\_3.07.1\_A03.07

No clear text in the error logbook when data in the SRAM is lost while shutting down

ID# 400041949, 400043852 : solved problem, known since ARSG4\_3.00.1\_A03.00, solved since ARSG4\_3.01.5\_E03.01

When there is a task overload, CANrwtab() doesn't work anymore

ID# 400041502, 400042654, 400043447 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.01.6\_F03.01

Due to an internal AR management problem, the warning "Mutex Table Overflow" is sometimes entered in the logbook. The application program is not affected by this.

ID#400037264 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.01.2\_B03.01

Task overload causes memory leak

If a task is overloaded, an incorrect implementation in the variable check results in a memory leak.

ID#400031184 : solved problem, known since V3.0.71.32 SP06, solved since ARSG4\_3.04.5\_E03.04

Memory requirements of local remanent variables when copying the PV values in Copy Mode

Twice as much PV memory is required to copy the variable values of remanent local PVs in Copy Mode because the old and the new memory areas are in use during the copy procedure.

ID#400029925 : solved problem, known since ARSG4\_2.95.21\_U02.95, solved since ARSG4\_2.96.2\_B02.96

The exception routine is not called correctly if multiple cycle time violations occur

If multiple cycle time violations occur in quick succession, it's possible that the corresponding exception routine is not called as often as the cycle time violations occur.

ID#400028102 : solved problem, known since ARSG4\_2.95.19\_S02.95, solved since ARSG4\_2.96.6\_F02.96

Higher priority for AsUDP

To reduce interruptions in the handling of UDP packages, the priority has been increased for the AsUDP library.

ID#400019086 : solved problem, known since V2.7.0.0015 SP08, solved since ARSG4\_3.04.5\_E03.04

Newly created global variables are always initialized with 0 during download in Copy Mode instead of with the corresponding initialization value

ID# 400019096 : solved problem, known since V2.6.0.0012 SP02, solved since ARSG4\_3.04.5\_E03.04

Copy Mode supports the acceptance of structure elements starting with AR E3.04

ID# 400002467, 400058853, 400058855 : new function since ARSG4\_3.08.7\_G03.08

Task class stack can only be configured up to a size of 1MB.

ID#400066308 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_3.07.10\_J03.07

Error copying CAN CMS objects

Data is copied byte-wise from the CMS object to the PVs, although the target PVs may have data types larger than one byte.

ID#400055674 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_3.08.4\_D03.08

Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem

ID# 400046190, 400041900 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_3.07.11\_K03.07

Upgrade to AR Version E3.01 can cause the CPU to continuously reboot

ID#400005281 : known problem since ARSG4\_2.94.22\_V02.94, correction planned for ARSG4\_3.08.2\_B03.08

INA online connection to X20CS1020 stops working when the modem configuration is also activated

#### AR - PP45

ID#400055836 : new function since ARSG4\_3.07.6\_F03.07

PP45 could fail at low temperatures

Low temperatures can cause a timer on the CPU to stop running. This problem can only be corrected by resetting the timer.

ID#400055836 : new function since ARSG4\_3.08.8\_H03.08

PP45 could fail at low temperatures

Low temperatures can cause a timer on the CPU to stop running. This problem can only be corrected by resetting the timer.

ID#400055836 : new function planned for ARSG4\_2.96.13\_M02.96

PP45 could fail at low temperatures

Low temperatures can cause a timer on the CPU to stop running. This problem can only be corrected by resetting the timer.

ID#400055836 : new function planned for ARSG4\_3.01.11\_K03.01

PP45 could fail at low temperatures

Low temperatures can cause a timer on the CPU to stop running. This problem can only be corrected by resetting the timer.

### Diagnose - Debugger

ID#400053447 : solved problem, known since V3.00.81.20 SP01, solved since ARSG4\_3.07.6\_F03.07

In some circumstances, the watchdog may be triggered during debugging because a required system resource (Mutex) is not available

ID#400053447 : solved problem, known since V3.00.81.20 SP01, solved since ARSG4\_3.01.11\_K03.01

In some circumstances, the watchdog may be triggered during debugging because a required system resource (Mutex) is not available

ID#400037524 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.08.3\_C03.08

Error "9098 - System I/O cross-link task cycle time violation" is generated when a SafePLC and standard PLC are linked and a breakpoint is set on the standard PLC.

ID# 400035047, 400036404 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.01.2\_B03.01

If a breakpoint is reached in the INIT SP, then it is no longer possible to leave the breakpoint. Execute (F5), Step Over (F10) or Step Into (F11) do not have an affect.

ID#400033130 : solved problem, known since ARSG4\_2.96.3\_C02.96, solved since ARSG4\_2.96.8\_H02.96

Using the debugger can cause cycle time violations

Nested calls (e.g. calling the function CANexcept() to start an exception task) causes a cycle time violation due to an error in the handling of cycle time monitoring.

ID#400054111 : known problem since ARSG4\_3.01.9\_I03.01, correction planned for ARSG4\_3.01.11\_K03.01

Debugger terminates online connection

If application data is being exchanged with a target system via Ethernet, and a breakpoint is reached, all Ethernet buffers are used up (since the data is no longer picked up) and Ethernet communication is terminated. It is also no longer possible to establish an online connection.

ID#400054111 : known problem since ARSG4\_3.01.9\_I03.01, correction planned for ARSG4\_3.07.4\_D03.07

Debugger terminates online connection

If application data is being exchanged with a target system via Ethernet, and a breakpoint is reached, all Ethernet buffers are used up (since the data is no longer picked up) and Ethernet communication is terminated. It is also no longer possible to establish an online connection.

ID#400054111 : known problem since ARSG4\_3.01.9\_I03.01, correction planned for ARSG4\_3.08.5\_E03.08

Debugger terminates online connection

If application data is being exchanged with a target system via Ethernet, and a breakpoint is reached, all Ethernet buffers are used up (since the data is no longer picked up) and Ethernet communication is terminated. It is also no longer possible to establish an online connection.

### Diagnose - Logger

ID#400057809 : solved problem, known since , solved since ARSG4\_3.08.6\_F03.08

Using logger functions in fast task classes can lead to cycle time violations

Due to the copying required, using logger functions in fast task classes can lead to cycle time violations.

### Diagnose - SDM

ID#400065562 : solved problem, known since ARSG4\_3.07.6\_F03.07, solved since ARSG4\_3.07.7\_G03.07

SDM 1 (Automation Studio 3.0.80) doesn't work with Firefox 4.0 and higher



The first version of the System Diagnostics Manager (SDM), delivered with Automation Studio 3.00.80 / 3.00.81 doesn't work correctly with Firefox version 4.0 or higher.  
Customers who use Firefox 4.0 or higher need to switch to SDM 2, provided with Automation Studio 3.00.90.

ID#400053957 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.4\_D03.07

Time calculation incorrect for logger entries in SDM

When time zones were used, calculation of the local time for logger entries in SDM was incorrect. This has been corrected.

ID#400053957 : solved problem, known since unbekannt, solved since ARSG4\_3.08.5\_E03.08

Time calculation incorrect for logger entries in SDM

When time zones were used, calculation of the local time for logger entries in SDM was incorrect. This has been corrected.

ID#208190 : solved problem, known since ARSG4\_3.00.12\_L03.00, solved since ARSG4\_3.06.4\_D03.06

Size limit in the System Diagnostics Manager hardware display

With bigger systems (over 1000 nodes), the hardware tree in the browser doesn't work.  
In this case, the contents of the XML file, which can be loaded from the SDM using the browser are incorrect.

ID#400013287 : new function since ARSG4\_3.08.9\_I03.08

Use the Diagnostics System Manager to list modules' diagnostics data points

The System Diagnostics Manager can be used to save all of a module's diagnostic data points in a system dump.

### Diagnose - Tracer

ID# 400053004, 400052525 : solved problem, known since V3.00.81.18, solved since ARSG4\_3.07.6\_F03.07

Trigger condition not working

If a trace with trigger condition is installed in the trace editor, then the trace will begin after the defined trigger event and automatically stop as soon as the buffer is full. If the trace is started again using the "Trace / Start" option in the main menu, the Start option in the shortcut menu or the "green traffic light" button, then the trace will be extremely slow or will not be started correctly.

ID# 400053004, 400052525 : solved problem, known since V3.00.81.18, solved since ARSG4\_3.08.8\_H03.08

Trigger condition not working

If a trace with trigger condition is installed in the trace editor, then the trace will begin after the defined trigger event and automatically stop as soon as the buffer is full. If the trace is started again using the "Trace / Start" option in the main menu, the Start option in the shortcut menu or the "green traffic light" button, then the trace will be extremely slow or will not be started correctly.

ID#400041569 : solved problem, known since ARSG4\_3.01.2\_B03.01, solved since ARSG4\_3.01.4\_D03.01

Trace is stopped when the configuration is changed or if the AS connection is lost

### IO System - 2003 Backplane

ID#400066089 : known problem since V2.7.0.4102 [V2.94], correction planned for ARSG4\_2.96.16\_P02.96

30479, 27306 when starting 7CP570.60-1 with four AF modules

When a fourth 7AF101.7 module with some free connections and five 7DM465.7 modules were connected to a 7AF101.7 module with three 7AF101.7 modules with no free connections, then turning on the analog module connected to the fourth 7AF101.7 caused a timeout, and Error 30479 was entered in the logbook. Then the AR resets the firmware of the 2003 backplane, and there is an I/O cycle time violation (27306). The timeout was set to low for this configuration and has been increased accordingly in the current version of AR.

ID#400066089 : known problem since V2.7.0.4102 [V2.94], correction planned for ARSG4\_3.01.13\_M03.01

30479, 27306 when starting 7CP570.60-1 with four AF modules

When a fourth 7AF101.7 module with some free connections and five 7DM465.7 modules were connected to a 7AF101.7 module with three 7AF101.7 modules with no free connections, then turning on the analog module connected to the fourth 7AF101.7 caused a timeout, and Error 30479 was entered in the logbook. Then the AR resets the firmware of the 2003 backplane, and there is an I/O cycle time violation (27306). The timeout was set to low for this configuration and has been increased accordingly in the current version of AR.

ID#400066089 : known problem since V2.7.0.4102 [V2.94], correction planned for ARSG4\_3.07.11\_K03.07

30479, 27306 when starting 7CP570.60-1 with four AF modules

When a fourth 7AF101.7 module with some free connections and five 7DM465.7 modules were connected to a 7AF101.7 module with three 7AF101.7 modules with no free connections, then turning on the analog module connected to the fourth 7AF101.7 caused a timeout, and Error 30479 was entered in the logbook. Then the AR resets the firmware of the 2003 backplane, and there is an I/O cycle time violation (27306). The timeout was set to low for this configuration and has been increased accordingly in the current version of AR.

ID#400066089 : known problem since V2.7.0.4102 [V2.94], correction planned for ARSG4\_3.09.1\_A03.09

30479, 27306 when starting 7CP570.60-1 with four AF modules

When a fourth 7AF101.7 module with some free connections and five 7DM465.7 modules were connected to a 7AF101.7 module with three 7AF101.7 modules with no free connections, then turning on the analog module connected to the fourth 7AF101.7 caused a timeout, and Error 30479 was entered in the logbook. Then the AR resets the firmware of the 2003 backplane, and there is an I/O cycle time violation (27306). The timeout was set to low for this configuration and has been increased accordingly in the current version of AR.

#### IO System - 2005 Backplane

ID#400046213 : solved problem, known since ARSG4\_3.06.3\_C03.06, solved since ARSG4\_3.06.5\_E03.06

EX350 modules that are configured but not connected hinder other 2005 system modules

If a 2005 project has a 3EX350.6 module configured but not connected, certain timing can result in other system modules (EX450, IP) being detected incorrectly or as having failed. Slave modules downstream from the EX450 module are detected as having failed although they are still running. This behavior no longer occurs with the current version.

#### IO System - CANIO

ID#400039937 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.07.6\_F03.07

CANIO slaves are not always found after startup

ID#400039937 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.08.8\_H03.08

CANIO slaves are not always found after startup

ID#400048831 : solved problem, known since ARSG4\_3.01.4\_D03.01, solved since ARSG4\_2.96.11\_K02.96

System clock doubled when using the LS172 as a timer device

When the 5LS172 is used as the system timer, the system clock ran at half the configured time.

#### IO System - CANopen

ID#400060887 : solved problem, known since V3.00.81.22 SP01, solved since ARSG4\_3.07.6\_F03.07

CANopen slave not started by the master if it sends only an emergency telegram with data =0 instead of a Boot-Up message

ID#400060887 : solved problem, known since V3.00.81.22 SP01, solved since ARSG4\_3.08.8\_H03.08

CANopen slave not started by the master if it sends only an emergency telegram with data =0 instead of a Boot-Up message

ID#400056381 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.4\_D03.07

Priority of CANopen master can be configured

The user can configure the priority of the CANopen master in order to adjust the system load for a particular application.

ID#400056381 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.5\_E03.08

Priority of CANopen master can be configured

The user can configure the priority of the CANopen master in order to adjust the system load for a particular application.

ID#400046758 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.01.7\_G03.01

CANopen master sends incorrect PDO

With more than 64 mapping entries, the CANopen master sends an incorrect PDO.

ID#400046901 : solved problem, known since ARSG4\_3.01.3\_C03.01, solved since ARSG4\_3.01.7\_G03.01

CANopen system task can cause a cycle time violation, among other things

If the CANopen system task writes messages to the fieldbus logbook, it's possible that this leads to a cycle time violation.

ID# 400045867, 400045710 : solved problem, known since ARSG4\_3.01.4\_D03.01, solved since ARSG4\_2.96.10\_J02.96

CANopen master sporadically returns incorrect slave node status or incorrect ModuleOK status

ID# 400032504, 400033988 : solved problem, known since unbekannt, solved since ARSG4\_2.96.4\_D02.96

High resource load for CANopen system task

Due to a locking problem, a high priority CANopen system task (with a higher priority than the cyclic task class) can result in long runtimes. In some circumstances this can lead to a cycle time violation in a cyclic task class.

ID#400032367 : solved problem, known since ARSG4\_2.96.2\_B02.96, solved since ARSG4\_2.96.4\_D02.96

Node guarding fails temporarily

A high load on the CANopen stack, can result in insufficient resources being available for the node guarding process temporarily.

ID#400031607 : solved problem, known since ARSG4\_3.06.1\_A03.06, solved since ARSG4\_3.06.4\_D03.06

Index of Emergency COB IDs can't be overwritten

ID#400031304 : solved problem, known since unbekannt, solved since ARSG4\_2.96.4\_D02.96

Error during slave configuration

After a slave has been configured, additional (not necessary) configuration commands are sent.

ID# 400022378, 400024266, 400024392, 400024391, 400024462, 400025270, 400026541, 400031748, 400032414, 400034127 : solved problem, known since V3.0.71.28 SP05, solved since ARSG4\_2.96.4\_D02.96

ACOPOSinverter X64 frequency inverter is sometimes not started correctly when turned off and turned back on. The CANopen slave doesn't go into operational mode.

#### IO System - General

ID#400064601 : solved problem, known since ARSG4\_3.08.8\_H03.08, solved since ARSG4\_3.08.10\_J03.08

Insufficient logbook entry when ArConfig has double channels/QLinks.

If the ArConfig contains double channels or QLinks, then Error 30965 "No name specification" appears, which hardly explains the actual cause of the error.

ID#400028352 : solved problem, known since ARSG4\_3.00.15\_O03.00, solved since ARSG4\_3.08.9\_I03.08

If global variables mapped to I/O points receive new addresses due to a change to the project, it is possible that the variable values are no longer transferred to the I/O points.

ID#400058109 : solved problem, known since V3.00.81.22 SP01, solved since ARSG4\_3.07.6\_F03.07

It can take very long to install I/O mappings, which can result in the connection being terminated due to a time violation.

ID#400058109 : solved problem, known since V3.00.81.22 SP01, solved since ARSG4\_3.08.7\_G03.08

It can take very long to install I/O mappings, which can result in the connection being terminated due to a time violation.

ID#400057340 : solved problem, known since ARSG4\_3.07.2\_B03.07, solved since ARSG4\_3.08.6\_F03.08

POWERLINK reports error 27306 when starting a visualization application

When initializing the graphics card, the SOC interrupt is delayed, which causes an I/O cycle time violation to be reported. Since cyclic data is not transferred in this early boot phase, I/O cycle time violations are now only evaluated after the beginning of cyclic data transfer.

ID#400057340 : solved problem, known since ARSG4\_3.07.2\_B03.07, solved since ARSG4\_3.07.4\_D03.07

POWERLINK reports error 27306 when starting a visualization application

When initializing the graphics card, the SOC interrupt is delayed, which causes an I/O cycle time violation to be reported. Since cyclic data is not transferred in this early boot phase, I/O cycle time violations are now only evaluated after the beginning of cyclic data transfer.

ID#400057827 : solved problem, known since ARSG4\_3.07.1\_A03.07, solved since ARSG4\_3.07.4\_D03.07

Maximum number of device handles exceeded with approx. 400 safety modules

A setup with approx. 400 safety modules and an X20CP1485 ran out of device handles, which is indicated in the logbook by Error 26003 "AR-DevMan: no free admin entry". The maximum number of device instances has been increased and is now 2.5 times higher

ID# 400053665, 400054105, 400055244 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.2\_B03.07

I/O cycle time violation during startup due to initialization of graphic card

During the startup of the CPU with a highly utilized PCI bus a IO cycle time violation 27306 could be triggered by the initialization of the visualization tasks. IO cycle time violations in early startup phases are now caught by the system.

ID#225792 : solved problem, known since ARSG4\_2.96.7\_G02.96, solved since ARSG4\_2.96.9\_I02.96

Variables with data types other than SINT and USINT can now be connected to OCTET data points

Previously, only variables with data types SINT and USINT or ARRAY OF SINT and ARRAY OF USINT could be connected to IO data points with data type OCTET.

When trying to connect other data types, error message 26603 was entered in the logbook. Now only a check is carried out to ensure that the total size matches.

ID#225099 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.01.3\_C03.01

Mapping PVs to I/O is not updated during task overload

Downloading a task, both in Copy and Overload mode, cause local variables in the respective task to be moved to new addresses. Because of an error in the install routine, the mapping tables of the shoveler are not updated, and incorrect addresses are used for further processing.

ID# 400028352, 400065604 : solved problem, known since ARSG4\_3.00.15\_O03.00, solved since ARSG4\_3.08.9\_I03.08

If global variables mapped to I/O points receive new addresses due to a change to the project, it is possible that the variable values are no longer transferred to the I/O points.

**IO System - HWD**

ID#235290 : solved problem, known since ARSG4\_3.01.6\_F03.01, solved since ARSG4\_3.01.7\_G03.01

Error 32244 when using 8AC114.60-2 only in NC Mapping table

If the module 8AC114.60-2 is configured , then with AR version F3.01 the following error can wrongly be indicated by the NC software (ACP10 or ARNC0):

- 32244: No PDO defined in the cyclic frame for this channel: NC object is disabled

If this error occurs with AR version F3.01, then another AR version must be used.

**IO System - ModbusRTU**

ID#400051798 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.01.10\_J03.01

ModuleOk detections sometimes takes very long for S44

ID# 400045626, 400046770 : solved problem, known since ARSG4\_3.01.4\_D03.01, solved since ARSG4\_3.01.6\_F03.01

ModbusRTU only works for one interface - simultaneous use of multiple interfaces not possible

**IO System - ModbusTCP**

ID#400060899 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.01.11\_K03.01

Due to an error in the task queue of the Modbus driver, packages that are received may no longer be allocated to the sent queries, thereby causing a connection timeout.

ID#400060899 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.07.6\_F03.07

Due to an error in the task queue of the Modbus driver, packages that are received may no longer be allocated to the sent queries, thereby causing a connection timeout.

ID#400060899 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.08.8\_H03.08

Due to an error in the task queue of the Modbus driver, packages that are received may no longer be allocated to the sent queries, thereby causing a connection timeout.

ID#400048959 : solved problem, known since ARSG4\_2.96.10\_J02.96, solved since ARSG4\_2.96.13\_M02.96

ModbusTCP master doesn't work on AC141

ID#400051942 : solved problem, known since unbekannt, solved since ARSG4\_3.01.11\_K03.01

ModbusTCP doesn't start all slaves

The problem is caused when there are no sockets available when establishing the connection. The ModbusTCP driver doesn't finish the initialization.

ID#400051942 : solved problem, known since unbekannt, solved since ARSG4\_3.07.5\_E03.07

ModbusTCP doesn't start all slaves

The problem is caused when there are no sockets available when establishing the connection. The ModbusTCP driver doesn't finish the initialization.

ID#400048959 : solved problem, known since ARSG4\_2.96.10\_J02.96, solved since ARSG4\_3.01.11\_K03.01

ModbusTCP master doesn't work on AC141

ID#400051942 : solved problem, known since unbekannt, solved since ARSG4\_3.08.6\_F03.08

ModbusTCP doesn't start all slaves

The problem is caused when there are no sockets available when establishing the connection. The ModbusTCP driver doesn't finish the initialization.

ID#400048959 : solved problem, known since ARSG4\_2.96.10\_J02.96, solved since ARSG4\_3.07.5\_E03.07

ModbusTCP master doesn't work on AC141

**IO System - netX**

ID#400069009 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.08.15\_O03.08

VC application blocks netX data communication

A priority problem interrupts netX data collection in the rhythm of the default update time of the data source.

ID#400065361 : solved problem, known since ARSG4\_3.07.3\_C03.07, solved since ARSG4\_3.07.7\_G03.07

IF1063-1 doesn't work on the BC1083

**IO System - Powerlink**

ID#400068763 : solved problem, known since ARSG4\_3.08.11\_K03.08, solved since ARSG4\_3.08.14\_N03.08

Naming of POWERLINK devices from other vendors in AsIODiag

The function blocks of the Library AsIODiag returned "plk\_any" or "epl\_any" for POWERLINK-Devices from other vendors than B&R in former versions.

The current Automation Runtime returns device names in the format "u%xV%x-unknown" where the first %x is replaced with the device identifier and the second %x is replaced by the vendor identifier.

Only if the option "Verify Device Type" is switched off, devices configured by XDD-Import will return "epl\_any".

ID#400065239 : solved problem, known since ARSG4\_3.07.2\_B03.07, solved since ARSG4\_3.07.7\_G03.07

Firmware Update for SafeMC did not complete.

Due to a change in B3.07, the firmware update for SafeMC modules doesn't complete. The R/E LED for SafeMC modules continues to double-blink green.

Starting with G3.07, the firmware update for SafeMC modules functions correctly again.

ID#400061758 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.14\_N03.08

ACOPOS synchronization problem 6002 in cascading POWERLINK networks when POWERLINK cycle time > 2ms

If a CPU with a system cycle time >2ms is synchronized as iCN with a higher level POWERLINK network, and ACOPOS stations with a POWERLINK cycle time >2ms are operated on a second POWERLINK interface, then the error 6002 can occur on the ACOPOS if the MN of the higher level POWERLINK network is still not active when the controller is started up.

Starting with AR version H3.08, the algorithm for starting synchronization upon startup has been improved so that the ACOPOS firmware can also be synchronized at startup even when there are very long cycle times and the MN has not been activated.

ID#251317 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.5\_E03.07

POWERLINK: ACOPOSmulti with SafeMC as chained station

ACOPOSmulti with SafeMC didn't work as a chained station.

ID#400060965 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.5\_E03.07

POWERLINK: ACOPOSmulti with SafeMC as chained station

ACOPOSmulti with SafeMC didn't work as a chained station.

ID#400060016 : solved problem, known since ARSG4\_3.07.2\_B03.07, solved since ARSG4\_3.08.12\_L03.08

Error 26051 in logbook when X20CS2770 after X20BCx083 on APC or Power Panel

If CANIO is enabled on both CAN interfaces of an X20CS2770 device being operated downstream from an X20BCx083 device, which itself is downstream from an APC or Power Panel, the error message "26051 AR-DD: xDeviceInit() error" is entered in the logbook.

Starting with AR K3.08, CANIO can be run on both CAN interfaces.

ID#400042474 : solved problem, known since ARSG4\_3.01.2\_B03.01, solved since ARSG4\_3.01.5\_E03.01

Depending on the selected timer device, hardware detection may not be completed

ID#229222 : solved problem, known since ARSG4\_3.05.2\_B03.05, solved since ARSG4\_3.06.1\_A03.06

Logbook entry ERR\_DDIOLK\_WRITEPARAM 30296 showed value 0 at Offset 8 in binary data

For the logbook entry ERR\_DDIOLK\_WRITEPARAM 30296, the value 0 was always entered at Offset 8 instead of the value of the write command.

ID#400039303 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.01.3\_C03.01

POWERLINK: SDO communication interrupted

During SDO communication from different tasks, it was possible for SDO communication to fail because of a locking problem.

ID#400025215 : solved problem, known since V3.0.71.30 SP05, solved since ARSG4\_2.95.20\_T02.95

INA routing via POWERLINK sometimes doesn't work because timeout times too low

ID#400068762 : new function since ARSG4\_3.08.12\_L03.08

Read ACOPOS device type using AsIODiag function block

Starting with ACOPOS OS 2.28.0, the ACOPOS device type can be read using the function blocks of the AsIODiag library.

ID#237362 : new function since ARSG4\_3.08.2\_B03.08

Logbook entry for firmware update now contains old and new version

When the firmware for POWERLINK stations is updated, both the old and new version numbers are noted in the logbook

ID#400040758 : new function since ARSG4\_3.08.2\_B03.08

Old and new firmware version entered in logbook

If the firmware on a POWERLINK V2 station is updated, the old and new firmware versions are now entered in the logbook, like they are for POWERLINK V1.



ID# 400034964, 400034661 : new function since ARSG4\_2.96.10\_J02.96

Modules that are configured downstream from the POWERLINK X2X controller but not physically present make the controller take longer to boot.

ID# 400009063, 400065339 : new function since ARSG4\_3.07.8\_H03.07

Find unconfigured POWERLINK stations with ASIODiag

Unconfigured POWERLINK stations can now be found using the ASIODiag library.

### IO System - Profibus

ID#400053732 : solved problem, known since V3.00.81.18, solved since ARSG4\_3.07.4\_D03.07

Priority of Profibus master can be configured

The user can configure the priority of the Profibus master in order to adjust the system load for a particular application.

ID#400053732 : solved problem, known since V3.00.81.18, solved since ARSG4\_3.08.5\_E03.08

Priority of Profibus master can be configured

The user can configure the priority of the Profibus master in order to adjust the system load for a particular application.

ID#400036980 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.01.2\_B03.01

Due to an error calculating the offset, I/O channels are not applied with the setting "Mapping = Channels"

ID#400027276 : solved problem, known since ARSG4\_2.95.19\_S02.95, solved since ARSG4\_2.96.2\_B02.96

Profibus master sends the wrong ident in the config frame

ID#206455 : solved problem, known since ARSG4\_3.00.11\_K03.00, solved since ARSG4\_2.96.7\_G02.96

EX450 modules sporadically won't start - "No ReadyFlag from Interface"

ID# 400020057 : solved problem, known since ARSG4\_2.95.12\_L02.95, solved since ARSG4\_2.96.4\_D02.96

Activating "Module monitoring" when using an X20BC0063 causes the controller to go into Service mode when booting

### IO System - X2X

ID#400044951 : solved problem, known since ARSG4\_3.01.1\_A03.01, solved since ARSG4\_3.01.1\_A03.01

Page fault caused by AsIOAccWrite on local X2X bus

If an AsIOAccWrite is performed on an X2X module on the local X2X interface, certain timing between the response of the module and the next call of the FB may result in a page fault in the task DdX2XAcc.<interface>, in the function "\_trspMuxHandlerResp". This timing problem has been corrected.

ID#216445 : solved problem, known since ARSG4\_2.96.1\_A02.96, solved since ARSG4\_2.96.4\_D02.96

Not enough time between frames on the X2X Link bus

When there is not enough time between frames on the X2X Link bus, the combination of certain quartz tolerances and a high bus load can result in the failure of some X2X frames.  
The time has been increased according to the worst-case tolerances. However, as a result there are fewer bytes of cyclic data available. Normally this is automatically compensated by a shortening of the acyclic frames.  
For configurations where the cyclic data is at the limit, it may be necessary to split the input and output data asymmetrically: Warning 30334 ERR\_DDIOX2X\_ASYMMETRIC in the logbook.  
For configurations that are at the absolute limit for cyclic data, the result may be that the configuration is no longer possible. Error message 30333 ERR\_DDIOX2X\_ASYNSIZE in the logbook.

ID#400028038 : solved problem, known since V2.7.0.0017 SP10, solved since ARSG4\_2.96.5\_E02.96

29-bit CAN ID when using the X20CS1070 causes an error when calling CANOpen()

ID# 400034627, 400034661 : new function since ARSG4\_2.96.4\_D02.96

Long boot time when many modules are configured that are not connected

Due to the timeout mechanism, the PLC may take a long time to boot if a large number of modules are configured and only a small percentage of them are actually connected.

ID#238445 : known problem since ARSG4\_3.08.1\_A03.08, correction planned for ARSG4\_3.08.2\_B03.08

StaleData on local X2X Link interface when X2X cycle > system cycle

If the X2X cycle time was longer than the system cycle time, the StaleData flag has been set during system cycles in which no new data was received on the X2X Link. This behaviour was inconsistent to X2X Link modules which were connected to a X2X Link/POWERLINK buscontroller. Now the StaleData flag is only set, if no data was received from the module during the X2X Link cycle. The Nettime of the X2X Link interface can be used. To determine if new X2X Link data was received during the latest system cycle.

ID#400042900 : known problem since ARSG4\_3.00.22\_V03.00, correction planned for ARSG4\_3.01.6\_F03.01

ModuleOK status for screw-in modules is not determined correctly in some cases

ID#40008018 : known problem since V2.7.0.0010 SP03, correction planned for ARSG4\_2.96.10\_J02.96

If a 7XX408.50-1 module is operated using an X20BC0083 and a BT9100, the PWM outputs do not function properly

#### Library - AsARCfg

ID#400047724 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.07.5\_E03.07

When multiple Ethernet interfaces are used, interference in the routing table causes Error 29004 when the function block CfgSetDefaultGateway() is called

ID#400047724 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.08.6\_F03.08

When multiple Ethernet interfaces are used, interference in the routing table causes Error 29004 when the function block CfgSetDefaultGateway() is called

ID# -, 400047408, 400049937 : solved problem, known since V3.00.81.12, solved since ARSG4\_3.07.5\_E03.07

Error 29009 occurs when reading the default gateway

ID# -, 400047408, 400049937 : solved problem, known since V3.00.81.12, solved since ARSG4\_3.08.6\_F03.08

Error 29009 occurs when reading the default gateway

ID#400057746 : solved problem, known since ARSG4\_3.06.4\_D03.06, solved since ARSG4\_3.07.5\_E03.07

Calling the function block CfgSetEthConfigMode() with the same mode that is already in use triggers Error 29003

ID#400057746 : solved problem, known since ARSG4\_3.06.4\_D03.06, solved since ARSG4\_3.08.6\_F03.08

Calling the function block CfgSetEthConfigMode() with the same mode that is already in use triggers Error 29003

ID#400057746 : solved problem, known since ARSG4\_3.06.4\_D03.06, solved since ARSG4\_3.07.5\_E03.07

Calling the function block CfgSetEthConfigMode() with the same mode that is already in use triggers Error 29003

ID# -, 400047408, 400049937 : solved problem, known since V3.00.81.12, solved since ARSG4\_3.07.5\_E03.07

Error 29009 occurs when reading the default gateway

ID#400029507 : solved problem, known since V3.00.80.20, solved since ARSG4\_2.96.4\_D02.96

NonVolatile option doesn't work with CfgSetEthConfigMode() function block

#### Library - AsARLog

ID#400059082 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.6\_F03.08

Creating a new logger module using AsArLogCreate() deletes any existing tasks with the same name

ID# 400031906, 400022988, 400026463 : solved problem, known since V3.0.71.31 SP05, solved since ARSG4\_2.96.3\_C02.96

AsArLogRead() provides incorrect time

Due to an error in calculating the time zone, the AsArLogRead() function block provides the incorrect time.

ID#400031708 : new function since ARSG4\_3.05.2\_B03.05

AsArRead() supports 0 for the parameter lenBin, memBin, lenAscii and memAscii - when 0 is transferred, the respective data isn't copied

ID#400072106 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_3.09.1\_A03.09

Accessing the "Safety" and "Fieldbus" logbooks via library (with an index) causes a PageFault. The problem can be avoided by specifying the names "\$safety" or "\$fieldbus."

#### Library - AsCANopen

ID#400064575 : solved problem, known since ARSG4\_3.07.3\_C03.07, solved since ARSG4\_3.07.7\_G03.07

Attempt to download AsCANopen library to ARsim rejected with error 9650 "Library function not available"

ID#400064575 : solved problem, known since ARSG4\_3.07.3\_C03.07, solved since ARSG4\_3.08.10\_J03.08

Attempt to download AsCANopen library to ARsim rejected with error 9650 "Library function not available"

ID#400055214 : solved problem, known since ARSG4\_3.01.8\_H03.01, solved since ARSG4\_3.07.4\_D03.07

Using CANopenNMT() can prevent a task download from completing

As a result the section of code for releasing the semaphore is not executed. The second time this function is called it is blocked by the semaphore and the task can't be completely transferred.

ID#400055214 : solved problem, known since ARSG4\_3.01.8\_H03.01, solved since ARSG4\_3.08.4\_D03.08

Using CANopenNMT() can prevent a task download from completing

As a result the section of code for releasing the semaphore is not executed. The second time this function is called it is blocked by the semaphore and the task can't be completely transferred.

ID#400054457 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.3\_C03.07

CANOpenSDOWriteData() terminates after downloading several hundred bytes due to a full CAN buffer

ID#400054457 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.4\_D03.08

CANOpenSDOWriteData() terminates after downloading several hundred bytes due to a full CAN buffer

ID#400055463 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.01.10\_J03.01

CANOpenSDOWrite8() only sends every second SDO

ID#400055463 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.07.3\_C03.07

CANOpenSDOWrite8() only sends every second SDO

ID#400055463 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.08.4\_D03.08

CANOpenSDOWrite8() only sends every second SDO

ID#400054360 : solved problem, known since V3.00.81.20 SP01, solved since ARSG4\_3.07.2\_B03.07

With the function block CanOpenGetState(), when enable=FALSE the function block freezes during execution

ID#400054360 : solved problem, known since V3.00.81.20 SP01, solved since ARSG4\_3.08.3\_C03.08

With the function block CanOpenGetState(), when enable=FALSE the function block freezes during execution

ID# 400048365, 400048594 : solved problem, known since V3.00.80.31 SP01, solved since ARSG4\_3.01.8\_H03.01

When using the function blocks CANOpenSDORead8(), CANOpenSDOWrite8(), CANOpenSDOReadData() and CANOpenSDOWriteData() a watchdog error occurs after running for a longer period of time.

ID#400041410 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.01.3\_C03.01

PDOs and SDOs get lost when using the AsCANopen library and when there is a heavy load on the CPU

ID#400035631 : new function since ARSG4\_3.01.6\_F03.01

New function blocks CANOpenSDOReadData() and CANOpenSDOWriteData()

ID#400012433 : new function since ARSG4\_3.04.4\_D03.04

New function blocks: CANOpenSDOReadData(), CANOpenSDOWriteData()

#### Library - AsEPL

ID#400055409 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.08.12\_L03.08

EplSDORead() stays in the status "Busy" after the enable FB is set to FALSE

ID#400055409 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.08.14\_N03.08

EplSDORead() stays in the status "Busy" after the enable FB is set to FALSE

#### Library - AsIMA

ID#400050977 : solved problem, known since unbekannt, solved since ARSG4\_3.08.8\_H03.08

AsIMA doesn't adjust for daylight savings time when reading the time from a peer station

ID#400040658 : solved problem, known since ARSG4\_3.01.2\_B03.01, solved since ARSG4\_3.01.3\_C03.01

When connecting from the server to the client, the client freezes in the step "IMA\_CONNECTING"

ID# 400039483, 400040973 : solved problem, known since ARSG4\_2.96.6\_F02.96, solved since ARSG4\_2.96.9\_I02.96

When connecting from the server to the client, the client freezes in the step "IMA\_CONNECTING"

ID#400039843 : known problem since ARSG4\_3.01.1\_A03.01, correction planned for ARSG4\_3.07.9\_I03.07

Under certain circumstances (INAAction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC

ID#400039843 : known problem since ARSG4\_3.01.1\_A03.01, correction planned for ARSG4\_3.08.14\_N03.08

Under certain circumstances (INAAction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC

ID# 400035792, 400020837 : known problem since ARSG4\_3.00.22\_V03.00, correction planned for ARSG4\_3.07.9\_I03.07

Under certain circumstances (INAAction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC

ID# 400035792, 400020837 : known problem since ARSG4\_3.00.22\_V03.00, correction planned for ARSG4\_3.08.14\_N03.08

Under certain circumstances (INAAction with multiple PV objects) AR version 3.06/3.07 for SG4 is no longer compatible with older versions of AR or with SG3 / SGC

ID#400007523 : known problem since V3.0.71.16 SP01, correction planned for ARSG4\_3.08.10\_J03.08

AsIMA ignores time zone information

**Library - AsIOAcc**

ID#400040238 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.01.3\_C03.01

AsIOAccWrite() doesn't work for ACOPOSinverter modules on the Modbus (call BUSY)

**Library - AsIODiag**

ID#257265 : new function since ARSG4\_3.08.16\_P03.08

Detection of POWERLINK hardware using AS-IO-Diag

In the past, when POWERLINK devices from other manufacturers were detected, the function block DiagGetStrInfo with infoCode asdiagPLUGGED\_MODULE returned the string "epl\_any".

Starting with AR N3.08, devices from other manufacturers will return a string with the format "u% xV% x-PL-unknown", where the first %x represents the hexadecimal product code and the second %x represents the hexadecimal vendor ID.

If the function for checking the vendor ID and product code is enabled and these codes match the detected POWERLINK device, then the model number of the configured device is applied so that the strings returned with the infoCodes asdiagCONFIG\_MODULE and asdiagPLUGGED\_MODULE match.

**Library - AsL2DP**

ID#400042115 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.01.5\_E03.01

Error 28826 when calling the AsL2DP function block with Max\_Module > 10 and S7 Profibus

**Library - AsMem**

ID# 400007099, 400044198 : solved problem, known since V2.7.0.0010 SP03, solved since ARSG4\_3.08.6\_F03.08

AsMemPartFree returned -8 byte free memory size

The function block AsMemPartFree for requesting the free memory size of a memory partition created with AsMemPartFree returned the value numByteFree = 4294967288 (= 16#FFFFFFF8 = -8), if the whole memory was allocated.

**Library - AsNxCoM**

ID#400062449 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.07.7\_G03.07

When using multiple netX CANopen master modules, a different handle is used for each module, which speeds up asynchronous function block processing.

ID#400062449 : solved problem, known since ARSG4\_3.07.4\_D03.07, solved since ARSG4\_3.08.10\_J03.08

When using multiple netX CANopen master modules, a different handle is used for each module, which speeds up asynchronous function block processing.

**Library - AsSem**

ID#400026881 : solved problem, known since ARSG4\_3.00.13\_M03.00, solved since ARSG4\_3.04.2\_B03.04

When the SemCreate() function block from the AsSem library is called with the parameter values initCount = maxCount, the function block reports the Status 33320 (semaphore could not be generated).

**Library - AsSNMP**

ID#400045366 : new function since ARSG4\_3.01.6\_F03.01

New AsSNMP library

ID#400038170 : new function since ARSG4\_3.05.1\_A03.05

New AsSNMP library

Library for sending and receiving SNMP packages.

**Library - AsTcp**

ID#400043972 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.01.6\_F03.01

The maximum number of parallel asynchronous function block calls is limited to 15

**Library - AsUSB**

ID#400051015 : solved problem, known since ARSG4\_3.07.1\_A03.07, solved since ARSG4\_3.07.3\_C03.07

Support for Cino F788-G barcode scanner

ID#400051015 : solved problem, known since ARSG4\_3.07.1\_A03.07, solved since ARSG4\_3.08.4\_D03.08

Support for Cino F788-G barcode scanner

**Library - AsXML**

ID#400054911 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.07.2\_B03.07

Function blocks from AsXML library ignore enable input

ID#400054911 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.3\_C03.08

Function blocks from AsXML library ignore enable input

ID#400047305 : solved problem, known since ARSG4\_3.01.5\_E03.01, solved since ARSG4\_3.01.7\_G03.01

Empty string not permitted as attribute value

#### Library - CAN\_lib

ID#400060652 : solved problem, known since ARSG4\_3.07.3\_C03.07, solved since ARSG4\_3.07.5\_E03.07

CANrwtab() returns invalid data

When CAN telegrams with fewer than 8 bytes are received, 8 are always written to the receive buffer (unused bytes are not written with 0).

ID#400060652 : solved problem, known since ARSG4\_3.07.3\_C03.07, solved since ARSG4\_3.08.7\_G03.08

CANrwtab() returns invalid data

When CAN telegrams with fewer than 8 bytes are received, 8 are always written to the receive buffer (unused bytes are not written with 0).

ID#400047219 : solved problem, known since V3.00.80.29 SP01, solved since ARSG4\_3.01.7\_G03.01

CAN exception not executed after calling CANwrite.enable = 0

ID#400030593 : solved problem, known since ARSG4\_2.95.22\_V02.95, solved since ARSG4\_2.96.2\_B02.96

Cycle time violation caused by CANwrite()

When using the CANwrite() function block, a cycle time violation can occur in cyclic tasks if multiple CAN interfaces were opened previously with the CANMulOpen() function block. The error is caused by allocation of management memory (SM\_malloc) using the CANwrite() function block.

ID#400028109 : solved problem, known since ARSG4\_2.95.20\_T02.95, solved since ARSG4\_2.96.1\_A02.96

CanQurw() sporadically delivers status 8810

When using two CAN interfaces at the same time, it's possible that the CANQurw() function block delivers the status 8810 resulting in telegrams being missed.

#### Library - FileIO

ID#400069276 : solved problem, known since ARSG4\_3.08.10\_J03.08, solved since ARSG4\_3.07.9\_I03.07

Using a handle that has already been closed can cause a page fault (read, write, or close on a handle)

ID#400069276 : solved problem, known since ARSG4\_3.08.10\_J03.08, solved since ARSG4\_3.08.14\_N03.08

Using a handle that has already been closed can cause a page fault (read, write, or close on a handle)

ID#400060157 : solved problem, known since ARSG4\_2.96.12\_L02.96, solved since ARSG4\_2.96.13\_M02.96

The status BUSY can remain set for up to 120 minutes if the connection is lost when using the function block DirInfo() over a network

ID#400060157 : solved problem, known since ARSG4\_2.96.12\_L02.96, solved since ARSG4\_3.07.6\_F03.07

The status BUSY can remain set for up to 120 minutes if the connection is lost when using the function block DirInfo() over a network

ID#400060157 : solved problem, known since ARSG4\_2.96.12\_L02.96, solved since ARSG4\_3.08.9\_I03.08

The status BUSY can remain set for up to 120 minutes if the connection is lost when using the function block DirInfo() over a network

ID#400053325 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.01.10\_J03.01

The maximum length for the device name when calling DevLink() on ARsim targets has been increased from 128 characters to 256 characters.

ID#400051743 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.2\_B03.08

If no destination directory is specified for DirCopy(), copying to ARsim doesn't work.

ID#400041545 : solved problem, known since ARSG4\_3.01.2\_B03.01, solved since ARSG4\_3.01.4\_D03.01

On ARsim, calling DirCreate() a second time with the same directory name does not report status 20725, but rather 20709

ID#400033999 : solved problem, known since V2.7.0.0019 SP12, solved since ARSG4\_3.01.4\_D03.01

Memory leak due to cyclic DevLink() / DevUnlink()

ID#400027971 : solved problem, known since V3.0.71.31 SP05, solved since ARSG4\_3.04.2\_B03.04

DirRead() reads the wrong time local time is not considered

ID#400024449 : solved problem, known since ARSG4\_3.04.2\_B03.04, solved since ARSG4\_3.05.1\_A03.05

Attempting to copy a directory to a subordinate directory is no longer permitted, and generates the error fiERR\_INVALID\_PATH

ID#400048318 : new function since ARSG4\_3.08.11\_K03.08

New function blocks FileWriteEx() and FileTruncate()

ID#400063458 : new function since ARSG4\_3.08.10\_J03.08



DevLink() blocks other file actions for a relatively long time

ID#400038864 : new function since ARSG4\_3.08.9\_I03.08

Function blocks now return the error 20709 (fiERR\_FILE\_DEVICE) if a device is not present

ID#400028201 : new function since ARSG4\_3.01.4\_D03.01

Running a DEVLink() or DEVUnlink() from ARwin on a directory shared in Windows (CIFS) can take up to 30 seconds

#### Library - INAcient

ID#400030615 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.01.1\_A03.01

Client doesn't read all PVs, reads incorrect values or no values at all.

#### Library - LoopConR V2.72.3

ID#400042434 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.01.8\_H03.01

If Mode = 0 or the constant LCRPID\_MODE\_OFF is transferred in the function block LCRPID, the status 31553 is returned.

#### Library - SYS\_lib

ID#400011003 : solved problem, known since ARSG4\_3.08.4\_D03.08, solved since ARSG4\_3.08.6\_F03.08

TIM\_musec returns incorrect time when the system tick isn't a whole number multiple or factor of 10 milliseconds

If the system tick is not a real factor or whole number multiple of 10 milliseconds, then the microsecond counter is not reset after exactly 10 milliseconds as specified.

For example, with a system tick of 1600µs it is reset after 9600µs (6x1600) or 11200µs (7x1600).

The AsIOTimeStamp() function from the AsIOTime library is better suited for time measurements.

ID# 400028877, 400038632 : solved problem, known since ARSG4\_2.95.5\_E02.95, solved since ARSG4\_2.96.11\_K02.96

ST\_name() doesn't return task names in the EXIT

#### System - ANSL

ID#400049393 : solved problem, known since ARSG4\_3.01.7\_G03.01, solved since ARSG4\_3.01.9\_I03.01

Communication places heavy load on the Terminal CPU

The problem occurs when dynamic PVs are not assigned a valid pointer (0). The recurring search for the PV overloads the system.

ID#400047610 : solved problem, known since ARSG4\_3.01.5\_E03.01, solved since ARSG4\_3.01.7\_G03.01

Terminal variables are not updated when they are initialized after startup.

ID#400036104 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.01.2\_B03.01

VC4 > Terminal Mode > Operating the visualization with AS3.00.80 considerably slower than in earlier versions

ID#400033456 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.01.2\_B03.01

Value changes to enumerations are not displayed on the terminal

ID#400023079 : solved problem, known since ARSG4\_2.95.19\_S02.95, solved since ARSG4\_2.96.2\_B02.96

Terminal mode: With a string length of 1024 or larger, the string is no longer transferred correctly

#### System - DHCP

ID# 400051264 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.01.9\_I03.01

Static routing doesn't work with DHCP

ID#400037131 : solved problem, known since ARSG4\_3.01.2\_B03.01, solved since ARSG4\_3.01.4\_D03.01

Receiving a DHCP offer package with the option 81 causes page fault

ID# 400021425 : solved problem, known since ARSG4\_2.95.2\_B02.95, solved since ARSG4\_2.96.5\_E02.96

Stack overflow on the DHCP server causes PageFault

#### System - Firmware

ID#257680 : solved problem, known since ARSG4\_3.01.11\_K03.01, solved since ARSG4\_2.96.14\_N02.96

PP065 in combination with a 4PP065.IF23-1 no longer booting due to a faulty flash access after a firmware update

ID#257435 : solved problem, known since ARSG4\_3.01.11\_K03.01, solved since ARSG4\_3.01.12\_L03.01

PP065 in combination with a 4PP065.IF23-1 no longer booting due to a faulty flash access after a firmware update

ID#257430 : solved problem, known since ARSG4\_3.01.11\_K03.01, solved since ARSG4\_3.07.6\_F03.07

PP065 in combination with a 4PP065.IF23-1 no longer booting due to a faulty flash access after a firmware update

ID#257375 : solved problem, known since ARSG4\_3.01.11\_K03.01, solved since ARSG4\_3.08.10\_J03.08

PP065 in combination with a 4PP065.IF23-1 no longer booting due to a faulty flash access after a firmware update

ID#400059335 : solved problem, known since unbekannt, solved since ARSG4\_2.96.13\_M02.96

Correction of the error in which very short and light pressure on the touch screen can cause the position to be evaluated incorrectly

ID#400059335 : solved problem, known since unbekannt, solved since ARSG4\_3.01.11\_K03.01

Correction of the error in which very short and light pressure on the touch screen can cause the position to be evaluated incorrectly

ID#400059335 : solved problem, known since unbekannt, solved since ARSG4\_3.07.6\_F03.07

Correction of the error in which very short and light pressure on the touch screen can cause the position to be evaluated incorrectly

ID#400059335 : solved problem, known since unbekannt, solved since ARSG4\_3.08.10\_J03.08

Correction of the error in which very short and light pressure on the touch screen can cause the position to be evaluated incorrectly

ID#400054833 : solved problem, known since ARSG4\_3.06.22\_V03.06, solved since ARSG4\_3.08.4\_D03.08

PP065: Warning "26061 Cannot configure minimum reduced cycle time due to old firmware" because of different drivers or POWERLINK firmware

ID#400045098 : solved problem, known since ARSG4\_2.96.9\_I02.96, solved since ARSG4\_2.96.9\_I02.96

PP065: If a device is operated at low temperatures, the background lighting remains dark.

ID# 400038343, 400039888, 400040075 : solved problem, known since ARSG4\_2.96.1\_A02.96, solved since ARSG4\_2.96.8\_H02.96

PP45 reports the wrong Module ID

ID#400037284 : new function since ARSG4\_3.08.10\_J03.08

Improved response time for PP065 touch screen

ID#400037284 : new function planned for ARSG4\_2.96.12\_L02.96

Improved response time for PP065 touch screen

ID#400037284 : new function planned for ARSG4\_3.07.2\_B03.07

Improved response time for PP065 touch screen

ID#400054833 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_3.07.2\_B03.07

PP065: Warning "26061 Cannot configure minimum reduced cycle time due to old firmware" because of different drivers or POWERLINK firmware

ID#400048657 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_3.07.2\_B03.07

PP045 with IF24 (L2DP) returns incorrect data when odd addresses are read in the Profibus image

#### System - Firmware

ID#400037284 : new function since ARSG4\_3.07.2\_B03.07

Improved response time for PP065 touch screen

ID#400048657 : known problem since ARSG4\_3.06.22\_V03.06, correction planned for ARSG4\_3.08.4\_D03.08

PP045 with IF24 (L2DP) returns incorrect data when odd addresses are read in the Profibus image

#### System - INA

ID#400041484 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.01.4\_D03.01

INA routing via POWERLINK doesn't work

ID#400039603 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.01.4\_D03.01

INA routing via POWERLINK doesn't work

ID#218739 : solved problem, known since ARSG4\_2.96.3\_C02.96, solved since ARSG4\_2.96.5\_E02.96

High resource load for INA Client connection with no peer station (server)

If there is an attempt to establish a client connection and the corresponding peer station is not available, the resource requirement for the INA Ethernet task may become very high.

#### System - Netboot

ID#400044001 : new function since ARSG4\_2.96.12\_L02.96

Remote install causes Warning 27058 "NV memory block cannot be backed up"

If a restart is triggered during a remote install, a missing uninstallation results in Warning 27058 "NV memory block cannot be backed up".

#### System - OPC

ID#400055614 : solved problem, known since PV13.00.00.3119, solved since ARSG4\_3.08.8\_H03.08

"VT\_DATE local" wrong for DCOM routines - in leap years the date is offset by one day

ID#400055610 : solved problem, known since ARSG4\_3.07.1\_A03.07, solved since ARSG4\_3.08.8\_H03.08

DT and DATE\_AND \_TIME variables are converted incorrectly by VT\_DATE when they are written.

ID#400046414 : solved problem, known since ARSG4\_3.06.3\_C03.06, solved since ARSG4\_3.07.1\_A03.07

Pagefault / Memory not in heap

Incorrect handling of strings leads to page fault or "Memory not in heap" errors.

ID#400036902 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.05.2\_B03.05

If an empty string is written to the AR OPC server, a page fault occurs

ID#400032324 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.01.2\_B03.01

The AR OPC server can only be accessed via the first Ethernet interface on the target system.

If the target system has multiple Ethernet interfaces, the OPC server can only be accessed via the first one.

ID# 400038150, 400037974 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.01.3\_C03.01

AR OPC server doesn't work on ARwin

#### System - USB Support

ID# 400040510, 400040224 400040220 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_2.96.8\_H02.96

Some USB flash drives don't work in Automation Runtime

Due to a timing change, some USB flash drives don't work in Automation Runtime.

#### System - WebServer

ID#400057308 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.07.5\_E03.07

Target crashes with page fault in the web server module when an ASP write command is run from a website with more than 9 variables.

ID#400052213 : solved problem, known since V3.00.80.31 SP01, solved since ARSG4\_3.08.11\_K03.08

ENUM data types in ASP functions

With the current version of AR, it is now possible to use ENUM data types in HTML pages via ASP functions.

ID#400057308 : solved problem, known since ARSG4\_3.01.9\_I03.01, solved since ARSG4\_3.08.11\_K03.08

Target crashes with page fault in the web server module when an ASP write command is run from a website with more than 9 variables.

ID#400053444 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.07.3\_C03.07

Variable values sometimes displayed incorrectly on ASP pages

On large ASP pages, some PV values are not evaluated correctly by the respective ASP function. As a result, the HTML page displays illegible special characters instead of the actual PV value. This error has been corrected.

ID#400053444 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.08.8\_H03.08

Variable values sometimes displayed incorrectly on ASP pages

On large ASP pages, some PV values are not evaluated correctly by the respective ASP function. As a result, the HTML page displays illegible special characters instead of the actual PV value. This error has been corrected.

ID#400057308 : solved problem, known since , solved since ARSG4\_3.08.8\_H03.08

Target crashes with page fault in the web server module when an ASP write command is run from a website with more than 9 variables.

ID#400053444 : solved problem, known since ARSG4\_3.00.22\_V03.00, solved since ARSG4\_3.08.8\_H03.08

Variable values sometimes displayed incorrectly on ASP pages

On large ASP pages, some PV values are not evaluated correctly by the respective ASP function. As a result, the HTML page displays illegible special characters instead of the actual PV value. This error has been corrected.

ID#400049979 : solved problem, known since ARSG4\_3.01.7\_G03.01, solved since ARSG4\_3.07.4\_D03.07

SDM - Update problems with dynamic page content

If a PC has multiple connections to the SDM (via multiple browser windows or multiple tabs within one browser), then dynamic SVG pages (CPU temperature, CPU load) are not updated continuously. This problem has been corrected.

ID#400049979 : solved problem, known since ARSG4\_3.01.7\_G03.01, solved since ARSG4\_3.08.5\_E03.08

SDM - Update problems with dynamic page content

If a PC has multiple connections to the SDM (via multiple browser windows or multiple tabs within one browser), then dynamic SVG pages (CPU temperature, CPU load) are not updated continuously.  
This problem has been corrected.

ID#400043289 : solved problem, known since ARSG4\_3.01.3\_C03.01, solved since ARSG4\_3.01.5\_E03.01

The webserver cache mechanism doesn't test the file date - as a result, changed data isn't displayed

ID#400041193 : solved problem, known since ARSG4\_3.01.1\_A03.01, solved since ARSG4\_3.01.4\_D03.01

As soon as a website is accessed that is either write-protected itself or that is inside a write-protected folder, the CPU crashes with a page fault.

ID#400041072 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.01.5\_E03.01

ReadPlc only reads the top two values of 4-byte values.

ID#400038693 : solved problem, known since V3.00.80.25, solved since ARSG4\_3.01.3\_C03.01

Parameter transfer for "webprint" function doesn't work with AR 3.00 and up. String cut off after "="

ID# 400029923, 400037586 : solved problem, known since ARSG4\_3.00.14\_N03.00, solved since ARSG4\_3.01.2\_B03.01

Web server doesn't work on User Partition (F:)

## **1A4300.02 (1.0 Automation Studio 3.x)**

### **Build - Transfer To Target**

ID#400062152 : solved problem, known since V3.00.81.24 SP0x, solved since ARSG4\_3.07.3\_C03.07

Status indication of tasks (RUN, IDLE, etc.) read incorrectly due to synchronization problems in Automation Studio - display problem