

## MCP2517FD Silicon Errata and Data Sheet Clarification

The functionality of the MCP2517FD device is described in the device Data Sheet ([DS20005688B](#)), except for the anomalies described below.

### 1. Module: SPI Module

#### TX MAB underflow/RX MAB overflow due to long delays between SPI bytes

The SPI interface can block the CAN FD Controller module from accessing RAM in-between SPI bytes, and between the last byte and the rising edge of the nCS line during an SPI READ or SPI READ\_CRC instruction while accessing RAM.

If the CAN FD Controller module is blocked for more than TSPIMAXDLY, a TX MAB underflow or an RX MAB overflow can occur.

#### Fix/Work Around

Keep the delay between two SPI bytes and between the last SPI byte, and the rising edge of nCS shorter than TSPIMAXDLY; see [Figure 1](#).


The maximum allowed delay between two bytes depends on which CAN message frame is transmitted, and on the selected Nominal Bit Time (NBT) and Data Bit Time (DBT). [Table 1](#) lists TSPIMAXDLY for the worst-case scenarios.

For example: TSPIMAXDLY is 8.5  $\mu$ s for a CAN FD frame at 500 kbps/2 Mbps. In comparison, an SPI byte takes 0.67  $\mu$ s at 12 MHz SCK. A delay of ten times the duration of one SPI byte could cause a TX MAB underflow. It is highly unlikely for an MCU application to introduce such a long delay, but this error could occur when running an operation system, such as Linux<sup>®</sup> on a slower MPU.

In case of a TX MAB underflow, the device will notify the application by setting SERRIF and MODIF, and by transitioning to Restricted Operation or Listen Only mode (depending on CiCON.SERR2LOM). After the application requests Normal mode, the CAN FD Controller module will automatically attempt to retransmit the message that caused the TX MAB underflow. It is not necessary to reset the device.

In case of an RX MAB overflow, the device will notify the application by setting SERRIF. The device will remain in Normal mode. The message that caused the RX MAB overflow will be discarded.

**FIGURE 1: MAXIMUM DELAY BETWEEN SPI BYTES**



**TABLE 1: WORST-CASE SCENARIOS**

Scenario	Frame Format	TSPIMAXDLY
1	CAN Base Frame	5 NBT
2	CAN FD Control Field	3 NBT + 5 DBT
3	CAN FD Data Phase	32 DBT

## 2. Module: SPI Module

### Incorrect CRC for certain READ\_CRC commands

It is possible that there is a mismatch between the transmitted CRC and the actual CRC for the transmitted data when data are updated at a specific time during the SPI READ\_CRC command. In these cases, the transmitted CRC is wrong. The data transmitted are correct.

#### Fix/Work Around:

If a CRC mismatch occurs, reissue the READ\_CRC command.

Only bits 7/15/23/31 of the following registers can be affected:

- CiTXIF
- CiRXIF
- CiCON
- CiTBC
- CiINT
- CiRXOVIF
- CiTXATIF
- CiTXREQ
- CiTREC
- CiBDIAG0
- CiBDIAG1
- CiTXQSTA
- CiFIFOSTAm

The occurrence can be minimized by not using FIFOs 7/15/23/31. In these cases, the registers, CiTXIF, CiRXIF, CiRXOVIF, CiTXATIF and CiTXREQ, are not affected.

Bit 31 of RAM reads with CRC could also be affected. This can be avoided by reading from a received FIFO only after the message has been loaded into the FIFO, indicated by the receive flags. This is the recommended procedure independent of the issue described here.

## 3. Module: ECC Module

### ECC Single Error Correction does not work in all cases

#### Fix/Work Around:

Enable Single Error Correction (SEC) and Double Error Detection (DED) interrupts by setting SECIE and DEDIE. Handle SECIF as a detection interrupt and do not rely on the error correction. Instead, handle both interrupts as a notification that the RAM word at ERRADDR was corrupted.

## 4. Module: SPI Module

### SFR address rollover does not work

The SFR address rollover, from 0x3FF to 0x000 and from 0xFFF to 0xE00, does not work. Instead, the address changes from 0x3FF to 0x400 and from 0xFFF to 0x000.

The address rollover for the RAM works as described.

#### Fix/Work Around:

None.

## 5. Module: SPI/RAM Module

### The SPI can read corrupted data from the RAM at fast SPI speeds

Simultaneous activity on the CAN bus while reading data from the RAM via the SPI interface, with a high SCK frequency, can lead to corrupted data being read from the RAM.

#### Fix/Work Around:

Ensure that FSCK is less than or equal to  $0.85 * (FSYSCLK/2)$ .

## 6. Module: SPI/GPIO Module

### Writing multiple bytes to the IOCON register using one SPI WRITE instruction can overwrite LAT0 and LAT1

Writing Byte 2 and Byte 3 of the IOCON register using one SPI WRITE instruction clears LAT0 and LAT1.

#### Fix/Work Around:

When setting LAT0 or LAT1, do not use a multi-data byte SPI WRITE instruction. Instead, write the bit fields in the IOCON register using single data byte SFR WRITE instructions.

## Data Sheet Clarifications:

In the “MCP2517FD Data Sheet” (DS20005688B), the following clarifications and corrections should be noted:

- a) None to report at this time.

## APPENDIX A: REVISION HISTORY

### Rev. C Document (September 2020)

- Added [Section 3. Module: “ECC Module”](#),
- Added [Section 4. Module: “SPI Module”](#),
- Added [Section 5. Module: “SMI/RAM Module”](#),
- Added [Section 6. Module: “SPI/GPIO Module”](#).

### Rev. B Document (July 2019)

- Updated [Section 1. Module: “SPI Module”](#),
- Updated [Figure 1](#),
- Added [Section 2. Module: “SPI Module”](#).

### Rev. A Document (May 2018)

- Initial release of this document.

# MCP2517FD

---

NOTES:

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods being used in attempts to breach the code protection features of the Microchip devices. We believe that these methods require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Attempts to breach these code protection features, most likely, cannot be accomplished without violating Microchip's intellectual property rights.
- Microchip is willing to work with any customer who is concerned about the integrity of its code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable." Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication is provided for the sole purpose of designing with and using Microchip products. Information regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL OR CONSEQUENTIAL LOSS, DAMAGE, COST OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

### Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Klear, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzr, PackTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TempTrackr, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, Vite, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KlearNet, KlearNet logo, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICKit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2018-2020, Microchip Technology Incorporated, All Rights Reserved.

ISBN: 978-1-5224-6895-0

For information regarding Microchip's Quality Management Systems, please visit [www.microchip.com/quality](http://www.microchip.com/quality).

## Worldwide Sales and Service

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://www.microchip.com/support>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Austin, TX**  
Tel: 512-257-3370

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Novi, MI  
Tel: 248-848-4000

**Houston, TX**  
Tel: 281-894-5983

**Indianapolis**  
Noblesville, IN  
Tel: 317-773-8323  
Fax: 317-773-5453  
Tel: 317-536-2380

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608  
Tel: 951-273-7800

**Raleigh, NC**  
Tel: 919-844-7510

**New York, NY**  
Tel: 631-435-6000

**San Jose, CA**  
Tel: 408-735-9110  
Tel: 408-436-4270

**Canada - Toronto**  
Tel: 905-695-1980  
Fax: 905-695-2078

### ASIA/PACIFIC

**Australia - Sydney**  
Tel: 61-2-9868-6733

**China - Beijing**  
Tel: 86-10-8569-7000

**China - Chengdu**  
Tel: 86-28-8665-5511

**China - Chongqing**  
Tel: 86-23-8980-9588

**China - Dongguan**  
Tel: 86-769-8702-9880

**China - Guangzhou**  
Tel: 86-20-8755-8029

**China - Hangzhou**  
Tel: 86-571-8792-8115

**China - Hong Kong SAR**  
Tel: 852-2943-5100

**China - Nanjing**  
Tel: 86-25-8473-2460

**China - Qingdao**  
Tel: 86-532-8502-7355

**China - Shanghai**  
Tel: 86-21-3326-8000

**China - Shenyang**  
Tel: 86-24-2334-2829

**China - Shenzhen**  
Tel: 86-755-8864-2200

**China - Suzhou**  
Tel: 86-186-6233-1526

**China - Wuhan**  
Tel: 86-27-5980-5300

**China - Xian**  
Tel: 86-29-8833-7252

**China - Xiamen**  
Tel: 86-592-2388138

**China - Zhuhai**  
Tel: 86-756-3210040

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-3090-4444

**India - New Delhi**  
Tel: 91-11-4160-8631

**India - Pune**  
Tel: 91-20-4121-0141

**Japan - Osaka**  
Tel: 81-6-6152-7160

**Japan - Tokyo**  
Tel: 81-3-6880-3770

**Korea - Daegu**  
Tel: 82-53-744-4301

**Korea - Seoul**  
Tel: 82-2-554-7200

**Malaysia - Kuala Lumpur**  
Tel: 60-3-7651-7906

**Malaysia - Penang**  
Tel: 60-4-227-8870

**Philippines - Manila**  
Tel: 63-2-634-9065

**Singapore**  
Tel: 65-6334-8870

**Taiwan - Hsin Chu**  
Tel: 886-3-577-8366

**Taiwan - Kaohsiung**  
Tel: 886-7-213-7830

**Taiwan - Taipei**  
Tel: 886-2-2508-8600

**Thailand - Bangkok**  
Tel: 66-2-694-1351

**Vietnam - Ho Chi Minh**  
Tel: 84-28-5448-2100

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4485-5910  
Fax: 45-4485-2829

**Finland - Espoo**  
Tel: 358-9-4520-820

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Garching**  
Tel: 49-8931-9700

**Germany - Haan**  
Tel: 49-2129-3766400

**Germany - Heilbronn**  
Tel: 49-7131-72400

**Germany - Karlsruhe**  
Tel: 49-721-625370

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Germany - Rosenheim**  
Tel: 49-8031-354-560

**Israel - Ra'anana**  
Tel: 972-9-744-7705

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Italy - Padova**  
Tel: 39-049-7625286

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Norway - Trondheim**  
Tel: 47-7288-4388

**Poland - Warsaw**  
Tel: 48-22-3325737

**Romania - Bucharest**  
Tel: 40-21-407-87-50

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**Sweden - Gothenberg**  
Tel: 46-31-704-60-40

**Sweden - Stockholm**  
Tel: 46-8-5090-4654

**UK - Wokingham**  
Tel: 44-118-921-5800  
Fax: 44-118-921-5820