

Unit 1 – Iron–Carbon Equilibrium Phase Diagram (100 MCQs)

1. The iron–carbon diagram is an example of a _____.

- a) Time–Temperature diagram
- b) Phase diagram
- c) Cooling curve
- d) Hardness chart

✓ Answer: b

2. The term “equilibrium” in the diagram indicates _____.

- a) Fast cooling
- b) Rapid transformation
- c) Slow rate of temperature change
- d) Instant heating

✓ Answer: c

3. Ferrite is also known as _____.

- a) α -iron
- b) γ -iron
- c) δ -iron
- d) β -iron

✓ Answer: a

4. Ferrite has which type of crystal structure?

- a) FCC
- b) BCC
- c) HCP
- d) Orthorhombic

✓ Answer: b

5. The carbon solubility in ferrite is approximately _____.

- a) 0.02%
- b) 0.8%
- c) 2.14%
- d) 6.67%

✓ Answer: a

6. Cementite is a compound of _____.

- a) Fe_2O_3
- b) Fe_3C
- c) FeO
- d) FeC

✓ Answer: b

7. Cementite contains approximately _____ carbon.

- a) 0.8%
- b) 2.14%
- c) 4.3%
- d) 6.67%

✓ Answer: d

8. Cementite is known for being _____.

- a) Soft and ductile
- b) Hard and brittle
- c) Magnetic
- d) Elastic

✓ Answer: b

9. Austenite has a _____ crystal structure.

- a) BCC
- b) FCC
- c) BCT
- d) Orthorhombic

✓ Answer: b

10. Austenite is stable at _____.

- a) Room temperature
- b) High temperature
- c) Low temperature
- d) Sub-zero temperature

✓ Answer: b

11. Pearlite is a mixture of _____.

- a) Ferrite and austenite
- b) Ferrite and cementite
- c) Austenite and martensite
- d) Cementite and graphite

✓ Answer: b

12. Pearlite is formed at a carbon content of approximately _____.

- a) 0.02%
- b) 0.8%
- c) 2.14%
- d) 4.3%

✓ Answer: b

13. The eutectoid point in the Fe-C diagram is at _____.

- a) 0.18% C
- b) 0.8% C

c) 2.14% C

d) 4.3% C

✓ Answer: b

14. The eutectic point corresponds to a carbon content of _____.

a) 0.8%

b) 2.14%

c) 4.3%

d) 6.67%

✓ Answer: c

15. The peritectic reaction occurs at _____.

a) 0.8% C

b) 0.18% C

c) 2.14% C

d) 4.3% C

✓ Answer: b

16. The lowest melting point in the Fe-C system occurs at _____.

a) 0.8% C

b) 2.14% C

c) 4.3% C

d) 6.67% C

✓ Answer: c

17. Martensite has a _____ crystal structure.

a) FCC

b) BCC

c) BCT

d) Orthorhombic

✓ Answer: c

18. Which phase is stable at room temperature in pure iron?

a) Austenite

b) Ferrite

c) Cementite

d) Martensite

✓ Answer: b

19. The eutectoid reaction occurs at a temperature of approximately _____.

a) 1147°C

b) 1493°C

c) 727°C

d) 911°C

✓ Answer: c

20. The eutectic reaction occurs at a temperature of about _____.

- a) 1147°C
- b) 727°C
- c) 911°C
- d) 1493°C

✓ Answer: a

21. The eutectic mixture in the Fe-C diagram is known as _____.

- a) Pearlite
- b) Ledeburite
- c) Bainite
- d) Martensite

✓ Answer: b

22. Austenite transforms to pearlite at _____.

- a) Above 911°C
- b) Around 727°C
- c) Below 400°C
- d) 1493°C

✓ Answer: b

23. Martensite is formed by _____.

- a) Slow cooling
- b) Rapid quenching
- c) Annealing
- d) Tempering

✓ Answer: b

24. The line separating ferrite and austenite regions in the Fe-C diagram is called _____.

- a) A₁ line
- b) A₃ line
- c) A₄ line
- d) Solvus line

✓ Answer: b

25. The solubility of carbon in austenite is up to _____.

- a) 0.02%
- b) 0.8%
- c) 2.14%
- d) 4.3%

✓ Answer: c

26. The structure of cast iron mainly depends on _____.

- a) Cooling rate
- b) Carbon content

- c) Both a and b
- d) None

✓ Answer: c

27. Which of the following is a metastable phase?

- a) Ferrite
- b) Pearlite
- c) Cementite
- d) Martensite

✓ Answer: d

28. The hard and brittle phase in steel is _____.

- a) Ferrite
- b) Pearlite
- c) Cementite
- d) Martensite

✓ Answer: c

29. The stable form of iron below 910°C is _____.

- a) α -iron
- b) β -iron
- c) γ -iron
- d) δ -iron

✓ Answer: a

30. The Fe-C phase diagram is valid up to _____ carbon content.

- a) 2.14%
- b) 4.3%
- c) 6.67%
- d) 10%

✓ Answer: c

31. The eutectoid mixture in the Fe-C system is called _____.

- a) Martensite
- b) Pearlite
- c) Ledeburite
- d) Bainite

✓ Answer: b

32. Eutectoid reaction in steel occurs when _____.

- a) Austenite \rightarrow Ferrite + Cementite
- b) Ferrite \rightarrow Austenite
- c) Cementite \rightarrow Austenite
- d) Austenite \rightarrow Martensite

✓ Answer: a

33. The carbon content in eutectoid steel is _____.

- a) 0.02%
- b) 0.8%
- c) 2.14%
- d) 4.3%

✓ **Answer:** b

34. The eutectic reaction in iron–carbon system is _____.

- a) $L \rightarrow \gamma + \text{Fe}_3\text{C}$
- b) $L \rightarrow \alpha + \text{Fe}_3\text{C}$
- c) $\gamma \rightarrow \alpha + \text{Fe}_3\text{C}$
- d) $L + \text{Fe}_3\text{C} \rightarrow \gamma$

✓ **Answer:** a

35. The phase present in hypoeutectoid steel just above 727°C is _____.

- a) Ferrite
- b) Austenite
- c) Pearlite
- d) Cementite

✓ **Answer:** b

36. The phase present below 727°C in eutectoid steel is _____.

- a) Pearlite
- b) Ferrite
- c) Cementite
- d) Martensite

✓ **Answer:** a

37. Hypoeutectoid steels contain _____.

- a) Less than 0.8% carbon
- b) Exactly 0.8% carbon
- c) More than 0.8% carbon
- d) More than 4.3% carbon

✓ **Answer:** a

38. Hypereutectoid steels contain _____.

- a) Less than 0.8% carbon
- b) Exactly 0.8% carbon
- c) More than 0.8% carbon but less than 2.14%
- d) More than 4.3% carbon

✓ **Answer:** c

39. Cast irons contain carbon more than _____.

- a) 0.8%
- b) 2.14%

c) 4.3%

d) 6.67%

✓ **Answer:** b

40. At 4.3% carbon, the alloy becomes _____.

a) Steel

b) Cast iron

c) Wrought iron

d) Ferritic iron

✓ **Answer:** b

41. The eutectic mixture of austenite and cementite is called _____.

a) Pearlite

b) Ledeburite

c) Bainite

d) Martensite

✓ **Answer:** b

42. Ferrite is _____ magnetic at room temperature.

a) Strongly

b) Weakly

c) Non

d) Paramagnetic

✓ **Answer:** a

43. Austenite is _____ magnetic at room temperature.

a) Strongly

b) Non

c) Weakly

d) Ferromagnetic

✓ **Answer:** b

44. Cementite is _____.

a) Soft and ductile

b) Very hard and brittle

c) Very soft and tough

d) Elastic

✓ **Answer:** b

45. Martensite is formed by _____ transformation.

a) Diffusional

b) Non-diffusional

c) Partial diffusion

d) Slow diffusion

✓ **Answer:** b

46. Martensitic transformation occurs during _____.

- a) Heating
- b) Cooling
- c) Isothermal holding
- d) Annealing

✓ **Answer:** b

47. The temperature at which austenite begins to form on heating is called _____.

- a) A_1
- b) A_3
- c) A_4
- d) A_{cm}

✓ **Answer:** b

48. The eutectoid temperature is also called the _____.

- a) A_1 line
- b) A_3 line
- c) A_4 line
- d) Solvus line

✓ **Answer:** a

49. The structure of hypoeutectoid steel below 727°C is _____.

- a) Ferrite + Pearlite
- b) Pearlite + Cementite
- c) Ferrite + Cementite
- d) Austenite + Cementite

✓ **Answer:** a

50. The structure of hypereutectoid steel below 727°C is _____.

- a) Ferrite + Pearlite
- b) Pearlite + Cementite
- c) Ferrite + Cementite
- d) Pearlite only

✓ **Answer:** b

51. The carbon content of pure iron is _____.

- a) 0%
- b) 0.02%
- c) 0.8%
- d) 2.14%

✓ **Answer:** a

52. Austenite can dissolve up to _____ carbon at 1147°C .

- a) 0.02%
- b) 0.8%

c) 2.14%

d) 4.3%

✓ **Answer:** c

53. Cementite appears as _____ in microstructure.

a) Dark plates

b) Bright plates

c) Light network

d) None

✓ **Answer:** b

54. The main constituent of white cast iron is _____.

a) Graphite

b) Cementite

c) Ferrite

d) Austenite

✓ **Answer:** b

55. The eutectic reaction in Fe-C occurs at _____°C.

a) 727

b) 911

c) 1147

d) 1493

✓ **Answer:** c

56. δ -ferrite is stable between _____.

a) Room temp – 912°C

b) 912°C – 1394°C

c) 1394°C – 1538°C

d) Above 1538°C

✓ **Answer:** c

57. The crystal structure of δ -ferrite is _____.

a) BCC

b) FCC

c) BCT

d) Orthorhombic

✓ **Answer:** a

58. The phase existing just below 912°C in pure iron is _____.

a) δ -ferrite

b) γ -austenite

c) α -ferrite

d) Cementite

✓ **Answer:** b

59. The carbon content at eutectic point is _____.

- a) 0.02%
- b) 0.8%
- c) 2.14%
- d) 4.3%

✓ **Answer:** d

60. Iron changes from BCC to FCC at about _____.

- a) 727°C
- b) 911°C
- c) 1147°C
- d) 1493°C

✓ **Answer:** b

61. The compound Fe_3C is called _____.

- a) Austenite
- b) Ferrite
- c) Cementite
- d) Martensite

✓ **Answer:** c

62. The term “pearlite” is derived due to its _____ appearance.

- a) Black
- b) Bright
- c) Pearl-like
- d) Dull

✓ **Answer:** c

63. The eutectic composition corresponds to _____.

- a) 0.8% C
- b) 2.14% C
- c) 4.3% C
- d) 6.67% C

✓ **Answer:** c

64. The eutectoid transformation occurs in _____.

- a) Steels
- b) Cast irons
- c) Wrought irons
- d) Pig iron

✓ **Answer:** a

65. Hypoeutectoid steels are softer due to the presence of _____.

- a) Ferrite
- b) Cementite

- c) Pearlite
- d) Martensite

✓ **Answer:** a

66. The melting point of pure iron is approximately ____.

- a) 1147°C
- b) 1394°C
- c) 1538°C
- d) 1600°C

✓ **Answer:** c

67. The transformation temperature of eutectoid steel is ____.

- a) 1147°C
- b) 727°C
- c) 911°C
- d) 1493°C

✓ **Answer:** b

68. The mechanical property of pearlite is ____.

- a) Soft and ductile
- b) Hard and strong
- c) Brittle
- d) Magnetic

✓ **Answer:** b

69. In the Fe–C system, Fe_3C is a ____ compound.

- a) Solid solution
- b) Intermediate compound
- c) Intermetallic compound
- d) Alloy

✓ **Answer:** b

70. The eutectic mixture is a combination of ____.

- a) Ferrite + Pearlite
- b) Austenite + Cementite
- c) Ferrite + Cementite
- d) Austenite + Graphite

✓ **Answer:** b

71. The solidification of cast iron begins at ____.

- a) 1147°C
- b) 1493°C
- c) 727°C
- d) 911°C

✓ **Answer:** a

72. In the Fe–C diagram, line PSK represents _____.

- a) Eutectoid reaction
- b) Eutectic reaction
- c) Peritectic reaction
- d) Solidus line

✓ **Answer:** a

73. In eutectoid steel, structure at room temperature is _____.

- a) Pearlite
- b) Ferrite
- c) Cementite
- d) Martensite

✓ **Answer:** a

74. The hard and brittle constituent in cast iron is _____.

- a) Ferrite
- b) Graphite
- c) Cementite
- d) Pearlite

✓ **Answer:** c

75. The region below 727°C in the Fe–C diagram mainly contains _____.

- a) $\alpha + \text{Fe}_3\text{C}$
- b) $\gamma + \text{Fe}_3\text{C}$
- c) $\alpha + \gamma$
- d) $L + \gamma$

✓ **Answer:** a

76. The eutectic mixture “ledeburite” transforms into _____ upon cooling.

- a) Pearlite + Cementite
- b) Ferrite + Pearlite
- c) Cementite + Graphite
- d) Austenite + Ferrite

✓ **Answer:** a

77. The peritectic reaction in Fe–C system occurs at about _____.

- a) 727°C
- b) 911°C
- c) 1493°C
- d) 1147°C

✓ **Answer:** c

78. The phase diagram helps determine _____.

- a) Hardness
- b) Corrosion rate

c) Phases present at given conditions

d) Grain size

✓ **Answer:** c

79. The percentage of carbon in cast iron lies between _____.

a) 0.02–0.8%

b) 0.8–2.14%

c) 2.14–6.67%

d) 6.67–10%

✓ **Answer:** c

80. Which of the following is *not* a phase in Fe–C system?

a) Ferrite

b) Pearlite

c) Cementite

d) Graphite

✓ **Answer:** d

81. Carbon exists in Fe–C system as _____.

a) Solute element

b) Solvent

c) Compound Fe_3C

d) Free graphite

✓ **Answer:** c

82. The solid solution of carbon in α -iron is called _____.

a) Austenite

b) Ferrite

c) Cementite

d) Martensite

✓ **Answer:** b

83. The microstructure formed at 0.2% carbon after cooling is _____.

a) Ferrite + Pearlite

b) Pearlite only

c) Pearlite + Cementite

d) Ferrite + Cementite

✓ **Answer:** a

84. The Fe–C diagram is drawn up to _____ carbon percentage.

a) 2%

b) 4.3%

c) 6.67%

d) 10%

✓ **Answer:** c

85. The Fe–C diagram is useful for _____.

- a) Predicting hardness
- b) Predicting phase transformations
- c) Measuring strength
- d) Determining density

✓ **Answer:** b

86. The eutectic composition gives _____ melting point.

- a) Maximum
- b) Minimum
- c) Average
- d) Variable

✓ **Answer:** b

87. At 0.8% carbon and 727°C, the phase present is _____.

- a) Austenite
- b) Pearlite
- c) Ferrite
- d) Cementite

✓ **Answer:** b

88. In the Fe–C diagram, the horizontal line at 727°C is known as _____.

- a) Eutectic line
- b) Eutectoid line
- c) Peritectic line
- d) Liquidus line

✓ **Answer:** b

89. Steel having 0.8% carbon is called _____.

- a) Hypoeutectoid
- b) Eutectoid
- c) Hypereutectoid
- d) None

✓ **Answer:** b

90. When austenite cools rapidly, it forms _____.

- a) Pearlite
- b) Bainite
- c) Martensite
- d) Ferrite

✓ **Answer:** c

91. The iron–carbon diagram is plotted up to _____°C.

- a) 1147
- b) 1394

- c) 1538
- d) 1600

✓ **Answer:** c

92. The eutectoid mixture contains _____.

- a) Ferrite + Cementite
- b) Austenite + Cementite
- c) Ferrite + Graphite
- d) Cementite only

✓ **Answer:** a

93. The Fe-C diagram is also called the _____ diagram.

- a) Binary equilibrium
- b) Ternary
- c) Pseudobinary
- d) None

✓ **Answer:** a

94. The hypoeutectoid steel contains _____ ferrite than pearlite.

- a) More
- b) Less
- c) Equal
- d) No

✓ **Answer:** a

95. Cementite is also known as _____.

- a) Iron carbide
- b) Iron oxide
- c) Iron sulphide
- d) Iron nitride

✓ **Answer:** a

96. Which phase has the highest hardness?

- a) Ferrite
- b) Pearlite
- c) Cementite
- d) Martensite

✓ **Answer:** d

97. Which phase has maximum ductility?

- a) Ferrite
- b) Pearlite
- c) Cementite
- d) Martensite

✓ **Answer:** a

98. The Fe–C diagram is used to design _____.

- a) Heat treatment processes
- b) Alloy addition
- c) Surface coating
- d) Welding joints

✓ **Answer:** a

99. Austenite exists between _____°C range in steel.

- a) 400–700°C
- b) 727–1147°C
- c) 911–1394°C
- d) 1394–1538°C

✓ **Answer:** c

100. The Fe–C diagram helps to predict _____.

- a) Microstructure
- b) Grain size
- c) Hardness directly
- d) Corrosion rate

✓ **Answer:** a

Unit 2 – Heat Treatment (100 MCQs)

1. Heat treatment is defined as _____.

- a) Heating metals above melting point
- b) Heating and cooling metals in solid state to get desired properties
- c) Cooling metals in liquid state
- d) Coating metals with oxide layer

✓ **Answer:** b

2. The main purpose of heat treatment is to _____.

- a) Improve color of metal
- b) Obtain desired mechanical properties
- c) Reduce cost
- d) Change shape

✓ **Answer:** b

3. The equilibrium structure of alloys can be predicted using _____.

- a) TTT diagram
- b) Equilibrium diagram
- c) Cooling curve

d) Hardness chart

✓ **Answer:** b

4. Which of the following is not a purpose of heat treatment?

- a) Improve mechanical properties
- b) Relieve stresses
- c) Change dimensions permanently
- d) Refine microstructure

✓ **Answer:** c

5. Hardness of cutting tools can be increased by _____.

- a) Annealing
- b) Hardening
- c) Normalizing
- d) Stress relieving

✓ **Answer:** b

6. Heat treatment improves fatigue strength in parts like _____.

- a) Bolts
- b) Crankshafts
- c) Nuts
- d) Rivets

✓ **Answer:** b

7. Annealing makes steel _____.

- a) Harder
- b) Softer and more machinable
- c) Brittle
- d) Unusable

✓ **Answer:** b

8. Stress relief heat treatment removes stresses caused by _____.

- a) Welding
- b) Machining
- c) Forging
- d) All of these

✓ **Answer:** d

9. Wear resistance can be increased by _____.

- a) Normalizing
- b) Case hardening
- c) Annealing
- d) Stress relieving

✓ **Answer:** b

10. The success of heat treatment depends on controlling _____.

- a) Heating rate
- b) Soaking time
- c) Cooling rate
- d) All of these

✓ **Answer:** d

11. During soaking, the part is _____.

- a) Rapidly cooled
- b) Held at constant temperature
- c) Hammered
- d) Tempered

✓ **Answer:** b

12. The unit of soaking time is _____.

- a) Minutes
- b) Hours
- c) Seconds
- d) Both a and b

✓ **Answer:** d

13. The cooling rate decides the _____ of the material.

- a) Color
- b) Microstructure
- c) Weight
- d) Composition

✓ **Answer:** b

14. The atmosphere in the furnace is controlled to avoid _____.

- a) Oxidation
- b) Decarburization
- c) Both a and b
- d) None

✓ **Answer:** c

15. Hardening and tempering is also known as _____.

- a) Case hardening
- b) Through hardening
- c) Nitriding
- d) Carbonitriding

✓ **Answer:** b

16. Hardening involves _____.

- a) Heating and slow cooling
- b) Heating and rapid cooling

- c) No heating
- d) Heating above melting point

✓ **Answer:** b

17. The medium used for quenching can be _____.

- a) Water
- b) Oil
- c) Salt bath
- d) All of these

✓ **Answer:** d

18. The key factors affecting hardening are _____.

- a) Composition of steel
- b) Size and shape of part
- c) Cooling rate
- d) All of these

✓ **Answer:** d

19. Hardening process is generally used for _____.

- a) Medium carbon steels
- b) Low carbon steels
- c) Stainless steels
- d) Cast irons

✓ **Answer:** a

20. The process of adding carbon to the surface of steel is called _____.

- a) Nitriding
- b) Carburizing
- c) Tempering
- d) Annealing

✓ **Answer:** b

21. Carburizing increases _____.

- a) Surface hardness
- b) Core toughness
- c) Both a and b
- d) None

✓ **Answer:** c

22. Carburizing is suitable for _____.

- a) Low carbon steels
- b) Medium carbon steels
- c) High carbon steels
- d) Cast irons

✓ **Answer:** a

23. The diffusion of carbon occurs during _____.

- a) Carburizing
- b) Tempering
- c) Annealing
- d) Normalizing

✓ **Answer:** a

24. Gas carburizing is carried out in a _____.

- a) Solid medium
- b) Gas medium
- c) Liquid medium
- d) None

✓ **Answer:** b

25. In pack carburizing, the medium used is _____.

- a) Ammonia
- b) Charcoal
- c) Salt bath
- d) Oil

✓ **Answer:** b

26. Liquid carburizing uses _____.

- a) Molten cyanide salts
- b) Molten copper
- c) Oil
- d) Water

✓ **Answer:** a

27. Carburized steel has _____ surface and _____ core.

- a) Soft, hard
- b) Hard, tough
- c) Brittle, soft
- d) Ductile, brittle

✓ **Answer:** b

28. Carbonitriding introduces _____ into steel.

- a) Carbon
- b) Nitrogen
- c) Both carbon and nitrogen
- d) Hydrogen

✓ **Answer:** c

29. Temperature range for carbonitriding is _____.

- a) 500–600°C
- b) 700–800°C

- c) 850–880°C
- d) 950–1050°C

✓ **Answer:** c

30. Carbonitriding is best suited for _____.

- a) Low carbon steels
- b) High carbon steels
- c) Cast iron
- d) Stainless steel

✓ **Answer:** a

31. The main advantage of carbonitriding is _____.

- a) High cost
- b) Shallow case depth
- c) Low cost and good surface hardness
- d) No diffusion

✓ **Answer:** c

32. Case depth achieved in carbonitriding is about _____.

- a) 0.1 mm
- b) 0.3–0.75 mm
- c) 1.5 mm
- d) 3 mm

✓ **Answer:** b

33. Surface hardness after carbonitriding is around _____.

- a) 20 HRC
- b) 30 HRC
- c) 52–56 HRC
- d) 65 HRC

✓ **Answer:** c

34. Nitriding involves diffusion of _____.

- a) Nitrogen
- b) Carbon
- c) Both
- d) Hydrogen

✓ **Answer:** a

35. The temperature range for nitriding is _____.

- a) 400–450°C
- b) 540–570°C
- c) 700–800°C
- d) 900–1000°C

✓ **Answer:** b

36. Nitriding is carried out in presence of _____.

- a) Ammonia gas
- b) Oxygen
- c) Steam
- d) Methane

✓ **Answer:** a

37. Nitriding does not require _____.

- a) Quenching
- b) Heating
- c) Furnace
- d) Nitrogen

✓ **Answer:** a

38. Nitriding gives very high _____.

- a) Surface hardness
- b) Core hardness
- c) Ductility
- d) Elongation

✓ **Answer:** a

39. Nitriding case depth ranges between _____.

- a) 0.1–0.5 mm
- b) 1–2 mm
- c) 2–4 mm
- d) 4–6 mm

✓ **Answer:** a

40. White layer in nitriding is also called _____.

- a) Compound zone
- b) Diffusion zone
- c) Austenite layer
- d) Tempered layer

✓ **Answer:** a

41. Diffusion zone in nitriding lies below _____.

- a) White layer
- b) Austenite zone
- c) Case depth
- d) None

✓ **Answer:** a

42. Gas nitriding compound layer thickness is _____.

- a) 10 μm
- b) 20–50 μm

c) 100 μm

d) 1 mm

✓ **Answer:** b

43. Nitriding steels usually contain _____.

a) Cr, Mo, V, Al

b) Ni, Cu, Zn

c) Mn, Si, Ti

d) Pb, Sn, Cd

✓ **Answer:** a

44. Nitriding improves _____.

a) Wear resistance

b) Fatigue life

c) Corrosion resistance

d) All of these

✓ **Answer:** d

45. Induction hardening uses _____.

a) Flame

b) Induced current

c) Chemical bath

d) Salt bath

✓ **Answer:** b

46. In induction hardening, heat is generated due to _____.

a) Radiation

b) Conduction

c) Eddy currents

d) Convection

✓ **Answer:** c

47. Induction heating frequency affects _____.

a) Case depth

b) Color

c) Grain size

d) Hardness only

✓ **Answer:** a

48. Medium frequency induction machine operates at _____.

a) 1–10 kHz

b) 50–60 Hz

c) 100–200 Hz

d) 200–500 kHz

✓ **Answer:** a

49. High frequency induction machines work at _____.

- a) 250–425 kHz
- b) 1–10 kHz
- c) 20–50 Hz
- d) 10–100 Hz

✓ **Answer:** a

50. The heat produced in induction hardening depends on _____.

- a) Frequency and current
- b) Temperature only
- c) Time only
- d) Magnetic field only

✓ **Answer:** a

51. Tempering is done after _____.

- a) Annealing
- b) Hardening
- c) Normalizing
- d) Nitriding

✓ **Answer:** b

52. The main purpose of tempering is to _____.

- a) Increase brittleness
- b) Reduce brittleness and improve toughness
- c) Increase hardness
- d) Remove corrosion

✓ **Answer:** b

53. Tempering temperature range for carburized steels is _____.

- a) 100–150°C
- b) 160–180°C
- c) 200–250°C
- d) 300–400°C

✓ **Answer:** b

54. Direct hardening steels are tempered at _____.

- a) 160–180°C
- b) 200–450°C
- c) 500–600°C
- d) 650°C

✓ **Answer:** b

55. Induction hardened parts are tempered at _____.

- a) 150°C
- b) 180–250°C

c) 300°C

d) 400°C

✓ **Answer:** b

56. Normalizing is done to _____.

a) Refine grain size

b) Relieve stresses

c) Both a and b

d) None

✓ **Answer:** c

57. The cooling medium in normalizing is _____.

a) Water

b) Oil

c) Air

d) Salt bath

✓ **Answer:** c

58. Stress relieving is done at temperatures between _____.

a) 100–200°C

b) 180–650°C

c) 700–900°C

d) 900–1100°C

✓ **Answer:** b

59. Stress relieving is mainly used for _____.

a) Forged components

b) Welded components

c) Castings

d) All of these

✓ **Answer:** d

60. Overheating during heat treatment causes _____.

a) Coarse grains

b) Finer grains

c) Bright color

d) High toughness

✓ **Answer:** a

61. Burning occurs when metal is heated _____.

a) Below critical temperature

b) Near melting point for long time

c) Slowly cooled

d) None

✓ **Answer:** b

62. Decarburization means _____.

- a) Increase of carbon content
- b) Loss of carbon from surface
- c) Increase of nitrogen
- d) None

✓ **Answer:** b

63. Cracks in hardened parts increase with _____.

- a) Higher carbon content
- b) Higher hardening temperature
- c) Faster cooling
- d) All of these

✓ **Answer:** d

64. Distortion or warpage occurs due to _____.

- a) Uneven heating
- b) Improper quenching
- c) Improper fixturing
- d) All of these

✓ **Answer:** d

65. Normalizing temperature range is in _____.

- a) Austenitic region
- b) Ferritic region
- c) Martensitic region
- d) None

✓ **Answer:** a

66. The purpose of annealing is to _____.

- a) Soften metal
- b) Increase hardness
- c) Induce stresses
- d) Reduce ductility

✓ **Answer:** a

67. Slow cooling during annealing is done _____.

- a) In air
- b) In furnace
- c) In oil
- d) In water

✓ **Answer:** b

68. Rapid quenching produces _____.

- a) Pearlite
- b) Martensite

- c) Bainite
- d) Ferrite

✓ **Answer:** b

69. Martensite is characterized by _____.

- a) High hardness
- b) Low toughness
- c) Both a and b
- d) None

✓ **Answer:** c

70. Normalizing results in _____.

- a) Fine grain structure
- b) Coarse grains
- c) Soft metal
- d) None

✓ **Answer:** a

71. Hardening temperature is selected to achieve _____.

- a) Full austenite formation
- b) Partial ferrite
- c) Cementite phase
- d) None

✓ **Answer:** a

72. The medium used for tempering is usually _____.

- a) Oil
- b) Air
- c) Furnace atmosphere
- d) Any of these

✓ **Answer:** d

73. Quenching media must be preheated to avoid _____.

- a) Boiling
- b) Cracks
- c) Explosion
- d) All

✓ **Answer:** d

74. Fire extinguishers near furnaces should be of _____ type.

- a) Water
- b) CO₂ or dry powder
- c) Foam
- d) Sand

✓ **Answer:** b

75. PPE in heat treatment includes _____.

- a) Gloves
- b) Goggles
- c) Apron
- d) All of these

✓ **Answer:** d

76. Oil quenching gives _____ cooling than water.

- a) Slower
- b) Faster
- c) Equal
- d) None

✓ **Answer:** a

77. Quenching medium affects _____.

- a) Case depth
- b) Cooling rate
- c) Hardness
- d) Both b and c

✓ **Answer:** d

78. Normalizing is applied to _____.

- a) Forged parts
- b) Castings
- c) Rolled parts
- d) All

✓ **Answer:** d

79. In tempering, hardness _____.

- a) Increases
- b) Decreases
- c) Remains same
- d) None

✓ **Answer:** b

80. Tempering relieves _____.

- a) Internal stresses
- b) External stresses
- c) Mechanical pressure
- d) All

✓ **Answer:** a

81. Case hardening includes _____.

- a) Carburizing
- b) Nitriding

- c) Carbonitriding
- d) All

✓ **Answer:** d

82. Carburizing temperature is usually around _____.

- a) 600°C
- b) 800°C
- c) 900–950°C
- d) 1000–1100°C

✓ **Answer:** c

83. Carbon potential in carburizing is _____.

- a) 0.2%
- b) 0.4%
- c) 0.75%
- d) 1%

✓ **Answer:** c

84. The microstructure of hardened steel consists of _____.

- a) Ferrite
- b) Martensite
- c) Pearlite
- d) Bainite

✓ **Answer:** b

85. After carburizing, parts are usually _____.

- a) Quenched
- b) Air cooled
- c) Oil cooled
- d) Both a and c

✓ **Answer:** d

86. Normalizing helps in obtaining _____.

- a) Uniform microstructure
- b) Variable hardness
- c) High brittleness
- d) Non-uniform grains

✓ **Answer:** a

87. Decarburization can be avoided by _____.

- a) Controlled atmosphere
- b) Rapid cooling
- c) Heating above melting
- d) Using oil

✓ **Answer:** a

88. Nitriding improves corrosion resistance due to _____.

- a) Nitrogen layer
- b) Carbon layer
- c) Chromium
- d) None

✓ **Answer:** a

89. The maximum hardness in nitriding exceeds _____.

- a) 100 Hv
- b) 500 Hv
- c) 1000 Hv
- d) 1500 Hv

✓ **Answer:** c

90. The distortion in parts during heat treatment can be minimized by _____.

- a) Slow heating and cooling
- b) Rapid quenching
- c) Random heating
- d) Overheating

✓ **Answer:** a

91. The compound zone in nitriding is sometimes called _____.

- a) White layer
- b) Black layer
- c) Diffusion layer
- d) Surface oxide

✓ **Answer:** a

92. Medium carbon steel examples include _____.

- a) EN8, C40, C45
- b) EN19, EN24
- c) EN31
- d) All of these

✓ **Answer:** d

93. Cracking tendency increases with _____.

- a) High carbon and fast cooling
- b) Low carbon and slow cooling
- c) Both
- d) None

✓ **Answer:** a

94. The main purpose of stress relieving is to _____.

- a) Increase strength
- b) Relieve internal stress

- c) Refine grains
- d) None

✓ **Answer:** b

95. In induction hardening, surface heating is achieved by _____.

- a) Induced current
- b) Radiation
- c) Convection
- d) Conduction

✓ **Answer:** a

96. In annealing, the structure becomes _____.

- a) Coarse pearlite
- b) Fine pearlite
- c) Martensite
- d) Bainite

✓ **Answer:** a

97. In normalizing, the structure becomes _____.

- a) Fine pearlite
- b) Coarse pearlite
- c) Martensite
- d) Austenite

✓ **Answer:** a

98. TTT diagram is used to study _____.

- a) Transformation of austenite
- b) Melting point
- c) Crystal defects
- d) Hardness

✓ **Answer:** a

99. TTT diagram helps to design _____.

- a) Heat treatment cycles
- b) Tool shape
- c) Casting molds
- d) Welding electrodes

✓ **Answer:** a

100. Heat treatment mainly aims at _____.

- a) Controlling microstructure
- b) Increasing mass
- c) Removing surface
- d) Changing composition

✓ **Answer:** a

