

1. Hardness of a material is the measure of its
- A) Resistance to corrosion
  - B) Resistance to indentation or scratching
  - C) Resistance to fatigue failure
  - D) Thermal conductivity

**Answer: B**

2. Hardenability is the ability of steel to
- A) Harden only at surface
  - B) Harden in depth under quenching
  - C) Become soft during cooling
  - D) Resist crack formation

**Answer: B**

3. Hardness is a \_\_\_\_\_ property.
- A) Surface
  - B) Core
  - C) Electrical
  - D) Thermal

**Answer: A**

4. Hardenability is measured using
- A) Rockwell test
  - B) Izod test
  - C) Jominy test
  - D) Vickers test

**Answer: C**

5. In Jominy test, water stream is applied
- A) Over full length
  - B) Only at one end
  - C) Only at center
  - D) To both ends

**Answer: B**

6. The hardness in Jominy test is measured
- A) At top only
  - B) At quenched end only
  - C) At intervals from quenched end
  - D) On unquenched face only

**Answer: C**

7. Grossmann method determines
- A) Grain size number
  - B) Critical diameter
  - C) Impact strength
  - D) Hardness number

**Answer: B**

8. Quench severity is highest in

- A) Still oil
- B) Water
- C) Brine
- D) Air

**Answer: C**

9. In hardness vs hardenability, the correct pair is

- A) Hardness = depth of hardness
- B) Hardenability = surface indentation resistance
- C) Hardness = surface resistance
- D) Hardenability = electrical resistance

**Answer: C**

10. Core hardness means hardness at

- A) Immediate surface
- B) Outer layer
- C) Centre of the material
- D) Heat-affected zone only

**Answer: C**

11. Quenching oil is mainly used for

- A) Fastest cooling
- B) Moderate cooling
- C) Slowest cooling
- D) No cooling

**Answer: B**

12. Air cooling is used in

- A) Hardening
- B) Annealing
- C) Normalizing
- D) Carbonitriding

**Answer: C**

13. The purpose of annealing is to

- A) Increase brittleness
- B) Increase grain size non-uniformity
- C) Soften material
- D) Harden surface

**Answer: C**

14. In annealing cooling occurs

- A) In furnace slowly
- B) In quench tank
- C) In air forcefully
- D) In liquid nitrogen

**Answer: A**

15. Normalising improves

- A) Wear resistance only
- B) Grain refinement & stress relief
- C) Case depth
- D) Colour of steel

**Answer: B**

16. Normalising cooling takes place in

- A) Oil
- B) Furnace
- C) Air
- D) Water

**Answer: C**

17. High distortion is expected in

- A) Furnace cooling
- B) Air cooling
- C) Water quenching
- D) No cooling

**Answer: C**

18. Hardening temperature corresponds to

- A) Austenitic region
- B) Ferritic region
- C) Cementite region
- D) Room temperature

**Answer: A**

19. Which one produces martensite?

- A) Slow cooling
- B) Step cooling
- C) Fast quenching
- D) No cooling

**Answer: C**

20. Best quench medium for **die steel like H13**

- A) Water
- B) Brine
- C) Polymer / air blast
- D) Mercury

**Answer: C**

21. A quenchant must be selected considering

- A) Only cost
- B) Only colour
- C) Steel grade & hardenability
- D) Melting point

**Answer: C**

22. Overheating during heat treatment leads to

- A) Strength increase
- B) Finer grains
- C) Coarse grains & brittleness
- D) Higher ductility

**Answer: C**

23. Burning defect occurs due to

- A) Under-heating
- B) Heating near melting temperature
- C) Low carburization
- D) High quenching oil viscosity

**Answer: B**

24. Decarburization is loss of carbon from

- A) Core
- B) Surface of steel
- C) Internal voids
- D) Grain boundaries only

**Answer: B**

25. Cracks in heat treatment increase with

- A) Lower carbon
- B) Smooth corners
- C) Higher cooling rate
- D) Polishing

**Answer: C**

26. Warpage results due to

- A) Symmetrical heating
- B) Very slow cooling
- C) Uneven quenching & overheating
- D) CNC machining

**Answer: C**

27. For through hardening of medium carbon steel, best quenchant

- A) Still air
- B) Water
- C) Oil
- D) Furnace cooling

**Answer: C**

28. Microstructure of normalized steel is mainly

- A) Pearlite + ferrite
- B) Pure martensite
- C) Pure austenite
- D) White cast iron

**Answer: A**

29. Hardness test scale for steels widely used

- A) HRB
- B) HRC
- C) Shore scale
- D) Moh's scale

**Answer: B**

30. Hardenability curve shows hardness on Y-axis and \_\_\_\_\_ on X-axis

- A) Time only
- B) Carbon percentage
- C) Distance from quenched end
- D) Quench medium name

**Answer: C**

31. Case hardening produces

- A) Hard core, soft surface
- B) Soft surface, soft core
- C) Hard surface, tough core
- D) Full hardness throughout

Answer: C

32. Carburizing is generally applicable to

- A) Low carbon steels
- B) High carbon steels
- C) Aluminium alloys
- D) Cast iron

Answer: A

33. Carbon absorption during carburizing occurs due to

- A) Diffusion
- B) Melting
- C) Electrical breakdown
- D) Shrinkage

Answer: A

34. Gas carburizing atmosphere controls

- A) Carbon potential
- B) Annealing rate
- C) Welding speed
- D) Nitrogen diffusion only

Answer: A

35. Effective case depth in carburized parts is evaluated by

- A) Impact testing
- B) Hardness profile
- C) Chemical corrosion test
- D) Thermal imaging

Answer: B

36. Carbonitriding adds

- A) Carbon only
- B) Nitrogen only
- C) Carbon and nitrogen both
- D) Oxygen and nitrogen

Answer: C

37. Carbonitriding is generally conducted at

- A) 500–600°C
- B) 700–750°C
- C) 850–880°C
- D) 1100–1200°C

Answer: C

38. A major advantage of carbonitriding is

- A) High case depth for heavy sections
- B) It reduces surface wear resistance
- C) Low cost + high hardenability
- D) No heat treatment required later

Answer: C

39. Nitriding temperature range is

- A) 200–300°C
- B) 450–500°C
- C) 540–570°C
- D) 900–1100°C

Answer: C

40. Nitriding achieves surface hardness

- A) 200–300 Hv
- B) 400–500 Hv
- C) >1000 Hv
- D) <300 Hv

Answer: C

41. A nitrided surface contains

- A) Ferrite only
- B) Pearlite only
- C) Compound (white) layer + diffusion zone
- D) Austenite only

Answer: C

42. Nitriding is preferred when

- A) Minimum distortion is desired
- B) Full martensite is required
- C) Recrystallization needs to be avoided
- D) Component must be soft

Answer: A

43. Induction hardening works using

- A) Convection
- B) Conduction
- C) Electromagnetic induction (eddy currents)
- D) Plastic deformation

Answer: C

44. Induction hardening increases

- A) Only ductility
- B) Surface hardness + case depth
- C) Only machinability
- D) Melting point

Answer: B

45. In induction hardening, higher frequency generates

- A) Deeper case
- B) Shallow case
- C) No case
- D) Surface softening

Answer: B

46. Suitable steel for induction hardening must have minimum carbon

- A) <0.05%
- B) <0.20%
- C) >0.37%
- D) >2.0%

Answer: C

47. Tempering is done after hardening to

- A) Increase brittleness
- B) Reduce internal stresses and improve toughness
- C) Remove carbon completely
- D) Eliminate surface hardness

Answer: B

48. Tempering temperature for carburized parts is usually

- A) 50–100°C
- B) 160–180°C
- C) 400–500°C
- D) 700–800°C

Answer: B

49. Higher tempering temperature generally

- A) Increases hardness
- B) Decreases toughness
- C) Reduces hardness but increases toughness
- D) Softens completely

Answer: C

50. Stress relieving is performed to

- A) Increase case depth
- B) Improve plasticity
- C) Remove residual stresses without major microstructural change
- D) Increase carbon content

Answer: C

51. Stress relieving temperature typically ranges

- A) 150–650°C
- B) 900–1100°C
- C) 1200–1400°C
- D) 50–200°C

Answer: A

52. Complete through hardening aims at

- A) Soft surface
- B) Fully martensitic structure
- C) Fully ferritic structure
- D) No phase change

Answer: B

53. Case depth in induction hardening depends on

- A) Only quenching medium
- B) Only tempering time
- C) Frequency and power of coil
- D) Colour of steel

Answer: C

54. Nitriding requires steels containing

- A) Cu & Pb
- B) Al, Cr, Mo, Ni, V
- C) Mg & Si
- D) Sn & Co

Answer: B

55. Advantage of nitriding over carburizing

- A) Higher distortion
- B) No quenching required
- C) Lower hardness
- D) White layer is unwanted only

Answer: B

56. In case hardened parts, failure generally initiates from

- A) Surface only
- B) Core only
- C) Transition region
- D) Outer coating

Answer: C



57. Ideal process for gear teeth wear resistance + tough core

- A) Normalizing
- B) Carburizing + hardening
- C) Cold working
- D) Shot blasting

Answer: B

58. Ideal process for crankshaft pin

- A) Annealing
- B) Induction hardening
- C) Brine quenching
- D) Case carburizing

Answer: B

59. Induction hardening cracks increase with

- A) Higher carbon content
- B) Lower carbon content
- C) Lower hardness
- D) Higher machining allowance

Answer: A

60. For only a particular region of part to be hardened, preferred method

- A) Nitriding
- B) Induction hardening
- C) Full annealing
- D) Normalizing

Answer: B

61. Austenite is stable at

- A) Room temperature
- B) Below 200°C
- C) High temperature region
- D) Freezing temperature

Answer: C

62. Martensite is formed by

- A) Slow cooling
- B) Air cooling
- C) Rapid quenching
- D) Furnace cooling

Answer: C

63. Microstructure formed by slow furnace cooling is mostly

- A) Martensite
- B) Pearlite + ferrite
- C) Austenite
- D) Bainite

Answer: B

64. Bainite forms at

- A) Higher temperature than pearlite
- B) Lower temperature than martensite
- C) Temperature between pearlite and martensite
- D) Melting temperature

Answer: C

65. Martensite is

- A) Very soft
- B) Very hard and brittle
- C) Very ductile
- D) Corrosion-proof layer

Answer: B

66. Critical cooling curve on a TTT diagram is one that

- A) Avoids martensite formation
- B) Just touches the nose of TTT curve
- C) Goes below Ms line directly
- D) Avoids austenite formation

Answer: B

67. On a TTT diagram, transformation begins when the cooling path

- A) Touches the start curve
- B) Touches the finish curve
- C) Touches Ms
- D) Touches Mf

Answer: A

68. The transformation to martensite starts at

- A) A1 temperature
- B) Ms temperature
- C) A3 temperature
- D) Solidus temperature

Answer: B

69. Ms is

- A) Minimum softening temperature
- B) Martensite start temperature
- C) Metal solidification temperature
- D) Matrix shrinking temperature

Answer: B

70. In Iron–Carbon diagram, eutectoid reaction occurs at

- A) 0.8% C and 727°C
- B) 4.3% C and 1147°C
- C) 2.11% C and 950°C
- D) 6% C and 700°C

Answer: A

71. Pearlite forms from austenite at

- A) High cooling rate
- B) Slow cooling rate
- C) No cooling
- D) Sub-zero treatment

Answer: B

72. The structure 100% martensite means

- A) Maximum strength but low toughness
- B) High ductility
- C) No brittleness
- D) Poor hardenability automatically

Answer: A

73. A grain-refined structure results in

- A) Lower strength
- B) Higher strength and toughness
- C) Colour change
- D) Poor machinability always

Answer: B

74. Bainite compared to pearlite has

- A) Lower toughness
- B) Higher toughness
- C) Same hardness
- D) No carbon present

Answer: B

75. The A1 temperature line represents

- A) Eutectoid temperature
- B) Liquidus
- C) Solidus
- D) Melting point

Answer: A

76. Increasing grain size

- A) Increases toughness
- B) Decreases brittleness
- C) Decreases tensile strength
- D) Improves fatigue life

Answer: C

77. Ideal quenchant for minimizing cracking while still achieving full hardness

- A) Brine
- B) Water
- C) Polymer / oil
- D) Air

Answer: C

78. A fully tempered martensite structure gives

- A) Low strength & high brittleness
- B) Balanced hardness + toughness
- C) No microstructure change
- D) No wear resistance

Answer: B

79. During heat treatment, phase transformation starts during

- A) Heating only
- B) Cooling only
- C) Both heating and cooling
- D) No transformation occurs

Answer: C

80. Carbide particles in tempered martensite improve

- A) Strength and wear resistance
- B) Ability to melt easily
- C) Electrical resistance
- D) Magnetic resistance

Answer: A

81. The eutectoid composition of steel is

- A) 0.2%
- B) 0.45%
- C) 0.8%
- D) 2.11%

Answer: C

82. Retained austenite is

- A) Austenite that did not transform during quenching
- B) Austenite formed during tempering
- C) Austenite present only in cast iron
- D) Corrosion layer on gear teeth

Answer: A

83. Austenite transforms to pearlite at

- A) High cooling rate
- B) Moderate cooling rate
- C) Extremely rapid cooling
- D) Very high temperature only

Answer: B

84. Increasing alloying elements such as Cr & Mo

- A) Decrease hardenability
- B) Increase hardenability
- C) Remove hardenability
- D) Cause corrosion

Answer: B

85. Temper embrittlement is caused by
- A) Incorrect tempering temperature selection
  - B) High carbon potential
  - C) Low case depth
  - D) Improper machining

Answer: A

86. Pearlite is a combination of
- A) Ferrite + Bainite
  - B) Ferrite + Cementite
  - C) Austenite + Martensite
  - D) Cementite + Graphite

Answer: B

87. Transformation to martensite is
- A) Diffusion-controlled
  - B) Non-diffusion (shear) transformation
  - C) Liquid-state transformation
  - D) No transformation

Answer: B

88. The TTT "nose" represents
- A) Fastest transformation point
  - B) Highest hardness region
  - C) Corrosion-resistant zone
  - D) Lowest toughness region

Answer: A

89. Bainite microstructure gives
- A) Higher brittleness than martensite
  - B) Higher strength + toughness balance
  - C) Zero hardness always
  - D) Softest steel

Answer: B

90. A fully annealed steel shows
- A) Coarse pearlite
  - B) 100% martensite
  - C) 100% bainite
  - D) Very fine martensite

Answer: A

91. Overheating during heat treatment results in
- A) Finer grains
  - B) Coarse grains and reduced toughness
  - C) Higher ductility
  - D) Lower distortion

Answer: B

92. Burning is caused by
- A) Low quenching rate
  - B) Heating near melting temperature for long duration
  - C) Excessive machining
  - D) Welding only

Answer: B

93. Decarburization is removal of carbon from
- A) Entire cross-section
  - B) Only the surface layer
  - C) Only the core
  - D) Steel grain boundaries

Answer: B

94. Quench cracks occur due to
- A) Slow cooling
  - B) High cooling rate + high carbon
  - C) No heat treatment
  - D) Removing machining allowance

Answer: B

95. Distortion / warpage results from
- A) Uniform quenching
  - B) Uneven heating / uneven quenching
  - C) Slow annealing
  - D) Use of nitriding steels

Answer: B

96. A steel with carbon below 0.37% is not suitable for
- A) Induction hardening
  - B) Welding
  - C) Annealing
  - D) Stress relieving

Answer: A

97. Steel with high carbon & sharp corners is more prone to
- A) Softening
  - B) Cracking
  - C) Decarburization only
  - D) No change

Answer: B

98. To reduce distortion during quenching
- A) Use brine
  - B) Use severe water spray
  - C) Use polymer / oil quench
  - D) Increase quench speed

Answer: C

99. ASTM grain size 6–8 refers to

- A) Very coarse grains
- B) Fine to medium fine grains
- C) No grains present
- D) Cast-iron structure

Answer: B

100. Grain refinement in steels leads to

- A) Increase in brittleness
- B) Decrease in fatigue life
- C) Increase in toughness and strength
- D) Zero hardness

Answer: C

101. A bolt requires core hardness 32–39 HRC → best process

- A) Nitriding
- B) Normalizing only
- C) Through hardening (Hardening + tempering)
- D) Tempering only

Answer: C

102. A gear requires very high surface hardness + wear resistance + tough core

- A) Normalizing
- B) Carburizing + Hardening
- C) Stress relieving
- D) Annealing

Answer: B

103. A rear axle requires hard teeth on surface + soft core

- A) Nitriding
- B) Annealing
- C) Case carburizing + hardening
- D) Normalizing

Answer: C

104. Shock-loaded component requiring low distortion & high wear resistance → preferred

- A) Case carburizing
- B) Nitriding
- C) Carbonitriding
- D) Shot peening

Answer: B

105. For large components where deep hardness is needed → best property

- A) High hardness
- B) High hardenability
- C) High machinability
- D) High electrical resistance

Answer: B

106. For cheap surface hardening of low-carbon steel → preferred

- A) Annealing
- B) Carbonitriding
- C) Nitriding
- D) Laser hardening

Answer: B

107. For spot hardening of a single region (e.g., cam lobe)

- A) Full carburizing
- B) Induction hardening
- C) Annealing
- D) Normalizing

Answer: B

108. To obtain 50% martensite at centre of a bar, we refer to

- A) Jominy test
- B) Grossmann's critical diameter method
- C) Izod impact test
- D) Rockwell test

Answer: B

109. Hardenability differs from hardness because it measures

- A) Hardness of the surface only
- B) Hardness value during machining
- C) Depth up to which hardness is achieved
- D) Machinability

Answer: C

110. The heat treatment process that produces lowest distortion

- A) Carburizing
- B) Nitriding
- C) Induction hardening
- D) Brine quenching

Answer: B

111. Low hardness after quenching may be due to

- A) Low carbon
- B) Under-austenitizing
- C) Too slow quench cooling
- D) All of the above

Answer: D

112. Tooth pitting failure in gears can be minimized by

- A) Increasing case depth
- B) Using air cooling
- C) Full annealing
- D) Removing core strength

Answer: A



113. After carburizing, tempering is done to

- A) Remove case
- B) Soften core
- C) Reduce brittleness and stabilize case
- D) Convert martensite to ferrite fully

Answer: C

114. After induction hardening, tempering is done to

- A) Reduce brittleness of surface layer
- B) Remove compound zone
- C) Remove case depth
- D) Increase annealing

Answer: A

115. Carbon content increases hardenability until approx.

- A) 0.2%
- B) 0.4%
- C) 0.8%
- D) 2.1%

Answer: C

116. The best quenchant for minimum cracks + controlled cooling

- A) Water
- B) Brine
- C) Oil / Polymer
- D) Air

Answer: C

117. Heat-treatment defect NOT caused by quenching

- A) Cracking
- B) Warpage
- C) Decarburization
- D) Distortion

Answer: C

118. The very fast transformation time is indicated on TTT curve at

- A) Far right
- B) Centre
- C) "Nose"
- D) End of curve

Answer: C

119. The best process when both surface and core must be hardened

- A) Through hardening
- B) Annealing
- C) Stress relieving
- D) Normalizing

Answer: A

120. The best method to harden only outer 1–2 mm without affecting core

A) Nitriding

B) Induction hardening

C) Annealing

D) Air cooling

Answer: B