




www.TPCpage.com

CAT. NO. 071-04-**A**

Digital Pressure Sensor

Series SPSA



- High accuracy semi conductor pressure sensor
- High brightness red LED.(Digit:9.5mm)
- Convertible pressure unit
- Various output modes
- Chattering prevention function of output
- Current protection circuit, Reverse power polarity protecting circuit
- Convertible Analog output(1-5VDC) scale



A Business Unit of TANHAY



www.tanhay.com



ISO 9001 CERTIFIED 「EM」, 「CE」 「UL」 MARK

Digital pressure Sensor

Series SPSA



Precision measurement of Pneumatic Pressure in Piping and Pneumatic products is necessary in being used in Industrial Progress, Inspection Progress, Control & Analysis Equipments.

Digital Sensors of TPC can effectively protect equipments by extraordinary pressure control from various and obstacle factors such as supply pressure, flow, ambient temperature change etc.

Digital Sensors of TPC furnish the greatest stabilized conditions with accuracy and precision control.

Digital Pressure Sensor

Series SPSA



- High accuracy semi conductor pressure sensor
- High brightness red LED.(Digit:9.5mm)
- Convertible pressure unit
- Various output modes
- Chattering prevention function of output
- Anglog output(1-5VDC)
- Current protection circuit, Reverse power polarity protecting circuit

How to order

SPS **A** **—** **V** **01** **P**

1 2 3 4 5 6

1 Model
SPS : Pressure Sensor

2 Body Type
A : Square(30mm×30mm)

3 Rating Pressure

Type	Range of Rating Pressure
01	0~100kPa(14.5psi)
1	0~1000kPa(145psi)
V01	-101.3~0kPa(-14.7~0psi)
C01	-100.0~100kPa(-14.5~14.5psi)

※ Blank : Standard pressure
V : Negative pressure(Vacuum)
C : Vacuum, Low pressure

4 Output
Blank : NPN Open Collector Output
P : PNP Open Collector Output

5 Port Size
Blank : Rc(PT) 1/8
U : NPT 1/8

6 Option
Blank : With Bracket(Bracket A, B)
C : Panel Mounting Bracket(PSO-01)
D : Panel Mounting Bracket
+Front Protection Cover(PSO-01+ PSO-02)

Pressure and Max. pressure display range

Pressure type	kPa	kgf/Cm ²	bar	psi	mmHg	inHg	mmH ₂ O
Negative pressure	0~-101.3 (5.0~-101.3)	0~-1.034 (0.051~-1.034)	0~-1.034 (0.05~-1.034)	0~-14.70 (0.72~-14.70)	0~-760 (38~-760)	0~-29.9 (1.5~29.9)	0~-103.4 (5.1~103.4)
Standard pressure	0~100.0 (-5.0~110.0)	0~1.020 (-0.051~1.122)	0~1.020 (-0.050~1.100)	0~14.50 (-0.72~15.90)	-	-	-
	0~1000 (-50~1013)	0~10.20 (-0.51~11.22)	0~10.20 (-0.50~11.00)	0~145.0 (-7.2~159.0)	-	-	-

※() is Max. pressure display range.

※mmH₂O Unit : Displayed pressure numberX100

Input conversion chart

from to	Pa	kPa	MPa	kgf/Cm ²	mmHg	mmH ₂ O	psi	bar	inHg
1kPa	1000.000	1	0.001000	0.010197	7.500616	101.9689	0.145038	0.010000	0.2953
1kgf/Cm ²	98069.10	98.06910	0.098069	1	735.5787	10000.20	14.22334	0.980691	28.95979
1mmHg	133.3220	0.133322	0.000133	0.001359	1	13.5954	0.019336	0.001333	0.039370
1mmH ₂ O	9.80665	0.00980	-	0.000099	0.0735578	1	0.00142	0.000098	0.002895
1psi	6894.939	6.89493	0.00689	0.070307	51.71630	703.07	1	0.068947	2.036074
1pa	100000.0	100.0000	0.100000	1.019689	750.062	10196.89	14.50339	1	29.52998
1inHg	3386.388	3.386388	0.003386	0.034530	25.40000	345.3240	0.491141	0.033863	1

Ex) When need to calculate 760mmHg as Pa unit.

: According to above chart, 1mmHg is 0.133322kPa, therefore 760mmHg will be 760x0.133322kPa=101.32472kPa.



Please read "Caution for your safety" in operation manual before using.



Specifications

Pressure type		Gauge pressure				
		Negative pressure type	Standard pressure type			
Model	NPN	SPSA-V01	SPSA-01	SPSA-1	SPSA-C01	
	PNP	SPSA-V01P	SPSA-01P	SPSA-1P	SPSA-C01P	
Rated pressure range		0.0~101.3kPa(0.0~14.7psi)	0.0~100.0kPa(0.0~14.5psi)	0.0~1,000kPa(0.0~145psi)	-100.0~100kPa(-14.5~14.5psi)	
Display pressure range		5.0~101.3kPa (0.72~14.7psi)	-5.0~110.0kPa (-0.72~15.9psi)	-5.0~1,100kPa (-7.25~159.5psi)	-101.3~110kPa (-14.7~15.9psi)	
Max. pressure range		2 times of rating pressure		1.5 times of rating pressure	2 times of rating pressure	
Applicable fluid		Air, Non-corrosive gas				
Power supply		12~24VDC±10%(Ripple P-P : Max. 10%)				
Current consumption		Max. 50mA				
Control output		· NPN open collector output ≡ Load current : Max. 100mA, Load voltage : Max. 30VDC, Residual voltage : Max. 1V · PNP open collector output ≡ Max. sink current : Max. 100mA, Residual voltage : Max. 2V				
		Hysteresis	1digit(2digit/psi) fixed		2digit/psi fixed	
		Repeat error	±0.2% F · S ±1digit		±0.2% F · S ±2digit	
		Response time	Selectable 2.5ms, 5ms, 100ms, 500ms			
		Short circuit protection	Built-in			
Analog output		· Output voltage: 1V-5VDC±2% F.S. · Zero point: Within 1VDC±2% F.S.		· Resolution: Approx. 1/200 · Linear: Within ±2% F.S.	· Span: Within 4VDC ±2% F.S. · Output impedance: 1kΩ	
Display method		3 1/2 digit LED 7Segment				
Min. display interval		1 digit(2digit/psi)			2digits	
Display Pressure unit		kPa, kgf/Cm², bar, psi mmHg, mmH₂O, inHg	kPa, kgf/Cm², bar, psi		kPa, kgf/Cm², bar, psi mmHg, mmH₂O, inHg	
Characteristic of control output and displayed temp		Max. ±1% F.S.			Max. ±2% F.S.	
Analog output temperature characteristic		Max. ±2% F.S. (25℃(77°F) standard)				
Environment	Ambient temperature	-10℃ to ±50℃(14~122°F)(at non-dew status)				
	Storage temperature	-20℃ to ±60℃(-4~140°F)(at non-freezing status)				
	Ambient humidity	35 to 85% RH				
	Storage humidity	35 to 85% RH				
	Vibration	1.5mm amplitude at frequency of 10 to 55Hz in each of X, Y, Z directions for 2 hours				
Material		Front case : PC, Rear case : PC(Insert glas), Pressure port : die-cast(Zn)				
Protection structure		IP40(IEC standard)				
Cable		5P, Ø4, Length : 2m(0.2mm2)				
Acquirement standard		CE				
Weight		Approx. 120g(4.23oz)				


※Weight : not including carton

※F.S. : Full Span


※(*1) Output operating, hysteresis is adjustable in F-1 mode

※(*2) ±1% F.S. or less (25℃)

Analog output voltage-Pressure characteristic




Analog output voltage linear



Dimensions


Product

(Unit : mm)




Fixed Bracket Dimensions

●Bracket A




●Bracket B




Panel Mounting Bracket Dimensions


●Accessory(Optional)




PSO-01




●Bracket-A



●Accessory:front protection Cover(Optional)




PSO-02




When putting front Cover

●Panel cut-out



(Panel thickness 0.8mm to 3.5mm)


●Bracket-B




※ Bracket- A / B : SPSA only.

Input/Output circuit and connection diagram

NPN open collector output type




PNP open collector output type



※There is no over current protection circuit in analog voltage output type. Do not connect this unit to power source or capacitive load directly.

※Please observe input impedance of connected equipment when using analog voltage output. And be sure with voltage drop by resistance of extended wire.

Front panel identification and function



③ 2 output indicator(Red) : Output 2 is ON, LED will be ON

④ Mode key : Parameter setting mode or preset setting mode, save setting value

⑤ Up key : Set the setting value to upper step in preset setting or pressure unit, output mode, response time, analog output scale, key lock, peak hold value, bottom hold value display in parameter setting.


⑥ Down key : Set setting value to lower step in preset setting or pressure unit, output mode, response time, analog output scale, key lock, peak hold, bottom hold display in parameter setting.

① 3 1/2 LED display(Red) : Display detected pressure, every setting value and display error




② 1 output indicator(Red) : Output 1 is ON, LED will be ON

⑦ Range of rating pressure : It is possible to change the pressure unit in Pressure sensor. Please use different unit as label for your application.

Setting



Zero point adjustment




1. In state of atmospheric pressure during RUN mode, press ▼ Key and ▲ Key at the same time for over 1 sec.

2. When the zero point adjustment is completed, it will display **0.0** and return to RUN mode automatically.

If execute Zero point when external pressure has been applied, **Er 1** will be flashing. Please execute Zero point again in state of atmospheric pressure.

※Please execute Zero point adjustment regularly.


Setting parameter




- ※When entering into Parameter setting mode and preset setting mode, it displays "Setting item" and "Previous setting value" by 0.5sec. turn.
- This display will stop by pressing ▼ or ▲ Key(Display setting value), if no key touched for over 1 sec., it will display old value by 0.5sec. turn again.
- ※If no key touched for 60sec. during setting, it will display previous setting value not current setting.
- ※Please check preset value again when changing the output mode.
- ※If changing pressure display unit, preset setting value will be changed automatically.
- ※There is memory retention by EEPROM, but life cycle of EEPROM is 100,000 times.

Preset value setting


Hysteresis mode(F-1) and 1 independent(F-3,F-4,F-5) output mode



Automatic sensitivity setting mode(F-2)



Window (F-6)




- Please check the preset value again when changing output operation mode.
- When changing the display unit, preset value will be calculated according to the display unit.
- If no key touched for 60sec., it will return to RUN mode. [automatic sensitivity setting mode(F-2) is exception]
- Whenever key touched one time, 2digits increased(decreased) but it will be continuously increasing(decreasing) by pressing key constantly.

Peak hold and Bottom hold

1. Press \square for more than 3sec. in RUN mode.
 2. **PEH** and memorized max. pressure(Negative type is for max. vacuum pressure) will flicker by turning on(0.5sec.)
 3. **boH** and memorized min. pressure(Negative type is for min. vacuum pressure) will flicker by turning on(0.5sec.) then display Bottom hold value.
 4. If press \square Key one time shortly, memorized Peak hold and Bottom hold value will be removed then return to RUN mode.
- ※ When the Peak hold and Bottom hold value is over the max. display pressure value, it displays **HHH**, On the opposite, it displays **LLL**.

Output operation mode

1. Hysteresis mode(F-1)



※It can be set for pressure detection lever(St1) and detection difference(St2)


※St1 setting range : Min.value of specified prssure ≤ St1 ≤

Max.value of specified pressure

St2 setting range : Min.value of specified pressure ≤ St2 < St1

- OUT 1 : When applying pressure is larger than St1, it will be ON.
- OUT 2 : When applying pressure is lower than St2, it will be ON.

2. Automatic sensitivity setting mode(F-2)



※This function is to set pressure detection level to the proper position automatically, it is set by received pressure from two position(St1, St2)

※SET value will be calculated as below.

$$\text{SET value} = \frac{(\text{St1} + \text{St2})}{2}$$

- OUT 1 : When applying pressure is larger than SET value, it will be ON.
- OUT 2 : When applying pressure is between St1 and St2, it will be ON.


Note1) If there is not enough difference of detecting level between St1 and St2, **Er3** will be displayed.

Please set again after applying enough pressure.

Note2) When need fine adjustment for detection level, adjust detection level(SET) by Key.

(Adjustment range : Between St1 and St2)

3. Independent 2 output mode(F-3, F-4, F-5)



※St1 and St2 can be set independently within specified pressure range.

※One is for control, the other is for alarm or optional control.

※St1 setting range : Min.value of specified pressure ≤ St1 ≤ Max. value of specified pressure

St2 setting range : Min.value of specified pressure ≤ St2 ≤ Max. value of specified pressure

●2 Independent output mode(F-3)

- OUT 1 : It will be ON, when it is beyond St1.
- OUT 2 : It will be ON, when it is beyond St2.


●2 Independent opposite mode(F-4)

- OUT 1 : It will be OFF, when it is beyond St1.
- OUT 2 : It will be OFF, when it is beyond St2.

●2 Independent cross mode(F-5)

- OUT 1 : It will be OFF, when it is under St1.
- OUT 2 : It will be ON, when it is under St2.

4. Window mode(F-6)



※It is able to set Lo/Hi-limit value of pressure detection level in this mode.

※Lo setting range : Min.value of specified prssure ≤ Lo ≤ Max.value of specified pressure

Hi setting range : Lo < Hi ≤ Max.value of specified pressure

- OUT 1 : It will be ON between High limit value(Hi) and Low limit value (Lo)
- OUT 2 : It will be ON when it is beyond High limit value(Hi) and Low limit value (Lo)

Function

1. Change of display unit

SPSA-V01(P) and SPSA-C01(P) has 7 kinds of pressure unit. SPSA-01(P) and SPSA-1(P) has 4 kinds of pressure unit. Please select the proper unit for application.

- SPSA-V01(P), SPSA-C01(P) : kPa, kgf/cm², bar, psi, mmHg, inHg, mmH₂O
- SPSA-01(P), SPSA-1(P) : kPa, kgf/cm², bar, psi

2. Change of output mode

There are 6 kinds of control output mode in order to realize the various pressure detection. Select a mode for your proper application.

- Hysteresis mode(F-1) : When needed to change hysteresis for detecting pressure.
- Automatic sensitivity setting mode(F-2) : When needed to set detection sensitivity automatically at proper position.
- Independent 2 output mode(F-3, F-4, F-5) : When needed to detect pressure from two position with one product.
- Window comparative output mode(F-6) : When needed to detect pressure in certain area.

3. Change of response time(Chattering prevention)

It can prevent chattering of control output by changing response time. It is able to set 4 kinds of response time(2.5ms, 5ms, 100ms, 500ms) and if the response time is getting longer, the detection will be more stable by increasing the number of digital filter.

4. Change of Analog output scale

It is not set the analog output(1-5VDC) scale as a rated pressure range but also this is a function to change properly for user application. It setting A1 position for 1VDC output and A5 position for 5VDC output, the pressure range of A1 to A5 is to 5VDC analog output. Therefore analog output will be 1-5VDC between A1 and A5.

5. Key lock function

This unit has 2 kinds of key lock function in order to prevent wrong operation.

- **Loc** : All keys are locked therefore it is impossible to change any parameter setting preset, Zero point adjustment, Peak hold and Bottom hold.(Able to change the status of lock)
- **PA.L** : This is partial locked status, therefore it is impossible to change parameter setting(Able to change the status of lock) only, the rest functions can be changed.
- **UnL** : All of the setting is available, all keys are unlocked.

6. Zero point adjustment function

This function is to set the display value pressure as Zero point forcibly in case that of port is opened to atmospheric pressure.

7. Peak hold and Bottom hold function


This function is to diagnosis malfunction of the system caused by parasitic pressure or to check through memorizing the max. /min, pressure occurred from the system.

8. Error



Error display	Problem	Remedy
Er1	If external pressure applied, when adjusting Zero point	Please try again after external pressure removing
Er2	When overloaded on control output	Remove overload
Er3	When the setting value is not matched with setting condition	Set proper setting value after checking setting condition
HHH	When the applied pressure exceeds the upper display pressure range up	Apply pressure within display pressure range
LLL	When the applied pressure exceeds the lower display pressure range down	

Installation

1. When installing pressure port it is able to bring pressure from 3 directions by changing the mounting direction of the pressure port.




2. Pressure port is PT1/8 it is able to use general on touch fitting.
3. Please use seal tape at port plug in order to prevent pressure leak.
4. Please block another two pressure ports not used with port plug.
5. Please connect it by using spanner(13mm) at the metal part in order not to overload on the body when connecting one touch fitting.



⚠ Caution


The tightening torque of one touch fitting should be Max 10N·m. it may cause mechanical trouble.

6. SPSA series has 2 kinds of brackets so it is able to install it in two different ways.
7. At first, please unscrew hexagon wrench bolt and assemble the bracket on this unit by fixing the hexagon wrench bolt.



In this case, tightening torque of hexagon wrench should be max. 3N·m. It may cause mechanical trouble.

8. Bracket(PSO-01) and front protection cover(PSO-02) are optional to sell. Please see the pictures for installation.




Accessories

• Pressure unit label


$\pm 100\text{kPa}$ -101.3kPa 100kPa 1MPa			
$\pm 1.020\text{kgf/cm}^2$	-1.034kgf/cm^2	1.020kgf/cm^2	10.20kgf/cm^2
$\pm 14.50\text{psi}$	-14.70psi	14.50psi	145.0psi
$\pm 1.000\text{bar}$	-1.013bar	1.000bar	10.00bar
$\pm 750\text{mmHg}$	-760mmHg	X10	X10
$\pm 29.5\text{inHg}$	-29.9inHg	X100	X100
$\pm 102.0\text{mmH}_2\text{O}$	$-103.4\text{mmH}_2\text{O}$	X1000	X1000

DISPLAY UNIT LABEL


• Port Plug



• Bracket A



• Bracket B



Caution for using

1. Do not insert any sharp or pointed object into pressure port. It may cause mechanical trouble due to sensor damage.
 2. Be sure that this unit must avoid direct touch with water, oil, thinner etc.
 3. Be sure to avoid transient time(within 3sec.) after initial power on.
 4. When a switching moving regulator is used for power supply, frame ground(F.G) terminal of its power supply part must be grounded.
 5. It may cause malfunction by noise, if wiring with power line or high voltage line.
 6. When moving this unit from warm place to cold place, please remove the humidity on the cover then use it.
 7. Do not press the setting button with sharp or pointed object.
 8. Do not put over 30N tensile strength on connection part or load.
 9. When using mmH_2O unit, please multiply display value by 100.
- ※ It may cause malfunction if above instructions are not followed.**

