

TRINIDAD AND TOBAGO FIRE SERVICE

FIRE REPORT FORM

No. 282

Tunapuna Fire Station

Date Call Received	05/12/2022	Wind: (Strong) (Average) (None)	
Time Call Received	0111 Hours	Owner's Name	Ministry of public Utilities
How Call Received	Over the Wireless from Fire Control		Trinidad and Tobago Telecommunications Services
Address Given			
	Maingot Road, Tunapuna just off of Tunapuna main road	Distance of nearest Hydrant to Fire	
			10 meters
Actual Address of Fire	Same as above	Cause of Fire	
			ACCIDENTAL
Time Appliance Left Station	0113 Hours	Was water supply sufficient? Yes	☒ No
Approx. Distance to Fire	1 Km	L.P.M. Available	4x1000 & 1x350
		L.P.M. Required	1x350

Type of Property

Involved was a wooden pole of diameter 12 inches and a height of approximately 25 ft. Placed at the side of the roadway, approximately 10 meters just off of Tunapuna Main road, that was used for distributing telephone lines within the area. There was also an area designated for garbage where an old wooden bed frame was left at the base of the TSTT pole.

How was Fire Extinguished

500 liters of water passing through the hose reel was used to extinguish both the wooden bed frame and the partially burnt TSTT lines.

Description of Damage

TSTT pole seemed to have rotted from the base, causing it to lean in a southerly direction and coming into contact with the T&Tec single phase lines. There was a discarded wooden bed frame that was under the pole which had severe fire damage. The TSTT lines showed burning, a distance of approximately 7 meters exposing the cable on three separate lines.

Appliances Attending:

Officers Attending:

F.S.S. /O.s Attending:

#654 Water Tanker

#671 Utility

Number of Men Attending:

3132 Firefighter John, 3184 Firefighter Mills, 3427 Firefighter Jones, 3460 Firefighter Ramoutar, 4599 Alfred, 5001 Firefighter Howard.

<i>Professionals</i>	<i>Auxiliary</i>
6	

List of casualties (Including the members of the service) with brief description of injuries and by whom treated.

1.

2.

3.

4.

5.

6.

Date

Signature

Rank

Value of Building \$

\$50,000

Value of Stock \$

Not Applicable

Damage to Building \$

\$50,000

Damage to Stock \$

Building and Stock Insured as follows:

Officer’s Observations

On arrival on Maingot Road just off of Tunapuna Main Road, there a TSTT pole that was rotted at the base that caused the TSTT pole to lean against a single phase electrical line. The TSTT line was well alight causing molten insulation to fall onto the wooden bed frame that was left for rubbish and the roadway.

ADDITIONAL INFORMATION

#8594 Police Constable Arthur and #20201 Woman Police Constable Kelly from Tunapuna Police Station along with #7532 Mohammed in charge and crew from T&Tec were present on the scene.

CAUSE DETERMINATION

Using the scientific method of Fire Investigation, identifying the Origin of the Fire being the TSTT lines and the area directly below on the roadway, There were no other Ignition sources identified within the area of origin other than the single phase electrical lines that came into contact with the TSTT lines and igniting the insulation to its Fire point, causing fire spread along the lines and drop down burning on the wooden bed frame and onto the roadway.