
高通多媒体技术期刊 20160330

QIIALCOMM[®]

Qualcomm Technologies, Inc.

Confidential and Proprietary – Qualcomm Technologies, Inc. 机密和专有信息——高通技术股份有限公司



Confidential and Proprietary – Qualcomm Technologies, Inc.

Confidential and Proprietary - Qualcomm Technologies, Inc.

NO PUBLIC DISCLOSURE PERMITTED: Please report postings of this document on public servers or web sites to: DocCtrlAgent@qualcomm.com. 禁止公开:如在公共服务器或网站上发现本文档,请报告至:DocCtrlAgent@qualcomm.com.

Restricted Distribution: Not to be distributed to anyone who is not an employee of either Qualcomm or its affiliated without the express approval of Qualcomm's Configuration Management. 限制分发:未经高通配置管理部门的明示批准,不得发布给任何非高通或高通附属及关联公司员工的人。 Not to be used, copied, reproduced, or modified in whole or in part, nor its contents revealed in any manner to others without the express written permission of Qualcomm Technologies, Inc. 未经高通技术股份有限公司明示的书面允许,不得使用、复印、 复制、或修改全部或部分文档,不得以任何形式向他人透露其内容。

The user of this documentation acknowledges and agrees that any Chinese text and/or translation herein shall be for reference purposes only and that in the event of any conflict between the English text and/or version and the Chinese text and/or version, the English text and/or version shall be controlling. 本文档的用户知悉并同意中文文本和/或翻译仅供参考之目的,如英文 文本和/或版本和中文文本和/或版本之间存在冲突,以英文文本和/或版本为准。 This document contains confidential and proprietary information and must be shredded when discarded. 未经高通明示的书面允许,不得使用、复印、复制全部或部分文档,不得以任何形式向他人透露其内容。本文档含有高通机密和专有信息,丢弃时必须粉碎销毁。

Qualcomm reserves the right to make changes to the product(s) or information contained herein without notice. No liability is assumed for any damages arising directly or indirectly by their use or application. The information provided in this document is provided on an "as is" basis. 高通保留未经通知即修改本文档中提及的产品或信息的权利。本公司对使用或应用本文档所产生的直接或间接损失概不负责。本文档中的信息为基于现状所提供,使用风险由用户自行承担。

Qualcomm is a trademark of QUALCOMM Incorporated, registered in the United States and other countries. All QUALCOMM Incorporated trademarks are used with permission. Other product and brand names may be trademarks or registered trademarks of their respective owners. Qualcomm是高通公司在美国及其它国家注册的商标。所有高通公司的商标皆获得使用许可。 其它产品和品牌名称可能为其各自所有者的商标或注册商标。

This technical data may be subject to U.S. and international export, re-export, or transfer ("export") laws. Diversion contrary to U.S. and international law is strictly prohibited. 本文档及所含技术资料可能受美国和国际出口、再出口或转移出口法律的 限制。严禁违反或偏离美国和国际的相关法律。

Qualcomm Technologies, Inc. 5775 Morehouse Drive San Diego, CA 92121 U.S.A. 高通技术股份有限公司,美国加利福尼亚州圣地亚哥市莫豪斯路 5775 号,邮编 92121

Revision History

Revision	Date	Description
А	Mar. 2016	Initial release

Note: There is no Rev. I, O, Q, S, X, or Z per Mil. standards.

内容

- Display
 - 8952/8956/8976 与ESD相关的丢帧问题
 - 8956/76 与Rotator相关的丢帧问题
 - 8956/76 显示颜色偏移问题
 - 8996 与MDSS Fence timeout相关的性能问题
 - 8996 4K DSC Panel Support
- Browser
 - M42 fix list until 3/2016





Display

[8952/8956/8976] 与ESD相关的丢帧问题

- 问题描述:
 - 在使能ESD check时,有时候会出现丢帧现象,可以通过systrace log看到丢帧。
- 解决方案:
 - msm: mdss: Reorder mutex locks in ESD thread
 - https://us.codeaurora.org/cgit/quic/la/kernel/msm 3.10/commit/?h=LA.BR.1.3.3_rb2.13&id=fa8c1a8ac93058328dea3f62dfe40092
 2a049d96
 - msm: mdss: Remove unnecessary offlock during fps update
 - https://us.codeaurora.org/cgit/quic/la/kernel/msm-3.10/commit/?h=LA.BR.1.3.3_rb2.13&id=b4f9f017b084a713c2c0252fd57a839e d82c6345
- 补充:
 - 可以通过disable ESD check 来进行确认。

[8956/76]与Rotator相关的丢帧问题

- 问题描述:
 - 在播放视频时,且需要旋转时,有时候会出现卡顿或者丢帧的现象,通过分析 systrace,发现rotator耗时比较多,从而照成在一个Vsync之内没办法完成一帧。
- 解决方案:
 - 具体修改如下

```
diff --git a/drivers/video/msm/mdss/mdss mdp.c b/drivers/video/msm/mdss/mdss mdp.c
index d7e56c4..aa6128a0 100644
--- a/drivers/video/msm/mdss/mdss mdp.c
+++ b/drivers/video/msm/mdss/mdss mdp.c
@@ -3598,9 +3598,9 @@ static void apply dynamic ot limit(u32 *ot lim,
   res = params->width * params->height;
   pr debug("w:%d h:%d rot:%d yuy:%d wb:%d res:%d\n",
   pr debug("w:%d h:%d rot:%d yuy:%d wb:%d res:%d fps:%d\n",
        params->width, params->height, params->is rot,
        params->is yuv, params->is wb, res);
        params->is yuv, params->is wb, res, params->frame rate);
    switch (mdata->mdp rev) {
    case MDSS MDP HW REV 111:
```

[8956/76]与Rotator相关的丢帧问题 -cont1

续上一页,如下

```
diff --git a/drivers/video/msm/mdss/mdss mdp intf writeback.c b/drivers/video/msm/mdss/mdss mdp intf
index cfe54f4..2f3ae06 100644
--- a/drivers/video/msm/mdss/mdss mdp intf writeback.c
+++ b/drivers/video/msm/mdss/mdss mdp intf writeback.c
@@ -330,7 +330,7 @@ static int mdss mdp writeback prepare rot(struct mdss mdp ctl *ctl, void *arg)
   ctx->bwc mode = rot->bwc mode;
   ctx->opmode |= ctx->bwc mode;
+ ctx->frame rate = ctl->frame rate;
   ctx->width = ctx->dst rect.w = rot->dnsc factor w ?
       rot->dst.w / rot->dnsc factor w : rot->dst.w;
    ctx->height = ctx->dst rect.h = rot->dnsc factor h ?
diff --git a/drivers/video/msm/mdss/mdss mdp pipe.c b/drivers/video/msm/mdss/mdss mdp pipe.c
index e5389b4..2f62352 100644
--- a/drivers/video/msm/mdss/mdss_mdp_pipe.c
+++ b/drivers/video/msm/mdss/mdss mdp pipe.c
@@ -1779,6 +1779,7 @@ static void mdss mdp set ot limit pipe(struct mdss mdp pipe *pipe)
    ot params.is rot = pipe->mixer left->rotator mode;
   ot params.is wb = ctl->intf num == MDSS MDP NO INTF;
   ot params.is yuv = pipe->src fmt->is yuv;
  ot params.frame rate = pipe->frame rate;
   mdss mdp set ot limit(&ot params);
```

[8956/76]显示颜色偏移问题

• 问题描述:

- 在使用某些app时,会出现显示异常问题,比如泛红,当时Disable HW Overlay 后,此问题消失。
- 从dumpsys SurefaceFlinger中,可以看到出现问题的layer的format为 RGBA4444。

• 解决方案:

```
diff --git a/drivers/video/msm/mdss/mdss mdp formats.h b/drivers/video/msm/mdss/mdss
index 8475f39..ce46b4a 100644
--- a/drivers/video/msm/mdss/mdss mdp formats.h
+++ b/drivers/video/msm/mdss/mdss mdp formats.h
@@ -269,10 +269,10 @@ static struct mdss mdp format params mdss mdp format map[] = {
        .bpp = 2
        .element = { C2 R Cr, C0 G Y, C1 B Cb, C0 G Y },
    },
    FMT RGB 1555 (MDP RGBA 5551, 1, C2 R Cr, C0 G Y, C1 B Cb, C3 ALPHA),
   FMT RGB 1555 (MDP ARGB 1555, 1, C3 ALPHA, C2 R Cr, C0 G Y, C1 B Cb),
   FMT RGB 4444 (MDP RGBA 4444, 1, C2 R Cr, C0 G Y, C1 B Cb, C3 ALPHA),
   FMT RGB 4444 (MDP ARGB 4444, 1, C3 ALPHA, C2 R Cr, C0 G Y, C1 B Cb),
   FMT RGB 1555 (MDP RGBA 5551, 1, C3 ALPHA, C1 B Cb, C0 G Y, C2 R Cr),
   FMT RGB 1555 (MDP ARGB 1555, 1, C1 B Cb, C0 G Y, C2 R Cr, C3 ALPHA),
   FMT RGB 4444 (MDP RGBA 4444, 1, C3 ALPHA, C1 B Cb, C0 G Y, C2 R Cr),
   FMT RGB 4444 (MDP ARGB 4444, 1, C1 B Cb, C0 G Y, C2 R Cr, C3 ALPHA),
};
```

[8996] 与MDSS Fence timeout相关的性能问题

问题描述:

 在某些场景进行压力测试时,比如camera use-case,有时候会出现来自MDSS fence timeout,从而照成fps比较低,主要由于pingpong done 计数器存在竞争。

解决方案:

- msm: mdss: handle race condition in pingpong done counter
- https://us.codeaurora.org/cgit/quic/la/kernel/msm-3.18/commit/?h=rel/msm-3.18&id=df9c33ad1a248b81dcb10948953f5713a5744694

补充:

此问题发生在command mode panel上。

[8996] 4K DSC Panel Support

▪ 在8996平台上,4K panel with DSC(Display Stream Compression) 支持

- 具体的link:

- dev: gcdb: display: add support for Sharp 4k dsc video panel selection
 https://us.codeaurora.org/cgit/quic/la/kernel/lk/commit/?h=LA.HB.1.3.1&id=8e1ce791aaa1ced74 decc65d574e4f9d1de6d120
- dev: gcdb: display: add support for Sharp 4k dsc cmd panel selection
 https://us.codeaurora.org/cgit/quic/la/kernel/lk/commit/?h=LA.HB.1.3.1&id=330038af8c46b29002a84b3bb546d8e57777289e
- ARM: dts: msm: add sharp dsc 4k video panel support for msm8996 https://us.codeaurora.org/cgit/quic/la/kernel/msm-3.18/commit/?h=rel/msm-3.18&id=6611a5a8470d7cccce90941104af2b1091eacae3
- ARM: dts: msm: fix config-select in sharp dsc 4k video mode panel https://us.codeaurora.org/cgit/quic/la/kernel/msm-3.18/commit/?h=rel/msm-3.18&id=0ddda74441a8f304ecac61ac1fef1c7c82d2d6b3
- ARM: dts: msm: fix panel on cmd for sharp 4k dsc video panel https://us.codeaurora.org/cgit/quic/la/kernel/msm-3.18/commit/?h=rel/msm-3.18&id=a2f1049d2bdfca33d9db20215cb9654d9c6f8e2f
- ARM: dts: msm: add sharp dsc 4k cmd panel support for msm8996 https://us.codeaurora.org/cgit/quic/la/kernel/msm-3.18/commit/?h=rel/msm-3.18&id=8040b58f1ab3ac1c0ee15b5896aefdb5478cfb18





Browser

fix	patches	classification
Fix linux compilation error because of upmerge	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=53a7e 0a7439c090f0dace1aad18e5d4171664b3a	rendering
Change logic for calculating SWE version	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=41f321237bc 5842d343ea0a916aeb59d9d9157f7	rendering
pick from google,BUG=391585	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=e01edcc0fb2 8b20fc82c096a702a05189fdb8b73	rendering
pick from google,BUG=497854	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=3b5dee24c49 8aa9e358655c1d5c04a747367d545	rendering
pick from google,BUG=364522	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=319bc7cee92 6264e01be65246a381a36cdc01b19	rendering
pick from google,BUG=427357	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=b1b5e05507b2145106066c225ee29e3dfad6c252	rendering
pick from google,BUG=364522	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=281fb0d397b f1a34eb809dd21c5f7459317effb4	rendering
pop up FC when use auto-fill function to select Chromium Auto- fill settings	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=e729b74efed dc48ef5b4cdbfc0fe1c954b5b3d52	stability
link to an unavailable web page when invoke gmail/whatsApp	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=43f9a3561f0 4b05a48620c31b30b8a233825fdfb https://codeaurora.org/cgit/quic/chrome4sdp/external/android/packages/apps/browser/commit/?h=m42&id=9169e94d049eab895c54d813701c35111e0ff885 https://codeaurora.org/cgit/quic/chrome4sdp/chromium/blink/commit/?h=m42&id=a3702e9a2 866f50b3ffef133d3a75d22c82e42b8	rendering
Fix The cursor doesn't display when tap input frame to register youku account	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=03080c1f821 9cf922146dece75616344083f112a	rendering
Add support for perflock in Android M	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=55f4fe734b6f 184334ce329090ff423792e97e1d	rendering
Enable swecore for browser. PAGE 13	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=e9b4a7d1042 533cc62d682f3da5a3fa9bc79b6d8 Confidential and Proprietary – Qualcomm Technologies, Inc. MAY CONTAIN U.S. AND INTERNATIONAL EXPO	rendering

fix	patches	classification
GPU channel timeout increased	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=539628fbd03 83b12f9938746ed73d24621b86622	rendering
Update with new MediaStreamInfoBarDelegate::Cr eate	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=9c563b2c1a9 3697a7167e5f723597fac87c97a5b	rendering
Limit the one instance of base to Android	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=6867a84b8f2 855f72468f833fe235370ebf83ab9	rendering
Update TabSettings when global settings changes.	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=9db8f9e6e7e 25ea326eca717aaf8a7f81fff7a7b	rendering
isplays half of screen when play video in Youku	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=8543d6d2ee5 ff74d6e1e4d46174b4bf2bf030faa	rendering
Fix issue the color of background and edittext no change under nightmode	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=9e1b8ddd1ccf7c43e44a1c2fd64d477c749f3c5dhttps://codeaurora.org/cgit/quic/chrome4sdp/chromium/blink/commit/?h=m42&id=bcd2734baaa05b497efc612ceefaa5357cd16df4	ui
Fix browser FC when use night mode	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=fafa3a1aa057 f12bc64a551506b7df95922df655	stability
Do not check Mass Storage state for external storage	https://codeaurora.org/cgit/quic/chrome4sdp/external/android/packages/apps/browser/commit/?h=m42&id=2df97b65a6b188cc9ccb26cfed8149d0cb3cdd46	ui
Fix a monkey crash issue	https://codeaurora.org/cgit/quic/chrome4sdp/external/android/packages/apps/browser/commit/?h=m42&id=5e19904024d5668b149713b7f7399ef052dbc604	stability
Add fast-webview configuration file	https://codeaurora.org/cgit/quic/chrome4sdp/external/android/packages/apps/browser/commit/?h=m42&id=d9c4f0678d2f03ecd81f4b6ba1d2df2ff471fe2f	ui
When firstly add browser widget is abnormal	https://codeaurora.org/cgit/quic/chrome4sdp/external/android/packages/apps/browser/commit/?h=m42&id=58475b15611084ed7871e53f18ec3a842c33d6cd	ui
Guard against null strings	https://codeaurora.org/cgit/quic/chrome4sdp/external/android/packages/apps/browser/commit/?h=m42&id=96096e56cf245e74ee472ea716415ca8283962ea	stability
Fix click some options in promption is invalid after long pressing the link	https://codeaurora.org/cgit/quic/chrome4sdp/external/android/packages/apps/browser/commit/?h=m42&id=d5038b9dfe1a115136595d2597d88876fd6d7e3e	ui

fix	patches	classification
It still can remember data when "Remember form data" function is turn off	https://codeaurora.org/cgit/quic/chrome4sdp/external/android/packages/apps/browser/commit/?h=m42&id=f3ba127232779bdecf590f1c39736fe3beae8262	ui
Fix UI behavior on saved pages	https://codeaurora.org/cgit/quic/chrome4sdp/external/android/packages/apps/browser/commit/?h=m42&id=0024f5449fe04ad904fdae5efdf4c51d12e3f42e	ui
Fix the tab interface display is not complete in landscape mode	https://codeaurora.org/cgit/quic/chrome4sdp/external/android/packages/apps/browser/commit/?h=m42&id=abbe487a1ebd1a10fe3de356f8fa04882359f5df	ui
Fix Video Fullscreen Crash Due To Text Flow Opt	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/blink/commit/?h=m42&id=0089f4587 35945a892a5c73d97fa0832101520e7	stability
Fix a linux build issue	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/blink/commit/?h=m42&id=72acee0ecd3987feddd56c36bcaaafd973909167	rendering
Added support for URL redirection for the download from ContextMenu	https://us.codeaurora.org/cgit/quic/chrome4sdp/external/android/packages/apps/browser/commit/?h=m42&id=10ffa66b401137fd0155d9a080ed0bed52c89082	ui
Fix browser crash on device reboot	https://us.codeaurora.org/cgit/quic/chrome4sdp/external/android/packages/apps/browser/commit/?h=m42&id=fc0e8dab6d0622ddd19575091fecf50bbdd1db8d	ui
Disable gpu rasterization on Adreno 3.x	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=4c9b2acdf8f73a402b3d10d22bc0c66a3a67de3f	rendering
NULL check to fix java.lang.NullPointerExceptio n	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=a84d7ecb09f4b779a2be00117d45dd0ef55bdc0a	ui
Disable partial composition to fix some flicker issue	https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=0b4a4 1594a774b2ab5dbe49f4319977f2a60531d https://codeaurora.org/cgit/quic/chrome4sdp/chromium/src/commit/?h=m42&id=b3fc7 82c8613804210106501bac55ee98591935e	rendering

Besides the fixes,M42 also updates v8 and skia parts to improve the stability in our latest tip.

So we strangely recommend you to sync your m42 codebase to our tip.

Questions?

https://support.cdmatech.com

