


Install heat-set inserts into each part using the plate-press technique.


More info on the plate-press technique can be found here:

https://hackaday.com/2019/02/28/threading-3d-printed-parts-how-to-use-heat-set-inserts/

В

Make four assemblies.





A


ITEM NO. DESCRIPTION		QTY.
1	Corner Foot Plate	4
2	M6 Tapered Heat-Set Insert	4

Heat-Set Insert Installation				
<u></u>	(i) BY	Created by: Joshua Vasquez	last edited: 10/8/2019	
		SCALE: 1:1	SHEET 2 OF 14	

Make 4 assemblies.

Keep these T-Nuts Loose; only two full turns. They will be tightened into the frame later/

В



Assembled View

Exploded View

Screw this foot partway into the assembly such that it protrudes from the top. (Exact amount doesn't matter as the printer will be leveled later.) Ensure that all four feet are approximately even with each other.

A

В


ITEM NO.	DESCRIPTION	QTY.
1	Corner Foot Plate with insert	4
3	M6 Swivel Foot	4
4	M5 x 0.8 Screw, Low Profile, 10mm	12
5	M5 Drop-In T-Nut for 20x20 Extrusion	12

Corner Foot Assembly				
(CC)	(i) BY	Created by: Joshua Vasquez	last edited: 10/8/2019	
		SCALE: 1:1	SHEET 3 OF 14	

Note that these inside-corner brackets should face upwards.

В

Securely screw down all four feet such that they are flush with the inside corners of the frame as shown below.



A


В

ITEM NO.	DESCRIPTION	
1	Base Frame Assembly	1
2	Corner Foot Assembly	4

Corner Foot Installation			
(cc)	•	Created by: Joshua Vasquez	last edited: 10/8/2019
	ВҮ	SCALE: 1:6	SHEET 4 OF 14


Make 3 Assemblies.

В



ITEM NO.DESCRIPTIONQTY.15mm to 8mm flexible plumb coupler12Nema 17 Stepper Motor13Z Thrust Bearing Spacer14M5 Shim, 0.2mm thick1

With one hand, compress the coupler onto the motor shaft to remove any space on the motor shaft. Securely screw down the coupler in this configuration.




7 Motor	Thrust	Coupling	Assembly	,
	HHUSL	Coupling	ASSCITION	У


CC	(i) BY	Created by: Joshua Vasquez	last edited: 10/8/2019
		SCALE: 1:1	SHEET 5 OF 14

В

A

Apply a dab of threadlock to the four M3 screws before tightening them down securely. (M5 screws do not need threadlock.)





В

	\
_	7


В


ITEM NO.	DESCRIPTION	QTY.
1	M5 x 0.8 Screw, Low Profile, 10mm	4
2	M3 Buttonhead Screw, 10mm long	4
3	Back Z Panel	1
4	Z Motor Offset Plate	1
5	M5 Drop-In T-Nut for 20x20 Extrusion	4

	Back Z Motor Plate Assembly 1			
(00)	(i)	Created by:	last edited:	
	BY	Joshua Vasquez	10/8/2019	
		SCALE: 1:1.5	SHEET 6 OF 14	

Apply a dab of threadlock to the four M3 screws before tightening them down securely.

В






A

ITEM NO.	DESCRIPTION	QTY.
2	M3 Buttonhead Screw, 10mm long	4
3	Back Plate Plate Assembly	1
6	Z Motor Thrust Coupling Assembly	1

Back Z Motor Plate Assembly 2			
	\bigcirc	Created by:	last edited:
CC	BY	Joshua Vasquez	10/8/2019
		SCALE: 1:1.5	SHEET 7 OF 14

Apply a dab of threadlock to the four M3 screws before tightening them down securely. (M5 screws do not need threadlock.)

В



Assembled View
Keep these T-Nuts Loose; only two full turns.

They will be tightened into the frame later.

A

ITEM NO.	DESCRIPTION	QTY.
1	M3 Buttonhead Screw, 10mm long	4
2	M5 x 0.8 Screw, Low Profile, 10mm	4
3	Z Motor Offset Plate	1
4	Front Z Panel	1
5	M5 Drop-In T-Nut for 20x20 Extrusion	4


Front Left Z Plate Assembly 1


Created by:
Joshua Vasquez

SCALE: 1:1.5

SHEET 8 OF 14

Apply a dab of threadlock to the four M3 screws before tightening them down securely.





В

A


В


ITEM NO.	DESCRIPTION	QTY.
1	M3 Buttonhead Screw, 10mm long	4
3	Front Left Z-Plate Plate Assembly	1
6	Z Motor Thrust Coupling Assembly	1

	Front Left Z Plate Assembly 2		
(CC)	()	Created by: Joshua Vasquez	last edited: 10/8/2019
		SCALE: 1:1.5	SHEET 9 OF 14

Apply a dab of threadlock to the four M3 screws before tightening them down securely. (M5 screws do not need threadlock.)

В





A

ITEM NO.	DESCRIPTION	QTY.
1	M3 Buttonhead Screw, 10mm long	4
2	Z Motor Offset Plate	1
3	M5 x 0.8 Screw, Low Profile, 10mm	4
4	Front Z Panel	1
5	M5 Drop-In T-Nut for 20x20 Extrusion	4

Front Right Z	Plate Assembly 1
---------------	------------------


a a	Created by:	last edited:
BY	Joshua Vasquez	10/8/2019
	SCALE: 1:1.5	SHEET 10 OF 14


2

•

Apply a dab of threadlock to the four M3 screws before tightening them down securely.

В






A

ITEM NO.	DESCRIPTION	QTY.
1	M3 Buttonhead Screw, 10mm long	4
2	Front Right Z-Plate Plate Assembly	1
6	Z Motor Thrust Coupling Assembly	1


Front Right Z Plate Assembly 2				
(0)	()	Created by: Joshua Vasquez	last edited: 10/8/2019	
		SCALE: 1:1.5	SHEET 11 OF 14	

Adjust the loose internal frame extrusions such that they matches the z motor assemblies. Then tigthen down their set scews.

В



Slide 2 pairs of inside-corner brackets into position between the coupler plates, but do not tighten them.



В

Top View

A

ITEM NO.	DESCRIPTION	
1	Base Frame Assembly with Feet	1
3	Back Z Plate Assembly	1
4	Front Left Z Plate Assembly	1
5	Front Right Z Plate Assembly	1
6	Inside corner bracket	12

Internal Extrusion Alignment				
<u></u>	(i) BY	Created by: Joshua Vasquez	last edited: 10/8/2019	
		SCALE: 1:6	SHEET 12 OF 14	

With the internal frame's extrusions tightened, securely install the 3 Z plate assemblies and tighten them down. tighten √tighten В tighten/ tighten tighten tighten tighten/ tighten tighten tighten tighten tighten

Z Plate Installation

Created by:
Joshua Vasquez

SCALE: 1:4


SHEET 13 OF 14

Top View

2

В

-



The Lower Frame Assembly is complete!

Λ			
_	1		

ITEM NO.	DESCRIPTION	QTY.
1	Lower Frame with Motors Installed	
6	Inside corner bracket	

Inside Corner Bracket Installation				
<u>cc</u>	()	Created by: Joshua Vasquez	last edited: 10/8/2019	
		SCALE: 1:3	SHEET 14 OF 14	