




Populate all screw holes with screws and nuts Keep all nuts loose. Only 1-2 turns. They will be fully tightened into the frame later.









В

Exploded Views









Assembled Views

Α


В

| ITEM NO. | DESCRIPTION | QTY. |
|----------|--------------------------------------|------|
| 1 | Back Right Foot | 1 |
| 2 | Back Left Foot | 1 |
| 3 | Front Right Foot | 1 |
| 4 | Front Left Foot | 1 |
| 5 | M5 Drop-In T-Nut for 20x20 Extrusion | 12 |
| 6 | M5 Buttonhead Screw, 10mm long | 12 |

| Foot Screw Installation | | | |
|-------------------------|----|----------------|---------------|
| | | Created by: | last edited: |
| | ВУ | Joshua Vasquez | 5/27/2020 |
| | | SCALE: 1:2 | SHEET 2 OF 14 |

2


.



Make 3 Assemblies.

В


The shim with a 10mm outer diameter has more surface area than the 7 or 8mm outer-diameter variants.



Exploded View

| ITEM NO. | DESCRIPTION | QTY. |
|----------|-----------------------------------|------|
| 1 | 5mm to 8mm flexible plumb coupler | 1 |
| 2 | Nema 17 Stepper Motor | 1 |
| 3 | Z Thrust Bearing Spacer | 1 |
| 4 | M5 Shim, 0.2mm thick, 10mm OD | 2 |

With one hand, compress the coupler onto the motor shaft to remove any space on the motor shaft. Securely screw down the coupler in this configuration.




Z Motor Thrust Coupling Assembly

| | Created by: | last edited: |
|----|----------------|---------------|
| BY | Joshua Vasquez | 5/27/2020 |
| | SCALE: 1:1 | SHEET 4 OF 14 |

В

Exploded View



\Keep these T-Nuts Loose; only two full turns. They will be tightened into the frame later.

A


| ITEM NO. | DESCRIPTION | QTY. |
|----------|--------------------------------------|------|
| 1 | M5 Buttonhead Screw, 10mm long | 4 |
| 2 | Back Z Motor Plate | 1 |
| 3 | M5 Drop-In T-Nut for 20x20 Extrusion | 4 |


| | Back Z Motor Plate Assembly 1 | | |
|----|-------------------------------|----------------|--------------|
| 1 | (i) | Created by: | last edited: |
|)_ | Ū | Joshua Vasquez | 5/27/2020 |

SCALE: 1:1.5 SHEET 5 OF 14

В

Apply a dab of threadlock to the tip of the four M3 screws before tightening them down securely.







| ITEM NO. | DESCRIPTION | QTY. |
|----------|----------------------------------|------|
| 2 | M3 Buttonhead Screw, 10mm long | 4 |
| 3 | Back Plate Plate Assembly | 1 |
| 5 | Z Motor Thrust Coupling Assembly | 1 |
| 6 | M3 Washer | 4 |

| Back Z | Motor Plate | e Assembly 2 |
|--------|-------------|--------------|

| | | Created by: | last edited: |
|----|----|----------------|---------------|
| CC | BY | Joshua Vasquez | 5/27/2020 |
| | | SCALE: 1:1.5 | SHEET 6 OF 14 |

В







Keep these T-Nuts Loose; only two full turns. They will be tightened into the frame later.

| ITEM NO. | DESCRIPTION | QTY. |
|----------|--------------------------------------|------|
| 1 | M5 Buttonhead Screw, 10mm long | 4 |
| 2 | Front Left Z Motor Plate | 1 |
| 3 | M5 Drop-In T-Nut for 20x20 Extrusion | 4 |

| Front Left Z Plate Assembly 1 | | | |
|-------------------------------|------------------|----------------------------|------------------------|
| <u></u> | (i) BY | Created by: Joshua Vasquez | last edited: 5/27/2020 |
| | | SCALE: 1:1.5 | SHEET 7 OF 14 |

Apply a dab of threadlock to the tip of the four M3 screws before tightening them down securely. Motor wires should poke up and out from this cavity. В 0 (O) Assembled Top View Scale 1:2 Wires should stick out in this direction. Assembled View **Exploded View** Front Left Z Plate Assembly 2 ITEM NO. QTY. **DESCRIPTION** M3 Buttonhead Screw, 12mm long last edited: Created by: Joshua Vasquez Z Motor Thrust Coupling Assembly 5/27/2020 5 M3 Washer 6 SCALE: 1:1.5 SHEET 8 OF 14






A

| ITEM NO. | DESCRIPTION | QTY. |
|----------|--------------------------------------|------|
| 1 | M5 Buttonhead Screw, 10mm long | 4 |
| 2 | Front Right Z Motor Plate | 1 |
| 3 | M5 Drop-In T-Nut for 20x20 Extrusion | 4 |

| | Front Right Z Plate Assembly 1 | | | | |
|----------|--------------------------------|-------------------------------|------------------------|--|--|
| <u>@</u> | (i) BY | Created by: Joshua Vasquez | last edited: 5/27/2020 | | |
| | | SCALE: 1:1.5 | SHEET 9 OF 14 | | |



1




2

•

Load the Z Motor Plates into the frame to set the spacing of the internal loose extrusions. Push these internal extrusions into the plates and fully tighten the 8 inside corner brackets shown below.

В



A

Top View

| ITEM NO. | DESCRIPTION | |
|----------|-------------------------------|---|
| 1 | Base Frame Assembly with Feet | 1 |
| 2 | Back Z Plate Assembly | 1 |
| 3 | Front Left Z Plate Assembly | 1 |
| 4 | Front Right Z Plate Assembly | 1 |

| Internal Extrusion Alignment | | | | | |
|------------------------------|------------------|-------------------------------|------------------------|--|--|
| CC | (i) BY | Created by: Joshua Vasquez | last edited: 5/27/2020 | | |
| | | SCALE: 1:4 | SHEET 11 OF 14 | | |

