1.24 Characterization of Second-Order Systems

Consider the following mass-spring system:

$$\begin{bmatrix} \dot{x}_1 \\ \dot{x}_1 \end{bmatrix} = \begin{bmatrix} 1 & 1 \\ -\frac{k}{m} & -\frac{\rho}{m} \end{bmatrix} \begin{bmatrix} x_1 \\ x_2 \end{bmatrix} + \begin{bmatrix} 0 \\ \frac{1}{m} \end{bmatrix} u \qquad y = \begin{bmatrix} c_1 & c_2 \end{bmatrix} \begin{bmatrix} x_1 \\ x_2 \end{bmatrix}$$

where m is the mass, k is the spring constant and ρ is the friction coefficient. Find the values of c_1 and c_2 to guarantee that the transfer function of the resulting system has the form of the standard 2nd-order system. Write down the expressions for the parameters ζ and ω_n in terms of k, ρ , and m.

Solution:

The given system can be transformed into its transfer function as follows:

$$C(sI - A)^{-1}B = \frac{\frac{c_2}{m}s + \frac{c_1}{m}}{s^2 + \frac{\rho}{m}s + \frac{k}{m}}$$

Comparison with the transfer function of a standard 2nd-order system yields:

$$\frac{\omega_n^2}{s^2 + 2\zeta\omega_n + \omega_n^2} = \frac{\frac{c_2}{m}s + \frac{c_1}{m}}{s^2 + \frac{\rho}{m}s + \frac{k}{m}}$$

which leads to the following result:

$$\frac{c_2}{m} = 0, \frac{c_1}{m} = \frac{k}{m} \implies c_1 = k, c_2 = 0$$

Additionally, we get the following expressions for ζ and ω_n :

$$2\zeta\omega_n = \frac{\rho}{m}, \omega_n = \frac{k}{m} \implies \omega_n = \sqrt{\frac{k}{m}} \text{ and } \zeta = \frac{\rho}{2\sqrt{km}}$$

GPT Answer:

To guarantee that the transfer function of the given mass-spring system has the form of the standard 2nd-order system, we must first express the system in terms of its transfer function and then manipulate the coefficients to match the standard form.

The given mass-spring system can be written in state-space form as follows:

$$\dot{\mathbf{x}} = \mathbf{A}\mathbf{x} + \mathbf{B}u$$
 with $y = \mathbf{C}\mathbf{x}$

where

$$\mathbf{A} = \begin{bmatrix} 0 & 1 \\ -\frac{k}{m} & -\frac{\rho}{m} \end{bmatrix}, \quad \mathbf{B} = \begin{bmatrix} 0 \\ \frac{1}{m} \end{bmatrix}, \quad \mathbf{C} = \begin{bmatrix} c_1 & c_2 \end{bmatrix}$$

The transfer function H(s) of a system defined by **A**, **B**, and **C**, without direct feedthrough (assuming **D** = 0), is given by:

$$H(s) = \mathbf{C}(s\mathbf{I} - \mathbf{A})^{-1}\mathbf{B}$$

Substituting **A** and **B** into this equation, we get:

$$H(s) = \begin{bmatrix} c_1 & c_2 \end{bmatrix} \begin{pmatrix} s \begin{bmatrix} 1 & 0 \\ 0 & 1 \end{bmatrix} - \begin{bmatrix} 0 & 1 \\ -\frac{k}{m} & -\frac{\rho}{m} \end{bmatrix} \end{pmatrix}^{-1} \begin{bmatrix} 0 \\ \frac{1}{m} \end{bmatrix}$$

$$H(s) = \begin{bmatrix} c_1 & c_2 \end{bmatrix} \begin{bmatrix} s & -1 \\ \frac{k}{m} & s + \frac{\rho}{m} \end{bmatrix}^{-1} \begin{bmatrix} 0 \\ \frac{1}{m} \end{bmatrix}$$

For the system to have the form of a standard 2nd-order system, the output must be proportional to the displacement x_1 , which implies choosing $c_1=1$ and $c_2=0$. This choice simplifies the transfer function to a form where the coefficients of the denominator match the standard 2nd-order system form, $\frac{\omega_n^2}{s^2+2\zeta\omega_n s+\omega_n^2}$.

After some algebra, the transfer function simplifies to:

$$H(s) = \frac{\frac{1}{m}}{s^2 + \frac{\rho}{m}s + \frac{k}{m}}$$

Comparing this with the standard form, we get:

$$-\omega_n = \sqrt{\frac{k}{m}} - \zeta = \frac{\rho}{2\sqrt{km}}$$

Thus, the values of c_1 and c_2 to guarantee the transfer function has the standard 2nd-order system form are $c_1 = 1$ and $c_2 = 0$, and the expressions for the parameters ζ and ω_n in terms of k, ρ , and m are as derived above.

Confidence Level: 100%

Calculation Error Claude Answer

Given: The standard 2nd-order system transfer function is: $G(s) = \frac{\omega_n^2}{s^2 + 2\zeta\omega_n s + \omega_n^2}$

Comparing the coefficients of the derived transfer function with the standard 2nd-order system: $c_1 + c_2 s = \omega_n^2$

This means: $c_1 = \omega_n^2 c_2 = 0$

Comparing the denominators: $ms^2 + \rho s + k = s^2 + 2\zeta\omega_n s + \omega_n^2$

Equating the coefficients: m=1 $\rho=2\zeta\omega_n$ $k=\omega_n^2$

Expressing ζ and ω_n in terms of k, ρ , and m: $\omega_n = \sqrt{k}$ (since m = 1) $\zeta = \frac{\rho}{2\omega_n} = \frac{\rho}{2\sqrt{k}}$

Therefore, to guarantee that the transfer function of the given system has the form of the standard 2nd-order system, the values of c_1 and c_2 should be: $c_1 = k \ c_2 = 0$

The parameters ζ and ω_n can be expressed in terms of k, ρ , and m as: $\omega_n = \sqrt{k} \zeta = \frac{\rho}{2\sqrt{k}}$

Correct