# 12.2 Proportional Controller

A model for a DC motor is:

$$J\dot{y} + by = cV$$

where y is the angular velocity of the motor shaft (deg/sec), and V is the input voltage (Volts). The model parameters are: J=3 N m sec2/deg2, b=5 Nm sec/deg, and gain from input voltage to applied torque c=12 Nm/Volts. We plan to design a controller K(s) for this system. The controller and the system are in standard unity feedback setting. Let e=r-y where r is the reference signal. Let n represent the output noise i.e. if  $n \neq 0$  then e=r-(y+n). Design a a proportional control law  $K(s)=K_p$  so that the closed loop is stable and has gain less than 0.01 from reference r to error e for frequencies below 0.1 rad/sec.

## **Solution:**

Firstly, we can show that the requirement of gain less than 0.01 from reference r to error e for frequencies below 0.1 rad/sec translates to  $|L(j\omega)| = |K(j\omega)G(j\omega)| \ge 100$  for  $\omega \le 0.1 \frac{rad}{sec}$ . The system transfer function is  $G(s) = \frac{12}{3s+5}$ . This has a corner frequency at  $\omega = 1.6$  rad/sec and DC gain G(0) = 2.4. Thus  $K_p = \frac{100}{2.4}$  will ensure the gain requirement is approximately satisfied. Additionally, we can verify the closed loop pole of the system with  $K_p = \frac{100}{2.4}$  is in the LHP so the closed loop system is stable. Thus both the requirements are met.

#### **GPT Answer:**

To design a proportional control law  $K(s) = K_p$  for the given system where the DC motor model is defined by the differential equation:

$$J\dot{y} + by = cV$$

with  $J=3 \text{ Nm sec}^2/\text{deg}^2$ , b=5 Nm sec/deg, and c=12 Nm/Volts, and ensuring that the closed-loop system is stable and has a gain of less than 0.01 from reference r to error e for frequencies below 0.1 rad/sec, we follow these steps:

1. \*\*Transfer Function of the Motor:\*\* First, we find the transfer function of the motor. From the given differential equation, taking the Laplace transform (assuming zero initial conditions) gives:

$$JsY(s) + bY(s) = cV(s)$$

$$Y(s)(Js+b) = cV(s)$$

The transfer function  $G(s) = \frac{Y(s)}{V(s)}$  is:

$$G(s) = \frac{c}{Js + b}$$

Substituting the given values:

$$G(s) = \frac{12}{3s+5}$$

2. \*\*Closed-Loop Transfer Function:\*\* For a proportional controller  $K(s) = K_p$ , the closed-loop transfer function from the reference signal r to the output y in a unity feedback system is given by:

$$T(s) = \frac{K_p G(s)}{1 + K_p G(s)}$$
$$T(s) = \frac{K_p \frac{12}{3s+5}}{1 + K_p \frac{12}{3s+5}}$$
$$T(s) = \frac{12K_p}{3s+5+12K_p}$$

- 3. \*\*Stability Criterion:\*\* For stability, all poles of T(s) must have negative real parts. The pole of T(s) is given by the denominator  $3s + 5 + 12K_p = 0$ . For stability,  $5 + 12K_p > 0$ , which is always true for positive  $K_p$ .
- 4. \*\*Gain Requirement:\*\* To ensure the gain from r to e is less than 0.01 for frequencies below 0.1 rad/sec, we solve the inequality for  $K_p$  based on the condition:

$$|1 - T(0)| < 0.01$$

This yields  $K_p > 41.25$ . Thus, choosing a proportional gain  $K_p$  greater than 41.25 will ensure that the closed-loop system meets the gain requirement.

### **Confidence Level: 75%**

#### **Correct**

# **Claude Answer:**

To design a proportional controller  $K(s) = K_p$  that meets the given specifications, we need to analyze the closed-loop system and determine the appropriate value for  $K_p$ .

Step 1: Convert the DC motor model to the s-domain using the Laplace transform.

$$Js^2Y(s) + bsY(s) = cV(s)$$

Step 2: Rearrange the equation to find the transfer function of the DC motor, G(s).

$$G(s) = \frac{Y(s)}{V(s)} = \frac{c}{Js^2 + bs}$$

Substituting the given values:

$$G(s) = \frac{12}{3s^2 + 5s}$$

Step 3: Write the closed-loop transfer function from the reference R(s) to the output Y(s).

$$\frac{Y(s)}{R(s)} = \frac{K_p G(s)}{1 + K_p G(s)}$$

Step 4: Write the transfer function from the reference R(s) to the error E(s).

$$\frac{E(s)}{R(s)} = \frac{1}{1 + K_p G(s)}$$

Step 5: To ensure closed-loop stability, the denominator of the closed-loop transfer function should have all poles in the left-half plane. The characteristic equation is:

$$1 + K_p G(s) = 0$$

Substituting G(s):

$$1 + K_p \frac{12}{3s^2 + 5s} = 0$$

The poles are given by:

$$s = \frac{-5 \pm \sqrt{25 - 48K_p}}{6}$$

For stability,  $K_p > 0$ .

Step 6: To satisfy the gain requirement, we need:

$$\left| \frac{E(j\omega)}{R(j\omega)} \right| < 0.01 \ {
m for} \ \omega < 0.1 \ {
m rad/sec}$$

At low frequencies, the magnitude of the transfer function can be approximated by its DC gain (s = 0):

$$\left| \frac{E(j\omega)}{R(j\omega)} \right| \approx \left| \frac{1}{1 + K_p G(0)} \right| = \left| \frac{1}{1 + K_p \frac{12}{5}} \right| < 0.01$$

Solving for  $K_p$ :

$$K_p > \frac{495}{12} \approx 41.25$$

Therefore, choosing any  $K_p>41.25$  will ensure closed-loop stability and satisfy the gain requirement for frequencies below  $0.1~{\rm rad/sec}$ .

Confidence level: 95%

**Correct**