

TEMPLATES Standards

Il faut bien donner les détails : Expliquer au L1 pourquoi on a fait l'action et c'est quoi le problème

1.All Devices

- Procédure de reset du device
- HVAC: Code 9 - Customer presence warning
- HVAC: Schedule
- Suppression du browsing history sur Google Maps
- Control part replacement
- Problèmes Bluetooth en général
- Remote Horn & Light
- Client ne reçoit pas les notifications de charge
- CHARGE : Mode Délégué
- Trame des erreurs MYR
- Problématique du LOGIN
- Problématique escaladée à l'équipe L3 SDSM

Template activation de service :

Réactivation de service CCS1 CCS2

Template ignition

Hello L1 team,

We have launched a (Reactivation, inventory....etc)

Please ask the user to do the following in a good network connectivity area within 48h after the reactivation start.

- a. Start the vehicle in an area with good connectivity and leave it on for at least 5 minutes.
- b. Check the IVI screen by following these steps: Car info > System > Software Update > Check for updates (Note: the actual options may vary depending on the IVI language settings.)

These steps should allow the device to connect to the server and complete the activation successfully.

Please ask the customer to wait 48h after doing the above actions before reverting back to us if the issue persists.

Best regards,

L2

Template trip + ignition

Hello L1,

Managed services activation is in progress
Last IVI connection:2026-03-19T14:24:06Z
Last IVC connection:2026-03-19T14:24:06Z

Could you please ask the customer to start his vehicle in a good connectivity area for more than 5mins.?

Additionally, please ask cst to check on IVI screen with following steps:
Car info > System > Software Update > Check for updates
(Note: the actual options may be different based on cst's preferred language in IVI.)

With above steps devices should connect to server and activation should be successful.

The customer must also do a TRIP for a 30 minutes.

If the issue persists, Could you please ask the customer to follow the below steps
Perform a factory reset on the IVI system.
Vehicle Menu > Settings > System > Reset options > Reset the factory settings
Perform ignition and check for updates
Take a 30-minute trip to allow synchronization.
Wait 48 hours for the system to process updates.
If the issue persists, ask the customer to provide new screenshots of the issue with timestamp (please put the timestamp on the name of the screenshot).

Best Regards

L2

Synchronisation sur ND :

Template :

Hello L1 team,

We have restarted a service synchronisation : Activation is in progress

Please ask user to do the following in a good network connectivity area within the 48h after the sync start

- Start the vehicle, and keep the vehicle ON for at least 5 mins.
- Then turn OFF the vehicle and start again, so the activation of service is successful

Once completed, can you also ask customer to perform a "check for update" through his onboard system screen ?
It will force the system to try and connect again to Renault's server to get back information

If the issue persists, please revert back to us

Thanks & regards
L2 team

Procédure de reset du device :

Template

In the main menu, press the "Settings" menu

Once in the "Settings" menu, select the "System" tab then press the "Factory Settings" submenu.

Check the part for which you want to delete the parameters, in our case check "Phone-Smartphone".

Press OK to validate the reset request.

HVAC : Code 9 - Customer presence warning

Appliquer le process de check "pas de client à proximité" ci-dessous

Template

Hello L1 team

Currently the vehicle is generating a "Customer presence" warning.
So user need to make sure about below things to avoid this kind of error.

The below are the scenarios which can trigger Customer presence error:

- if all doors are not closed.
- if Ignition is on.
- if all windows are not closed.
- if any seatbelts are engaged.
- if any gears/Transmission is not in parking state
- if Keyfob/key is inside the vehicle.

Please ask the customer to try preconditioning again if all the previous condition are fulfilled

Thanks & regards
L2

HVAC : schedule

Template des vérifications à demander au client

Hello L1,

Could you please ask the customer to follow the steps below:

- a.
 - i. Schedule a program on the vehicle to start in 5 or 10 minutes.
 - ii. Go back to the application and schedule the same program also (also in 5–10 minutes)
=>Let the program run until execution.
 - iii. After the execution, the customer can create a new program in the application to confirm if it is correctly taken into account.

After this we need the customer to provide feedback on the results — specifically:

- Does the program work onboard ?
- Did they receive a notification saying "HVAC started" if it works ?
- Did the program work without notification?

- Or did it fail to function at all?

Thank you for your feedback.

Best regards,
L2

Cas ou le client souhaite supprimer le browsing history sur Google Maps

Template

Hello L1

we would like to confirm that when customer do not login google account and do search locations:

- + All the search history is saved temporarily offline in the map app.
- + Delete all history option will be enabled when search history data exists, and disabled when not having search history data

-When customer login google account:

- + All the search history in offline mode will be clear, and delete history option will not be displayed.
- + The customer can only delete the search history of google account on the web and mobile app.
- + After deleting some destinations (or clear all history) from web/mobile google account, he need to verify if the destinations is still there or not from web/mobile google maps before going to google maps in vehicle

- + If the deleted destinations is still there, can he try to clear all history in order to solve the issue
- + If the history is deleted, he need to force stop google maps application in the car Or logout/login again to google account from google maps application.

Best regards
L2

Control part replacement

Template

Hello L1 team,

It seems that customer had a part replacement that was not perfectly done, we could see some data issues from the calculators
Can the customer take a dealer appointment to make sure the calculators are updated ?

Dealer must apply "Before After Reparation Process" on the part : xxxxxxxxxxx (Radnav si Rad / HU / IVI) /// TCU (si TCU ou IVC)

Thanks & regards
L2

Problèmes Bluetooth en général

Template

Hello L1 team

Before going any further we need additional information about this case.

Has the customer been to a workshop recently ?

What is the exact phone model + software version xx.yyy.zz and the network provider (Orange, SFR, Bouygues)

did the customer try to test with another Smartphone (from another brand ideally) ? what is the result ?

Can he proceed to a complete unpair of the phone like this :

- Try to unpair completely the phone and pair it again
- Remove the device from the smartphone
- Remove the smartphone from the device

Did the customer recently perform a software update of the radio?

Did the customer recently perform a software update of his smartphone ?

Most important, can he provide additional photos or video if someone can record (video) the issue he is facing ?

Thanks & regards
L2

Remote Horn & Light

Template

Hello L1,

Could you please ask cst to follow the below steps and if issue still persist revert back to us with latest screenshots.

Quick fix:

1 - Start MyR app and define a new PINCODE (lost pincode / unspecified pincode)

2 - Perform the Start-stop engine process :

Have the vehicle turned on, then off and then on again (ON > OFF > ON) withing 1 minutes to have the PIN code saved in the vehicle.

3 - Lock then unlock the car

4 - Move away from the car (Minimum 3 meters, ideally more)

5 - Try the remote commands again

Regards,

L2

Client ne reçoit pas les notifications de charge

Template

Hello L1,

Can you please first ask the customer to check the settings bellow :

To enable SMS notifications the customer has to:

1. Open the My Renault app

2. Go to Settings / My Account

3. Go to My Notifications

4. Choose the VIN for which to change SMS notifications

5. Select the desired SMS notifications

If the issue persists, please revert back to us.

Thank you

L2

Mode Délégué

Le Mode Délégué dans la charge ne s'active que si le client utilise l'application Smart Charge

Template

Hi L1,

Charging mode on MyR app should change to "delegated" automatically after customer pairs his vehicle with Smart Charge Jedlix app.

Activating smart charging once these elements trigger delegated mode (invisible to the customer) and MyR will no longer manage the charging

Disabling Smart Charge will also deactivate delegate mode which will give control back to MyR for "classic" modes.

Regards,

L2

Trame des erreurs MYR

Template

Hello L1,

We kindly ask you to send us the following details to help us investigate and resolve the problem efficiently:

- a.** A screenshot or video of the issue, including a visible timestamp.
- b.** Exact date and time when the issue occurred.
- c.** Device details:
 - Phone model and brand
 - Operating system (Android or iOS) and version
- d.** Last time the application worked properly
- e.** Detailed steps: Please describe step-by-step what you were doing before the issue occurred.
- f.** Problem frequency:
 - Occurred once
 - Happens randomly
 - Occurs every time you use the application

Best regards

L2

Problématique du LOGIN

Template

Hello L1,

Before escalating the case, we would like to perform a few additional checks to rule out any potential browser or device-related issues.

Verify that cookies are enabled

Please check the browser settings according to the device being used:

- - Firefox
Menu Settings Privacy & Security Enhanced Tracking Protection Select Standard (not Strict).
 - Google Chrome (Computer)
Settings Privacy and Security Cookies and other site data Allow cookies.
 - Google Chrome (Android)
Settings Site Settings Cookies Allow cookies.
 - Safari (iPhone/iPad)
Settings Safari Advanced Ensure cookies are enabled.
 - Microsoft Edge
Settings Cookies and site permissions Enable cookies.

Recommendation: Please ensure first-party cookies are enabled. Third-party cookies may be blocked if preferred.

Test using another smartphone

Kindly ask the customer to try accessing the service from a different smartphone.

- - If the service works on the second device, the issue may be related to the configuration or settings of the original phone.

Information required

Please provide the following details:

- - Phone model used for testing
 - Operating system version
 - Browser name and version
 - Network type (Wi-Fi / 4G / 5G)
 - Confirmation whether the issue is reproduced on the second device

Once we receive this information, we will proceed with further analysis and escalate the case if necessary.

In case of password error

If the issue occurs when entering the password, please ensure that the customer:

- - Types the password manually
 - Does not copy and paste the password
 - Does not use password generator tools

This helps prevent hidden characters, formatting issues, or compatibility problems that may occur when a password is automatically generated or pasted.

Thank you for your cooperation.

Best regards,
L2 Support

Problématique escaladés à l'équipe L3 SDSM

Template

Hello SDSM Team,

The customer is experiencing an issue with the **[Service/Pack Name] contract**, which was not created/activated after [action performed – e.g., PBO push / service synchronization]. A service synchronization has already been performed; however, the issue still persists.

The customer has agreed to allow further investigation and testing using their VIN. Could you plz analysis?

Vehicle details:

VIN: [Insert VIN]

IVI serial number: [Insert Serial Number]

Software version: [Insert SW Version] (see attached screenshot)

Network status: [Connected/Disconnected] (see attached screenshot)

Data Sharing: [On/Off]

ND Status:

Service/Pack status: [Missing / Activation in progress / Activated] – [Request ID if applicable]

Bootstrap status IVC: [OK/Not OK] – [Date & Time]

Bootstrap status IVI: [OK/Not OK] – [Date & Time]

Provisioning status: [OK/Completed/Pending] – [Date & Time]

PBO requested from onboard: [Date & Time]

Activation of connected commercial services – PBO: [Done/Not Done]

OTP pairing status: [Done/Not Done] – [Date & Time]

As checked in VCPS:

Feature: [Feature name]

UID: [UID]

Status: [Activated/Deactivated] – Last status update: [Date & Time]

CVC Inventory Check:

[Insert JSON Output]

Status: [OperationResult.Success / Failed]

Action: [Execute Profile / Other]

Attachments:

Screenshots of ND status, software version, and relevant logs (if applicable).

Could you please investigate and advise on the next steps to ensure the **[Service/Pack Name] contract** is properly activated?

Thank you,
L2

2. EASY LINK / CCS1

- Template appairage EASYLINK
- Factory Reset
- RS MONITOR
- MODEM ISSUE
- Template de diag connectivité
- Problème MY Car Finder pour les FNAV
- Réactivation de service CCS1

Template appairage EASYLINK :

Template

Hello L1,

Please ask the cst try the following :

- Unpair the vin from the APP
- Remove vehicle from the garage
- Disconnect from the app (complete logout)
- Then try to reconnect
- Add the vin to the garage
- Pair again with the pin code

Best regards,
L2

Factory Reset

Template

Hello L1 Team

Please ask the customer to perform factory reset.
On receiving the confirmation, Please escalate the ticket back so we can start a service synchronization

Thanks & regards,
L2

RS MONITOR :

Template

Hello SDSM Team

Customer has lost RS Monitor app
>> Factory reset has been performed

Last VCPS Sync did not solve the issue, can you check from your end ?

In VCPS

Activation du Véhicule	: BOOTSTRAPPED
IVI Bootstrap	: activated
IVC Bootstrap	:activated
Activation de service PBO	: activated

Contracts and services are available and synced
The customer agreed to let you use his VIN for tests

Cst informations:
VIN: xxxxxxxxxxxxxxxxx
SW: xxxxxxxxxxxxxxxxx

Regards,
L2

MODEM ISSUE

Template

Hello L1 team

We could see that the Mobile Network Code (MCC/MNC) is currently set to 6553525 as seen on the device screen.

Can you check with customer to book dealer appointment.
Dealer must perform a Software Update and Autoconfiguration of the IVC

After the update and configuration, wait for 24h to see if the network connection is restored and the issue is solved.
If the issue persists, please ask the cotech (dealer) to open a FIC case for a thorough investigation.

Thanks and regards
L2

Template de diag connectivité

Template

Hello L1 team

It seems that the vehicle has some communication issues
Please ask the customer to take a dealer appointment and perform the following actions:

Perform a connectivity test (AC002).
Perform an IVC (TCU) reset.
Diag of the IVC (TCU)
Update the IVC (TCU) software to the latest available version.
Autoconfiguration of the IVI (HU / Head Unit) and IVC (TCU / Telematic Control Unit)

If none of the above worked, please perform a reset battery (RZ001)
Perform a DTC and ECU reading at the end. (DTC : Diagnostic Trouble Code) // ECU : calculators)
Dealer should know how to solve the troubles detected

If the issue persists, please open a ticket for FIC team

Thanks & regards
L2

Problème MY Car Finder pour les FNAV

Template

Hello L1,

Thank you for your patience,

After checking with L3 Team, they assert that the TR5/2025 (VIES-13713) was solutioned for this issue and the fix is QLU13 software update.

In order to fix this issue please ask the cst to go to dealer for a Software update and autoconf IVI + service reinitialization .

Best regards,
L2

Template de diag connectivité

Template :

Hello L1 team
It seems that the vehicle has some communication issues
Please ask the customer to take a dealer appointment and perform the following actions:

Perform a connectivity test (AC002).
Perform an IVC (TCU) reset.
Diag of the IVC (TCU)
Update the IVC (TCU) software to the latest available version.
Autoconfiguration of the IVI (HU / Head Unit) and IVC (TCU / Telematic Control Unit)

If none of the above worked, please perform a reset battery (RZ001)
Perform a DTC and ECU reading at the end. (DTC : Diagnostic Trouble Code) // ECU : calculators)
Dealer should know how to solve the troubles detected

If the issue persists, please open a ticket for FIC team

Thanks & regards
L2

Appairage du vehicule avec smartphone

Template 1

Hello L1,

Please ask first customer to perform a factory reset.

Make sure the customer has the latest software update too, I suggest to check it at the dealer directly if sw version already ends up in ".Q2S_prd.user"

Could you please ask the customer to do pairing following:

- a. Go to your Profile on your vehicle's screen (on-board)
 2. Press My Renault Account
 3. Enter your My Renault Login information(i)
 4. Press the Login button.
- Additionally, please ensure that the MyR app is closed before proceeding.

Note that in order to synchronize the "My Renault" app (onboard) with your vehicle, you must be present in your vehicle with the ignition on and the multimedia system switched on and parked in an area with network coverage.

Once "My Renault" app is synchronized with your vehicle, will be able to access your service contracts.

Please revert to this link and share it with the customer :

<https://www.youtube.com/watch?v=0Jt8hM8MQKk&list=PLCZAINsWHBjYKm-Rd3uCiDNj8ttDwR3i8&index=3>

If issue not resolve revert back to us with more latest screenshot :

-Picture of MyR onboard

-Picture of the error message on the application

Best regards,
L2

Template 2

Hello L1 team

Please ask first customer to perform a factory reset.

Make sure the customer has the latest software update too, I suggest to check it at the dealer directly if sw version already ends up in ".Q2S_prd.user"

Then please perform the following steps

MyRenault account synchronization must be only performed onboard, not on the phone.

- follow the instructions on the multimedia system screen

- In order to synchronize the "My Renault" app (onboard) with your vehicle, you must be present in your vehicle with the ignition on and the multimedia system switched on and parked in an area with network coverage.

- then enter your myR account email and password

Once "My Renault" app is synchronized with your vehicle, will be able to access your service contracts.

I hope it helps

Thanks & regards
L2

Template 3

Hello L1,

Could you please ask the customer to do pairing following:

- a. Go to your Profile on your vehicle's screen (on-board)
2. Press My Renault Account
3. Enter your My Renault Login information(i)
4. Press the Login button.

Additionally, please ensure that the MyR app is closed before proceeding.

Thanks & regards

L2

MODEM ISSUE

Template :

Hello L1 team

We could see that the Mobile Network Code (MCC/MNC) is currently set to 6553525 as seen on the device screen.
Can you check with customer to book dealer appointment.

Dealer must perform an OTS 0DY1 and then Actis Solution 76373
It should restore the network connection and solve the issue
If the issue persists, please open a FIC ticket for the cotech in order to pursue the verifications.

Thanks and regards
L2

MODEM ISSUE : Pour les plaintes en provenance de SWIZERLAND

Template :

Hello L1,

Please perform ACTIS 76373 at the dealer.
If issue persists, replace the TCU.
Perform ECU/DTC reading at the end.

Best regards

L2

Pour la Suppression de compte ADMIN

Si le client souhaite pour une raison de blockage ou autre supprimer le compte admin, il faut aller au dealer :

Template :

Hello L1,
Please ask customer to go to the dealer's premises to apply the process "OPENR LINK - RESTORE FACTORY SETTINGS - ADMIN PROFILE LOCKED" in attached file.
Thanks
L2

4.MEDIA NAV

- Communication Issue : problème lié à la TCU
- SYNCHRONISATION
- HVAC PRESENCE WARNING
- MEDIA NAV - ULC Log generation
- MAP UPDATE ET TOOLBOX

Communication Issue : problème lié à la TCU

Template

Hello L1 team

It seems that the vehicle has some communication issues,

Perform a connectivity test (AC002).

Perform an IVC (TCU) reset.

Diag of the IVC (TCU)

Update the IVC (TCU) software to the latest available version.

If none of the above worked, please perform a reset battery (RZ001)

Perform a DTC and ECU reading at the end. (DTC : Diagnostic Trouble Code) // ECU : calculators)

Dealer should know how to solve the troubles detected

If the issue persists, please revert back to us

Thanks & regards

L2

SYNCHRONISATION :

Template

Hello L1 team,

We have restarted a service synchronisation : Activation is in progress

Please ask user to do the following in a good network connectivity area within the 48h after the sync start

- Start the vehicle, and keep the vehicle ON for at least 5 mins .
- Then turn OFF the vehicle and start again, so the activation of service is successful

If the issue persists, please revert back to us

Thanks & regards

L2 team

MEDIA NAV - UKC Log generation

Voici la procédure à communiquer au L1 avant de redescendre le ticket

Template

Hello L1 Team

In order to continue the investigation, L3 team requires additional logs to be provided. Please find the process below, customer has to do it and return the requested folder(s)

- At the root of the USB Key, create a folder named ""logfiles_bavn"" (careful with the spelling)
- Then proceed to connect the USB key to Head Unit
- Wait for about 30+ seconds.
- A message saying : ""Log to USB, Copying is completed"" is supposed to appear
- Disconnect USB Key
- When check on the computer Log files will be available in the ""logfiles_bavn"" directory

There should be few folders (bsd, core_dump, log_data, log_emmc...) and files available.

Ask the customer to ZIP them all and please revert back to us with the content.

Thanks & regards

L2 team

MAP UPDATE ET TOOLBOX :

Template

Hello L1 team

Unfortunately we do not deal with toolbox, cartography update of Medianav or Naviextra account management, it is for NNG team through REDA tickets.

I advise you to escalate ticket to NNG_ext queue & open a REDA (Jira) tickets for this kind of issue.

Thanks

L2