

Monitoring of web break detectors

When Operations is having constant PRS breaks and they call you to check web detectors, after physically checking web detectors for anything obvious such as sensor being dirty, being misaligned or needing to adjust sensitivity, then go to the troubleshooting PC and go to the data page and type in all the bits (B472-B479) corresponding to that particular line you are working on (see below). Once all the bits are typed in, if any bits are at a "1" then reset by toggling to a "0". Next time line goes back into production, this only works in "production", when they have a web break then check to see what sensors were made when the line went down. This should give you an idea of where the problems might be. Problem could be a PRS belt problem such as slipping or a tension problem such as chuck on core to name a few. It is NOT always a sensor at fault.

Bits B2482 and B2492 are bits that come on after the line has been in production for approximately 1 to 2 minutes. B2482 is for TDO sensors and B2492 is for PRS and Winder sensors

Explanation: When an input of the web detector does not see web while in production then this sets the bit from a "0" to a "1"

XE01 Main L190

If not I94,A . B2482 then set B472 _ TDO exit

If not I85,D . B2492 then set B473 _ PRS

If not I95,D . B2492 then set B474 _ PRS

If not I95,E . B2492 then set B475 _ PRS

If not I95,F . B2492 then set B476 _ PRS

If not IB4,C . B2492 then set B477 _ Winder Tension (F201)

XE02 Main L190+49

If not I94,A . B2482 then set B472 _ TDO exit

If not I85,D . B2492 then set B473 _ PRS

If not I95,D . B2492 then set B474 _ PRS

If not I95,E . B2492 then set B475 _ PRS

If not I95,F . B2492 then set B476 _ PRS

If not IB1,C . B2492 then set B477 _ PRS

If not IB1,D . B2492 then set B478 _ PRS

If not IB4,C . B2492 then set B479 _ Winder Tension (F201)

XE03 Main L190

If not I94,A . B2482 then set B472 _ TDO exit

If not I94,B . B2482 then set B473 _ TDO exit

If not I85,D . B2492 then set B474 _ PRS

If not I95,D . B2492 then set B475 _ PRS

If not I95,E . B2492 then set B476 _ PRS

If not I95,F . B2492 then set B477 _ PRS

If not IB4,C . B2492 then set B478 _ Winder Tension (F201)

XE04 Main L190+38

If not I94,A . B2482 then set B472 _ TDO exit

If not I85,5 . B2492 then set B473 _ PRS

If not I85,6 . B2492 then set B474 _ PRS

If not I85,D . B2492 then set B475 _ PRS

If not IB4,C . B2492 then set B476 _ Winder Tension (F201)