

ROTAX 912 iS SERVICE BULLETINS & TECHNICAL INSTRUCTIONS (SB / SI)

****Official OEM Airworthiness Directives & Service Engineering Bulletins****

1. MANDATORY SERVICE BULLETINS

* ****SB-912iS-005 (Fuel Rail Retaining Clip Inspection):**** Mandatory inspection of fuel injector delivery clips to prevent micro-vibration decoupling at high altitude. Torque to 6.0 Nm.

* ****SB-912iS-012 (Propeller Reduction Gearbox Dog-Clutch Backlash):**** Mandatory backlash inspection at 100-hour intervals. Maximum allowable backlash is 0.05 mm. If 3rd harmonic vibration RMS exceeds 1.8 mm/s, replace dog clutch cam rings (Part No. 881-280).

* ****SB-912iS-019 (Oil Pressure Relief Valve Spring Fatigue):**** Dry-sump relief valve spring inspection under high thermal duty cycles. If pressure drops below 2.2 bar during loiter, replace bypass spring assembly.

2. SERVICE INSTRUCTIONS

* ****SI-912iS-008 (Cold Weather High-Altitude Operation):**** In sub-zero theaters (Ladakh FL200, OAT < -20 deg C), use synthetic multi-grade aero oil (AeroShell Oil Sport Plus 4 5W-40) to prevent scavenge line oil starvation and cavitation.

* ****SI-912iS-015 (FADEC MAP Sensor Cleaning & Calibration):**** In dusty environments (Thar Desert), clean MAP sensor manifold pickup tube at 50-hour intervals to prevent transducer offset drift.