

SITE INSPECTION REPORT

Property: Greenfield Residency, Block C | Report No: BSI-2026-047

Date: 28 March 2026

Inspector: John Matthews | Firm: BuildSafe Inspections Pvt. Ltd.

Property Information

Property Address:	Block C, Greenfield Residency, Sector 14, Nagpur - 440001
Property Type:	Residential Apartment Complex — 4 Floors, 24 Units
Year of Construction:	2015
Inspection Date:	28 March 2026
Inspector Name:	John Matthews
Inspector ID:	BSI-IN-2204
Weather Conditions:	Clear, 32 degrees Celsius, Humidity 58%
Report Reference:	BSI-2026-047

Executive Summary

A comprehensive visual inspection of Block C, Greenfield Residency was conducted on 28 March 2026. The property shows significant signs of water ingress across multiple areas including the rooftop, east-facing external walls, and basement parking level. Structural cracks were observed on the third floor corridor ceiling and in the stairwell. Electrical panels in common areas show signs of overheating and require immediate professional assessment. Overall the building presents a mix of critical and moderate issues that need to be addressed in a phased remediation plan.

Area 1 — Rooftop & Terrace

General Condition:

The rooftop terrace is accessible via the fourth floor stairwell. The waterproofing membrane shows visible deterioration with multiple areas of bubbling and peeling. Standing water was observed in the north-west corner due to a blocked drainage outlet.

Observed Issues:

- Waterproofing membrane bubbling and delaminating across 40% of total roof area.
- Blocked roof drain in north-west corner causing standing water pooling (approx. 15mm depth).
- Three expansion joint seals along the parapet wall have failed — visible gaps of 8-12mm.
- Overhead water tank (1000L capacity) shows rust staining on base plate and external seams.
- Two sections of parapet wall coping tiles are cracked and displaced.
- Satellite dish mounting brackets have penetrated the waterproofing layer without proper sealing.

Severity Assessment:

CRITICAL — Active water ingress through failed membrane is causing damage to floors below. Immediate remediation required.

Area 2 — East External Facade

General Condition:

The east-facing external wall spans all four floors. Paint coating shows widespread efflorescence and staining consistent with long-term water seepage. Multiple hairline cracks were mapped across all floors.

Observed Issues:

- Efflorescence and white salt deposits visible on floors 2, 3, and 4 of the east facade.
- Hairline cracks (0.2mm to 0.5mm width) running vertically along window frames — 9 windows affected.
- External plaster detachment in two patches: 0.8 sqm near 2nd floor window and 1.2 sqm near 3rd floor slab edge.
- Window sealant on all east-facing windows is dried, cracked, and non-functional.
- Rust staining below window sill level on floors 2 and 3 indicating corroding embedded iron.

Severity Assessment:

HIGH — Water seepage through facade cracks is causing progressive structural damage. Remediation should begin within 30 days.

Area 3 — Third Floor Internal Corridor

General Condition:

The third floor common corridor (length approx. 28m) shows signs of ongoing water seepage from the ceiling, consistent with rooftop water ingress identified above.

Observed Issues:

- Ceiling plaster is damp and soft to touch across a 6m stretch near the north-west corner.
- One section of ceiling plaster (approx. 0.5 sqm) has fully collapsed — debris visible on floor.
- Yellow-brown water staining on ceiling over 3 apartment doorways (Units C-301, C-302, C-303).
- Structural crack running diagonally across the corridor ceiling — approximately 1.8m in length, 1-2mm wide.
- Damp smell consistent with mold growth behind ceiling plaster.
- Electrical conduit running through damp ceiling section — insulation visibly compromised.

Severity Assessment:

CRITICAL — Partial ceiling collapse already occurred. Structural crack requires immediate engineering assessment. Electrical safety hazard present.

Area 4 — Basement Parking Level

General Condition:

The basement level serves as a parking area for 18 vehicles. Active water seepage was observed through the ceiling slab joints and along the retaining walls on the north side.

Observed Issues:

- Active water dripping from ceiling slab construction joint — two locations identified.

- White efflorescence deposits on north retaining wall over a 4m x 2m area.
- Floor surface shows wet patches and algae growth in north-east corner.
- Sump pump operational but discharge pipe shows signs of blockage — water level near overflow.
- Two parking bay markings are completely faded — safety concern.
- Fire extinguisher mounting bracket near entry ramp is corroded and insecure.

Severity Assessment:

HIGH — Active water ingress in basement requires waterproofing treatment. Sump pump blockage is immediate safety concern.

Area 5 — Common Area Electrical Panels

General Condition:

Three common area electrical distribution panels were inspected — located on ground floor lobby, second floor landing, and fourth floor stairwell.

Observed Issues:

- Ground floor panel: visible scorch marks on two MCB switches — signs of past overheating event.
- Ground floor panel: panel door hinge broken — door cannot close properly, live components exposed.
- Second floor panel: three circuit breakers showing signs of heat damage, tripping mechanism questionable.
- Fourth floor panel: located directly below identified ceiling water seepage area — moisture risk.
- Cable insulation on feeder cable entering ground floor panel is cracked and brittle.
- No residual current device (RCD) protection observed on any of the three panels.

Severity Assessment:

CRITICAL — Exposed live components and scorched MCBs represent an immediate fire and electrocution hazard. Qualified electrician must assess within 48 hours.

Inspector Notes & Recommendations

Based on the inspection findings, the following priority actions are recommended:

- Immediate (0-7 days): Isolate and replace damaged electrical components. Barricade third floor corridor section below collapsed ceiling.
- Short-term (7-30 days): Engage waterproofing contractor for rooftop membrane replacement. Reseal all east facade window joints.
- Medium-term (1-3 months): Full external facade treatment and crack injection. Basement waterproofing via crystalline treatment.
- Long-term (3-6 months): Replace overhead water tank. Full electrical audit and RCD installation across all panels.

This report is prepared based on visual inspection only. Invasive testing, structural engineering assessment, and specialist electrical evaluation are recommended for the issues flagged as Critical.