

Received 1 - 28 pages

Sign

DATE

Sign

DATE



Home Inspection Report



825 S. 22nd Street, San Jose

Ordered by: Ashwin Veeravalli
The Agency
497 N. Santa Cruz Avenue
Los Gatos, CA 95030

Inspected by:


Kane Howell
May 9, 2025

Table of Contents

Report Overview	3
Structure	9
Roofing	10
Exterior	11
Electrical	13
Heating System	15
Cooling/Heat Pump System	16
Insulation/Ventilation	17
Plumbing	18
Interior	20
Photographs	22
Maintenance Advice	26

Report Overview

A GENERAL DESCRIPTION OF THE STRUCTURE

This is a two story single family dwelling. Based on the information provided, the structure was built in 2006. Ongoing maintenance is required and improvements to the systems of the home will be needed over time.

WEATHER CONDITIONS

Dry weather conditions prevailed at the time of the inspection.

! - IMMEDIATE RECOMMENDED IMPROVEMENTS

The following is a synopsis of the potentially significant improvements that should be budgeted for over the short term. Other significant improvements, outside the scope of this inspection, may also be necessary. Please refer to the body of this report for further details on these and other recommendations. No relative importance should be placed on the photographs provided in this report. The photographs in this report do not necessarily illustrate all of the damage in any particular finding. Also, not all problem areas will be supported by photographs. If more than one photograph is available for a particular item, additional photographs can be found at the end of the report in the section entitled 'Photographs'. Please contact HomeGuard if you have any questions.

Roofing

1. Repairs to the roof covering are recommended. Damaged, loose or missing roofing material at the field should be repaired or replaced. All roof penetrations should be examined and sealed as necessary. For further evaluation of the condition of the roof we recommend you consult a licensed roofing contractor. (See Photo 6)




Photo 06

2. Leaks were noted in the downspouts and/or gutters at the rear. During wet weather conditions these areas are more obvious and during dry weather conditions they are noted from the stains at the areas where the leaks have occurred. We recommend all leaks be repaired. (See Illustration 2D) (See Photo 4)



Photo 04

Exterior

3. Water damage was observed to the rafters at the rear. We recommend the services of a licensed general contractor and/or structural pest control company. (See Photo 3)




Photo 03

Electrical

4. Exterior receptacles at the front porch and rear are missing a weatherproof cover plate. We recommend an approved exterior cover be installed. (See Photo 1)
(See Photo 2) (See Photo 5)



Photo 01

5. Any openings inside the electrical branch/auxiliary panel cover "Dead Front" or panel box should be covered with approved filler plates or plugs. (See Illustration 4F) (See Photo 10)



Photo 10

Heating System

6. The heater thermostat was inoperable at the time of our inspection, and therefore the heater was not tested. We recommend the thermostat be repaired or replaced and proper operation of the heater verified by appropriate trades. (See Photo 12) (See Photo 17)



Photo 12

Plumbing

7. The water heater seismic straps are loose, this will allow movement of the tank in an earthquake. We recommend tightening the straps and/or adding bracing between the tank and wall to improve safety. (See Photo 7)



Photo 07

Plumbing

8. The tub faucet and/or handles are leaking at the master bathroom. We recommend all leaks be repaired. (See Photo 18)



Photo 18

9. The sink faucet hot and cold water controls are reversed at the downstairs hall bathroom and second story hall bathroom. Reversed hot and cold water can result in hot water burns. We recommend that this condition be corrected. (See Illustration 8A) (See Photo 13) (See Photo 19)



Photo 13

10. For enhanced safety, it is recommended that the loose or damaged connections of the water heater venting system be improved. A minimum of 3 screws at each section of the duct is recommended. (See Illustration 8M) (See Photo 9)



Photo 09

11. The temperature and pressure relief valve for the water heater lacks a proper discharge pipe. We recommend the installation of approved piping to an approved location. (See Photo 8)



Photo 08

Interior

12. The air-gap or its connection to the disposal, appears to be restricted, causing water to flow out of the air-gap during the drain cycle of the dishwasher. We recommend that the drain system be cleaned or modified to correct this deficiency. (See Illustration 9F) (See Photo 15)



Photo 15

Interior

13. Cracked, deteriorated and/or missing tub/shower enclosure caulk in the master bathroom should be replaced. Water leaking through non-sealed areas can cause damage. Damage caused by water seepage cannot be determined by this visual observation. (See Photo 21)



Photo 21

14. The base and/or side of the master bathroom sink cabinet sink shelf is deteriorated. We recommend the advice and services of a licensed pest control operator for investigation and possible repair of this condition. (See Photo 20)



Photo 20

15. The interior windows at the downstairs bedroom are inoperable, stuck, or painted shut. We recommend repair or replacement to restore functional use of these areas. (See Photo 11)



Photo 11

16. One or more of the windows are not fully serviceable because their lift mechanism sash cords or springs are missing or damaged. We recommend these windows be repaired and their full functional use restored. (See Photo 16)



Photo 16

17. Evidence of vermin activity was observed within the structure. It is likely this evidence will extend into inaccessible areas. The owner is advised to contact the appropriate trade for further evaluation and remedial measures if necessary. (See Photo 22)



Photo 22

Interior

18. The gas was off at the time of our inspection, therefore the kitchen gas appliances were not tested. We recommend operation of the appliances by interested parties when all services have been restored. (See Photo 14)



Photo 14

The Scope of the Inspection

All components designated for inspection in the ASHI standards of practice are inspected, except as may be noted in the "Limitations" section within the report. This inspection will not disclose compliance with regulatory requirements (codes, regulation laws, ordinances, etc.)

This inspection is visual only. Only a representative sample of the building and system components was viewed. No destructive testing or dismantling of building components was performed. The strength, adequacy, effectiveness, or efficiency of any system or components was not determined. Not all recommended improvements will be identified in this inspection. Unexpected repairs should still be anticipated. This inspection should not be considered a guarantee or warranty of any kind. The purpose of our inspection is to provide a general overview of the structure reflecting the conditions present at the time of this inspection. The inspection is performed by visual means only, reflecting only the opinions of the inspector. Nothing in the report, and no opinion of the inspector, should be construed as advice to purchase, or to not purchase, the property. It is the goal of this inspection to put the buyer in a better position to make a buying decision

Our inspection does not address, and is not intended to address, the possible presence of hazardous plants or animals or danger from known and unknown environmental pollutants such as, but not limited to, asbestos, mold, radon gas, lead, urea formaldehyde, underground storage tanks, soil contamination and other indoor and outdoor substances, water contamination, toxic or flammable chemicals, water or airborne related illness or disease, and all other similar or potentially harmful substances and conditions. This property was not inspected for the presence or absence of health related molds or fungi. We are neither qualified, authorized nor licensed to inspect for health related molds or fungi. If you desire information about the presence or absence health related molds, you should contact the appropriate specialist. Be aware that many materials used in building construction may potentially contain hazardous substances. Furthermore, other environmental concerns may exist elsewhere. An environmental specialist should be contacted if additional information is desired about these issues.

PLEASE NOTE: The inspector is NOT required to determine whether items, materials, conditions or components are subject to recall, controversy, litigation, product liability, or other adverse claims or conditions.

PLEASE NOTE: Important disclosure information and other inspection reports may exist. All present and prior disclosures along with other inspection reports should be reviewed and any adverse conditions and/or concerns that may not be mentioned in our report should be addressed prior to the close of escrow. Furthermore, there may be conditions known by the seller that have not been disclosed to us.

PLEASE NOTE: Work performed by others will be reinspected, upon request, for an additional fee for each trip out to the property.

Pictures are provided to assist in clarifying some of the findings made in the report. No relative importance should be placed on these pictures. There are likely to be significant comments that do not have pictures associated with them. Please read the report thoroughly. Sections of this building appear to have been remodeled. We recommend consultation with the owner or local municipality to determine whether the necessary permits were obtained, inspections performed and final signatures received.

BINDING ARBITRATION PROVISION

Any controversy or claim arising out of or relating to the inspection performed by HomeGuard Incorporated shall be settled by final and binding arbitration filed by the aggrieved party with and administered by the American Arbitration Association (hereafter referred to as "AAA") in accordance with its Construction Arbitration Rules in effect at the time the claim is filed. The Rules, information and forms of the AAA may be obtained and all claims shall be filed at any office of the AAA or at Corporate Headquarters, 335 Madison Avenue, Floor 10, New York, New York 10017-4605. Telephone: 212-716-5800, Fax: 212-716-5905, Website: <http://www.adr.org/>. The arbitration of all disputes shall be decided by a neutral arbitrator, and judgment on the award rendered by the arbitrator may be entered in any court having competent jurisdiction thereof. Any such arbitration will be conducted in the city nearest to the property that was inspected by HomeGuard Incorporated having an AAA regional office. Each party shall bear its own costs and expenses and an equal share of the administrative and arbitrators' fees of arbitration. This arbitration Agreement is made pursuant to a transaction involving interstate commerce, and shall be governed by the Federal Arbitration Act, 9 U.S.C. Sections 1-16. THE PARTIES UNDERSTAND THAT THEY WOULD HAVE HAD A RIGHT OR OPPORTUNITY TO LITIGATE THROUGH A COURT AND TO HAVE A JUDGE OR JURY DECIDE THEIR CASE, BUT THEY CHOOSE TO HAVE ANY AND ALL DISPUTES DECIDED THROUGH ARBITRATION. BY SIGNING THIS AGREEMENT, THE PARTIES ARE GIVING UP ANY RIGHT THEY MIGHT HAVE TO SUE EACH OTHER.

Structure

ITEM DESCRIPTIONS:

Attic (Access)	• Location: Hallway • Attic Method Of Inspection: From the Access
Roof Structure	• Truss • Plywood or Orientated Strand Board
Ceiling Structure	• Truss
Wall Structure	• Wood Frame
Floor Structure	• Unknown/Inaccessible (Not Inspected)
Crawlspace/Basement (Access)	• None (Slab)
Foundation	• Slab on grade

COMMENTS:

Due to the design of this building foundation anchor bolts were concealed from view.

RECOMMENDATIONS/OBSERVATIONS - '!' indicates an immediate improvement recommendation item.

1. The garage floor slab has typical cracks. This is usually the result of shrinkage and/or settling of the slab. No further recommendations are given.

LIMITATIONS:

This is a visual inspection to the accessible areas only. Assessing the structural integrity of a building is beyond the scope of a typical inspection. A certified professional engineer is recommended where there are structural concerns about the building.

- Structural components concealed behind finished surfaces could not be inspected.
- Only a representative sampling of visible structural components was inspected.
- Furniture and/or storage restricted access to some of the structural components.
- The attic was viewed from the attic access hatch only due to insulation covering the wood members. If further inspection of this area is desired catwalks or planks will need to be installed over the exposed ceiling joists. When access has been provided we will return and further inspect this area.
- Insulation within the roof attic cavity obstructed the view of some structural members, plumbing and electrical components.

Roofing

ITEM DESCRIPTIONS:

Roof	• Concrete Tile • Method of inspection: From The Ground.
Chimney	• None
Gutters and Downspouts	• Metal • Installation Of Gutters/Downspouts: Full • Downspouts Discharge Location: Above Grade

COMMENTS:

We recommend reviewing a roof inspection report performed by a licensed roof inspector on this structure.

RECOMMENDATIONS/OBSERVATIONS - '!' indicates an immediate improvement recommendation item.

- ! 1. Repairs to the roof covering are recommended. Damaged, loose or missing roofing material at the field should be repaired or replaced. All roof penetrations should be examined and sealed as necessary. For further evaluation of the condition of the roof we recommend you consult a licensed roofing contractor. (See Photo 6)
- ! 2. Leaks were noted in the downspouts and/or gutters at the rear. During wet weather conditions these areas are more obvious and during dry weather conditions they are noted from the stains at the areas where the leaks have occurred. We recommend all leaks be repaired. (See Illustration 2D) (See Photo 4)
3. The roof was inspected from the ground level only. Most of the roof could not be reached without jeopardizing the safety of the inspector or the integrity of the roof material. Our comments are based only upon a limited visual inspection. For further evaluation of the condition of the roof we recommend you consult a licensed roofing contractor.
4. The downspouts discharge water adjacent to the structure. Water should be directed to flow at least 5 feet away from the building at the point of discharge. The installation of underground drainage where applicable will help control surface drainage.

LIMITATIONS:

This is a visual inspection to the accessible areas only. Roofing life expectancies can vary depending on several factors. Any estimates on remaining life are approximations only. This assessment of the roof does not preclude the possibility of leakage. Leakage can develop at any time and may depend on rain intensity, wind direction, ice build up, etc.

- The roof was inspected from ground level only.




Illustration 2D

Exterior

ITEM DESCRIPTIONS:

Lot Topography	• Level grade
Driveway	• Concrete
Walkway & Sidewalks	• Concrete
Retaining Walls/Abutments	• None
Fencing/Gates	• Wood
Porch/Deck, Patio Covers	• Concrete
Stairs/Railings/Landings	• Concrete • Metal
Exterior Walls	• Stucco
Fascia, Eaves and Rafters	• Wood • Open Rafters
Windows	• Vinyl
Doors	• Metal • Sliding Glass
Garage/Carport	• Attached
Garage Door	• Metal • Automatic Opener Installed
The Swimming Pool Safety Act	• Not Applicable

COMMENTS:

The auto reverse mechanism on the overhead garage door responded properly to testing. This is an important safety feature that should be tested regularly. Refer to the owner's manual or contact the manufacturer for more information. There is a serious risk of injury, particularly to children, if this feature is not working properly. Information on garage door openers is available from the Consumer Product Safety Commission at www.cpsc.gov.

RECOMMENDATIONS/OBSERVATIONS - '!' indicates an immediate improvement recommendation item.

- ! 1. Water damage was observed to the rafters at the rear. We recommend the services of a licensed general contractor and/or structural pest control company. (See Photo 3)
2. The screen for the sliding glass door is torn. We recommend the screen be repaired or replaced.
3. Vegetation growing on or within 6" of exterior walls should be kept trimmed away from siding, window trims and the eaves.
4. The tree proximity at the front and rear could disrupt drainage pipes, cause mechanical damage to the exterior of the house or influence the foundation over time. For additional information and recommendations we recommend appropriate trades be consulted. (See Illustration 3T)
5. The gaps in the exterior trim/siding should be caulked as necessary.
6. There are minor sized cracks in the exterior stucco that should be patched and sealed as part of preparation for the next painting. Flexible patching materials are recommended rather than rigid patching compounds.
7. Portions of the exterior are weathered/peeling, exposed and subject to damage. We recommend thorough scraping, sanding, caulking and priming prior to applications of a high quality exterior finish.

LIMITATIONS:

This is a visual inspection to the accessible areas only.

- A representative sample of exterior components was inspected.
- The inspection does not include an assessment of geological conditions, site stability and property surface and/or underground drainage runoff.
- Interior finishes (floors, walls, ceilings) and/or insulation restricted the inspection of the garage.




Illustration 3T

Electrical

ITEM DESCRIPTIONS:

Service	• 120/240 volt main service
Service Entrance	• Underground Service Wires
Service Ground	• Copper Ground Wire • Ufer (foundation rebar) Connections
Main Disconnect	• Breakers • Main Service Rating: 200 Amps
Main Distribution Panel	• Breakers • Location: Exterior Rear • Panel Rating (Amps): 200
Branch/Auxiliary Panel	• Breakers • Location: Garage • Panel Rating (Amps): 200
Distribution Wiring	• Copper Wire • Aluminum Wire
Outlets, Switches & Lights	• Grounded
Ground Fault Circuit Interrupters	• Bathroom • Garage • Kitchen

COMMENTS:

RECOMMENDATIONS/OBSERVATIONS - '!' indicates an immediate improvement recommendation item.

- ! 1. Exterior receptacles at the front porch and rear are missing a weatherproof cover plate. We recommend an approved exterior cover be installed. (See Photo 1) (See Photo 2) (See Photo 5)
- ! 2. Any openings inside the electrical branch/auxiliary panel cover "Dead Front" or panel box should be covered with approved filler plates or plugs. (See Illustration 4F) (See Photo 10)
- 3. The accessible aluminum connectors inside the electrical main and/or branch panel are lacking the application of an anti-oxidant. We recommend that each accessible connection be covered with an anti-oxidant.
- 4. The missing switch cover plates at the pantry should be replaced.

MAINTENANCE ITEMS & GENERAL INFORMATION

- 5. Aluminum wiring was noted for the 240 volt circuitry of the home. Aluminum wiring is typically used for 240 volt appliance circuits and no action is necessary.
- 6. Arc fault circuit breakers were noted in the main or branch electric circuit panel. Arc fault breakers help protect against fires caused by arcing wires and are designed to trip by sensing a short that causes a massive amount of electricity to pass through the circuit.

DISCRETIONARY IMPROVEMENTS AND/OR UPGRADES

- 7. Today's electrical standard now requires a device called an arc-fault circuit interrupter "AFCI". As defined in proposals for the 1999 NEC, an "AFCI" is a device that provides protection from effects of arc faults by recognizing characteristics unique to arcing, and then de-energizing the circuit upon detection of an arc fault. Its basic application is protection of 15 amp and 20 amp branch circuits in single and multi-family residential occupancies. These devices are now installed in the habitable bedrooms of new construction.
- 8. The installation of ground fault circuit interrupter "GFCI" devices is advisable on exterior, garage, bathroom, laundry, and some kitchen outlets. Any whirlpool or swimming pool equipment should also be fitted with "GFCI"s. A ground fault circuit interrupter "GFCI" offers protection from shock or electrocution. Please note that "GFCI" may already be in one or more of these areas. See "description" section above for exact location of any "GFCI" which may be present on this property. (See Illustration 4L)

LIMITATIONS:

This is a visual inspection to the accessible areas only. The inspection does not include (if applicable) low voltage systems, telephone wiring, intercoms, alarm systems, TV cable, timers, central vacuum systems, exterior sprinkler systems, exterior landscape lighting or exterior motion sensor lights. Also smoke detectors out of reach were only visually inspected unless noted otherwise. We recommend these systems be checked by interested parties for proper operation when possible.

- Due to inaccessibility of concealed wiring or undocumented improvements of the structure, we are unable to predict whether the number of circuits within a home will be sufficient for the needs of the occupants during a typical home inspection. If fuses blow or breakers trip regularly, this may indicate that additional loads or remodeling modifications may have been added to existing circuits.

- Inspection of the installation, wiring and function of an electrical vehicle charger is excluded from this report. We recommend consulting the vehicles manufacturer specifications for further information on installation, testing and operation.
- Electrical components concealed behind finished surfaces could not be inspected.
- According to "ASHI" standards only a representative sampling of outlets and light fixtures were tested.
- Furniture and/or storage may have restricted access to some electrical components.
- Exterior light fixtures on motion or light sensors were not tested.

Ground fault interrupter

the GFI circuitry within the outlet checks constantly for a difference between the current in the black and white wires

if there is a difference (even as little as 5 milliamps), there is a current leak (possibly through your body) and the GFI shuts down the receptacle and other receptacles downstream

note:

if the GFI is in the panel, the entire circuit will be shut down




Illustration 4L

Panel openings

any exposed panel openings (that would allow access to the inside of the panel) should be fitted with secure covers

openings requiring covers




Illustration 4F

Heating System

ITEM DESCRIPTIONS:

Primary Source Heat	• Gas
Heating System	• Forced Air • Manufacturer: Carrier • Location: Attic
Distribution/Ducting	• Ductwork

COMMENTS:

We recommend a licensed HVAC contractor be retained for further evaluation of the heating unit.

RECOMMENDATIONS/OBSERVATIONS - '!' indicates an immediate improvement recommendation item.

- !** 1. The heater thermostat was inoperable at the time of our inspection, and therefore the heater was not tested. We recommend the thermostat be repaired or replaced and proper operation of the heater verified by appropriate trades. (See Photo 12) (See Photo 17)

MAINTENANCE ITEMS & GENERAL INFORMATION

2. This home is heated with a mid efficiency forced air furnace. In this type of furnace, air is circulated by a blower motor through a heat exchanger, which is heated by the burner unit at the base. An induced draft motor is used to force the exhaust from the furnace to the exterior

LIMITATIONS:

This is a visual inspection to the accessible areas only. The inspection of the heating system is general and not technically exhaustive. A detailed evaluation of the furnace heat exchanger is beyond the scope of this inspection.

- As per ASHI standards determining furnace heat supply adequacy or inadequacy, distribution balance or sizing of the unit or units is not a part of this inspection.
- The wall mount and/or window mounted air conditioning unit (if applicable) was not inspected and are excluded from this report.
- Heating and/or air conditioning registers where accessible were visually inspected. Manual operation of the registers was not performed.
- Due to the conditions noted above the heater was not operated.
- As per ASHI standards the heat exchanger of the furnace was not inspected and interior portions of the heater were restricted. For additional information we recommend the services of a licensed heating contractor. As a free public service, the local utility company will perform a "safety" review of the heat exchanger and other gas operated components. We recommend that you take advantage of this service before the next seasonal operation.
- Inspection of the heater and/or air conditioner thermostat is limited to operating the units(s) on and off function only. Testing of the thermostat timer, temperature accuracy, clock, set back functions, etc. were not performed.

Cooling/Heat Pump System

ITEM DESCRIPTIONS:

Primary Source A/C

• 240 Volt Power Supply

Cooling System

• Air Cooled Central • Manufacturer: Carrier • Location: Exterior Rear

COMMENTS:

We recommend a licensed HVAC contractor be retained for further evaluation of the cooling unit.

RECOMMENDATIONS/OBSERVATIONS - 'I' indicates an immediate improvement recommendation item.

1. Damaged insulation on air conditioner refrigerant lines should be repaired. This will help to increase the efficiency of the unit.

LIMITATIONS:

This is a visual inspection to the accessible areas only. Air conditioning and heat pump systems, like most mechanical components, can fail at any time.

Insulation/Ventilation

ITEM DESCRIPTIONS:

Attic/Roof Insulation	• Fiberglass • Cellulose • Depth (inches): 10-12
Exterior Walls Insulation	• Unknown
Crawlspace Insulation	• Not Applicable
Attic/Roof Ventilation	• Roof Vents • Gable vents
Crawlspace Ventilation	• Not Applicable

COMMENTS:

LIMITATIONS:

This is a visual inspection to the accessible areas only.

- Insulation/ventilation type and levels in concealed areas cannot be determined. No destructive tests were performed.
- Potentially hazardous materials such as Asbestos and Urea Formaldehyde Foam Insulation (UFFI) cannot be positively identified without a detailed inspection and laboratory analysis. This is beyond the scope of the inspection.
- An analysis of indoor air quality is beyond the scope of this inspection.
- Any estimates of insulation "R" values or depths are rough average values.

Plumbing

ITEM DESCRIPTIONS:

Main Water Valve	• Location: Exterior Side
Supply Piping	• Metallic Material
Drain/Waste/Vent	• Plastic Material
Cleanout	• Location: Exterior
Main Gas Valve	• Location: Exterior Rear
Water Heaters	• Manufacturer: A.O. Smith • Capacity: 50 Gallons • Approximate Age (years): 7 • Gas • Location: Garage
Seismic Gas Shut-off	• Not Present
Excess Flow Gas Shut-off	• Not Present

COMMENTS:

Due to the design of this unit/building, most of the supply piping was inaccessible for inspection. For additional information, we recommend a licensed plumbing contractor be consulted.

Due to the design of this unit/building, most of the drain lines were inaccessible for inspection. For additional information, we recommend a licensed plumbing contractor be consulted.

RECOMMENDATIONS/OBSERVATIONS - '!' indicates an immediate improvement recommendation item.

- ! 1. The water heater seismic straps are loose, this will allow movement of the tank in an earthquake. We recommend tightening the straps and/or adding bracing between the tank and wall to improve safety. (See Photo 7)
- ! 2. For enhanced safety, it is recommended that the loose or damaged connections of the water heater venting system be improved. A minimum of 3 screws at each section of the duct is recommended. (See Illustration 8M) (See Photo 9)
- ! 3. The temperature and pressure relief valve for the water heater lacks a proper discharge pipe. We recommend the installation of approved piping to an approved location. (See Photo 8)
4. The installation of a sediment trap at the water heater appliance gas line is recommended.
5. The exterior hose bib handle at the rear of the structure is missing. We recommend it be replaced.
6. There is a metal pan under the water heater to catch dripping water, however the pan is not plumbed to divert the water to the exterior. We recommend the pan be improved to drain any excess water to the exterior of the structure.
- ! 7. The tub faucet and/or handles are leaking at the master bathroom. We recommend all leaks be repaired. (See Photo 18)
- ! 8. The sink faucet hot and cold water controls are reversed at the downstairs hall bathroom and second story hall bathroom. Reversed hot and cold water can result in hot water burns. We recommend that this condition be corrected. (See Illustration 8A) (See Photo 13) (See Photo 19)
9. There is a gap between the tub spout and wall at the downstairs hall and second story hall bathroom which should be sealed to prevent moisture intrusion.

DISCRETIONARY IMPROVEMENTS AND/OR UPGRADES

10. To reduce the risk of contamination of supply water, installation of anti-siphon devices on exterior hose bibs are recommended.

LIMITATIONS:

This is a visual inspection to the accessible areas only. We do not determine whether the properties' water supply and sewage disposal are public or private. Testing of the sinks, tubs and shower fixtures is limited to running hot and cold water for a brief moment, we cannot detect backups or obstructions in the homes main drain or sewer lateral systems.

- Water and gas shut-off valves, including but not limited to seismic, excess flow shut-off valves and gas fireplace valves where applicable, were not operated or tested. Identification of these devices is limited to the accessible areas only.
- Portions of the plumbing system concealed by finishes and/or storage (below sinks, below the structure and beneath the yard) were not inspected.
- Water quantity and quality are not tested. The effect of lead content in solder and/or supply lines is beyond the scope of the inspection.
- Inspection of any water conditioning system (filters, purifiers, softeners, etc.) is beyond the scope of this inspection and are excluded from this report.

- Inspection of any lawn sprinkler system is beyond the scope of this inspection and are excluded from this report (unless noted otherwise).
- The interior portions of the water heater were restricted. For additional information we recommend the services of a licensed plumbing contractor. As a free public service, the local utility company will perform a "safety" review of the interior of the water heater and other gas operated components. We recommend that you take advantage of this service before the next seasonal operation.
- HomeGuard Incorporated does not determine if any fixtures or toilets are water conserving.
- Inspection of the water softener system is beyond the scope of this inspection and is excluded from this report.
- Inspection of the fire sprinkler system and related equipment is beyond the scope of this inspection and are excluded from this report.




Illustration 8A




Illustration 8M

Interior

ITEM DESCRIPTIONS:

Kitchen Appliances Tested	• Built in Electric Oven • Gas Cooktop • Microwave • Dishwasher • Waste Disposer • Exhaust Hood
Wall Finishes	• Drywall/Plaster
Ceiling Finishes	• Drywall/Plaster
Floors	• Tile/Stone • Laminate Flooring
Doors	• Hollow Core • Solid Core • Raised Panel • Sliding
Window Style and Glazing	• Double/Single Hung • Sliders • Double Pane
Stairs/Railings	• Present
Fireplace/Wood Stove	• None
Cabinets/Countertops	• Wood • Solid Surface
Laundry Facilities/Hookup	• 240 Volt Circuit for Dryer • 120 Volt Circuit for Washer • Hot and Cold Water Supply for Washer • Waste Standpipe for Washer • Dryer vent noted
Other Components Inspected	• Smoke Detector • Door Bell • Carbon Monoxide Detector

COMMENTS:

The gas was off at the time of our inspection, therefore the kitchen gas appliances were not tested. We recommend operation of the appliances by interested parties when all services have been restored. (See Photo 14)

RECOMMENDATIONS/OBSERVATIONS - '!' indicates an immediate improvement recommendation item.

INTERIOR

- ! 1. The interior windows at the downstairs bedroom are inoperable, stuck, or painted shut. We recommend repair or replacement to restore functional use of these areas. (See Photo 11)
- ! 2. One or more of the windows are not fully serviceable because their lift mechanism sash cords or springs are missing or damaged. We recommend these windows be repaired and their full functional use restored. (See Photo 16)
- ! 3. Evidence of vermin activity was observed within the structure. It is likely this evidence will extend into inaccessible areas. The owner is advised to contact the appropriate trade for further evaluation and remedial measures if necessary. (See Photo 22)
- 4. The operation of some of the sliding windows is rough. We recommend they be cleaned, lubricated and adjusted for smoother operation.
- 5. It may be desirable to replace the window screens where missing or damaged.
- 6. Various double pane windows were dirty at the time of our inspection, therefore, the condition of the windows was not fully verified. We recommend the windows be cleaned to verify their thermal seal.
- 7. Various interior doors, windows, and electrical outlets were partially inaccessible due to personal belongings and/or furniture at the time of our inspection. With access and an opportunity for a complete inspection, conditions in need of attention may be discovered. We recommend all personal belongings and furniture be removed and these areas further inspected.
- 8. The window at the right side wall exhibits conditions and/or symptoms that indicate a possible breached seal or failed thermal pane. This has or can result in condensation and/or moisture developing between the panes of glass that will effect the cosmetic appearance of the windows and their insulating performance. We recommend all insulated glass units be further evaluated by a licensed glazier and repaired or replaced as required.

KITCHEN

- ! 9. The air-gap or its connection to the disposal, appears to be restricted, causing water to flow out of the air-gap during the drain cycle of the dishwasher. We recommend that the drain system be cleaned or modified to correct this deficiency. (See Illustration 9F) (See Photo 15)

BATHROOMS

- ! 10. Cracked, deteriorated and/or missing tub/shower enclosure caulk in the master bathroom should be replaced. Water leaking through non-sealed areas can cause damage. Damage caused by water seepage cannot be determined by this visual observation. (See Photo 21)
- ! 11. The base and/or side of the master bathroom sink cabinet sink shelf is deteriorated. We recommend the advice and services of a licensed pest control operator for investigation and possible repair of this condition. (See Photo 20)
- 12. The tub drain stopper at the second story hall bathroom was not functioning properly or is missing. We recommend repair or replacement. (See Illustration 9E)

13. The window and sill of the downstairs hall bathroom bathtub and second story hall bathroom bathtub and master bathroom bathtub enclosure should be protected from moisture. Windows in bathtub/shower enclosures have a reputation for allowing leakage behind the walls, causing water damage. Damage caused by water seepage cannot be determined by this visual observation.

MAINTENANCE ITEMS & GENERAL INFORMATION

INTERIOR

14. The evaluation of the thermal pane windows ("dual pane/glazed") is limited to accessible windows exhibiting noticeable conditions at the time of our inspection, such as condensation and/or evidence of moisture developing between the panes of glass. Due to the known design and/or characteristics associated with thermal pane windows, conditions may be discovered at a later date, however seal failure can occur at any time.

KITCHEN

15. Carbon monoxide is a colorless, odorless gas that can result from a faulty fuel burning furnace, range, water heater, space heater or wood stove. Proper maintenance of these appliances is the best way to reduce the risk of carbon monoxide poisoning. For more information, consult the Consumer Product Safety Commission CPSC at www.cpsc.gov for further guidance.

LIMITATIONS:

This is a visual inspection to the accessible areas only. Assessing the quality of interior finishes is highly subjective. Issues such as cleanliness, cosmetic flaws, quality of materials, architectural appeal and color are outside the scope of this inspection. Comments are general, except where functional concerns exist. Due to texturing and painting of interior surfaces there is no possible way of determining point of origin of any gypsum (sheetrock) material without destructive testing. HomeGuard Incorporated does not perform any destructive testing. Smoke detectors and carbon monoxide detectors were not manually tested. The sensors of these units are not tested. Both smoke detectors and carbon monoxide detectors have a limited life span and should be replaced according to the manufactures instructions.

- Furniture, storage, appliances and/or wall hangings restricted the inspection of the interior.
- No access was gained to the wall cavities of the home.
- The operation of the dishwasher was limited to a filling and draining cycle only, however due to time limitations timers, dryer cycles and/or higher functions were not tested. For additional information in regards to the operation and full function of the dishwasher we recommend consultation with the owner or appropriate trades.
- The washing machine faucets were visually inspected however they were not tested.
- The above listed kitchen appliances were operated unless noted otherwise. These appliances were not inspected for installation according to manufacturer specifications and were not evaluated for performance, efficiency or adequacy during their operation. No refrigerators whether "built in" or portable are operated, inspected or tested.
- All appliances not "built in" to the structure such as washing machine, dryer, refrigerator and/or countertop microwaves were not inspected and are excluded from this report. No refrigerators whether "built in" or portable are operated, inspected or tested.
- Fireplace screens or doors were not inspected (unless otherwise noted) and are excluded from this report.
- Testing of the oven cleaning function is beyond the scope of this inspection. For proper operation and testing of this function we recommend consultation with the existing homeowner.




Illustration 9F




Illustration 9E

Photographs

No relative importance should be placed on the photographs provided in this report. The photographs in this report do not necessarily illustrate all of the damage in any particular finding. Also, not all problem areas will be supported with photographs. Please contact HomeGuard if you have any questions.



Photo 01



Photo 02



Photo 03



Photo 04



Photo 05



Photo 06



Photo 07



Photo 08



Photo 09



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22

Maintenance Advice

UPON TAKING OWNERSHIP

After taking ownership of a new home, there are some maintenance and safety issues that should be addressed immediately. The following checklist should help you undertake these improvements.

- ☐ Change the locks on all exterior entrances, for improved security.
- ☐ Check that all windows and doors are secure. Improve window hardware as necessary. Security rods can be added to sliding windows and doors. Considerations could also be given to a security system.
- ☐ Install smoke detectors on each level of the home. Ensure that there is a smoke detector outside all sleeping areas. Replace batteries on any existing smoke detectors and test them. Make a note to replace batteries again in one year.
- ☐ Create a plan of action in the event of a fire in your home. Ensure that there is an operable window or door in every room of the house. Consult with your local fire department regarding fire safety issues and what to do in the event of a fire.
- ☐ Examine driveways and walkways for trip hazards. Undertake repairs where necessary.
- ☐ Examine the interior of the home for trip hazards. Loose or torn carpeting and flooring should be repaired.
- ☐ Undertake improvements to all stairways, decks, porches and landings where there is a risk of falling or stumbling.
- ☐ Review your home inspection report for any items that require immediate improvement or further investigation. Address these areas as required.
- ☐ Install rain caps and vermin screens on all chimney flues, as necessary.
- ☐ Investigate the location of the main shut-offs for the plumbing, heating and electrical systems. If you attend the home inspection, these items have been pointed out to you.

REGULAR MAINTENANCE

EVERY MONTH

- ☐ Check that fire extinguisher(s) are fully charged. Re-charge if necessary.
- ☐ Examine heating/cooling air filters and replace or clean as necessary.
- ☐ Inspect and clean humidifiers and electronic air cleaners.
- ☐ If the house has hot water heating, bleed radiator valves.
- ☐ Clean gutters and downspouts. Ensure that downspouts are secure, and that the discharge of the downspouts is appropriate. Remove debris from window wells.
- ☐ Carefully inspect the condition of shower enclosures. Repair or replace deteriorated grout and caulk. Ensure that water is not escaping the enclosure during showering. Check below all plumbing fixtures for evidence of leakage.
- ☐ Repair or replace leaking faucets or shower heads.
- ☐ Secure loose toilets, or repair flush mechanisms that become troublesome.

SPRING AND FALL

- ☐ Examine the roof for evidence of damage to roof covering, flashings and chimneys.
- ☐ Look in the attic (if accessible) to ensure that roof vents are not obstructed. Check for evidence of leakage, condensation or vermin activity. Level out insulation if needed.
- ☐ Trim back tree branches and shrubs to ensure that they are not in contact with the house.
- ☐ Inspect the exterior walls and foundation for evidence of damage, cracking or movement. Watch for bird nests or other vermin or insect activity.
- ☐ Survey the basement and/or crawl space walls for evidence of moisture seepage.
- ☐ Look at overhead wires coming to the house. They should be secure and clear of trees or other obstructions.
- ☐ Ensure that the grade of the land around the house encourages water to flow away from the foundation.

- ☐ Inspect all driveways, walkways, decks, porches, and landscape components for evidence of deterioration, movement or safety hazards.
- ☐ Clean windows and test their operation. Improve caulking and weather-stripping as necessary. Watch for evidence of rot in wood windows frames. Paint and repair window sills and frames as necessary.
- ☐ Test all ground fault circuit interrupter (GFCI) devices, as identified in the inspection report.
- ☐ Shut off isolating valves for exterior hose bibs in the fall, if below freezing temperatures are anticipated.
- ☐ Test the Temperature and Pressure Relief (TPR) Valve on water heaters.
- ☐ Inspect for evidence of wood boring insect activity. Eliminate any wood/soil contact around the perimeter of the home.
- ☐ Test the overhead garage door opener, to ensure that the auto-reverse mechanism is responding properly. Clean and lubricate hinges, rollers and tracks on overhead doors.
- ☐ Replace or clean exhaust hood filters.
- ☐ Clean, inspect and/or service all appliances as per the manufacturer's recommendations.

ANNUALLY

- ☐ Replace smoke detector batteries.
- ☐ Have the heating, cooling and water heater systems cleaned and serviced.
- ☐ Have chimneys inspected and cleaned. Ensure that rain caps and vermin screens are secure.
- ☐ Examine the electrical panels, wiring and electrical components for evidence of overheating. Ensure that all components are secure. Flip the breakers on and off to ensure that they are not sticky.
- ☐ If the house utilizes a well, check and service the pump and holding tank. Have the water quality tested. If the property has a septic system, have the tank inspected (and pumped as needed).
- ☐ If your home is in an area prone to wood destroying insects (termites, carpenter ants, etc.), have the home inspected by a licensed specialist. Preventive treatments may be recommended in some cases.

PREVENTION IS THE BEST APPROACH

Although we've heard it many times, nothing could be more true than the old cliché "an ounce of prevention is worth a pound of cure." Preventative maintenance is the best way to keep your house in great shape. It also reduces the risk of unexpected repairs and improves the odds of selling your house at fair market value, when the time comes. Please feel free to contact our office should you have any questions regarding the operation or maintenance of your home. Enjoy your home!



Invoice

Invoice Date 5/9/2025

Invoice No: 1136242P

Bill To:

Ashwin Veeravalli
The Agency
497 N. Santa Cruz Avenue
Los Gatos, CA 95030

Property Information:

Address: 825 S. 22nd Street
San Jose CA, 95116
Report No: 657384TPR
Escrow#:

Billing Information:

5/9/2025	Home Inspection	\$835.00
----------	-----------------	----------

Total Due:	\$835.00
------------	----------

DUE UPON RECEIPT

Please remit to 510 Madera Ave., San Jose, CA 95112

There is a \$25 fee for all returned checks