

Version 9

# Design of Experiments Guide

"The real voyage of discovery consists not in seeking new landscapes, but in having new eyes."

Marcel Proust

The correct bibliographic citation for this manual is as follows: SAS Institute Inc. 2010. *JMP*<sup>®</sup> 9 Design of Experiments Guide . Cary, NC: SAS Institute Inc.

#### JMP® 9 Design of Experiments Guide

Copyright © 2010, SAS Institute Inc., Cary, NC, USA

ISBN 978-1-60764-597-9

All rights reserved. Produced in the United States of America.

For a hard-copy book: No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without the prior written permission of the publisher, SAS Institute Inc.

For a Web download or e-book: Your use of this publication shall be governed by the terms established by the vendor at the time you acquire this publication.

The scanning, uploading, and distribution of this book via the Internet or any other means without the permission of the publisher is illegal and punishable by law. Please purchase only authorized electronic editions and do not participate in or encourage electronic piracy of copyrighted materials. Your support of others' rights is appreciated.

U.S. Government Restricted Rights Notice: Use, duplication, or disclosure of this software and related documentation by the U.S. government is subject to the Agreement with SAS Institute and the restrictions set forth in FAR 52.227-19, Commercial Computer Software-Restricted Rights (June 1987).

SAS Institute Inc., SAS Campus Drive, Cary, North Carolina 27513.

1st printing, September 2010

2nd printing, January 2011

3rd printing, June 2011

SAS® Publishing provides a complete selection of books and electronic products to help customers use SAS software to its fullest potential. For more information about our e-books, e-learning products, CDs, and hard-copy books, visit the SAS Publishing Web site at support.sas.com/publishing or call 1-800-727-3228.

 $JMP^{\circledR}$ ,  $SAS^{\circledR}$  and all other SAS Institute Inc. product or service names are registered trademarks or trademarks of SAS Institute Inc. in the USA and other countries.  $\circledR$  indicates USA registration.

Other brand and product names are registered trademarks or trademarks of their respective companies.

# Get the Most from JMP®

Whether you are a first-time or a long-time user, there is always something to learn about JMP.

Visit JMP.com to find the following:

- live and recorded Webcasts about how to get started with JMP
- video demos and Webcasts of new features and advanced techniques
- schedules for seminars being held in your area
- success stories showing how others use JMP
- a blog with tips, tricks, and stories from JMP staff
- a forum to discuss JMP with other users

http://www.jmp.com/getstarted/

# **Contents**

# **Design of Experiments**

About Designing Experiments	3
My First Experiment	3
The Situation	3
Step 1: Design the Experiment	3
Step 2: Define Factor Constraints	5
Step 3: Add Interaction Terms	6
Step 4: Determine the Number of Runs	7
Step 5: Check the Design	
Step 6: Gather and Enter the Data	
Step 7: Analyze the Results	Ю
xamples Using the Custom Designer	
	15
Creating Screening Experiments	17
Creating a Main-Effects-Only Screening Design	
, , , , , , , , , , , , , , , , , , , ,	
Creating a Screening Design to Fit All Two-Factor Interactions	19
Creating a Screening Design to Fit All Two-Factor Interactions  A Compromise Design Between Main Effects Only and All Interactions	
	21
A Compromise Design Between Main Effects Only and All Interactions	2I 23
A Compromise Design Between Main Effects Only and All Interactions	2I 23 27
A Compromise Design Between Main Effects Only and All Interactions  Creating 'Super' Screening Designs  Screening Designs with Flexible Block Sizes	2I 23 27 3I
A Compromise Design Between Main Effects Only and All Interactions Creating 'Super' Screening Designs Screening Designs with Flexible Block Sizes Checking for Curvature Using One Extra Run Creating Response Surface Experiments	21 23 27 31 34
A Compromise Design Between Main Effects Only and All Interactions Creating 'Super' Screening Designs Screening Designs with Flexible Block Sizes Checking for Curvature Using One Extra Run Creating Response Surface Experiments Exploring the Prediction Variance Surface	21 23 27 31 34
A Compromise Design Between Main Effects Only and All Interactions Creating 'Super' Screening Designs Screening Designs with Flexible Block Sizes Checking for Curvature Using One Extra Run Creating Response Surface Experiments	211 233 277 311 344 353 37
A Compromise Design Between Main Effects Only and All Interactions Creating 'Super' Screening Designs Screening Designs with Flexible Block Sizes Checking for Curvature Using One Extra Run  Creating Response Surface Experiments Exploring the Prediction Variance Surface Introducing I-Optimal Designs for Response Surface Modeling	211 233 277 311 344 35 37 38
A Compromise Design Between Main Effects Only and All Interactions Creating 'Super' Screening Designs Screening Designs with Flexible Block Sizes Checking for Curvature Using One Extra Run  Creating Response Surface Experiments Exploring the Prediction Variance Surface Introducing I-Optimal Designs for Response Surface Modeling A Three-Factor Response Surface Design Response Surface with a Blocking Factor	211 233 277 311 344 355 377 388 40
A Compromise Design Between Main Effects Only and All Interactions Creating 'Super' Screening Designs Screening Designs with Flexible Block Sizes Checking for Curvature Using One Extra Run  Creating Response Surface Experiments Exploring the Prediction Variance Surface Introducing I-Optimal Designs for Response Surface Modeling A Three-Factor Response Surface Design	211 233 277 311 344 355 377 388 400 444

	Special-Purpose Uses of the Custom Designer
	Designing Experiments with Fixed Covariate Factors
	Creating a Design with Two Hard-to-Change Factors: Split Plot
	Technical Discussion
3	Building Custom Designs
•	The Basic Steps
	Creating a Custom Design
	Enter Responses and Factors into the Custom Designer
	Describe the Model
	Specifying Alias Terms
	Select the Number of Runs
	Understanding Design Evaluation
	Specify Output Options
	Make the JMP Design Table
	Creating Random Block Designs
	Creating Split Plot Designs
	Creating Split-Split Plot Designs
	Creating Strip Plot Designs
	Special Custom Design Commands
	Save Responses and Save Factors
	Load Responses and Load Factors 85
	Save Constraints and Load Constraints
	Set Random Seed: Setting the Number Generator
	Simulate Responses
	Save X Matrix: Viewing the Number of Rows in the Moments Matrix and the Design Matrix (X) in the Log
	Optimality Criterion
	Number of Starts: Changing the Number of Random Starts
	Sphere Radius: Constraining a Design to a Hypersphere
	Disallowed Combinations: Accounting for Factor Level Restrictions
	Advanced Options for the Custom Designer
	Save Script to Script Window
	Assigning Column Properties
	Define Low and High Values (DOE Coding) for Columns
	Set Columns as Factors for Mixture Experiments
	Define Response Column Values

	Assign Columns a Design Role	
	How Custom Designs Work: Behind the Scenes	
4	Screening Designs	IOI
	Screening Design Examples	103
		103
	Creating a Screening Design	109
	Enter Responses Enter Factors Choose a Design Display and Modify a Design Specify Output Options View the Design Table	111 115 119
	Create a Plackett-Burman design	120
	Analysis of Screening Data  Using the Screening Analysis Platform  Using the Fit Model Platform	123
5	Response Surface Designs	127
	The Prediction Profiler	129 132 134 136
	Creating a Response Surface Design	136
	Enter Responses and Factors Choose a Design Specify Output Options View the Design Table	139
6	Full Factorial Designs	
		143
	The Five-Factor Reactor Example	145 146
	Creating a Factorial Design	

	Enter Responses and Factors
	Select Output Options
	Make the Table
7	Mixture Designs
	155
	Mixture Design Types
	The Optimal Mixture Design
	The Simplex Centroid Design
	Creating the Design
	The Simplex Lattice Design
	The Extreme Vertices Design
	Creating the Design
	An Extreme Vertices Example with Range Constraints
	An Extreme Vertices Example with Linear Constraints
	The ABCD Design
	Creating Ternary Plots
	Fitting Mixture Designs170
	Whole Model Tests and Analysis of Variance Reports
	Understanding Response Surface Reports
	A Chemical Mixture Example
	Create the Design
	Analyze the Mixture Model
	The Prediction Profiler
	A Ternary Plot of the Mixture Response Surface
8	Discrete Choice Designs
0	
	Introduction
	Create an Example Choice Experiment
	Analyze the Example Choice Experiment
	Design a Choice Experiment Using Prior Information
	Administer the Survey and Analyze Results

	Initial Choice Platform Analysis	
9	Space-Filling Designs	192
•		195
	Introduction to Space-Filling Designs	197
	Sphere-Packing Designs	197
		197 199
	Latin Hypercube Designs	200
	Creating a Latin Hypercube Design  Visualizing the Latin Hypercube Design	
	Uniform Designs	204
	Comparing Sphere-Packing, Latin Hypercube, and Uniform Methods	206
	Minimum Potential Designs	207
	Maximum Entropy Designs	209
	Gaussian Process IMSE Optimal Designs	211
	Borehole Model: A Sphere-Packing Example	211
	Create the Sphere-Packing Design for the Borehole Data Guidelines for the Analysis of Deterministic Data	213
	Results of the Borehole Experiment	213
10	Accelerated Life Test Designs Designing Experiments for Accelerated Life Tests	217
	Overview of Accelerated Life Test Designs	219
	Using the ALT Design Platform	219
	Platform Options	224
	Example	224
11	Nonlinear Designs	229
	Examples of Nonlinear Designs	
	Using Nonlinear Fit to Find Prior Parameter Estimates  Creating a Nonlinear Design with No Prior Data	
	Creating a Nonlinear Design	241
	Identify the Response and Factor Column with Formula	241

	Set Up Factors and Parameters in the Nonlinear Design Dialog	242
	Enter the Number of Runs and Preview the Design	
	Make Table or Augment the Table	
	Advanced Options for the Nonlinear Designer	245
12	Taguchi Designs	
		247
	The Taguchi Design Approach	249
	Taguchi Design Example	249
	Analyze the Data	252
	Creating a Taguchi Design	254
	Detail the Response and Add Factors	
	Choose Inner and Outer Array Designs	
	Display Coded Design	-
	Make the Design Table	257
13	Augmented Designs	
	A D-Optimal Augmentation of the Reactor Example	
	Analyze the Augmented Design	264
	Creating an Augmented Design	271
	Replicate a Design	
	Add Center Points	
		276
	Adding New Runs and Terms	277 278
	Special Augment Design Commands	
	Save the Design (X) Matrix	
	Modify the Design Criterion ( <i>D</i> - or <i>I</i> - Optimality)	
	Select the Number of Random Starts	
	Specify the Sphere Radius Value	
	Disallow Factor Combinations	284
14	Prospective Sample Size and Power	
		285
	Launching the Sample Size and Power Platform	287
	One-Sample and Two-Sample Means	287
	Single-Sample Mean	289

	Sample Size and Power Animation for One Mean	292
	Two-Sample Means	293
	k-Sample Means	294
	One Sample Standard Deviation	296
	One Sample Standard Deviation Example	297
	One-Sample and Two-Sample Proportions	298
	One Sample Proportion	298
	Two Sample Proportions	300
	Counts per Unit	303
	Counts per Unit Example	304
	Sigma Quality Level	305
	Sigma Quality Level Example	305
	Number of Defects Computation Example	306
	Reliability Test Plan and Demonstration	-
	Reliability Test Plan	
	Reliability Demonstration	309
lr	ndex	
	Design of Experiments	317

### **Credits and Acknowledgments**

#### Origin

JMP was developed by SAS Institute Inc., Cary, NC. JMP is not a part of the SAS System, though portions of JMP were adapted from routines in the SAS System, particularly for linear algebra and probability calculations. Version 1 of JMP went into production in October 1989.

#### **Credits**

JMP was conceived and started by John Sall. Design and development were done by John Sall, Chung-Wei Ng, Michael Hecht, Richard Potter, Brian Corcoran, Annie Dudley Zangi, Bradley Jones, Craige Hales, Chris Gotwalt, Paul Nelson, Xan Gregg, Jianfeng Ding, Eric Hill, John Schroedl, Laura Lancaster, Scott McQuiggan, Melinda Thielbar, Clay Barker, Peng Liu, Dave Barbour, Jeff Polzin, John Ponte, and Steve Amerige.

In the SAS Institute Technical Support division, Duane Hayes, Wendy Murphrey, Rosemary Lucas, Win LeDinh, Bobby Riggs, Glen Grimme, Sue Walsh, Mike Stockstill, Kathleen Kiernan, and Liz Edwards provide technical support.

Nicole Jones, Kyoko Keener, Hui Di, Joseph Morgan, Wenjun Bao, Fang Chen, Susan Shao, Michael Crotty, Jong-Seok Lee, Tonya Mauldin, Audrey Ventura, Ani Eloyan, Bo Meng, and Sequola McNeill provide ongoing quality assurance. Additional testing and technical support are provided by Noriki Inoue, Kyoko Takenaka, Yusuke Ono, Masakazu Okada, and Naohiro Masukawa from SAS Japan.

Bob Hickey and Jim Borek are the release engineers.

The JMP books were written by Ann Lehman, Lee Creighton, John Sall, Bradley Jones, Erin Vang, Melanie Drake, Meredith Blackwelder, Diane Perhac, Jonathan Gatlin, Susan Conaghan, and Sheila Loring, with contributions from Annie Dudley Zangi and Brian Corcoran. Creative services and production was done by SAS Publications. Melanie Drake implemented the Help system.

Jon Weisz and Jeff Perkinson provided project management. Also thanks to Lou Valente, Ian Cox, Mark Bailey, and Malcolm Moore for technical advice.

Thanks also to Georges Guirguis, Warren Sarle, Gordon Johnston, Duane Hayes, Russell Wolfinger, Randall Tobias, Robert N. Rodriguez, Ying So, Warren Kuhfeld, George MacKensie, Bob Lucas, Warren Kuhfeld, Mike Leonard, and Padraic Neville for statistical R&D support. Thanks are also due to Doug Melzer, Bryan Wolfe, Vincent DelGobbo, Biff Beers, Russell Gonsalves, Mitchel Soltys, Dave Mackie, and Stephanie Smith, who helped us get started with SAS Foundation Services from JMP.

#### **Acknowledgments**

We owe special gratitude to the people that encouraged us to start JMP, to the alpha and beta testers of JMP, and to the reviewers of the documentation. In particular we thank Michael Benson, Howard Yetter (d),

Andy Mauromoustakos, Al Best, Stan Young, Robert Muenchen, Lenore Herzenberg, Ramon Leon, Tom Lange, Homer Hegedus, Skip Weed, Michael Emptage, Pat Spagan, Paul Wenz, Mike Bowen, Lori Gates, Georgia Morgan, David Tanaka, Zoe Jewell, Sky Alibhai, David Coleman, Linda Blazek, Michael Friendly, Joe Hockman, Frank Shen, J.H. Goodman, David Iklé, Barry Hembree, Dan Obermiller, Jeff Sweeney, Lynn Vanatta, and Kris Ghosh.

Also, we thank Dick DeVeaux, Gray McQuarrie, Robert Stine, George Fraction, Avigdor Cahaner, José Ramirez, Gudmunder Axelsson, Al Fulmer, Cary Tuckfield, Ron Thisted, Nancy McDermott, Veronica Czitrom, Tom Johnson, Cy Wegman, Paul Dwyer, DaRon Huffaker, Kevin Norwood, Mike Thompson, Jack Reese, François Mainville, and John Wass.

We also thank the following individuals for expert advice in their statistical specialties: R. Hocking and P. Spector for advice on effective hypotheses; Robert Mee for screening design generators; Roselinde Kessels for advice on choice experiments; Greg Piepel, Peter Goos, J. Stuart Hunter, Dennis Lin, Doug Montgomery, and Chris Nachtsheim for advice on design of experiments; Jason Hsu for advice on multiple comparisons methods (not all of which we were able to incorporate in JMP); Ralph O'Brien for advice on homogeneity of variance tests; Ralph O'Brien and S. Paul Wright for advice on statistical power; Keith Muller for advice in multivariate methods, Harry Martz, Wayne Nelson, Ramon Leon, Dave Trindade, Paul Tobias, and William Q. Meeker for advice on reliability plots; Lijian Yang and J.S. Marron for bivariate smoothing design; George Milliken and Yurii Bulavski for development of mixed models; Will Potts and Cathy Maahs-Fladung for data mining; Clay Thompson for advice on contour plotting algorithms; and Tom Little, Damon Stoddard, Blanton Godfrey, Tim Clapp, and Joe Ficalora for advice in the area of Six Sigma; and Josef Schmee and Alan Bowman for advice on simulation and tolerance design.

For sample data, thanks to Patrice Strahle for Pareto examples, the Texas air control board for the pollution data, and David Coleman for the pollen (eureka) data.

#### **Translations**

Trish O'Grady coordinates localization. Special thanks to Noriki Inoue, Kyoko Takenaka, Masakazu Okada, Naohiro Masukawa, and Yusuke Ono (SAS Japan); and Professor Toshiro Haga (retired, Tokyo University of Science) and Professor Hirohiko Asano (Tokyo Metropolitan University) for reviewing our Japanese translation; François Bergeret for reviewing the French translation; Bertram Schäfer and David Meintrup (consultants, StatCon) for reviewing the German translation; Patrizia Omodei, Maria Scaccabarozzi, and Letizia Bazzani (SAS Italy) for reviewing the Italian translation; RuiQi Qiao, Rula Li, and Molly Li for reviewing Simplified Chinese translation (SAS R&D Beijing); Finally, thanks to all the members of our outstanding translation and engineering teams.

#### **Past Support**

Many people were important in the evolution of JMP. Special thanks to David DeLong, Mary Cole, Kristin Nauta, Aaron Walker, Ike Walker, Eric Gjertsen, Dave Tilley, Ruth Lee, Annette Sanders, Tim Christensen, Eric Wasserman, Charles Soper, Wenjie Bao, and Junji Kishimoto. Thanks to SAS Institute quality assurance by Jeanne Martin, Fouad Younan, and Frank Lassiter. Additional testing for Versions 3 and 4 was done by Li Yang, Brenda Sun, Katrina Hauser, and Andrea Ritter.

Also thanks to Jenny Kendall, John Hansen, Eddie Routten, David Schlotzhauer, and James Mulherin. Thanks to Steve Shack, Greg Weier, and Maura Stokes for testing JMP Version 1.

Thanks for support from Charles Shipp, Harold Gugel (d), Jim Winters, Matthew Lay, Tim Rey, Rubin Gabriel, Brian Ruff, William Lisowski, David Morganstein, Tom Esposito, Susan West, Chris Fehily, Dan Chilko, Jim Shook, Ken Bodner, Rick Blahunka, Dana C. Aultman, and William Fehlner.

#### **Technology License Notices**

Scintilla is Copyright 1998-2003 by Neil Hodgson <neilh@scintilla.org>. Neil Hodgson disclaims all warranties with regard to this software, including all implied warranties of merchantability and fitness, in no event shall neil hodgson be liable for any special, indirect or consequential damages or any damages whatsoever resulting from loss of use, data or profits, whether in an action of contract, negligence or other tortious action, arising out of or in connection with the use or performance of this software.

XRender is Copyright © 2002 Keith Packard. Keith Packard disclaims all warranties with regard to this software, including all implied warranties of merchantability and fitness, in no event shall keith packard be liable for any special, indirect or consequential damages or any damages whatsoever resulting from loss of use, data or profits, whether in an action of contract, negligence or other tortious action, arising out of or in connection with the use or performance of this software.

ImageMagick software is Copyright © 1999-2010 ImageMagick Studio LLC, a non-profit organization dedicated to making software imaging solutions freely available.

bzlib software is Copyright © 1991-2009, Thomas G. Lane, Guido Vollbeding. All Rights Reserved.

FreeType software is Copyright © 1996-2002 The FreeType Project (www.freetype.org). All rights reserved.

# Chapter 1

# **Introduction to Designing Experiments**

A Beginner's Tutorial

This tutorial chapter introduces you to the design of experiments (DOE) using JMP's custom designer. It gives a general understanding of how to design an experiment using JMP. Refer to subsequent chapters in this book for more examples and procedures on how to design an experiment for your specific project.

# **Contents**

About Designing Experiments
My First Experiment
The Situation
Step 1: Design the Experiment
Step 2: Define Factor Constraints
Step 3: Add Interaction Terms
Step 4: Determine the Number of Runs
Step 5: Check the Design 8
Step 6: Gather and Enter the Data9
Step 7: Analyze the Results

#### **About Designing Experiments**

Increasing productivity and improving quality are important goals in any business. The methods for determining *how* to increase productivity and improve quality are evolving. They have changed from costly and time-consuming trial-and-error searches to the powerful, elegant, and cost-effective statistical methods that JMP provides.

Designing experiments in JMP is centered around factors, responses, a model, and runs. JMP helps you determine if and how a factor affects a response.

#### My First Experiment

If you have never used JMP to design an experiment, this section shows you how to design the experiment and how to understand JMP's output.

**Tip:** The recommended way to create an experiment is to use the custom designer. JMP also provides classical designs for use in textbook situations.

#### The Situation

Your goal is to find the best way to microwave a bag of popcorn. Because you have some experience with this, it is easy to decide on reasonable ranges for the important factors:

- how long to cook the popcorn (between 3 and 5 minutes)
- what level of power to use on the microwave oven (between settings 5 and 10)
- which brand of popcorn to use (Top Secret or Wilbur)

When a bag of popcorn is popped, most of the kernels pop, but some remain unpopped. You prefer to have all (or nearly all) of the kernels popped and no (or very few) unpopped kernels. Therefore, you define "the best popped bag" based on the ratio of popped kernels to the total number of kernels.

A good way to improve any procedure is to conduct an experiment. For each experimental run, JMP's custom designer determines which brand to use, how long to cook each bag in the microwave and what power setting to use. Each *run* involves popping one bag of corn. After popping a bag, enter the total number of kernels and the number of popped kernels into the appropriate row of a JMP data table. After doing all the experimental runs, use JMP's model fitting capabilities to do the data analysis. Then, you can use JMP's profiling tools to determine the optimal settings of popping time, power level, and brand.

#### Step 1: Design the Experiment

The first step is to select **DOE** > **Custom Design**. Then, define the responses and factors.


#### Define the Responses: Popped Kernels and Total Kernels

There are two responses in this experiment:

- the number of popped kernels
- the total number of kernels in the bag. After popping the bag add the number of unpopped kernels to the number of popped kernels to get the total number of kernels in the bag.

By default, the custom designer contains one response labeled Y (Figure 1.1).

Figure 1.1 Custom Design Responses Panel




You want to add a second response to the Responses panel and change the names to be more descriptive:

- 1. To rename the Y response, double-click the name and type "Number Popped." Since you want to increase the number of popped kernels, leave the goal at **Maximize**.
- 2. To add the second response (total number of kernels), click **Add Response** and choose **None** from the menu that appears. JMP labels this response Y2 by default.
- 3. Double-click Y2 and type "Total Kernels" to rename it.

The completed Responses panel looks like Figure 1.2.

Figure 1.2 Renamed Responses with Specified Goals



#### Define the Factors: Time, Power, and Brand

In this experiment, the factors are:

- brand of popcorn (Top Secret or Wilbur)
- cooking time for the popcorn (3 or 5 minutes)
- microwave oven power level (setting 5 or 10)

In the Factors panel, add Brand as a two-level categorical factor:

- 1. Click Add Factor and select Categorical > 2 Level.
- 2. To change the name of the factor (currently named X1), type Brand.
- 3. To rename the default levels (L1 and L2), click the level names and type Top Secret and Wilbur.


Add Time as a two-level continuous factor:

- 4. Click Add Factor and select Continuous.
- 5. Change the default name of the factor (X2) by typing Time.
- 6. Likewise, to rename the default levels (-1 and 1) as 3 and 5, click the current level name and type in the new value.

Add Power as a two-level continuous factor:

- Click Add Factor and select Continuous.
- 8. Change the name of the factor (currently named X3) by typing Power.
- 9. Rename the default levels (currently named **-1** and **1**) as 5 and 10 by clicking the current name and typing. The completed Factors panel looks like Figure 1.3.

Figure 1.3 Renamed Factors with Specified Values



10. Click Continue.

#### **Step 2: Define Factor Constraints**

The popping time for this experiment is either 3 or 5 minutes, and the power settings on the microwave are 5 and 10. From experience, you know that

- popping corn for a long time on a high setting tends to scorch kernels.
- not many kernels pop when the popping time is brief and the power setting is low.


You want to constrain the combined popping time and power settings to be less than or equal to 13, but greater than or equal to 10. To define these limits:

My First Experiment

- 1. Open the Constraints panel by clicking the disclosure button beside the **Define Factor Constraints** title bar (see Figure 1.4).
- 2. Click the Add Constraint button twice, once for each of the known constraints.
- 3. Complete the information, as shown to the right in Figure 1.4. These constraints tell the Custom Designer to avoid combinations of Power and Time that sum to less than 10 and more than 13. Be sure to change <= to >= in the second constraint.

The area inside the parallelogram, illustrated on the left in Figure 1.4, is the allowable region for the runs. You can see that popping for 5 minutes at a power of 10 is not allowed and neither is popping for 3 minutes at a power of 5.

Figure 1.4 Defining Factor Constraints



#### **Step 3: Add Interaction Terms**

You are interested in the possibility that the effect of any factor on the proportion of popped kernels may depend on the value of some other factor. For example, the effect of a change in popping time for the Wilbur popcorn brand could be larger than the same change in time for the Top Secret brand. This kind of synergistic effect of factors acting in concert is called a *two-factor interaction*. You can examine all possible two-factor interactions in your *a priori* model of the popcorn popping process.


1. Click **Interactions** in the Model panel and select **2nd**. JMP adds two-factor interactions to the model as shown to the left in Figure 1.5.


In addition, you suspect the graph of the relationship between any factor and any response might be curved. You can see whether this kind of curvature exists with a quadratic model formed by adding the second order powers of effects to the model, as follows.

2. Click Powers and select 2nd to add quadratic effects of the continuous factors, Power and Time.

The completed Model should look like the one to the right in Figure 1.5.

Figure 1.5 Add Interaction and Power Terms to the Model






#### **Step 4: Determine the Number of Runs**

The Design Generation panel in Figure 1.6 shows the minimum number of runs needed to perform the experiment with the effects you've added to the model. You can use that minimum or the default number of runs, or you can specify your own number of runs as long as that number is more than the minimum. JMP has no restrictions on the number of runs you request. For this example, use the default number of runs, 16. Click **Make Design** to continue.

Figure 1.6 Model and Design Generation Panels



#### Step 5: Check the Design

When you click **Make Design**, JMP generates and displays a design, as shown on the left in Figure 1.7. Note that because JMP uses a random seed to generate custom designs and there is no unique optimal design for this problem, your table may be different than the one shown here. You can see in the table that the custom design requires 8 runs using each brand of popcorn.

Scroll to the bottom of the Custom Design window and look at the Output Options area (shown to the right in Figure 1.7. The Run Order option lets you designate the order you want the runs to appear in the data table when it is created. Keep the selection at Randomize so the rows (runs) in the output table appear in a random order.

Now click **Make Table** in the Output Options section.




Figure 1.7 Design and Output Options Section of Custom Designer

The resulting data table (Figure 1.8) shows the order in which you should do the experimental runs and provides columns for you to enter the number of popped and total kernels. Note that the design matrix is updated to match the order of runs, the Time and Power values, and the Number Popped and Total Kernels columns are added.

You do not have fractional control over the power and time settings on a microwave oven, so you should round the power and time settings, as shown in the data table. Although this altered design is slightly less optimal than the one the custom designer suggested, the difference is negligible.

**Tip:** Note that optionally, before clicking **Make Table** in the Output Options, you could select **Sort Left to Right** in the Run Order menu to have JMP present the results in the data table according to the brand. We have conducted this experiment for you and placed the results, called **Popcorn DOE Results.jmp**, in the **Sample Data** folder installed with JMP. These results have the columns sorted from left to right.

▼ Custom Design	4 €					
Design Custom Design	•	Brand	Time	Power	Number Popped	Total Kernels
Criterion D Optimal	1	Wilbur	3	7	•	•
Screening	2	Top Secret	3	7		
▼ Model	3	Top Secret	5	5	•	•
Constraint     □ DOE Dialog	4	Wilbur	3	10	•	•
▼ DOE Dialog	5	Wilbur	3	7	•	•
	6	Top Secret	3	9	•	•
	7	Top Secret	5	8	•	•
	8	Wilbur	5	5	•	•
▼ Columns (5/0)	9	Top Secret	5	7	•	•
■ Brand 🛪	10	Top Secret	3	10	•	•
✓ Time ★	11	Top Secret	4	9	•	•
✓ Power ★	12	Top Secret	4	6		•
🚄 Number Popped 🛠	13	Wilbur	5	8	•	•
🚄 Total Kernels 🗱	14	Wilbur	4	8		•
	15	Wilbur	5	5	•	•
	16	Wilbur	5	8	•	•
- Daws						

Figure 1.8 JMP Data Table of Design Runs Generated by Custom Designer

#### Step 6: Gather and Enter the Data

Pop the popcorn according to the design JMP provided. Then, count the number of popped and unpopped kernels left in each bag. Finally, enter the numbers shown below into the appropriate columns of the data table.

We have conducted this experiment for you and placed the results in the Sample Data folder installed with JMP. To see the results, open Popcorn DOE Results.jmp from the Design Experiment folder in the sample data. The data table is shown in Figure 1.9.

Popcorn DOE Resu... Number Total Custom Design Brand Time Power Popped Kernels Design Criterion D Optimal 1 Top Secret 3 30 420 scripts to Screening 2 Top Secret 3 420 120 ▼ Model 3 Top Secret 3 10 120 400 analyze data Constraint 4 Top Secret 4 8 250 430 ▼ DOE Dialog 5 5 370 5 Top Secret 420 6 Top Secret 5 5 400 420 results from 7 Top Secret 5 8 350 420 experiment 8 Top Secret 5 8 370 380 3 9 Wilbur 374 400 ▼ Columns (5/0) 10 Wilbur 3 8 340 440 🔥 Brand 🗱 3 10 20 410 11 Wilbur 🚄 Time 🗱 4 440 460 12 Wilbur 🚄 Power 🛠 400 13 Wilbur 4 340 🚄 Number Popped 🛠 5 5 🚄 Total Kernels 🗱 14 Wilbur 170 370 15 Wilbur 5 370 380 16 Wilbur 450

Figure 1.9 Results of the Popcorn DOE Experiment

#### **Step 7: Analyze the Results**

After the experiment is finished and the number of popped kernels and total kernels have been entered into the data table, it is time to analyze the data. The design data table has a script, labeled **Model**, that shows in the top left panel of the table. When you created the design, a standard least squares analysis was stored in the **Model** script with the data table.

1. Click the red triangle for **Model** and select **Run Script**.

The default fitting personality in the model dialog is **Standard Least Squares**. One assumption of standard least squares is that your responses are normally distributed. But because you are modeling the proportion of popped kernels it is more appropriate to assume that your responses come from a binomial distribution. You can use this assumption by changing to a generalized linear model.

2. Change the Personality to **Generalized Linear Model**, Distribution to **Binomial**, and Link Function to **Logit**, as shown in Figure 1.10.





Figure 1.10 Fitting the Model

#### 3. Click Run.

4. Scroll down to view the Effect Tests table (Figure 1.11) and look in the column labeled Prob>Chisq. This column lists *p*-values. A low *p*-value (a value less than 0.05) indicates that results are statistically significant. There are asterisks that identify the low *p*-values. You can therefore conclude that, in this experiment, all the model effects except for Time\*Time are highly significant. You have confirmed that there is a strong relationship between popping time (Time), microwave setting (Power), popcorn brand (Brand), and the proportion of popped kernels.


Figure 1.11 Investigating p-Values




To further investigate, use the Prediction Profiler to see how changes in the factor settings affect the numbers of popped and unpopped kernels:


1. Choose **Profilers > Profiler** from the red triangle menu on the Generalized Linear Model Fit title bar. The Prediction Profiler is shown at the bottom of the report. Figure 1.12 shows the Prediction Profiler for the popcorn experiment. Prediction traces are displayed for each factor.

Figure 1.12 The Prediction Profiler



2. Move the vertical red dotted lines to see the effect that changing a factor value has on the response. For example, drag the red line in the Time graph to the right and left (Figure 1.13).





As Time increases and decreases, the curved Brand and Power prediction traces shift their slope and maximum/minimum values. The substantial slope shift tells you there is an interaction (synergistic effect) between Time and Brand and Time and Power.

Furthermore, the steepness of a prediction trace reveals a factor's importance. Because the prediction trace for Time is steeper than that for Brand or Power for the values shown in Figure 1.13, you can predict that cooking time is more important than the brand of popcorn or the microwave power setting.


Now for the final steps.

- 3. Click the red triangle icon in the Prediction Profiler title bar and select **Desirability Functions**.
- 4. Click the red triangle icon in the Prediction Profiler title bar and select **Maximize Desirability**. JMP automatically adjusts the graph to display the optimal settings at which the most kernels will be popped (Figure 1.14).

Our experiment found how to cook the bag of popcorn with the greatest proportion of popped kernels: use Top Secret, cook for five minutes, and use a power level of 8. The experiment predicts that cooking at these settings will yield greater than 96.5% popped kernels.

My First Experiment

Figure 1.14 The Most Desirable Settings



The best settings are the Top Secret brand, cooking time at 5, and power set at 8.

# Introduction to Designing Experiments My First Experiment

14

Chapter 1

## **Examples Using the Custom Designer**

The use of statistical methods in industry is increasing. Arguably, the most cost-beneficial of these methods for quality and productivity improvement is statistical design of experiments. A trial-and -error search for the *vital few* factors that most affect quality is costly and time-consuming. The purpose of *experimental design* is to characterize, predict, and then improve the behavior of any system or process. Designed experiments are a cost-effective way to accomplish these goals.

JMP's custom designer is the recommended way to describe your process and create a design that works for your situation. To use the custom designer, you first enter the process variables and constraints, then JMP tailors a design to suit your unique case. This approach is more general and requires less experience and expertise than previous tools supporting the statistical design of experiments.

Custom designs accommodate any number of factors of any type. You can also control the number of experimental runs. This makes custom design more flexible and more cost effective than alternative approaches.

This chapter presents several examples showing the use of custom designs. It shows how to drive its interface to build a design using this easy step-by-step approach:

Key engineering steps: process knowledge and engineering judgement are important. Collect Fit **Predict Describe** Design Identify factors Compute design Use design to set Compute best fit Use model to find and responses. for maximum factors: measure of mathematical best factor settings information from response for each model to data for on-target from test runs. responses and runs. run. minimum variability. Key mathematical steps: appropriate computer-based tools are empowering.

Figure 2.1 Approach to Experimental Design

# **Contents**

Creating Screening Experiments
Creating a Main-Effects-Only Screening Design
Creating a Screening Design to Fit All Two-Factor Interactions
A Compromise Design Between Main Effects Only and All Interactions21
Creating 'Super' Screening Designs
Screening Designs with Flexible Block Sizes
Checking for Curvature Using One Extra Run
Creating Response Surface Experiments
Exploring the Prediction Variance Surface
Introducing I-Optimal Designs for Response Surface Modeling37
A Three-Factor Response Surface Design38
Response Surface with a Blocking Factor. 40
Creating Mixture Experiments
Mixtures Having Nonmixture Factors
Experiments that are Mixtures of Mixtures
Special-Purpose Uses of the Custom Designer
Designing Experiments with Fixed Covariate Factors
Creating a Design with Two Hard-to-Change Factors: Split Plot55
Technical Discussion 60

#### **Creating Screening Experiments**

You can use the screening designer in JMP to create screening designs, but the custom designer is more flexible and general. The straightforward screening examples described below show that 'custom' does not mean 'exotic.' The custom designer is a general purpose design environment that can create screening designs.


#### **Creating a Main-Effects-Only Screening Design**

To create a main-effects-only screening design using the custom designer:

- 1. Select **DOE** > **Custom Design**.
- 2. Enter six continuous factors into the Factors panel (see "Step 1: Design the Experiment," p. 3, for details). Figure 2.2 shows the six factors.
- 3. Click **Continue**. The default model contains only the main effects.
- 4. Using the default of eight runs, click **Make Design**. Click the disclosure button ( and on Windows and on the Macintosh) to open the **Design Evaluation** outline node.

**Note to DOE experts:** The result is a resolution-three screening design. All the main effects are estimable, but they are confounded with two factor interactions.

Figure 2.2 A Main-Effects-Only Screening Design



5. Click the disclosure buttons beside Design Evaluation and then beside Alias Matrix ( on Windows and on the Macintosh) to open the Alias Matrix. Figure 2.3 shows the Alias Matrix, which is a table of zeros, ones, and negative ones.

The Alias Matrix shows how the coefficients of the constant and main effect terms in the model are biased by any active two-factor interaction effects not already added to the model. The column labels identify interactions. For example, the columns labeled X2\*X6 and X3\*X4 in the table have a 1 and -1 in the row for X1. This means that the expected value of the main effect of X1 is actually the sum of the main effect of X1 and X2\*X6, minus the effect of X3\*X4. You are assuming that these interactions are negligible in size compared to the effect of X1.

Figure 2.3 The Alias Matrix

Alias Matrix															
Effect	X1*X2	X1'X3	X1*X4	X1*X5	X1*X6	X2*X3	X2*X4	X2*X5	X2*X6	X3*X4	X3*X5	X3*X6	X4*X5	X4*X6	X5*X6
ntercept	0	0	0	0	0	0	0	0	0_	0	0	0	0	0	0
X1	0	0	0	0	0	0	0	0	(1	-1)	0	0	0	0	0
X2	0	0	0	0	1	0	0	0	0	0	-1	0	0	0	0
Х3	0	0	-1	0	0	0	0	-1	0	0	0	0	0	0	0
X4	0	-1	0	0	0	0	0	0	0	0	0	0	0	0	1
X5	0	0	0	0	0	-1	0	0	0	0	0	0	0	1	0
X6	1	0	0	0	0	0	0	0	0	0	0	0	1	0	(

**Note to DOE experts:** The Alias matrix is a generalization of the confounding pattern in fractional factorial designs.

#### Creating a Screening Design to Fit All Two-Factor Interactions


There is risk involved in designs for main effects only. The risk is that two-factor interactions, if they are strong, can confuse the results of such experiments. To avoid this risk, you can create experiments resolving all the two-factor interactions.

**Note to DOE experts:** The result in this example is a resolution-five screening design. Two-factor interactions are estimable but are confounded with three-factor interactions.

- 1. Select DOE > Custom Design.
- 2. Enter five continuous factors into the Factors panel (see "Step 1: Design the Experiment," p. 3 in the "Introduction to Designing Experiments" chapter for details).
- 3. Click Continue.
- 4. In the Model panel, select Interactions > 2nd.
- 5. In the Design Generation Panel choose Minimum for Number of Runs and click Make Design.

Figure 2.4 shows the runs of the two-factor design with all interactions. The sample size, 16 (a power of two) is large enough to fit all the terms in the model. The values in your table may be different from those shown below.

Figure 2.4 All Two-Factor Interactions



6. Click the disclosure button ( and on Windows and on the Macintosh) and to open the Design Evaluation outlines, then open Alias Matrix. Figure 2.5 shows the alias matrix table of zeros and ones. The columns labels identify an interaction. For example, the column labelled X1\*X2 refers to the interaction of the first and second effect, the column labelled X2\*X3 refers to the interaction between the second and third effect, and so forth.

Look at the column labelled X1\*X2. There is only one value of 1 in that column. All others are 0. The 1 occurs in the row labelled X1\*X2. All the other rows and columns are similar. This means that the expected value of the two-factor interaction X1\*X2 is not biased by any other terms. All the rows above the row labelled X1\*X2 contain only zeros, which means that the Intercept and main effect terms are not biased by any two-factor interactions.

Effect	X1'X2	X1'X3	X1*X4	X1'X5	X2*X3	X2*X4	X2*X5	X3*X4	X3'X5	X4*X5
ntercept	0	0	0	0	0	0	0	0	0	0
X1	0	0	0	0	0	0	0	0	0	0
X2	0	0	0	0	0	0	0	0	0	0
Х3	0	0	0	0	0	0	0	0	0	0
X4	0	0	0	0	0	0	0	0	0	0
X5	4	0	0	0	0	0	0	0	0	0
X1*X2	(1)	) 0	0	0	0	0	0	0	0	(
X1*X3	Ú	1	0	0	0	0	0	0	0	(
X1*X4	0	0	1	0	0	0	0	0	0	(
X1*X5	0	0	0	1	0	0	0	0	0	(
X2*X3	0	0	0	0	1	0	0	0	0	(
X2*X4	0	0	0	0	0	1	0	0	0	(
X2*X5	0	0	0	0	0	0	1	0	0	- 1
X3*X4	0	0	0	0	0	0	0	1	0	- (
X3*X5	0	0	0	0	0	0	0	0	1	- (
X4*X5	0	0	0	0	0	0	0	0	0	

Figure 2.5 Alias Matrix Showing all Two-Factor Interactions Clear of all Main Effects


## A Compromise Design Between Main Effects Only and All Interactions

In a screening situation, suppose there are six continuous factors and resources for n = 16 runs. The first example in this section showed an eight-run design that fit all the main effects. With six factors, there are 15 possible two-factor interactions. The minimum number of runs that could fit the constant, six main effects and 15 two-factor interactions is 22. This is more than the resource budget of 16 runs. It would be good to find a compromise between the main-effects only design and a design capable of fitting all the two-factor interactions.

This example shows how to obtain such a design compromise using the custom designer.

- 1. Select **DOE > Custom Design**.
- 2. Define six continuous factors (X1 X6).
- 3. Click **Continue**. The model includes the main effect terms by default. The default estimability of these terms is **Necessary**.
- 4. Click the **Interactions** button and choose **2nd** to add all the two-factor interactions.
- Select all the interaction terms and click the current estimability (Necessary) to reveal a menu. Change Necessary to If Possible, as shown in Figure 2.6.

Figure 2.6 Model for Six-Variable Design with Two-Factor Interactions Designated If Possible



- 6. Type 16 in the User Specified edit box in the Number of Runs section, as shown. Although the desired number of runs (16) is less than the total number of model terms, the custom designer builds a design to estimate as many two-factor interactions as possible.
- Click Make Design.

After the custom designer creates the design, click the disclosure button beside Design Evaluation to open the Alias Matrix (Figure 2.7). The values in your table may be different from those shown below, but with a similar pattern.

Effect	X1'X2	X1'X3	X1*X4	X1'X5	X1'X6	X2'X3	X2*X4	X2*X5	X2*X6	X3*X4	X3*X5	X3*X6	X4*X5	X4*X6	X5*X6
Intercept	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
X1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
X2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Х3	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
X4	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
X5	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
X6	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
X1*X2	0.333	0	0	0	0	0	0	0	0	0	0.333	0	0	0	(
X1*X3	0	0.25	0	0	0	0	0	0.25	0	0	0	0	0	0.25	0
X1*X4	0	0	0.333	0	0	0	0	0	0	0	0	0.333	0	0	0
X1*X5	0	0	0	0.333	0	0.333	0	0	0	0	0	0	0	0	0
X1*X6	0	0	0	0	0.333	0	0	0	0	0.333	0	0	0	0	0
X2*X3	0	0	0	0.333	0	0.333	0	0	0	0	0	0	0	0	0
X2*X4	0	0	0	0	0	0	0.333	0	0	0	0	0	0	0	0.333
X2*X5	0	0.25	0	0	0	0	0	0.25	0	0	0	0	0	0.25	0
X2*X6	0	0	0	0	0	0	0	0	0.333	0	0	0	0.333	0	0
X3*X4	0	0	0	0	0.333	0	0	0	0	0.333	0	0	0	0	0
X3*X5	0.333	0	0	0	0	0	0	0	0	0	0.333	0	0	0	0
X3*X6	0	0	0.333	0	0	0	0	0	0	0	0	0.333	0	0	0
X4*X5	0	0	0	0	0	0	0	0	0.333	0	0	0	0.333	0	0
X4*X6	0	0.25	0	0	0	0	0	0.25	0	0	0	0	0	0.25	0
X5*X6	0	0	0	0	0	0	0.333	0	0	0	0	0	0	0	0.333

Figure 2.7 Alias Matrix

All the rows above the row labelled X1\*X2 contain only zeros, which means that the Intercept and main effect terms are not biased by any two-factor interactions. The row labelled X1\*X2 has the value 0.333 in the X1\*X2 column and the same value in the X3\*X5 column. That means the expected value of the estimate for X1\*X2 is actually the sum of X1\*X2 and any real effect due to X3\*X5.

**Note to DOE experts:** The result in this particular example is a resolution-four screening design. Two-factor interactions are estimable but are aliased with other two-factor interactions.

# Creating 'Super' Screening Designs

This section shows how to use the technique shown in the previous example to create 'super' (supersaturated) screening designs. Supersaturated designs have fewer runs than factors, which makes them attractive for factor screening when there are many factors and experimental runs are expensive.

In a saturated design, the number of runs equals the number of model terms. In a supersaturated design, as the name suggests, the number of model terms exceeds the number of runs (Lin, 1993). A supersaturated design can examine dozens of factors using fewer than half as many runs as factors.

### The Need for Supersaturated Designs

The  $2^{7-4}$  and the  $2^{15-11}$  fractional factorial designs available using the screening designer are both saturated with respect to a main effects model. In the analysis of a saturated design, you can (barely) fit the model, but there are no degrees of freedom for error or for lack of fit. Until recently, saturated designs represented the limit of efficiency in designs for screening.

Creating Screening Experiments

Factor screening relies on the *sparsity* principle. The experimenter expects that only a few of the factors in a screening experiment are active. The problem is not knowing which are the vital few factors and which are the trivial many. It is common for brainstorming sessions to turn up dozens of factors. Yet, in practice, screening experiments rarely involve more than ten factors. What happens to winnow the list from dozens to ten or so?

If the experimenter is limited to designs that have more runs than factors, then dozens of factors translate into dozens of runs. Often, this is not economically feasible. The result is that the factor list is reduced without the benefit of data. In a supersaturated design, the number of model terms exceeds the number of runs, and you can examine dozens of factors using less than half as many runs.

#### There are drawbacks:

- If the number of *active* factors approaches the number of runs in the experiment, then it is likely that these factors will be impossible to identify. A rule of thumb is that the number of runs should be at least four times larger than the number of active factors. If you expect that there might be as many as five active factors, you should have at least 20 runs.
- Analysis of supersaturated designs cannot yet be reduced to an automatic procedure. However, using
  forward stepwise regression is reasonable and the Screening platform (Analyze > Modeling >
  Screening) offers a more streamlined analysis.

### Example: Twelve Factors in Eight Runs

As an example, consider a supersaturated design with twelve factors. Using model terms designated If Possible provides the software machinery for creating a supersaturated design.

In the last example, two-factor interaction terms were specified If Possible. In a supersaturated design, all terms—including main effects—are If Possible. Note in Figure 2.8, the only primary term is the intercept.

To see an example of a supersaturated design with twelve factors in eight runs:

- Select DOE > Custom Design.
- 2. Add 12 continuous factors and click **Continue**.
- 3. Highlight all terms except the Intercept and click the current estimability (Necessary) to reveal the menu. Change Necessary to If Possible, as shown in Figure 2.8.

⊿ Model Main Effects Interactions ▼ Cross Powers ▼ Remove Term Name Estimability Intercept Necessary If Possible If Possible Necessary lf I If I If Possible If I If Possible If Possible If Possible If Possible If Possible If Possible **▶** Alias Terms ■ Design Generation Group runs into random blocks of size: Number of Runs: Minimum Default 16 User Specified 16

Figure 2.8 Changing the Estimability

Make Design

Apply

- 4. The desired number of runs is eight so type 8 in the User Specified edit box in the Number of Runs section.
- 5. Click the red triangle on the Custom Design title bar and select **Simulate Responses**.
- 6. Click Make Design, then click Make Table. A window named Simulate Responses and a design table appear, similar to the one in Figure 2.9. The Y column values are controlled by the coefficients of the model in the Simulate Responses window. The values in your table may be different from those shown below.

■ Custom Design Desig A Simulate Responses Criteri -1 -1 -1 -1 52.21 Effects Scr 2 46.69 Intercept **▼**Moc 27.91 -1 X1 3 ▼D0 4 21.28 5.95 ХЗ -1 -1 **▼**Col 49 47 6 -1 -1 -1 -1 -1 ▲ X1 X5 7 -1 36.74 **⊿** X2 X6 -8 22.96 Х7 0 X8 -6 Х9 X10 -8 X11 X12 Error Std.

Figure 2.9 Simulated Responses and Design Table


Creating Screening Experiments

26

7. Change the default settings of the coefficients in the Simulate Responses dialog to match those in Figure 2.10 and click Apply. The numbers in the Y column change. Because you have set X2 and X10 as active factors in the simulation, the analysis should be able to identify the same two factors.

Note that random noise is added to the Y column formula, so the numbers you see might not necessarily match those in the figure. The values in your table may be different from those shown below.

Figure 2.10 Give Values to Two Main Effects and Specify the Standard Error as 0.5



To identify active factors using stepwise regression:

- 1. To run the Model script in the design table, click the red triangle beside Model and select Run Script.
- Change the Personality in the Model Specification window from Standard Least Squares to Stepwise.
- 3. Click **Run** on the Fit Model dialog.
- 4. In the resulting display click the **Step** button two times. JMP enters the factors with the largest effects. From the report that appears, you should identify two active factors, X2 and X10, as shown in Figure 2.11. The step history appears in the bottom part of the report. Because random noise is added, your estimates will be slightly different from those shown below.




Figure 2.11 Stepwise Regression Identifies Active Factors

**Note:** This example defines two large main effects and sets the rest to zero. In real-world situations, it may be less likely to have such clearly differentiated effects.


## Screening Designs with Flexible Block Sizes

When you create a design using the Screening designer (**DOE** > **Screening**), the available block sizes for the listed designs are a power of two. However, custom designs in JMP can have blocks of any size. The blocking example shown in this section is flexible because it is using three runs per block, instead of a power of two.

After you select **DOE** > **Custom Design** and enter factors, the blocking factor shows only one level in the Values section of the Factors panel because the sample size is unknown at this point. After you complete the design, JMP shows the appropriate number of blocks, which is calculated as the sample size divided by the number of runs per block.


For example, Figure 2.12 shows that when you enter three continuous factors and one blocking factor with three runs per block, only one block appears in the Factors panel.

Figure 2.12 One Block Appears in the Factors Panel




The default sample size of nine requires three blocks. After you click **Continue**, there are three blocks in the Factors panel (Figure 2.13). This is because the default sample size is nine, which requires three blocks with three runs each.

Figure 2.13 Three Blocks in the Factors Panel




If you enter 24 runs in the User Specified box of the **Number of Runs** section, the Factors panel changes and now contains 8 blocks (Figure 2.14).





If you add all the two-factor interactions and change the number of runs to 15, three runs per block produces five blocks (as shown in Figure 2.15), so the Factors panel displays five blocks in the Values section.

Figure 2.15 Changing the Runs to 15



Click **Make Design**, then click the disclosure button ( on Windows and on the Macintosh) to open the Design Evaluation outline node. Then, click the disclosure button to open the Relative Variance of Coefficients report. Figure 2.16 shows the variance of each coefficient in the model relative to the unknown error variance.

The values in your table may be slightly different from those shown below. Notice that the variance of each coefficient is about one-tenth the error variance and that all the variances are roughly the same size. The error variance is assumed to be 1.

Significance Level Signal to Noise Ratio Effect Variance Power Intercept 0.07 0.802 X1 0.078 0.763 X2 0.106 0.638 Х3 0.083 0.736 X4 1 0.082 0.744 X4 2 0.081 0.75 X43 0.082 0.744 X4 4 0.106

0.083 0.736

0.079 0.757

0.078 0.763

X1\*X2

X1\*X3

X2\*X3

Figure 2.16 Table of Relative Variance of the Model Coefficients

The main question here is whether the relative size of the coefficient variance is acceptably small. If not, adding more runs (18 or more) will lower the variance of each coefficient.

For more details, see "The Relative Variance of Coefficients and Power Table," p. 75.

**Note to DOE experts:** There are four rows associated with X4 (the block factor). That is because X4 has 5 blocks and, therefore, 4 degrees of freedom. Each degree of freedom is associated with one unknown coefficient in the model.

## **Checking for Curvature Using One Extra Run**


In screening designs, experimenters often add center points and other check points to a design to help determine whether the assumed model is adequate. Although this is good practice, it is also *ad hoc*. The custom designer provides a way to improve on this *ad hoc* practice while supplying a theoretical foundation and an easy-to-use interface for choosing a design robust to the modeling assumptions.

The purpose of check points in a design is to provide a detection mechanism for higher-order effects that are contained in the assumed model. These higher-order terms are called *potential terms*. (Let *q* denote the potential terms, designated If Possible in JMP.) The assumed model consists of the *primary terms*. (Let *p* denote the primary terms designated Necessary in JMP.)

To take advantage of the benefits of the approach using If Possible model terms, the sample size should be larger than the number of Necessary (primary) terms but smaller than the sum of the Necessary and If Possible (potential) terms. That is, p < n < p+q. The formal name of the approach using If Possible model terms is *Bayesian D-Optimal design*. This type of design allows the precise estimation of all of the Necessary terms while providing omnibus detectability (and some estimability) for the If Possible terms.

For a two-factor design having a model with an intercept, two main effects, and an interaction, there are p = 4 primary terms. When you enter this model in the custom designer, the default minimum runs value is a four-run design with the factor settings shown in Figure 2.17.

Figure 2.17 Two Continuous Factors with Interaction




Now suppose you can afford an extra run (n = 5). You would like to use this point as a check point for curvature. If you leave the model the same and increase the sample size, the custom designer replicates one of the four vertices. Replicating any run is the optimal choice for improving the estimates of the terms in the model, but it provides no way to check for lack of fit.

Adding the two quadratic terms to the model makes a total of six terms. This is a way to model curvature directly. However, to do this the custom designer requires two additional runs (at a minimum), which exceeds your budget of five runs.

The Bayesian *D*-Optimal design provides a way to check for curvature while adding only one extra run. To create this design:


- 1. Select **DOE** > **Custom Design**.
- 2. Define two continuous factors (X1 and X2).
- 3. Click Continue.
- 4. Choose **2nd** from the **Interactions** menu in the Model panel. The results appear as shown in Figure 2.18.

Figure 2.18 Second-Level Interactions



- 5. Choose **2nd** from the **Powers** button in the Model panel. This adds two quadratic terms.
- 6. Select the two quadratic terms (X1\*X1 and X2\*X2) and click the current estimability (**Necessary**) to see the menu and change **Necessary** to **If Possible**, as shown in Figure 2.19.


Figure 2.19 Changing the Estimability



Now, the p = 4 primary terms (the intercept, two main effects, and the interaction) are designated as Necessary while the q = 2 potential terms (the two quadratic terms) are designated as If Possible. The desired number of runs, five, is between p = 4 and p + q = 6.


- 7. Enter 5 into the User Specified edit box in the Number of Runs section of the Design Generation panel.
- 8. Click **Make Design**. The resulting factor settings appear in Figure 2.20. The values in your design may be different from those shown below.

Figure 2.20 Five-Run Bayesian D-Optimal Design



- 9. Click Make Table to create a JMP data table of the runs.
- 10. Create the overlay plot in Figure 2.21 with **Graph > Overlay Plot**, and assign X1 as Y and X2 as X. The overlay plot illustrates how the design incorporates the single extra run. In this example the design places the factor settings at the center of the design instead of at one of the corners.

Figure 2.21 Overlay Plot of Five-run Bayesian D-Optimal Design



# **Creating Response Surface Experiments**

Response surface experiments traditionally involve a small number (generally 2 to 8) of continuous factors. The *a priori* model for a response surface experiment is usually quadratic.

In contrast to screening experiments, researchers use response surface experiments when they already know which factors are important. The main goal of response surface experiments is to create a predictive model of the relationship between the factors and the response. Using this predictive model allows the experimenter to find better operating settings for the process.


In screening experiments one measure of the quality of the design is the size of the relative variance of the coefficients. In response surface experiments, the prediction variance over the range of the factors is more important than the variance of the coefficients. One way to visualize the prediction variance is JMP's prediction variance profile plot. This plot is a powerful diagnostic tool for evaluating and comparing response surface designs.

## **Exploring the Prediction Variance Surface**

The purpose of the example below is to generate and interpret a simple Prediction Variance Profile Plot. Follow the steps below to create a design for a quadratic model with a single continuous factor.


- 1. Select **DOE** > **Custom Design**.
- 2. Add one continuous factor by selecting Add Factor > Continuous (Figure 2.22), and click Continue.
- 3. In the Model panel, select **Powers > 2nd** to create a quadratic term (Figure 2.22).

Figure 2.22 Adding a Factor and a Quadratic Term



4. In the Design Generation panel, use the default number of runs (six) and click **Make Design** (Figure 2.23). The number of runs is inversely proportional to the size of variance of the predicted response. As the number of runs increases, the prediction variances decrease.

Figure 2.23 Using the Default Number of Runs




5. Click the disclosure button ( and on Windows and von the Macintosh) to open the **Design** Evaluation outline node, and then the **Prediction Variance Profile**, as shown in Figure 2.24.

For continuous factors, the initial setting is at the mid-range of the factor values. For categorical factors, the initial setting is the first level. If the design model is quadratic, then the prediction variance function is quartic. The *y*-axis is the relative variance of prediction of the expected value of the response.

In this design, the three design points are -1, 0, and 1. The prediction variance profile shows that the variance is a maximum at each of these points on the interval -1 to 1.

Figure 2.24 Prediction Profile for Single Factor Quadratic Model




The prediction variance is relative to the error variance. When the relative prediction variance is one, the absolute variance is equal to the error variance of the regression model. More detail on the Prediction Variance Profiler is in "Understanding Design Evaluation," p. 72.

- 6. To compare profile plots, click the **Back** button and choose **Minimum** in the Design Generation panel, which gives a sample size of three.
- 7. Click Make Design and then open the Prediction Variance Profile again.

Now you see a curve that has the same shape as the previous plot, but the maxima are at one instead of 0.5. Figure 2.25 compares plots for a sample size of six and sample size of three for this quadratic model. You can see the prediction variance increase as the sample size decreases. Since the prediction variance is inversely proportional to the sample size, doubling the number of runs halves the prediction variance. These profiles show settings for the maximum variance and minimum variance, for sample sizes six (top charts) and sample size three (bottom charts). The axes on the bottom plots are adjusted to match the axes on the top plot.

Figure 2.25 Comparison of Prediction Variance Profiles



**Tip:** Hold the CTRL key and click (hold the COMMAND key and click on Macintosh) on the factor to set a factor level precisely.

8. To create an unbalanced design, click the **Back** button and enter a sample size of 7 in the User Specified text edit box in the Design Generation panel, then click **Make Design**. The results are shown in Figure 2.26.

You can see that the variance of prediction at -1 is lower than the other sample points (its value is 0.33 instead of 0.5). The symmetry of the plot is related to the balance of the factor settings. When the design is balanced, the plot is symmetric, as shown in Figure 2.25. When the design is unbalanced, the prediction plot might not be symmetric, as shown in Figure 2.26.




Figure 2.26 Sample Size of Seven for the One-Factor Quadratic Model

## Introducing I-Optimal Designs for Response Surface Modeling

The custom designer generates designs using a mathematical optimality criterion. All the designs in this chapter so far have been *D*-Optimal designs. *D*-Optimal designs are most appropriate for screening experiments because the optimality criterion focuses on precise estimates of the coefficients. If an experimenter has precise estimates of the factor effects, then it is easy to tell which factors' effects are important and which are negligible. However, *D*-Optimal designs are not as appropriate for designing experiments where the primary goal is prediction.


*I*-Optimal designs minimize the average prediction variance inside the region of the factors. This makes *I*-Optimal designs more appropriate for prediction. As a result *I*-Optimality is the recommended criterion for JMP response surface designs.

An *I*-Optimal design tends to place fewer runs at the extremes of the design space than does a *D*-Optimal design. As an example, consider a one-factor design for a quadratic model using n = 12 experimental runs. The *D*-Optimal design for this model puts four runs at each end of the range of interest and four runs in the middle. The *I*-Optimal design puts three runs at each end point and six runs in the middle. In this case, the *D*-Optimal design places two-thirds of its runs at the extremes versus one-half for the *I*-Optimal design.

Figure 2.27 compares prediction variance profiles of the one-factor I- and D-Optimal designs for a quadratic model with (n = 12) runs. The variance function for the I-Optimal design is less than the

corresponding function for the D-Optimal design in the center of the design space; the converse is true at the edges.

Figure 2.27 Prediction Variance Profiles for 12-Run I-Optimal (left) and D-Optimal (right) Designs



At the center of the design space, the average variance (relative to the error variance) for the *I*-Optimal design is 0.1667 compared to the *D*-Optimal design, which is 0.25. This means that confidence intervals for prediction will be nearly 10% shorter on average for the *I*-Optimal design.

To compare the two design criteria, create a one-factor design with a quadratic model that uses the *I*-Optimality criterion, and another one that uses *D*-Optimality:

- 1. Select DOE > Custom Design.
- 2. Add one continuous factor: X1.
- 3. Click Continue.
- 4. Click the **RSM** button in the Model panel to make the design *I*-Optimal.
- 5. Change the number of runs to 12.
- 6. Click Make Design.
- 7. Click the disclosure button ( and on Windows and on the Macintosh) to open the **Design** Evaluation outline node.
- 8. Click the disclosure button ( and on Windows and on the Macintosh) to open the **Prediction Variance Profile**. (The Prediction Variance Profile is shown on the left in Figure 2.27.)
- 9. Repeat the same steps to create a *D*-Optimal design, but select **Optimality Criterion > Make D-Optimal Design** from the red triangle menu on the custom design title bar. The results in the Prediction Variance Profile should look the same as those on the right in Figure 2.27.

## A Three-Factor Response Surface Design

In higher dimensions, the *I*-Optimal design continues to place more emphasis on the center of the region of the factors. The *D*-Optimal and *I*-Optimal designs for fitting a full quadratic model in three factors using 16 runs are shown in Figure 2.28.

To compare the two design criteria, create a three-factor design that uses the *I*-Optimality criterion, and another one that uses *D*-Optimality:

- 1. Select DOE > Custom Design.
- 2. Add three continuous factors: X1, X2, and X3.
- Click Continue.
- 4. Click the **RSM** button in the Model panel to add interaction and quadratic terms to the model and to change the default optimality criterion to *I*-Optimal.
- 5. Use the default of 16 runs.
- 6. Click Make Design.

The design is shown in the Design panel (the left in Figure 2.28).

7. If you want to create a *D*-Optimal design for comparison, repeat the same steps but select **Optimality Criterion > Make D-Optimal Design** from the red triangle menu on the custom design title bar. The design should look similar to those on the right in Figure 2.28. The values in your design may be different from those shown below.

Figure 2.28 16-run I-Optimal and D-Optimal designs for RSM Model

⊿(I-Optima	l Design		
Run	X1	X2	Х3
1	1	0	0
2	-1	1	1
3	1	-1	1
4	1	1	-1
5	0	0	-1
6	0	0	0
7	-1	1	-1
8	0	0	1
9	0	1	0
10	-1	0	0
11	1	-1	-1
12	-1	-1	1
13	0	0	0
14	1	1	1
15	0	-1	0
16	-1	-1	-1

⊿D-Optima	al Design		
Run	X1	X2	Х3
1	1	-1	-1
2	-1	1	1
3	1	-1	1
4	1	1	-1
5	1	-1	0
6	-1	1	-1
7	1	1	1
8	0	-1	-1
9	-1	0	0
10	0	1	0
11	0	0	-1
12	1	0	1
13	-1	-1	-1
14	-1	-1	1
15	0	-1	1
16	-1	-1	0

Profile plots of the variance function are displayed in Figure 2.29. These plots show slices of the variance function as a function of each factor, with all other factors fixed at zero. The *I*-Optimal design has the lowest prediction variance at the center. Note that there are two center points in this design.

The *D*-Optimal design has no center points and its prediction variance at the center of the factor space is almost three times the variance of the *I*-Optimal design. The variance at the vertices of the *D*-Optimal design is not shown. However, note that the *D*-Optimal design predicts better than the *I*-Optimal design near the vertices.

I-Optimal RSM Design with 16 runs

1.2 0.8-0.6 0.4 0.2 0

D-Optimal RSM Design with 16 runs


## **Response Surface with a Blocking Factor**

It is not unusual for a process to depend on both qualitative and quantitative factors. For example, in the chemical industry, the yield of a process might depend not only on the quantitative factors temperature and pressure, but also on such qualitative factors as the batch of raw material and the type of reactor. Likewise, an antibiotic might be given orally or by injection, a qualitative factor with two levels. The composition and dosage of the antibiotic could be quantitative factors (Atkinson and Doney, 1992).

The response surface designer (described in "Response Surface Designs," p. 127) only deals with quantitative factors. You could use the response surface designer to produce a Response Surface Model (RSM) design with a qualitative factor by replicating the design over each level of the factor. But, this is unnecessarily time-consuming and expensive. Using custom designer is simpler and more cost-effective because fewer runs are required. The following steps show how to accommodate a blocking factor in a response surface design using the custom designer:


- 1. First, define two continuous factors (X1 and X2).
- 2. Now, click Add Factor and select Blocking > 4 runs per block to create a blocking factor(X3). The blocking factor appears with one level, as shown in Figure 2.30, but the number of levels adjusts later to accommodate the number of runs specified for the design.

Figure 2.30 Add Two Continuous Factors and a Blocking Factor




3. Click **Continue**, and then click **RSM** in the Model panel to add the quadratic terms to the model (Figure 2.31). This automatically changes the recommended optimality criterion from *D*-Optimal to *I*-Optimal. Note that when you click RSM, a message reminds you that nominal factors (such as the blocking factor) cannot have quadratic effects.

Figure 2.31 Add Response Surface Terms



4. Enter 12 in the User Specified text edit box in the Design Generation panel, and note that the Factors panel now shows the Blocking factor, X3, with three levels (Figure 2.32). Twelve runs defines three blocks with four runs per block.



- 5. Click Make Design.
- 6. In the Output Options, select Sort Right to Left from the Run Order list.
- 7. Click **Make Table** to see an *I*-Optimal table similar to the one on the left in Figure 2.33.

Figure 2.33 compares the results of a 12-run *I*-Optimal design and a 12-run *D*-Optimal Design.

To see the *D*-Optimal design:

- 1. Click the **Back** button.
- 2. Click the red triangle icon on the Custom Design title bar and select **Optimality Criterion > Make D-Optimal Design**.
- 3. Click Make Design, then click Make Table.

Figure 2.33 JMP Design Tables for 12-Run I-Optimal and D-Optimal Designs

⊿(I-Optima	l Design				nal Design		
Run	X1	X2	ХЗ	Run	X1	X2	ХЗ
1	0	0	2	1	-0.14	0	3
2	1	0	3	2	1	-1	3
3	0	0	3	3	-1	0	2
4	-1	-1	3	4	-1	1	3
5	1	-1	1	5	-1	1	1
6	-1	0	1	6	-1	-1	1
7	0	1	1	7	1	-1	2
8	1	1	2	8	0	-1	1
9	-1	1	2	9	1	0	1
10	0	1	3	10	1	1	3
11	0	0	1	11	-1	-1	2
12	0	-1	2	12	0	1	2
	0	-1	2		0	1	

Figure 2.34 gives a graphical view of the designs generated by this example. These plots were generated for the runs in each JMP table by choosing **Graph > Overlay Plot** from the main menu andusing the blocking factor (X3) as the **Grouping** variable.

Note that there is a center point in each block of the *I*-Optimal design. The *D*-Optimal design has only one center point. The values in your graph may be different from those shown in Figure 2.34.




Figure 2.34 Plots of *I*-Optimal (left) and *D*-Optimal (right) Design Points by Block.

Either of the designs in Figure 2.34 supports fitting the specified model. The *D*-Optimal design does a slightly better job of estimating the model coefficients. The diagnostics (Figure 2.35) for the designs show beneath the design tables. In this example, the *D*-efficiency of the *I*-Optimal design is about 51%, and is 55% for the D-Optimal design.

The *I*-Optimal design is preferable for predicting the response inside the design region. Using the formulas given in "Technical Discussion," p. 60, you can compute the relative average variance for these designs. The average variance (relative to the error variance) for the *I*-Optimal design is 0.5 compared to 0.59 for the *D*-Optimal design (See Figure 2.35). This means confidence intervals for prediction will be almost 20% longer on average for *D*-Optimal designs.

Figure 2.35 Design Diagnostics for I-Optimal and D-Optimal Designs



# **Creating Mixture Experiments**

If you have factors that are ingredients in a mixture, you can use either the custom designer or the specialized mixture designer. However, the mixture designer is limited because it requires all factors to be mixture components and you might want to vary the process settings along with the percentages of the mixture ingredients. The optimal formulation could change depending on the operating environment. The custom designer can handle mixture ingredients and process variables in the same study. You are not forced to modify your problem to conform to the restrictions of a special-purpose design approach.

## **Mixtures Having Nonmixture Factors**

The following example from Atkinson and Donev (1992) shows how to create designs for experiments with mixtures where one or more factors are not ingredients in the mixture. In this example:

- The response is the electromagnetic damping of an acrylonitrile powder.
- The three mixture ingredients are copper sulphate, sodium thiosulphate, and glyoxal.
- The nonmixture environmental factor of interest is the wavelength of light.

Though wavelength is a continuous variable, the researchers were only interested in predictions at three discrete wavelengths. As a result, they treated it as a categorical factor with three levels. To create this custom design:

- 1. Select **DOE** > **Custom Design**.
- 2. Create Damping as the response. The authors do not mention how much damping is desirable, so right-click the goal and create Damping's response goal to be **None**.
- 3. In the Factors panel, add the three mixture ingredients and the categorical factor, Wavelength. The mixture ingredients have range constraints that arise from the mechanism of the chemical reaction. Rather than entering them by hand, load them from the Sample Data folder that was installed with JMP: click the red triangle icon on the Custom Design title bar and select Load Factors. Open Donev Mixture Factors.jmp, from the Design Experiment sample data folder. The custom design panels should now look like those shown in Figure 2.36.


**⊿** Responses Add Response ▼ Remove Number of Responses... Upper Limit Response Name Goal Lower Limit Importance Damping None NA NA NA **⊿** Factors Add Factor ▼ Remove Add N Factors 1 Name Role Changes Values ▲CuSO4 Mixture Easy 0.2 ■Na2S2O3 0.2 8.0 Mixture Easy Glyoxal 0.6 Mixture Easy ✓ Wavelength Categorical Easy L2 L3

Figure 2.36 Mixture Experiment Response Panel and Factors Panel

The model, shown in Figure 2.37 is a response surface model in the mixture ingredients along with the additive effect of the wavelength. To create this model:

- 1. Click **Interactions**, and choose **2nd**. A warning dialog appears telling you that JMP removes the main effect terms for non-mixture factors that interact with all the mixture factors. Click **OK**.
- 2. In the Design Generation panel, type 18 in the User Specified text edit box (Figure 2.37), which results in six runs each for the three levels of the wavelength factor.

Figure 2.37 Mixture Experiment Design Generation Panel



### 3. Click Make Design, and then click Make Table.

The resulting data table is shown in Figure 2.38. The values in your table may be different from those shown below.

▼ Custom Design Design Custom Design CuSO4 Na2S2O3 Glyoxal Wavelength Damping Criterion D Optimal 0.2 8.0 0 L1 ■ Model 2 0.5 0.2 0.3 L1 ■ DOE Dialog 3 0.2 8.0 0 L2 4 0.5 0.5 0 L1 Columns (5/0) 5 0.2 0.8 0 1 1 ∠ CuSO4 ★ 6 0.5 0.2 0.3 L2 ■ Na2S2O3 \* 7 0.2 0.5 0.3 L1 🚄 Giyoxal 🛠 8 0.2 0.5 0.3 L2 Wavelength 

★ Damping \* 9 0.5 0.5 0 L2 10 0.2 0.2 0.6 L2 ■ Rows 11 0.2 0.2 0.6 L1 All rows 18 12 0.5 0.2 0.3 L3 Selected 13 0.5 0.5 0 L3 Excluded 0 0.2 14 8.0 0 13 Hidden 0 15 0.8 0.2 0 12 Labelled 16 0.2 0.5 03 13 17 0.2 8.0 0 L3 0.2 0.2 0.6 L3


Figure 2.38 Mixture Experiment Design Table

Atkinson and Donev also discuss the design where the number of runs is limited to 10. In that case, it is not possible to run a complete mixture response surface design for every wavelength.

To view this:

- 1. Click the **Back** button.
- 2. Remove all the effects by highlighting them and clicking **Remove Term**.
- 3. Add the main effects by clicking the **Main Effects** button.
- 4. In the Design Generation panel, change the number of runs to 10 (Figure 2.39) and click **Make Design**. The Design table to the right in Figure 2.39 shows the factor settings for 10 runs.

Figure 2.39 Ten-Run Mixture Response Surface Design



esign					
Run	CuSO4	Na2S2O3	Glyoxal	Wavelength	Damping
1	0.2	0.2	0.6	L2	
2	0.2	0.8	0	L2	
3	0.2	0.2	0.6	L3	
4	0.2	0.8	0	L1	
5	0.8	0.2	0	L3	
6	0.8	0.2	0	L1	
7	0.2	0.8	0	L3	
8	0.8	0.2	0	L1	
9	0.8	0.2	0	L2	
10	0.2	0.2	0.6	L1	

Note that there are necessarily unequal numbers of runs for each wavelength. Because of this lack of balance it is a good idea to look at the prediction variance plot (top plot in Figure 2.40).

5. Open the Design Evaluation outline node, then open the Prediction Variance Profile.

The prediction variance is almost constant across the three wavelengths, which is a good indication that the lack of balance is not a problem.

The values of the first three ingredients sum to one because they are mixture ingredients. If you vary one of the values, the others adjust to keep the sum constant.

6. Select **Maximize Desirability** from red triangle menu on the Prediction Variance Profile title bar, as shown in the bottom profiler in Figure 2.40.

The most desirable wavelength is L3, with the CuSO4 percentage decreasing from about 0.4 to 0.2, Glyoxal percentage is zero, and Na2S2O3 is 0.8, which maintains the mixture.




Figure 2.40 Prediction Variance Plots for Ten-Run Design

# **Experiments that are Mixtures of Mixtures**

As a way to illustrate the idea of a 'mixture of mixtures' situation, imagine the ingredients that go into baking a cake and assume the following:

- dry ingredients composed of flour, sugar, and cocoa
- wet (or non-dry) ingredients consisting of milk, melted butter, and eggs.

These two components (wet and dry) of the cake are two mixtures that are first mixed separately and then blended together.

The dessert chef knows that the dry component (the mixture of flour, sugar, and cocoa) contributes 45% of the combined mixture and the wet component (butter, milk, and eggs) contributes 55%.

The objective of such an experiment might be to identify proportions within the two components that maximize some measure of taste or consistency.

This is a main effects model except that you must leave out one of the factors in order to avoid singularity. The choice of which factor to leave out of the model is arbitrary.

For now, consider these upper and lower levels of the various factors:

### Within the dry mixture:

- cocoa must be greater than 10% but less than 20%
- sugar must be greater than 0% but less than 15%
- flour must be greater than 20% but less than 30%

#### Within the wet mixture:

- melted butter must be greater than 10% but less than 20%
- milk must be greater than 25% and less than 35%
- eggs constitute more than 5% but less than 20%


You want to bake cakes and measure taste on a scale from 1 to 10

Use the Custom Designer to set up this example, as follows:

- 1. In the Response Panel, enter one response and call it **Taste**.
- 2. Give Taste a Lower Limit of 1 and an Upper Limit of 10. (You are assuming a taste test where the respondents reply on a scale of 1 to 10.)
- 3. In the Factors Panel, enter the six cake factors described above.
- 4. Enter the given percentage values of the factors as proportions in the Values section of the Factors panel.

The completed Response and Factors panels should look like those shown in Figure 2.41.

Figure 2.41 Completed Responses and Factors Panel for the Cake Example




- 5. Next, click Continue.
- 6. Open the Define Factor Constraints pane and click Add Constraint twice.
- 7. Enter the constraints as shown in Figure 2.42. For the second constraint setting, click on the less than or equal to button and select the greater than or equal to direction.

By confining the dry factors to exactly 45% in this way, the mixture role of all the factors ensures that the wet factors constitute the remaining 55%.

8. Open the Model dialog and note that it lists all 6 effects. Because these are mixture factors, including all effects would render the model singular. Highlight any one of the terms in the model and click **Remove Term**, as shown.

Figure 2.42 Constraints to Define the Double Mixture Experiment



- 9. To see a completed example, choose **Simulate Responses** from the menu on the Custom Design title bar.
- 10. In the Design Generation panel, enter 10 as the number of runs for the example. That is, you would bake cakes with 10 different sets of ingredient proportions.
- 11. Click Make Design in the Design Generation panel, and then click Make Table.

The table in Figure 2.43 shows that the two sets of cake ingredients (dry and wet) adhere to the proportions 45% and 55% as defined by the entered constraints. In addition, the amount of each ingredient in each cake recipe (run) conforms to the upper and lower limits given in the factors dialog.

Custom Design	4			_				
Design Custom Design	•	Cocoa	Sugar	Flour	Butter	Milk	Eggs	Taste
Criterion D Optimal	1	0.15	0	0.3	0.1	0.35	0.1	5.13
▼ Model	2	0.2	0.05	0.2	0.2	0.25	0.1	5.7
Constraint	3	0.2	0	0.25	0.2	0.25	0.1	5.95
▼ DOE Dialog	4	0.1	0.05	0.3	0.1	0.25	0.2	1.1
Columns (7/0)	5	0.2	0.05	0.2	0.1	0.35	0.1	5.64
	6	0.1	0.15	0.2	0.15	0.35	0.05	2.88
🚄 Sugar 🗱	7	0.1	0.05	0.3	0.2	0.3	0.05	3.49
flour *	8	0.1	0.15	0.2	0.2	0.25	0.1	3.62
₫ Butter 🗱	9	0.1	0.15	0.2	0.1	0.25	0.2	5.07
<b>1</b> Milk <b>≭</b>	10	0.2	0.05	0.2	0.1	0.25	0.2	7.18
₫ Eggs <b>≭</b> ₫ Taste <b>≭</b>		$\overline{/}$						
	Each rur	sums	to 0.4	5 (45%	(o)	Each	run su	ms to

Figure 2.43 Cake Experiment Conforming to a Mixture of Mixture Design

**Note**: As a word of caution, keep in mind that it is easy to define constraints in such a way that it is impossible to construct a design that fits the model. In such a case, you will get a message saying "Could not find a valid starting design. Please check your constraints for consistency."

# **Special-Purpose Uses of the Custom Designer**

While some of the designs discussed in previous sections can be created using other designers in JMP or by looking them up in a textbook containing tables of designs, the designs presented in this section cannot be created without using the custom designer.

## **Designing Experiments with Fixed Covariate Factors**

Pre-tabulated designs rely on the assumption that the experimenter controls all the factors. Sometimes you have quantitative measurements (a covariate) on the experimental units before the experiment begins. If this variable affects the experimental response, the covariate should be a design factor. The pre-defined design that allows only a few discrete values is too restrictive. The custom designer supplies a reasonable design option.

For this example, suppose there are a group of students participating in a study. A physical education researcher has proposed an experiment where you vary the number of hours of sleep and the calories for breakfast and ask each student to run 1/4 mile. The weight of the student is known and it seems important to include this information in the experimental design.

To follow along with this example that shows column properties, open Big Class.jmp from the Sample Data folder that was installed when you installed JMP.


Build the custom design as follows:

Select DOE > Custom Design.

Special-Purpose Uses of the Custom Designer

- 2. Add two continuous variables to the models by entering 2 beside Add N Factors, clicking **Add Factor** and selecting **Continuous**, naming them calories and sleep.
- 3. Click **Add Factor** and select **Covariate**, as shown in Figure 2.44. The **Covariate** selection displays a list of the variables in the current data table.

Figure 2.44 Add a Covariate Factor




4. Select weight from the variable list (Figure 2.45) and click **OK**.

Figure 2.45 Design with Fixed Covariate




- Click Continue.
- 6. Add the interaction to the model by selecting calories in the Factors panel, selecting sleep in the Model panel, and then clicking the Cross button (Figure 2.46).

Figure 2.46 Design With Fixed Covariate Factor



7. Click **Make Design**, then click **Make Table**. The data table in Figure 2.47 shows the design table. Your runs might not look the same because the order of the runs has been randomized.

Figure 2.47 Design Table for Covariate Example



**Note:** Covariate factors cannot have missing values.


Remember that weight is the covariate factor, measured for each student, but it is not controlled. The custom designer has calculated settings for calories and sleep for each student. It would be desirable if the correlations between calories, sleep and weight were as small as possible. You can see how well the custom designer did by fitting a model of weight as a function of calories and sleep. If that fit has a small model sum of squares, that means the custom designer has successfully separated the effect of weight from the effects of calories and sleep.

Special-Purpose Uses of the Custom Designer

8. Click the red triangle icon beside Model in the data table and select Run Script, as shown on the left in Figure 2.48.

Figure 2.48 Model Script


54



9. Rearrange the dialog so weight is Y and calories, sleep, and calories\*sleep are the model effects, as shown to the right in Figure 2.48. Click Run.

The leverage plots are nearly horizontal, and the analysis of variance table shows that the model sum of squares is near zero compared to the residuals (Figure 2.49). Therefore, weight is independent of calories and sleep. The values in your analysis may be a little different from those shown below.

Figure 2.49 Analysis to Check That Weight is Independent of Calories and Sleep



## Creating a Design with Two Hard-to-Change Factors: Split Plot

While there is substantial research literature covering the analysis of split plot designs, it has only been possible in the last few years to create optimal split plot designs (Goos 2002). The split plot design capability accessible in the JMP custom designer is the first commercially available tool for generating optimal split plot designs.

The split plot design originated in agriculture, but is commonplace in manufacturing and engineering studies. In split plot experiments, hard-to-change factors only change between one whole plot and the next. The whole plot is divided into subplots, and the levels of the easy-to-change factors are randomly assigned to each subplot.


The example in this section is adapted from Kowalski, Cornell, and Vining (2002). The experiment studies the effect of five factors on the thickness of vinyl used to make automobile seat covers. The response and factors in the experiment are described below:

- Three of the factors are ingredients in a mixture. They are plasticizers whose proportions, m1, m2, and m3, sum to one. Additionally, the mixture components are the subplot factors of the experiment.
- Two of the factors are process variables. They are the rate of extrusion (extrusion rate) and the temperature (temperature) of drying. These process variables are the whole plot factors of the experiment. They are hard to change.
- The response in the experiment is the thickness of the vinyl used for automobile seat covers. The response of interest (thickness) depends both on the proportions of the mixtures and on the effects of the process variables.

To create this design in JMP:

- 1. Select **DOE** > **Custom Design**.
- 2. By default, there is one response, Y, showing. Double-click the name and change it to thickness. Use the default goal, **Maximize** (Figure 2.50).
- 3. Enter the lower limit of 10.
- 4. To add three mixture factors, type 3 in the box beside Add N Factors, and click Add Factor > Mixture.
- 5. Name the three mixture factors m1, m2, and m3. Use the default levels 0 and 1 for those three factors.
- 6. Add two continuous factors by typing 2 in the box beside Add N Factors, and click Add Factor > Continuous. Name these factors extrusion rate and temperature.
- 7. Ensure that you are using the default levels, -1 and 1, in the Values area corresponding to these two factors.
- 8. To make extrusion rate a whole plot factor, click **Easy** and select **Hard**.
- 9. To make temperature a whole plot factor, click **Easy** and select **Hard**. Your dialog should look like the one in Figure 2.50.


Figure 2.50 Entering Responses and Factors



#### 10. Click Continue.


11. Next, add interaction terms to the model by selecting **Interactions > 2nd** (Figure 2.51). This causes a warning that JMP removes the main effect terms for non-mixture factors that interact with all the mixture factors. Click **OK**.

Figure 2.51 Adding Interaction Terms



- 12. In the Design Generation panel, type 7 in the Number of Whole Plots text edit box.
- 13. For Number of Runs, type 28 in the User Specified text edit box (Figure 2.52).


Figure 2.52 Assigning the Number of Whole Plots and Number of Runs



**Note:** If you enter a missing value in the Number of Whole Plots edit box, then JMP considers many different numbers of whole plots and chooses the number that maximizes the information about the coefficients in the model. It maximizes the determinant of  $\mathbf{X}'\mathbf{V}^{-1}\mathbf{X}$  where  $\mathbf{V}^{-1}$  is the inverse of the variance matrix of the responses. The matrix,  $\mathbf{V}$ , is a function of how many whole plots there are, so changing the number of whole plots changes  $\mathbf{V}$ , which can make a difference in the amount of information a design contains.

14. Click **Make Design**. The result is shown in Figure 2.53.

Figure 2.53 Partial Listing of the Final Design Structure



#### 15. Click Make Table.

16. From the Sample Data folder that was installed with JMP, open Vinyl Data.jmp from the Design Experiment folder, which contains 28 runs as well as response values. The values in the table you generated with the custom designer may be different from those from the Sample Data folder, shown in Figure 2.54.

Figure 2.54 The Vinyl Data Design Table


▼Vinyl Data ▷	4 €							
Design Custom Design	•	Whole Plots	m1	m2	m3	extrusion rate	temperature	thickness
Criterion D Optimal	1	1	0	1	0	-1	-1	4
▼ Model	2	1	1	0	0	-1	-1	10
Columns (7/0)	3	1	0	0	1	-1	-1	3
Whole Plots ★	4	1	0.5	0	0.5	-1	-1	9
m1 ★	5	2	0.5	0.5	0	-1	1	8
m2 <b>*</b>	6	2	0	1	0	-1	1	5
	7	2	1	0	0	-1	1	6
extrusion rate *	8	2	0	0	1	-1	1	2
	9	3	0	1	0	1	-1	7
	10	3	0	0.5	0.5	1	-1	9
▼Rows	11	3	0	0	1	1	-1	14
All rows 28	12	3	1	0	0	1	-1	12
Selected 0	13	4	0	1	0	1	1	5
Excluded 0	14	4	0	0	1	1	1	2
Hidden 0	15	4	1	0	0	1	1	6
Labelled 0	16	4	0.5	0	0.5	1	1	7

17. Click the red triangle icon next to the Model script and select **Run Script**. The dialog in Figure 2.55 appears.

The models for split plots have a random effect associated with the whole plots' effect.

As shown in the dialog in Figure 2.55, JMP designates the error term by appending &Random to the name of the effect. REML will be used for the analysis, as indicated in the menu beside Method in Figure 2.55. For more information about REML models, see *Modeling and Multivariate Methods*.






18. Click **Run** to run the analysis. The results are shown in Figure 2.56.

Technical Discussion

Figure 2.56 Split Plot Analysis Results



# **Technical Discussion**

This section provides information about *I-*, *D-*, Bayesian *I-*, Bayesian *D-*, and Alias-Optimal designs.

#### D-Optimality:

- is the default design type produced by the custom designer except when the RSM button has been clicked to create a full quadratic model.
- minimizes the variance of the model coefficient estimates. This is appropriate for first-order models and in screening situations, because the experimental goal in such situations is often to identify the active factors; parameter estimation is key.
- is dependent on a pre-stated model. This is a limitation because in most real situations, the form of the pre-stated model is not known in advance.
- has runs whose purpose is to lower the variability of the coefficients of this pre-stated model. By focusing on minimizing the standard errors of coefficients, a *D*-Optimal design may not allow for checking that the model is correct. It will not include center points when investigating a first-order model. In the extreme, a *D*-Optimal design may have just *p* distinct runs with no degrees of freedom for lack of fit.

Chapter 2

maximizes D when

$$D = \det[\mathbf{X}'\mathbf{X}]$$

D-optimal split plot designs maximize D when

$$D = \det[\mathbf{X}'\mathbf{V}^{-1}\mathbf{X}]$$

where V<sup>-1</sup> is the block diagonal variance matrix of the responses (Goos 2002).

#### Bayesian *D*-Optimality:

- is a modification of the D-Optimality criterion that effectively estimates the coefficients in a model, and at the same time has the ability to detect and estimate some higher-order terms. If there are interactions or curvature, the Bayesian D-Optimality criterion is advantageous.
- works best when the sample size is larger than the number of Necessary terms but smaller than the sum of the Necessary and If Possible terms. That is, p + q > n > p. The Bayesian D-Optimal design is an approach that allows the precise estimation of all of the Necessary terms while providing omnibus detectability (and some estimability) for the If Possible terms.
- uses the If Possible terms to force in runs that allow for detecting any inadequacy in the model containing only the Necessary terms. Let K be the (p + q) by (p + q) diagonal matrix whose first p diagonal elements are equal to 0 and whose last q diagonal elements are the constant, k. If there are 2-factor interactions then k = 4. Otherwise k = 1. The Bayesian D-Optimal design maximizes the determinant of (X'X + K). The difference between the criterion for D-Optimality and Bayesian D-Optimality is this constant added to the diagonal elements corresponding to the If Possible terms in the X'X matrix.

#### *I*-Optimality:

- minimizes the average variance of prediction over the region of the data.
- is more appropriate than D-Optimality if your goal is to predict the response rather than the coefficients, such as in response surface design problems. Using the I-Optimality criterion is more appropriate because you can predict the response anywhere inside the region of data and therefore find the factor settings that produce the most desirable response value. It is more appropriate when your objective is to determine optimum operating conditions, and also is appropriate to determine regions in the design space where the response falls within an acceptable range. Precise estimation of the response therefore takes precedence over precise estimation of the parameters.
- minimizes this criterion: If f'(x) denotes a row of the X matrix corresponding to factor combinations x,

$$I = \int_{R} f'(x) (\mathbf{X}'\mathbf{X})^{-1} f(x) dx = \operatorname{Trace}[(\mathbf{X}'\mathbf{X})^{-1} \mathbf{M}]$$

where

$$M = \int_{R} f(x)f(x)'dx$$

**Technical Discussion** 

is a moment matrix that is independent of the design and can be computed in advance.

#### Bayesian I-Optimality:

Bayesian *I*-Optimality has a different objective function to optimize than the Bayesian D-optimal design, so the designs that result are different. The variance matrix of the coefficients for Bayesian *I*-optimality is X'X + K where K is a matrix having zeros for the Necessary model terms and some constant value for the If Possible model terms.

The variance of the predicted value at a point  $x_0$  is:

$$\operatorname{var}(Y|x_0) = (\mathbf{x}_0'(\mathbf{X}'\mathbf{X} + \mathbf{K})^{-1})\mathbf{x}_0$$

The Bayesian I-Optimal design minimizes the average prediction variance over the design region:

$$I_R = \text{Trace}[(\mathbf{X}'\mathbf{X} + \mathbf{K})^{-1}\mathbf{M}]$$

where M is defined as before.

#### Alias Optimality:

• seeks to minimize the aliasing between model effects and alias effects.

Specifically, let  $X_1$  be the design matrix corresponding to the model effects, and let  $X_2$  be the matrix of alias effects, and let

$$A = (X_1'X_1)^{-1}X_1'X_2$$

be the alias matrix.

Then, alias optimality seeks to minimize the tr(AA'), subject to the D-Efficiency being greater than some lower bound. In other words, it seeks to minimize the sum of the squared diagonal elements of A.

# **Building Custom Designs**

The Basic Steps



JMP can build a *custom* design that both matches the description of your engineering problem and remains within your budget for time and material. Custom designs are general, flexible, and good for routine factor screening or response optimization. To create these tailor-made designs, use the **Custom Design** command found on the **DOE** menu or the **Custom Design** button found on the **DOE** panel of the JMP Starter.

This chapter introduces you to the steps you need to complete to build a custom design.

# **Contents**

Creating a Custom Design69
Enter Responses and Factors into the Custom Designer
Describe the Model
Specifying Alias Terms
Select the Number of Runs
Understanding Design Evaluation
Specify Output Options
Make the JMP Design Table
Creating Random Block Designs
Creating Split Plot Designs
Creating Split-Split Plot Designs
Creating Strip Plot Designs
Special Custom Design Commands
Save Responses and Save Factors
Load Responses and Load Factors
Save Constraints and Load Constraints
Set Random Seed: Setting the Number Generator89
Simulate Responses
Save X Matrix: Viewing the Number of Rows in the Moments Matrix and the Design Matrix (X) in the
Log
Optimality Criterion
Number of Starts: Changing the Number of Random Starts
Sphere Radius: Constraining a Design to a Hypersphere
Disallowed Combinations: Accounting for Factor Level Restrictions
Advanced Options for the Custom Designer
Assigning Column Properties
Define Low and High Values (DOE Coding) for Columns
Set Columns as Factors for Mixture Experiments
Define Response Column Values
Assign Columns a Design Role
Identify Factor Changes Column Property
How Custom Designs Work: Behind the Scenes

# **Creating a Custom Design**

To begin, select **DOE** > **Custom Design**, or click the **Custom Design** button on the JMP Starter **DOE** page. Then, follow the steps below.

- Enter responses and factors into the custom designer.
- Describe the model.
- Select the number of runs.
- Check the design diagnostics, if desired.
- Specify output options.
- Make the JMP design table.

The following sections describe each of these steps.


### **Enter Responses and Factors into the Custom Designer**

#### How to Enter Responses

To enter responses, follow the steps in Figure 3.1.

- 1. To enter one response at a time, click Add Response, and then select a goal type. Possible goal types are Maximize, Match Target, Minimize, or None.
- 2. (Optional) Double-click to edit the response name.
- 3. (Optional) Click to change the response goal.
- 4. Click to enter lower and upper limits and importance weights.

Figure 3.1 Entering Responses



**Tip:** To quickly enter multiple responses, click **Number of Responses** and enter the number of responses you want.

66

### Specifying Response Goal Types and Lower and Upper Limits

When entering responses, you can tell JMP that your goal is to obtain the maximum or minimum value possible, to match a specific value, or that there is no response goal.

The following description explains the relationship between the goal type (step 3 in Figure 3.1) and the lower and upper limits (step 4 in Figure 3.1):

- For responses such as strength or yield, the best value is usually the largest possible. A goal of **Maximize** supports this objective.
- The **Minimize** goal supports an objective of having the smallest value, such as when the response is impurity or defects.
- The **Match Target** goal supports the objective when the best value for a response is a specific target value, such as a dimension for a manufactured part. The default target value is assumed to be midway between the given lower and upper limits.

**Note:** If your target response is not equidistant from the lower and upper acceptable bounds, you can alter the default target after you make a table from the design. In the data table, open the Column Info dialog for the response column (**Cols** > **Column Info**) and enter the desired target value.

### **Understanding Response Importance Weights**


To compute and maximize overall desirability, JMP uses the value you enter as the importance weight (step 4 in Figure 3.1) of each response. If there is only one response, then importance weight is unnecessary. With two responses you can give greater weight to one response by assigning it a higher importance value.

#### Adding Simulated Responses, If Desired

If you do not have values for specific responses, you might want to add simulated responses to see a prospective analysis in advance of real data collection.

- 1. Create the design.
- Before you click Make Table, click the red triangle icon in the title bar and select Simulate Responses.
- 3. Click Make Table to create the design table. The Y column contains values for simulated responses.
- 4. For custom and augment designs, a window (Figure 3.2) appears along with the design data table. In this window, enter values you want to apply to the Y column in the data table and click **Apply**. The numbers you enter represent the coefficients in an equation. An example of such an equation, as shown in Figure 3.2, would be, y = 28 + 4X1 + 5X2 + random noise, where the *random noise* is distributed with mean zero and standard deviation one.

Figure 3.2 In Custom and Augment Designs, Specify Values for Simulated Responses




#### How to Enter Factors

To enter factors, follow the steps in Figure 3.3.

- 1. To add one factor, click **Add Factor** and select a factor type. Possible factor types are **Continuous**, **Categorical**, **Blocking**, **Covariate**, **Mixture**, **Constant**, or **Uncontrolled**. See "Types of Factors," p. 67.
- 2. Click a factor and select **Add Level** to increase the number of levels.
- 3. Double-click a factor to edit the factor name.
- 4. Click to indicate that changing a factor's setting from run to run is **Easy**, **Hard**, or **Very Hard**. Changing to Hard or Very Hard will cause the resulting design to be a split plot or split-split plot design.
- 5. Click to enter or change factor values. To remove a level, click it, press the delete key on the keyboard, then press the Return or Enter key on the keyboard.
- 6. To add multiple factors, type the number of factors in the **Add N Factors** box, click the **Add Factor** button, and select the factor type.

Figure 3.3 Entering Factors in a Custom Design



#### Types of Factors

When adding factors, click the **Add Factor** button and choose the type of factor.

**Continuous** Continuous factors are numeric data types only. In theory, you can set a continuous factor to any value between the lower and upper limits you supply.

- **Categorical** Either numeric or character data types. Categorical data types have no implied order. If the values are numbers, the order is the numeric magnitude. If the values are character, the order is the sorting sequence. The settings of a categorical factor are discrete and have no intrinsic order. Examples of categorical factors are machine, operator, and gender.
- **Blocking** Either numeric or character data types. Blocking factors are a special kind of categorical factor. Blocking factors differ from other categorical factors in that there is a limit to the number of runs that you can perform within one level of a blocking factor.
- **Covariate** Either numeric or character data types. Covariate factors are not controllable, but their values are known in advance of an experiment.
- **Mixture** Mixture factors are continuous factors that are ingredients in a mixture. Factor settings for a run are the proportion of that factor in a mixture and vary between zero and one.
- **Constant** Either numeric or character data types. Constant factors are factors whose values are fixed during an experiment.
- **Uncontrolled** Either numeric or character data types. Uncontrolled factors have values that cannot be controlled during an experiment, but they are factors you want to include in the model.

# Factors that are Easy, Hard, or Very Hard, to Change: Creating Optimal Split-Plot and Split-Split-Plot Designs

Split plot experiments are performed in groups of runs where one or more factors are held constant within a group but vary between groups. In industrial experimentation this structure is desirable because certain factors may be difficult and expensive to change from one run to the next. It is convenient to make several runs while keeping such factors constant. Until now, commercial software has not supplied a general capability for the design and analysis of these experiments.

To indicate the difficulty level of changing a factor's setting, click in Changes column of the Factors panel for a given factor and select Easy, Hard, or Very Hard from the menu that appears. Changing to Hard results in a split-plot design and Very Hard results in a split-plot design.

See "Creating Split Plot Designs," p. 80, for more details.

## **Defining Factor Constraints, If Necessary**

Sometimes it is impossible to vary factors simultaneously over their entire experimental range. For example, if you are studying the affect of cooking time and microwave power level on the number of kernels popped in a microwave popcorn bag, the study cannot simultaneously set high power and long time without burning all the kernels. Therefore, you have factors whose levels are *constrained*.

#### To define the constraints:

- 1. After you add factors and click **Continue**, click the disclosure button ( and on Windows and on the Macintosh) to open the Define Factor Constraints panel.
- 2. Click the **Add Constraint** button. Note that this feature is disabled if you have already controlled the design region by entering disallowed combinations or chosen a sphere radius.

Figure 3.4 Add Constraint



- 3. Specify the coefficients and their limiting value in the boxes provided, as shown to the right. When you need to change the direction of the constraint, click on the default less than or equal button and select the greater than or equal to direction.
- 4. To add another constraint, click the **Add Constraint** button again and repeat the above steps.

#### **Describe the Model**

Initially, the Model panel lists only the main effects corresponding to the factors you entered, as shown in Figure 3.5. However, you can add factor interactions or powers of continuous factors to the model. For example, to add all the two-factor interactions and quadratic effects at once, click the **RSM** button.

Figure 3.5 Add Terms




Table 3.1 summarizes the ways to add specific factor types to the model.

Table 3.1 How to Add Terms to a Model

Action	Instructions
Add interaction terms involving selected factors. If none are selected, JMP adds all of the interactions to the specified order.	Click the <b>Interactions</b> button and select <b>2nd</b> , <b>3rd</b> , <b>4th</b> , or <b>5th</b> . For example, if the factors are X1 and X2 and you click <b>Interactions</b> > <b>2nd</b> , X1*X2 is added to the list of model terms.

**Table 3.1** How to Add Terms to a Model (Continued)

Action	Instructions
Add all second-order effects, including two-factor interactions and quadratic effects	Click the <b>RSM</b> button. The design now uses <i>I</i> -Optimality criterion rather than <i>D</i> -Optimality criterion.
Add selected cross product terms	<ol> <li>Highlight the factor names.</li> <li>Highlight term(s) in the model list.</li> <li>Click the Cross button.</li> </ol>
Add powers of continuous factors to the model effects	Click the <b>Powers</b> button and select <b>2nd</b> , <b>3rd</b> , <b>4th</b> , or <b>5th</b> .

# **Specifying Alias Terms**

You can investigate the aliasing between the model terms and terms you specify in the Alias Terms panel.

For example, suppose you specify a design with three main effects in six runs, and you want to see how those main effects are aliased by the two-way interactions and the three-way interaction. In the Alias Terms panel, specify the interactions as shown in Figure 3.6. Also, specify six runs in the Design Generation panel.

Figure 3.6 Alias Terms



After you click the **Make Design** button at the bottom of the Custom Design panel, open the Alias Matrix panel in the Design Evaluation panel to see the alias matrix. See Figure 3.7.

Figure 3.7 Aliasing


△ Alias Matrix					
Effect	X1*X2	X1*X3	X2*X3	X1'X2'X3	
Intercept	0	0	0.5	-0.5	
X1	0	0	-0.5	0.5	
X2	0.5	-0.5	0	0	
X3	-0.5	0.5	0	0	

In this example, all the main effects are partially aliased with two of the interactions. Also see "The Alias Matrix (Confounding Pattern)," p. 76.

#### Select the Number of Runs

The Design Generation panel (Figure 3.8) shows the minimum number of runs needed to perform the experiment based on the effects you've added to the model (two main effects in the example above). It also shows alternate (default) numbers of runs, or lets you choose your own number of runs. Balancing the cost of each run with the information gained by extra runs you add is a judgment call that you control.

Figure 3.8 Options for Selecting the Number of Runs



The Design Generation panel has these options for selecting the number of runs you want:

**Minimum** is the smallest number of terms that can create a design. When you use Minimum, the resulting design is saturated (no degrees of freedom for error). This is an extreme and risky choice, and is appropriate only when the cost of extra runs is prohibitive.

**Default** is a custom design suggestion for the number of runs. This value is based on heuristics for creating balanced designs with a few additional runs above the minimum.

**User Specified** is a value that specifies the number of runs you want. Enter that value into the Number of Runs text box.

**Note:** In general, the custom design suggests a number of runs that is the smallest number that can be evenly divided by the number of levels of each of the factors and is larger than the minimum possible sample size. For designs with factors at two levels only, the default sample size is the smallest power of two larger than the minimum sample size.

When the Design Generation panel shows the number of runs you want, click Make Design.

72

## **Understanding Design Evaluation**


After making the design, you can preview the design and investigate details by looking at various plots and tables that serve as design diagnostic tools.

Although different tools are available depending on the model you specify, most designs display

- the Prediction Variance Profile Plot
- the Fraction of Design Space Plot
- the Prediction Variance Surface Plot
- the Relative Variance of Coefficients and Power Table
- the Alias Matrix
- Design Diagnostic Table

These diagnostic tools are outline nodes beneath the Design Evaluation panel, as shown in Figure 3.9. JMP always provides the Prediction Variance Profile, but the Prediction Surface Plot only appears if there are two or more variables.

Figure 3.9 Custom Design Evaluation and Diagnostic Tools




#### The Prediction Variance Profile


The example in Figure 3.10 shows the prediction variance profile for a response surface model (RSM) with 2 variables and 8 runs. To see a response surface design similar to this:

- 1. Chose DOE > Custom Design.
- 2. In the Factors panel, add 2 continuous factors.
- 3. Click Continue.
- 4. In the Model panel, click **RSM**.

- 5. Click Make Design.
- 6. Open the Prediction Variance Profile.

Figure 3.10 A Factor Design Layout For a Response Surface Design with 2 Variables





The prediction variance for any factor setting is the product of the error variance and a quantity that depends on the design and the factor setting. Before you collect the data the error variance is unknown, so the prediction variance is also unknown. However, the ratio of the prediction variance to the error variance is not a function of the error variance. This ratio, called the relative variance of prediction, depends only on the design and the factor setting and can be calculated before acquiring the data. The prediction variance profile plots the relative variance of prediction as a function of each factor at fixed values of the other factors

After you run the experiment, collect the data, and fit the model, you can estimate the actual variance of prediction at any setting by multiplying the relative variance of prediction by the mean squared error (MSE) of the least squares fit.


It is ideal for the prediction variance to be small throughout the allowable regions of the factors. Generally, the error variance drops as the sample size increases. Comparing the prediction variance profilers for two designs side-by-side, is one way to compare two designs. A design that has lower prediction variance on the average is preferred.


In the profiler, drag the vertical lines in the plot to change the factor settings to different points. Dragging the lines reveals any points that have prediction variances that are larger than you would like.

Another way to evaluate a design, or to compare designs, is to try and minimize the maximum variance. You can use the **Maximize Desirability** command on the Prediction Variance Profile title bar to identify the maximum prediction variance for a model. Consider the Prediction Variance profile for the two-factor RSM model shown in Figure 3.11. The plots on the left are the default plots. The plots on the right identify the factor values where the maximum variance (or worst-case scenario) occur, which helps you evaluate the acceptability of the model.

74

Figure 3.11 Find Maximum Prediction Variance






#### The Fraction of Design Space Plot

The Fraction of Design Space plot is a way to see how much of the model prediction variance lies above (or below) a given value. As a simple example, consider the Prediction Variance plot for a single factor quadratic model, shown on the left in Figure 3.12. The Prediction Variance plot shows that 100% of the values are smaller than 0.5. You can move the vertical trace and also see that all the values are above 0.332. The Fraction of Design Space plot displays the same information. The *X* axis is the proportion of prediction variance values, ranging from 0 to 100%, and the *Y* axis is the range of prediction variance values. In this simple example, the Fraction of Design plot verifies that 100% of the values are below 0.5 and 0% of the values are below approximately 0.3. You can use the crosshair tool and find the percentage of values for any value of the prediction variance. The example to the right in Figure 3.12 shows that 75% of the prediction variance values are below approximately 0.46.

The Fraction of Design space is most useful when there are multiple factors. It summarizes the prediction variance, showing the fractional design space for all the factors taken together.

Figure 3.12 Variance Profile and Fraction of Design Space



#### The Prediction Variance Surface

When there are two or more factors, the Prediction Variance Surface plots the surface of the prediction variance for any two variables. This feature uses the **Graph** > **Surface Plot** platform in JMP, and has all its functionality. Drag on the plot to rotate and change the perspective. Figure 3.13 shows the Prediction Variance Surface plot for a two-factor RSM model. The factors are on the x and y axes, and the prediction variance is on the z axis. You can clearly see that there are high and low variance areas for both factors. Compare this plot to the Prediction Variance Profile shown in Figure 3.11.




Figure 3.13 Prediction Variance Surface Plot for Two-Factor RSM Model

You can find complete documentation for the Surface Plot platform in the *Modeling and Multivariate Methods* book.

#### The Relative Variance of Coefficients and Power Table

Before clicking **Make Table** in the custom designer, click the disclosure button ( and on Windows and on the Macintosh) to open Design Evaluation and then again to open the Relative Variance of Coefficients table.

The Relative Variance of Coefficients table (Figure 3.14) shows the relative variance of all the coefficients for the example RSM custom design (see Figure 3.10). The variances are relative to the error variance, which is unknown before the experiment, and is assumed to be one. Once you complete the experiment and have an estimate for the error variance, you can multiply it by the relative variance to get the estimated variance of the coefficient. The square root of this value should match the standard error of prediction for the coefficient when you fit a model using **Analyze > Fit Model**.


The Power column shows the power of the design as specified to detect effects of a certain size. In the text edit boxes, you can change the alpha level of the test and the magnitude of the effects compared to the error standard deviation. The alpha level edit box is called Significance Level. The magnitude of the effects edit box is called Signal to Noise Ratio. This is the ratio of the absolute value of the regression parameter to sigma (the square root of the error variance).

If you enter a smaller alpha (requiring a more significant test), then the power falls. If you increase the magnitude of the effect you want to detect, the power rises.

The power reported is the probability of finding a significant model parameter if the true effect is Signal to Noise Ratio times sigma. The Relative Variance of Coefficients table on the left in Figure 3.14 shows the results for the two-factor RSM model.

As another example, suppose you have a 3-factor 8-run experiment with a linear model and you want to detect any regression coefficient that is twice as large as the error standard deviation, with an alpha level of 0.05. The Relative Variance of Coefficients table on the right in Figure 3.14 shows that the resulting power is 0.984 for all the parameters.

Figure 3.14 Table of Relative Variance of Coefficients




### The Alias Matrix (Confounding Pattern)

Click the Alias Matrix disclosure button ( and on Windows and various on the Macintosh) to open the alias matrix (Figure 3.15).

The alias matrix shows the aliasing between the model terms and the terms you specify in the Alias Terms panel (see "Specifying Alias Terms," p. 70). It allows you to see the confounding patterns.

Figure 3.15 Alias Matrix



#### Color Map on Correlations

The Color Map On Correlations panel (see Figure 3.16) shows the correlations between all model terms and alias terms you specify in the Alias Terms panel (see "Specifying Alias Terms," p. 70). The colors correspond to the absolute value of the correlations.




Figure 3.16 Color Map of Correlations

#### The Design Diagnostics Table

Open the Design Diagnostics outline node to display a table with relative *D*-, *G*-, and *A*-efficiencies, average variance of prediction, and length of time to create the design. The design efficiencies are computed as follows:

$$D\text{-efficiency} = 100 \left( \frac{1}{N_D} |\mathbf{X'X}|^{1/p} \right)$$

$$A\text{-efficiency} = 100 \left( \frac{p}{\operatorname{trace}(N_D(\mathbf{X'X})^{-1})} \right)$$

$$G\text{-efficiency} = 100 \left( \frac{\sqrt{p}}{\sigma_{\mathrm{M}}} \right)$$

#### where

- $N_{\rm D}$  is the number of points in the design
- *p* is the number of effects in the model including the intercept
- $\sigma_{M}$  is the maximum standard error for prediction over the design points.

These efficiency measures are single numbers attempting to quantify one mathematical design characteristic. While the maximum efficiency is 100 for any criterion, an efficiency of 100% is impossible for many design

# **Building Custom Designs**Creating a Custom Design

problems. It is best to use these design measures to compare two competitive designs with the same model and number of runs rather than as some absolute measure of design quality.

Figure 3.17 Custom Design Showing Diagnostics



## **Specify Output Options**

Use the Output Options panel to specify how you want the output data table to appear.

Figure 3.18 Output Options Panel



Run Order lets you designate the order you want the runs to appear in the data table when it is created. Choices are:

**Keep the Same** the rows (runs) in the output table will appear as they do in the Design panel.

Sort Left to Right the rows (runs) in the output table will appear sorted from left to right.

Randomize the rows (runs) in the output table will appear in a random order.

**Sort Right to Left** the rows (runs) in the output table will appear sorted from right to left.

**Randomize within Blocks** the rows (runs) in the output table will appear in random order within the blocks you set up.

Add additional points using options from Make JMP Table from design plus:

**Number of Center Points:** Specifies additional runs placed at the center of each continuous factor's range.

**Number of Replicates:** Specify the number of times to replicate the entire design, including centerpoints. Type the number of times you want to replicate the design in the associated text box. One replicate doubles the number of runs.

### Make the JMP Design Table

When the Design panel shows the layout you want, click **Make Table**. Parts of the table contain information you might need to continue working with the table in JMP. The upper-left of the design table can have one or more of the following scripts:

- a Screening script runs the Analyze > Modeling > Screening platform when appropriate for the generated design.
- a Model script runs the Analyze > Fit Model platform with the model appropriate for the design.
- a constraint script that shows any model constraints you entered in the Define Factor Constraints panel
  of the Custom Design dialog.
- a DOE Dialog script that recreates the dialog used to generate the design table, and regenerates the
  design table.




Figure 3.19 Example Design Table

- 1. This area identifies the design type that generated the table. Click **Custom Design** to edit.
- 2. Model is a script. Click the red triangle icon and select **Run Script** to open the Fit Model dialog, which is used to generate the analysis appropriate to the design.
- 3. DOE Dialog is a script. Click the red triangle icon and select **Run Script** to recreate the DOE Custom Dialog and generate a new design table.

# **Creating Random Block Designs**

It is often necessary to group the runs of an experiment into blocks. Runs within a block of runs are more homogeneous than runs in different blocks. For example, the experiment described in Goos (2002), describes a pastry dough mixing experiment that took several days to run. It is likely that random day-to-day differences in environmental variables have some effect on all the runs performed on a given day. Random block designs are useful in situations like this, where there is a non-reproducible shock to the system between each block of runs. In Goos (2002), the purpose of the experiment was to understand how certain properties of the dough depend on three factors: feed flow rate, initial moisture content, and rotational

80

Creating Split Plot Designs

screw speed. It was only possible to conduct four runs a day. Because day-to-day variation was likely, it was important to group the runs so that this variation would not compromise the information about the three factors. Thus, blocking the runs into groups of four was necessary. Each day's experimentation was one block. The factor, Day, is an example of a random block factor.

To create a random block, use the custom design and enter responses and factors, and define your model as usual. In the Design Generation panel, check the Group runs into random blocks of size check box and enter the number of runs you want in each block. When you select or enter the sample size, the number of runs specified are assigned to the blocks.

Figure 3.20 Assigning Runs to Blocks

△ Design Generation				
☑Group runs into random blocks of size:				
Number of Runs:				
OMinimum	10			
<ul><li>Default</li></ul>	16			
OUser Specified	16			
Make Design				

In this example, the Design Generation Panel shown here designates four runs per block, and the number of runs (16) indicates there will be four days (blocks) of 4 runs. If the number of runs is not an even multiple of the random block size, some blocks will have a fewer runs than others.

# **Creating Split Plot Designs**

Split plot experiments happen when it is convenient to run an experiment in groups of runs (called whole plots) where one or more factors stay constant within each group. Usually this is because these factors are difficult or expensive to change from run to run. JMP calls these factors **Hard** to change because this is usually how split plotting arises in industrial practice.

In a completely randomized design, any factor can change its setting from one run to the next. When certain factors are hard to change, the completely randomized design may require more changes in the settings of hard-to-change factors than desired.

If you know that a factor or two are difficult to change, then you can set the Changes setting of a factor from the default of **Easy** to **Hard**. Before making the design, you can set the number of whole plots you are willing to run.

For an example of creating a split plot design, see "Creating a Design with Two Hard-to-Change Factors: Split Plot," p. 55.

To create a split plot design using the custom designer:

1. In the factors table there is a column called Changes. By default, changes are **Easy** for all factors. If, however, you click in the changes area for a factor, you can choose to make the factor **Hard** to change.

2. Once you finish defining the factors and click continue, you see an edit box for supplying the number of whole plots. You can supply any value as long as it is above the minimum necessary to fit all the model parameters. You can also leave this field empty. In this case, JMP chooses a number of whole plots to minimize the omnibus uncertainty of the fixed parameters.

**Note:** If you enter a missing value in the Number of Whole Plots edit box, then JMP considers many different numbers of whole plots and chooses the number that maximizes the information about the coefficients in the model. It maximizes the determinant of  $X'V^{-1}X$  where  $V^{-1}$  is the inverse of the variance matrix of the responses. The matrix, V, is a function of how many whole plots there are, so changing the number of whole plots changes V, which can make a difference in the amount of information a design contains.

To create a split plot design every time you use a certain factor, save steps by setting up that factor to be "hard" in all experiments. See "Identify Factor Changes Column Property," p. 98, for details.

# **Creating Split-Split Plot Designs**

Split-split plot designs are a three stratum extension of split plot designs. Now there are factors that are Very-Hard-to-change, Hard-to-change, and Easy-to-change. Here, in the top stratum, the Very-Hard-to-change factors stay fixed within each whole plot. In the middle stratum the Hard-to-change factors stay fixed within each subplot. Finally, the Easy-to-change factors may vary (and should be reset) between runs within a subplot. This structure is natural when an experiment covers three processing steps. The factors in the first step are Very-Hard-to-change in the sense that once the material passes through the first processing stage, these factor settings are fixed. Now the material passes to the second stage where the factors are all Hard-to-change. In the third stage, the factors are Easy-to-change.

Schoen (1999) provides an example of three-stage processing involving the production of cheese that leads to a split-split plot design. The first processing step is milk storage. Typically milk from one storage facility provides the raw material for several curds processing units—the second processing stage. Then the curds are further processed to yield individual cheeses.

In a split-split plot design the material from one processing stage passes to the next stage in such a way that nests the subplots within a whole plot. In the example above, milk from a storage facility becomes divided into two curds processing units. Each milk storage tank provided milk to a different set of curds processors. So, the curds processors were nested within the milk storage unit.

Figure 3.21 shows an example of how factors might be defined for the cheese processing example.

82

Figure 3.21 Example of Split-Split Response and Factors in Custom Designer Dialog

# **Creating Strip Plot Designs**

In a strip plot design it is possible to reorder material between processing stages. Suppose units are labelled and go through the first stage in a particular order. If it is possible to collect all the units at the end of the first stage and reorder them for the second stage process, then the second stage variables are not nested within the blocks of the first stage variables. For example, in semiconductor manufacturing a boat of wafers may go through the first processing step together. However, after this step, the wafers in a given boat may be divided among many boats for the second stage.

To set up a strip plot design, enter responses and factors as usual, designating factors as Very Hard, Hard, or Easy to change. Then, in the Design Generation panel, check the box that says **Hard to change factors** can vary independently of Very Hard to change factors, as shown in Figure 3.22. Note that the Design Generation panel specified 6 whole plots, 12 subplots, and 24 runs.

When you click **Make Design**, the design table on the right in Figure 3.22 lists the run with subplots that are not nested in the whole plots.


Add Factor ▼ Remove Add N Factors Run Whole Plots Subplots deposition 1 1 1 -1 Name Role Changes Values -1 deposition 1 Continuous Very Hard 3 3 deposition 2 Continuous Very Hard |-1 4 1 4 detch 1 Continuous Hard -1 5 2 5 detch 2 Continuous Hard -1 etch 3 -1 1 Continuous Hard 7 2 7 detch 4 Continuous Hard -1 8 2 8 🚄 clean 1 Continuous Hard 9 9 -1 clean 2 Continuous Easy 10 3 10 dean 3 Continuous Easy 11 3 1 Define Factor Constraints 12 2 13 4 3 Model 14 4 4 **▶** Alias Terms 15 16 6 17 5 7 Hard to change factors can vary independently of Very Hard to change factors. 18 8 Number of Whole Plots 19 5 9 Number of Subplots 20 10 Number of Runs: Minimum 10 Default 20 User Specified Make Design

Figure 3.22 Example of Strip Split Factors and Design Generation panel in Custom Designer Dialog

# **Special Custom Design Commands**

After you select **DOE** > **Custom Design**, click the red triangle icon on the title bar to see the list of commands available to the Custom designer (Figure 3.23). The commands found on this menu vary, depending on which DOE command you select. However, the commands to save and load responses and factors, the command to set the random seed, and the command to simulate responses are available to all designers. You should examine the red triangle menu for each designer you use to determine which commands are available. If a designer has additional commands, they are described in the appropriate chapter.





The following sections describe these menu commands and how to use them.

## **Save Responses and Save Factors**

If you plan to do further experiments with factors and/or responses to which you have given meaningful names and values, you can save them for later use.

To save factors or responses:

- 1. Select a design type from the DOE menu.
- 2. Enter the factors and responses into the appropriate panels (see "Enter Responses and Factors into the Custom Designer," p. 65, for details).
- Click the red triangle icon on the title bar and select Save Responses or Save Factors.
  - **Save Responses** creates a data table containing a row for each response with a column called Response Name that identifies the responses. Four additional columns identify more information about the responses: Lower Limit, Upper Limit, Response Goal, and Importance.
  - **Save Factors** creates a data table containing a column for each factor and a row for each factor level. The columns have two column properties (noted with asterisks icons in the column panel). These properties include:
    - **Design Role** that identifies the factor as a DOE factor and lists its type (continuous, categorical, blocking, and so on).
    - **Factor Changes** that identifies how difficult it is to change the factor level. Factor Changes options are **Easy**, **Hard**, and **Very Hard**.
- 4. Save the data table.

### **Load Responses and Load Factors**

If you have saved responses and factors, you can quickly apply them to your design and avoid retyping this information each time you run an experiment.

To design an experiment using responses or factors you have previously saved:

- 1. Open the data table that contains the factor names and levels.
- 2. Select a design type from the DOE menu.
- 3. Click the red triangle icon on the title bar and select Load Responses or Load Factors.

**Tip:** It is possible to create a factors table by keying data into an empty table, but remember to assign each column a factor type. Do this by right-clicking the column name, selecting **Column Info**, and then selecting **Column Properties > Design Role**. Lastly, click the button in the Design Role area and select the appropriate role.

#### Save Constraints and Load Constraints

In custom, augment, and mixture designs, if you set up factor constraints and plan to do further experiments with them, you can save them for later use. You can quickly apply these constraints to your design and avoid retyping this information each time you run an experiment.

To save factor constraints:

- 1. Select a design type from the DOE menu.
- 2. Enter the factor constraints into the appropriate panels (see "Enter Responses and Factors into the Custom Designer," p. 65, for details).
- 3. Click the red triangle icon on the title bar and select **Save Constraints**. **Save Constraints** creates a data table that contains the information you enter into a constraints panel. There is a column for each constraint. Each has a column property called Constraint State that identifies it as a 'less than' or a 'greater than' constraint. There is a row for each variable and an additional row that has the inequality condition for each variable.
- 4. Save the data table.

To design an experiment using factor constraints you have previously saved:

- 1. Open the data table that contains the constraints.
- 2. Select a design type from the DOE menu.
- 3. Click the red triangle icon on the title bar and select **Load Constraints**.

# **Set Random Seed: Setting the Number Generator**

The design process begins with a random starting design. To set the random seed that the custom designer uses to create this starting design, click the red triangle icon in the design title bar and select **Set Random Seed**.


86

Special Custom Design Commands

The window that appears shows the *generating seed* for that design (Figure 3.24). From this window, you can set a new random number and then run the design again.

If you use the same seed as a previous design, you will get the same design again.

Figure 3.24 Setting the Random Seed



**Note:** The random seed is also used when you simulate responses to be used with a design, as described next.

## Simulate Responses

Often, when you define a custom design (or any standard design), it may be useful to look at properties of the design with response data before you have collected data. The **Simulate Responses** command adds random response values to the JMP table that the custom designer creates. To use the command, select it before you click **Make Table**. When you click **Make Table** to create the design table, the Y column contains values for simulated responses.

For custom and augment designs, an additional window appears with the design data table that lists coefficients for the design you described in the designer panels. You can enter any coefficient values you want and click **Apply** to see new Y values in the data table. An example of an equation for a model with two factors and interaction (Figure 3.25) would be,

$$y = 21 + 4X1 + 6X2 - 5X1X2 + random noise,$$

where the *random noise* is distributed with mean zero and standard deviation one.

Figure 3.25 Example of a Custom Design with Simulated Responses



# Save X Matrix: Viewing the Number of Rows in the Moments Matrix and the Design Matrix (X) in the Log

To create scripts for the Moments Matrix and the Design Matrix, and to save these matrices as table properties in the data table that will be generated from the design, click the red triangle icon in the Custom Design title bar (Figure 3.23) and select **Save X Matrix**. After the design and table are created, two scripts are saved as table properties and are called the Moments Matrix and the Design Matrix. Each script can be selected and run from the upper left panel of the resulting data table. Results from running each of the scripts are shown in the Log. When you run the script for the Moments Matrix, JMP shows the number of rows for the global matrix, called Moments, in the Log. Similarly, when you run the script for the Design Matrix, JMP displays the number of rows for the global matrix, called X, in the Log. The Moments Matrix and the Design Matrix are used to calculate the Average Variance of Prediction, shown in the Design Diagnostics section of the Design Evaluation. Saving these scripts to the data table provides an easy way to remember and recreate your design at a later time and to compare the matrices values with alternate designs. If you do not have the log visible, select **View > Log (Window > Log** on the Macintosh). To illustrate these features:

- 1. Select DOE > Custom Design.
- 2. Add 3 continuous factors and click Continue.
- 3. Click on Interactions > 2nd and select Save X Matrix from the drop-down menu of Custom Design.
- 4. Using the Default Number of Runs (8), click Make Design and then Make Table.
- 5. If it is not already open, select **View > Log (Window > Log** on the Macintosh).
- 6. Click on the Moments Matrix red triangle in the upper left panel of the data table under Custom Design and select Run Script. The result shows in the log as N Row(::Moments):7, which is the number of rows in the global matrix called Moments. The Moments Matrix is dependent upon the model effects but is independent of the design. (The model effects can be viewed by clicking the red triangle by Model in the upper left panel of the data table and clicking on Run Script.) The Moments Matrix script for this example displays the value of each moment and is shown by clicking on the red triangle of the Moments Matrix and selecting Edit:

```
Moments = [1 0 0 0 0 0 0,
0 0.333333333333333 0 0 0 0 0,
0 0 0 0.3333333333333 0 0 0 0,
0 0 0 0 0.3333333333333 0 0 0,
0 0 0 0 0 0.11111111111111 0 0,
0 0 0 0 0 0 0.1111111111111111 0,
0 0 0 0 0 0 0 0.111111111111111111];
```

7. Click on the Design Matrix red triangle in the upper left panel of the data table under Custom Design and select Run Script. The result shows in the log as N Row(::X):8, which is the number of rows in the global matrix called X. The X Matrix is dependent upon the design for the experiment. The script for this example shows the underlying design of the X matrix and is viewed by clicking on the red triangle of the Design Matrix and selecting Edit:

Special Custom Design Commands

Note that the Moments Matrix is defined as:

$$M = \int_{R} f(x)f(x)'dx$$

where M is a moments matrix of the parameter space that is independent of the design and can be computed in advance, and where f(x) denotes a row of the design matrix corresponding to factor combinations of x. For additional details concerning moments and design matrices, see Myers, Montgomery, and Anderson-Cook (2009, pp. 365-371). Note that the moment matrix is called a matrix of region moments in this book.

## **Optimality Criterion**

To change the design criterion, click the red triangle icon in the Custom Design title bar (Figure 3.23) and select **Optimality Criterion**, then choose one of the options:


- Make D-Optimal Design
- Make I-Optimal Design
- Make Alias Optimal Design

The default criterion for **Recommended** is *D*-optimal for all design types unless you have used the **RSM** button in the Model panel to add effects that make the model quadratic. For specific information about optimality criterion, see "Technical Discussion," p. 60.

## Number of Starts: Changing the Number of Random Starts

To override the default number of random starts, click the red triangle icon in the Custom Design title bar (Figure 3.23) and select **Number of Starts**. When you select this command, the window shown in Figure 3.26 appears with an edit box for you to enter the number of random starts for the design you want to build. The number you enter overrides the default number of starts, which varies depending on the design.

Figure 3.26 Selecting the Number of Starts



**Note:** If the design iterations are taking too long, click the **Cancel** button. The Custom Designer stops and gives the best design found at that point.

#### Why Change the Number of Starts?

One difficulty with the creation of optimal designs is that the methods used do not always find the globally optimal design in cases where the optimal design is known from theory. For example, orthogonal designs are *D*-optimal with respect to a linear additive model and a cubic design space.

As the number of factors and sample size increase, the optimization problem becomes harder. It is easy for an optimizer to converge to a local optimum instead of a global optimum.

It is useful to know that:

- If random starts are used for the optimization, the design produced at the end is not always the same. Increasing the number of random starts tends to improve the optimality of the resulting design.
- For designs with all two-level factors, there is a formula for the optimal determinant:
   If D is the determinant, n is the sample size, and c is the number of columns in the design matrix, the LogD = cLogn.

If the determinants that result from the random starts match the formula above, the algorithm stops. The design is *D*-optimal and orthogonal.

#### Default Choice of Number of Random Starts: Technical Information

JMP does not start over with random designs until a jackpot is hit. The time it takes for one iteration of the algorithm (coordinate exchange) increases roughly as the product of the sample size and the number of terms in the model increases. By doing a large number of random starts for small sample sizes and reducing this number proportional to the square of the sample size as the designs get larger, the total time it takes to generate a design is kept roughly constant over the range of usual sample sizes.

The Custom Designer always attempts to find globally optimal designs when such designs are known from theory. For example,

- 2-level fractional factorial designs are globally D-optimal for all main effect and two-factor interaction models
- Latin-Square designs are D-optimal for main effect models assuming the right sample size and numbers
  of levels of the factors.
- Plackett-Burman designs are D-optimal for main effect models.

If the custom designer can identify one of these special cases, it does many more random starts. In general, however, the default number of random starts is controlled by the sample size, n, as follows:

Table 3.2 Sample Size and Random Starts

Sample Size	Number of Starts
9 or fewer	80
from 9 to 16	40
from 17 to 24	10
from 25 to 32	5

# **Building Custom Designs**Special Custom Design Commands

Table 3.2 Sample Size and Random Starts (Continued)

Sample Size	Number of Starts
more than 32	2

Note the following exceptions:

- If each factor has only two levers, the number of terms in the model is one greater than the number of factors, and the sample size is a multiple of 4, then multiply the default number of starts shown in the table above by 40.
- If the design is I-optimal divide all the Number of Starts in the table above by 2 and add 1.
- If the design could be a Latin Square, the Custom Designer does 1000 random starts.
- If the number of terms in the model is greater than 100, though, the number of random starts is 1.

After each random start, the design is checked to see if it is globally optimal, and if so, the iterations stop. Therefore, even if the default number of starts is large, it may only take a small fraction of the default number to find the globally optimal design. Again, if the process seems to be taking too long, use the **Cancel** button to see the best design found at that point.

### Sphere Radius: Constraining a Design to a Hypersphere

You can constrain custom and augmented designs to a hypersphere by editing the sphere radius. Before making the design, click the red triangle icon in the Custom Design title bar (Figure 3.23) and select **Sphere Radius**. Enter the appropriate value and click **OK**.

Note that hypersphere constraints do not work with other constraints. Also, split plot designs cannot be generated with hypersphere constraints.

If you have designed any factor's changes as Hard (see "Factors that are Easy, Hard, or Very Hard, to Change: Creating Optimal Split-Plot and Split-Split-Plot Designs," p. 68, and "Creating Random Block Designs," p. 79), the sphere radius item becomes unavailable. Conversely, once you set the sphere radius, you cannot make a factor Hard to change.

## **Disallowed Combinations: Accounting for Factor Level Restrictions**

JMP gives you the flexibility to disallow particular combinations of levels of factors. You can do this for custom and augmented designs except for experiments with mixture or blocking factors. This feature can also be used with continuous factors or mixed continuous and categorical factors.

For example, in a market research choice experiment, you might want to exclude a choice that allows all the best features of a product at the lowest price. In this case, the factor Feature has levels of worst (1), medium (2), and best (3), and the factor Price has levels of high (1), medium (2), and low (3). You want to exclude the third Feature level (best) and the third Price level (low).

To disallow a combination of factor levels:


1. Begin by adding the factors.

- Click the red triangle icon in the title bar (Figure 3.23) of the designer window and select **Disallowed** Combinations. Note that this menu item is not available if you have already defined linear inequality
   constraints.
- 3. Enter a Boolean expression that identifies what you do not want allowed (Figure 3.27). JMP evaluates your expression, and when it sees it as true, it disallows the specified combination.

**Note:** When forming the expression, use the ordinal value of the level instead of the name of the level. If the level names of the factor called **Price** are high, medium, and low, their associated ordinal values are 1, 2, and 3.

For example, in Figure 3.27, Feature==3 & Price==3 will not allow a run containing the best features at the lowest price. If there were two disallowed combinations in this example, you would use Feature==3 & Price==3 | Quality==3 & Price==3, which tells JMP to disallow a run with the best features at the lowest price or a run with the best quality and lowest price.

Figure 3.27 Enter a Boolean Expression



4. Make the design. It excludes the combination of factors you specified, as shown in Figure 3.28.

Figure 3.28 No Row Contains L3 for Both Price and Feature



# **Advanced Options for the Custom Designer**

The following options are for advanced design of experiment users.

#### Changing the Search Points Per Factor

92

For a main effects model, the coordinate exchange algorithm in the custom designer only considers the high and low values. However, you can change this so the algorithm considers more search points. For example, if you enter 5, then JMP considers five equally spaced settings for each factor. The 5 levels are considered, but all 5 levels may not appear in the output table. The Custom Designer finds a D- or I-Optimal design, which might not need to include all 5 levels.

To change the search points:

- 1. Select **DOE** > **Custom Design**.
- 2. Click the red triangle icon in the title bar (Figure 3.23) of the designer window and select **Advanced** Options > Search Points Per Factor.
- 3. Enter a positive integer and click **OK**.
- 4. Make the design.

#### Altering the Mixture Sum

If you want to keep a component of a mixture constant throughout an experiment, then the sum of the other mixture components must be between 0.001 and 1. You may have one or more fixed ingredients so that the sum of the remaining add to less than one but more than zero. To alter the mixture sum:

- 1. Select **DOE** > **Custom Design**.
- 2. Click the red triangle icon in the title bar (Figure 3.23) of the designer window and select **Advanced** Options > Mixture Sum.
- 3. Enter a positive number and click **OK**.
- 4. Make the design.

### Split Plot Variance Ratio

The optimal split plot design depends on the ratio of the variance of the random whole plot variance to the error variance. By default, this variance is one. If you have some prior knowledge of this variance ratio, you can supply it by following these steps:

- 1. Select **DOE** > **Custom Design**.
- 2. Click the red triangle icon in the title bar (Figure 3.23) of the designer window and select **Advanced** Options > Split Plot Variance Ratio.
- 3. Enter a positive number in the resulting entry field and click **OK**.
- 4. Make the design.

#### Prior Parameter Variance

If you have specified **If Possible** as the **Estimability** for any factors in your model, then you can use this option to also specify the weight used for these terms. Default values are one. Larger values represent more prior information and a smaller variance. Variances are the reciprocals of the entered values.

- 1. Select DOE > Custom Design.
- 2. Click the red triangle icon in the title bar (Figure 3.23) of the designer window and select **Advanced** Options > Prior Parameter Variance.
- 3. Enter a positive number for each of the terms for which you want to specify a weight and click **OK**.
- 4. Make the design.

#### D Efficiency Weight

Specify the relative importance of D-Efficiency (reducing the variance of the coefficients) versus aliasing reduction. Values should be between 0 and 1, with larger values weighting more toward D-Efficiency.

### Save Script to Script Window

This command creates the script for the design you described in the Custom Designer and saves it in an open script window.

### **Assigning Column Properties**

Columns in a data table can contain special column properties. Figure 3.29 shows that a column called Stretch has two special properties: Role and Response Limits, that were assigned by the Custom Designer when the table was created. To see the example in Figure 3.29, open Bounce Data.jmp from the Design Experiment folder found in the sample data installed with JMP. Then, right-click the column name in the data table and select Column Info. When the Column Info dialog appears, click on the property you want to see.

OK 'Stretch' in Table 'Bounce Data' Column Name Stretch Cancel Lock Apply Data Type Numeric ▼ Help Modeling Type Continuous ▼ Format Best ▼ Width Use thousands separator (,) Column Properties ▼ Response Limits Role Response Limits are bounds on a optional item response's range of acceptability. The prediction and contour profilers use these values. Click below to key in Remove Match Target ▼ Importance 1 Add Desirability Lower 350 Middle 450 Upper 550

Figure 3.29 Column Properties Menu in the Column Info Dialog

All special column properties are covered in the *Using JMP*. The following discussion gives details about properties specific to DOE and that are useful for analyzing DOE data.

### **Define Low and High Values (DOE Coding) for Columns**

Show as graph reference lines

For continuous variables, the *Coding* column property transforms data in the range you specify from -1 to +1. When you analyze the coded variable, JMP uses those transformed data values to compute meaningful parameter estimates. You can specify the range in which the low and high values of the column are transformed.

By default, when JMP generates a design table from values entered in the Factors panel, it uses those values as the low and high values of the coding property. If a column has one or more limits missing, JMP substitutes the data's minimum and maximum for the high and low values.

You can use the Column Info dialog to manually add or delete a coding property, or change the range in which the low and high values are transformed. Figure 3.30 shows the coding values for the Temperature variable in the Reactor 8 Runs data table from the Design Experiment Sample Data.

OK 'Temperature' in Table 'Reactor 8 Runs' Column Name | Temperature Cancel Lock Apply Data Type Numeric ▼ Help Modeling Type | Continuous ▼ Format Best ▼ Width 10 Use thousands separator (,) Column Properties ▼ Coding Design Role Coding declares that when you fit it in a optional item model, the range Low to High is transformed into the range -1 to 1. This property makes tests and parameters estimates more meaningful Low Value 140 Remove 180 High Value

Figure 3.30 Coding Column Property in Column Info Dialog

### Set Columns as Factors for Mixture Experiments

You might have a column in a data table that is one of several factors that form 100% of a mixture. You can set up the column so JMP uses it to automatically generate a no-intercept model when you analyze the data with the Fit Model platform. The following example uses the Donev Mixture Data from the Design Experiment sample data

To set up the CuS04 column as a mixture factor, first select Cols > Column Info to see the Column Info dialog for CuS04. Then continue as follows:

- 1. Select **Mixture** from the **Column Properties** drop-down menu. Upper and Lower limits, and the sum of the limits appear in a panel on the dialog, as shown in Figure 3.31. You can use these limits, or enter your own values.
- Optionally, check the boxes beside L PseudoComponent Coding, U PseudoComponent Coding, or both L and U PseudoComponent Coding. Using the example in Figure 3.31, where the mixture sum value is 1, the terms are coded as:

$$X_i L = (X_i - L_i)/(1 - L)$$
 for the L pseudocomponent

$$X_i U = (U_i - X_i)/(U - 1)$$
 for the *U* pseudocomponent

where  $L_i$  and  $U_i$  are the lower and upper bounds, L is the sum of  $L_i$  and U is the sum of  $U_i$ .

Note: If you check either L PseudoComponent Coding or U PseudoComponent Coding for the mixture coding of one mixture factor and you check the other alternative for one or more other mixture factors in the model, of if you check both boxes for one or more of the mixture factors, the Fit Model platform uses the L coding if (1-L) < (U-1), and the U coding otherwise. If only one coding box is checked consistently for all mixture factors in the model, then only that one pseudocomponent coding is used.

Assigning Column Properties

In the Fit Model report, the main effects are labeled with the coding transformation. Crossed effects are not labeled, but coding values are used. All the features of fitting, such as the profilers and saved formulas, respect the pseudocomponent coding but present the un-coded values in the tables and plots.

- 3. Select the **Design Role** Column Property, and choose **Mixture** from its drop down menu.
- 4. Click **OK**. The properties icon (\*) now appears next to the column name in the columns panel, indicating the column contains one or more column properties.




Figure 3.31 Column Info to Create Mixture Column For Analysis

5. Repeat the above steps for any other mixture factors that will be included in the model.


### **Define Response Column Values**

You can save response limits in a column, which means you can run analyses without having to re-specify response limits each time. Saving these limits in a column facilitates consistency. For example, if you run an analysis that employs these limits, then come back later and change the data, you can run a new analysis using the same limits without having to reenter them. To see the example in Figure 3.32, open Bounce Data.jmp from the Design Experiment folder in the sample data installed with JMP.

Figure 3.32 shows the panel with values that specify lower, middle, and upper limits, and a desirability value. You can also select a possible goal for a DOE response variable: Maximize, Match Target, Minimize, or **None**. If you have more than one response, you can enter an importance value, which lets JMP know how to weigh the importance of one response against another.

To enter response limits:

- 1. Double-click the column name Stretch in the data grid. The Column Info dialog appears.
- 2. Select Response Limits from the Column Properties drop-down menu.
- 3. Select a goal for the response variable. For example, if you are in the prediction profiler and want the desired value to be close to 450, select Match Target.
- 4. When you have two responses, enter a number in the **Importance** box to indicate the amount of weight you want this response to have when JMP computes the overall desirability.
- 5. Enter the lower, middle and upper limits as well as the desirability values.



550 Show as graph reference lines

Figure 3.32 Completed Response Limits

Upper

6. Click **OK**. The properties icon (\*) now appears next to the column name in the column panel of the data table to indicate that the column contains a property.

### Assign Columns a Design Role

The Custom designer in JMP assigns design roles to factors when you create the design. However, you can assign a property to a column that identifies a factor column as a continuous, categorical, blocking, covariate, mixture, constant, signal, or noise factor. The example in Figure 3.33 shows the Whole Plots factor in the Vinyl Data.jmp table from the Design Experiment sample data assigned the Random Block design role.


To give a column a design role:

1. Double-click the column name in the data grid. The Column Info window appears.

# **Building Custom Designs**Assigning Column Properties

- 2. Select **Design Role** from the **Column Properties** drop-down menu, as shown in Figure 3.33. Design role information appears on the right.
- 3. Click the Design Role drop-down menu and select how you want JMP to use the factor column: Continuous, Categorical, Blocking, Covariate, Mixture, Constant, Signal, Noise, Uncontrolled, or Random Block.
- 4. Click **OK** to see the property icon (★) next to the column name in the data table's column panel.

Figure 3.33 Assign a Design Role to a Factor Column



**Note:** Although you can save design roles for factors, which are then automatically used each time those factors are loaded, you must always verify that the model for the design you create is correctly entered into the DOE custom designer.


### Identify Factor Changes Column Property

To create split plot or split-split plot designs, you must identify a factor as having values that are hard to change, or very hard to change. This is done in the DOE design panel (see "Creating Split Plot Designs," p. 80, for details) each time you design an experiment. However, if you know that every time you use that factor, you want it to be considered hard or very hard to change, you can save yourself steps by setting up a column property to be used in all experiments using that factor. To do this:

- 1. Double-click the column name in the data grid to see the Column Info dialog for that column.
- 2. Select Factor Changes from the Column Properties drop-down menu, as shown in Figure 3.34.
- 3. Click the **Factor Changes** button and select **Easy**, **Hard**, or **Very Hard** from the **Factor Changes** drop-down menu.
- Click OK. The properties icon (★) now appears next to the column name in the column panel of the data table.

How Custom Designs Work: Behind the Scenes

Figure 3.34 Factor Changes Column Property



### **How Custom Designs Work: Behind the Scenes**

The custom designer starts with a random set of points inside the range of each factor. The computational method is an iterative algorithm called *coordinate exchange* (Meyer and Nachtsheim, 1995). Each iteration of the algorithm involves testing every value of every factor in the design to determine if replacing that value increases the optimality criterion. If so, the new value replaces the old. This process continues until no replacement occurs for an entire iteration.

To avoid converging to a local optimum, the whole process is repeated several times using a different random start. The custom designer displays the best of these designs. For more details, see the section "Optimality Criterion," p. 88.

Sometimes a design problem can have several *equivalent* solutions. Equivalent solutions are designs with equal precision for estimating the model coefficients as a group. When this is true, the design algorithm may generate different (but equivalent) designs when you click the **Back** and **Make Design** buttons repeatedly.

IOO

**Building Custom Designs** How Custom Designs Work: Behind the Scenes

Chapter 3

# **Screening Designs**



Screening designs are some of the most popular designs for industrial experimentation. They examine many factors to see which have the greatest effect on the results of a process.

Screening designs generally require fewer experimental runs, which is why they cost less. Thus, they are attractive because they are a relatively inexpensive and efficient way to begin improving a process.

Often screening designs are a prelude to further experiments. It is wise to spend only about a quarter of your resource budget on an initial screening experiment. You can then use the results to guide further study.

The efficiency of screening designs depends on the critical assumption of *effect sparsity*. Effect sparsity results because real-world processes usually have only a few driving factors; other factors are relatively unimportant. To understand the importance of effect sparsity, you can contrast screening designs to full factorial designs:

- Full factorial designs consist of all combinations of the levels of the factors. The number of runs is the product of the factor levels. For example, a factorial experiment with a two-level factor, a three-level factor, and a four-level factor has 2 x 3 x 4 = 24 runs.
- By contrast, screening designs reduce the number of runs by restricting the factors to two (or three) levels and by performing only a fraction of the full factorial design.

Each factor in a screening design is usually set at two levels to economize on the number of runs needed, and response measurements are taken for only a fraction of the possible combinations of levels. In the case described above, you can restrict the factors to two levels, which yield  $2 \times 2 \times 2 = 8$  runs. Further, by doing half of these eight combinations you can still assess the separate effects of the three factors. So the screening approach can reduce the original 24-run experiment to four runs.

Of course, there is a price for this reduction. This chapter discusses the screening approach in detail, showing both pros and cons. It also describes how to use JMP's screening designer, which supplies a list of popular screening designs for two or more factors. These factors can be continuous or categorical, with two or three levels. The list of screening designs you can use includes designs that group the experimental runs into blocks of equal sizes where the size is a power of two.

# **Contents**

Screening Design Examples
Using Two Continuous Factors and One Categorical Factor
Using Five Continuous Factors
Creating a Screening Design
Enter Responses
Enter Factors
Choose a Design
Display and Modify a Design
Specify Output Options
View the Design Table.
Create a Plackett-Burman design
Analysis of Screening Data122
Using the Screening Analysis Platform123
Using the Fit Model Platform

### **Screening Design Examples**

This chapter is divided into two sections. The first section consists of two examples using screening designs. The second section outlines the procedures to follow to create a screening design to match your needs.

### **Using Two Continuous Factors and One Categorical Factor**

Suppose an engineer wants to investigate a process that uses an electron beam welding machine to join two parts. The engineer fits the two parts into a welding fixture that holds them snugly together. A voltage applied to a beam generator creates a stream of electrons that heats the two parts, causing them to fuse. The ideal depth of the fused region is 0.17 inches. The engineer wants to study the welding process to determine the best settings for the beam generator to produce the desired depth in the fused region.

For this study, the engineer wants to explore the following three inputs, which are the factors for the study:

- Operator, who is the technician operating the welding machine
- Rotation Speed, which is the speed at which the part rotates under the beam
- Beam Current, which is a current that affects the intensity of the beam

After each processing run, the engineer cuts the part in half. This reveals an area where the two parts have fused. The Length of this fused area is the depth of penetration of the weld. This depth of penetration is the response for the study.


The goals of the study are to:

- · find which factors affect the depth of the weld
- quantify those effects
- find specific factor settings that predict a weld depth of 0.17 inches

To begin this example, select **DOE > Screening Design** from the main menu. Note that in the Responses panel, there is a single default response called Y. Change the default response as follows:

- 1. Double-click the response name and change it to Depth (In.).
- 2. The default goal for the single default response is Maximize, but the goal of this process is to get a target value of 0.17 inches with a lower bound of 0.12 and an upper bound of 0.22. Click the **Goal** box and choose **Match Target** from the drop-down menu, as shown in Figure 4.1.

Figure 4.1 Screening Design Response With Match Target Goal




3. Click the **Lower Limit** text edit area and enter 0.12 as the lower limit (minimum acceptable value). Then click the **Upper Limit** text edit area and enter 0.22 as the upper limit (maximum acceptable value).

This example has one categorical factor (Operator) and two continuous factors (Speed and Current).

- Add the categorical factor by clicking the Add button beside 2-Level Categorical.
- 5. Add two continuous factors by typing 2 in the Continuous box and clicking the associated Add button.
- 6. Double-click the factor names and rename them Operator, Speed, and Current.
- 7. Set high and low values for Speed to 3 and 5 rpm. Set high and low values for Current to 150 and 165 amps, and assign John and Mary as values for the categorical factor called Operator, as shown in Figure 4.2.


Figure 4.2 Screening Design with Two Continuous and One Categorical Factor



- 8. Click Continue.
- 9. Select **Full Factorial** in the list of designs, as shown in Figure 4.3, and then click **Continue**.

IOS


Figure 4.3 List of Screening Designs for Two Continuous and One Categorical Factors



In the Output Options section of the Display and Modify Design panel that appears, click on the Run Order menu and select Sort Left to Right, which arranges the runs in the JMP design data table (see Figure 4.7). Then click Make Table to create the JMP table that contains the specified design.

The table in Figure 4.4 appears. The table uses the names for responses, factors, and levels you specified. The Pattern variable shows the coded design runs. You can also see the table produced in this example by selecting Help > Sample Data > Design of Experiments > DOE Example 1. (You can also open DOE Example 1.jmp from the sample data directory.)

Figure 4.4 The Design Data Table



### **Using Five Continuous Factors**

As illustrated in the previous section, experiments for screening the effects of many factors usually consider only two levels of each factor. This allows the examination of many factors with a minimum number of runs.

The following example, adapted from Meyer, *et al.* (1996), demonstrates how to use JMP's screening designer when you have many factors. In this study, a chemical engineer investigates the effects of five factors on the percent reaction of a chemical process. The factors are:

Chapter 4


Screening Design Examples

- feed rate, the amount of raw material added to the reaction chamber in liters per minute
- percentage of catalyst
- stir rate, the RPMs of a propeller in the chamber
- · reaction temperature in degrees Celsius
- concentration of reactant

#### To start the example:

- 1. Select **DOE** > **Screening Design**.
- 2. You see one default response called Y. Change the default response name (Y) to Percent Reacted.
- 3. The Goal is to maximize the response, but change the minimum acceptable reaction percentage to 90 (Lower Limit), and upper limit to 99 (Upper Limit), as shown in Figure 4.5.
- 4. Add five continuous factors.
- 5. Change the default factor names (X1-X5) to Feed Rate, Catalyst, Stir Rate, Temperature, and Concentration.
- 6. Enter the high and low values, as shown in Figure 4.5.


Figure 4.5 Screening for Many Factors



- 7. Click **Continue**. Now, JMP lists the designs for the number of factors you specified, as shown to the left in Figure 4.6.
- 8. Select the first item in the list, which is an 8-run fractional factorial design with no blocks.

9. Click **Continue** to see the Output Options outline on the right in Figure 4.6.


Figure 4.6 Two-level Screening Design (left) and design output options (right)



The design dialog has options shown in Figure 4.7 that can modify the final design table.

10. Select **Sort Left to Right** from the Run Order Menu.

Figure 4.7 Output Options for Design Table



11. Click **Make Table** to create the data table shown in Figure 4.8 that lists the runs for the design you selected. Note that it also has a column called **Percent Reacted** for recording experimental results, showing as the rightmost column of the data table.


Figure 4.8 JMP Table of Runs for Screening Example

🕶 Fractional Factorial 🕒	4							
Design Fractional Factoria	•	Pattern	Feed Rate	Catalyst	Stir Rate	Temperature	Concentration	Percent Reacted
▼ Screening	1	+	10	1	100	140	6	•
▼ Model	2	+	10	1	120	180	3	
Columns (7/0)	3	-+-+-	10	2	100	180	3	•
♣ Pattern 🕮	4	-++-+	10	2	120	140	6	•
▲ Feed Rate ★	5	+++	15	1	100	180	6	•
✓ Catalyst ★	6	+-+	15	1	120	140	3	•
✓ Stir Rate   ★	7	++	15	2	100	140	3	•
Temperature *	8	+++++	15	2	120	180	6	•
Percent Reacted *								

Of the five factors in the reaction percentage experiment, you expect a few to stand out in comparison to the others. Let's take an approach to the analysis that looks for active effects.

- 12. To run the model generated by the data shown in Figure 4.8, open Reactor 8 Runs.jmp from the Design Experiment folder found in the sample data that was installed with JMP. This table has the design runs and the results of the experiment.
- 13. In the design data table, click the Screening script that shows on the upper left of the data table, and select Run Script. Or, you can choose Analyze > Modeling > Screening to analyze the data. Select Percent Reacted as *Y* and all other continuous variables as *X*. Click OK. The report is shown in Figure 4.9.

Figure 4.9 Report for Screening Example



**Note:** Analysis of the screening data is covered in the section "Create a Plackett-Burman design," p. 120 at the end of this chapter.

## **Creating a Screening Design**

To begin, select **DOE** > **Screening Design**, or click the **Screening Design** button on the JMP Starter **DOE** page. Then, see the following sections for each step to create a screening design:


- 1. "Enter Responses," p. 109
- 2. "Enter Factors," p. 110
- 3. "Choose a Design," p. 111
- 4. "Display and Modify a Design," p. 115
- 5. "Specify Output Options," p. 119
- 6. "View the Design Table," p. 120

#### **Enter Responses**

To enter responses, follow the steps in Figure 4.10.

- 1. To enter one response at a time, click and then select a goal type. Possible goal types are **Maximize**, **Match Target**, **Minimize**, or **None**.
- 2. (Optional) Double-click to edit the response name.
- 3. (Optional) Click to change the response goal.
- 4. Click to enter lower and upper limits and importance weights.

Figure 4.10 Entering Responses



**Tip:** To quickly enter multiple responses, click the **Number of Responses** button and enter the number of responses you want.

#### Specifying Goal Types and Lower and Upper Limits

When entering responses, you can tell JMP that your goal is to obtain the maximum or minimum value possible, to match a specific value, or that there is no goal.

The following description explains the relationship between the goal type (step 3 in Figure 4.10) and the lower and upper limits (step 4 in Figure 4.10):

- For responses such as strength or yield, the best value is usually the largest possible. A goal of **Maximize** supports this objective.
- The **Minimize** goal supports an objective of having the smallest value be the most desirable, such as when the response is impurity or defects.
- The Match Target goal supports the objective when the best value for a response is a specific target value, such as dimensions of a manufactured part. The default target value is assumed to be midway between the lower and upper limits.

**Note:** If your target range is not symmetric around the target value, you can alter the default target after you make a table from the design. In the data table, open the response's Column Info dialog by double-clicking the column name, and enter an asymmetric target value.

#### **Understanding Importance Weights**


When computing overall desirability, JMP uses the value you enter as the importance weight (step 4 in Figure 4.10) as the weight of each response. If there is only one response, then specifying importance is unnecessary. With two responses you can give greater weight to one response by assigning it a higher importance value.

#### **Enter Factors**

Next, you enter factors. The Factors panel's appearance depends on the design you select. Entering factors is the same in **Screening Design**, **Space Filling Design**, **Mixture Design**, and **Response Surface Design**. This process is described below, in Figure 4.11.

- 1. To enter factors, type the number of factors and click Add.
- 2. Highlight the factor and click the **Remove Selected** button to remove a factor in the list.
- 3. Double-click to edit the factor name.
- 4. Click to enter factor values. To remove a level, click it, press the delete key on your keyboard, then press the Return or Enter key on your keyboard.

Figure 4.11 Entering Factors



#### Types of Factors

In general, when designing experiments, you can enter different types of factors in the model. Below is a description of factor types from which you can choose when creating screening designs:

**Continuous** Continuous factors have numeric data types only. In theory, you can set a continuous factor to any value between the lower and upper limits you supply.


**Categorical** Categorical factors (either numeric or categorical data types) have no implied order. If the values are numbers, the order is the numeric magnitude. If the values are character, the order is the sorting sequence. The settings of a categorical factor are discrete and have no intrinsic order. Examples of categorical factors are machine, operator, and gender.

After you enter responses and factors, click Continue.

### **Choose a Design**

The list of screening designs you can use includes designs that group the experimental runs into blocks of equal sizes where the size is a power of two. Highlight the type of screening design you want to use and click **Continue**.

Figure 4.12 Choosing a Type of Screening Design



The screening designer provides the following types of designs:

#### Two-Level Full Factorial

A full factorial design has runs for all combinations of the levels of the factors. The samples size is the product of the levels of the factors. For two-level designs, this is  $2^k$  where k is the number of factors. This can be expensive if the number of factors is greater than 3 or 4.

These designs are orthogonal. This means that the estimates of the effects are uncorrelated. If you remove an effect in the analysis, the values of the other estimates remain the same. Their *p*-values change slightly, because the estimate of the error variance and the degrees of freedom are different.

Full factorial designs allow the estimation of interactions of all orders up to the number of factors. Most empirical modeling involves first- or second-order approximations to the true functional relationship between the factors and the responses. The figure to the left in Figure 4.13 is a geometric representation of a two-level factorial.

#### Two-Level Fractional Factorial

A fractional factorial design also has a sample size that is a power of two. If k is the number of factors, the number of runs is  $2^{k-p}$  where p < k. The fraction of the full factorial is  $2^{-p}$ . Like the full factorial, fractional factorial designs are orthogonal.

The trade-off in screening designs is between the number of runs and the *resolution* of the design. If price is no object, you can run several replicates of all possible combinations of *m* factor levels. This provides a good estimate of everything, including interaction effects to the *m*th degree. But because running experiments costs time and money, you typically only run a fraction of all possible levels. This causes some of the higher-order effects in a model to become *nonestimable*. An effect is nonestimable when it is confounded with another effect. In fact, fractional factorials are designed by deciding in advance which interaction effects are confounded with the other interaction effects.

#### Resolution Number: The Degree of Confounding

In practice, few experimenters worry about interactions higher than two-way interactions. These higher-order interactions are assumed to be zero.


Experiments can therefore be classified by resolution number into three groups:

- Resolution = 3 means that main effects are confounded with one or more two-way interactions, which must be assumed to be zero for the main effects to be meaningful.
- Resolution = 4 means that main effects are not confounded with other main effects or two-factor interactions. However, two-factor interactions are confounded with other two-factor interactions.
- Resolution ≥ 5 means there is no confounding between main effects, between two-factor interactions, or between main effects and two-factor interactions.

A *minimum aberration* design is one in which there are a minimum number of confoundings for a given resolution. For DOE experts, the minimum aberration design of a given resolution minimizes the number of words in the defining relation that are of minimum length.

The figure on the right in Figure 4.13 is geometric representation of a two-level fractional factorial design.

Figure 4.13 Representation of Full Factorial (Left) and Two-Level Fractional Factorial (Right) Designs



#### Plackett-Burman Designs

Plackett-Burman designs are an alternative to fractional factorials for screening. One useful characteristic is that the sample size is a multiple of four rather than a power of two. There are no two-level fractional factorial designs with sample sizes between 16 and 32 runs. However, there are 20-run, 24-run, and 28-run Plackett-Burman designs.

The main effects are orthogonal and two-factor interactions are only partially confounded with main effects. This is different from resolution-three fractional factorial where two-factor interactions are indistinguishable from main effects.

In cases of effect sparsity, a stepwise regression approach can allow for removing some insignificant main effects while adding highly significant and only somewhat correlated two-factor interactions. The new Screening platform in JMP, **Analyze** > **Modeling** > **Screening**, is a streamlined approach for looking at sparse data. This platform can accept multiple responses and multiple factors, then automatically fits a two-level design and shows significant effects with plots and statistics. See the chapter in the *Modeling and Multivariate Methods* book on the Screening platform for more information.

### Mixed-Level Designs

If you have qualitative factors with three values, then none of the classical designs discussed previously are appropriate. For pure three-level factorials, JMP offers fractional factorials. For mixed two-level and three-level designs, JMP offers complete factorials and specialized orthogonal-array designs, listed in Table 4.1

If you have fewer than or equal to the number of factors for a design listed in the table, you can use that design by selecting an appropriate subset of columns from the original design. Some of these designs are not balanced, even though they are all orthogonal.

Table 4.1 Table of Mixed-Level Designs

Design	Two-Level Factors	Three-Level Factors
L18 John	1	7

Creating a Screening Design

 Table 4.1 Table of Mixed-Level Designs (Continued)

Design	Two-Level Factors	Three-Level Factors
L18 Chakravarty	3	6
L18 Hunter	8	4
L36	11	12

#### **Cotter Designs**

Cotter designs are used when you have very few resources and many factors, and you believe there may be interactions. Suppose you believe in effect sparsity— that very few effects are truly nonzero. You believe in this so strongly that you are willing to bet that if you add up a number of effects, the sum will show an effect if it contains an active effect. The danger is that several active effects with mixed signs will cancel and still sum to near zero and give a false negative.

Cotter designs are easy to set up. For k factors, there are 2k + 2 runs. The design is similar to the "vary one factor at a time" approach many books call inefficient and naive.

A Cotter design begins with a run having all factors at their high level. Then follow k runs each with one factor in turn at its low level, and the others high. The next run sets all factors at their low level and sequences through k more runs with one factor high and the rest low. This completes the Cotter design, subject to randomizing the runs.

When you use JMP to generate a Cotter design, the design also includes a set of extra columns to use as regressors. These are of the form *factor*Odd and *factor*Even where *factor* is a factor name. They are constructed by adding up all the odd and even interaction terms for each factor. For example, if you have three factors, A, B, and C:

**Table 4.2** Cotter Design Table

AOdd = A + ABC	AEven = AB + AC
BOdd = B + ABC	BEven = AB + BC
COdd = C + ABC	CEven = BC + AC

Because these columns in a Cotter design make an orthogonal transformation, testing the parameters on these combinations is equivalent to testing the combinations on the original effects. In the example of factors listed above, AOdd estimates the sum of odd terms involving A. AEven estimates the sum of the even terms involving A, and so forth.

Because Cotter designs have a false-negative risk, many statisticians discourage their use.

#### How to Run a Cotter Design

By default, JMP does not include a Cotter design in the list of available screening designs (Figure 4.12). However, if you want to make a Cotter design:

- 1. Immediately after entering responses and factors (and before clicking **Continue**), click the red triangle icon in the Screening Design title bar.
- 2. Select Supress Cotter Designs (to uncheck it).


Changing the setting via the red triangle menu applies only to the *current* design. To alter the setting for *all* screening designs:

- 1. Select File > Preferences.
- 2. Click the Platforms icon.
- 3. Click **DOE** to highlight it.
- 4. Uncheck the box beside **Suppress Cotter Designs**.

### Display and Modify a Design

After you select a design type, open the Display and Modify Design outline.

Figure 4.14 Display and Modification Options



**Change Generating Rules** Controls the choice of different fractional factorial designs for a given number of factors.


**Aliasing of Effects** Shows the confounding pattern for fractional factorial designs.

**Coded Design** Shows the pattern of high and low values for the factors in each run.

#### Aliasing of Effects

To see which effects are confounded with which other effects, open the Aliasing of Effects outline. It shows effects and confounding up to two-factor interactions.

Figure 4.15 Generating Rules and Aliasing of Effects Panel



For example, a full factorial with five factors requires  $2^5 = 32$  runs. Eight runs can only accommodate a full factorial with three two-level factors. It is necessary to construct the two additional factors in terms of the first three factors.

The price of reducing the number of runs from 32 to eight is effect aliasing (confounding). Confounding is the direct result of the assignment of new factor values to products of the coded design columns.

In the example above, the values for Temperature are the product of the values for Feed Rate and Concentration. This means that you can't tell the difference of the effect of Temperature and the synergistic (interactive) effect of Feed Rate and Concentration.

In the example shown in Figure 4.15, all the main effects are confounded with two-factor interactions. This is characteristic of resolution-three designs.

### Look at the Confounding Pattern

JMP can create a data table that shows the aliasing pattern for a specified level. To create this table:

- 1. Click the red triangle at the bottom of the Aliasing of Effects area.
- 2. Select Show Confounding Pattern (Figure 4.16).

Figure 4.16 Show Confounding Patterns

△ Aliasing of Effe	ects
Effects	Aliases
Feed Rate	= Temperature*Concentration
Catalyst	= Stir Rate*Concentration
Stir Rate	= Catalyst*Concentration
Temperature	= Feed Rate*Concentration
Concentration	= Feed Rate*Temperature = Catalyst*Stir Rate
Feed Rate*Catalyst	= Stir Rate*Temperature
Feed Rate*Stir Rate	= Catalyst*Temperature
Show Confour	nding Pattern 🔓
Design Evaluation	n
Output Options	
Run Order:	Randomize ▼
Make JMP Table from	design plus
Number of Center Poi	nts: 0
Number of Replicates	: 0
Make Table	
Back	

3. Enter the order of confounding you want to see (Figure 4.17).

Figure 4.17 Enter Order of Confounding in Text Edit Box



#### 4. Click OK.

Figure 4.18 shows the third order aliasing for the five-factor reactor example. The effect names begin with C (Constant) and are shown by their order number in the design. Thus, Temperature appears as "4", with second order aliasing as "1 5" (Feed Rate and Concentration), and third order confounding as "1 2 3" (Feed Rate, Catalyst, and Stir Rate).


Figure 4.18 The Third Level Alias for the Five-Factor Reactor Example

Confounding Pa	D	4 🔻		
		•	Effect Names	Alias Names
		1	С	= 235 = 145
Columns (2/0)		2	1	= 234 = 45
♣ Effect Names	_	3	2	= 134 = 35
Alias Names		4	12	= 34 = 135 = 245
		5	3	= 1 2 4 = 2 5
Rows		6	13	= 24 = 125 = 345
All rows	26	7	23	= 14 = 5
Selected	0	8	123	= 4 = 15
Excluded	0	9	4	=123 =15
Hidden	0	10	14	=23 =5
Labelled	0	11	24	=13 =125 =345
		12	124	= 3 = 25
		13	3 4	=12=135=245
Labelled	0	12	124	=3 =25

#### **Understanding Design Codes**

In the Coded Design panel, each row represents a run. Plus signs designate high levels and minus signs represent low levels. As shown in Figure 4.19, rows for the first three columns of the coded design, which represent Feed Rate, Catalyst, and Stir Rate are all combinations of high and low values (a full factorial design). The fourth column (Temperature) of the coded design is the element-by-element product of the first three columns. Similarly, the last column (Concentration) is the product of the second and third columns.

Figure 4.19 Default Coded Designs




#### Changing the Coded Design

In the Change Generating Rules panel, changing the check marks and clicking **Apply** changes the coded design; it changes the choice of different fractional factorial designs for a given number of factors. The Coded Design table in Figure 4.19 shows how the last two columns are constructed in terms of the first three columns. The check marks in the Change Generating Rules table shown in Figure 4.20 for Temperature now show it is a function of Feed Rate, and Catalyst. The check marks for Concentration show it is a function of Feed Rate and Stir Rate.

If you check the options as shown in Figure 4.20 and click **Apply**, the Coded Design panel changes. The first three columns of the coded design remain a full factorial for the first three factors (Feed Rate, Catalyst, and Stir Rate). Temperature is now the product of Feed Rate and Catalyst, so the fourth column of the coded design is the element by element product of the first two columns. Concentration is a function of Feed Rate and Stir Rate.

Figure 4.20 Modified Coded Designs and Generating Rules



### **Specify Output Options**

Use the Output Options panel (Figure 4.21) to specify how you want the output data table to appear. When the options are the way you want them, click **Make Table**.

Figure 4.21 Select the Output Options



Create a Plackett-Burman design

**Run Order** Lets you designate the order you want the runs to appear in the data table when it is created. Choices are:

**Keep the Same** the rows (runs) in the output table appear as they do in the Coded Design panel.

**Sort Left to Right** the rows (runs) in the output table appear sorted from left to right.

**Randomize** the rows (runs) in the output table appear in a random order.

**Sort Right to Left** the rows (runs) in the output table appear sorted from right to left.

**Randomize within Blocks** the rows (runs) in the output table will appear in random order within the blocks you set up.

**Number of Center Points** Specifies additional runs placed at the center points.

**Number of Replicates** Specify the number of times to replicate the entire design, including centerpoints. Type the number of times you want to replicate the design in the associated text box. One replicate doubles the number of runs.

### **View the Design Table**

Click **Make Table** to create a data table that contains the runs for your experiment. In the table, the high and low values you specified are displayed for each run.

Fractional Factorial Design Fractional Factorial Pattern Feed Rate Catalyst Stir Rate Temperature Concentration Percent Reacted Screening 10 100 140 6 ■ Model 2 --++-10 120 180 3 3 -+-+-10 2 180 3 100 Columns (7/0) 4 -++-+ 10 2 120 140 6 ul. Pattern 🚑 15 100 180 6 Feed Rate \* 6 +-+--15 120 140 3 1 Catalyst \* 7 ++---15 2 100 140 3 🚄 Stir Rate 🛠 🚄 Temperature 🛠 15 8 +++++ 2 120 180 6 Concentration \* Percent Reacted \*

Figure 4.22 The Design Data Table

The name of the table is the design type that generated it. Run the Screening script to screen for active effects. The column called Pattern shows the pattern of low values denoted "-" and high values denoted "+". Pattern is especially useful as a label variable in plots.

### Create a Plackett-Burman design

The previous example shows an 8-run fractional factorial design for five continuous factors. But suppose you can afford 4 additional runs. First, repeat the steps shown in the previous sections. This time, use the Load Responses and Load Factors commands to define the design, as follows:

Select DOE > Screening Design.

- Select Load Responses from the red triangle menu on the Screening Design title bar. Navigate to the Design Experiment folder in the Sample Data installed with JMP and open the file called Reactor Response.jmp.
- Next, select Load Factors from red triangle menu on the Screening Design title bar. Navigate to the
  Design Experiment folder in the Sample Data installed with JMP and open the file called
  Reactor Factors.jmp.

These two commands complete the DOE screening dialog for you, with the correct response and factor names, goal and limits for the response, and the values for the factors.

4. Click **Continue** on the completed Screening design dialog to see the list of designs in Figure 4.23, and chose the Plackett-Burman, as shown.





Figure 4.23 Design List for 5-factor Plackett-Burman Screening Design

#### Click Continue.

After you select the model from the Design list, the outlines for modifying and evaluating the model appear. In the Custom designer, you have the ability to form any model effects you want. The Screening designer creates the design effects based on the design you choose. In particular, the full factorial with all two-factor interactions has no aliasing of the included interactions, as shown in Figure 4.24.

Figure 4.24 No aliasing of the included interactions



A complete discussion of the Design Evaluation options is found in Chapter 3, "Building Custom Designs." To continue with this example, do the following:

- 6. Choose **Sort Left to Right** in the Output Options panel.
- 7. Click **Make Table** to see the design runs shown in Figure 4.25.

Examine the data table and note the Pattern variable to see the arrangement of plus and minus signs that define the runs. This table is used in the analysis sections that follow.

▼ Plackett-Burman Design Plackett-Burman Pattern | Feed Rate | Catalyst | Stir Rate | Temperature | Concentration | Percent Reacted Screening 10 100 180 3 Model 2 --+--140 10 120 3 3 --+-+ 10 120 140 6 4 -+--+ 10 2 100 140 6 5 -+-++ 10 2 100 180 6 6 -+++-10 120 180 3 Columns (7/0) 7 +---+ 15 100 140 🔥 Pattern 🚑 8 +--+-15 100 180 3 🚄 Feed Rate 🛠 9 +-+++ 15 120 180 6 🚄 Catalyst 🗱 10 ++---15 2 100 140 3 🚄 Stir Rate 🗱 11 +++--15 2 120 140 3 🚄 Temperature 🛪 15 6 🚄 Concentration 🛠 12 +++++ 120 180 🕯 Percent Reacted 🗱

Figure 4.25 Listing of a 5-factor Placket-Burman Design Table

### **Analysis of Screening Data**


After creating and viewing the data table, you can now run analyses on the data. As an example, open the data table called Plackett-Burman.jmp, found in Design Experiment folder in the Sample Data installed with JMP. This table contains the design runs and the Percent Reacted experimental results for the 12-run Plackett-burman design created in the previous section.

### **Using the Screening Analysis Platform**

The data table has two scripts called **Screening** and **Model**, showing in the upper-left corner of the table, that were created by the DOE Screening designer. You can use these scripts to analyze the data, however it is simple to run the analyses yourself.


Select Analyze > Modeling > Screening to see the completed launch dialog shown in Figure 4.26.
When you create a DOE design table, the variable roles are saved with the data table and used by the launch platform to complete the dialog.

Figure 4.26 Launch Dialog for the Screening Platform




2. Click **OK** to see the Screening platform result shown in Figure 4.27.

The Contrasts section of the Screening platform results lists all possible model effects, a contrast value for each effect, Lenth *t*-ratios (calculated as the contrast value divided by the Lenth PSE (pseudo-standard error), individual and simultaneous *p*-values, and aliases if there are any. Significant and marginally significant effects are highlighted. See the chapter on analyzing Screening designs in the *Modeling and Multivariate Methods* book for complete documentation of the Screening analysis platform.



Analysis of Screening Data



3. Examine the Half Normal plot in Figure 4.27.

### **Using the Fit Model Platform**

The Make Model button beneath the Half Normal Plot creates a Fit Model dialog that includes all the highlighted effects. However, note that the Catalyst\*Stir Rate interaction is highlighted, but the Stir Rate main effect is not. Therefore, that interaction shouldn't be in the model.

- 4. Click the Make Model Button beneath the Half Normal Plot.
- 5. Highlight the Catalyst\*Stir Rate interaction and click **Remove** on the Fit Model dialog. The dialog is shown in Figure 4.28.
- 6. Then click **Run** to see the analysis results.

Select Columns Pick Role Variables Personality: Standard Least Squares ♣Pattern Percent Reacted Emphasis: Effect Leverage Feed Rate optional Catalyst ■Stir Rate Help Run Weight optional numeric Temperature ▲Concentration Recall Keep dialog open optional numeric Percent Reacted Remove Ву optional Construct Model Effects Catalyst Add Temperature Cross Catalyst\*Temperature Nest Macros ▼ 2

Figure 4.28 Create Fit Model Dialog and Remove Unwanted Effect


#### The Actual-by-Predicted Plot

The Whole Model actual-by-predicted plot, shown in Figure 4.29, appears at the top of the Fit Model report. You see at a glance that this model fits well. The blue line falls outside the bounds of the 95% confidence curves (red-dotted lines), which tells you the model is significant. The model p-value (p = 0.0178),  $R^2$ , and RMSE appear below the plot. The RMSE is an estimate of the standard deviation of the process noise, assuming that the unestimated effects are negligible.

Figure 4.29 An Actual-by-Predicted Plot

Degree 2
Attributes ▼
Transform ▼


No Intercept



### The Scaled Estimates Report

To see a scaled estimates report, use **Effect Screening** > **Scaled Estimates** found in the red triangle menu on the **Response Percent Reacted** title bar. When there are quadratic or polynomial effects, the coefficients and the tests for them are more meaningful if effects are scaled and coded. The Scaled Estimates report includes a bar chart of the individual effects embedded in a table of parameter estimates. The last column of the table has the *p*-values for each effect.

Figure 4.30 Example of a Scaled Estimates Report




#### A Power Analysis

The Fit Model report has outline nodes for the Catalyst and Temperature effects. To run a power analysis for an effect, click the red triangle icon on its title bar and select **Power Analysis**.

This example shows a power analysis for the Catalyst variable, using default value for  $\alpha$  (0.05), the root mean square error and parameter estimate for Catalyst, for a sample size of 12. The resulting power is 0.802, which means that in similar experiments, you can expect an 89% chance of detecting a significant effect for Catalyst.

Figure 4.31 Example of a Power Analysis



Refer to *Modeling and Multivariate Methods* for details.

# **Response Surface Designs**



Response surface designs are useful for modeling a curved quadratic surface to continuous factors. A response surface model can pinpoint a minimum or maximum response, if one exists inside the factor region. Three distinct values for each factor are necessary to fit a quadratic function, so the standard two-level designs cannot fit curved surfaces.

The most popular response surface design is the central composite design, illustrated in the figure to the left below. It combines a two-level fractional factorial and two other kinds of points:

- Center points, for which all the factor values are at the zero (or midrange) value.
- Axial (or star) points, for which all but one factor are set at zero (midrange) and that one factor is set at outer (axial) values.

The Box-Behnken design, illustrated in the figure on the right below, is an alternative to central composite designs. One distinguishing feature of the Box-Behnken design is that there are only three levels per factor.

Another important difference between the two design types is that the Box-Behnken design has no points at the vertices of the cube defined by the ranges of the factors. This is sometimes useful when it is desirable to avoid these points due to engineering considerations. The price of this characteristic is the higher uncertainty of prediction near the vertices compared to the central composite design.

Figure 5.1 Response Surface Designs

Central Composite Design

Box-Behnken Design

fractional factorial points

axial points

center points

# **Contents**


A Box-Behnken Design: The Tennis Ball Example	29
The Prediction Profiler	32
A Response Surface Plot (Contour Profiler)	34
Geometry of a Box-Behnken Design	36
Creating a Response Surface Design	36
Enter Responses and Factors	37
Choose a Design	38
Specify Output Options	39
View the Design Table	40

## A Box-Behnken Design: The Tennis Ball Example

The Bounce Data.jmp sample data file has response surface data inspired by the tire tread data described in Derringer and Suich (1980). The objective of this experiment is to match a standardized target value (450) of tennis ball bounciness. The bounciness varies with amounts of Silica, Silane, and Sulfur used to manufacture the tennis balls. The experimenter wants to collect data over a wide range of values for these variables to see if a response surface can find a combination of factors that matches a specified bounce target. To follow this example:


- Select DOE > Response Surface Design.
- Load factors by clicking the red triangle icon on the Response Surface Design title bar and selecting Load Factors. Navigate to the Sample Data folder installed with JMP, and open Bounce Factors.jmp from the Design Experiment folder.
- 3. Load the responses by clicking the red triangle icon on the Response Surface Design title bar and selecting Load Responses. Navigate to the Sample Data folder, and open Bounce Response.jmp from the Design Experiment folder. Figure 5.2 shows the completed Response panel and Factors panel.

Figure 5.2 Response and Factors For Bounce Data



After the response data and factors data are loaded, the Response Surface Design Choice dialog lists the designs in Figure 5.3. (Click **Continue** to see the choices on the right.)

Figure 5.3 Response Surface Design Selection



130

The Box-Behnken design selected for three effects generates the design table of 15 runs shown in Figure 5.4.

In real life, you would conduct the experiment and then enter the responses into the data table. Suppose you completed the experiment and the final data table is Bounce Data.jmp.

1. Open Bounce Data.jmp from the Design Experiment folder found in the sample data installed with JMP (Figure 5.4).

Bounce Data ◉ Box-Behnken Pattern Silica Sulfur Silane Stretch Design ■ Model 1 --0 0.7 1.8 50 570 2 -+0 0.7 2.8 50 285 Columns (5/0) 3 +-0 1.7 1.8 50 260 u Pattern 🕮 4 ++0 1.7 2.8 50 433 Silica \* 5 0--1.2 1.8 40 422 Sulfur \* 6 0-+ 1.2 1.8 60 351 🚄 Silane 🛠 7 0+-1.2 2.8 40 278 🚄 Stretch 🛠 8 0++ 1.2 2.8 60 392 Rows 9 -0-0.7 40 2.3 451 15 All rows 10 +0-1.7 2.3 40 372 Selected 0 0.7 2.3 474 11 -0+ 60 Excluded 0 12 +0+ 1.7 2.3 60 394 Hidden 0 13 000 1.2 2.3 50 398 0 Labelled 14 000 1.2 2.3 50 394

15 000

Figure 5.4 JMP Table for a Three-Factor Box-Behnken Design

After opening the Bounce Data.jmp data table, run a fit model analysis on the data. The data table contains a script labeled **Model**, showing in the upper left panel of the table.

Click the red triangle next to Model and select Run Script to start a fit model analysis.

2.3

1.2

3. When the Fit Model dialog appears, click Run.

The standard Fit Model analysis results appear in tables shown in Figure 5.5, with parameter estimates for all response surface and crossed effects in the model.

The prediction model is highly significant with no evidence of lack of fit. All main effect terms are significant as well as the two interaction effects involving Sulfur.

✓ Response Stretch Parameter Estimates ■ Effect Tests ■ Summary of Fit
 ■ **RSquare** 0.999777 Sum of RSquare Adj 0.999375 Source Nparm DF Squares F Ratio Prob > F <.0001\* Root Mean Square Error 1.987461 Silica(0.7,1.7) 1 12880.125 3260.791 1 Mean of Response 391.3333 Silane(40,60) 1 1 968.000 245.0633 <.0001\* Observations (or Sum Wgts) 15 Sulfur(1.8,2.8) 1 1 5778.125 1462.816 <.0001\* Silane\*Silica 0.250 0.0633 0.8114 1 △ Analysis of Variance Sulfur\*Silica 1 1 52441.000 13276.20 <.0001\* Sum of Sulfur\*Silane 1 1 8556.250 2166.139 <.0001\* Source Squares Mean Square F Ratio 1 2592.923 656.4362 Silica\*Silica 1 < 0001\* Model 9 88453.583 9828.18 2488.146 Silane\*Silane 1 1 0.231 0.0584 0.8186 3.95 Prob > F Error 5 19 750 Sulfur\*Sulfur 1 1 4653.231 1178.033 <.0001\* C. Total 14 88473.333 <.0001\* △ Lack Of Fit Sum of F Ratio Source Squares Mean Square 0.9792 Lack Of Fit 3 11.750000 3.91667 Prob > F Pure Error 2 8.000000 4.00000 0.5411 Total Error 5 19.750000 Max RSq 0.9999

Figure 5.5 JMP Statistical Reports for a Response Surface Analysis of Bounce Data

See *Modeling and Multivariate Methods* for more information about interpretation of the tables in Figure 5.5.


**Note:** DOE response surface designs are available for up to eight factors only. In the DOE Response Surface Design platform, an error message is generated if more than eight factors are specified with a response surface design. Response surface designs with more than eight factors can be generated using **DOE** > **Custom Design**, where either a D-optimal or an I-optimal design can be specified. See "Creating Response Surface Experiments," p. 34 OF *JMP Design of Experiments* for how to use the custom designer to create response surface designs. Curvature analysis is not shown (no error or warning message is given) for response surface designs of more than 20 factors when using the custom designer or the Fit Model platform; all other analyses are valid and are shown.

The Response Surface report also has the tables shown in Figure 5.6.

132

A Box-Behnken Design: The Tennis Ball Example

Figure 5.6 Statistical Reports for a Response Surface Analysis



The Response Surface report shows a summary of the parameter estimates.

The Solution report lists the critical values of the surface factors and tells the kind of solution (maximum, minimum, or saddle point). The solution for this example is a saddle point. The table also warns that the critical values given by the solution are outside the range of data values.

The Canonical Curvature report shows eigenvalues and eigenvectors of the effects. The eigenvector values show that the dominant negative curvature (yielding a maximum) is mostly in the Sulfur direction. The dominant positive curvature (yielding a minimum) is mostly in the Silica direction. This is confirmed by the prediction profiler in Figure 5.8.

See Modeling and Multivariate Methods for details about the response surface analysis tables in Figure 5.6.

#### The Prediction Profiler

Next, use the response Prediction Profiler to get a closer look at the response surface and help find the settings that produce the best response target. The Prediction Profiler is a way to interactively change variables and look at the effects on the predicted response.

1. If the Prediction Profiler is not already open, click the red triangle on the Response Stretch title bar and select Factor Profiling > Profiler.


The first three plots in the top row of plots in the Prediction Profiler (Figure 5.7) display prediction traces for each x variable. A prediction trace is the predicted response as one variable is changed while the others are held constant at the current values (Jones 1991).

The current predicted value of Stretch, 396, is based on the default factor setting. It is represented by the horizontal dotted line that shows slightly below the desirability function target value (Figure 5.7). The

profiler shows desirability settings for the factors Silica, Silane, and Sulfur that give a value for Stretch of 396, which is quite different from the specified target of 450.

The bottom row has a plot for each factor, showing its *desirability trace*. The profiler also contains a Desirability column, which graphs desirability on a scale from 0 to 1 and has an adjustable desirability function for each  $\gamma$  variable. The overall desirability measure is on the left of the desirability traces.

Figure 5.7 The Prediction Profiler




2. To adjust the prediction traces of the factors and find a Stretch value that is closer to the target, click the red triangle on the Prediction Profiler title bar and select Maximize Desirability. This command adjusts the profile traces to produce the response value closest to the specified target (the target given by the desirability function). The range of acceptable values is determined by the positions of the upper and lower handles.

Figure 5.8 shows the result of the most desirable settings. Changing the settings of Silica from 1.2 to 1.7, Silane from 50 to 54, and Sulfur from 2.3 to 2.8 raised the predicted response from 396 to the target value of 450. Finding maximum desirability is an iterative process so your results may differ slightly from those shown below.

134

A Box-Behnken Design: The Tennis Ball Example

Figure 5.8 Prediction Profiler with Maximum Desirability Set for a Response Surface Analysis



See Modeling and Multivariate Methods for further discussion of the Prediction Profiler.


#### A Response Surface Plot (Contour Profiler)

Another way to look at the response surface is to use the Contour Profiler. Click the red triangle on the Response Stretch title bar and select Factor Profiling > Contour Profiler to display the interactive contour profiler, as shown in Figure 5.9.

The contour profiler is useful for viewing response surfaces graphically, especially when there are multiple responses. This example shows the profile to Silica and Sulfur for a fixed value of Silane.


Options on the Contour Profiler title bar can be used to set the grid density, request a surface plot (mesh plot), and add contours at specified intervals, like those shown in the contour plot in Figure 5.9. The sliders for each factor set values for Current X and Current Y.

Figure 5.9 Contour Profiler for a Response Surface Analysis



Enter the Lo limit and Hi limit values to shade the unacceptable regions in the contour plot

Figure 5.10 Contour Profiler with High and Low Limits



The Prediction Profiler and the Contour Profiler are discussed in more detail in *Modeling and Multivariate Methods*.

#### Geometry of a Box-Behnken Design

The geometric structure of a design with three effects is seen by using the Scatterplot 3D platform. The plot shown in Figure 5.11 illustrates the three Box-Behnken design columns. You can clearly see the center points and the 12 points midway between the vertices. For details on how to use the Scatterplot 3D platform, see *Basic Analysis and Graphing*.




Figure 5.11 Scatterplot 3D Rendition of a Box-Behnken Design for Three Effects

## **Creating a Response Surface Design**

Response Surface Methodology (RSM) is an experimental technique invented to find the optimal response within specified ranges of the factors. These designs are capable of fitting a second-order prediction equation for the response. The quadratic terms in these equations model the curvature in the true response function. If a maximum or minimum exists inside the factor region, RSM can estimate it. In industrial applications, RSM designs usually involve a small number of factors. This is because the required number of runs increases dramatically with the number of factors. Using the response surface designer, you choose to use well-known RSM designs for two to eight continuous factors. Some of these designs also allow blocking.

Response surface designs are useful for modeling and analyzing curved surfaces.

To start a response surface design, select **DOE** > **Response Surface Design**, or click the **Response Surface Design** button on the JMP Starter **DOE** page. Then, follow the steps described in the following sections.


- "Enter Responses and Factors," p. 137
- "Choose a Design," p. 138
- "Specify Axial Value (Central Composite Designs Only)," p. 138
- "Specify Output Options," p. 139
- "View the Design Table," p. 140

#### **Enter Responses and Factors**

The steps for entering responses are the same in Screening Design, Space Filling Design, Mixture Design, Response Surface Design, Custom Design, and Full Factorial Design. These steps are outlined in "Enter Responses and Factors into the Custom Designer," p. 65

Factors in a response surface design can only be continuous. The Factors panel for a response surface design appears with two default continuous factors. To enter more factors, type the number you want in the Factors panel edit box and click **Add**, as shown in Figure 5.12.

Figure 5.12 Enter Factors into a Response Surface Design




Click **Continue** to proceed to the next step.

#### **Choose a Design**

Highlight the type of response surface design you want and click **Continue**. The next sections describe the types of response surface designs shown in Figure 5.13.

Figure 5.13 Choose a Design Type



#### Box-Behnken Designs

The Box-Behnken design has only three levels per factor and has no points at the vertices of the cube defined by the ranges of the factors. This is sometimes useful when it is desirable to avoid extreme points due to engineering considerations. The price of this characteristic is the higher uncertainty of prediction near the vertices compared to the central composite design.

#### Central Composite Designs


The response surface design list contains two types of central composite designs: *uniform precision* and *orthogonal*. These properties of central composite designs relate to the number of center points in the design and to the axial values:

- Uniform precision means that the number of center points is chosen so that the prediction variance near the center of the design space is very flat.
- For orthogonal designs, the number of center points is chosen so that the second order parameter estimates are minimally correlated with the other parameter estimates.

#### Specify Axial Value (Central Composite Designs Only)

When you select a central composite (CCD-Uniform Precision) design and then click **Continue**, you see the panel in Figure 5.14. It supplies default axial scaling information. Entering 1.0 in the text box instructs JMP to place the axial value on the face of the cube defined by the factors, which controls how far out the axial points are. You have the flexibility to enter the values you want to use.

Figure 5.14 Display and Modify the Central Composite Design



**Rotatable** makes the variance of prediction depend only on the scaled distance from the center of the design. This causes the axial points to be more extreme than the range of the factor. If this factor range cannot be practically achieved, it is recommended that you choose **On Face** or specify your own value.

**Orthogonal** makes the effects orthogonal in the analysis. This causes the axial points to be more extreme than the -1 or 1 representing the range of the factor. If this factor range cannot be practically achieved, it is recommended that you choose **On Face** or specify your own value.

**On Face** leaves the axial points at the end of the -1 and 1 ranges.

**User Specified** uses the value you enter in the Axial Value text box.

If you want to inscribe the design, click the box beside **Inscribe**. When checked, JMP rescales the whole design so that the axial points are at the low and high ends of the range (the axials are –1 and 1 and the factorials are shrunken based on that scaling).

### **Specify Output Options**

Use the Output Options panel to specify how you want the output data table to appear. When the options are specified the way you want them, click **Make Table**. Note that the example shown in Figure 5.15 is for a Box-Behnken design. The Box-Behnken design from the design list and the Output Options request 3 center points for a single replicate.

Figure 5.15 Select the Output Options

3 Factors		
Box-Behnken		
Display and Modify Design		
Design Evaluation		
Output Options		
Run Order:	Randomize	•
Make JMP Table from design p	olus	
Number of Center Points:	3	
Number of Replicates:	0	
Make Table		

Creating a Response Surface Design

Run Order provides a menu with options for designating the order you want the runs to appear in the data table when it is created. Menu choices are:

**Keep the Same** the rows (runs) in the output table will appear in the standard order.

**Sort Left to Right** the rows (runs) in the output table will appear sorted from left to right.

Randomize the rows (runs) in the output table will appear in a random order.

**Sort Right to Left** the rows (runs) in the output table will appear sorted from right to left.

**Randomize within Blocks** the rows (runs) in the output table will appear in random order within the blocks you set up.

Add additional points with options given by Make JMP Table from design plus:

Number of Center Points Specifies additional runs placed at the center points.

Number of Replicates Specify the number of times to replicate the entire design, including centerpoints. Type the number of times you want to replicate the design in the associated text box. One replicate doubles the number of runs.

### View the Design Table

Now you have a data table that outlines your experiment, as described in Figure 5.16.

• Box-Behnken Pattern X1 X2 ХЗ Design Box-Behnken ■ Model 1 +0+ 0 1 2 0+-0 1 -1 ▼ Columns (5/0) 3 -0+ -1 1 u Pattern 🕮 4 +0-1 0 -1 ✓ X1 ★ 5 0-+ 0 -1 1 ✓ X2 ★ 0 6 000 0 0 ✓ X3 ★ 7 0++ 0 1 1 ✓ Y \* 1 8 -+0 -1 0 9 000 0 0 0 Rows 0 0 10 000 0 All rows 15 1 0 11 ++0 1 Selected 0 12 0--0 -1 -1 Excluded 0 Hidden 0 13 -0--1 0 -1 Labelled 0 14 +-0 -1 15 --0 -1 -1 0

Figure 5.16 The Design Data Table

The name of the table is the design type that generated it.

Run the Model script to fit a model using the values in the design table.

The column called Pattern identifies the coding of the factors. It shows all the codings with "+" for high, "-" for low factor, "a" and "A" for low and high axial values, and "0" for midrange. Pattern is suitable to use as a label variable in plots because when you hover over a point in a plot of the factors, the pattern value

Creating a Response Surface Design

shows the factor coding of the point. The three rows whose values in the Pattern column are 000 are three center points.

The runs in the Pattern column are in the order you selected from the Run Order menu.

The Y column is for recording experimental results.

# Response Surface Designs Creating a Response Surface Design

142

Chapter 5

## **Full Factorial Designs**



A full factorial design contains all possible combinations of a set of factors. This is the most fool proof design approach, but it is also the most costly in experimental resources. The full factorial designer supports both continuous factors and categorical factors with up to nine levels.


In full factorial designs, you perform an experimental run at every combination of the factor levels. The sample size is the product of the numbers of levels of the factors. For example, a factorial experiment with a two-level factor, a three-level factor, and a four-level factor has  $2 \times 3 \times 4 = 24$  runs.

Factorial designs with only two-level factors have a sample size that is a power of two (specifically  $2^f$  where f is the number of factors). When there are three factors, the factorial design points are at the vertices of a cube as shown in the diagram below. For more factors, the design points are the vertices of a hypercube.

Full factorial designs are the most conservative of all design types. There is little scope for ambiguity when you are willing to try all combinations of the factor settings.

Unfortunately, the sample size grows exponentially in the number of factors, so full factorial designs are too expensive to run for most practical purposes.

Figure 6.1 Full Factorial Design



## **Contents**

he Five-Factor Reactor Example	145
Analyze the Reactor Data	146
reating a Factorial Design	151
Enter Responses and Factors	151
Select Output Options	152
Make the Table	152

## The Five-Factor Reactor Example


The following example, adapted from Meyer *et al.* (1996) and Box, Hunter, and Hunter (1978), shows a five-factor reactor example.

Previously, the screening designer was used to investigate the effects of five factors on the percent reaction of a chemical process (see "Screening Designs," p. 101). The factors (Feed Rate, Catalyst, Stir Rate, Temperature, and Concentration) are all two-level continuous factors. The next example studies the same system using a full factorial design.

- 1. Select **DOE** > Full Factorial Design.
- 2. Click the red triangle icon on the Full Factorial Design title bar and select Load Responses.
- 3. In the Sample Data folder (installed with JMP), open Reactor Response.jmp found in the Design Experiment folder.
- 4. Click the red triangle icon on the Full Factorial Design title bar and select **Load Factors**.
- 5. In the Sample Data folder (installed with JMP), open Reactor Factors.jmp found in the Design Experiment folder.

The completed dialog should look like the one shown in Figure 6.2.

Figure 6.2 Full Factorial Example Response and Factors Panels



6. Click Continue to see the Output Options panel. In the Output Options panel, select Sort Left to Right from the Run Order menu, as shown to the right. This command defines the order of runs as they will be in the final JMP design table. The Five-Factor Reactor Example



#### 7. Click Make Table.

The design data table (Figure 6.3) contains a run for every combination of high and low values for the five variables, which covers all combinations of five factors with two levels each. Since there are five variables, there are  $2^5$ =32 runs. Initially, the table has an empty Y column named Percent Reacted for entering response values when the experiment is complete.

To see the completed experiment and continue this example, open Reactor 32 Runs.jmp found in the Design Experiment Sample Data folder.

Reactor 32 Runs Percent Concentration Design 2x2x2x2x2 Factorial Pattern Feed Rate Catalyst Stir Rate Temperature Reacted Fit Model Columns (7/0) ---+-🔥 Pattern 🚑 Feed Rate \* 5 --+--🚄 Catalyst 🖈 6 --+-+ 🚄 Stir Rate 🛠 Temperature \* 7 --++-🚄 Concentration 🛠 8 --+++ 🚄 Percent Reacted 🖈 9 -+---10 -+--+ Rows All rows 12 -+-++ Selected 13 -++--Excluded 14 -++-+ Hidden 15 -+++-Labelled

Figure 6.3 Partial Listing of Reactor 32 Runs.jmp from the Sample Data Folder

#### **Analyze the Reactor Data**

Begin the analysis with a quick look at the response data before fitting the factorial model.

- 1. Select Analyze > Distribution.
- 2. Highlight Percent Reacted and click Y, Columns. Then click OK.
- 3. Click the red triangle icon on the Percent Reacted title bar and select **Normal Quantile Plot**. The results are shown in Figure 6.4.




Figure 6.4 Distribution of Response Variable for Reactor Data

This initial analysis shows some experimental runs with a very high percent reacted response.

Start the formal analysis with a stepwise regression. The data table has a script stored with it that automatically defines an analysis of the model with main effects and all two-factor interactions.

- 4. Click the red triangle icon next to the Fit Model script and select **Run Script**. The stepwise analysis begins with the Stepwise Regression Control panel shown in Figure 6.5.
- 5. Select P-value Threshold from the Stopping Rule list.
- 6. The probability to enter a factor (Prob to Enter) in the model should be 0.05.
- 7. The probability to remove a factor (Prob to Leave) should be 0.1.
- 8. A useful way to use the Stepwise platform is to check all the main effects in the Current Estimates table. However, make sure that the menu beside Direction in the Stepwise Regression Control panel specifies **Mixed** (see Figure 6.5).

Figure 6.5 Stepwise Control Panel



9. Check the boxes for the main effects of the factors as shown in Figure 6.6.

Figure 6.6 Starting Model For Stepwise Process

⊿(Cu	irrent l	Estimates					
Loci	kEntere	d Parameter	Estimate	nDF	SS	"F Ratio"	"Prob>F"
1	1	Intercept	65.5	1	0	0.000	1
	<b>V</b>	Feed Rate(10,15)	-0.6875	1	15.125	0.149	0.70282
	<b>J</b>	Catalyst(1,2)	9.75	1	3042	29.928	0.00001
	<b>V</b>	Stir Rate(100,120)	-0.3125	1	3.125	0.031	0.86217
	V	Temperature(140,180)	5.375	1	924.5	9.095	0.00566
	V	Concentration(3,6)	-3.125	1	312.5	3.074	0.09132
		Feed Rate*Catalyst	0	1	15.125	0.144	0.70763
		Feed Rate*Stir Rate	0	1	4.5	0.043	0.83807
		Feed Rate*Temperature	0	1	6.125	0.058	0.81153
		Feed Rate*Concentration	0	1	0.125	0.001	0.97284
		Catalyst*Stir Rate	0	1	6.125	0.058	0.81153
		Catalyst*Temperature	0	1	1404.5	28.357	1.61e-5
		Catalyst*Concentration	0	1	32	0.306	0.5848
		Temperature*Concentration	0	1	968	14.450	0.00082


#### 10. Click Go.


The mixed stepwise procedure removes insignificant main effects and adds important interactions. The end result is shown in Figure 6.7. Note that the Feed Rate and Stir Rate factors are no longer in the model.

Figure 6.7 Model After Mixed Stepwise Regression

⊿Cu	rrent	Estimates					
Lock	Entere	d Parameter	Estimate	nDF	SS	"F Ratio"	"Prob>F"
1	1	Intercept	65.5	1	0	0.000	1
		Feed Rate(10,15)	0	1	15.125	1.383	0.25064
	1	Catalyst(1,2)	9.75	2	4446.5	200.362	1.6e-16
		Stir Rate(100,120)	0	1	3.125	0.274	0.60543
	1	Temperature(140,180)	5.375	3	3297	99.043	2.4e-14
	<b>J</b>	Concentration(3,6)	-3.125	2	1280.5	57.700	2.7e-10
		Feed Rate*Catalyst	0	2	30.25	1.406	0.26469
		Feed Rate*Stir Rate	0	3	22.75	0.656	0.58722
		Feed Rate*Temperature	0	2	21.25	0.954	0.39927
		Feed Rate*Concentration	0	2	15.25	0.670	0.52116
		Catalyst*Stir Rate	0	2	9.25	0.397	0.67635
	<b>J</b>	Catalyst*Temperature	6.625	1	1404.5	126.575	1.7e-11
		Catalyst*Concentration	0	1	32	3.119	0.0896
	1	Temperature*Concentration	-5.5	1	968	87.237	8.6e-10

11. Click the **Make Model** button in the Stepwise Regression Control panel. The Model Specification window that appears is automatically set up with the appropriate effects (Figure 6.8).







#### 12. Click Run to see the analysis for a candidate prediction model (Figure 6.9).

The figure on the left in Figure 6.9 shows the actual by predicted plot for the model. The predicted model covers a range of predictions from 40% to 95% reacted. The size of the random noise as measured by the RMSE is only 3.3311%, which is more than an order of magnitude smaller than the range of predictions. This is strong evidence that the model has good predictive capability.

The figure on the right in Figure 6.9 shows a table of model coefficients and their standard errors (labeled Parameter Estimates). All effects selected by the stepwise process are highly significant.

Figure 6.9 Actual by Predicted Plot and Prediction Parameter Estimates Table






The factor Prediction Profiler also gives you a way to compare the factors and find optimal settings.

The Five-Factor Reactor Example

1. To open the Prediction Profiler, click the red triangle on the Response Percent Reacted title bar and select **Factor Profiling > Profiler**.


Figure 6.10 shows the profiler's initial display. The Prediction Profiler is discussed in more detail in the chapter "Response Surface Designs," p. 127, and in *Modeling and Multivariate Methods*.

Figure 6.10 Viewing the Profiler



2. Click the red triangle on the Prediction Profiler title bar and select **Maximize Desirability** to see the profiler in Figure 6.11.

Figure 6.11 Viewing the Prediction Profiles at the Optimum Settings



The goal is to maximize Percent Reacted. The reaction is unfeasible economically unless the Percent Reacted is above 90%. Percent Reacted increases from 65.5 at the center of the factor ranges to a predicted maximum of  $95.875 \pm 2.96$  at the most desirable settings. The best settings of all three factors are

at the ends of their ranges. Future experiments could investigate what happens as you continue moving further in this direction.

## **Creating a Factorial Design**

To start a full factorial design, select **DOE** > **Full Factorial Design**, or click the **Full Factorial Design** button on the JMP Starter **DOE** page. Then, follow the steps below:

- "Enter Responses and Factors," p. 151
- "Select Output Options," p. 152
- "Make the Table," p. 152


#### **Enter Responses and Factors**

The steps for entering responses are outlined in "Enter Responses and Factors into the Custom Designer," p. 65

The steps for entering factors in a full factorial design are unique to this design. To add factors, see Figure 6.12.

- 1. To enter factors, click either the **Continuous** button or the **Categorical** button and select a factor type, level 2 9.
- 2. Double-click to edit the factor name.
- 3. Click to enter values or change the level names.

Figure 6.12 Entering Factors in a Full Factorial Design



When you finish adding factors, click **Continue**.

## **Select Output Options**

152

Use the Output Options panel to specify how you want the output data table to appear, as illustrated in Figure 6.13:

Figure 6.13 Output Options Panel

2x3 Factorial Output Options	
Run Order:	Sort Left to Right ▼
Number of Runs:	6
Number of Center Points:	0
Number of Replicates:	0
Make Table	
Back	

Run Order gives options to designate the order you want the runs to appear in the data table when it is created. Choices are:

**Keep the Same** the rows (runs) in the output table will appear in the standard order.

**Sort Left to Right** the rows (runs) in the output table will appear sorted from left to right.

**Randomize** the rows (runs) in the output table will appear in a random order.

**Sort Right to Left** the rows (runs) in the output table will appear sorted from right to left.

Add additional points to the data table with these options:


**Number of Center Points** Specifies additional runs placed at the center of each continuous factor's range.

**Number of Replicates** Specify the number of times to replicate the entire design, including centerpoints. Type the number of times you want to replicate the design in the associated text box. One replicate doubles the number of runs.

#### Make the Table

When you click **Make Table**, the table shown in Figure 6.14 appears.

Figure 6.14 Factorial Design Table



The name of the table is the design type that generated it.

Run the Model script to fit a model using values in the design table.

Values in the Pattern column describe the run each row represents.

- For continuous factors, a plus sign represents high levels.
- For continuous factors, a minus sign represents low levels.
- Level numbers represent values of categorical factors.

154

## **Mixture Designs**



The mixture designer supports experiments with factors that are ingredients in a mixture. You can choose among several classical mixture design approaches, such as simplex, extreme vertices, and lattice. For the extreme vertices approach you can supply a set of linear inequality constraints limiting the geometry of the mixture factor space.


The properties of a mixture are almost always a function of the relative proportions of the ingredients rather than their absolute amounts. In experiments with mixtures, a factor's value is its proportion in the mixture, which falls between zero and one. The sum of the proportions in any mixture recipe is one (100%).

Designs for mixture experiments are fundamentally different from those for screening. Screening experiments are orthogonal. That is, over the course of an experiment, the setting of one factor varies independently of any other factor. Thus, the interpretation of screening experiments is relatively simple, because the effects of the factors on the response are separable.

With mixtures, it is impossible to vary one factor independently of all the others. When you change the proportion of one ingredient, the proportion of one or more other ingredients must also change to compensate. This simple fact has a profound effect on every aspect of experimentation with mixtures: the factor space, the design properties, and the interpretation of the results.

Because the proportions sum to one, mixture designs have an interesting geometry. The feasible region for the response in a mixture design takes the form of a simplex. For example, consider three factors in a 3-D graph. The plane where the sum of the three factors sum to one is a triangle-shaped slice. You can rotate the plane to see the triangle face-on and see the points in the form of a ternary plot.

Figure 7.1 Mixture Design



## Contents

Mixture Design Types	7
The Optimal Mixture Design	7
The Simplex Centroid Design15	8
Creating the Design	
The Simplex Lattice Design16	ī
The Extreme Vertices Design16	3
Creating the Design	4
The ABCD Design16	8
Creating Ternary Plots16	8
Fitting Mixture Designs	'I
A Chemical Mixture Example	Ί
Create the Design	4
A Ternary Plot of the Mixture Response Surface	

## **Mixture Design Types**

To create a mixture design, choose **DOE** > **Mixture Design**, enter the responses and factors into the initial mixture designer panel, and click **Continue**. You then see the Choose Mixture Design Type panel shown in Figure 7.2. Select one of the designs from the panel:

**Optimal** invokes the custom designer with all the mixture variables already defined.

**Simplex Centroid** lets you specify the degree to which the factor combinations are made.

**Simplex Lattice** lets you specify how many levels you want on each edge of the grid.

**Extreme Vertices** lets you specify linear constraints or restrict the upper and lower bounds to be within the 0 to 1 range.

**ABCD Design** generates a screening design for mixtures devised by Snee (1975).

Figure 7.2 Mixture Design Selection Dialog

Choose Mixture Des	ign Type
Optimal	Create a design tailored to meet specific requirements.
Simplex Centroid	Run each ingredient without mixing, then mix equal proportions of K ingredients at a time to the specified limit.
Simplex Lattice	Triangular grid.  Specify number of levels per factor:  of Levels  5
Extreme Vertices	Find the vertices of the simplex. Then add the mid-points of the edges and averages of vertices to the specified degree.
	Linear Constraint Add linear constraints on the relative proportions of ingredients. Click once for each constraint.
ABCD Design	A mixture design for factor screening.
Back	

After you select the design type, choose the number of runs in the Design Generation panel and click **Make Design**.

The following sections describe each mixture design type and show examples.

## The Optimal Mixture Design

The **Optimal** mixture design choice invokes the custom designer with the mixture variables entered into the response and factors panels. To create an optimal mixture design:

- Select DOE > Mixture Design.
- 2. Enter factors and responses. The steps for entering responses are outlined in "Enter Responses and Factors into the Custom Designer," p. 65.
- 3. After you enter responses and factors, click **Continue**.


The Simplex Centroid Design

- 4. Click **Optimal** on the Choose Mixture Design Type panel.
- 5. Add effects to the model using the instructions below.

#### Adding Effects to the Model

Initially, the Model panel lists only the main effects corresponding to the factors you entered, as shown in Figure 7.3.

Figure 7.3 The Model Panel



However, you can add factor interactions, specific crossed factor terms, powers, or Scheffe Cubic terms to the model.

- To add interaction terms to a model, click the Interactions button and select 2nd, 3rd, 4th, or 5th. For example, if you have factors X1 and X2, click Interactions > 2nd and X1\*X2 is added to the list of model effects.
- To add crossed effects to a model, highlight the factors and effects you want to cross and click the **Cross** button.
- To add powers of continuous factors to the model, click the Powers button and select 2nd, 3rd, 4th, or
- When you want a mixture model with third-degree polynomial terms, the **Scheffe Cubic** button provides a polynomial specification of the surface by adding terms of the form X1\*X2\*(X1-X2).

### The Simplex Centroid Design

A simplex centroid design of degree *k* with *n* factors is composed of mixture runs with

- all one factor
- all combinations of two factors at equal levels
- all combinations of three factors at equal levels
- and so on up to k factors at a time combined at k equal levels.


A center point run with equal amounts of all the ingredients is always included.

#### **Creating the Design**

To create a simplex centroid design:

- 1. Select **DOE** > **Mixture Design**.
- 2. Enter factors and responses. The steps for entering responses are outlined in "Enter Responses and Factors into the Custom Designer," p. 65.
- 3. After you enter responses and factors, click Continue.
- 4. Enter the number of ingredients in the box under **K**. JMP will create runs for each ingredient without mixing, then create runs that mix equal proportions of K ingredients at a time to the specified limit.
- 5. Click the **Simplex Centroid** button.
- 6. View factor settings and Output Options, as illustrated in Figure 7.4.

Figure 7.4 Example of Factor Settings and Output Options



7. Specify Run Order, which is the order you want the runs to appear in the data table when it is created. Run order choices are:

**Keep the Same** the rows (runs) in the output table will appear as they do in the Factor Settings panel.

**Sort Left to Right** the rows (runs) in the output table will appear sorted from left to right.

**Randomize** the rows (runs) in the output table will appear in a random order.

**Sort Right to Left** the rows (runs) in the output table will appear sorted from right to left.

**Randomize within Blocks** the rows (runs) in the output table will appear in random order within the blocks you set up.

8. Specify Number of Replicates. The number of replicates is the number of times to replicate the entire design, including centerpoints. Type the number of times you want to replicate the design in the associated text box. One replicate doubles the number of runs.


9. Click Make Table.

#### **Simplex Centroid Design Examples**

The table of runs for a design of degree 1 with three factors (left in Figure 7.5) shows runs for each single ingredient followed by the center point. The table of runs to the right is for three factors of degree 2. The first three runs are for each single ingredient, the second set shows each combination of two ingredients in equal parts, and the last run is the center point.

Figure 7.5 Three-Factor Simplex Centroid Designs of Degrees 1 and 2

Ru	n X1	X2	X3	Run	X1	X2	Х3
1	1	0	0	1	1	0	0
2	0	1	0	2	0	1	0
3	0	0	1	3	0	0	1
4	0.333	0.333	0.333	4	0.5	0.5	0
				5	0.5	0	0.5
				6	0	0.5	0.5
				7	0.333	0.333	0.333



To generate the two sets of runs in Figure 7.5:

- 1. Choose **DOE** > Mixture Design.
- 2. Enter three mixture factors.
- 3. Click Continue.
- 4. Enter 1 in the K box, and click Simplex Centroid to see the design on the left in Figure 7.6.
- 5. Click the **Back** button, then click **Continue**, and enter 2 in the **K** box. Then click **Simplex Centroid** to see the design on the right in Figure 7.6.

Figure 7.6 Create Simplex Centroid Designs of Degrees 1 and 2

△ Factor Settings									
Run	X1	X2	X3						
1	1.00000	0.00000	0.00000						
2	0.00000	1.00000	0.00000						
3	0.00000	0.00000	1.00000						
4	0.33333	0.33333	0.33333						

Factor	Settings		
Run	X1	X2	Х3
1	1.00000	0.00000	0.00000
2	0.00000	1.00000	0.00000
3	0.00000	0.00000	1.00000
4	0.50000	0.50000	0.00000
5	0.50000	0.00000	0.50000
6	0.00000	0.50000	0.50000
7	0.33333	0.33333	0.33333

As another example:

The Simplex Lattice Design

- Choose DOE > Mixture Design.
- 2. Enter five factors and click Continue.
- 3. Use the default value, 4, in the K box.
- 4. Click Simplex Centroid.
- 5. Click **Make Table** to see the 31-run JMP data table shown in Figure 7.7.

Figure 7.7 Partial Listing of Factor Settings for Five-Factor Simplex Centroid Design

Simplex Centroid	4 €						
Design Simplex Centroid	•	X1	X2	Х3	X4	X5	Υ
<b>▼</b> Model	1	0	0.5	0	0	0.5	•
	2	0.5	0	0	0	0.5	
	3	1	0	0	0	0	•
- 0 - t (0/0)	4	0.2	0.2	0.2	0.2	0.2	
▼ Columns (6/0)	5	0	0	1	0	0	
▲ X1 <b>*</b> ▲ X2 <b>*</b>	6	0	0.3333333333	0.3333333333	0	0.3333333333	
^2 <b>*</b> X3 <b>*</b>	7	0.25	0	0.25	0.25	0.25	
✓ X4 <b>*</b>	8	0	0	0.5	0	0.5	
∡ x5 <b>*</b>	9	0.5	0	0.5	0	0	
<b>⊿</b> Y <b>≭</b>	10	0.3333333333	0.3333333333	0.333333333	0	0	
	11	0.3333333333	0	0.3333333333	0	0.3333333333	
<b>▼</b> Rows	12	0.25	0.25	0	0.25	0.25	•
All rows 31	13	0.5	0.5	0	0	0	
Selected 0	14	0.25	0.25	0.25	0	0.25	
Excluded 0	15	0.3333333333	0.3333333333	0	0	0.3333333333	•
Hidden 0	16	0.3333333333	0	0.3333333333	0.3333333333	0	•
Labelled 0		0	0	0	0.5	0.5	

## The Simplex Lattice Design

The simplex lattice design is a space filling design that creates a triangular grid of runs. The design is the set of all combinations where the factors' values are  $i \mid m$ , where i is an integer from 0 to m such that the sum of the factors is 1.

To create simplex lattice designs:

- 1. Select **DOE** > **Mixture Design**.
- 2. Enter factors and responses. The steps for entering responses are outlined in "Enter Responses and Factors into the Custom Designer," p. 65.
- 3. Click Continue.
- 4. Specify the number of levels you want in the Mixture Design Type dialog (Figure 7.2) and click **Simplex Lattice**.

Figure 7.8 shows the runs for three-factor simplex lattice designs of degrees 3, 4, and 5, with their corresponding geometric representations. In contrast to the simplex centroid design, the simplex lattice design does not necessarily include the centroid.

The Simplex Lattice Design

Figure 7.8 Three-Factor Simplex Lattice Designs for Factor Levels 3, 4, and 5

Factor	Settings			⊿ Factor	Settings			⊿ Factor	Settings		
Run	X1	X2	Х3	Run	X1	X2	Х3	Run	X1	X2	Х3
1	0.00000	0.00000	1.00000	1	0.00000	0.00000	1.00000	1	0.00000	0.00000	1.00000
2	0.00000	0.33333	0.66667	2	0.00000	0.25000	0.75000	2	0.00000	0.20000	0.80000
3	0.00000	0.66667	0.33333	3	0.00000	0.50000	0.50000	3	0.00000	0.40000	0.60000
4	0.00000	1.00000	0.00000	4	0.00000	0.75000	0.25000	4	0.00000	0.60000	0.40000
5	0.33333	0.00000	0.66667	5	0.00000	1.00000	0.00000	5	0.00000	0.80000	0.20000
6	0.33333	0.33333	0.33333	6	0.25000	0.00000	0.75000	6	0.00000	1.00000	0.00000
7	0.33333	0.66667	0.00000	7	0.25000	0.25000	0.50000	7	0.20000	0.00000	0.80000
8	0.66667	0.00000	0.33333	8	0.25000	0.50000	0.25000	8	0.20000	0.20000	0.60000
9	0.66667	0.33333	0.00000	9	0.25000	0.75000	0.00000	9	0.20000	0.40000	0.40000
10	1.00000	0.00000	0.00000	10	0.50000	0.00000	0.50000	10	0.20000	0.60000	0.20000
				11	0.50000	0.25000	0.25000	11	0.20000	0.80000	0.00000
	4	$\supset$		12	0.50000	0.50000	0.00000	12	0.40000	0.00000	0.60000
	•			13	0.75000	0.00000	0.25000	13	0.40000	0.20000	0.40000
				14	0.75000	0.25000	0.00000	14	0.40000	0.40000	0.20000
		•		15	1.00000	0.00000	0.00000	15	0.40000	0.60000	0.00000
	ــــــــــــــــــــــــــــــــــــــ							16	0.60000	0.00000	0.40000
	<i>C</i>				<del>4-</del>			17	0.60000	0.20000	0.20000
					:•			18	0.60000	0.40000	0.00000
						:.		19	0.80000	0.00000	0.20000
					= =			20	0.80000	0.20000	0.00000
								21	1.00000	0.00000	0.00000

Figure 7.9 lists the runs for a simplex lattice of degree 3 for five effects. In the five-level example, the runs creep across the hyper-triangular region and fill the space in a grid-like manner.

X1 X5 Run X2 X3 X4 0.00000 0.00000 0.00000 0.00000 1.00000 0.00000 0.00000 0.00000 0.33333 0.66667 0.00000 0.00000 0.00000 0.66667 0.33333 0.00000 0.00000 0.00000 1.00000 0.00000 0.00000 0.00000 0.33333 0.00000 0.00000 0.00000 0.33333 0.33333 0.33333 0.66667 0.00000 0.00000 0.66667 0.00000 0.333333 0.00000 0.00000 0.66667 0.33333 n nnnnn 10 0.00000 0.00000 1.00000 0.00000 0.00000 0.00000 0.33333 0.00000 0.00000 0.66667 0.00000 0.00000 0.33333 0.33333 0.33333 13 0.00000 0.33333 0.00000 0.66667 0.00000 0.00000 0.33333 0.33333 0.00000 U 33333 15 0.00000 0.33333 0.33333 0.33333 0.00000 0.00000 0.33333 0.66667 0.00000 0.00000 17 0.00000 0.66667 0.00000 0.00000 0.33333 0.00000 0.66667 0.00000 0.33333 0.00000 0.00000 0.66667 0.33333 0.00000 0.00000 0.00000 1.00000 0.00000 0.00000 0.00000 0.00000 0.00000 0.33333 0.00000 0.33333 0.33333 0.33333 0.00000 0.00000 0.66667 0.00000 0.33333 0.33333 0.00000 0.33333 0.00000 0.33333 0.00000 0.33333 0.33333 0.00000 0.33333 0.00000 0.66667 0.00000 0.00000 0.33333 0.33333 0.00000 0.00000 0.33333 0.33333 0.00000 0.00000 0.33333 0.33333 0.33333 0.33333 0.33333 0.00000 0.00000 0.33333 0.66667 0.00000 0.00000 0.00000 0.66667 0.00000 0.00000 0.00000 0.33333 0.66667 0.00000 0.00000 0.33333 0.00000 0.66667 0.00000 0.33333 0.00000 0.00000 0.66667 0.33333 0.00000 0.00000 0.00000 1.00000 0.00000 0.00000 0.00000

Figure 7.9 JMP Design Table for Simplex Lattice with Five Variables, Order (Degree) 3

### The Extreme Vertices Design

The extreme vertices design accounts for factor limits and selects vertices and their averages (formed by factor limits) as design points. Additional limits are usually in the form of range constraints, upper bounds, and lower bounds on the factor values.

The extreme vertices design finds the corners (vertices) of a factor space constrained by limits specified for one or more of the factors. The property that the factors must be non-negative and must add up to one is the basic mixture constraint that makes a triangular-shaped region.

Sometimes other ingredients need range constraints that confine their values to be greater than a lower bound or less than an upper bound. Range constraints chop off parts of the triangular-shaped (simplex) region to make additional vertices. It is also possible to have a linear constraint, which defines a linear combination of factors to be greater or smaller than some constant.

The geometric shape of a region bound by linear constraints is called a simplex, and because the vertices represent extreme conditions of the operating environment, they are often the best places to use as design points in an experiment.

You usually want to add points between the vertices. The average of points that share a constraint boundary is called a *centroid* point, and centroid points of various degrees can be added. The centroid point for two

The Extreme Vertices Design

neighboring vertices joined by a line is a second degree centroid because a line is two dimensional. The centroid point for vertices sharing a plane is a third degree centroid because a plane is three dimensional, and so on.

If you specify an extreme vertices design but give no constraints, a simplex centroid design results.

#### Creating the Design

Follow these steps to create an extreme vertices design. The next sections show examples with specific constraints.

- 1. Select **DOE** > **Mixture Design**.
- 2. Enter factors and responses. These steps are outlined in "Enter Responses and Factors into the Custom Designer," p. 65. Remember to enter the upper and lower limits in the factors panel (see Figure 7.10).
- 3. Click Continue.
- 4. In the **Degree** text box, enter the degree of the centroid point you want to add. The centroid point is the average of points that share a constraint boundary.
- 5. If you have linear constraints, click the **Linear Constraints** button for each constraint you want to add. Use the text boxes that appear to define a linear combination of factors to be greater or smaller than some constant.
- 6. Click **Extreme Vertices** to see the factor settings.
- 7. (Optional) Change the order of the runs in the data table when it is created. Run order choices are:

Keep the Same—the rows (runs) in the output table will appear as they do in the Design panel.

**Sort Left to Right**—the rows (runs) in the output table will appear sorted from left to right.

**Randomize**—the rows (runs) in the output table will appear in a random order.

Sort Right to Left—the rows (runs) in the output table will appear sorted from right to left.

Randomize within Blocks—the rows (runs) in the output table will appear in random order within the blocks you set up.

- 8. (Optional) Type the sample size you want in the Choose desired sample size text box.
- 9. (Optional) Click **Find Subset** to generate the optimal subset having the number of runs specified in sample size box described in Step 8. The **Find Subset** option uses the row exchange method (not coordinate exchange) to find the optimal subset of rows.
- 10. Click Make Table.


#### **An Extreme Vertices Example with Range Constraints**

The following example design table is for five factors with the range constraints shown in Figure 7.10, where the ranges are smaller than the default 0 to 1 range.

- 1. Select **DOE > Mixture Design**.
- 2. Add two additional factors (for a total of 5 factors) and give them the values shown in Figure 7.10.
- 3. Click Continue.

4. Enter '4' in the **Degree** text box (Figure 7.10).

Figure 7.10 Example of Five-factor Extreme Vertices



- 5. Click Extreme Vertices.
- 6. Select Sort Left to Right from the Run Order menu.
- 7. Click **Make Table**. Figure 7.11 shows a partial listing of the resulting table. Note that the Rows panel in the data table shows that the table has the default 116 runs.

Figure 7.11 JMP Design Table for Extreme Vertices with Range Constraints

■ Extreme Vertices	4						
Design Extreme Vertices	•	X1	X2	X3	X4	<b>X</b> 5	Υ
▼ Model	1	0.05	0.1	0.2	0.4	0.25	
	2	0.05	0.1	0.25	0.4	0.2	•
Columns (6/0)	3	0.05	0.1	0.3	0.4	0.15	•
▲ X1 *	4	0.05	0.1	0.2666666667	0.3666666667	0.2166666667	
∠ X2 ★	5	0.05	0.15	0.15	0.4	0.25	•
<b>4</b> X3 <b>★</b>	6	0.05	0.15	0.3	0.4	0.1	•
▲ X4 <b>*</b>	7	0.05	0.2	0.1	0.4	0.25	
<b>4</b> X5 <b>*</b> <b>4</b> Y <b>*</b>	8	0.05	0.2	0.2	0.4	0.15	•
<b>4</b> 1 <b>4</b>	9	0.05	0.2	0.3	0.4	0.05	•
	10	0.05	0.25	0.1	0.4	0.2	
Rows	11	0.05	0.25	0.25	0.4	0.05	•
All rows 116	12	0.05	0.2666666667	0.1	0.3666666667	0.2166666667	•
Selected 0	13	0.05	0.2666666667	0.2666666667	0.3666666667	0.05	•
Excluded 0 Hidden 0	14	0.05	0.3	0.1	0.4	0.15	•
Labelled 0	15	0.05	0.3	0.15	0.4	0.1	•
- Capping o	16	0.05	0.3	0.2	0.4	0.05	

166

Chapter 7

The Extreme Vertices Design

Suppose you want fewer runs. You can go back and enter a different sample size (number of runs).

- 8. Click Back, then click Continue.
- 9. Enter '4' in the **Degree** text box and click **Extreme Vertices**.
- 10. In the sample size text box, enter '10' as the sample size.
- 11. Click **Find Subset** to generate the optimal subset having the number of runs specified. The resulting design (Figure 7.12) is the optimal 10-run subset of the 116 current runs. This is useful when the extreme vertices design generates a large number of vertices.

Extreme Vertices 2 X1 **X**3 X4 **X**5 Design Extreme Vertices X2 ▼ Model 0.05 0.3 0.2 0.4 0.05 2 0.3 0.25 0.05 0.1 0.3 Columns (6/0) 3 0.05 0.3 0.3 0.1 0.25 🚄 X1 🗱 0.05 0.3 0.1 0.3 0.25 ∠ X2 ★ 0.3 0.4 0.15 0.1 0.05 🚄 X3 🖈 0.25 0.1 0.3 0.1 0.25 🚄 X4 🖈 0.25 0.1 0.1 0.3 0.25 🚄 X5 🖈 0.25 0.2 0.1 0.4 0.05 8 ▲Y\* 9 0.25 0.3 0.1 0.1 0.25 Rows 10 0.25 0.3 0.3 0.1 0.05 10 All rows Selected 0 0 Excluded Hidden 0 0 Labelled

Figure 7.12 JMP Design Table for 10-Run Subset of the 116 Current Runs

**Note:** The **Find Subset** option uses the row exchange method (not coordinate exchange) to find the optimal subset of rows.

#### An Extreme Vertices Example with Linear Constraints


Consider the classic example presented by Snee (1979) and Piepel (1988). This example has three factors, X1, X2, and X3, with five individual factor bound constraints and three additional linear constraints:


Table 7.1 Linear Constraints for the Snee and Piepel Example

$X1 \geq 0.1$	$90 \le 85*X1 + 90*X2 + 100*X3$
$X1 \leq 0.5$	$85*X1 + 90*X2 + 100*X3 \le 95$ .4 \le 0.7*X1 + X3
X2 ≥ 0.1	
$X2 \leq 0.7$	
X3 ≤ 0.7	

To enter these constraints:

- 1. Enter the upper and lower limits in the factors panel.
- Click Continue.
- 3. Click the **Linear Constraint** button three times. Enter the constraints as shown in Figure 7.13.
- 4. Click the Extreme Vertices button.
- 5. Change the run order to **Sort Right to Left,** and keep the sample size at 13. See Figure 7.13 for the default Factor Settings and completed Output Options.
- 6. Click Make Table.





This example is best understood by viewing the design as a ternary plot, as shown at the end of this chapter, in Figure 7.15. The ternary plot shows how close to one a given component is by how close it is to the vertex of that variable in the triangle. See "Creating Ternary Plots," p. 168, for details.

#### **Extreme Vertices Method: How It Works**

If there are linear constraints, JMP uses the CONSIM algorithm developed by R.E. Wheeler, described in Snee (1979) and presented by Piepel (1988) as CONVRT. The method is also described in Cornell (1990, Appendix 10a). The method combines constraints and checks to see if vertices violate them. If so, it drops the vertices and calculates new ones. The method named CONAEV for doing centroid points is by Piepel (1988).

If there are no linear constraints (only range constraints), the extreme vertices design is constructed using the XVERT method developed by Snee and Marquardt (1974) and Snee (1975). After the vertices are found, a simplex centroid method generates combinations of vertices up to a specified order.

Chapter 7

The XVERT method first creates a full  $2^{nf-1}$  design using the given low and high values of the nf-1 factors with smallest range. Then, it computes the value of the one factor left out based on the restriction that the factors' values must sum to one. It keeps the point if it is in that factor's range. If not, it increments or decrements it to bring it within range, and decrements or increments each of the other factors in turn by the same amount, keeping the points that still satisfy the initial restrictions.

The above algorithm creates the vertices of the feasible region in the simplex defined by the factor constraints. However, Snee (1975) has shown that it can also be useful to have the centroids of the edges and faces of the feasible region. A generalized n-dimensional face of the feasible region is defined by nf - n of the boundaries and the centroid of a face defined to be the average of the vertices lying on it. The algorithm generates all possible combinations of the boundary conditions and then averages over the vertices generated on the first step.

## The ABCD Design

This approach by Snee (1975) generates a screening design for mixtures. To create an ABCD design:

- 1. Select **DOE** > **Mixture Design**.
- 2. Enter factors and responses. The steps for entering responses are outlined in "Enter Responses and Factors into the Custom Designer," p. 65.
- 3. After you enter responses and factors, click Continue.
- 4. Click the **ABCD Design** button.
- 5. View factor settings and Output Options.
- 6. Specify Run Order, which is the order you want the runs to appear in the data table when it is created. Run order choices are:

**Keep the Same** The rows (runs) in the output table will appear as they do in the Factor Settings panel.

**Sort Left to Right** The rows (runs) in the output table will appear sorted from left to right.

**Randomize** The rows (runs) in the output table will appear in a random order.

**Sort Right to Left** The rows (runs) in the output table will appear sorted from right to left.

**Randomize within Blocks** The rows (runs) in the output table will appear in random order within the blocks you set up.


- 7. Specify Number of Replicates. The number of replicates is the number of times to replicate the entire design, including centerpoints. Type the number of times you want to replicate the design in the associated text box. One replicate doubles the number of runs.
- 8. Click Make Table.


### **Creating Ternary Plots**

A mixture problem in three components can be represented in two dimensions because the third component is a linear function of the others. The *ternary plot* in Figure 7.15 shows how close to one (1) a

given component is by how close it is to the vertex of that variable in the triangle. The plot to the left in Figure 7.14 illustrates a ternary plot.

Figure 7.14 Ternary Plot (left) and Tetrary Plot (right) for Mixture Design





The Piepel (1979) example referenced in "An Extreme Vertices Example with Linear Constraints," p. 166 is best understood by the ternary plot shown in Figure 7.15.

To view a mixture design as a ternary plot:

- 1. Create the Piepel mixture data as shown previously, or open the table called Peipel.jmp, found in the Design Experiments folder of the Sample Data Library.
- 2. Choose **Graph > Ternary Plot**.
- 3. In the ternary plot launch dialog, specify the three mixture components and click **OK**.

The JMP Ternary plot platform recognizes the three factors as mixture factors, and also considers the upper and lower constraints entered into the Factors panel when the design was created. The Ternary plot uses shading to exclude the unfeasible areas excluded by those constraints.

The Piepel data had additional constraints, entered as linear constraints for the extreme vertices design. There are six active constraints, six vertices, and six centroid points shown on the plot, as well as two inactive (redundant) constraints. The feasible area is the inner white polygon delimited by the design points and constraint lines.




Figure 7.15 Diagram of Ternary Plot Showing Piepel Example Constraints

### **Fitting Mixture Designs**

When fitting a model for mixture designs, you must take into account that all the factors add up to a constant, and thus a traditional full linear model will not be fully estimable.

The recommended response surface model, called the Scheffé polynomial (Scheffé 1958), does the following:

- suppresses the intercept
- includes all the linear main-effect terms
- excludes all the square terms (such as X1\*X1)
- includes all the cross terms (such as X1\*X2)

#### To fit a model:

- 1. Choose **DOE** > **Mixture Design** and make the design data table. Remember that to fit a model, the Y column in the data table must contain values, so either assign responses or click the red triangle menu and select **Simulate Responses** before you click **Make Table**.
- 2. The design data table stores the model in the data table as a table property. This table property is a JSL script called **Model**, located in the left panel of the table.
- 3. Right-click the model and select **Run Script** to launch the Fit Model dialog, which is automatically filled with the saved model.
- 4. Click **Run** on the Fit Model dialog.

In this model, the parameters are easy to interpret (Cornell 1990). The coefficients on the linear terms are the fitted response at the extreme points where the mixture consists of a single factor. The coefficients on the cross terms indicate the curvature across each edge of the factor space.

The model report usually has several sections of interest, including the whole model tests, Analysis of Variance reports, and response surface reports, which are described below.

#### Whole Model Tests and Analysis of Variance Reports

In a whole-model Analysis of Variance table, JMP traditionally tests that all the parameters are zero except for the intercept. In a mixture model without an intercept, JMP looks for a hidden intercept, in the sense that a linear combination of effects is a constant. If it finds a hidden intercept, it does the whole model test with respect to the intercept model rather than a zero-intercept model. This test is equivalent to testing that all the parameters are zero except the linear parameters, and testing that they are equal.

The hidden-intercept property also causes the R<sup>2</sup> to be reported with respect to the intercept model rather than reported as missing.

#### Understanding Response Surface Reports

When there are effects marked as response surface effects "&RS," JMP creates additional reports that analyze the fitted response surface. These reports were originally designed for full response surfaces, not mixture models. However, if JMP encounters a no-intercept model and finds a hidden intercept with linear response surface terms, but no square terms, then it *folds* its calculations, collapsing on the last response surface term to calculate critical values for the optimum. This can be done for any combination that yields a constant and involves the last response surface term.

### **A Chemical Mixture Example**

Three plasticizers (p1, p2, and p3) comprise 79.5% of the vinyl used for automobile seat covers (Cornell, 1990). Within this 79.5%, the individual plasticizers are restricted by the following constraints:  $0.409 \le x1 \le 0.849$ ,  $0 \le x2 \le 0.252$ , and  $0.151 \le x3 \le 0.274$ .


#### **Create the Design**

To create Cornell's mixture design in JMP:

- 1. Select **DOE** > **Mixture Design**.
- 2. In the Factors panel, use the three default factors but name them p1, p2, and p3, and enter the high and low constraints as shown in Figure 7.16. Or, load the factors with the **Load Factors** command in the red triangle on the Mixture Design title bar. To import the factors, open Plastifactors.jmp, found in the Design Experiment Sample Data folder that was installed with JMP.


172

Figure 7.16 Factors and Factor Constraints for the Plasticizer Experiment



- 3. Click Continue.
- 4. Enter 3 in the **Degree** text box.
- Click Extreme Vertices.
- 6. Click **Make Table**. JMP uses the 9 factor settings to generate a JMP table (Figure 7.17).

Figure 7.17 Extreme Vertices Mixture Design



7. Add an extra five design runs by duplicating the vertex points and center point, to give a total of 14 rows in the table.

**Note:** To identify the vertex points and the center (or interior) point, use the sample data script called LabelMixturePoints.jsl in the Sample Scripts folder installed with JMP.

8. Run the LabelMixturePoints.jsl to see the results in Figure 7.18, and highlight the vertex points and the interior point as shown.

Figure 7.18 Identify Vertices and Center Point with Sample Script

Extreme Vertices	4	•					
Design Extreme Vertices	•		p1	p2	р3	Υ	Point Type
▼ Model	•	1	0.849	0	0.151	•	Vertex
▼ Ternary Plot	•	2	0.6	0.126	0.274	•	Edge
Columns (5/0)		3	0.7875	0	0.2125	•	Edge
<b>⊿</b> p1 <b>*</b>	•	4	0.6615	0.126	0.2125	•	Interior
<b>⊿</b> p2 <b>≭</b>	•	5	0.726	0	0.274	•	Vertex
<b>⊿</b> p3 <b>≭</b>	•	6	0.474	0.252	0.274	•	Vertex
<b>△</b> Y <b>*</b>	•	7	0.5355	0.252	0.2125	•	Edge
🔥 Point Type 🚑	•	8	0.723	0.126	0.151	•	Edge
Rows	•	9	0.597	0.252	0.151	•	Vertex
All rows 9							
Selected 5							

- 9. Select **Edit > Copy**, to copy the selected rows to the clipboard.
- 10. Select **Rows > Add Rows** and type **5** as the number of rows to add.
- 11. Click the At End radio button on the dialog, then click **OK**.
- 12. Highlight the new rows and select **Edit > Paste** to add the duplicate rows to the table.

The Plasticizer data with the results (*Y* values) that Cornell obtained are available in the Sample data. Open Plasticizer.jmp in the Sample Data folder installed with JMP to see this table (Figure 7.19).

Figure 7.19 Plasticizer.jmp Data Table from the Sample Data Library

▼ Plasticizer	4	•						Pred
Design Extreme Vertices	•		p1	p2	р3	Υ	Point Type	Formula Y
▼ Model	•	1	0.474	0.252	0.274	12	Vertex	10.892307
▼ Ternary Plot	•	2	0.726	0	0.274	4	Vertex	5.0923076
▼ Columns (6/0)	•	3	0.849	0	0.151	8	Vertex	7.4923076
p1 <b>★</b> 0	•	4	0.597	0.252	0.151	13	Vertex	11.292307
<b>⊿</b> p2 <b>★</b> ③	•	5	0.6	0.126	0.274	13	Edge	13.030769
⊿ p3 <b>*</b> 3	•	6	0.6615	0.126	0.2125	18	Interior	19.269230
▲ Y 🗱 🕦	•	7	0.7875	0	0.2125	12	Edge	11.830769
🔥 Point Type 🚑	•	8	0.723	0.126	0.151	14	Edge	14.430769
✓ Pred Formula Y ♣	•	9	0.5355	0.252	0.2125	16	Edge	16.630769
Rows	•	10	0.474	0.252	0.274	10	Vertex	10.892307
All rows 14	•	11	0.726	0	0.274	6	Vertex	5.0923076
Selected 0	•	12	0.849	0	0.151	7	Vertex	7.4923076
Excluded 0	•	13	0.597	0.252	0.151	10	Vertex	11.292307
Hidden 0	•	14	0.6615	0.126	0.2125	21	Interior	19.269230
Labelled 0								

#### **Analyze the Mixture Model**

Use the Cornell plasticizer data from the Sample Data library (Figure 7.19) to run the mixture model:

- 1. Click the table property named Model on the upper-left of the data table and select **Run Script**, which runs a script that displays a completed Fit Model dialog. Click **Run** to see the response surface analysis.
- 2. Plasticizer.jmp contains a column called Pred Formula Y. This column was added after the analysis by selecting Save Columns > Prediction Formula from the red triangle menu in the Response Y title bar of the analysis report. To see the prediction formula, right-click (Ctrl+click on the Mac) the column name and select Formula:

```
0-50.1465*p1 - 282.1982*p2 - 911.6484*p3 + p2*p1*317.363 + p3*p1*1464.3298 + p3*p2*1846.2177
```

**Note:** These results correct the coefficients reported in Cornell (1990).

The Response Surface Solution report (Figure 7.20) shows that a maximum predicted value of 19.570299 occurs at point (0.63505, 0.15568, 0.20927).

Figure 7.20 Mixture Response Surface Analysis



#### The Prediction Profiler

The report contains a prediction profiler.

1. If the profiler is not visible, click the red triangle in the Response Y title bar and select **Factor Profiling** > **Profiler**. You should see the initial profiler shown in Figure 7.21.


The crossed effects show as curvature in the prediction traces. Drag one of the vertical reference lines, and the other two move in the opposite direction maintaining their ratio.

**Note:** The axes of prediction profiler traces range from the upper and lower bounds of the factors, p1, p2, and p3, entered to create the design and the design table. When you experiment moving a variable trace, you see the other traces move such that their ratio is preserved. As a result, when the limit of a variable is reached, it cannot move further and only the third variable changes.

- 2. To limit the visible profile curves to bounds that use all three variables, use the **Profile at Boundary > Stop at Boundaries** command from the menu on the Prediction Profiler title bar.
- 3. If needed, select the **Desirability Functions** command to display the desirability function showing to the right of the prediction profile plots in Figure 7.22.
- 4. Then select Maximize Desirability from the Prediction Profiler menu to see the best factor settings.

The profiler in Figure 7.22, displays optimal settings (rounded) of 0.6350 for p1, 0.1557 for p2, and 0.2093 for p3, which give an estimated response of 19.5703.








Figure 7.22 Maximum Desirability in Profiler for Mixture Analysis Example

#### The Mixture Profiler

The Fit Model report also has a **Mixture Profiler** that is useful for visualizing and optimizing response surfaces from mixture experiments.

Many of the features are the same as those of the Contour Profiler however some are unique to the Mixture Profiler:

- A ternary plot is used instead of a Cartesian plot, which enables you to view three mixture factors at a time
- If you have more than three factors, radio buttons let you choose which factors to plot.
- If the factors have constraints, you can enter their low and high limits in the Lo Limit and Hi Limit columns. This shades non-feasible regions in the profiler.

Select **Factor Profiling > Mixture Profiler** from the menu on the Response Y title bar to see the mixture profiler for the plasticizer data, shown in Figure 7.23.





Figure 7.23 Mixture Profiler for Plasticizer Example

### A Ternary Plot of the Mixture Response Surface

You can also plot the response surface of the plasticizer data as a ternary plot using the Ternary graph platform and contour the plot with information from an additional variable:


- 1. Choose Graph > Ternary Plot.
- 2. Specify plot variables (p1, p2, and p3) and click **X, Plottling**, as shown in Figure 7.24. To identify the contour variable (the prediction equation), select Pred Formula Y and click the **Contour Formula** button. The contour variable must have a prediction formula to form the contour lines, as shown by the ternary plots at the bottom in Figure 7.25. If there is no prediction formula, the ternary plot only shows points.

Figure 7.24 Launch Dialog for the Ternary Plot Platform



3. Click **OK** and view the results, as shown in Figure 7.25. By default, the ternary plot displays contour lines only, but you can request a **Fill Above** or **Fill Below**, as shown, with the **Contour Fill** command found in the red triangle menu on the Ternary Plot title bar.

Figure 7.25 Ternary Plot of a Mixture Response Surface



## **Discrete Choice Designs**



The Discrete Choice designer creates experiments with factors that are product attributes. A collection of attributes is called a product profile. Respondents choose one in each set of product profiles.

Industrial experimentation deals with the question of how to improve processes to deliver better products. Choice experiments help a company prioritize product features for their market. The purpose of a choice experiment is to define a product that people want to buy.

Choice experiments always involve people comparing prospective products and picking the one they prefer. For example, suppose a computer company wants to update its high-end laptop. Laptops have many features that are important to customers such as processor speed, hard disk size, screen size, battery life, and price. To build a laptop that customers want, the computer company needs to know the relative importance of each feature. Most people prefer a faster computer with more storage, longer battery life, and a low price. What the company does not know is how much more an extra hour of battery life is worth to a customer or whether doubling the hard disk size is as important as doubling the processor speed. A choice experiment can answer these questions and indicate the optimal set of trade-offs among product features.

# **Contents**

Introduction	181
Create an Example Choice Experiment	183
Analyze the Example Choice Experiment	186
Design a Choice Experiment Using Prior Information	188
Administer the Survey and Analyze Results	190
Initial Choice Platform Analysis	191
Find Unit Cost and Trade Off Costs with the Profiler	192

#### Introduction

Most choice experiments involve conducting a market research survey. The survey consists of a series of questions about attributes of interest about a potential new product or product modification. For example, a computer manufacturer might be interested in manufacturing a new laptop and wants information about customer preference before beginning an expensive development process. Computer characteristics change so rapidly that it is crucial to quickly identify the attributes that help the manufacturers to design and build a new machine most likely to capture enough market share to be profitable.

Often, the attributes are obvious. For example, the consumer wants a laptop that has a large screen, weighs almost nothing, costs almost nothing, and lasts forever on a single battery charge. The question, then, is how much is the customer willing to compromise these desires? How important is each of these attributes, and which kinds of trade off is the customer most likely to accept and still purchase a new machine?

Assume a simple situation where a computer manufacturer wants to examine preferences for four possible laptop configurations. Notice that there are no 'right' or 'wrong' selections. Instead there are just preferences. A well designed questionnaire and proper analysis of results can tell a manufacturer how to proceed. The manufacturer wants information about the following four laptop attributes.

- size of hard drive disk (40 GB or 80 GB)
- speed of processor (1.5 GHz or 2.0 GHz)
- battery life (4 Hrs or 6 Hrs)
- cost of computer (\$1000, \$1200 or \$1500)

If a survey were constructed that offered the possibility of choosing any combination of these attributes, a respondent would be forced to evaluate 24 possible combinations and make a single response. Instead each respondent usually evaluates several choice sets and for each choice set, chooses the preferred profile. In the simplest situation, each respondent chooses between sets of two profiles.

Then, you analyze the choices of multiple respondents. A well designed choice experiment, correctly analyzed is a efficient way to give the researcher the most information for the least time and expense.

Table 1 shows hypothetical results from a single *survey* designed to collect information about consumer preferences about laptop computers.

- Each column in the survey identifies a laptop *attribute*.
- Each line in the survey defines a laptop *profile*, which is a collection of attribute values.
- Each *choice set* consists of two attribute profiles.
- All of the attribute values are allowed to change across the two profiles in a choice set.

Table 8.1 Hypothetical Choice Survey Results from a single Respondent, Subject ID 2

For each pair, please check the combination of attributes you find most appealing.								
		Disk Size	Speed	Battery Life	Price	Preference		
1	1	40 GB	1.5 GHz	6 hours	\$1,000	_X_		
	2	80 GB	1.5 GHz	4 hours	\$1,200			

Table 8.1 Hypothetical Choice Survey Results from a single Respondent, Subject ID 2 (Continued)

		Disk Size	Speed	Battery Life	Price	Preference
2	1	40 GB	1.5 GHz	4 hours	\$1,500	
	2	80 GB	2.0 GHz	4 hours	\$1,200	
3	1	40 GB	2.0 GHz	4 hours	\$1,200	_X_
<u> </u>	2	80 GB	2.0 GHz	6 hours	\$1,500	
					44 005	
4	2	40 GB 80 GB	2.0 GHz 1.5 GHz	4 hours 6 hours	\$1,000 \$1,200	_X_
					·	
5	1	40 GB	1.5 GHz	6 hours	\$1,000	_X_
	2	40 GB	2.0 GHz	4 hours	\$1,500	<u> </u>
6	1	40 GB	2.0 GHz	6 hours	\$1,200	_X_
	2	80 GB	1.5 GHz	4 hours	\$1,500	_
7	1	40 GB	2.0 GHz	6 hours	\$1,500	<u> </u>
	2	80 GB	1.5 GHz	4 hours	\$1,000	_X_
8	1	40 GB	1.5 GHz	4 hours	\$1,200	
	2	80 GB	2.0 GHz	4 hours	\$1,000	<u> </u>

The DOE Choice designer can create a survey like that shown in Table 8.1. However, to create an effective design, the Choice designer needs information about the attributes. For example, most laptop attributes have values that are intrinsic preferences. That is, a bigger disk size is better, longer battery life is better, and so forth. The purpose of conducting a choice survey is to find out how the potential laptop purchasers feels about the advantages of a collection of tractates.

One way to gain prior information about attributes in a survey is to conduct a single example survey, analyze the results, and use those results as prior information to create the final survey instrument.


This chapter shows how to create a sample survey and use its results as prior information for a final survey design

### **Create an Example Choice Experiment**

The Choice design can create a survey like the one in Table 1. As an example,

1. Choose **DOE** > **Choice Design**, and complete the initial dialog as shown in Figure 8.1.

Figure 8.1 Choice Design Dialog with Attributes Defined




2. Click **Continue**. For this example, use the default values in the Model Control panel and in the Design Generation panel, as shown in Figure 8.2.

Optionally, you can use the DOE Model Controls panel to add interactions to the choice model in situations where you expect there are interactions and want to generate profile sets that will help detect them.

184

Figure 8.2 Design Generation Panel for the Laptop Experiment



The values in the Design Generation panel describe the laptop survey.

Number of attributes that can change within a choice set There are four laptop attributes. Entering 4 as the number of attributes that can change within a choice set means that the Choice designer can change 4 or fewer attribute values within a single choice set. You can enter fewer than the total number of attributes to constrain the total number that can be changed within a choice set. This might be a reasonable thing to do if you had a large number of attributes and you want to make it easier for the respondents to make a choice. For example, a survey might be interested in 20 or more attributes of a cell phone, but show and change only 5 or fewer attributes in a choice set.

**Number of profiles per choice set** This example has two profiles per choice set. You can design choice experiments with more than two profiles in a choice set.

**Number of choice sets per survey** There are eight choice sets in the example survey but often there are many more.


**Number of surveys** The example only shows a single survey. Normally you expect multiple respondents and would request more than one survey.

**Expected number of respondents per survey** You might want to give surveys to 10 people, but use two different surveys. So you enter 2 as the Number of surveys and 5 as the Expected number of respondents per survey.

**Note:** Recall that this first example is used to generate prior information, then used to create a more realistic survey. This example is a single survey given to a single respondent.

3. Click **Make Design** to see the example survey results in Figure 8.3.

Figure 8.3 Survey Results based on a Simple Model and Default Prior Information



The Radio buttons beneath the design settings let you choose between having the survey settings in one JMP table and gathering survey results in a second table, or generating a single table that shows the settings and has an additional column for the choice response.

You can see that there are eight choice sets, each consisting of two laptop profiles. At this point you can press **Back** and modify the design, or click **Make Table** and generate the JMP table shown in Figure 8.4.

This default design was created with no given prior information. Without prior information, the Choice designer has no way of knowing which attribute levels are better. That is, the Choice designer cannot know that a lower price might be more desirable than a higher price, a faster machine is better than a slower machine, and so forth. As a result, you can see that some choice sets might not convey useful information. The analysis results are used as prior information in a new Choice design dialog.

Figure 8.4 JMP Data Table for Preliminary Laptop Choice Survey

Choice Profiles ▷	4						
Design Discrete Choice	•	Choice Set	Response Indicator	Disk Size	Speed	Battery Life	Price
▼ Choice	1	1	•	80 GB	2.0 GHz	6 Hrs	\$1,500
Columns (6/0)	2	1	•	40 GB	1.5 GHz	4 Hrs	\$1,200
h Choice Set	3	2	•	40 GB	2.0 GHz	6 Hrs	\$1,500
Response Indicator	4	2	•	80 GB	2.0 GHz	4 Hrs	\$1,200
L Disk Size	5	3	•	80 GB	1.5 GHz	6 Hrs	\$1,000
♣ Speed	6	3	•	40 GB	2.0 GHz	4 Hrs	\$1,500
🔥 Battery Life	7	4	•	80 GB	2.0 GHz	4 Hrs	\$1,500
♣ Price	8	4	•	40 GB	2.0 GHz	6 Hrs	\$1,000
Rows	9	5	•	40 GB	2.0 GHz	6 Hrs	\$1,200
All rows 16	10	5	•	80 GB	1.5 GHz	4 Hrs	\$1,000
Selected 0	11	6	•	80 GB	1.5 GHz	6 Hrs	\$1,200
Excluded 0	12	6	•	40 GB	2.0 GHz	4 Hrs	\$1,000
Hidden 0	13	7	•	40 GB	1.5 GHz	4 Hrs	\$1,200
Labelled 0	14	7	•	80 GB	2.0 GHz	4 Hrs	\$1,000
	15	8	•	40 GB	2.0 GHz	4 Hrs	\$1,200
	16	8	•	40 GB	1.5 GHz	4 Hrs	\$1,500

## **Analyze the Example Choice Experiment**

Once a survey design is complete, a respondent chooses one profile from each set, entering '1' for the chosen profile and '0' for the rejected profile. Suppose a respondent completed the example survey as shown in Figure 8.5. You can now analyze these results using the Choice platform in the **Analyze** menu (**Analyze** > **Modeling** > **Choice**).

Figure 8.5 JMP Table with Survey Choice Sets and Responses


■ Laptop Design	4 •	Choice	Response				
Design Discrete Choice	•	Set	Indicator	Disk Size	Speed	Battery Life	Price
▼ Choice	1	1	1	40 GB	1.5 GHz	6 Hrs	\$1,000
	2	1	0	80 GB	1.5 GHz	4 Hrs	\$1,200
	3	2	0	40 GB	1.5 GHz	4 Hrs	\$1,500
	4	2	1	80 GB	2.0 GHz	4 Hrs	\$1,200
	5	3	1	40 GB	2.0 GHz	4 Hrs	\$1,200
	6	3	0	80 GB	2.0 GHz	6 Hrs	\$1,500
▼ Columns (6/0)	7	4	1	40 GB	2.0 GHz	4 Hrs	\$1,000
♣ Choice Set	8	4	0	80 GB	1.5 GHz	6 Hrs	\$1,200
🔥 Response Indicator	9	5	1	40 GB	1.5 GHz	6 Hrs	\$1,000
🔥 Disk Size	10	5	0	40 GB	2.0 GHz	4 Hrs	\$1,500
🔥 Speed	11	6	1	40 GB	2.0 GHz	6 Hrs	\$1,200
■ Battery Life	12	6	0	80 GB	1.5 GHz	4 Hrs	\$1,500
<b>♣</b> Price	13	7	0	40 GB	2.0 GHz	6 Hrs	\$1,500
	14	7	1	80 GB	1.5 GHz	4 Hrs	\$1,000
	15	8	0	40 GB	1.5 GHz	4 Hrs	\$1,200
5-	16	8	1	80 GB	2.0 GHz	4 Hrs	\$1,000

Analyze the Example Choice Experiment

1. Click the Choice script in the Laptop Design data table and select **Run Script** to analyze that data with the Choice modeling platform from the **Analyze** menu.

When you run the Choice model script, the Choice launch dialog shown in Figure 8.6 appears, The Choice dialog is designed to cover a variety of choice survey results, which can include data saved in multiple data tables. This example has all data contained in a single table. For details about using the Choice analysis dialog, see the Choice Modeling chapter in the *Modeling and Multivariate Methods* book.

Figure 8.6 Choice Model Fitting Dialog



- 2. Click Run Model on the Choice model fitting dialog.
- 3. An additional dialog then appears asking if this is a one-table analysis with all the data in the Profile Table, which is the case in this sample survey. Click **Yes** in this dialog to continue.


The analysis shows as in Figure 8.7.

To design the final choice survey using prior information, you will need to enter estimates of the mean and variance of the attribute parameter estimates. The analysis on the left in Figure 8.7 has estimates of the attribute means, called **Estimate**, and estimates of the standard deviation of the attributes, called **Std Error**. An easy way to see the variance of the attributes is to capture the analysis in a JMP table and compute the variance:

- 4. Right click on the Parameter Estimates report and choose **Make into Data Table** from the menu, as shown
- 5. In the new Untitled data table, create a new column and call it Var.
- 6. Select Formula from the Cols menu (Cols > Formula), or right-click at the top of the Var column and select Formula for the menu that shows.

7. In the Formula Editor, click the Std Error column in the column list and click the exponent button (🕼) on the formula editor panel to compute the variance shown on the right in Figure 8.7.

Figure 8.7 Analysis of the sample Laptop Survey



This preliminary survey with its analysis gives you the information needed to design a final survey appropriate for gathering information from multiple respondents. Keep in mind that in a real situation, you might have prior information about factor attributes and not need to do a sample design.

**Note**: Leave the Untitled data table with the mean and variance information open to be used in the next example.


### **Design a Choice Experiment Using Prior Information**

In some situations, you will know from previous surveys or experience how to give prior information to the Choice designer about product attributes. This example continues by designing the laptop experiment again, using the analysis information gained from the sample design.

1. Choose **DOE** > **Choice Design** and enter the attributes and values as before.

- 2. Click **Continue** to see the Choice design panels in Figure 8.8.
- 3. Now enter the values from the JMP table created by the previous analysis into the Prior Mean and Prior Variance Matrix panels of the Choice Design dialog, as shown in Figure 8.8. You can copy-and-paste to transfer the values from the data table to the Choice dialog panels.


Figure 8.8 Enter Prior Mean and Variance Information from Preliminary Survey



- 4. Enter the values into the Design Generation panel, as shown in Figure 8.9.
  - Four or fewer attribute levels can change within a choice set.
  - There are two profiles per choice set.
  - Each survey has eight choice sets.
  - The design generates two separate surveys.
  - Five respondents are expected to complete each survey (for a total of 10 respondents).


**Discrete Choice Designs** 

Figure 8.9 Design Specifications for final Laptop Survey



5. Click **Make Design**. A partial view of the design is shown in Figure 8.10.

Figure 8.10 Design Runs for Two Choice Surveys



6. Click **Make Table**. The final data table will have runs for ten survey respondents, giving a total of 160 observations (2 profiles \* 8 choice sets \* 2 surveys \* 5 respondents = 160 observations).

## **Administer the Survey and Analyze Results**


The survey data table with its results is stored in the Sample Data Design Experiment folder installed with JMP. Figure 8.11 is a partial listing of the survey data table with results. The Choice script created by the Choice designer and saved with the survey data table can be used to analyze the data. The default data table created by the Choice designer is named Choice Profiles. Note in Figure 8.11, the data table name is changed to Laptop Results.

#### **Initial Choice Platform Analysis**

- 1. To continue the example, open the table called Laptop Results.jmp, saved in the Sample Data folder.
- 2. To analyze the data, click the Choice script saved with the data and select **Run Script** from the menu to see the completed dialog shown in Figure 8.11.

Note that this dialog has three grouping variables (Respondent, Survey, and Choice Set, whereas the dialog shown Figure 8.6 had only the Choice Set grouping variable because there was a single survey and a single respondent. This example included multiple surveys and respondents, which must be included in the analysis.

Figure 8.11 Choice Model Fitting Dialog to Analyze the Laptop Survey




3. Click **Run** on the Fit Model dialog. The query again appears asking if the analysis is a one-table analysis with all the data in the profile table. Click **Yes** to see the initial analysis result shown in Figure 8.12.

The results are clear. While all the effects are significant, the most significant attribute is Speed.

Administer the Survey and Analyze Results

Figure 8.12 Initial Analysis of the Final Laptop Survey




#### Find Unit Cost and Trade Off Costs with the Profiler

You would like to know how changing the price, or other characteristics, of a laptop affects the desirability as perceived by potential buyers. This desirability is called the utility value of the laptop attributes. The profiler shows the utility value and how it changes as the laptop attributes change.

1. Select **Profiler** from the menu on the Choice Model title bar to see the Prediction Profiler in Figure 8.13.

Figure 8.13 Default Prediction Profiler for Laptop Choice Analysis




When each attribute value is set to its lowest value, the Utility value is -0.3406. The first thing you want to know is the unit utility cost.

2. To find the unit utility cost, move the trace for Price to \$1,500 and note how the Utility value changes.

Compare the Utility values in Figure 8.13 and Figure 8.14. The value of Utility changes from -0.3406 to -2.3303 when cost is raised from \$1,000 to \$1,500. That is, raising the price of a laptop \$500.00 lowers the utility (or desirability) approximately 2 units. Thus, you can say that the unit utility cost is roughly \$250.00.

Figure 8.14 Compare Change in Utility Over Price




With this unit utility cost estimate you can now vary the other attributes, note the change in utility, and find an approximate dollar value associated with that attribute change. For example, the most significant attribute is speed (see Figure 8.12).

3. In the Prediction Profiler, set Price to its lowest value and change Speed to its higher value.

You can see in Figure 8.15 that the Utility value changes from the original value shown in Figure 8.13 of -0.3406 to 0.9886, for a total change of 1.3292 units. If the unit utility cost is estimated to be \$250.00, as shown above, then the increase in price for a 2.0 GHz laptop over a 1.5 GHz laptop can be computed to be 1.3292\*\$250.00 = \$332.30. This is the dollar value the Choice survey provides the manufacturer as a basis for pricing different laptop products. You can make similar calculations for the other attributes.

Figure 8.15 Change Speed in Profiler and Note Utility Value



This simple Choice survey and its analysis shows how this kind if information can be used to help manufacturers and retailers identify important product attributes and assign values to them.

#### 194 Discrete Choice Designs

Administer the Survey and Analyze Results

The Choice designer allows more complex designs, such as designs with interactions and other terms. The Choice analysis platform can be used to analyze complex designs, and it can be used to incorporate data from multiple data sets that include demographic information about the respondents.

Chapter 8

# **Space-Filling Designs**




Space-filling designs are useful in situations where run-to-run variability is of far less concern than the form of the model. Sensitivity studies of computer simulations is one such situation. For this case, and any mechanistic or deterministic modeling problem, any variability is small enough to be ignored. For systems with no variability, randomization and blocking are irrelevant. Replication is undesirable because repeating the same run yields the same result. In space-filling designs, there are two objectives:


- Prevent replicate points by spreading the design points out to the maximum distance possible between any two points.
- Space the points uniformly.

The following methods are implemented for these types of designs:

- The Sphere-Packing method emphasizes spread of points.
- The Latin Hypercube method is a compromise between spread of points and uniform spacing.
- The Uniform method mimics the uniform probability distribution.
- The Minimum Potential method minimizes energy designs in a hypersphere.
- The Maximum Entropy method measures the amount of information contained in the distribution of a set of data.
- The Gaussian Process IMSE Optimal method creates a design that minimizes the integrated mean squared error of the gaussian process over the experimental region.

Figure 9.1 Space-Filling Design





# **Contents**

Introduction to Space-Filling Designs
Sphere-Packing Designs
Creating a Sphere-Packing Design
Latin Hypercube Designs
Creating a Latin Hypercube Design
Uniform Designs
Comparing Sphere-Packing, Latin Hypercube, and Uniform Methods
Minimum Potential Designs
Maximum Entropy Designs
Gaussian Process IMSE Optimal Designs
Borehole Model: A Sphere-Packing Example
Create the Sphere-Packing Design for the Borehole Data
Results of the Borehole Experiment

### **Introduction to Space-Filling Designs**

Space-filling designs are useful for modeling systems that are deterministic or near-deterministic. One example of a deterministic system is a computer simulation. Such simulations can be very complex involving many variables with complicated interrelationships. A goal of designed experiments on these systems is to find a simpler empirical model that adequately predicts the behavior of the system over limited ranges of the factors.

In experiments on systems where there is substantial random noise, the goal is to minimize the variance of prediction. In experiments on deterministic systems, there is no variance but there is *bias*. Bias is the difference between the approximation model and the true mathematical function. The goal of space-filling designs is to bound the bias.

There are two schools of thought on how to bound the bias. One approach is to spread the design points out as far from each other as possible consistent with staying inside the experimental boundaries. The other approach is to space the points out evenly over the region of interest.

The **Space Filling** designer supports the following design methods:

**Sphere Packing** maximizes the minimum distance between pairs of design points.

**Latin Hypercube** maximizes the minimum distance between design points but requires even spacing of the levels of each factor. This method produces designs that mimic the uniform distribution. The Latin Hypercube method is a compromise between the Sphere-Packing method and the Uniform design method.

**Uniform** minimizes the discrepancy between the design points (which have an empirical uniform distribution) and a theoretical uniform distribution.

**Minimum Potential** spreads points out inside a sphere around the center.

**Maximum Entropy** measures the amount of information contained in the distribution of a set of data.

**Gaussian Process IMSE Optimal** creates a design that minimizes the integrated mean squared error of the Gaussian process over the experimental region.

### **Sphere-Packing Designs**

The Sphere-Packing design method maximizes the minimum distance between pairs of design points. The effect of this maximization is to spread the points out as much as possible inside the design region.

#### Creating a Sphere-Packing Design

- 1. Select DOE > Space Filling Design.
- 2. Enter responses and factors. (See "Enter Responses and Factors into the Custom Designer," p. 65.)
- 3. Alter the factor level values, if necessary. For example, Figure 9.2 shows the two existing factors, X1 and X2, with values that range from 0 to 1 (instead of the default –1 to 1).

Figure 9.2 Space-Filling Dialog for Two Factors



- 4. Click Continue.
- 5. In the design specification dialog, specify a sample size (**Number of Runs**). Figure 9.3 shows a sample size of eight.

Figure 9.3 Space-Filling Design Dialog



6. Click Sphere Packing.

JMP creates the design and displays the design runs and the design diagnostics. Figure 9.4 shows the Design Diagnostics panel open with 0.518 as the **Minimum Distance**. Your results might differ slightly from the ones below, but the minimum distance will be the same.

Figure 9.4 Sphere-Packing Design Diagnostics

△ Design Diagnostics									
			Minimum	Nearest					
Run	ScaledX1	ScaledX2	Distance	Point					
1	0.13397	0.50000	0.518	8					
2	0.50000	0.86603	0.518	6					
3	0.86603	0.50000	0.518	7					
4	1.00000	1.00000	0.518	3					
5	1.00000	0.00000	0.518	7					
6	0.00000	1.00000	0.518	2					
7	0.50000	0.13398	0.518	5					
8	0.00000	0.00000	0.518	1					
discrepancy = 0.0469 Design Table									
Make Table Back									

7. Click Make Table. Use this table to complete the visualization example, described next.

#### Visualizing the Sphere-Packing Design

To visualize the nature of the Sphere-Packing technique, create an overlay plot, adjust the plot's frame size, and add circles using the minimum distance from the diagnostic report shown in Figure 9.4 as the radius for the circles. Using the table you just created:

- 1. Select Graph > Overlay Plot.
- 2. Specify X1 as X and X2 as Y, then click **OK**.
- Adjust the frame size so that the frame is square by right-clicking the plot and selecting Size/Scale > Size to Isometric.
- 4. Right-click the plot and select **Customize**. When the Customize panel appears, click the plus sign to see a text edit area and enter the following script:

For Each Row(Circle({:X1, :X2}, 0.518/2))


- where **0.518** is the minimum distance number you noted in the Design Diagnostics panel. This script draws a circle centered at each design point with radius 0.259 (half the diameter, 0.518), as shown on the left in Figure 9.5. This plot shows the efficient way JMP packs the design points.
- 5. Now repeat the procedure exactly as described in the previous section, but with a sample size of 10 instead of eight.

Remember to change **0.518** in the graphics script to the minimum distance produced by 10 runs. When the plot appears, again set the frame size and create a graphics script using the minimum distance from the diagnostic report as the diameter for the circle. You should see a graph similar to the one on the right in Figure 9.5. Note the irregular nature of the sphere packing. In fact, you can repeat the process a

Space-Filling Designs Latin Hypercube Designs

third time to get a slightly different picture because the arrangement is dependent on the random starting point.

Figure 9.5 Sphere-Packing Example with Eight Runs (left) and 10 Runs (right)



### **Latin Hypercube Designs**


In a Latin Hypercube, each factor has as many levels as there are runs in the design. The levels are spaced evenly from the lower bound to the upper bound of the factor. Like the sphere-packing method, the Latin Hypercube method chooses points to maximize the minimum distance between design points, but with a constraint. The constraint maintains the even spacing between factor levels.

### Creating a Latin Hypercube Design

To use the Latin Hypercube method:

- 1. Select DOE > Space Filling Design.
- 2. Enter responses, if necessary, and factors. (See "Enter Responses and Factors into the Custom Designer," p. 65.)
- 3. Alter the factor level values, if necessary. For example, Figure 9.6 shows adding two factors to the two existing factors and changing their values to 1 and 8 instead of the default –1 and 1.

Figure 9.6 Space-Filling Dialog for Four Factors




- Click Continue.
- 5. In the design specification dialog, specify a sample size (**Number of Runs**). This example uses a sample size of eight.
- 6. Click **Latin Hypercube** (see Figure 9.3). Factor settings and design diagnostics results appear similar to those in Figure 9.7, which shows the Latin Hypercube design with four factors and eight runs.

**Note:** The purpose of this example is to show that each column (factor) is assigned each level only once, and each column is a different permutation of the levels.

202

Figure 9.7 Latin Hypercube Design for Four Factors and Eight Runs with Eight Levels



### Visualizing the Latin Hypercube Design

To visualize the nature of the Latin Hypercube technique, create an overlay plot, adjust the plot's frame size, and add circles using the minimum distance from the diagnostic report as the radius for the circle.

- 1. First, create another Latin Hypercube design using the default X1 and X2 factors.
- 2. Be sure to change the factor values so they are 0 and 1 instead of the default –1 and 1.
- Click Continue.
- 4. Specify a sample size of eight (**Number of Runs**).
- 5. Click Latin Hypercube. Factor settings and design diagnostics are shown in Figure 9.8.




Figure 9.8 Latin Hypercube Design with two Factors and Eight Runs


- Click Make Table.
- Select Graph > Overlay Plot.
- 8. Specify X1 as X and X2 as Y, then click **OK**.
- Right-click the plot and select Size/Scale > Size to Isometric to adjust the frame size so that the frame is square.
- 10. Right-click the plot, select **Customize** from the menu. In the Customize panel, click the large plus sign to see a text edit area, and enter the following script:


where **0.404** is the minimum distance number you noted in the Design Diagnostics panel (Figure 9.8). This script draws a circle centered at each design point with radius 0.202 (half the diameter, 0.404), as shown on the left in Figure 9.9. This plot shows the efficient way JMP packs the design points.

11. Repeat the above procedure exactly, but with 10 runs instead of eight (step 5). Remember to change 0.404 in the graphics script to the minimum distance produced by 10 runs.

You should see a graph similar to the one on the right in Figure 9.9. Note the irregular nature of the sphere packing. In fact, you can repeat the process to get a slightly different picture because the arrangement is dependent on the random starting point.

Figure 9.9 Comparison of Latin Hypercube Designs with Eight Runs (left) and 10 Runs (right)





Note that the minimum distance between each pair of points in the Latin Hypercube design is smaller than that for the Sphere-Packing design. This is because the Latin Hypercube design constrains the levels of each factor to be evenly spaced. The Sphere-Packing design maximizes the minimum distance without any constraints.

# **Uniform Designs**


The Uniform design minimizes the discrepancy between the design points (empirical uniform distribution) and a theoretical uniform distribution.

**Note:** These designs are most useful for getting a simple and precise estimate of the integral of an unknown function. The estimate is the average of the observed responses from the experiment.

- 1. Select **DOE** > **Space** Filling **Design**.
- 2. Enter responses, if necessary, and factors. (See "Enter Responses and Factors into the Custom Designer," p. 65.)
- 3. Alter the factor level values to 0 and 1.
- 4. Click Continue.
- 5. In the design specification dialog, specify a sample size. This example uses a sample size of eight (Number of Runs).
- 6. Click the **Uniform** button. JMP creates this design and displays the design runs and the design diagnostics as shown in Figure 9.10.

**Note:** The emphasis of the Uniform design method is not to spread out the points. The minimum distances in Figure 9.10 vary substantially.


Figure 9.10 Factor Settings and Diagnostics for Uniform Space-Filling Designs with Eight Runs



#### 7. Click Make Table.

A Uniform design does not guarantee even spacing of the factor levels. However, increasing the number of runs and running a distribution on each factor (use **Analyze** > **Distribution**) shows flat histograms.

Figure 9.11 Histograms are Flat for each Factor when Number of Runs is Increased to 20



# Comparing Sphere-Packing, Latin Hypercube, and Uniform Methods

To compare space-filling design methods, create the **Sphere Packing**, **Latin Hypercube**, and **Uniform** designs, as shown in the previous examples. The Design Diagnostics tables show the values for the factors scaled from zero to one. The minimum distance is based on these scaled values and is the minimum distance from each point to its closest neighbor. The discrepancy value is the integrated difference between the design points and the uniform distribution.

Figure 9.12 shows a comparison of the design diagnostics for three eight-run space-filling designs. Note that the discrepancy for the Uniform design is the smallest (best). The discrepancy for the Sphere-Packing design is the largest (worst). The discrepancy for the Latin Hypercube takes an intermediate value that is closer to the optimal value.

Also note that the minimum distance between pairs of points is largest (best) for the Sphere-Packing method. The Uniform design has pairs of points that are only about half as far apart. The Latin Hypercube design behaves more like the Sphere-Packing design in spreading the points out.

For both spread and discrepancy, the Latin Hypercube design represents a healthy compromise solution.

 △ Design Diagnostics Minimum Nearest Run ScaledX1 ScaledX2 Distance Point 1 0.86603 0.50000 0.518 2 0.50000 0.13397 0.518 Sphere-0.518 3 0.00000 5 1.00000 Packing 0.518 1.00000 1.00000 5 0.50000 0.86603 0.518 8 6 1.00000 0.518 0.00000 7 0.00000 0.00000 0.518 8 0.13397 0.50000 0.518 discrepancy = 0.0469 △ Design Diagnostics Minimum Nearest Run ScaledX1 ScaledX2 Distance Point 0.57143 0.85714 0.404 4 2 0.71429 0.404 0.42857 Latin 3 1.00000 0.71429 0.404 Hypercube 4 0.28571 0.57143 0.404 0.404 2 5 0.42857 0.14286 0.85714 0.00000 0.452 0.00000 0.28571 0.404 4 8 0.14286 0.452 1.00000 discrepancy = 0.0092 ■ Design Diagnostics Minimum Nearest Run ScaledX1 ScaledX2 Distance 1 0.43532 0.93541 0.284 8 Uniform 0.285 2 0.18514 6 0.69286 0.56557 0.18590 0.277 5 0.93541 0.56468 0.284 5 0.81486 0.30724 0.277 3 6 0.06460 0.43504 0.285 2 7 0.30959 0.06908 0.281 3 0.284 8 0.69286 0.81486

Figure 9.12 Comparison of Diagnostics for Three Eight-Run Space-Filling Methods


Another point of comparison is the time it takes to compute a design. The Uniform design method requires the most time to compute. Also, the time to compute the design increases rapidly with the number of runs. For comparable problems, all the space-filling design methods take longer to compute than the *D*-optimal designs in the Custom Designer.

# Minimum Potential Designs

discrepancy = 0.0046

The Minimum Potential design spreads points out inside a sphere. To understand how this design is created, imagine the points as electrons with springs attached to every other point, as illustrated to the right. The coulomb force pushes the points apart, but the springs pull them together. The design is the spacing of points that minimizes the potential energy of the system.

Figure 9.13 Minimum Potential Design



#### Minimum Potential designs:


- have spherical symmetry
- · are nearly orthogonal
- · have uniform spacing

To see a Minimum Potential example:

- 1. Select **DOE** > **Space** Filling **Design**.
- 2. Add 1 continuous factor. (See "Enter Responses and Factors into the Custom Designer," p. 65.)
- 3. Alter the factor level values to 0 and 1, if necessary.
- 4. Click Continue.
- 5. In the design specification dialog (shown on the left in Figure 9.14), enter a sample size (**Number of Runs**). This example uses a sample size of 12.
- 6. Click the **Minimum Potential** button. JMP creates this design and displays the design runs (shown on the right in Figure 9.14) and the design diagnostics.

Figure 9.14 Space-Filling Methods and Design Diagnostics for Minimum Potential Design





7. Click Make Table.

You can see the spherical symmetry of the Minimum Potential design using the Scatterplot 3D graphics platform.

- 1. After you make the JMP design table, choose the **Graph** > **Scatterplot 3D** command.
- 2. In the Scatterplot 3D launch dialog, select X1, X2, and X3 as Y, Columns and click OK to see the initial three dimensional scatterplot of the design points.
- 3. To see the results similar to those in Figure 9.15, select the Normal Contour Ellipsoids option from the menu in the Scatterplot 3D title bar, and make the points larger by right-clicking on the plot and selecting Settings, then increasing the Marker Size slider.

Now it is easy to see the points spread evenly on the surface of the ellipsoid.





Figure 9.15 Minimum Potential Design Points on Sphere

### **Maximum Entropy Designs**

The Latin Hypercube design is currently the most popular design assuming you are going to analyze the data using a Gaussian-Process model. Computer simulation experts like to use the Latin Hypercube design because all projections onto the coordinate axes are uniform.


However, as the example at the top in Figure 9.16 shows, the Latin Hypercube design does not necessarily do a great job of space filling. This is a two-factor Latin Hypercube with 16 runs, with the factor level settings set between -1 and 1. Note that this design appears to leave a hole in the bottom right of the overlay plot.

Figure 9.16 Two-factor Latin Hypercube Design



The Maximum Entropy design is a competitor to the Latin Hypercube design for computer experiments because it optimizes a measure of the amount of information contained in an experiment. See the technical note below. With the factor levels set between -1 and 1, the two-factor Maximum Entropy design shown in Figure 9.17 covers the region better than the Latin hypercube design in Figure 9.16. The space-filling property generally improves as the number of runs increases without bound.

Figure 9.17 Two-Factor Maximum Entropy Design



**Technical Note:** Maximum Entropy designs maximize the Shannon information (Shewry and Wynn (1987)) of an experiment, assuming that the data come from a normal (m, s<sup>2</sup> R) distribution, where

$$R_{ij} = \exp\left(-\sum_{k} \theta_{k} (x_{ik} - x_{jk})^{2}\right)$$

is the correlation of response values at two different design points,  $x_i$  and  $x_j$ . Computationally, these designs maximize  $|\mathbf{R}|$ , the determinant of the correlation matrix of the sample. When  $x_i$  and  $x_j$  are far apart, then  $\mathbf{R}_{ij}$  approaches zero. When  $x_i$  and  $x_j$  are close together, then  $\mathbf{R}_{ij}$  is near one.

# **Gaussian Process IMSE Optimal Designs**

The Gaussian process IMSE optimal design is also a competitor to the Latin Hypercube design because it minimizes the integrated mean squared error of the Gaussian process model over the experimental region.

You can compare the IMSE optimal design to the Latin Hypercube (shown previously in Figure 9.16). The table and overlay plot in Figure 9.18 show a Gaussian IMSE optimal design. You can see that the design provides uniform coverage of the factor region.




Figure 9.18 Comparison of Two-factor Latin Hypercube and Gaussian IMSE Optimal Designs

**Note:** Both the Maximum Entropy design and the Gaussian Process IMSE Optimal design were created using 100 random starts.

# **Borehole Model: A Sphere-Packing Example**

Worley (1987) presented a model of the flow of water through a borehole that is drilled from the ground surface through two aquifers. The response variable y is the flow rate through the borehole in  $m^3$ /year and is determined by the following equation:

212

Borehole Model: A Sphere-Packing Example

$$y = \frac{2\pi T_u (H_u - H_l)}{\ln(r/r_w) \left[1 + \frac{2LT_u}{\ln(r/r_w)r_w^2 K_w} + \frac{T_u}{T_l}\right]}$$

There are eight inputs to this model:

 $r_w$  = radius of borehole, 0.05 to 0.15 m

r = radius of influence, 100 to 50,000 m

 $T_u$  = transmissivity of upper aquifier, 63,070 to 115,600 m<sup>2</sup>/year

 $H_u$  = potentiometric head of upper aquifier, 990 to 1100 m

 $T_l$  = transmissivity of lower aquifier, 63.1 to 116 m<sup>2</sup>/year

 $H_l$  = potentiometric head of lower aquifier, 700 to 820 m

L = length of borehole, 1120 to 1680 m

 $K_w$  = hydraulic conductivity of borehole, 9855 to 12,045 m/year

This example is atypical of most computer experiments because the response can be expressed as a simple, explicit function of the input variables. However, this simplicity is useful for explaining the design methods.

### Create the Sphere-Packing Design for the Borehole Data

To create a Sphere-Packing design for the borehole problem:

- 1. Select DOE > Space Filling Design.
- 2. Click the red triangle icon on the Space Filling Design title bar and select Load Factors.
- 3. Open the Sample Data folder installed with JMP. In the Design Experiment folder, open Borehole Factors.jmp from the Design Experiment folder to load the factors (Figure 9.19).

Figure 9.19 Factors Panel with Factor Values Loaded for Borehole Example

Factors				
Add 1 Continuous				
Remove Selected				
Name	Role	Values		
▲log10 Rw	Continuous	-1.3	-0.82	
■log10 R	Continuous	2	4.7	
<b>⊿</b> Tu	Continuous	63070	115600	
<b>⊿</b> TI	Continuous	63.1	116	
<b>⊿</b> Hu	Continuous	990	1110	
<b>⊿</b> HI	Continuous	700	820	
▲L	Continuous	1120	1680	
<b>⊿</b> Kw	Continuous	9855	12045	

**Note:** The logarithm of r and  $r_w$  are used in the following discussion.

- Click Continue.
- 5. Specify a sample size (Number of Runs) of 32 as shown in Figure 9.20.

Figure 9.20 Space-Filling Design Method Panel Showing 32 Runs



- 6. Click the **Sphere Packing** button to produce the design.
- 7. Click Make Table to make a table showing the design settings for the experiment. The factor settings in the example table might not have the same ones you see when generating the design because the designs are generated from a random seed.
- 8. To see a completed data table for this example, open Borehole Sphere Packing.jmp from the Design Experiment Sample Data folder installed with JMP. This table also has a table variable that contains a script to analyze the data. The results of the analysis are saved as columns in the table.

### **Guidelines for the Analysis of Deterministic Data**

It is important to remember that deterministic data have no random component. As a result, *p*-values from fitted statistical models do not have their usual meanings. A large *F* statistic (low *p*-value) is an indication of an effect due to a model term. However, you cannot make valid confidence intervals about the size of the effects or about predictions made using the model.

Residuals from any model fit to deterministic data are not a measure of noise. Instead, a residual shows the model bias for the current model at the current point. Distinct patterns in the residuals indicate new terms to add to the model to reduce model bias.

### Results of the Borehole Experiment

The example described in the previous sections produced the following results:

 A stepwise regression of the response, log y, versus the full quadratic model in the eight factors, led to the prediction formula column. Borehole Model: A Sphere-Packing Example

- The prediction bias column is the difference between the true model column and the prediction formula column.
- The prediction bias is relatively small for each of the experimental points. This indicates that the model fits the data well.


In real world examples, the true model is generally not available in a simple analytical form. As a result, it is impossible to know the prediction bias at points other than the observed data without doing additional runs


In this case, the true model column contains a formula that allows profiling the prediction bias to find its value anywhere in the region of the data. To understand the prediction bias in this example:

- 1. Select Graph > Profiler.
- 2. Highlight the prediction bias column and click the Y, Prediction Formula button.
- 3. Check the **Expand Intermediate Formulas** box, as shown at the bottom on the Profiler dialog in Figure 9.21, because the prediction bias formula is a function of columns that are also created by formulas.
- 4. Click OK.

The profile plots at the bottom in Figure 9.21 show the prediction bias at the center of the design region. If there were no bias, the profile traces would be constant between the value ranges of each factor. In this example, the variables Hu and HI show nonlinear effects.


Figure 9.21 Profiler Dialog and Profile of the Prediction Bias in the Borehole Sphere-Packing Data





The range of the prediction bias on the data is smaller than the range of the prediction bias over the entire domain of interest. To see this, look at the distribution analysis (**Analyze > Distribution**) of the prediction bias in Figure 9.22. Note that the maximum bias is 1.826 and the minimum is –0.684 (the range is 2.51).


Figure 9.22 Distribution of the Prediction Bias



The top plot in Figure 9.23 shows the maximum bias (2.91) over the entire domain of the factors. The plot at the bottom shows the comparable minimum bias (-4.84). This gives a range of 7.75. This is more than three times the size of the range over the observed data.

Borehole Model: A Sphere-Packing Example

Figure 9.23 Prediction Plots showing Maximum and Minimum Bias Over Factor Domains



Keep in mind that, in this example, the true model is known. In any meaningful application, the response at any factor setting is unknown. The prediction bias over the experimental data underestimates the bias throughout the design domain.

There are two ways to assess the extent of this underestimation:

- Cross-validation refits the data to the model while holding back a subset of the points and looks at the error in estimating those points.
- Verification runs (new runs performed) at different settings to assess the lack of fit of the empirical model.


# **Accelerated Life Test Designs**

# **Designing Experiments for Accelerated Life Tests**



The Accelerated Life Test Design platform can be used to design experimental plans for accelerated life testing. You can design initial experiments, or augment existing experiments.

Figure 10.1 Accelerated Life Test Design



# **Contents**

Overview of Accelerated Life Test Designs.	219
Using the ALT Design Platform	219
Platform Options	224
Example	224

# **Overview of Accelerated Life Test Designs**

Often in reliability studies, the product reliability at use conditions is so high that the time required to test the product until it fails is prohibitive. As an alternative, you can test the product in conditions that are more extreme than normal use conditions. The extreme conditions enable the product to degrade and fail sooner, making a reliability study possible. Results are used to predict product reliability at normal use conditions.

The **Accelerated Life Testing Design** platform can be used to design experimental plans for accelerated life testing (ALT) experiments. The ALT Design platform can be used to design initial experiments, or augment existing experiments. Augmenting designs is useful if you want to obtain more data, so that you can decrease the variance associated with predicting product reliability.


The ALT Design platform can create designs for situations involving one or two accelerating factors. For two accelerating factors, you can choose to include the interaction. You can use D-optimality or two types of I-optimality criterion.

The process requires estimates of acceleration model parameters. Since those parameters might not be known in advance, you can specify prior distributions to account for the uncertainty. Designs can be created for either Lognormal or Weibull life distributions.

# **Using the ALT Design Platform**

1. To launch the ALT Design platform, select **DOE** > **Accelerated Life Test Design**.

Figure 10.2 Initial ALT Design Window



2. Select one or two accelerating factors.

For two factors, you can choose to include the interaction between the factors.

Click Continue.

A window appears for specifying details of the accelerating factor or factors.

Using the ALT Design Platform

Figure 10.3 Accelerating Factor Details Window



#### 4. Fill in these options:

**Factor Name** Enter a name for the accelerating factor.

**Number of Levels** Enter the number of levels of the factor to include in the experiment.

**Factor Transformation** Select a transformation for the factor. The options are Arrhenius Celsius, Reciprocal, Log, Square Root, and Linear.


**Low Usage Condition** Enter a value for the low usage conditions.

**High Usage Conditions** Enter a value for the high usage conditions.

#### 5. Click Continue.

A window appears for specifying additional information about the assumed distribution and desired experimental conditions.

Figure 10.4 Distribution Details



#### 6. Fill in these options:

**Factors** Enter the values of the accelerating factor levels.

**Distribution Choice** Select the failure distribution, either Weibull or LogNormal.

**Prior Mean** Enter the acceleration model parameters. These values can be either a best guess or the estimates of the parameters from an analysis of previously obtained data.

**Prior Variance Matrix** Enter variances and covariances for the acceleration model parameters. These values can be either a best guess or the estimated variance matrix from an analysis of previously obtained data.

Ignore prior variance Select this option to ignore variances and covariances for model parameters. When the variances and covariances are ignored, the design is created for the specific fixed parameters entered under Prior Mean. The resulting design is said to be a locally optimal design. This design will be good if the prior mean parameters are close to the true values. However, the design will not be robust to mis-specified parameters. When the variances and covariances are used, a multivariate normal prior distribution is assumed for the acceleration model parameters. This is useful when the values entered under Prior Mean are estimates or guesses, and you want the design to reflect the associated uncertainty.

#### **Diagnostic Choices** Enter values for the following:

Time range of interest are values for which you want an estimated probability of failure. For example, if you are interested in the probability of failure by 100,000 hours, then enter 100,000 for both the lower and upper ranges.

**Probability of interest** is the value for which you want an estimated time of failure. For example, if you are most interested in obtaining the time until 10% of units fail, then enter 0.1.

#### **Design Choices** Enter values for the following:

**Length of Test** is the length of time to run the experiment.

**Number of Units Under Test** is the number of units in the experiment. If augmenting a previous experiment, enter the number of units from the previous experiment plus the number of units that you want to run for the next experiment. If designing an initial experiment, enter the number of units that you want to run.

#### 7. Click Continue.

New outline nodes appear as shown in Figure 10.5.




Figure 10.5 Additional Outline Nodes

**Candidate Runs** Enter the minimum and maximum number of runs allowed at each level of the acceleration factor. If augmenting a previous experiment, enter the number of units already run at each level for the Minimum Units.

**Parameter Variance for Balanced Design** Gives the expected variances and covariances for the acceleration model parameters after running and analyzing the balanced design (same number of runs at each level of the acceleration factor). These values are valid under the assumption that the values for the prior mean and variance are correct.

These values can be compared to the ones entered under Prior Variance Matrix, to see whether the balanced design can improve the variances of the parameter estimates. They can also be compared to the final parameter variances for the optimal design, after clicking **Make Design**.

**Distribution Profiler** Use the profiler to visualize the probability that a unit will fail at different values of the acceleration factor and time.

- 8. Click **Update Profiler** to update the profiler if changes are made to the distribution choice, means, variances, design choices, or candidate runs.
- 9. Click **Make Design** to create the optimal design and display the results.




Figure 10.6 Design Results

The information below describes the results you get after clicking **Make Design**.

The **Design** report gives the expected number of failures for each level of the acceleration factor. Also given is the probability that none of the units at this setting will fail.

The Parameter Variance for Optimal Design report gives the variances and covariances for the acceleration model parameters for the optimal design. These values are valid under the assumption that the values for the prior mean and variance are correct. These values can be compared to those under Parameter Variance for Balanced Design to determine whether the optimal design is able to reduce the parameter variances more than the balanced design.

The **Optimality Criteria** report gives the values of the optimality criterion for the optimal design. For more information about the optimality criterion, see "Platform Options," p. 224.

Platform Options

224

The **Make Design** button updates the optimal design if any changes are made to the distribution choice, prior means or variances, design choices, or candidate runs.

The **Make Test Plan** button creates a data table with the acceleration factor levels and the number of units to include in the experiment for each level.

The Make Table button creates a table that can be used for data collection during the experiment.

# **Platform Options**

The red triangle menu for Accelerated Life Test Plan has the following options:

**Simulate Responses** Adds simulated responses to the table when you click **Make Table**.

**ALT Optimality Criterion** Gives three choices for design optimality:

Make D-Optimal Design creates a design that minimizes the variance of the model coefficients.

Make Time I-Optimal Design creates a design that minimizes the prediction variance when predicting the time to failure for the probability given in "Diagnostic Choices," p. 222.

**Make Probability I-Optimal Design** creates a design that minimizes the prediction variance when predicting the failure probability for the times given in "Diagnostic Choices," p. 222.

**Advanced Options** Gives the N Monte Carlo Spheres option, which affects the speed and accuracy of numerical integration. For more information, see "Advanced Options for the Nonlinear Designer," p. 245 in the "Nonlinear Designs" chapter.


# **Example**

This example shows how to use the Accelerated Life Test Design to augment an existing design.

An accelerated life test was performed, and the results are in the Capacitor ALT.jmp sample data table (in the Design Experiment folder). Fifty units were tested at each of three temperatures (85°, 105°, and 125° Celsius) for 1500 hours. The resulting model is used to predict the probability of failure at 100,000 hours at normal use conditions of 25°.

- 1. Open the Capacitor ALT.jmp data table in the Design Experiment folder.
- 2. Run the **Fit Life by X** table script.
- 3. In the Distribution Profiler, enter 25 for Temperature and 100,000 for hours. The profiler is shown in Figure 10.7.

Figure 10.7 Distribution Profiler for Capacitor Model



The predicted probability of failure at 100,000 hours at 25° is 0.00358, with a confidence interval of 0.00056 to 0.0227. The analyst wants to decrease the width of the confidence interval. To do so, the experiment needs to be augmented with additional data.

To augment the design in the optimal way, use the Accelerated Life Test Design platform. Follow the steps below to use the platform:

- Select DOE > Accelerated Life Test Design.
- 2. Select Design for one accelerating factor and click Continue.
- 3. Enter Temperature for **Factor Name**.
- 4. Enter 5 for Number of Levels.
- 5. Enter 25 for both Low Usage Condition and High Usage Condition.
- 6. Click Continue.
- 7. Enter 85, 95, 105, 115, and 125 for the Temperature Level Values.
- 8. Select Weibull for Distribution Choice.
- 9. Under **Prior Mean**, enter the acceleration model parameters from the Fit Life by X Estimates report. See Figure 10.8.
  - Enter −35.200 for Intercept.
  - Enter 1.389 for Temperature.
  - Enter 1.305 for scale.

Figure 10.8 Fit Life by X Estimates

<b>△</b> Estimates					
Parameter	Estimate	Std Error	Lower 95%	Upper 95%	
βΟ	-35.19979	4.6912686	-44.39451	-26.00508	
β1	1.38891	0.1566297	1.08192	1.69589	
σ	1.30471	0.1119128	1.08536	1.52405	


Example

In the Fit Life by X output, under the Estimates report, is the Covariance Matrix report. Note the variances for the acceleration model parameters are 22, 0.025, and 0.013. These values will be compared to our final results at the end.

- 10. Enter 100,000 for both boxes for Time range of interest.
- 11. Enter 1500 for Length of Test.
- 12. Enter 300 for **Number of Units Under Test**. The previous experiment used 150 units, and the next experiment uses 150 units, for a total of 300.

The completed window is shown in Figure 10.9.

Figure 10.9 Completed Window



#### 13. Click Continue.

- 14. To account for the units in the previous experiment, enter the following under Candidate Runs.
  - Enter 50 for Minimum Units for 85°.
  - Enter 50 for Minimum Units for 105°.

- Enter 50 for Minimum Units for 125°.
- 15. From the red triangle menu for Accelerated Life Test Plan, select **ALT Optimality Criterion > Make Probability I-Optimal Design**.
- 16. Click Make Design.

The optimal experimental design is returned, along with other results. See Figure 10.10.

Figure 10.10 Optimal Design

Design					
		Expected	All Censored		
Temperature	N Units	Failures	Probability		
85	184	25.3	0.0		
95	0	0.0	0.0		
105	50	30.0	0.0		
115	0	0.0	0.0		
125	66	65.4	0.0		
△ Parameter Variance for Optimal Design					
Effect I	ntercept	Temperatu	re scale		
Intercept	11.9646	-0.397	74 -0.2060		
Temperature		0.0133	22 0.00691		
scale			0.00994		
△ Optimality Criteria					
D Criterion	-13.6	35			
Quantile Criterio	n 1.063	36			
Probability Crite	rion 0.38				

The optimal design is computed based on the Number of Units Under Test, Candidate Runs, and other information that you specified earlier. The optimal design consists of the following number of units at each temperature level:

- 184 units at 85°. Since the previous experiment used 50 units, 134 additional units are needed.
- 0 units at 95°. The next experiment will not utilize any units at this level.
- 50 units at 105°. Since the previous experiment already used 50 units, no additional units are needed.
- 0 units at 115°. The next experiment will not utilize any units at this level.
- 66 units at 125°. Since the previous experiment used 50 units, 16 additional units are needed.

As we entered earlier, a total of 134+16=150 units are used for the new experiment.

An estimate of the acceleration model parameters variances is given. Note that, due to the additional data, all three variances are smaller than before from the original Fit Life by X report.

In the Profiler, enter 25 for Temperature and 100,000 for Time. The estimated probability of failure is 0.00357, with an estimated confidence interval of 0.00106 to 0.01201. This interval is narrower than the one from the previous experiment, as a result of the additional units to be tested.

To decrease the interval further, try entering more than 300 units to be tested.

228

# **Nonlinear Designs**



Design of experiments with models that are nonlinear in their parameters is available using either the DOE menu or the JMP Starter DOE category.

Nonlinear designs offer both advantages and disadvantages compared to designs for linear models.

On the positive side, predictions using a well chosen model are likely to be good over a wider range of factor settings. It is also possible to model response surfaces with more curvature and with asymptotic behavior.

On the negative side, the researcher needs a greater understanding of both the system and of the nonlinear design tool.

# Contents

Exa	amples of Nonlinear Designs	231
	Using Nonlinear Fit to Find Prior Parameter Estimates	231
	Creating a Nonlinear Design with No Prior Data	237
Cre	eating a Nonlinear Design	241
	Identify the Response and Factor Column with Formula	241
	Set Up Factors and Parameters in the Nonlinear Design Dialog	242
	Enter the Number of Runs and Preview the Design	243
	Make Table or Augment the Table.	244
Ad	vanced Options for the Nonlinear Designer	245

## **Examples of Nonlinear Designs**

The Nonlinear Designer allows scientists to generate optimal designs and optimally augment data for fitting models that are nonlinear in their parameters. Such models, when they are descriptive of the underlying process, can yield more accurate prediction of process behavior than is possible with the standard polynomial models.

To use the Nonlinear Designer, you first need a data table that has

- one column for each factor
- one column for the response
- a column that contains a formula showing the functional relationship between the factor(s) and the response.

This is the same format for a table you would supply to the nonlinear platform for modeling.

The first example in this section describes how to approach creating a nonlinear design when there is prior data. The second example describes how to approach creating the design without data, but with reasonable starting values for the parameter estimates.

## **Using Nonlinear Fit to Find Prior Parameter Estimates**

Suppose you have already collected experimental data and placed it in a JMP data table. That table can be used to create a nonlinear design for improving the estimates of the model's parameters.

To follow along with this example, open Chemical Kinetics.jmp from the Nonlinear Examples folder found in the sample data installed with JMP.

Chemical Kinetics.jmp (Figure 11.1) contains a column (Model (x))whose values are formed by a formula with a poor guess of the parameter values.

Figure 11.1	Chemical	Kinetics.jmp
-------------	----------	--------------

▼ Chemical Kinetics	4 💌			
Notes Meyers, R.H. (198	•	Velocity (y)	Concentration	Model (x)
	1	0.0773895	0.417	0.04
Columns (3/0)	2	0.0688714	0.417	0.04
✓ Velocity (y)	3	0.0819351	0.417	0.04
▲ Concentration	4	0.0737034	0.833	0.04
▲ Model (x) ♣	5	0.0738753	0.833	0.04
	6	0.0712396	0.833	0.04
▼ Rows	7	0.065042	1.67	0.04
All rows 13	8	0.0547667	1.67	0.04
Selected 0	9	0.0497128	3.75	0.04
Excluded 0	10	0.0642727	3.75	0.04
Hidden 0	11	0.0613005	6.25	0.04
Labelled 0	12	0.0643576	6.25	0.04
	13	0.0393892	6.25	0.04


#### Examples of Nonlinear Designs

232

First, fit the data to the model using nonlinear least squares to get better parameter values.

- 1. Select Analyze > Modeling > Nonlinear.
- 2. Select Velocity (y) and click Y, Response on the nonlinear launch dialog.
- 3. Select Model (x) and click **X**, **Predictor Formula** (see Figure 11.2). Note that the formula given by Model (X) shows in the launch dialog.

Figure 11.2 Initial Nonlinear Analysis Launch Dialog




- 4. Click **OK** on the launch dialog to see the Nonlinear control panel.
- 5. Click the **Go** button on the Nonlinear control panel to see the results (Figure 11.3).

The **Save Estimates** button adds the new fitted parameter values in the **Model** (x) column in the Chemical Kinetics.jmp data table.

The **Confidence Limits** button computes confidence intervals used to create a nonlinear design.


The ranges for LowerCL and UpperCL are the intervals for Vmax and k. They are asymptotically normal. Use these limits to create a nonlinear design in JMP.

Figure 11.3 Nonlinear Fit Results



- 6. Click the Confidence Limits button to produce confidence intervals.
- 7. Click **Save Estimates** to add the new fitted parameter values in the Model (x) column in the Chemical Kinetics.jmp data table, which contains the formula:

Figure 11.4 Formula Produced by Save Estimates



**Note:** Leave the nonlinear analysis report open because these results are needed in the DOE nonlinear design dialog described next.


Now create a design for fitting the model's nonlinear parameters.

1. With the Chemical Kinetics.jmp data table open, select **DOE > Nonlinear Design**.

**Examples of Nonlinear Designs** 


2. Complete the launch dialog the same way as the Nonlinear Analysis launch dialog shown previously. That is, Select Velocity (y) and click Y, Response. Select Model (x) and click the X, Predictor Formula. Figure 11.5 shows the completed dialog.

Figure 11.5 Initial Nonlinear Design Launch Dialog



3. Click **OK** to see the completed Design panels for factors and parameters, as shown in Figure 11.6.

Figure 11.6 Nonlinear Design Panels for Factors and Parameters



Note that in Chemical Kinetics.jmp (Figure 11.1), the range of data for Concentration goes from 0.417 to 6.25. Therefore, these values initially appear as the high and low values in the Factors control panel as follows:


4. Change the factor range for Concentration to a broader interval—from 0.1 to 7 (Figure 11.7).

Note that the *a priori* distribution of the parameters Vmax and k is Normal, which is correct for this example. Change the current level of uncertainty in the two parameters using the analysis results.

 Look back at the analysis report in Figure 11.3 and locate the upper and lower confidence limits for Vmax and k in the Solution table. Change the values for Vmax and k to correspond to those limits, as shown in Figure 11.7.

Now you have described the current level of uncertainty of the two parameters.

Figure 11.7 Change Values for Factor and Parameters



- 6. If necessary, type the desired number of runs (17 is the default value for this example) into the text box. Use commands from the menu on the Nonlinear Design title bar to get the best possible design:
- 7. Select **Number of Starts** from the menu on the title bar and enter 100 in the text box.
- 8. Select Advanced Options > Number of Monte Carlo Samples and enter 2 in the text box.
- 9. Click **Make Design** to preview the design (Figure 11.8). Your results might differ from those shown for the additional runs.

Examples of Nonlinear Designs

Figure 11.8 Selecting the Number of Runs


⊿ Design					
Run	Concentration	Velocity (y)			
1	0.417	0.07739			
2	0.417	0.068871			
3	0.417	0.081935			
4	0.833	0.073703			
5	0.833	0.073875			
6	0.833	0.07124			
7	1.67	0.065042			
8	1.67	0.054767			
9	3.75	0.049713			
10	3.75	0.064273			
11	6.25	0.061301			
12	6.25	0.064358			
13	6.25	0.039389			
14	0.10551				
15	0.205311				
16	0.10551				
17	0.10551				

#### 10. Click Make Table.

This creates a new JMP design table (Figure 11.9) whose rows are the runs defined by the nonlinear design.

**Note:** This example creates a new table to avoid altering the sample data table Chemical Kinetics.jmp. In most cases, however, you can augment the original table using the **Augment Table** option in the Nonlinear Designer instead of making a new table. This option adds the new runs shown in the Design to the existing data table.

Figure 11.9 Making a Table with the Nonlinear Designer



The new runs use the wider interval of allowed concentration, which leads to more precise estimates of k and Vmax.


#### **Creating a Nonlinear Design with No Prior Data**

This next example describes how to create a design when you have not yet collected data, but have a guess for the unknown parameters.

To follow along with this example, open Reaction Kinetics Start.jmp, found in the Design Experiment folder in the sample data installed with JMP. Notice that the table is a template. That is, the table has columns with properties and formulas, but there are no observations in the table. The design has not yet been created and data have not been collected.

This table is used to supply the formula in the yield model column to the Nonlinear DOE platform. The formula is used to create a nonlinear design for fitting the model's nonlinear parameters.

#### Figure 11.10 Yield Model Formula




This model is from Box and Draper (1987). The formula arises from the fractional yield of the intermediate product in a consecutive chemical reaction. It is written as a function of time and temperature.

- 1. With the Reaction Kinetics Start.jmp data table open, select **DOE > Nonlinear Design** to see the initial launch dialog.
- 2. Select observed yield and click Y, Response.
- 3. Select yield model (the column with the formula) and click X, Predictor Formula.


The completed dialog should look like the one in Figure 11.11.

Figure 11.11 Nonlinear Design launch Dialog



- 4. Click **OK** to see the nonlinear design Factors and Parameters panels in Figure 11.12.
- 5. Change the two factors' values to be a reasonable range of values. (In your experiment, these values might have to be an educated guess.) For this example, use the values 510 and 540 for Reaction Temperature. Use the values 0.1 and 0.3 for Reaction Time.
- 6. Change the values of the parameter t1 to 25 and 50, and t3 to 30 and 35.
- 7. Click on the Distribution of each parameter and select **Uniform** from the menu to change the distribution from the default **Normal** (see Figure 11.12).
- 8. Change the number of runs to 12 in the Design Generation panel.

Figure 11.12 Change Factor Values, Parameter Distributions, and Number of Runs




9. Click Make Design, then Make Table. Your results should look similar to those in Figure 11.13.

Figure 11.13 Design Table

■ Nonlinear Design	4 💌				
Design Nonlinear Design	•	Reaction Temperature	Reaction Time	observed yield	yield model
■ Model	1	540	0.107270436	•	56.745725
	2	540	0.3	•	58.093235
Columns (4/0)	3	540	0.3	•	58.093235
A Reaction Temperature *	4	510	0.1	•	11.2590804
A Reaction Time *	5	540	0.3	•	58.093235
d observed yield ★ vield model +	6	510	0.1	•	11.2590804
a yield Model 4	7	526.2712314	0.1	•	30.7102877
Rows	8	540	0.3	•	58.093235
All rows 12	9	540	0.107270436	•	56.745725
Selected 0	10	526.2712314	0.1	•	30.7102877
Excluded 0	11	540	0.107270436	•	56.745725
Hidden 0	12	540	0.107270436	•	56.745725
Labelled 0					

10. To analyze data that contains values for the response, observed yield, open Reaction Kinetics.jmp from the Design Experiment folder in the sample data installed with JMP (Figure 11.14).


Figure 11.14 Reaction Kinetics.jmp



First, examine the design region with an overlay plot.

- 11. Select Graph > Overlay Plot.
- 12. Remove all existing column assignments.
- 13. Select Reaction Temperature and click Y
- 14. Select Reaction Time and click X as shown in the Overlay Plot launch dialog in Figure 11.15.
- 15. Click **OK** to see the overlay plot in Figure 11.15.

Figure 11.15 Create an Overlay Plot



Notice that the points are not at the corners of the design region. In particular, there are no points at low temperature and high time—the lower right corner of the graph.

- 16. Select Analyze > Modeling > Nonlinear.
- 17. Remove all existing column assignments.
- 18. Select observed yield and click Y, Response.
- 19. Select yield model and click the X, Predictor Formula, then click OK.
- 20. Click **Go** on the Nonlinear control panel.
- 21. Now, choose Profilers > Profiler from the red triangle menu on the Nonlinear Fit title bar.
- 22. To maximize the yield, choose **Maximize Desirability** from the red triangle menu on the Prediction Profiler title bar.

The maximum yield is approximately 63.5% at a reaction temperature of 540 degrees Kelvin and a reaction time of 0.1945 minutes.




Figure 11.16 Time and Temperature Settings for Maximum Yield

### **Creating a Nonlinear Design**

To begin, open a data table that has a column whose values are formed by a formula (for details about formulas, see the *Using JMP*). This formula must have parameters.


Select **DOE >Nonlinear Design**, or click the **Nonlinear Design** button on the JMP Starter **DOE** page. Then, follow the steps below:

- "Identify the Response and Factor Column with Formula," p. 241
- "Set Up Factors and Parameters in the Nonlinear Design Dialog," p. 242
- "Enter the Number of Runs and Preview the Design," p. 243
- "Make Table or Augment the Table," p. 244

### Identify the Response and Factor Column with Formula

- 1. Open a data table that contains a column whose values are formed by a formula that has parameters. This example uses Corn.jmp from the Nonlinear Examples folder in the sample data installed with JMP.
- 2. Select **DOE** > **Nonlinear Design** to see the initial launch dialog.
- 3. Select yield and click Y, Response. The response column cannot have missing values.
- 4. Select quad and click **X**, **Predictor Formula**. The quad variable has a formula that includes nitrate and three parameters (Figure 11.17).
- 5. Click **OK** on the launch dialog to see the Nonlinear Design DOE panels.


Figure 11.17 Identify Response (Y) and the Column with the Nonlinear Formula (X)



### Set Up Factors and Parameters in the Nonlinear Design Dialog

First, look at the formula for quad, shown in Figure 11.18, and notice there are three parameters. These parameters show in the Parameters panel of the Nonlinear design dialog, with initial parameter values.

Figure 11.18 Formula for quad has Parameters a, b, and c



Use Figure 11.19 to understand how to set up factor and parameter names and values.

- The initial values for the factor and the parameters are reasonable and do not need to be changed.
- If necessary, change the Distribution of the parameters to Uniform, as shown in Figure 11.19.





Figure 11.19 Example of Setting Up Factors and Parameters

#### **Enter the Number of Runs and Preview the Design**

- 1. The Design Generation panel shows 150 as the default number of runs. This number includes observations in the current data. 147 runs are desired. Since there are originally 144 rows, 3 additional runs need to be added. Enter 147 in the **Number of Runs** edit box.
- 2. Click **Make Design** before creating the data table to preview the design. Figure 11.20 shows a partial listing of the design.


Figure 11.20 Example Preview Design



#### Make Table or Augment the Table

3. The last step is to click either Make Table or Augment Table. The Make Table command creates a new table (Figure 11.21) with all runs included. The Augment Table command adds the new runs to the existing table.

Figure 11.21 Partial Listing of an Example Nonlinear Design Table




## **Advanced Options for the Nonlinear Designer**

For advanced users, the Nonlinear Designer has the two additional options, as shown in Figure 11.22. These advanced options are included because finding nonlinear DOE solutions involves minimizing the integral of the log of the determinant of the Fisher information matrix with respect to the prior distribution of the parameters. These integrals are complicated and have to be calculated numerically.

The way the integration is done for Normal distribution priors uses a numerical integration technique where the integral is reparameterized into a radial direction, and the number of parameters minus one angular directions. The radial part of the integral is handled using Radau-Gauss-Laguerre quadrature with an evaluation at radius=0. A randomized Mysovskikh quadrature is used to calculate the integral over the spherical part, which is equivalent to integrating over the surface of a hypersphere.

**Note:** If some of the prior distributions are not Normal, then the integral is reparameterized so that the new parameters have normal distribution, and then the radial-spherical integration method is applied. However, if the prior distribution set for the parameters does not lend itself to a solution, sometimes the process fails and gives the message that the Fisher information is singular in a region of the parameter space, and advises changing the prior distribution or the ranges of the parameters.

Figure 11.22 Advanced Options for the Nonlinear Designer



The following is a technical description for these two advanced options:

**Number of Monte Carlo Samples** sets the number of octahedra per sphere. Because each octahedron is a fixed unit, this option can be thought of as setting the number of octahedra per sphere.

**N Monte Carlo Spheres** are the number of nonzero radius values used. The default is two spheres and one center point. Each radial value requires integration over the angular dimensions. This is done by constructing a certain number of hyperoctahedra (the generalization of an octagon in arbitrary dimensions), and randomly rotating each of them.

**Technical Note:** The reason for the approach given by these advanced options is to get good integral approximations much faster than using standard methods. For instance, with six parameters, using two radii and one sample per sphere, these methods give a generalized five- point rule that needs only 113 observations to get a good approximation. Using the most common approach (Simpson's rule) would need

246 **Nonlinear Designs** Chapter 11

Advanced Options for the Nonlinear Designer

 $5^6$  = 15,625 evaluations. The straight Monte Carlo approach also requires thousands of function evaluations to get the same level of quality in the answer. For more details, see Gotwalt, Jones, and Steinberg (2009).

Keep in mind that if the number of radii is set to zero, then just the center point is used, which gives a local design that is optimal for a particular value of the parameters. For some people this is good enough for their purposes. These designs are created much faster than if the integration is performed.

# Chapter 12

# **Taguchi Designs**



Quality was the watchword of 1980s, and Genichi Taguchi was a leader in the growth of quality consciousness. One of Taguchi's technical contributions to the field of quality control was a new approach to industrial experimentation. The purpose of the *Taguchi method* was to develop products that worked well in spite of natural variation in materials, operators, suppliers, and environmental change. This is *robust* engineering.

Much of the Taguchi method is traditional. His *orthogonal arrays* are two-level, three-level, and mixed-level fractional factorial designs. The unique aspects of his approach are the use of *signal* and *noise* factors, *inner* and *outer arrays*, and *signal-to-noise ratios*.

The goal of the Taguchi method is to find control factor settings that generate acceptable responses despite natural environmental and process variability. In each experiment, Taguchi's design approach employs two designs called the *inner* and *outer* array. The Taguchi experiment is the cross product of these two arrays. The *control* factors, used to tweak the process, form the inner array. The *noise* factors, associated with process or environmental variability, form the outer array. Taguchi's *signal-to-noise ratios* are functions of the observed responses over an outer array. The Taguchi designer supports all these features of the Taguchi method. You choose from inner and outer array designs, which use the traditional Taguchi orthogonal arrays, such as L4, L8, and L16.

Dividing system variables according to their signal and noise factors is a key ingredient in robust engineering. Signal factors are system control inputs. Noise factors are variables that are typically difficult or expensive to control.

The inner array is a design in the signal factors and the outer array is a design in the noise factors. A signal-to-noise ratio is a statistic calculated over an entire outer array. Its formula depends on whether the experimental goal is to maximize, minimize or match a target value of the quality characteristic of interest.

A Taguchi experiment repeats the outer array design for each run of the inner array. The response variable in the data analysis is not the raw response or quality characteristic; it is the signal-to-noise ratio.

The **Taguchi** designer in JMP supports signal and noise factors, inner and outer arrays, and signal-to-noise ratios as Taguchi specifies.

# **Contents**

The Taguchi Design Approach
Taguchi Design Example24
Analyze the Data
Creating a Taguchi Design25
Detail the Response and Add Factors
Choose Inner and Outer Array Designs25
Display Coded Design
Make the Design Table 25

# The Taguchi Design Approach

The Taguchi method defines two types of factors: control factors and noise factors. An *inner* design constructed over the control factors finds optimum settings. An *outer* design over the noise factors looks at how the response behaves for a wide range of noise conditions. The experiment is performed on all combinations of the inner and outer design runs. A performance statistic is calculated across the outer runs for each inner run. This becomes the response for a fit across the inner design runs. Table 12.1 lists the recommended performance statistics.

<b>Table 12.1</b> F	Recommended	Performance	Statistics
---------------------	-------------	-------------	------------

Goal	S/N Ratio Formula
nominal is best	$\frac{S}{N} = 10\log\left(\frac{\overline{Y}^2}{s^2}\right)$
larger-is-better (maximize)	$\frac{S}{N} = -10\log\left(\frac{1}{n}\sum_{i}\frac{1}{Y_{i}^{2}}\right)$
smaller-is-better (minimize)	$\frac{S}{N} = -10\log\left(\frac{1}{n}\sum_{i}Y_{i}^{2}\right)$

# **Taguchi Design Example**

The following example is an experiment done at Baylock Manufacturing Corporation and described by Byrne and Taguchi (1986). The objective of the experiment is to find settings of predetermined control factors that simultaneously maximize the adhesiveness (pull-off force) and minimize the assembly costs of nylon tubing.

To follow along with this example, open the Byrne Taguchi Data.jmp table found in the Design Experiment folder of the Sample Data installed with JMP. Or, generate the original design table on your own using DOE > Taguchi Arrays.

Table 12.2 shows the signal and noise factors in the Byrne Taguchi Data for this example.

Table 12.2 Signal and Noise Factors

Factor Name	Туре	Levels	Comment
Interfer	control	3	tubing and connector interference
Wall	control	3	the wall thickness of the connector
Depth	control	3	insertion depth of the tubing into the connector

Taguchi Design Example

Table 12.2 Signal and Noise Factors (Continued)


Factor Name	Туре	Levels	Comment
Adhesive	control	3	percent adhesive
Time	noise	2	the conditioning time
Temperature	noise	2	temperature
Humidity	noise	2	the relative humidity

#### To start this example:

- 1. Select **DOE** > **Taguchi Arrays**.
- 2. Click the red triangle icon on the Taguchi Design title bar and select **Load Factors**.
- 3. When the Open File dialog appears, open the factors table, Byrne Taguchi Factors.jmp found in the Design Experiment Sample Data folder installed with JMP.

The factors panel then shows the four three-level control (signal) factors and three noise factors, as shown in Figure 12.1.

Figure 12.1 Response, and Signal and Noise Factors for the Byrne-Taguchi Example



- 4. Highlight **L9-Taguchi** to give the L9 orthogonal array for the inner design.
- 5. Highlight L8 to give an eight-run outer array design.
- 6. Click Continue.

The outer design has three two-level factors. A full factorial in eight runs is generated. However, it is only used as a guide to identify a new set of eight columns in the final JMP data table—one for each combination of levels in the outer design.

7. Click **Make Table** to create the design table shown in Figure 12.2.

4															
•	Interfer	Wall	Depth	Adhesive	Pattern		+	-+-	-++	+	+-+	++-	+++	Mean	SN Ratio
1	1	1	1	1		•	•	•	•	•	•	•	•	•	•
2	1	2	2	2	-000	•	•			•	•	•	•	•	•
3	1	3	3	3	-+++	•	•	•	•	•	•	•	•	•	•
4	2	1	2	3	0-0+	•	•	•		•	•	•	•	•	•
5	2	2	3	1	00+-	•	•	•	•	•	•	•	•	•	•
6	2	3	1	2	0+-0	•	•	•		•	•	•	•	•	•
7	3	1	3	2	+-+0	•	•			•	•	•	•	•	•
8	3	2	1	3	+0-+	•	•	•	•	•	•	•	•	•	•
9	3	3	2	1	++0-	•	•	•	•	•	•	•	•	•	•

Now, suppose the pull-off adhesive force measures are collected and entered into the columns containing missing data, as shown in Figure 12.3. The missing data column names are appended with the letter Y before the levels (+ or –) of the noise factors for that run. For example, Y--- is the column of measurements taken with the three noise factors set at their low levels.

8. To see the completed experiment, open the data table, Byrne Taguchi Data.jmp found in the Design Experiment Sample Data folder installed with JMP. Figure 12.3 shows the completed design.

Figure 12.3 Complete Taguchi Design Table (Byrne Taguchi Data.jmp)

4 💌															
•	Interfer	Wall	Depth	Adhesive	Pattern	Y	Y+	Y.+.	Y.++	Y+	Y+.+	Y++.	Y+++	MeanY	SN Ratio Y
1	1	1	1	1		15.6	9.5	16.9	19.9	19.6	19.6	20	19.1	17.525	24.02534
2	1	2	2	2	-000	15	16.2	19.4	19.6	19.7	19.8	24.2	21.9	19.475	25.52164
3	1	3	3	3	-+++	16.3	16.7	19.1	15.6	22.6	18.2	23.3	20.4	19.025	25.33476
4	2	1	2	3	0-0+	18.3	17.4	18.9	18.6	21	18.9	23.2	24.7	20.125	25.90425
5	2	2	3	1	00+-	19.7	18.6	19.4	25.1	25.6	21.4	27.5	25.3	22.825	26.90753
6	2	3	1	2	0+-0	16.2	16.3	20	19.8	14.7	19.6	22.5	24.7	19.225	25.32574
7	3	1	3	2	+-+0	16.4	19.1	18.4	23.6	16.8	18.6	24.3	21.6	19.85	25.71081
8	3	2	1	3	+0-+	14.2	15.6	15.1	16.8	17.8	19.6	23.2	24.4	18.3375	24.83231
9	3	3	2	1	++0-	16.1	19.9	19.3	17.3	23.1	22.7	22.6	28.6	21.2	26.15198

The column named SN Ratio Y is the performance statistic computed with the formula shown below. In this case, it is the "larger-the-better" (LTB) formula, which is –10 times the common logarithm of the average squared reciprocal:

252

This expression is large when all of the individual *y* values are large.

#### Analyze the Data


Taguchi Design Example

The data in Byrne Taguchi Data.jmp are now ready to analyze. The goal of the analysis is to find factor settings that maximize both the mean and the signal-to-noise ratio.

1. Click the red triangle icon next to Model on the upper left of the data table and select **Run Script**. The Model script produces the Fit Model dialog shown in Figure 12.4.

The Fit Model dialog that appears automatically has the appropriate effects. It includes the main effects of the four signal factors. The two responses are the mean (Mean Y) and signal-to-noise ratio (SN Ratio Y) over the outer array.

Figure 12.4 Fit Model Dialog for Taguchi Data




Click Run on the Fit Model dialog.

The prediction profiler is a quick way to find settings that give the highest signal-to-noise ratio for this experiment.

3. To open the Prediction Profiler, click the red triangle on the Response Mean Y title bar and select **Factor Profiling > Profiler**.

The profile traces (Figure 12.5) indicate that different settings of the first three factors would increase SN Ratio Y.


Figure 12.5 The Prediction Profiler



- 4. To find optimal settings, click the red triangle on the Prediction Profiler title bar and select **Desirability Functions**. This adds the row of traces and a column of function settings to the profiler, as shown in Figure 12.6. The default desirability functions are set to larger-is-better, which is what you want in this experiment. See *Modeling and Multivariate Methods* for more details about the prediction profiler.
- Again click the red triangle on the Prediction Profiler title bar and select Maximize Desirability to automatically set the prediction traces that give the best results according to the desirability functions.

In this example, the settings for Interfer and Wall changed from 1 to 2. (See Figure 12.5 and Figure 12.6). The Depth setting changed from 1 to 3. The settings for Adhesive did not change. These new settings increased the signal-to-noise ratio from 24.0253 to 26.9075.

Figure 12.6 Best Factor Settings for Byrne Taguchi Data



# Creating a Taguchi Design

To start a Taguchi design, select **DOE** >**Taguchi Arrays**, or click the **Taguchi Arrays** button on the JMP Starter **DOE** page. Then, follow the steps below:


- "Detail the Response and Add Factors," p. 254
- "Choose Inner and Outer Array Designs," p. 255
- "Display Coded Design," p. 256
- "Make the Design Table," p. 257

#### **Detail the Response and Add Factors**

The Responses panel has a single default response. The steps for setting up the details of this response are outlined in Figure 12.7. For information on importance weights and lower and upper limits, see "Understanding Response Importance Weights," p. 66.

- 1. Double-click to edit the response name.
- 2. Click to change the response goal: Larger Is Better, Nominal is Best, Smaller is Better, or None.
- 3. Click to enter lower and upper limits and importance weights.


Figure 12.7 Setting Up the Response



The steps for setting up the factors are outlined in Figure 12.8.

- Click to add a signal, then select a signal type: 2 Level, or 3 Level.
   Or click to add a noise.
- 2. Double-click to edit the factor name.
- 3. To change the value of a signal or noise, click and then type the new value.

Figure 12.8 Entering Factors




When you finish adding factors, click Continue.

#### **Choose Inner and Outer Array Designs**

Your choice for inner and outer arrays depends on the number and type of factors you have. Figure 12.9 shows the available inner array choices when you have eight signal factors. If you also have noise factors, choices include designs for the outer array. To follow along, enter eight two-level Signal factors and click **Continue**. Then highlight the design you want and again click **Continue**. This example uses the L12 design.

Figure 12.9 Selecting a Design for Eight Signal Factors




If you did not specify a noise factor, after you click **Continue**, a dialog appears that asks you to specify how many times you want to perform each inner array run. Specify two (2) for this example.

#### **Display Coded Design**

After you select a design type, the Coded Design (Figure 12.10) is shown below the Factors panel.

Figure 12.10 Coding for Eight Factor L12 Design



The Coded Design shows the pattern of high and low values for the factors in each run. For more details on the coded design, see "Understanding Design Codes," p. 118.

### Make the Design Table

When you click **Make Table**, a table similar to that shown in Figure 12.11 appears. In the data table, each row represents a run. In the values for the **Pattern** variable, plus signs designate high levels and minus signs represent low levels.

Figure 12.11 Taguchi Design Table for Eight Factor L12 Design

▼ Taguchi Array L12	4 🗨													
Design Taguchi Array L13	2 💌	X1	X2	X3	X4	X5	X6	X7	X8	Pattern	run 1	run 2	Mean	SN Ratio
▼ Model	1	1	1	1	1	1	1	1	1		•	•	•	
▼ Columns (13/0)	2	1	1	1	1	1	2	2	2	++				
<b>L</b> X1 <b>★</b>	3	1	1	2	2	2	1	1	1	++	•			
<b>L</b> X2 <b>≭</b>	4	1	2	1	2	2	1	2	2	-+-++-++				
<b>L</b> X3 <b>≭</b>	5	1	2	2	1	2	2	1	2	-++-+-+				
<b></b> X4 <b>≭</b>	6	1	2	2	2	1	2	2	1	-+++-				
<b></b> X5 <b>≭</b>	7	2	1	2	2	1	1	2	2	+-++++				
<b>止</b> X6 <b>≭</b>	8	2	1	2	1	2	2	2	1	+-+-++-				
<b>L</b> X7 <b>★</b>	9	2	1	1	2	2	2	1	2	+++-+				
<u> </u>	10	2	2	2	1	1	1	1	2	++++				
L Pattern ✓ run 1	11	2	2	1	2	1	2	1	1	++-+-				
✓ run 1 ✓ run 2	12	2	2	1	1	2	1	2	1	+++-				
▲ Mean ♣														
▲ SN Ratio ♣								مسمم		-				

258

# **Augmented Designs**



If you treat experimentation as an iterative process, you can master the temptation to assume that one successful screening experiment has optimized your process. You can also avoid disappointment if a screening experiment leaves behind some ambiguities. The augment designer helps facilitate experimentation as an iterative process.

The augment designer modifies an existing design data table, supporting your iterative process. It gives the following five choices:

- · replicate the design a specified number of times
- add center points
- create a foldover design
- add axial points together with center points to transform a screening design to a response surface design
- · add runs to the design using a model that can have more terms than the original model

This chapter provides an overview of the augment designer. It also presents a case study of design augmentation.

# **Contents**

A D-Optimal Augmentation of the Reactor Example
Analyze the Augmented Design
Creating an Augmented Design271
Replicate a Design272
Add Center Points275
Creating a Foldover Design
Adding Axial Points
Adding New Runs and Terms
Special Augment Design Commands
Save the Design (X) Matrix
Modify the Design Criterion (D- or I- Optimality)282
Select the Number of Random Starts
Specify the Sphere Radius Value
Disallow Factor Combinations

**Augmented Designs** 

# A D-Optimal Augmentation of the Reactor Example


This example, adapted from Meyer, *et al.* (1996), demonstrates how to use the augment designer in JMP to resolve ambiguities left by a screening design. In this study, a chemical engineer investigates the effects of five factors on the percent reaction of a chemical process.

To begin, open Reactor 8 Runs.jmp found in the Design Experiment Sample Data folder installed with JMP. Then select Augment Design from the DOE menu. When the initial launch dialog appears:

- 1. Select Percent Reacted and click Y, Response.
- 2. Select all other variables except Pattern and click X, Factor.
- 3. Click **OK** on the launch dialog to see the Augment Design dialog in Figure 13.1.

**Note:** You can check **Group new runs into separate block** to add a blocking factor to any design. However, the purpose of this example is to estimate all two-factor interactions in 16 runs, which can't be done when there is the additional blocking factor in the model.


Figure 13.1 Augment Design Dialog for the Reactor Example



4. Now click **Augment** on the Augment Design dialog to see the display in Figure 13.2.

This model shown in Figure 13.2 is the result of the model stored with the data table when it was created by the Custom designer. However, the augmented design is to have 16 runs in order to estimate all two-factor interactions.


Figure 13.2 Initial Augmented Model



To continue with the augmented reactor design:

5. Choose **2nd** from the Interactions menu as shown in Figure 13.3. This adds all the two-factor interactions to the model. The Minimum number of runs given for the specified model is 16, as shown in the Design Generation text edit box.

Figure 13.3 Augmented Model with All Two-Factor Interactions



#### 6. Click Make Design.


JMP now computes D-optimally augmented factor settings, similar to the design shown in Figure 13.4.

Figure 13.4 D-Optimally Augmented Factor Settings

Desig	n					
Run	Feed Rate	Catalyst	Stir Rate	Temperature	Concentration	Percen Reacte
1	10	1	100	180	6	4
2	10	1	120	180	3	6
3	10	2	100	140	6	7
4	10	2	120	140	3	5
5	15	1	100	140	3	5
6	15	1	120	140	6	5
7	15	2	100	180	3	9
8	15	2	120	180	6	8
9	10	2	120	180	6	
10	15	2	100	180	6	
11	10	1	100	140	6	
12	15	2	100	140	3	
13	15	1	120	180	6	
14	10	1	100	140	3	
15	10	2	120	180	3	
16	15	1	120	140	3	

**Note:** The resulting design is a function of an initial random number seed. To reproduce the exact factor settings table in Figure 13.4, (or the most recent design you generated), choose **Set Random Seed** from the popup menu on the Augment Design title bar. A dialog shows the most recently used random number. Click **OK** to use that number again, or **Cancel** to generate a design based on a new random number. The dialog in Figure 13.5 shows the random number (12834729) used to generate the runs in Figure 13.4.

Figure 13.5 Specifying a Random Number



7. Click **Make Table** to generate the JMP table with *D*-Optimally augmented runs.

#### **Analyze the Augmented Design**

264


Suppose you have already run the experiment on the augmented data and recorded results in the Percent Reacted column of the data table.

1. To see these results, open Reactor Augment Data.jmp found in the Design Experiment Sample Data folder installed with JMP.

It is desirable to maximize Percent Reacted, however its column in this sample data table has a response limits column property set to **Minimize**.

- 2. Click the asterisk next to the Percent Reacted column name in the Columns panel of the data table and select Response Limits, as shown on the left in Figure 13.6.
- 3. In the Column Info dialog that appears, change the response limit to **Maximize**, as shown on the right in Figure 13.6.

Figure 13.6 Change the Response Limits Column Property for the Percent Reacted Column



You are now ready to run the analysis.

**Augmented Designs** 

4. To start the analysis, click the red triangle for Model in the upper left of the data table and select Run **Script** from the menu, as shown in Figure 13.7.

Figure 13.7 Completed Augmented Experiment (Reactor Augment Data.jmp)


Augmented Design	4 💌						Percent
Design Augmented Design	•	Feed Rate	Catalyst	Stir Rate	Temperature	Concentration	Reacted
Screening	1	10	1	100	180	6	44
<u> Model</u>	2	10	1	120	180	3	66
Run Script	3	10	2	100	140	6	70
Edit "	4	10	2	120	140	3	54
Delete	5	15	1	100	140	3	53
Сору	6	15	1	120	140	6	55
▼ Columns (6/0)	7	15	2	100	180	3	93
✓ Feed Rate ★	8	15	2	120	180	6	82
	9	15	1	100	180	3	
✓ Sur Rate ★ ✓ Temperature ★	10	15	1	120	140	3	•
✓ Concentration ★	11	10	1	100	180	3	•
✓ Percent Reacted ★	12	10	2	100	140	3	
	13	15	2	120	140	6	
	14	15	2	100	180	6	
Rows	15	10	2	120	180	6	
All rows 16	16	10	1	120	140	6	•
Selected 0							
Excluded 0							
Hidden 0							
Labelled 0							

The Model script, stored as a table property with the data, contains the JSL commands that display the Fit Model dialog with all main effects and two-factor interactions as effects.

5. Change the fitting personality on the Fit Model dialog from Standard Least Squares to Stepwise, as shown in Figure 13.8.

266


Figure 13.8 Fit Model Dialog for Stepwise Regression on Generated Model



6. When you click **Run**, the stepwise regression control panel appears. Click the check boxes for all the main effect terms.

**Important:** Choose **P-value Threshold** from the **Stopping Rule** menu, **Mixed** from the **Direction** menu, and make sure **Prob to Enter** is 0.050 and **Prob to Leave** is 0.100. These are not the default values. You should see the dialog shown in Figure 13.9.

267



0.0343

0.5779

689.0625

41.58173

0.6831

Figure 13.9 Initial Stepwise Model

Temperature(140,180) Entered

Concentration(3,6)

7. Click **Go** to start the stepwise regression and watch it continue until all terms are entered into the model that meet the **Prob to Enter** and **Prob to Leave** criteria in the Stepwise Regression Control panel.


137.084

132.386 🔾

143.23 134.638 💿


Figure 13.10, shows the result of this example analysis. Note that Feed Rate is out of the model while the Catalyst\*Temperature, Stir Rate\*Temperature, and the Temperature\*Concentration interactions have entered the model.

Figure 13.10 Completed Stepwise Model




- 8. After Stepwise is finished, click **Make Model** on the Stepwise control panel to generate this reduced model, as shown in Figure 13.11.
- Click Run and fit the reduced model to do additional diagnostic work, make predictions, and find the optimal factor settings.

Figure 13.11 New Prediction Model Dialog



The Analysis of Variance and Lack of Fit Tests in Figure 13.12, indicate a highly significant regression model with no evidence of Lack of Fit.


Figure 13.12 Prediction Model Analysis of Variance and Lack of Fit Tests



A D-Optimal Augmentation of the Reactor Example

The Sorted Parameter Estimates table in Figure 13.13 shows that Catalyst has the largest main effect. However, the significance of the two-factor interactions are of the same order of magnitude as the main effects. This is the reason that the initial screening experiment, shown in the chapter "Screening Designs," p. 101, had ambiguous results.

Figure 13.13 Prediction Model Estimates Plot



10. Choose Maximize Desirability from the menu on the Prediction Profiler title bar.

The prediction profile plot at the bottom in Figure 13.14 shows that maximum occurs at the high levels of Catalyst, Stir Rate, and Temperature and the low level of Concentration. At these extreme settings, the estimate of Percent Reacted increases from 65.17 to 98.38.




Figure 13.14 Maximum Percent Reacted

To summarize, compare the analysis of 16 runs with the analyses of reactor data from previous chapters:

- "Screening Designs," p. 101, the analysis of a screening design with only 8 runs produced a model with the five main effects and two interaction effects with confounding. None of the factors effects were significant, although the Catalyst factor was large enough to encourage collecting data for further runs.
- "Full Factorial Designs," p. 143, a full factorial of the five two-level reactor factors, 32 runs, was first subjected to a stepwise regression. This approach identified three main effects (Catalyst, Temperature, and Concentration) and two interactions (Temperature\*Catalyst, Contentration\*Temperature) as significant effects.
- By using a D-optimal augmentation of 8 runs to produce 8 additional runs, a stepwise analysis returned the same results as the analysis of 32 runs. The bottom line is that only half as many runs yielded the same information. Thus, using an iterative approach to DOE can save time and money.

# **Creating an Augmented Design**

The augment designer modifies an existing design data table. It gives the following five choices:

**Replicate** replicates the design a specified number of times. See "Replicate a Design," p. 272.

Creating an Augmented Design

**Add Centerpoints** adds center points. See "Add Center Points," p. 275.

**Fold Over** creates a foldover design. See "Creating a Foldover Design," p. 276.

**Add Axial** adds axial points together with center points to transform a screening design to a response surface design. See "Adding Axial Points," p. 277.

**Augment** adds runs to the design (augment) using a model, which can have more terms than the original model. See "Adding New Runs and Terms," p. 278.


### Replicate a Design

Replication provides a direct check on the assumption that the error variance is constant. It also reduces the variability of the regression coefficients in the presence of large process or measurement variability.

To replicate the design a specified number of times:


- 1. Open a data table that contains a design you want to augment. This example uses Reactor 8 Runs.jmp from the Design Experiment Sample Data folder installed with JMP.
- 2. Select **DOE** > **Augment Design** to see the initial dialog for specifying factors and responses.
- 3. Select Percent Reacted and click Y, Response.
- 4. Select all other variables (except Pattern) and click **X**, **Factor** to identify the factors you want to use for the augmented design (Figure 13.15).

Figure 13.15 Identify Response and Factors



- 5. Click **OK** to see the Augment Design panel shown in Figure 13.16.
- 6. If you want the original runs and the resulting augmented runs to be identified by a blocking factor, check the box beside **Group New Runs into Separate Block** on the Augment Design panel.

Figure 13.16 Choose an Augmentation Type




7. Click the **Replicate** button to see the dialog shown on the left in Figure 13.17. Enter the number of times you want JMP to perform each run, then click **OK**.

**Note:** Entering 2 specifies that you want each run to appear twice in the resulting design. This is the same as one replicate (Figure 13.17).

8. View the design, shown on the right in Figure 13.17.

Figure 13.17 Reactor Data Design Augmented With Two Replicates




### 274 Augmented Designs

Creating an Augmented Design

9. Click the disclosure icons next to Prediction Variance Profile and Prediction Variance Surface to see the profile and surface plots shown in Figure 13.18.

Figure 13.18 Prediction Profiler and Surface Plot



10. Click **Make Table** to produce the design table shown in Figure 13.19.

Augmented Design Design Augmented Design Feed Rate | Catalyst | Stir Rate | Temperature | Concentration Reacted Screening **▼** Model Columns (6/0) 🚄 Feed Rate 🛠 🚄 Catalyst 🛠 🚄 Stir Rate 🗱 🚄 Temperature 🛠 🚄 Concentration 🛠 🚄 Percent Reacted 🖈 Rows All rows Selected Excluded Hidden Labelled 

Figure 13.19 The Replicated Design

#### Add Center Points

Adding center points is useful to check for curvature and reduce the prediction error in the center of the factor region. Center points are usually replicated points that allow for an independent estimate of pure error, which can be used in a lack-of-fit test.

To add center points:

- 1. Open a data table that contains a design you want to augment. This example uses Reactor 8 Runs.jmp found in the Design Experiment Sample Data folder installed with JMP.
- 2. Select DOE > Augment Design.
- 3. In the initial Augment Design dialog, identify the response and factors you want to use for the augmented design (see Figure 13.15) and click **OK**.
- 4. If you want the original runs and the resulting augmented runs to be identified by a blocking factor, check the box beside Group new runs into separate block. (Figure 13.16 shows the check box location directly under the Factors panel.)
- 5. Click the **Add Centerpoints** button and type the number of center points you want to add. For this example, add two center points, and click **OK**.
- 6. Click **Make Table** to see the data table in Figure 13.20.

The table shows two center points appended to the end of the design.

Figure 13.20 Design with Two Center Points Added

Augmented Design	4 🔻						Percent
Design Augmented Design	•	Feed Rate	Catalyst	Stir Rate	Temperature	Concentration	Reacted
Screening	1	10	1	100	180	6	44
▼ Model	2	10	1	120	180	3	66
Columns (6/0)	3	10	2	100	140	6	70
▲ Feed Rate ★	4	10	2	120	140	3	54
✓ Catalyst ★	5	15	1	100	140	3	53
✓ Stir Rate   ★	6	15	1	120	140	6	55
🚄 Temperature 🛪	7	15	2	100	180	3	93
▲ Concentration ★	8	15	2	120	180	6	82
✓ Percent Reacted ★	9	12.5	1.5	110	160	4.5	
Rows	10	12.5	1.5	110	160	4.5	•
All rows 10							
Selected 0							
Excluded 0							
Hidden 0							
Labelled 0							

## **Creating a Foldover Design**

A foldover design removes the confounding of two-factor interactions and main effects. This is especially useful as a follow-up to saturated or near-saturated fractional factorial or Plackett-Burman designs.

To create a foldover design:

- 1. Open a data table that contains a design you want to augment. This example uses Reactor 8 Runs.jmp, found in the Design Experiment Sample Data folder installed with JMP.
- 2. Select **DOE** > Augment Design.
- 3. In the initial Augment Design dialog, identify the response and factors you want to use for the augmented design (see Figure 13.15) and click **OK**.
- 4. Check the box to the left of **Group new runs into separate block**. (Figure 13.16 shows the check box location directly under the Factors panel.) This identifies the original runs and the resulting augmented runs with a blocking factor.
- 5. Click the **Fold Over** button. A dialog appears that lists all the design factors.
- 6. Choose (select) which factors to fold. The default, if you choose no factors, is to fold on all design factors. If you choose a subset of factors to fold over, the remaining factors are replicates of the original runs. The example in Figure 13.21 folds on all five factors and includes a blocking factor.
- 7. Click **Make Table**. The design data table that results lists the original set of runs as block 1 and the new (foldover) runs are block 2.

■ Augmented Design								Percent
Design Augmented Design	•	Feed Rate	Catalyst	Stir Rate	Temperature	Concentration	Block	Reacted
Screening	1	10	1	100	180	6	1	44
▼ Model	2	10	1	120	180	3	1	66
▼ Columns (7/0)	3	10	2	100	140	6	1	70
▲ Feed Rate ★	4	10	2	120	140	3	1	54
Catalyst *	5	15	1	100	140	3	1	53
✓ Stir Rate   ★	6	15	1	120	140	6	1	55
✓ Temperature ★	7	15	2	100	180	3	1	93
✓ Concentration ★	8	15	2	120	180	6	1	82
♣ Block ★ ✓ Percent Reacted ★	9	15	2	120	140	3	2	•
A Percent Reacted *	10	15	2	100	140	6	2	•
▼Rows	11	15	1	120	180	3	2	•
All rows 16	12	15	1	100	180	6	2	•
Selected 0	13	10	2	120	180	6	2	•
Excluded 0	14	10	2	100	180	3	2	•
Hidden 0	15	10	1	120	140	6	2	•
Labelled 0	16	10	1	100	140	3	2	•

Figure 13.21 Listing of a Foldover Design On All Factors

## **Adding Axial Points**

You can add axial points together with center points, which transforms a screening design to a response surface design. To do this:

- 1. Open a data table that contains a design you want to augment. This example uses Reactor 8 Runs.jmp, from the Design Experiment Sample Data folder installed with JMP.
- 2. Select **DOE** > Augment Design.
- 3. In the initial Augment Design dialog, identify the response and factors you want to use for the augmented design (see Figure 13.15) and click **OK**.
- 4. If you want the original runs and the resulting augmented runs to be identified by a blocking factor, check the box beside **Group New Runs into Separate Block** (Figure 13.16).
- 5. Click Add Axial.
- 6. Enter the axial values in units of the factors scaled from –1 to +1, then enter the number of center points you want. When you click **OK**, the augmented design includes the number of center points specified and constructs two axial points for each variable in the original design.

Figure 13.22 Entering Axial Values



7. Click **Make Table**. The design table appears. Figure 13.23 shows a table augmented with two center points and two axial points for five variables.

Augmented Design Percent Design Augmented Design Feed Rate | Catalyst | Stir Rate | Temperature | Concentration Reacted Screening 100 180 44 1 10 1 ĥ ■ Model 2 10 1 120 180 3 66 2 100 140 6 70 3 10 4 10 2 120 140 3 54 Columns (6/0) 5 15 1 100 140 3 53 🚄 Feed Rate 🛠 center points 6 15 120 140 6 55 Satalyst \* 15 2 100 3 93 7 180 🚄 Stir Rate 🔻 2 82 8 15 120 180 6 🚄 Temperature 🛪 q 12.5 1.5 110 160 4.5 🚄 Concentration 🛠 10 12.5 110 160 4.5 Percent Reacted \* 1.5 11 15 1.5 110 160 4.5 12 10 1.5 110 160 4.5 Rows 12.5 4.5 13 2 110 160 20 All rows 14 12.5 110 160 4.5 Selected 0 axial points 15 12.5 1.5 160 4.5 Excluded 120 0 Hidden 16 12.5 1.5 100 160 4.5 Labelled 0 17 12.5 1.5 110 180 4.5 18 12.5 1.5 110 140 4.5 19 12.5 1.5 110 160 6 20 12.5 1.5 110 160 3

Figure 13.23 Design Augmented With Two Center and Ten Axial Points

## **Adding New Runs and Terms**

A powerful use of the augment designer is to add runs using a model that can have more terms than the original model. For example, you can achieve the objectives of response surface methodology by changing a linear model to a full quadratic model and adding the necessary number of runs. Suppose you start with a two-factor, two-level, four-run design. If you add quadratic terms to the model and five new points, JMP generates the 3 by 3 full factorial as the optimal augmented design.


D-optimal augmentation is a powerful tool for sequential design. Using this feature you can add terms to the original model and find optimal new test runs with respect to this expanded model. You can also group the two sets of experimental runs into separate blocks, which optimally blocks the second set with respect to the first.

To add new runs and terms to the original model:

- 1. Open a data table that contains a design you want to augment. This example uses Reactor Augment Data.jmp, from the Design Experiment Sample Data folder installed with JMP.
- 2. Select **DOE** > Augment Design.
- 3. In the initial Augment Design dialog, identify the response and factors you want to use for the augmented design (see Figure 13.15) and click **OK**.
- 4. If you want the original runs and the resulting augmented runs to be identified by a blocking factor, check the box beside **Group New Runs into Separate Block** (not used in this example).


5. Click the **Augment** button. The original number of runs (Figure 13.24) appear in the Factor Design panel.

Figure 13.24 Viewing the Existing Design



- 6. In the Design Generation panel, enter the number of total runs you want this design to contain. The number you enter is the original number of runs plus the number of additional runs you want.
- 7. Click the **Make Design** button. The new number of runs (Figure 13.25) appear in the Design panel.

Figure 13.25 24 Total Runs



- 8. If desired, view the prediction variance profile and the prediction variance surface.
- 9. Click Make Table to create the augmented design JMP table (Figure 13.26) with the additional runs.

Augmented Design Feed Rate | Catalyst | Stir Rate | Temperature | Concentration Design Augmented Design Reacted Screening **▼** Model Columns (6/0) 🚄 Feed Rate 🛠 Catalyst \* 🚄 Stir Rate 🗱 🚄 Temperature 🛠 🚄 Concentration 🛪 🚄 Percent Reacted 🛠 Rows All rows Selected Excluded Hidden Labelled additional runs 

Figure 13.26 The Augmented Design Table with New Runs


**Technical Note:** The Augment designer does not support designs that have terms whose estimability has been set to If Possible instead of Necessary, as is done in some screening designs that have fewer runs than terms.

## **Special Augment Design Commands**

After you select **DOE** > **Augment Design** and identify factors and responses, the window in Figure 13.27 appears. Click the red triangle icon on the Augment Design title bar to see a list of commands. Most of these commands are for saving and loading information about variables; they are available in all designs and more information is in "Special Custom Design Commands," p. 83. The following sections describe commands found in this menu that are specific to augment designs.

Special Augment Design Commands

Figure 13.27 Click the Red Triangle Icon to Reveal Commands



## Save the Design (X) Matrix

To create a script and save it as a table property in the JMP design data table, click the red triangle icon in the Augment Design title bar (Figure 13.27) and select Save X Matrix. Two or three scripts are saved to the table. Moments Matrix and Design Matrix scripts are always saved. If the design is a split plot design, an additional V Inverse script is also saved. When you run the Moments Matrix script, JMP creates a matrix called Moments and displays its number of rows in the log. When you run the Design Matrix script, JMP creates a matrix called X and displays its number of rows in the log. When you run the **V Inverse** script, JMP creates the inverse of the variance matrix of the responses, and displays its number of rows in the log. If you do not have the log visible, select View > Log or Window > Log on the Macintosh.

## Modify the Design Criterion (*D*- or *I*- Optimality)

To modify the design optimality criterion, click the red triangle icon in the Augment Design title bar (Figure 13.28) and select Optimality Criterion, then choose Make D-Optimal Design or Make I-Optimal **Design**. The default criterion for **Recommended** is *D*-optimal for all design types unless you have used the **RSM** button in the Model panel to add effects that make the model quadratic.





Figure 13.28 Change the Optimality Criterion

#### Select the Number of Random Starts

To override the default number of random starts, click the red triangle icon in the Augment Design title bar (Figure 13.28) and select **Number of Starts**. The window in Figure 13.29 appears with an edit box for you to enter the number of random starts for the design you want to build. The number you enter overrides the default number of starts, which varies depending on the design.

Figure 13.29 Changing the Number of Starts



For additional information on the number of starts, see "Why Change the Number of Starts?," p. 89.

## Specify the Sphere Radius Value

Augment designs can be constrained to a hypersphere. To edit the sphere radius for the design in units of the coded factors (-1, 1), click the red triangle icon in the Augment Design title bar (Figure 13.27) and select **Sphere Radius**. Enter the appropriate value and click **OK**.

Or, use JSL and submit the following command before you build a custom design:

DOE Sphere Radius = 1.0;

In this statement you can replace 1.0 with any positive number.

### **Disallow Factor Combinations**

In addition to linear inequality constraints on continuous factors and constraining a design to a hypersphere, you can define general factor constraints on the factors. You can disallow any combination of levels of categorical factors if you have not already defined linear inequality constraints.

For information on how to do this, see "Disallowed Combinations: Accounting for Factor Level Restrictions," p. 90.

# **Prospective Sample Size and Power**



Use the **DOE** > **Sample Size and Power** command to answer the question "How many runs do I need?" The important quantities are sample size, power, and the magnitude of the effect. These depend on the significance level, alpha, of the hypothesis test for the effect and the standard deviation of the noise in the response. You can supply either one or two of the three values. If you supply only one of these values, the result is a plot of the other two. If you supply two values, the third value is computed.

The **Sample Size and Power** platform can answer the question, "Will I detect the group differences I am looking for, given my proposed sample size, estimate of within-group variance, and alpha level?" In this type of analysis, you must approximate the group means and sample sizes in a data table as well as approximate the within-group standard deviation  $(\sigma)$ .

The sample size and power computations determine the sample size necessary for yielding a significant result, given that the true effect size is at least a certain size. It requires that you enter two out of three possible quantities; difference to detect, sample size, and power. The third quantity is computed for the following cases:

- difference between a one sample mean and a hypothesized value
- difference between two sample means
- differences in the means among k samples
- difference between a standard deviation and a hypothesized value
- difference between a one sample proportion and a hypothesized value
- difference between two sample proportions
- difference between counts per unit in a Poisson-distributed sample and a hypothesized value.

The calculations assume that there are equal numbers of units in each group. You can apply this platform to more general experimental designs, if they are balanced and an adjustment for the number-of-parameters is specified.

You can also compute the required sample sizes needed for reliability studies and demonstrations.

# **Contents**

Launching the Sample Size and Power Platform
One-Sample and Two-Sample Means
Single-Sample Mean
Sample Size and Power Animation for One Mean
Two-Sample Means
k-Sample Means
One Sample Standard Deviation
One Sample Standard Deviation Example
One-Sample and Two-Sample Proportions
One Sample Proportion
Two Sample Proportions
Counts per Unit
Counts per Unit Example
Sigma Quality Level
Sigma Quality Level Example
Number of Defects Computation Example
Reliability Test Plan and Demonstration
Reliability Test Plan
Reliability Demonstration


## Launching the Sample Size and Power Platform

The **Sample Size and Power** platform helps you plan your study for a single mean or proportion comparison, a two sample mean or proportion comparison, a one-sample standard deviation comparison, a k sample means comparison, or a counts per unit comparison. Depending upon your experimental situation, you supply one or two quantities to obtain a third quantity. These quantities include:

- required sample size
- expected power
- expected effect size

When you select **DOE** > **Sample Size and Power**, the panel in Figure 14.1 appears with button selections for experimental situations. The following sections describe each of these selections and explain how to enter the quantities and obtain the desired computation.

Figure 14.1 Sample Size and Power Choices




## **One-Sample and Two-Sample Means**

After you click either **One Sample Mean**, or **Two Sample Means** in the initial Sample Size selection list (Figure 14.1), a Sample Size and Power window appears. (See Figure 14.2.)

One-Sample and Two-Sample Means

Figure 14.2 Initial Sample Size and Power Windows for Single Mean (left) and Two Means (right)



The windows are the same except that the One Mean window has a button at the bottom that accesses an animation script.

The initial Sample Size and Power window requires values for Alpha, Std Dev (the error standard deviation), and one or two of the other three values: Difference to detect, Sample Size, and Power. The Sample Size and Power platform calculates the missing item. If there are two unspecified fields, a plot is constructed, showing the relationship between these two values:

- power as a function of sample size, given specific effect size
- power as a function of effect size, given a sample size
- effect size as a function of sample size, for a given power.

The Sample Size and Power window asks for these values:

**Alpha** s the probability of a type I error, which is the probability of rejecting the null hypothesis when it is true. It is commonly referred to as the significance level of the test. The default alpha level is 0.05. This implies a willingness to accept (if the true difference between groups is zero) that, 5% (alpha) of the time, a significant difference is incorrectly declared.

**Std Dev** is the error standard deviation. It is a measure of the unexplained random variation around the mean. Even though the true error is not known, the power calculations are an exercise in probability that calculates what might happen if the true value is the one you specify. An estimate of the error standard deviation could be the root mean square error (RMSE) from a previous model fit.

**Extra Parameters** is only for multi-factor designs. Leave this field zero in simple cases. In a multi-factor balanced design, in addition to fitting the means described in the situation, there are other factors with extra parameters that can be specified here. For example, in a three-factor two-level design with all three two-factor interactions, the number of extra parameters is five. (This includes two parameters for the extra main effects, and three parameters for the interactions.) In

practice, the particular values entered are not that important, unless the experimental range has very few degrees of freedom for error.

**Difference to Detect** is the smallest detectable difference (how small a difference you want to be able to declare statistically significant) to test against. For single sample problems this is the difference between the hypothesized value and the true value.

**Sample Size** is the total number of observations (runs, experimental units, or samples) in your experiment. Sample size is not the number per group, but the total over all groups.

**Power** is the probability of rejecting the null hypothesis when it is false. A large power value is better, but the cost is a higher sample size.

**Continue** evaluates at the entered values.

**Back** returns to the previous Sample Size and Power window so that you can either redo an analysis or start a new analysis.

**Animation Script** runs a JSL script that displays an interactive plot showing power or sample size. See the section, "Sample Size and Power Animation for One Mean," p. 292, for an illustration of the animation script.

### Single-Sample Mean

Using the Sample Size and Power window, you can test if one mean is different from the hypothesized value. For the one sample mean, the hypothesis supported is

$$H_0$$
:  $\mu = \mu_0$ 

and the two-sided alternative is

$$H_a$$
:  $\mu \neq \mu_0$ 

where  $\mu$  is the population mean and  $\mu_0$  is the null mean to test against or is the difference to detect. It is assumed that the population of interest is normally distributed and the true mean is zero. Note that the power for this setting is the same as for the power when the null hypothesis is  $H_0$ :  $\mu$ =0 and the true mean is  $\mu_0$ .


Suppose you are interested in testing the flammability of a new fabric being developed by your company. Previous testing indicates that the standard deviation for burn times of this fabric is 2 seconds. The goal is to detect a difference of 1.5 seconds when alpha is equal to 0.05, the sample size is 20, and the standard deviation is 2 seconds. For this example,  $\mu_0$  is equal to 1.5. To calculate the power:

- Select DOE > Sample Size and Power.
- 2. Click the **One Sample Mean** button in the Sample Size and Power Window.
- 3. Leave **Alpha** as 0.05.
- 4. Leave Extra Parameters as 0.
- 5. Enter 2 for Std Dev.
- 6. Enter 1.5 as Difference to detect.
- 7. Enter 20 for Sample Size.

- One-Sample and Two-Sample Means
- 8. Leave **Power** blank. (See the left window in Figure 14.3.)
- 9. Click Continue.

The power is calculated as 0.8888478174 and is rounded to 0.89. (See right window in Figure 14.3.) The conclusion is that your experiment has an 89% chance of detecting a significant difference in the burn time, given that your significance level is 0.05, the difference to detect is 1.5 seconds, and the sample size is 20.

Figure 14.3 A One-Sample Example




### Power versus Sample Size Plot

To see a plot of the relationship of Sample Size and Power, leave both Sample Size and Power empty in the window and click Continue.

The plots in Figure 14.4, show a range of sample sizes for which the power varies from about 0.1 to about 0.95. The plot on the right in Figure 14.4 shows using the crosshair tool to illustrate the example in Figure 14.3.

25



20

15 Sample Size 25

Figure 14.4 A One-Sample Example Plot

#### Power versus Difference Plot

Back

When only **Sample Size** is specified (Figure 14.5) and **Difference to Detect** and **Power** are empty, a plot of Power by Difference appears, after clicking **Continue**.


Back


10

15

Sample Size

Figure 14.5 Plot of Power by Difference to Detect for a Given Sample Size





## Sample Size and Power Animation for One Mean

Clicking the **Animation Script** button on the Sample Size and Power window for one mean shows an interactive plot. This plot illustrates the effect that changing the sample size has on power. As an example of using the **Animation Script**:

- 1. Select DOE > Sample Size and Power.
- 2. Click the One Sample Mean button in the Sample Size and Power Window.
- 3. Enter 2 for **Std Dev**.
- 4. Enter 1.5 as Difference to detect.
- 5. Enter 20 for Sample Size.
- 6. Leave Power blank.

The Sample Size and Power window appears as shown on the left of Figure 14.6.

#### 7. Click Animation Script.

The initial animation plot shows two t-density curves. The blue curve shows the t-distribution when the true mean is zero. The red curve shows the t-distribution when the true mean is 1.5, which is the difference to be detected. The probability of committing a type II error (not detecting a difference when there is a difference) is shaded blue on this plot. (This probability is often represented as  $\beta$  in the literature.) Similarly, the probability of committing a type I error (deciding that the difference to detect is significant when there is no difference) is shaded as the red areas under the red curve. (The red-shaded areas under the curve are represented as  $\alpha$  in the literature.)

Select and drag the square handles to see the changes in statistics based on the positions of the curves. To change the values of **Sample Size** and **Alpha**, click on their values beneath the plot.




Figure 14.6 Example of Animation Script to Illustrate Power

## **Two-Sample Means**

The Sample Size and Power windows work similarly for one and two sample means; the **Difference to Detect** is the difference between two means. The comparison is between two random samples instead of one sample and a hypothesized mean.

For testing the difference between two means, the hypothesis supported is

$$H_0: \mu_1 - \mu_2 = D_0$$

and the two-sided alternative is

$$H_a: \mu_1 - \mu_2 \neq D_0$$

where  $\mu_1$  and  $\mu_2$  are the two population means and  $D_0$  is the difference in the two means or the difference to detect. It is assumed that the populations of interest are normally distributed and the true difference is zero. Note that the power for this setting is the same as for the power when the null hypothesis is  $H_0$ :  $\mu_1 - \mu_2 = 0$  and the true difference is  $D_0$ .

Suppose the standard deviation is 2 (as before) for both groups, the desired detectable difference between the two means is 1.5, and the sample size is 30 (15 per group). To estimate the power for this example:

Select DOE > Sample Size and Power.

294


- 2. Click the **Two Sample Means** button in the Sample Size and Power Window.
- 3. Leave **Alpha** as 0.05.
- 4. Enter 2 for Std Dev.
- 5. Leave Extra Parameters as 0.
- 6. Enter 1.5 as Difference to detect.
- 7. Enter 30 for **Sample Size**.
- 8. Leave Power blank.
- 9. Click Continue.


The **Power** is calculated as 0.51. (See the left window in Figure 14.7.) This means that you have a 51% chance of detecting a significant difference between the two sample means when your significance level is 0.05, the difference to detect is 1.5, and each sample size is 15.

### Plot of Power by Sample Size

To have a greater power requires a larger sample. To find out how large, leave both **Sample Size** and **Power** blank for this same example and click **Continue**. Figure 14.7 shows the resulting plot, with the crosshair tool estimating that a sample size of about 78 is needed to obtain a power of 0.9.

Figure 14.7 Plot of Power by Sample Size to Detect for a Given Difference





## k-Sample Means

Using the **k-Sample Means** option, you can compare up to 10 means. Consider a situation where 4 levels of means are expected to be in the range of 10 to 13, the standard deviation is 0.9, and your sample size is 16.

The hypothesis to be tested is:

 $H_0$ :  $\mu_1 = \mu_2 = \mu_3 = \mu_4$  versus  $H_a$ : at least one mean is different

To determine the power:


- 1. Select DOE > Sample Size and Power.
- 2. Click the k Sample Means button in the Sample Size and Power Window.
- 3. Leave **Alpha** as 0.05.
- 4. Enter 0.9 for Std Dev.
- 5. Leave Extra Parameters as 0.
- 6. Enter 10, 11, 12, and 13 as the four levels of means.
- 7. Enter 16 for **Sample Size**.
- 8. Leave Power blank.
- Click Continue.


The **Power** is calculated as 0.95. (See the left of Figure 14.8.) This means that there is a 95% chance of detecting that at least one of the means is different when the significance level is 0.05, the population means are 10, 11, 12, and 13, and the total sample size is 16.

If both **Sample Size** and **Power** are left blank for this example, the sample size and power calculations produce the **Power** versus **Sample Size** curve. (See the right of Figure 14.8.) This confirms that a sample size of 16 looks acceptable.

Notice that the difference in means is 2.236, calculated as square root of the sum of squared deviations from the grand mean. In this case it is the square root of  $(-1.5)^2 + (-0.5)^2 + (0.5)^2 + (1.5)^2$ , which is the square root of 5.

Figure 14.8 Prospective Power for k-Means and Plot of Power by Sample Size





## **One Sample Standard Deviation**

Use the **One-Sample Standard Deviation** option on the Sample Size and Power window (Figure 14.1) to determine the sample size needed for detecting a change in the standard deviation of your data. The usual purpose of this option is to compute a large enough sample size to guarantee that the risk of a type II error,  $\beta$ , is small. (This is the probability of failing to reject the null hypothesis when it is false.)

In the Sample Size and Power window, specify:

**Alpha** is the significance level, usually 0.05. This implies a willingness to accept (if the true difference between standard deviation and the hypothesized standard deviation is zero) that a significant difference is incorrectly declared 5% of the time.

**Hypothesized Standard Deviation** is the hypothesized or baseline standard deviation to which the sample standard deviation is compared.

**Alternative Standard Deviation** can select **Larger** or **Smaller** from the menu to indicate the direction of the change you want to detect.

**Difference to Detect** is the smallest detectable difference (how small a difference you want to be able to declare statistically significant). For single sample problems this is the difference between the hypothesized value and the true value.

**Sample Size** is how many experimental units (runs, or samples) are involved in the experiment.

**Power** is the probability of declaring a significant result. It is the probability of rejecting the null hypothesis when it is false.

In the lower part of the window you enter two of the items and the Sample Size and Power calculation determines the third.

Some examples in this chapter use engineering examples from the online manual of The National Institute of Standards and Technology (NIST). You can access the NIST manual examples at http://www.itl.nist.gov/div898/handbook.

### One Sample Standard Deviation Example

One example from the NIST manual states a problem in terms of the variance and difference to detect. The variance for resistivity measurements on a lot of silicon wafers is claimed to be 100 ohm-cm. The buyer is unwilling to accept a shipment if the variance is greater than 155 ohm-cm for a particular lot (55 ohm-cm above the baseline of 100 ohm-cm).

In the Sample Size and Power window, the One Sample Standard Deviation computations use the standard deviation instead of the variance. The hypothesis to be tested is:

 $H_0$ :  $\sigma = \sigma_0$ , where  $\sigma_0$  is the hypothesized standard deviation. The true standard deviation is  $\sigma_0$  plus the difference to detect.

In this example the hypothesized standard deviation,  $\sigma_0$ , is 10 (the square root of 100) and  $\sigma$  is 12.4499 (the square root of 100 + 55 = 155). The difference to detect is 12.4499 – 10 = 2.4499.


You want to detect an increase in the standard deviation of 2.4499 for a standard deviation of 10, with an alpha of 0.05 and a power of 0.99. To determine the necessary sample size:

- 1. Select **DOE** > **Sample Size** and **Power**.
- 2. Click the **One Sample Standard Deviation** button in the Sample Size and Power Window.
- 3. Leave **Alpha** as 0.05.
- 4. Enter 10 for Hypothesized Standard Deviation.
- Select Larger for Alternate Standard Deviation.
- 6. Enter 2.4499 as Difference to Detect.
- 7. Enter 0.99 for Power.
- 8. Leave **Sample Size** blank. (See the left of Figure 14.9.)
- Click Continue.

The **Sample Size** is calculated as 171. (See the right of Figure 14.9.) This result is the sample size rounded up to the next whole number.

**Note**: Sometimes you want to detect a change to a smaller standard deviation. If you select **Smaller** from the **Alternative Standard Deviation** menu, enter a negative amount in the **Difference to Detect** field.

Figure 14.9 Window To Compare Single-Direction One-Sample Standard Deviation



## **One-Sample and Two-Sample Proportions**

The Sample Size windows and computations to test sample sizes and power for proportions are similar to those for testing means. You enter a true **Proportion** and choose an **Alpha** level. Then, for the one-sample proportion case, enter the **Sample Size** and **Null Proportion** to obtain the **Power**. Or, enter the **Power** and **Null Proportion** to obtain the **Sample Size**. Similarly, to obtain a value for **Null Proportion**, enter values for **Sample Size** and **Power**. For the two-sample proportion case, either the two sample sizes or the desired **Power** must be entered. (See Figure 14.10 and Figure 14.11.)

The sampling distribution for proportions is normal, but the computations to determine sample size and test proportions use exact methods based on the binomial distribution. Exact methods are more reliable since using the normal approximation to the binomial can provide erroneous results when small samples or proportions are used. Exact power calculations are used in conjunction with a modified Wald test statistic described in Agresti and Coull (1998).

## **One Sample Proportion**

Clicking the **One Sample Proportion** option on the Sample Size and Power window yields a One Proportion window. In this window, you can specify the alpha level and the true proportion. The sample size, power, or the hypothesized proportion is calculated. If you supply two of these quantities, the third is computed, or if you enter any one of the quantities, you see a plot of the other two.

For example, if you have a hypothesized proportion of defects, you can use the **One Sample Proportion** window to estimate a large enough sample size to guarantee that the risk of accepting a false hypothesis  $(\beta)$  is small. That is, you want to detect, with reasonable certainty, a difference in the proportion of defects.

For the one sample proportion, the hypothesis supported is

$$H_0: p = p_0$$

and the two-sided alternative is

$$H_a$$
:  $p \neq p_0$ 

where p is the population proportion and  $p_0$  is the null proportion to test against. Note that if you are interested in testing whether the population proportion is greater than or less than the null proportion, you use a one-sided test. The one-sided alternative is either

$$H_a$$
:  $p < p_0$ 

or

$$H_a: p > p_0$$

#### One-Sample Proportion Window Specifications

In the top portion of the Sample Size window, you can specify or enter values for:

**Alpha** is the significance level of your test. The default value is 0.05.

**Proportion** is the true proportion, which could be known or hypothesized. The default value is 0.1.

**One-Sided or Two-Sided** Specify either a one-sided or a two-sided test. The default setting is the two-sided test.

In the bottom portion of the window, enter two of the following quantities to see the third, or a single quantity to see a plot of the other two.

**Null Proportion** is the proportion to test against  $(p_0)$  or is left blank for computation. The default value is 0.2.

**Sample Size** is the sample size, or is left blank for computation. If **Sample Size** is left blank, then values for **Proportion** and **Null Proportion** must be different.

**Power** is the desired power, or is left blank for computation.

#### **One-Sample Proportion Example**


As an example, suppose that an assembly line has a historical proportion of defects equal to 0.1, and you want to know the power to detect that the proportion is different from 0.2, given an alpha level of 0.05 and a sample size of 100.

- 1. Select DOE > Sample Size and Power.
- Click One Sample Proportion.
- 3. Leave **Alpha** as 0.05.
- 4. Leave 0.1 as the value for **Proportion**.
- 5. Accept the default option of **Two-Sided**. (A one-sided test is selected if you are interested in testing if the proportion is either greater than or less than the **Null Proportion**.)
- 6. Leave 0.2 as the value for **Null Proportion**.
- 7. Enter 100 as the **Sample Size**.
- 8. Click Continue.

One-Sample and Two-Sample Proportions

The **Power** is calculated and is shown as approximately 0.7. See Figure 14.10.

Figure 14.10 Power and Sample Window for One-Sample Proportions



## **Two Sample Proportions**

The **Two Sample Proportions** option computes the power or sample sizes needed to detect the difference between two proportions,  $p_1$  and  $p_2$ .

For the two sample proportion, the hypothesis supported is

$$H_0: p_1 - p_2 = D_0$$

and the two-sided alternative is

$$H_a: p_1 - p_2 \neq D_0$$

where p1 and p2 are the population proportions from two populations, and  $D_0$  is the hypothesized difference in proportions.

The one-sided alternative is either

$$H_{d}$$
:  $(p_1 - p_2) < D_0$ 

or

$$H_a: (p_1 - p_2) > D_0$$

### Two Sample Proportion Window Specifications

Specifications for the Two Sample Proportions window include:

**Alpha** is the significance level of your test. The default value is 0.05.

**Proportion 1** is the proportion for population 1, which could be known or hypothesized. The default value is 0.5.

**Proportion 2** is the proportion for population 2, which could be known or hypothesized. The default value is 0.1.

**One-Sided or Two-Sided** Specify either a one-sided or a two-sided test. The default setting is the two-sided test.

**Null Difference in Proportion** is the proportion difference ( $D_0$ ) to test against, or is left blank for computation. The default value is 0.2.

**Sample Size 1** is the sample size for population 1, or is left blank for computation.

Sample Size 2 is the sample size for population 2, or is left blank for computation.

**Power** is the desired power, or is left blank for computation.

If you enter any two of the following three quantities, the third quantity is computed:

- Null Difference in Proportion
- Sample Size 1 and Sample Size 2
- Power

#### Example of Determining Sample Sizes with a Two-Sided Test

As an example, suppose you are responsible for two silicon wafer assembly lines. Based on the knowledge from many runs, one of the assembly lines has a defect rate of 8%; the other line has a defect rate of 6%. You want to know the sample size necessary to have 80% power to reject the null hypothesis of equal proportions of defects for each line.

To estimate the necessary sample sizes for this example:

- Select DOE > Sample Size and Power.
- 2. Click Two Sample Proportions.
- 3. Accept the default value of **Alpha** as 0.05.
- 4. Enter 0.08 for **Proportion 1**.
- 5. Enter 0.06 for **Proportion 2**.
- 6. Accept the default option of **Two-Sided**.
- 7. Enter 0.0 for Null Difference in Proportion.
- 8. Enter 0.8 for **Power**.
- 9. Leave Sample Size 1 and Sample Size 2 blank.

The completed window appears as the left window in Figure 14.11.


#### 10. Click Continue.

The Sample Size window shows sample sizes of 2554. (See the figure on the right in Figure 14.11.) Testing for a one-sided test is conducted similarly. Simply select the **One-Sided** option.

**Note:** The computations for finding two sample sizes can take a little time so be patient.

One-Sample and Two-Sample Proportions

Figure 14.11 Difference Between Two Proportions for a Two-Sided Test



#### Example of Determining Power with Two Sample Proportions Using a One-Sided Test

Suppose you want to compare the effectiveness of two chemical additives. The standard additive is known to be 50% effective in preventing cracking in the final product. The new additive is assumed to be 60% effective. You plan on conducting a study, randomly assigning parts to the two groups. You have 800 parts available to use for the study (400 parts for each additive). Your objective is to determine the power of your test, given a null difference in proportions of 0.01 and an alpha level of 0.05. Because you are interested in testing that the difference in proportions is greater than 0.01, you use a one-sided test.


- Select DOE > Sample Size and Power.
- 2. Click Two Sample Proportions.
- 3. Accept the default value of **Alpha** as 0.05.
- 4. Enter 0.6 for **Proportion 1**.
- 5. Enter 0.5 for **Proportion 2**.
- 6. Select One-Sided.
- 7. Enter 0.01 as the Null Difference in Proportion.
- 8. Enter 400 for Sample Size 1.
- 9. Enter 400 for Sample Size 2.
- 10. Leave Power blank.

Figure 14.12 (left side) shows the completed Two Proportions window.

Click Continue.

Figure 14.12 (right side) shows the Two Proportions windows with the estimated **Power** calculation of 0.82.

Figure 14.12 Difference Between Two Proportions for a One-Sided Test



You conclude that there is about an 82% chance of rejecting the null hypothesis at the 0.05 level of significance, given that the sample sizes for the two groups are each 400.

## **Counts per Unit**

You can use the **Counts per Unit** option from the Sample Size and Power window (Figure 14.1) to calculate the sample size needed when you measure more than one defect per unit. A unit can be an area and the counts can be fractions or large numbers.

Although the number of defects observed in an area of a given size is often assumed to have a Poisson distribution, it is understood that the area and count are large enough to support a normal approximation.

Questions of interest are:

- Is the defect density within prescribed limits?
- Is the defect density greater than or less than a prescribed limit?

In the Counts per Unit window, options include:

**Alpha** is the significance level of your test. The default value is 0.05.

**Baseline Count per Unit** is the number of targeted defects per unit. The default value is 0.1.

Counts per Unit

304

**Difference to detect** is the smallest detectable difference to test against and is specified in defects per unit, or is left blank for computation.

**Sample Size** is the sample size, or is left blank for computation.

**Power** is the desired power, or is left blank for computation.

In the Counts per Unit window, enter Alpha and the Baseline Count per Unit. Then enter two of the remaining fields to see the calculation of the third. The test is for a one-sided (one-tailed) change. Enter the Difference to Detect in terms of the Baseline Count per Unit (defects per unit). The computed sample size is expressed as the number of units, rounded to the next whole number.


## **Counts per Unit Example**

As an example, consider a wafer manufacturing process with a target of 4 defects per wafer. You want to verify that a new process meets that target within a difference of 1 defect per wafer with a significance level of 0.05. In the Counts per Unit window:

- 1. Leave Alpha as 0.05 (the chance of failing the test if the new process is as good as the target).
- 2. Enter 4 as the **Baseline Counts per Unit**, indicating the target of 4 defects per wafer.
- 3. Enter 1 as the **Difference to detect**.
- 4. Enter a power of 0.9, which is the chance of detecting a change larger than 1 (5 defects per wafer). In this type of situation, alpha is sometimes called the *producer's risk* and beta is called the *consumer's risk*.
- 5. Click **Continue** to see the results in Figure 14.13, showing a computed sample size of 38 (rounded to the next whole number).

The process meets the target if there are less than 190 defects (5 defects per wafer in a sample of 38 wafers).

Figure 14.13 Window For Counts Per Unit Example



,	Cample Cine
4	Sample Size
	Counts per Unit
	Detecting change in count per unit, e.g. DPU (defects per unit) Alpha
	Baseline Count per Unit 4
	Supply two values to determine the third.
	Difference to detect1
	Sample Size (38)
	Power 0.9
	Using normal approximations
	Continue
	Back

## **Sigma Quality Level**

The Sigma Quality Level feature is a simple statistic that puts a given defect rate on a "six-sigma" scale. For example, on a scale of one million opportunities, 3.397 defects result in a six-sigma process. The computation that gives the Sigma Quality Level statistic is

Sigma Quality Level = NormalQuantile(1 - defects/opportunities) + 1.5

Two of three quantities can be entered to determine the Sigma Quality Level statistic in the Sample Size and Power window:

- Number of Defects
- Number of Opportunities
- Sigma Quality Level

When you click **Continue**, the sigma quality calculator computes the missing quantity.


### Sigma Quality Level Example

As an example, use the Sample Size and Power feature to compute the Sigma Quality Level for 50 defects in 1,000,000 opportunities:

- 1. Select DOE > Sample Size and Power.
- 2. Click the Sigma Quality Level button.
- 3. Enter 50 for the Number of Defects.
- 4. Enter 1000000 as the Number of Opportunities. (See window to the left in Figure 14.14.)
- 5. Click Continue.

The results are a Sigma Quality Level of 5.39 defects in 1,000,000 opportunities. (See right window in Figure 14.14.)

Figure 14.14 Sigma Quality Level Example 1




## **Number of Defects Computation Example**

If you want to know how many defects reduce the Sigma Quality Level to "six-sigma" for 1,000,000 opportunities:

- 1. Select DOE > Sample Size and Power.
- 2. Click the Sigma Quality Level button.
- 3. Enter 6 as Sigma Quality Level.
- 4. Enter 1000000 as the Number of Opportunities. (See left window in Figure 14.14.)
- 5. Leave **Number of Defects** blank.
- 6. Click Continue.

The computation shows that the **Number of Defects** cannot be more than approximately 3.4. (See right window in Figure 14.15.)

Figure 14.15 Sigma Quality Level Example 2



## **Reliability Test Plan and Demonstration**


You can compute required sample sizes for reliability tests and reliability demonstrations using the Reliability Test Plan and Reliability Demonstration features.

## **Reliability Test Plan**

The **Reliability Test Plan** feature computes required sample sizes, censor times, or precision, for estimating failure times and failure probabilities.

To launch the Reliability Test Plan calculator, select **DOE** > **Sample Size and Power**, and then select **Reliability Test Plan**. Figure 14.16 shows the Reliability Test Plan window.

Figure 14.16 Reliability Test Plan Window



The Reliability Test Plan window has the following options:

**Alpha** is the significance level. It is also 1 minus the confidence level.

**Distribution** is the assumed failure distribution, with the associated parameters.

Reliability Test Plan and Demonstration

**Precision Measure** is the precision measure. In the following definitions, U and L correspond to the upper and lower confidence limits of the quantity being estimated (either a time or failure probability), and T corresponds to the true time or probability for the specified distribution.

**Interval Ratio** is sqrt(U/L), the square root of the ratio of the upper and lower limits.

Two-sided Interval Absolute Width is U-L, the difference of the upper and lower limits.

Lower One-sided Interval Absolute Width is T-L, the true value minus the lower limit.

**Two-sided Interval Relative Width** is (U-L)/T, the difference between the upper and lower limits, divided by the true value.

**Lower One-sided Interval Relative Width** is (T-L)/T, the difference between the true value and the lower limit, divided by the true value.

**Objective** is the objective of the study. The objective can be one of the following two:

- estimate the time associated with a specific probability of failure.
- estimate the probability of failure at a specific time.

**CDF Plot** is a plot of the CDF of the specified distribution. When estimating a time, the true time associated with the specified probability is written on the plot. When estimating a failure probability, the true probability associated with the specified time is written on the plot.

**Sample Size** is the required number of units to include in the reliability test.

**Censor Time** is the amount of time to run the reliability test.

**Precision** is the level of precision. This value corresponds to the Precision Measure chosen above.

**Large-sample approximate covariance matrix** gives the approximate variances and covariance for the location and scale parameters of the distribution.

**Continue** click here to make the calculations.

**Back** click here to go back to the Power and Sample Size window.

After the **Continue** button is clicked, two additional statistics are shown:

**Expected number of failures** is the expected number of failures for the specified reliability test.

**Probability of fewer than 3 failures** is the probability that the specified reliability test will result in fewer than three failures. This is important because a minimum of three failures is required to reliably estimate the parameters of the failure distribution. With only one or two failures, the estimates are unstable. If this probability is large, you risk not being able to achieve enough failures to reliably estimate the distribution parameters, and you should consider changing the test plan. Increasing the sample size or censor time are two ways of lowering the probability of fewer than three failures.

#### Example

A company has developed a new product and wants to know the required sample size to estimate the time till 20% of units fail, with a two-sided absolute precision of 200 hours. In other words, when a confidence interval is created for the estimated time, the difference between the upper and lower limits needs to be approximately 200 hours. The company can run the experiment for 2500 hours. Additionally, from studies done on similar products, they believe the failure distribution to be approximately Weibull (2000, 3).

To compute the required sample size, do the following steps:

- 1. Select DOE > Sample Size and Power.
- 2. Select Reliability Test Plan.
- 3. Select Weibull from the Distribution list.
- 4. Enter 2000 for the Weibull  $\alpha$  parameter.
- 5. Enter 3 for the Weibull  $\beta$  parameter.
- 6. Select Two-sided Interval Absolute Width from the Precision Measure list.
- 7. Select Estimate time associated with specified failure probability.
- 8. Enter 0.2 for p.
- 9. Enter 2500 for Censor Time.
- 10. Enter 200 for Precision.
- 11. Click **Continue**. Figure 14.17 shows the results.

Figure 14.17 Reliability Test Plan Results

Sample Size	217	
Censor Time	2,500	
Precision	200	
Expected number of failures		186.2229
Probability of fewer than 3 failures		7.4e-179

The required sample size is 217 units if the company wants to estimate the time till 20% failures with a precision of 200 hours. The probability of fewer than 3 failures is small, so the experiment will likely result in enough failures to reliably estimate the distribution parameters.


### Reliability Demonstration

A reliability demonstration consists of testing a specified number of units for a specified period of time. If fewer than *k* units fail, you pass the demonstration, and conclude that the product reliability meets or exceeds a reliability standard.

The **Reliability Demonstration** feature computes required sample sizes and experimental run-times for demonstrating that a product meets or exceeds a specified reliability standard.

To launch the Reliability Demonstration calculator, select **DOE** > **Sample Size and Power**, and then select **Reliability Demonstration**. Figure 14.18 shows the Reliability Demonstration window.

Figure 14.18 Reliability Demonstration Window



The Reliability Demonstration window has the following options:

**Alpha** is the alpha level.

**Distribution** is the assumed failure distribution. After selecting a distribution, specify the associated scale parameter in the text field under the **Distribution** menu.

**Max Failures Tolerated** is the maximum number of failures you want to allow during the demonstration. If we observe this many failures or fewer, then we say we passed the demonstration.

**Time** is the time component of the reliability standard you want to meet.

**Probability of Surviving** is the probability component of the reliability standard you want to meet.

**Time of Demonstration** is the required time for the demonstration.

**Number of Units Tested** is the required number of units for the demonstration.

**Continue** click here to make the calculations.

**Back** click here to go back to the Power and Sample Size window.

After the Continue button is clicked, a plot appears (see Figure 14.19).




Figure 14.19 Reliability Demonstration Plot

The true probability of a unit surviving to the specified time is unknown. The Y axis of the plot gives the probability of passing the demonstration (concluding the true reliability meets or exceeds the standard) as a function of the true probability of a unit surviving to the standard time. Notice the line is increasing, meaning that the further the truth is above the standard, the more likely you are to detect the difference.


#### Example

A company wants to get the required sample size for assessing the reliability of a new product against an historical reliability standard of 90% survival after 1000 hours. From prior studies on similar products, it is believed that the failure distribution is Weibull, with a  $\beta$  parameter of 3. The company can afford to run the demonstration for 800 hours, and wants the experiment to result in no more than 2 failures.

To compute the required sample size, do the following steps:

- Select DOE > Sample Size and Power.
- 2. Select Reliability Demonstration.
- 3. Select Weibull from the Distribution list.
- 4. Enter 3 for the Weibull β.
- 5. Enter 2 for Max Failures Tolerated.
- 6. Enter 1000 for Time.
- 7. Enter 0.9 for Probability of Surviving.
- 8. Enter 800 for Time of Demonstration.
- 9. Click **Continue**. Figure 14.20 shows the results.

Figure 14.20 Reliability Demonstration Results



The company needs to run 118 units in the demonstration. Furthermore, if they observe 2 or fewer failures by 800 hours, we can conclude that the new product reliability is at least as reliable as the standard.

- Agresti, A., and Caffo, B. N. (2000), "Simple and Effective Confidence Intervals for Proportions and Differences of Proportions Result from Adding Two Successes and Two Failures," The American Statistician, 54, 280-288.
- Atkinson, A. C. and Donev, A. N.(1992), Optimum Experimental Designs, Clarendon Press, Oxford p.148.
- Bose, R.C., (1947), "Mathematical Theory of the Symmetrical Factorial Design" *Sankhya: The Indian Journal of Statistics*, Vol. 8, Part 2, pp. 107-166.
- Box, G.E.P. and Wilson, K.B. (1951), "On the Experimental Attainment of Optimum Conditions," *Journal of the Royal Statistical Society*, Series B, 13, 1-45.
- Box, G.E.P. and Behnken, D.W. (1960), "Some New Three-Level Designs for the Study of Quantitative Variables," *Technometrics* 2, 455–475.
- Box, G.E.P. and Meyer, R.D. (1986), "An Analysis of Unreplicated Fractional Factorials," *Technometrics* 28, 11–18.
- Box, G.E.P. and Draper, N.R. (1987), *Empirical Model–Building and Response Surfaces*, New York: John Wiley and Sons.
- Box, G.E.P. (1988), "Signal-to-Noise Ratio, Performance Criteria, and Transformations," *Technometrics* 30, 1–40.
- Box, G.E.P., Hunter, W.G., and Hunter, J.S. (1978), *Statistics for Experimenters*, New York: John Wiley and Sons, Inc.
- Byrne, D.M. and Taguchi, G. (1986), ASQC 40th Anniversary Quality Control Congress Transactions, Milwaukee, WI: American Society of Quality Control, 168–177.
- Chen, J., Sun, D.X., and Wu, C.F.J. (1993), "A Catalogue of Two-level and Three-Level Fractional Factorial Designs with Small Runs," International Statistical Review, 61, 1, p131-145, International Statistical Institute.
- Cochran, W.G. and Cox, G.M. (1957), *Experimental Designs*, Second Edition, New York: John Wiley and Sons
- Cornell, J.A. (1990), Experiments with Mixtures, Second Edition New York: John Wiley & Sons.
- Cook, R.D. and Nachtsheim, C.J. (1990), "Letter to the Editor: Response to James M. Lucas," *Technometrics* 32, 363-364.
- Daniel, C. (1959), "Use of Half–normal Plots in Interpreting Factorial Two–level Experiments," *Technometrics*, 1, 311–314.
- Daniel C. and Wood, F. (1980), *Fitting Equations to Data*, Revised Edition, New York: John Wiley and Sons, Inc.

Derringer, D. and Suich, R. (1980), "Simultaneous Optimization of Several Response Variables," *Journal of Quality Technology*, Oct. 1980, 12:4, 214–219.

- DuMouchel, W. and Jones, B. (1994), "A Simple Bayesian Modification of *D*-Optimal Designs to Reduce Dependence on an Assumed Model," *Technometrics*, 36, 37–47.
- Fang, K.T. and Sudfianto, A. (2006), *Design and Modeling for Computer Experiments*, Chapman and Hall CRC, Boca Ratan. Florida
- Goos, P. (2002) The Optimal Design of Blocked and Split Plot Experiments, New York: Springer
- Gotwalt, C. M., Jones, B.A., and Steinberg, D. M., (2009) "Fast Computation of Designs Robust to Parameter Uncertainty for Nonlinear Settings," *Technometrics*, 51:1, 88-95.
- Haaland, P.D. (1989), Experimental Design in Biotechnology, New York: Marcel Dekker, Inc.
- Hahn, G. J., Meeker, W.Q., and Feder, P. I., (1976), "The Evaluation and Comparison of Experimental Designs for Fitting Regression Relationships," *Journal of Quality Technology*, Vol. 8, #3, pp. 140-157.
- John, P.W.M. (1972), Statistical Design and Analysis of Experiments, New York: Macmillan Publishing Company, Inc.
- Johnson, M.E. and Nachtsheim, C.J. (1983), "Some Guidelines for Constructing Exact D-Optimal Designs on Convex Design Spaces," *Technometrics* 25, 271–277.
- Jones, Bradley (1991), "An Interactive Graph For Exploring Multidimensional Response Surfaces," 1991 Joint Statistical Meetings, Atlanta, Georgia.
- Jones, Bradley and Goos, Peter (2007), "A Candidate-set-free Algorithm for Generating D-optimal Designs," *Applied Statistics*, 56, Part 3, pp 1-18.
- Khuri, A.I. and Cornell, J.A. (1987) Response Surfaces: Design and Analysis, New York: Marcel Dekker.
- Kowalski, S.M., Cornell, J.A., and Vining, G.G. (2002) "Split Plot Designs and Estimation Methods for Mixture Experiments with Process Variables," *Technometrics* 44: 72-79.
- Lenth, R.V. (1989), "Quick and Easy Analysis of Unreplicated Fractional Factorials," *Technometrics*, 31, 469–473.
- Lin, D. K. J. (1993), "A New Class of Supersaturated Design," *Technometrics*, 35, 28-31.
- Lucas, J.M., (1990), "Letter to the Editor: Comments on Cook and Nachtsheim (1989)," *Technometrics*, 32, 363–364.
- Mahalanobis, P.C. (1947), Sankhya, The Indian Journal of Statistics, Vol 8, Part 2, April.
- Myers, R.H. (1976) Response Surface Methodology, Boston: Allyn and Bacon.
- Myers, R.H. (1988), Response Surface Methodology, Virginia Polytechnic and State University.
- Meyer, R.K. and Nachtsheim, C.J. (1995), The Coordinate Exchange Algorithm for Constructing Exact Optimal Designs," *Technometrics*, Vol 37, pp. 60-69.
- Meyer, R.D., Steinberg, D.M., and Box, G.(1996), Follow-up Designs to Resolve Confounding in Multifactor Experiments, *Technometrics*, 38:4, p307.
- Mitchell, T.J. (1974), "An algorithm for the Construction of D-Optimal Experimental Designs," *Technometrics*, 16:2, pp.203-210.
- Montgomery, D.C. (2009), *Design and Analysis of Experiments*, Seventh Edition, Hoboken: John Wiley & Sons, Inc.

Morris, M.D., Mitchell, T.J., and Ylvisaker, D. (1993), "Bayesian Design and Analysis of Computer Experiments: Use of Derivatives in Surface Prediction," *Technometrics* 35:2, 243-255.

- Myers, R.H., Montgomery, D.C., and Anderson-Cook, C.M. (2009), Response Surface Methodology, Process and Product Optimization Using Designed Experiments, Third Edition, Hoboken: John Wiley & Sons, Inc.
- Piepel, G.F. (1988), "Programs for Generating Extreme Vertices and Centroids of Linearly Constrained Experimental Regions," *Journal of Quality Technology* 20:2, 125-139.
- Plackett, R.L. and Burman, J.P. (1947), "The Design of Optimum Multifactorial Experiments," *Biometrika*, 33, 305–325.
- Santner, T.B., Williams, B., and Notz, W. (2003), *The Design and Analysis of Computer Experiments*, Springer, New York.
- Schoen, E. D. (1999), "Designing Fractional Two-level Experiments with Nested Error Structures," *Journal of Applied Statistics* 26: 495-508.
- Shannon, C.E. and Weaver, W. (1949), "The Mathematical Theory Of Communication," University Of Illinois Press, Urbana, Illinois.
- Scheffé, H. (1958) "Experiments with Mixtures", Journal of the Royal Statistical Society B v20, 344–360.
- Shewry, M.C. and Wynn, H.P. (1987), "Maximum Entropy Sampling," *Journal of Applied Statistics* 14, 165-170.
- Snee, R.D. and Marquardt, D.W. (1974), "Extreme Vertices Designs for Linear Mixture Models," *Technometrics*, 16, 391–408.
- Snee, R.D. (1975), "Experimental Designs for Quadratic Models in Constrained Mixture Spaces," Technometrics, 17:2, 149–159.
- Snee, R.D. (1979), "Experimental Designs for Mixture Systems with Multicomponent Constraints," *Commun. Statistics*, A8(4), 303–326.
- Snee, Ronald D. (1985) Computer Aided Design of Experiments Some Practical Experiences, Journal of Quality Technology, Vol 17. No. 4 October 1985 p.231.
- St. John, R.C. and Draper, N.R. (1975), "D-Optimality for Regression Designs: A Review," *Technometrics*, 17 pp 15-23.
- Taguchi, G. (1976), "An Introduction to Quality Control," Nagoya, Japan: Central Japan Quality Control Association.
- Welch, W.J. (1984), "Computer-Aided Design of Experiments for Response Estimation," *Technometrics*, 26, 217–224.
- Zahran, A., Anderson-Cook, C.M., and Myers, R.H. (2003), "Fraction of Design Space to Assess the Prediction Capability of Response Surface Designs," *Journal of Quality Technology*, 35, 377–386.

## **Design of Experiments**

A	В
ABCD designs 168	balanced designs 71
acceptable values See lower limits and upper limits	Bayesian D-optimal designs 31, 60–61
Actual-by-Predicted plots 125	Bayesian I-optimal designs 60, 62
adding	Big Class.jmp 51
center points in augment designs 275, 277	block sizes 27
factors 40, 67	Borehole Factors.jmp 212
linear constraints 164	Borehole Sphere Packing.jmp 213
runs and terms in augment designs 279	Bounce Data.jmp 129
additional runs 78, 120, 140, 152	Bounce Factors.jmp 129–130
advanced options (nonlinear designer) 245	Box-Behnken designs 127, 129, 138
algorithms, coordinate exchange 99	See also Response Surface designs
alias matrix 76	Byrne Taguchi Factors.jmp 250-251
explanation 18	
showing 18	С
aliasing effects 115	1.0
Alias-optimal designs 60, 88	categorical factors 68, III
Alpha 288	CCD See central composite designs
animation scripts 289	center points
Anova reports 171	augment designs 275, 277
assigning importance (of responses) 65, 109, 254	central composite designs 127
assigning importance of responses 84	response surface designs 127
attribute, discrete choice designs 181	simplex centroid designs 158
augment nonlinear design table 244	central composite designs 127, 138
Augmented Designs 259–284	See also response surface designs
add centerpoints 272, 275	centroid points 163
add new runs and terms 272, 278	Chakravarty 114
adding axial points 272, 277	Chemical Kinetics.jmp 231
disallow factor combinations 284	chemical mixture, examples 171
D-optimal 278	choice designs
extending experiments 271	example 179
foldover 272, 276	purpose 179
modify D- or I- optimality criterion 282	choice set, discrete choice designs 181
replicate 271–272	coding, column property 94
saved design (X) matrix 282	coefficients, relative variance 75
select number of random starts 283	column properties
special commands 281	coding 94
specify sphere radius value 283	constrained state 85
axial	design roles 84, 97
points 127	factors for mixture experiments 99
scaling, central composite designs 138	high and low values 94

response limits 96	Save X Matrix 87
combinations, disallowing 90, 283	design diagnostics table 206
CONAEV method 167	Design of Experiments. See DOE
confounding 116	design roles 97
resolution numbers 112	designs
confounding pattern 76, 116	ABCD 168
constraints	aberration 112
adding 164	augment 271
disallowing combinations 90, 283	balanced 71
entering 85	Bayesian D-optimal 31, 61
linear 166	Bayesian I-optimal 62
loading 85	Box-Behnken 127, 129, 138
saving 85	central composite 127
continuous factors 67, III	discrete choice 179
control factors 247, 249	foldover 276
CONVRT method 167	fractional factorial 112
coordinate exchange algorithms 99	full factorial 101, 143, 151
Corn.jmp 241	full factorials 112
Cotter designs 114	Gaussian process IMSE optimal space filling 211
counts per unit (power and sample size) 303	I-optimal 61
covariate factors 51	Latin hypercube space filling design 200–204
creating factors tables 85	maximum entropy space filling 209
criterion, optimality 88, 282	minimum aberration 112
custom design commands 83	minimum potential space filling 207
custom designs	mixed-level 113
data tables 79	mixture 155, 171
Design Generation panel 7, 71	nonlinear 231
factors, defining 65	orthogonal
flexible block size 27	screening designs 112
how they work 99	screening experiments 155
models, describing 69	surface designs 138
random block design 79	orthogonal arrays 113
screening 17	Plackett-Burman 113
special commands 83	random block 79
split plot 80	replicating 272-273
split-split plot 81	response surface 127
strip plot 82	saturated 71
**** F*** **	screening 101
<b>D</b>	simplex centroid 158
D	simplex centroids 158
defaults	simplex lattice 161
number of random starts 88	space filling 197–216
defects 303	sphere packing space filling 197
D-efficiencies 43	split plot 80
describing models 69, 158	split-split plot 81
design	strip plot 82
matrix table properties 87	uniform precision 138
Moments Matrix 87	uniform space filling 204
resolutions 112	desirability
roles 84	functions 133, 253
* I	14110110110 177, 277

maximizing 133	finding optimal subsets 164
values 66, 110	range constraints 164
desirability traces 133	
desirability values, as column properties 96	F
determinant formula 89	1
diagnostics for custom designs 86, 282	Factor Changes 84
Difference to Detect option 288–289, 293, 296	factor combinations, disallowing 90
disallowing combinations 90, 283	Factor Profiling option 132, 134, 150, 175, 253
discrete choice designs	factorial designs
analysis 186, 190	fractional 112
attribute 181	full 101, 112, 143, 151
attributes panel 183	three level 113
choice set 181	factors
definition 179	adding 40, 67
design generation panel 184	categorical 68, III
dialog 183	column 98
example 181, 183–184	continuous 67, III
prior information 188	control factors 247, 249
profile 181	covariate 51
survey 181	for mixture experiments 95
DOE (Design of Experiments)	key factors 101
coding 94	loading 85
simple examples 103	nonmixture 44
DOE Sphere Radius 283	saving 84
Donev Mixture Factors.jmp 44	tables, creating 85
D-optimal	false negatives 114
augmentation 278	finding optimal subsets (extreme vertices) 164
designs 31, 60–61	fitting mixture designs 170
optimality criteria 88, 282	fixed covariate factors 51
	fixed covariates example 51
_	folding the calculation 171
E	foldover designs 276
effect	fraction of design space plot 74
aliasing 116	fractional factorial designs 112
eigenvalue 132	Full Factorial Designs 143–153
eigenvector 132	design generation panel 71
nonestimable 112	examples 145
orthogonal 139, 247	full factorial designs 112, 143
sparsity 101, 113–114	functions, desirability 133, 253
efficiencies	7 33. 73
D, G, and A 77	G
eigenvalue of effect 132	G
eigenvector of effect 132	Gaussian process IMSE optimal design 195, 211
equivalent solutions 99	global optimum 89
error standard deviation 288	goal types 65, 109
error variance 36	matching targets 66, 110
excluding factor combinations 90	minimizing and maximizing 66, 110
extra parameters 288	Group New Runs into Separates Block option 275
extreme vertices 163	- ''
algorithms 167	

н	M
hidden intercepts 171	matching target goals 65-66, 96, 109-110
hyperspheres 90, 283	matrix, alias 76
	matrix, design 87
1	maximize responses 65, 109
•	maximizing
identifying key factors 101	desirability 133
importance of responses 65, 84, 109, 254	goals 66, 110
entering 96	maximum entropy space filling design 195, 209
industrial experimentation 179	means, one- and two-sample (power and sample
inner arrays, inner designs 247, 249	size) 287
Inscribe option 139	methods
interactions 114	CONAEV 167
high-order 112	minimize responses 65, 109
intercepts, hidden 171	minimizing goals 66, 110
I-optimal	minimum aberration designs 112
designs 60-62	minimum potential design 207
optimality criteria 88, 282	minimum potential space filling design 195
I-optimal designs 61	mixed-level designs 113
	Mixture Designs 155–179
J	ABCD design 168
J	compared to screening designs 155
JSL (JMP Scripting Language)	definition 155
animation scripts 289	examples 171–174
augmented designs 265	extreme vertices 163
sphere radius 283	fitting 170
	linear constraints 166
K	optimal 157
N.	optimal subsets 164
Keep the Same 78	response surfaces 175
k-Sample Means (power and sample size) 294	simplex centroids 158
1 1 1	simplex lattice 161
ı	ternary plots 168
L	with nonmixture factors 44
L18 Chakravarty 114	mixture designs
L18 Hunter 114	
L18 John 113	examples 171 mixture experiments (column property) 95
L36 114	
L9-Taguchi 250	mixture, column properties 95 Model script
Label column 120, 140	Model Specification dialog 123, 130
larger-the-better formulas (LTB) 251	models
Latin hypercube space filling design 200–204	
limits, responses 96	custom design 69
linear constraints 164, 166	describing 69, 158
loading	
constraints 85	N
factors 85	N factors adding 67
responses 85	N factors, adding 67
local optimum 89	N Monte Carlo Spheres (nonlinear design
1	option) 245 N Responses 65

Index 32I

N Responses button 109	Р
no-intercept model 95	- 00
noise factors 247, 249	parameters, extra 288
nonestimable effect II2	Pattern column 105, 120, 140, 153
nonlinear design	patterns, confounding 116
advanced options 245	performance statistics 249
augment table 236, 244	Placket-Burman design
create using prior parameter estimates 233	creating 120
creating 241	Plackett-Burman designs 113
creating with no prior data 237	Plastifactors.jmp 171
distribution of parameters 238	plots
fitting to find prior parameter estimates 231	Actual-by-Predicted 125
introduction 229	Scatterplot 3D 136
launch dialog 234, 241–242	ternary 155, 168
number of Monte Carlo samples 235	points
number of starts 235	axial 127
overlay plot of design points 239	center See center points
using prior parameter estimates 233	centroid 163
Nonlinear Designs 229–246	potential terms (DOE) 31
advanced options 245	power and sample size calculations 285–306
creating 24I	analyses 287
examples 231	animation 292
nonmixture factors in mixture designs 44	counts per unit 303
Number of Monte Carlo Samples (nonlinear design	in statistical tests on means 296
option) 245	k-sample means 294
number of runs 15, 71	one-sample and two sample proportions 298
screening designs 112	one-sample mean 288–289
number of starts 88, 283	one-sample variance 296, 298, 300
	Sigma quality level 305
0	two-sample means 293
	prediction
On Face option 139	profilers 35, 38
one-sample and two-sample means (power and sample	traces 132
size) 287	variances 36, 138 prediction formulas, saving 174
one-sample and two-sample proportion (power and	
sample size) 298	prediction profiler 132
one-sample variance (power and sample size) 296	prediction variance profile plot 35 prediction variance surface plot 75
optimal determinant formula 89	primary terms (Bayesian D-optimal design) 31
optimal subsets (mixture designs) 164	profile, discrete choice designs 181
Optimality Criterion 88, 282	profilers
optimality criterion 88	mixture response surface 175
order of runs 78, 120, 140, 152, 159, 164, 168	prediction profilers 38, 132
orthogonal array designs 113, 247	prediction variance plot 35
orthogonal designs	prediction Variance profiler 35
screening designs 112	properties, columns 93
screening experiments 155	proportions (power and sample size) 298
surface designs 138	prospective power and sample size 285
Orthogonal option 139	prospective power and sample size calculations (see
outer arrays, outer designs 247, 249	power and sample size) 306
	pseudocomponent (mixture column property) 95

pure error 275	upper limits 66, 110
	responses, multiple 96
Q	RMSE 125, 149
·	robust engineering 247
quadratic model 34–76	roles, design 97
	Rotatable option 139
R	RSM (Response Surface Methodology) 136
	runs
radius, sphere 90, 283	additional 78, 120, 140, 152
random block designs 79	order they appear in table 78, 120, 140, 152, 159,
random seed, setting 85	164, 168
random starts 88	requesting additional 78, 120, 140, 152
Randomize within Blocks 78	screening designs 112
randomizing runs 78	
range constraints 163	S
Reaction Kinetics Start.jmp 237	
Reaction Kinetics.jmp 239	sample means (power and sample size) 287
Reactor 8 Runs.jmp 261	sample sizes
Reactor Factors.jmp 145–146	example comparing single-direction one-sample
Reactor Response.jmp 145	variances 296, 298
regressor columns 114	example with counts per unit 303
relative proportions See mixture designs	one and two sample means 289
relative variance of coefficients 75	prospective power analysis 296
relative variance of coefficients and power table 30	screening designs 143
replicating	saturated designs 71
designs 273	saving
replicating designs 272	constraints 85
reponses, loading 85	factors 84
requesting additional runs 78, 120, 140, 152	prediction formulas 174
rescaling designs 139	responses 84
resolution numbers 112	X Matrix 87, 282
resolutions of designs 112	scaling
response limits, column property 96	axial 138
Response Surface Designs 127–141	designs 139
examples 129–136	Scatterplot 3D
introduction 136	Box-Behnken designs 136
purpose 127	Scheffé polynomial 170
reports 131	screening designs 101
with blocking factors 40	custom designs 17
with categorical factors 40	design types III
response surface effects 171	dialogs 106, 120
Response Surface Methodology (RSM) 136	examples 105–140
response surfaces	scripts
mixture designs 175	animation 289
responses	generating the analysis model 123, 130
custom designs 65, 109, 137	Model script See Model table property
desirability values 66, 110	scripting <i>See</i> JSL
goals 65, 109	Set Random Seed command 85
goals, desirability functions 133	sigma quality level (power and sample size) 305
lower limits 66, 110	signal factors 247
saving 84	

	C 11 C 1 1 .
signal-to-noise ratios 247	full factorial designs 145
simplex 155	mixture designs 171–174
centroid designs 158	response surface designs 129, 134, 136
lattice designs 161	screening designs 105
single-sample means (power and sample size) 289	two-level categorical 104
solutions, equivalent 99	two-level fractional factorials 112
Sort Left to Right options 78	two-level full factorials 112
Sort Right to Left option 78	two-sample and one-sample means 293
Space Filling Designs 197–216	two-sample means (power and sample size) 287
borehole problem, sphere packing example 212	two-sample proportion (power and sample size) 298
Gaussian process IMSE optimal 195, 211	
Latin hypercube 195, 200–204	U
maximum entropy 195, 209	
minimum potential 195, 207	Uniform (space filling design) 195
sphere packing 195, 197	uniform (space filling design) 204
uniform 195, 204	uniform precision designs 138
sparsity, effect 101, 113–114	User Defined option 139
sphere packing design 195, 197	
sphere radius 90, 283	V
split plot designs 68, 80	•
split-split plot designs 81	values
star points 127	high and low for columns (in DOE) 94
starts, number of 88, 283	target 66, 110
starts, random 88	variance of prediction 139
statistics, performance 249	variance, error and prediction 36
strip plot designs 82	vertices
subsets, finding optimal 164	extreme 163
supersaturated designs 23	extreme, finding optimal subsets 164
surface designs See response surface designs	
survey, discrete choice designs 181	W-Z
	VV-Z
Т	weight, importance of response 65, 84, 97, 109, 254
1	whole model test 171
tables	X Matrix, saving 87, 282
factors table, creating 85	XVERT method 167
making in custom designs 79	
Taguchi designs 247–254	
description 247	
methods 247	
target values 66, 96, 110	
ternary plots 155, 168	
three-dimensional scatterplot	
Box-Behnken designs 136	
traces, desirability 133	
trade-off in screening designs 112	
tutorial examples	
augment designs 261–271	
custom design 1–13	
DOE 103	

flexible block size 27